



Beauly to Blackhillock to New Deer to Peterhead 400 kV OHL Project
Environmental Impact Assessment Report
Volume 3 | Figures

September 2025

VOLUME 3: FIGURES

CONTENTS

Figure 1.1	Site Location Overview
Figure 1.2	Site Location Detail
Figure 3.1	Site Layout
Figure 3.2	Limit of Deviation - Proposed Development
Figure 3.3	Limit of Deviation - Proposed Towers and OHL Alignment
Figure 3.4a-d	Tower Designs
Figure 3.5a-f	Existing OHL Crossing
Figure 3.6	Typical Access Track Sections
Figure 3.7	Typical Bellmouth Layout
Figure 3.8	Typical Watercourse Crossing Sections
Figure 3.9a-b	Typical Tower Working Area Arrangement
Figure 3.10	Landholdings Excluded from Limit of Deviation
Figure 4.1	Corridor Options
Figure 4.2	Proposed Corridor
Figure 4.3	Route Options
Figure 4.4	Proposed Route
Figure 4.5	Proposed Route and Further Refined Route
Figure 4.6	Alignment Options
Figure 4.7	Coachford Alignment Options
Figure 4.8	Proposed Alignment
Figure 5.1	Cumulative Developments
Figure 7.1	Zone of Theoretical Visibility 10km LVIA Study Area - Bare Earth
Figure 7.2	Zone of Theoretical Visibility 10km LVIA Study Area – Screening
Figure 7.3a	Zone of Theoretical Visibility The Highland Council, Caledonian Canal Crossing - Bare Earth
Figure 7.3b	Zone of Theoretical Visibility The Highland Council, Caledonian Canal Crossing - Screening
Figure 7.3c	Comparative Zone of Theoretical Visibility Kellas Alternative Alignment - Bare Earth
Figure 7.4	Landscape Character Types and Key Landscape Features
Figure 7.5	Landscape Character Type Photos
Figure 7.6	Visual Amenity Receptors and Viewpoint Locations
Figure 7.7	Visual Context
Figure 8.1	International Designated Sites
Figure 8.2	National, Local / Non-statutory Designated Sites
Figure 8.3	Ancient Woodland and Peatland Records
Figure 9.1	Natural Heritage Zones

Figure 9.2	Ornithological Mitigation Measures
Figure 10.1	Hydrology and Watercourse Crossings
Figure 10.2	Bedrock Geology
Figure 10.3	Superficial Geology
Figure 11.1	Designated Heritage Assets
Figure 11.2	Heritage Assets and the Limit of Deviation
Figure 11.3	Designated Heritage Assets and Zone of Theoretical Visibility
Figure 11.4	Cultural Heritage Viewpoint Locations
Figure 12.1	Proposed Felling
Figure 12.2	Proposed Felling and Environmental Constraints
Figure 13.1	Highland Council - Traffic and Transport Study Area
Figure 13.2	Highland Council - Traffic Count Site Locations
Figure 13.3	Highland Council - Personal Injury Accident Locations
Figure 13.4	Moray Council - Traffic and Transport Study Area
Figure 13.5	Moray Council - Traffic Count Site Locations
Figure 13.6	Moray Council - Personal Injury Accident Locations
Figure 13.7	Aberdeenshire Council - Traffic and Transport Study Area
Figure 13.8	Aberdeenshire Council - Traffic Count Site Locations
Figure 13.9	Aberdeenshire Council - Personal Injury Accident Locations
Figure 14.1	Recreational and Tourist Facilities and Activities
Figure 14.2	Public Access Routes
Figure 15.1	Noise Sensitive Receptors (NSRs)

Other Volumes

- Volume 1: Non-Technical Summary
- Volume 2: Main Report
- Volume 3: Figures**
- Volume 4: Visualisations
- Volume 5: Appendices