Council	Highland
Condition:	Ruinous
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Small square unroofed structure c2x2m. Consists of low stone walls c0.5m heigh, 0.25m width. Taken as a point as outside survey corridor. Not depicted on historic maps.

Asset/Event Number	696
Asset/Event Name	Dyke, Buoltach
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	317190
Northing	935236
Council	Highland
Condition:	Good
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Low stone dyke between two unroofed post-medieval structures (Assets 695-698). Taken as point as outside survey area. Not depicted on historic maps.

Asset/Event Number	698
Asset/Event Name	Building, Buoltach
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317208
Northing	935249
Council	Highland
Condition:	Degraded
Alignment:	ENE/WSW
Importance:	Low

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular roofless stone building measuring c8m by 5m over walls and overgrown by gorse along the N elevation. The W gable remains intact and stands m tall, while the N and S elevations stand 1.4m tall. The E gable has been removed, and the building seems likely to have been used as a livestock pen. A possible fireplace stands in the N wall. Small windows in N and S walls and a possible fireplace in the N wall. Depicted as a roofed building on the 1st edition OS map but not depicted at all on the 2nd edition OS map. OS. 1877. Caithness XXXIII. Surveyed: 1871, Published: 1877. OS. 1907. Caithness XXXIII. Surveyed: 1905, Published: 1907.

Asset/Event Number	699
Asset/Event Name	Ditch, Buoltach
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	317193
Northing	935309
Council	Highland
Condition:	Fair
Alignment:	NNW/SSE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Drainage ditch under grass measuring 2m wide and 0.8m deep, recorded extent measuring c90m long but continues outwith survey corridor to the S. Continues the boundary formed by Asset 700 and runs parallel to a new fence line, which may stand on the former boundary. Depicted as a boundary on the 1st edition OS map. OS. 1877. Caithness XXXIII. Surveyed: 1871, Published: 1877.

Asset/Event Number	700
Asset/Event Name	Dyke, Buoltach
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	317113
Northing	935453
Council	Highland
Condition:	Degraded

Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Drystone dyke that stands up to 0.8m tall and collapsed to ground level under grass in parts. Section to the N oriented SW to NE survives as just a low earth mound. Depicted as a boundary on the 1st edition OS map. Perhaps continues as a drainage ditch to the S (Asset 699). OS. 1877. Caithness XXXIII. Surveyed: 1871, Published: 1877.

Asset/Event Number	701
Asset/Event Name	Track, Buoltach
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	317048
Northing	935467
Council	Highland
Condition:	Very degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A relict track, c5m wide and extending c30m long through the survey corridor. Consistent with a track depicted on the 1st edition OS map that spans the survey corridor, but the visible extent is as surveyed. OS. 1877. Caithness XXXIII. Surveyed: 1871, Published: 1877.

Asset/Event Number	702
Asset/Event Name	Building, Buoltach
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317082
Northing	935624
Council	Highland
Condition:	Ruinous
Alignment:	E/W
Importance:	Low

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Ruinous stone building measuring c12m long by 5m wide, partially under grass. Two internal insertions split it into three compartments. The gable ends survive to a height of c3m, while longer elevations are c1.8m tall. A small porch measuring 4m by 2m and roofed in large flagstones extends off the SE elevation. Depicted as a roofed building on the 1st and 2nd edition OS maps. OS. 1877. Caithness XXXIII. Surveyed: 1871, Published: 1877. OS. 1907. Caithness XXXIII. Surveyed: 1905, Published: 1907.

Asset/Event Number	703.1
Asset/Event Name	Enclosure, Buoltach
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	317196
Northing	935648
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A somewhat D-shaped enclosure under grass, measuring c30m by 9m and composed of a stone and turf dyke that stands 0.9m tall and spread c1.5m wide. Depicted on the 1st edition OS map. OS. 1877. Caithness XXXIII. Surveyed: 1871, Published: 1877.

Asset/Event Number	703.2
Asset/Event Name	Building, Buoltach
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	317195
Northing	935661
Council	Highland
Condition:	Ruinous
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A roofless rectangular

	building measuring c25m by 5m over walls are 0.6m wide. The W gable wall stands almost to full height of 4m, but the E has been reduced to near ground level and the walls are general no more than 1m tall. A fireplace stands in the W elevation. Depicted as a roofed building on the 1st and 2nd edition OS maps. OS. 1877. Caithness XXXIII. Surveyed: 1871, Published: 1877. OS. 1907. Caithness XXXIII. Surveyed: 1905, Published: 1907.

Asset/Event Number	703.3
Asset/Event Name	Building, Buoltach
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	317182
Northing	935659
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A roofless rectangular stone building measuring c5m by 5m over walls that are 0.6m wide in the N and S elevation and 1.1m wide in the E elevation, a former gable that also stands to a height of c4m while the N and S elevations are 3m tall. The building has been reduced to foundation level in W side. A blocked up window sits in the E enable elevation. A large entrance 3m by 3m in the S elevation suggests this was a cart shed, with manure and modern detritus in the interior indicating the building has been latterly used as a livestock pen or shelter. Depicted as a roofed building on the 1st and 2nd edition OS maps. OS. 1877. Caithness XXXIII. Surveyed: 1871, Published: 1877. OS. 1907. Caithness XXXIII. Surveyed: 1905, Published: 1907.

Asset/Event Number	704
Asset/Event Name	Structure, Buoltach
Type of Asset/Event	Structure
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	317181
Northing	935523
Council	Highland

Condition:	Fair
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Unusual subterranean feature, not dissimilar to a small prehistoric souterrain, constructed into a small hillock. The structure is visible as a pair of revetted drystone walls bearing a lintelled roof creating an access c0.5m by 0.5m, with exposed stone visible c1.5m beyond the entrance suggesting the structure continues at least partially into the slope, though has infilled with material. While a prehistoric origin for the structure is not discounted, it seems contemporary with the nearby farmstead (Asset 706-709, and may comprise some kind of storage structure, such as a cold room. Not depicted on historic mapping.

Asset/Event Number	706
Asset/Event Name	Building, Buoltach
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	317225
Northing	935520
Council	Highland
Condition:	Fair
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Rectangular roofless structure, measuring 8m by 5m over walls that are 0.25m wide and stand between 1-2m in height. An internal partition separates the building in to two compartments. The SE portion is of different build quality and it appear this is likely a later extension. Depicted as a roofed building on the 1st edition OS map but unroofed by the time of the 2nd edition OS map. OS. 1877. Caithness XXXIII. Surveyed: 1871, Published: 1877. OS. 1907. Caithness XXXIII. Surveyed: 1905, Published: 1907.

Asset/Event Number	707
Asset/Event Name	Building, Buoltach
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	317223

Northing	935539
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Rectangular roofless building measuring 25m by 5m over walls which stand up to a height of 2m and are 0.5m wide. Three internal partitions separate the building into four compartments with the entrances to each in the SE elevation. Depicted as a roofed building on the 1st and 2nd edition OS maps. OS. 1877. Caithness XXXIII. Surveyed: 1871, Published: 1877. OS. 1907. Caithness XXXIII. Surveyed: 1905, Published: 1907.

Asset/Event Number	708
Asset/Event Name	Clearance cairn, Buoltach
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	317210
Northing	935548
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn measuring c4m in diameter and standing 0.4m tall.

Asset/Event Number	709
Asset/Event Name	Enclosure, Buoltach
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	317251
Northing	935551
Council	Highland
Condition:	Degraded

Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Enclosure composed of drystone dykes measuring 0.6m wide and 1.2m tall with some evidence of capping remaining. Measures c15m by 20m. Depicted on the 1st and 2nd edition OS map. OS. 1877. Caithness XXXIII. Surveyed: 1871, Published: 1877.

Asset/Event Number	710
Asset/Event Name	Dyke, Buoltach
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	317228
Northing	935609
Council	Highland
Condition:	Fair
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke, mostly visible as a 0.5m tall and wide bank with ditch on either side, recorded extent c200m long but continues outwith survey corridor to E and W. Besides modern post and wire fence line. Stone visible along the dyke, but largely overgrown by grass, so hard to see any structural elements. Depicted as a boundary on the 1st edition OS map. OS. 1877. Caithness XXXIII. Surveyed: 1871, Published: 1877.

Asset/Event Number	711
Asset/Event Name	Bridge, Buoltach
Type of Asset/Event	Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	317217
Northing	935645
Council	Highland
Condition:	Fair
Alignment:	N/S
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Small bridge composed of four over-lapping like flagstones set above built up stone on either edge of a low field ditch, measuring 2m by 1.5m, likely associated with the farmstead (Assets 703) to the W to facilitate access. Not depicted on historic maps.

Asset/Event Number	712
Asset/Event Name	Bank, Braehungie
Type of Asset/Event	Bank
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	317520
Northing	936502
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A turf bank measuring c77m in length, c1.5m wide with height of c0.4m. Possible ditch to SW but may be undulating ground. Consistent with a boundary depicted on the 1st edition OS map. OS. 1877. Caithness XXXIII. Surveyed: 1871, Published: 1877.

Asset/Event Number	713
Asset/Event Name	Enclosure, Braehungie
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	317698
Northing	936602
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Small sheepfold or enclosure composed of a circular low drystone wall 6m in diameter and reduced to 0.1m-0.5m in height with walls 0.25m wide. Not depicted on historic mapping.

Asset/Event Number	714
Asset/Event Name	Track, Cnoc na Snathaid
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	316476
Northing	934303
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A relict track, c2m wide and heather and grass, recorded extent measures c200m long but continues outwith survey corridor to the N and S. Not depicted on historic mapping.

Asset/Event Number	715
Asset/Event Name	Peat cutting, Cnoc na Snathaid
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	316394
Northing	934293
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Small L shaped peat cut under heather, c20m by 20m with a bank 0.3m deep.

Asset/Event Number	716
Asset/Event Name	Peat cutting, Cnoc na Snathaid
Type of Asset/Event	Peat cutting

Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	316402
Northing	934251
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Area of peat cutting c40m by 40m under heather with banks 0.4m deep.

Asset/Event Number	717
Asset/Event Name	Track, Cnoc na Snathaid
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	316378
Northing	934246
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A relict track under vegetation with heathery banks to either side, measures 2.5m wide and recorded extent c250m long but continues outwith survey corridor to the S and N. Depicted on the 1st edition OS map. OS. 1877. Caithness XXXIII. Surveyed: 1871, Published: 1877.

Asset/Event Number	718
Asset/Event Name	Cairn, Burn of Houstry
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	ND13SE 28
HER Number	MHG1155
Status	Non-designated Heritage Asset

Section:	A1.4
Easting	315879
Northing	933531
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Cairn not directly accessed as no land access permission granted for the land parcel it occupied. Viewed from c20m away, appears as described below. Https://her.highland.gov.uk/Monument/MHG1155 This cairn is situated on leading edge of a peat-covered terrace on E side of valley of the Burn of Houstry, and commands extensive views from the NW to the SW. The cairn, which measures 13m in diameter by 0.9m in height, is grass and heather grown, but stone is visible protruding through most of its surface, and also where it has been dug into on the W and E. A square-based marker cairn some 1.3m in height has been built on the summit of the cairn, and a small pen or shelter has been constructed in the disturbance on the NE. Visited by RCAHMS (SPH) August 1997 No change. Visited by OS (J M) 19 October 1982. Cairn (NR) OS 1:10,000 map, (1979) A heavily mutilated turf and heather-covered cairn, measures c 12m in diameter and 0.9m high. Visited by OS (A A) 22 March 1965. Cairn (NAT) OS 25" map, Caithness, 2nd ed., (1907)

Asset/Event Number	719
Asset/Event Name	Ditch and bank, Burn of Houstry
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	315739
Northing	933216
Council	Highland
Condition:	Very degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A ditch and stone and turf bank, ditch measuring c0.5m wide and 0.5m deep and c95m long. Bank runs parallel with ditch and is composed of stone and turf and covered in long heather distinct from surrounding area, measuring 0.3m tall and spread 1.5m wide. Not depicted on historic mapping.

Asset/Event Number	720
Asset/Event Name	Ditch and bank, Burn of Houstry
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	315724
Northing	933232
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A ditch and bank perpendicular to ditch and bank Asset 719, measuring c40m long. Ditch is c1.5m wide and the bank is c0.7m wide and 0.4m tall. Both under heather. Not depicted on historic mapping.

Asset/Event Number	721
Asset/Event Name	Dyke, Burn of Houstry
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND13SE 104
HER Number	MHG13591
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	315495
Northing	933060
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Drystone rubble build stone dyke measuring c175m long, standing up to 0.8m tall and spread 1m wide. Forms field boundary and enclosure for farmstead Assets 722-727. Depicted on 1st edition OS map. OS. 1877. Caithness XXXIX (Inset XLIII), Surveyed: 1871, Published: 1877. https://her.highland.gov.uk/Monument/MHG13591 Cuag is depicted as a group of four roofed and two unroofed buildings on the 1st edition of the OS 6-inch map (Caithness, 1871), sheet xxxiii, and is still shown on the latest edition of the OS 1:10000 map as three unroofed buildings. The OS Name Book describes Cuag as 'a

farmsteading and dwelling house on the slope betwixt the public road and the Burn of Houstry' (ONB 1871).
Information from RCAHMS (DE) July 1997

The farmstead of Cuag is situated at the foot of the river terrace below the hut-circle ND13SE 44 and on the E bank of the Burn of Houstry. It comprises two ranges around a yard (with the main range along the S side), a kiln, and several enclosures. The building forming the E end of main S range, on the S side of the yard, has opposed entrances and cruck slots are visible in its walls. Set into a small bank to the SE of this range there is a kiln; overall the kiln measures 5m from N to S by 4m transversely and there is a circular stoke hole on the SW.
The OS Name Book describes Cuag as a 'farmsteading and dwelling house on the slope between the public road and the Burn of Houstry, about 2 miles N East from Dunbeath, property of Sinclair Esq of Dunbeath Castle' (Name Book, Caithness, No. 6, p. 238 <1>] and it is depicted as roofed on the 1st edition of the OS 6-inch map (Caithness, 1872, sheet xxxiii).
Visited by RCAHMS (DE, IP) August 1997

This site was visited during a walkover survey in July 2009. It was found to comprise one building roofed in corrugated iron with at least two houses and a possible third, a byre and an enclosure. <2>
<1> SHG3364 Text/Publication/Volume: Name Book (County). Object Name Books of the Ordnance Survey. Book No. 32, 196.
<2> SHG24446 Text/Report/Fieldwork Report: Farrell, S. 07/2009. Report of Archaeological Desktop & Walkover Survey, Knockinnon, Houstry. Unaffiliated. Digital. Site 7.

Asset/Event Number	722
Asset/Event Name	Possible structure, Burn of Houstry
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND13SE 104
HER Number	MHG13591
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	315528
Northing	932971
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Under grass and built partly onto the SW facing hill slope is a probable corn-drying kiln measuring c6m in diameter over the pronounced mound. Internal box still visible c0.5m wide and 0.4m tall. Possibly depicted as a roofed building on the 1st edition OS maps but unroofed by the 2nd edition OS map. For HER asset description see Asset 721. OS. 1877. Caithness XXXIX (Inset XLIII), Surveyed: 1871, Published: 1877 OS. 1907. Caithness XXXIX & XLIII, Surveyed: 1905, Published: 1907

Asset/Event Number	723

Asset/Event Name	Structure, Burn of Houstry
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND13SE 104
HER Number	MHG13591
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	315489
Northing	932989
Council	Highland
Condition:	Fair
Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An unroofed drystone building measuring 8m by 7m over walls that stand to full height to 1.5m in some parts, and 4m at the S gable end. The interior is overgrown with bracken and dyke Asset 721 extends NW to form the enclosure that stands adjacent to the E of the structure. An entrance stands in the S elevation, blocked by wooden slats, and a window in the W. A collapse in the E elevation facilitates access, and the blocked original entrance is likely to allow the enclosure to still be used as a livestock pen for sheep. Depicted as a roofed building on the 1st and 2nd edition OS maps. For HER asset description see Asset 721. OS. 1877. Caithness XXXIX (Inset XLIII), Surveyed: 1871, Published: 1877 OS. 1907. Caithness XXXIX & XLIII, Surveyed: 1905, Published: 1907

Asset/Event Number	724
Asset/Event Name	Building, Burn of Houstry
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND13SE 104
HER Number	MHG13591
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	315510
Northing	932979
Council	Highland
Condition:	Ruinous
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A ruinous but partially roofed long stone building measuring c35m by 5m over walls and extending over sloping ground to the SW. Contains four partition walls delineating five internal compartments. Walls are c 0.75m wide and stand to wall head height of c 2.5 m along S and N elevations, with E gable nearly 4m tall. Fireplace in E gable. The W most of these is roofed with corrugated iron sheets and the floor comprises compacted animal manure, indicating its use as a livestock pen. Various re-working of the rest of the building has occurred likely for use as an animal

store. Blocked and gated entrances and windows in all compartments. Depicted as a roofed building on the 1st and 2nd edition OS maps. For HER asset description see Asset 721.
OS. 1877. Caithness XXXIX (Inset XLIII), Surveyed: 1871, Published: 1877
OS. 1907. Caithness XXXIX & XLIII, Surveyed: 1905, Published: 1907

Asset/Event Number	725
Asset/Event Name	Cist and cairn, Braehiller
Type of Asset/Event	Cairn; cist
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	MHG13578
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	314800
Northing	932200
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Low/Medium
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Not surveyed as no land access granted. Https://her.highland.gov.uk/Monument/MHG13578 This cist (1.5m x 1m) consists of one large upright stone plus smaller horizontal stones around the pit, in an area of stone scatter. Further to the north of this is a circular concentration of stones, partly turf covered, which are the possible remains of a cairn (3-5m in diameter). G.U Survey: 1986: DB 13/4

Asset/Event Number	726
Asset/Event Name	Dyke, Burn of Houstry
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND13SE 104
HER Number	MHG13591
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	315495
Northing	932982
Council	Highland
Condition:	Degraded
Alignment:	Various

Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A Z-shaped segment of drystone dyke joining buildings Asset 723 and 724 at their S and W ends respectively. Dyke stands 1m tall and 0.6m wide, measuring c10m long. Depicted on the 1st and 2nd edition OS maps but here a straight length of dyke is shown, so this may be a later re-build. For HER asset description see Asset 721. OS. 1877. Caithness XXXIX (Inset XLIII), Surveyed: 1871, Published: 1877 OS. 1907. Caithness XXXIX & XLIII, Surveyed: 1905, Published: 1907

Asset/Event Number	727
Asset/Event Name	Enclosure, Burn of Houstry
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND13SE 104
HER Number	MHG13591
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	315505
Northing	932966
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Drystone dyke measuring c30m long and standing 0.6m tall, spread up to 1.5m wide. Likely part of enclosure wall Asset 721 and much collapsed. Measures C Drystone rubble build, much collapsed. Depicted on the 1st and 2nd edition OS maps, though degraded in the latter. For HER asset description see Asset 721. OS. 1877. Caithness XXXIX (Inset XLIII), Surveyed: 1871, Published: 1877 OS. 1907. Caithness XXXIX & XLIII, Surveyed: 1905, Published: 1907

Asset/Event Number	728
Asset/Event Name	Bridge, Burn of Houstry
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	315427
Northing	933085
Council	Highland
Condition:	Fair

Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Bridge constructed of large stone boulders, iron girders and thin slate, measures 8m by 2m and likely added in the 20th century to make passable. Spans the Houstry burn and likely associated with the farmstead to the SE (Assets 721-727), providing access to the moorland hills to the W. Not depicted on historic mapping.

Asset/Event Number	729
Asset/Event Name	Burnt mound (possible), Strath Sgitheach
Type of Asset/Event	Burnt mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	251625
Northing	863402
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible burnt mound under heather and grass, measures 16.5m by 12.5m and situated on S-facing slope with a small burn to the S. Some stone visible on top with potential evidence for burning - though this may also be moor burn. Commands long views across the strath.

Asset/Event Number	730
Asset/Event Name	Dyke, Strath Sgitheach
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	251875
Northing	863513
Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone and turf dyke measuring c140m long, measuring 0.25-0.5m height and spread up to 1.5m wide, under dense vegetation. Forms a network of probable enclosures with Assets 731-733 and 735. Not depicted on historic mapping.

Asset/Event Number	731
Asset/Event Name	Dyke, Strath Sgitheach
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	251895
Northing	863615
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A series of stone and turf dykes, some forming enclosures with Assets 730, 733 and 735. c350m in length and of a degraded nature, under vegetation. Generally measure 0.5m tall and spread up to 1.5m wide. Not depicted on historic mapping.

Asset/Event Number	732
Asset/Event Name	Dyke, Strath Sgitheach
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	251928
Northing	863662
Council	Highland
Condition:	Fair
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A probable stone and turf dyke represented mostly by intermittent boulders, with the turf element likely eroded away, and forming an enclosure at the SW end. Measures c500m in length, with the enclosure measuring c80m NE/SW by 70m. Forms a network of probable enclosures with Assets 730,

731, 733 and 735. Not depicted on historic mapping.

Asset/Event Number	733
Asset/Event Name	Dyke, Strath Sgitheach
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	252170
Northing	863712
Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Turf and stone dyke measuring c150m in length and standing c0.5m tall, spread up to 2m wide. Forms a network of probable enclosures with Assets 730-733. Not depicted on historic mapping.

Asset/Event Number	734
Asset/Event Name	Dyke, Strath Sgitheach
Type of Asset/Event	Dyke
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	252096
Northing	863614
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under vegetation which enclosed an area of human activity. Curvilinear and measures c110m in length, spread up to 1m wide and standing c0.3-0.5m tall. Likely formed an enclosure (c45m in diameter) associated with the farmstead Asset 736 to the E, but is not depicted on historic mapping.

Asset/Event Number	735
Asset/Event Name	Dyke, Strath Sgitheach
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	252094
Northing	863599
Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under vegetation, c130m long and broadly T-shaped, standing c0.4m tall and spread up to 1.5m wide. Forms a network of probable enclosures with Assets 730-733 and 735. Not depicted on historic mapping.

Asset/Event Number	736
Asset/Event Name	Building, Strath Sgitheach
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG8918
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	252221
Northing	863763
Council	Highland
Condition:	Very Degraded
Alignment:	ENE/WSW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone footings for a rectangular building under grass, measuring c23m by 5m over walls, which do not stand taller than 0.3m in height and are spread up to c1.5m. Two partition walls define three compartments overall and the entrances appear to have been in the SSW elevation. Stands on raised ground overlooking a burn to the N. Depicted on the 1st edition OS map as a roofless structure with three compartments. OS. 1880. Ross-shire & Cromartyshire (Mainland) LXXVI, Surveyed: 1875-6, Published: 1880 https://her.highland.gov.uk/Monument/MHG8918 A three-roomed cottage, apparently of dry-stone construction, standing in cleared ground. (see also NH 56 SW 29). Visited September 1978. RCAHMS 1979, visited September 1978.

A farmstead comprising an unroofed long building of three compartments and an enclosure or field are depicted on the 1st edition of the OS 6-inch map (Ross-shire and Cromartyshire 1881, sheet lxxvi). The unroofed building is shown on the current edition of the OS 1:10560 map (1969).
Information from RCAHMS (SAH) 1 March 1996
--- SHG2670 Text/Report: RCAHMS. 1979. The Royal Commission on the Ancient and Historical Monuments of Scotland. The archaeological sites and monuments of Easter Ross, Ross and Cromarty District, Highland Region. . 35, No. 322.

Asset/Event Number	737
Asset/Event Name	Hut circle - Strath Sgitheach
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	MHG8903
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	252238
Northing	863817
Council	Highland
Condition:	Unknown
Alignment:	Circular
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Not visible during the survey, located within an area of dense bracken. Https://her.highland.gov.uk/Monument/MHG8903 This hut circle is located on a bluff above a burn, NW of NH 56 SW 20. Poorly preserved, it measures c. 9.5m in diameter between walls of indeterminate width. It has no obvious entrance. Visited June 1989. Information from S T Driscoll and S M Foster (Mss, 6, No. 7.1.) 1989 A walkover survey was undertaken by Meryl Marshall of NOSAS in 2020 comparing existing Canmore and HER records. <1> Note: Site not visible on aerial photographs so location based on grid coordinates. (T. Blackie 14/11/22) <1> SHG29225 Text/Correspondence: Marshall, M.. 2020. Walkover survey at Strath Sgitheach by NOSAS. North of Scotland Archaeology Society (NOSAS). Yes. Digital. XY

Asset/Event Number	739
Asset/Event Name	Enclosure, Strath Sgitheach
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	D1.2
Easting	252303
Northing	863821
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Small rectangular stone and turf enclosure measuring c30m by 17m over banks. Visible as a low line of stones c0.5m across, mostly overgrown with turf. Not depicted on historic mapping.

Asset/Event Number	740
Asset/Event Name	Dyke, Strath Sgitheach
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	252654
Northing	864082
Council	Highland
Condition:	Fair
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A turf and stone dyke under grass and heather, stands 0.5m tall and spread c2m wide, L-shaped in plan and recorded extent measures c290m. Not depicted on historic mapping.

Asset/Event Number	741
Asset/Event Name	Enclosure, Strath Sgitheach
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	252491
Northing	864060

Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A turf and stone dyke under grass and heather, stands 0.5m tall and spread c2m wide and forms an enclosure (c160m by c45m) with two enclosed areas (N: c115m by c45m, S: c50m by c45m). Not depicted on historic mapping.

Asset/Event Number	742
Asset/Event Name	Sheep fold, Strath Sgitheach
Type of Asset/Event	Sheepfold
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG8922
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	253112
Northing	864328
Council	Highland
Condition:	Fair
Alignment:	Curving
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone sheepfold, survives as rubble stone wall c40m in diameter, c1m tall and 0.5m wide. It is marked on the 1st edition OS map as an 'X', and is depicted in its current form on the 2nd edition OS map. OS. 1880. Ross-shire & Cromartyshire (Mainland) LXXVI, Surveyed: 1875-6, Published: 1880 OS. 1907. Ross and Cromarty LXXVI, Surveyed: 1904, Published: 1907. https://her.highland.gov.uk/Monument/MHG8922 A circular sheep fold is depicted on the 2nd edition OS 6" Ross-shire map. <1> This sheepfold is visible in aerial photography taken 1999-2001. It measures approximately 15m in diameter. <2> <1> SHG23732 Image/Map: Ordnance Survey. 1905. Ordnance Survey 2nd edition 6 inch map: Ross-shire. Digital. <2> SHG27491 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 1999-2001. Get Mapping colour vertical aerial photography 1999-2001 (The Millennium Map).

Asset/Event Number	743
Asset/Event Name	Dyke, Strath Sgitheach
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	D1.2
Easting	253195
Northing	864369
Council	Highland
Condition:	Fair
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Small section of linear bank under grass, L-shaped in plan and measuring c90m long, 0.25-0.5 tall and spread up to 1m wide. Not depicted on historic mapping.

Asset/Event Number	744
Asset/Event Name	Flood bank, Coille Uisge
Type of Asset/Event	Other
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	247173
Northing	854261
Council	Highland
Condition:	Fair
Alignment:	Various
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Large linear bank under dense vegetation, forming a flood defence that continues around the rounded spur of land at the confluence of the Rivers Conon to the S and the Black Water to the N. Dimensions difficult to discern due to the vegetation, but likely substantial. Recorded extent spans the survey corridor but continues outwith it the E and W. Depicted on the 1st and 2nd edition OS maps. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXXVII, Surveyed: 1876, Published: 1881 OS. 1907. Ross and Cromarty LXXXVII, Surveyed: 1902, Published: 1907

Asset/Event Number	745
Asset/Event Name	Hollow, Kinnahaird
Type of Asset/Event	Hollow
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset

Section:	N/A
Easting	246775
Northing	854948
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Small squarish hollow c2m by 2m and 0.25m deep with a setting of stones, potentially a small storage pit. Not depicted on historic mapping.

Asset/Event Number	750
Asset/Event Name	Peat cutting, Creagan Cosach
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	308909
Northing	921386
Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under heather and grass, c6m x 30m with banks 0.3m deep.

Asset/Event Number	751
Asset/Event Name	Building, Langwell
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND02SE 39
HER Number	MHG28685
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	309402
Northing	922181
Council	Highland
Condition:	Degraded

Alignment:	ESE/WNW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular building under tall bracken, dimensions somewhat difficult to discern due to vegetation but c33m by 6m over walls. Not depicted on historic mapping. Https://her.highland.gov.uk/Monument/MHG28685 A long building, situated on the crest of a slope falling away to the Langwell Water on the N, was recorded by Headland Archaeology during a pre-afforestation survey in 1998. The building measures 34m from WNW to ESE by 6m externally and has rubble-built walls up to 0.8m thick and 1.5m, or seven courses, high. A 15m long, slightly curving wall forms a partition some 14m from the W end with a second partition wall, broken by a doorway, lying 3m from the W end. Doorways on the S side of the building lead into the two rooms formed by the partitions. A 5m break in the S wall lies to the E of the major partition wall. The enclosure lying to the east of the hut-circle (see MHG2427) may be associated with the long building. <1> GIS spatial data amended in 2018 to location as shown on 2009 Aps. <2> <1> SHG27187 Text/Report/Fieldwork Report: Colm Moloney & Louise Baker. 1998. Forestry Survey - Langwell, Berriedale, Caithness. Headland Archaeology. Digital (scanned as PDF). Area 3 Site 15. <2> SHG27382 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 2009. Getmapping aerial photography 2009. XY

Asset/Event Number	752
Asset/Event Name	Hut circle, Langwell
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	ND02SE 6
HER Number	MHG2427
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	309458
Northing	922168
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle c14m in diameter under tall bracken, dimensions otherwise difficult to determine due vegetation. Depicted as a 'Pict's house' on the 1st edition OS map. OS. 1877. Caithness XLII, Surveyed: 1871, Published: 1877. https://her.highland.gov.uk/Monument/MHG2427 Fortified Enclosure, Langwell: On the top of the S bank of the Langwell Water, some 260 yds SSE of the road bridge below Cnoc Bad Fhasgaidh, and about 100 yds below the moor road, is a circular enclosure whose walls have evidently been spoiled to build an adjacent cottage and fold, now in ruins. The interior, which is slightly below the surrounding level, measures 32ft in diameter. The wall, which appears to have been faced on either side with large stones, is about 11ft thick and stands some 4ft above the level of the interior, 3ft above ground level externally. The entrance has been from the S. RCAHMS 1911, visited 1910.

ND 0945 2216. An oval enclosure, 14.1m N-S by 13.5 m transversely, with an earth-and-stone bank 1.1m high internally, but only 0.6m high externally. No internal features were noted, and the entrance would appear to have been in E (not S as stated by RCAHMS), where NW corner of a later, stone-walled enclosure overlies the bank. The enclosure is one of the usual type, and may even be an old sheepfold.
Visited by OS (W D J) 16 June 1960.

(ND 0945 2216) Enclosure (NR) OS 6" map, (1964)
This is not a fortified enclosure, but a massive hut circle of Kilphedir II type (see NC91NE 25); other, similar dwellings occur in the area (see ND02SE 11 and 13). The site has not deteriorated since visit by RCAHMS. The entrance was probably in ESE; there is no break visible in the wall, but this sector is overlaid by an early-modern enclosure.
Revised at 1:10,000. Visited by OS (N K B) 16 November 1982.
This hut-circle was visited by Headland Archaeology during a pre-afforestation survey in 1998. The adjacent rectangular enclosure may be associated with the long building to the west (see MHG28685) ND02SE 39). <1>
GIS spatial data amended in 2018 to location as seen on 2009 Aps. <2>
--- SHG2664 Text/Report: RCAHMS. 1911. The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Third report and inventory of monuments and constructions in the county of Caithness. . 61, No. 224.
<1> SHG27187 Text/Report/Fieldwork Report: Colm Moloney & Louise Baker. 1998. Forestry Survey - Langwell, Berriedale, Caithness. Headland Archaeology. Digital (scanned as PDF). Area 3 No.14.
<2> SHG27382 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 2009. Getmapping aerial photography 2009. XY

Asset/Event Number	753
Asset/Event Name	Enclosure, Langwell
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	309466
Northing	922154
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A turf and stone dyke under bracken forms a square-shaped enclosure measuring c11m by 11m. Not depicted on historic mapping.

Asset/Event Number	754
Asset/Event Name	Rig and furrow, Langwell
Type of Asset/Event	Rig and furrow

Date and/or Period	Post-medieval
Listing No./NRHE Number	ND02SE 40
HER Number	MHG28687
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	309626
Northing	922312
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of rig and furrow c110m by 30m faintly visible below bracken and grass along a terrace above the Langwell Water.

Asset/Event Number	755
Asset/Event Name	Building, Langwell
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG39806
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	309762
Northing	922336
Council	Highland
Condition:	Very degraded
Alignment:	WNW/ESE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Very ephemeral footings for a rectangular building under grass, truncated on the WNW end by the existing track. Visible extent measures c20m by c5.5m. Not depicted on historic mapping. Https://her.highland.gov.uk/Monument/MHG39806 Langwell Tulloch broch (see MHG1508) was visited by Headland Archaeology in 1998 in the course of a pre-afforestation survey. A large stone and turf enclosure, extending north from the outer broch enclosure was recorded in addition to the broch remains previously noted. <1> On 2009 AP evidence this enclosure (although the northern section as recorded in <1> is not evident) appears to be associated with the remains of a long rectangular building immediately on the north side of the trackway that passes the broch. This building, apparently not seen during the 1998 survey, has been truncated by the trackway and appears to be similar in size to others in the area. Together with the enclosure it probably formed a small farmstead. <2> The GIS spatial data was amended in 2018 according to its position as seen on the 2009 Aps <1> SHG27187 Text/Report/Fieldwork Report: Colm Moloney & Louise Baker. 1998. Forestry

Survey - Langwell, Berriedale, Caithness. Headland Archaeology. Digital (scanned as PDF). Area 3 Site 17 Addendum.
<2> SHG27382 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 2009. Getmapping aerial photography 2009. XY

Asset/Event Number	756
Asset/Event Name	Dyke, Langwell
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG39806
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	309794
Northing	922356
Council	Highland
Condition:	Very degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Lengths of curvilinear stone and turf dyke under grass, (W: c150m in length, E: c100m in length) very ephemeral and not easily identified in the field but apparent in satellite imagery. The dykes stand to a height of c0.2m with intermittent boulders c0.4m long. For HER asset description see Asset 755.

Asset/Event Number	757
Asset/Event Name	Peat cutting, Langwell
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	309837
Northing	922566
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Area of peat cutting under heather, c9m by 9m and banks 0.3m deep.

Asset/Event Number	758
Asset/Event Name	Quarry, Langwell
Type of Asset/Event	Quarry
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	309933
Northing	922590
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Subcircular cut into hillside, likely for a quarry, c19m by 14m.

Asset/Event Number	759
Asset/Event Name	Possible hut circle, Langwell
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	310166
Northing	922926
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible hut circle under heather, subcircular in plan and measures c7m by 5m with central depression.

Asset/Event Number	760
Asset/Event Name	Quarry, Langwell
Type of Asset/Event	Quarry
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A

HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	310464
Northing	923208
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of quarrying under grass, measures c20m x 20m and c3m deep.

Asset/Event Number	761
Asset/Event Name	Dyke, Langwell
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	310205
Northing	922815
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Several boulders in a line, possibly a small segment of turf and stone dyke with turf eroded. Not depicted on historic mapping.

Asset/Event Number	762
Asset/Event Name	Earthwork, Langwell
Type of Asset/Event	Earthwork
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	310517
Northing	923250

Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Possible earthwork bank under thick gorse, difficult to determine extent but c15m long and spread up to 3m wide and likely continues below gorse to S. not depicted on historic mapping.

Asset/Event Number	763
Asset/Event Name	Souterrain, Rinsary
Type of Asset/Event	Souterrain
Date and/or Period	Prehistoric
Listing No./NRHE Number	ND12SW 22
HER Number	MHG2544
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	310740
Northing	923270
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A souterrain is recorded as having been located here but removed. No upstanding remains associated with it were observed during the walkover survey. Https://her.highland.gov.uk/monument/MHG2544 Pict's House (NR) (site of) OS 6" map, Caithness, 1st ed., (1871) 'A Pictish dwelling stood here, but on improvement of the land it was totally removed; the spot, however, on which it stood may be distinguished from the appearance of its soil which is of a sandy nature.' Name Book 1871. The site falls in a field. There is no trace of any structure here. Visited by OS (J M) 23 November 1982. 1st Edition OS 6" <2> --- SHG3345 Text/Publication/Volume: Name Book (County). Object Name Books of the Ordnance Survey. Book No. 15, 124. <2> SHG23892 Image/Map: Ordnance Survey. 1876-77. Ordnance Survey 1st edition 6 inch map: Caithness (surveyed 1870-73). Digital.

Asset/Event Number	764
Asset/Event Name	Rig and furrow, Rinsary
Type of Asset/Event	Rig and furrow
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND12SW 73

HER Number	MHG29210
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	310767
Northing	923363
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of rig and furrow c90m by 90m extends down a gentle N-facing slope above the Berriedale Water. This could not be visibly discerned during the walkover survey but the NW/SE aligned rig and furrow shows up well on Bing satellite imagery. Https://her.highland.gov.uk/monument/MHG29210 An area of rig, lying on a NE-facing slope above a steep drop down to the Berriedale Water, was recorded during a pre-afforestation survey of Langwell-Rinsary Braes, Berriedale. The rig, which measures 5m in width, runs under the drystone dyke at its S end but is not visible in the improved ground to the S. S Carter and J Rideout (Headland Archaeology) 3 March 1999; NMRS MS 899/141, no.6 <1> NGR adjusted based on 1999-2001 vertical aerial photographs. <2> <1> SHG2829 Text/Report/Fieldwork Report: Carter, S. & Rideout, J.. 1999. Forestry Survey: Langwell - Rinsary Braes, Berriedale, Caithness. Headland Archaeology. 03/03/1999. Paper and Digital. No.6. <2> SHG27491 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 1999-2001. Get Mapping colour vertical aerial photography 1999-2001 (The Millennium Map). XY

Asset/Event Number	765
Asset/Event Name	Enclosure, Rinsary
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	310610
Northing	923238
Council	Highland
Condition:	Good
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke forms a parallelogram-shaped enclosure 290m by 145m. The dyke stands 1.3m tall and 0.8m at base, tapering to 0.4m at the top. Depicted on the 1st edition OS map. OS. 1877. Caithness XLII, Surveyed: 1871, Published: 1877.

Asset/Event Number	766
Asset/Event Name	Clearance cairn, Rinsary
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	310644
Northing	923367
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn of medium and large stones under grass with tree growing through S side, measures 6m by 4m.

Asset/Event Number	767
Asset/Event Name	Clearance cairn, Rinsary
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	311330
Northing	924005
Council	Highland
Condition:	Very degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn under heather, measuring c10m in diameter and c0.1m in height. Stone is loosely spread across slope.

Asset/Event Number	768
Asset/Event Name	Peat cutting, Beinn nan Coireag
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval

Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	312009
Northing	924650
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Area of peat cutting under heather, measuring c8m x c15m. Dis-used.

Asset/Event Number	769
Asset/Event Name	Peat cutting, Beinn nan Coireag
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	311862
Northing	924714
Council	Highland
Condition:	Fair
Alignment:	WNW/ESE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Area of peat cutting under heather, measuring c45m x c35m and 1m deep, L-shaped. Dis-used.

Asset/Event Number	770
Asset/Event Name	Shieling, Beinn nan Coireag
Type of Asset/Event	Shieling
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	312116

Northing	924828
Council	Highland
Condition:	Ruinous
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Possible structure under heather, circular in plan and defined by a c3.5m in diameter hollow, surrounded by earth banks c0.4m tall and perhaps c1m wide. No discernible entrance. Possible shieling. Not depicted on historic mapping.

Asset/Event Number	771
Asset/Event Name	Hut circle, Longall
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	312908
Northing	926529
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Possible hut circle under heather, c10m diameter with raised bank up to 1.5m wide and 0.4m tall and depressed centred.

Asset/Event Number	772
Asset/Event Name	Boundary stone, Longall
Type of Asset/Event	Boundary stone
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG13507
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	312690
Northing	926297
Council	Highland
Condition:	Fair

Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Solitary stone, c0.8m tall with no nearby features. Https://her.highland.gov.uk/monument/MHG13507 No description.

Asset/Event Number	773
Asset/Event Name	Peat cutting, Longall
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	312503
Northing	926230
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under heather, measuring c25m by 25m and banks 0.3m deep.

Asset/Event Number	774
Asset/Event Name	Peat cutting, Longall
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	312397
Northing	925982
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under heather, measuring c175m by 150m and banks 0.3m deep.

Asset/Event Number	775
Asset/Event Name	Spring, Longall
Type of Asset/Event	Spring
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	MHG13506
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	312570
Northing	926150
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A spring is identified on the HER in this locale but nothing was identified during the walkover survey. Https://her.highland.gov.uk/monument/MHG13506 No description.

Asset/Event Number	776
Asset/Event Name	Settlement, Knockanruah
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND15NE 23
HER Number	MHG19157
Status	Non-designated Heritage Asset
Section:	A1.1
Easting	316176
Northing	956952
Council	Highland
Condition:	Unknown
Alignment:	Various
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. On the HER a settlement is recorded here. At the time of the walkover survey the land surrounding the asset had recently been ploughed and sown with seed so access to it was not attempted. The polygon has been drawn from satellite imagery as an extent of uncultivated ground and measures 90m by 45m. Depicted on the 1st edition OS map as a farmstead named Knockraha, comprising a roofed building with adjacent enclosures and a well, the 2nd edition OS map shows it as roofless.

OS. 1877. Caithness XVIII Surveyed: 1871, Published: 1877.
OS. 1907. Caithness XVIII Surveyed: 1905, Published: 1907.

https://her.highland.gov.uk/Monument/MHG19157
Longhouse (ND 1620 5695). Dimensions: 28 x 6m. Rectangular structure defined by grass and reed covered banks 0.45m high. It was apparently divided into five units and is associated with an enclosure 28 x 35m, to the W. Orientation NNE-SSW.
R J Mercer, NMRS MS/828/29, 1995
A farmstead comprising one partially roofed long building and one unroofed building attached to an enclosure, is depicted on the 1st edition of the 6-inch map (Caithness 1877, sheet xviii). One unroofed building and an enclosure are shown on the current edition of the OS 1:10560 map (1971).
Information from RCAHMS (SAH) 6 December 1995

Asset/Event Number	777
Asset/Event Name	Sheepfold, Knockanruah
Type of Asset/Event	Sheepfold
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG33110
Status	Non-designated Heritage Asset
Section:	A1.1
Easting	316112
Northing	956850
Council	Highland
Condition:	Good
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A circular drystone sheepfold measuring 18m in diameter over walls, with the entrance in the SW side. The fold has collapsed in some parts, surviving to height of 1.4m at its tallest point. Constructed from shaped and stacked Caithness flagstones, the walls are 0.7m thick. The entrance is slightly splayed, standing 1m tall and 1.3m wide. The sheepfold is labelled and depicted on the 1st edition OS map. OS. 1877. Caithness XVIII Surveyed: 1871, Published: 1877. https://her.highland.gov.uk/Monument/MHG33110 A 'Sheepfold' is depicted on the OS 1st Edition Map.

Asset/Event Number	778
Asset/Event Name	Boundary ditch, Achalone
Type of Asset/Event	Boundary ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset

Section:	A1.1
Easting	316037
Northing	956659
Council	Highland
Condition:	Fair
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A boundary ditch under grass, measuring 3m wide and 1m deep and likely also used for drainage. Has an associated degraded stone and turf dyke running parallelly with on the N side, standing 0.3m tall, spread up to 2m wide. Recorded extent measures c740m long but asset continues outwith survey corridor to the SW. Depicted on the 1st edition OS map. OS. 1877. Caithness XVIII Surveyed: 1871, Published: 1877.

Asset/Event Number	779
Asset/Event Name	Boundary dyke, Banniskirk
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1
Easting	316505
Northing	956376
Council	Highland
Condition:	Good
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A flagstone dyke, standing 1.2m tall with larger stones used as gate posts at gated entrances; the dyke extends beyond the survey corridor to the SW and SE. Forms rectilinear enclosures. Ditch up to 3m wide and 1.2m deep under grass runs externally to it. Depicted on the 1st edition OS map. OS. 1877. Caithness XVIII Surveyed: 1871, Published: 1877.

Asset/Event Number	780
Asset/Event Name	Boundary dyke, Banniskirk
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1

Easting	316966
Northing	956252
Council	Highland
Condition:	Fair
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke, as opposed to the flagstone dyke (Asset 779) to the immediate W. This dyke stands 1.2m tall, 0.8m at base, 0.4m at top, recorded extent measures c380m but asset continues outwith survey corridor to the NW. Depicted on the 1st edition OS map. OS. 1877. Caithness XVIII Surveyed: 1871, Published: 1877.

Asset/Event Number	781
Asset/Event Name	Possible structure, Cnoc Reile
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	316705
Northing	934663
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small hollow defined by a shallow depression surrounded by a low bank under grass measuring 4m by 2m. Possibly a small shieling or similar. Not depicted on historic mapping.

Asset/Event Number	782
Asset/Event Name	Flood bank, Auchtabannock
Type of Asset/Event	Other
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	247236
Northing	854213
Council	Highland

Condition:	Fair
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A linear earthwork extending along the S side of the River Conon E of Auchtabannock. The embankment is generally concealed below vegetation Large linear bank under dense vegetation, forming a flood defence on the S side of the River Conon. Dimensions difficult to discern due to the vegetation, but likely substantial. Recorded extent spans the survey corridor but continues outwith it the E and W. Depicted on the 1st and 2nd edition OS maps. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXXVII, Surveyed: 1876, Published: 1881 OS. 1907. Ross and Cromarty LXXXVII, Surveyed: 1902, Published: 1907

Asset/Event Number	783
Asset/Event Name	Structure, Allt na Criche
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG62153
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	245733
Northing	845838
Council	Highland
Condition:	Very degraded
Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A structure revetted into hill slope, under tall heather and grass. Curvilinear and c9m by 6m over banks which stand up to 0.4m tall, open to the W towards a stream. Probably still bothy as described below. Https://her.highland.gov.uk/monument/MHG62153 The North of Scotland Archaeological Society (NoSAS) undertook an archaeological survey of Urchany in 2015. Site B07; A still bothy or shieling hut. At the northern end of a small heather-and-bracken covered area of open flat ground are the well-preserved low remains of a turf covered stone and turf building. It lies 3m from the Allt na Criche on its east bank, cut slightly into the bank. All four walls survive. The back retaining wall is single faced, whereas the two gables and west wall are double faced, now well covered with rank heather, fine grasses, moss and bracken. This low rectangular building, 7m NW-SE x 2.5m NE-SW internal dimensions, has an entrance in the SW corner of the west front wall. The walls are c.0.75m wide and up to 0.5m high. The front wall is a little lower than the two gable walls. It is likely to be a still bothy, although the open aspect might also suggest a sheiling hut. <1> NGR adjusted based on 2015 aerial photographs. <2> <1> SHG28596 Text/Report/Fieldwork Report: Spencer-Jones, R.. 2020. A NoSAS Survey of the Lands of Urchany: A Multi-period Settlement on the Braes West of Beauly: 6th-10th April 2015. North of Scotland Archaeological Society. Digital. P.50,53 Site B07, figures 141,152-154. XY <2> SHG27328 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 2015. Getmapping aerial photography 2015.

Asset/Event Number	784
Asset/Event Name	Track, Breakachy
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	245271
Northing	844273
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A relict track under grass, measures 2.5m wide, extending E/W across the survey corridor and continuing outwith it in the same directions. The track leads from Beakachy farm to the E up to the hills to the W, including to an area of old peat cutting (Asset 1001), and so may also be an old peat road. Depicted on the 1st edition maps. OS. Inverness-shire Mainland IX, Surveyed: 1873, Published: 1876. OS. Inverness-shire M(mainland) X, Surveyed: 1872, Published: 1876.

Asset/Event Number	785
Asset/Event Name	Shieling, Strath Sgitheach
Type of Asset/Event	Shieling
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG62707
Status	Non-designated Heritage Asset
Section:	
Easting	252421
Northing	863177
Council	Highland
Condition:	Degraded
Alignment:	Unknown
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Asset not identified during walkover survey. Https://her.highland.gov.uk/monument/MHG62707 A number of settlement features are visible across this area on an aerial photograph taken

by Jim Bone in 2010. <1>
The Strath Sgitheach area was surveyed by Meryl Marshall in 2020.
Strath Sgitheach Post Medieval sites.
Shieling (SS10) – this oval structure on the summit of a grassy knoll is on a NW-SE alignment and measures 5m x 3m overall. The footings are of stone and turf and quite low but distinct. <2>
NGR adjusted based on 2018 aerial photographs. <3>

Asset/Event Number	786
Asset/Event Name	Shieling, Strath Sgitheach
Type of Asset/Event	Shieling
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG62700
Status	Non-designated Heritage Asset
Section:	
Easting	252382
Northing	863191
Council	Highland
Condition:	Very degraded
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Asset not identified during walkover survey. Https://her.highland.gov.uk/monument/MHG62700 A number of settlement features are visible across this area on an aerial photograph taken by Jim Bone in 2010. <1> The Strath Sgitheach area was surveyed by Meryl Marshall in 2020. Strath Sgitheach Post Medieval sites. Farmstead - building/?farmstead/?inn (SS9) – this rectangular building is barely discernible and defined as much by the changes in vegetation as its slopes. It is on an E-W alignment, measures 9mx3m internally and has distinct rounded ends. The surrounding banks are covered in heathery turf and are up to 0.3m height x 1m spread those on the south side more evident. Internal ground cover is coarse grass and moss. There is a possible entrance at the east end. <2> NGR adjusted based on 2009 aerial photographs. <3> <1> SHG24870 Image/Photograph(s)/Aerial Photograph/Oblique: Bone, J. 01/2010. Strath Sgitheach NH 526 634. Colour. . Digital. <2> SHG29225 Text/Correspondence: Marshall, M.. 2020. Walkover survey at Strath Sgitheach by NOSAS. North of Scotland Archaeology Society (NOSAS). Yes. Digital. XY <3> SHG27382 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 2009. Getmapping aerial photography 2009.

Asset/Event Number	787
Asset/Event Name	Hut circle or cairn, Carbisdale Wood
Type of Asset/Event	Unknown

Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	MHG62766
Status	Non-designated Heritage Asset
Section:	C1.2
Easting	256370
Northing	895311
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Asset not definitively identified during the walkover survey - the area is under dense commercial forestry plantation and the point is indicative only. Visible on LiDAR imagery. Https://her.highland.gov.uk/monument/MHG62766 A possible hut circle or cairn in Carbisdale Wood. The feature is visible in SEPA LiDAR data. It is approximately 10m in diameter and appears to be on a slope. <1>

Asset/Event Number	788
Asset/Event Name	Shieling, Invershin
Type of Asset/Event	Shieling
Date and/or Period	Post Medieval
Listing No./NRHE Number	NH59NE 33
HER Number	MHG12904
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	257800
Northing	896500
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Previously recorded shielings and field clearance located in what is now fairly dense birch woodland. These assets were not identified during the walkover survey due to the vegetation. Https://her.highland.gov.uk/monument/MHG12904 NH59NE 33 578 965. A group of shielings, one, at NH 5784 9651, measures 7.5m by 3m and, has a possible kiln in the SW side. Several similar shielings surround it. A possible shieling, sub rectangular, 7m by 3m defined by mounds and stones, lies at NH 5786 9652; and a group of five possible shielings, 6m by 3m on average, occupy a grassy platform at NH 5789 9652. R J Mercer 1980. Early modern field clearance heaps. The alleged kiln is disturbance in the side of one of them.

Visited by OS 12 June 1981.

Asset/Event Number	789
Asset/Event Name	Battle Site, Blar Na Pairce
Type of Asset/Event	Battlefield
Date and/or Period	Medieval
Listing No./NRHE Number	NH45NE 8
HER Number	MHG6284
Status	Non-designated Heritage Asset
Section:	
Easting	247320
Northing	856900
Council	Highland
Condition:	Unknown
Alignment:	N/A
Importance:	Low/Medium
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Possible location of a battlefield within arable fields - no upstanding remains are visible. Https://her.highland.gov.uk/monument/MHG6284 Blar na Pairce. Site of conflict between Macdonalds and MacKenzies about AD1490 {NAT} OS 6"map, Ross-shire, 2nd ed., 1907 Macdonalds fought MacKenzies at battle of the Park near Loch Kinellan, between 1485 and 1491. H A Fraser 1917 <1> No further information Visited by OS (R L) 16 November 1970 A metal detecting survey, to the W of the possible battle site, recorded no finds associated with the battle. This field is now very boggy, and the battle is likely to have been confined to the areas of drier ground. However, it is possible artefacts associated with the battle could have ended up in the bog rather than being recovered, but these may have been too deep for metal detector detection. As part of the survey, desk-based research was conducted. David Alston, in Ross and Cromarty: a Historical Guide (1999) states: Blair na Pairc 1491. Possibly near Dingwall. Defeat of Alexander MacDonald of Lochalsh In 1491 Alexander MacDonald of Lochalsh led a raid into Easter Ross and, along with Farquhar, son of the MacIntosh chief, seized the castle of Inverness before being defeated at Blair na Pairc, possibly near Dingwall. There is a more detailed account of the battle by James Brown in his A History of the Highlands and of the Highland Clans (1837) Gillespoc, cousin of the Lord of the Isles, at the head of a large body of the islanders, invaded the higher part of Ross, and committed great devastation. The inhabitants, or as many as the shortness of the time would permit, amongst whom the Calnkenzie were chiefly distinguished, speedily assembled, and met the islanders on the banks of the Connan, where a sharp conflict took place. The Clankenzie fought with great valour, and pressed the

enemy so hard, that Gillespoc MacDonald was overthrown, and the greater part of his men were slain or drowned in the river about two miles from Braile, thence called Blar-na-Pairc…..It is reported that, before the skirmish, the Clandonald robbed and burned a chapel near the river Connan, not far from the place they fought

If there is any truth in this account, the only candidates to be the chapel burned by the MacDonalds would be Contin parish church, known to have been in use in 1490, or Praes Mairi, a private burial ground associated with St Maelrubha which may have been the site of an early chapel. Both of these are near to the Blackwater rather than the Conon, but are both only 2km from the recorded site of Blar na Pairc. The details given in this account would suggest that the actual battle took place on a river bank. <2>
<1> SHG951 Text/Publication/Article: Fraser, H A. 1917. 'Investigation of the artificial island in Loch Kinellan, Strathpeffer', Proc Soc Antiq Scot Vol. 51 1916-17, p.48-98. Proc Soc Antiq Scot. 48-98. 51.
<2> SHG23351 Text/Report/Fieldwork Report: Dagg, C. Metal Detecting Survey and Watching Brief at Kinellan Farm, Strathpeffer. . Digital.

Asset/Event Number	790
Asset/Event Name	Enclosure, Kinnahaird
Type of Asset/Event	Enclosure
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	MHG14111
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	246500
Northing	855300
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A cropmark is recorded in this location; no upstanding features are visible. Https://her.highland.gov.uk/monument/MHG14111 No upstanding remains. 'a circular enclosure in the form of a cropmark, roughly 20m in diameter in green corn.' Wordsworth 1992 (Recorded on the HER pdf attached to the record)

Asset/Event Number	791
Asset/Event Name	Roman Coin - Contin
Type of Asset/Event	Findspot
Date and/or Period	Roman
Listing No./NRHE Number	N/A
HER Number	MHG60682
Status	Non-designated Heritage Asset

Section:	
Easting	246000
Northing	855000
Council	Highland
Condition:	Good
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Findspot; no upstanding remains. Https://her.highland.gov.uk/monument/MHG60682 A Roman copper alloy coin discovered during metal detecting was submitted to TT (TT 14/19). It was worn but complete. The condition of the coin is poor, with only part of the bust visible on the obverse and the legs of the horse on the reverse resulting in a tentative type identification: Obv. […] E…M […] Bust of Trajan, r., very worn but possibly laureate. Rev. S - C in exergue. Horse, r, with front legs off the ground, with a rider (Trajan?). It was allocated to Inverness Museum but this needs confirming. See attached TT report for photo. <1> <2> Four figure grid reference given is marginal. A more precise GR is held by Treasure Trove. GW 02/07/20 <1> SHG28208 Dataset/Database File: Treasure Trove. 2019. Highland Finds from Treasure Trove Annual Reports 2004-18. Treasure Trove. Digital. TT 14/19. XY <2> SHG28370 Text/Record Form: Treasure Trove. 2019. Treasure Trove Artefact Reports for Highland Area 1994-2018. Treasure Trove. Digital. TT 14/19.

Asset/Event Number	792
Asset/Event Name	Enclosure or shelter - Allt na Criche, Urchany
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	
HER Number	MHG62143
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	246139
Northing	846330
Council	Highland
Condition:	Unknown
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Asset within tall bracken and not identified during the walkover survey. Https://her.highland.gov.uk/monument/MHG62143 The North of Scotland Archaeological Society (NoSAS) undertook an archaeological survey of Urchany in 2015. Site B08; Enclosure or simple shelter. The tumbled remains of an approximately square building are set at the foot of a steep slope with cliffs immediately above, to the north.

Below and to the south is a strip of south-facing improved grazing. The walls are roughly built with large stones & boulders, remaining to 1m high. A large boulder at NE forms part of the structure. The 1m wide entrance is in the south. The stones of the walls are covered with moss whereas the sunken interior is covered with fine grass and bracken. This could be an animal enclosure, or a simple shelter. <1>
NGR adjusted based on 2009 aerial photographs. <2>
<1> SHG28596 Text/Report/Fieldwork Report: Spencer-Jones, R.. 2020. A NoSAS Survey of the Lands of Urchany: A Multi-period Settlement on the Braes West of Beauly: 6th-10th April 2015. North of Scotland Archaeological Society. Digital. P.46, 47, site B08, figures 129-131. XY
<2> SHG27382 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 2009. Getmapping aerial photography 2009.

Asset/Event Number	793
Asset/Event Name	Cairn - Allt na Criche, Urchany
Type of Asset/Event	Clearance cairn? Cairn?
Date and/or Period	Unknown
Listing No./NRHE Number	
HER Number	MHG62142
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	246168
Northing	846287
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Asset within tall bracken and not identified during the walkover survey. Https://her.highland.gov.uk/monument/MHG62142 The North of Scotland Archaeological Society (NoSAS) undertook an archaeological survey of Urchany in 2015 and surveyed some structures north of the Allt na Criche. The field surveyors identified four cairns in this higher ground. They suggested they might all be prehistoric burial cairns, due to their position above the improved grazing ground. However, this can only be conjectural. The improved pasture may well have been ploughed at some stage, producing clearance cairns not burial cairns. Site C25; Cairn. This oval pile of large stones and boulders, 8m x 3.5m, stands up to 1.0m high. <1> NGR adjusted based on 2015 aerial photographs. <2> <1> SHG28596 Text/Report/Fieldwork Report: Spencer-Jones, R.. 2020. A NoSAS Survey of the Lands of Urchany: A Multi-period Settlement on the Braes West of Beauly: 6th-10th April 2015. North of Scotland Archaeological Society. Digital. P.46, site C25. XY <2> SHG27328 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 2015. Getmapping aerial photography 2015.

Asset/Event Number	794
Asset/Event Name	Cairn - Allt na Criche, Urchany

Type of Asset/Event	Clearance cairn? Cairn?
Date and/or Period	Unknown
Listing No./NRHE Number	
HER Number	MHG62141
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	246148
Northing	846265
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Asset within tall bracken and not identified during the walkover survey. Https://her.highland.gov.uk/monument/MHG62141 The North of Scotland Archaeological Society (NoSAS) undertook an archaeological survey of Urchany in 2015 and surveyed some structures north of the Allt na Criche. The field surveyors identified four cairns in this higher ground. They suggested they might all be prehistoric burial cairns, due to their position above the improved grazing ground. However, this can only be conjectural. The improved pasture may well have been ploughed at some stage, producing clearance cairns not burial cairns. Site C24; Cairn. This circular pile of large stones and boulders, 4m diameter, stands up to 0.5m high. <1> NGR adjusted based on 2015 aerial photographs. <2> <1> SHG28596 Text/Report/Fieldwork Report: Spencer-Jones, R.. 2020. A NoSAS Survey of the Lands of Urchany: A Multi-period Settlement on the Braes West of Beauly: 6th-10th April 2015. North of Scotland Archaeological Society. Digital. P.46, site C24. XY <2> SHG27328 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 2015. Getmapping aerial photography 2015.

Asset/Event Number	795
Asset/Event Name	Dyke, Tiadh Allt
Type of Asset/Event	Dyke
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	247711
Northing	860659
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Grass and felled wood covered dyke, measuring c1m tall and spread up to 2m wide, c200 m long and extending along south side of existing forestry track and likely contemporary with its construction. The asset is not depicted on historic maps.

Asset/Event Number	795.1
Asset/Event Name	House, Ardochy
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.2 (in access track corridor to section)
Easting	246275
Northing	843867
Council	Highland
Condition:	Good
Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A two-storey farm house measuring c20m by 7m and associated with the farmstead of Ardochy. The farmstead is in active use and the house was not directly approached. During the walkover survey. Depicted on 1st edition OS map. OS. 1876. Inverness-shire (Mainland) X, Surveyed: 1872, Published: 1876

Asset/Event Number	795.2
Asset/Event Name	Steading, Ardochy
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.2 (in access track corridor to section)
Easting	246245
Northing	843868
Council	Highland
Condition:	Good
Alignment:	Various
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A single-storey L-shaped steading measuring c17m by 5m on the NE/SW arm, and 25m by 5m on the NW/SE arm. Roofed with corrugated iron sheets on a pitched roof, and accesses in the NE and SE

elevations. Part of the active Ardochy farmstead and not closely inspected. Depicted on the 1st edition OS map.
OS. 1876. Inverness-shire (Mainland) X, Surveyed: 1872, Published: 1876

Asset/Event Number	795.3
Asset/Event Name	Building, Ardochy
Type of Asset/Event	Building
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.2 (in access track corridor to section)
Easting	246256
Northing	843882
Council	Highland
Condition:	Good
Alignment:	NNE/SSW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A single-storey shed building measuring 7m by 4m over walls which have been harled. Entrance in the N elevation. Forms part of the Ardochy farmstead but a later addition to the extant buildings Assets 795.1 and 795.2 as does not appear on the historic maps.

Asset/Event Number	796
Asset/Event Name	Dyke, Lon a' Ghlinne
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	NA
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246490
Northing	861157
Council	Highland
Condition:	Fair
Alignment:	NE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass, Stands 0.75m tall and spread up to 1.5m wide, extending c16m long. Possibly remnants of an enclosure truncated by modern commercial forestry operations. Not depicted on historic maps.

Asset/Event Number	798
Asset/Event Name	Enclosure, Glensgaich
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245679
Northing	860822
Council	Highland
Condition:	Fair
Alignment:	Circular
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An irregular shaped enclosure measuring c100m by 90m, truncated by track and forestry plantation to the NW. Enclosure composed of a drystone dyke standing 1m tall and spread up to 1.5m wide and c200m long. Depicted on 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXV, Surveyed: 1875, Published: 1881

Asset/Event Number	799
Asset/Event Name	Marker cairn, Allt Strath Lunndaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval/Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	277134
Northing	902272
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A pronounced small mound of stone under heather measuring 3m by 2m and standing 0.3m tall, located on open peat lands and unlikely to be field clearance, so potentially a navigation or marker cairn, or even a deer lick. Not depicted on historic maps.

Asset/Event Number	800
Asset/Event Name	Dyke, Glen Sletdale
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293298
Northing	912885
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke and grass and heather, standing 0.8m tall and spread up to 3m wide. Continued on the N side of modern track in part by Asset 453.Recorded extent measures c140m but it continues outwith corridor to S. Depicted on the 1st edition OS map. OS. 1879. Sutherland LXXXIX, Surveyed: 1871, Published: 1879

Asset/Event Number	801
Asset/Event Name	Mound, Glen Sletdale
Type of Asset/Event	Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293093
Northing	912768
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A pronounced mound under heather. The mound is somewhat elongated in plan and measures c23m by c19m and c3m tall, and while it appears natural, several boulders up to 1.5m long have been set at its base. The mound is located on a terrace above the Sletdale, though not intervisible, and had excellent long ranging views up Glen Sletdale and down to Craikie area. Intervisible with prehistoric settlement Asset 119 and others. Possibly augmented.

Asset/Event Number	802

Asset/Event Name	Hut circle, Glen Sletdale
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293045
Northing	912690
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under grass and heather, c16m in diameter and with banks that stand 0.8m tall and are spread up to 2.5m wide but reduced in some parts very low. Possible entrance in the S side. Not included within the HER extents for the nearby hut circles to the northwest (MHG10027; MHG10048).

Asset/Event Number	803
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	
Northing	
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	VOID - number not assigned.

Asset/Event Number	805
Asset/Event Name	Quarry, Upper Borgue
Type of Asset/Event	Quarry
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	A1.4
Easting	312796
Northing	926750
Council	Highland
Condition:	Fair
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rock quarry cut into the N side of a small slope, some bare rock showing, and partly now infilled with modern rubbish. Measures 19m wide by 10m deep and 7m tall. Not depicted on historic maps.

Asset/Event Number	806
Asset/Event Name	Clearance, Upper Borgue
Type of Asset/Event	Clearance cairn
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	312826
Northing	926765
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large spread of field clearance stone and modern detritus under nettles and grass, c60m by 18m. Spread around quarry Asset 805 and may represent later clearance, but could also have post-medieval clearance under the modern detritus. Stands 1m tall in parts. Not depicted on historic maps.

Asset/Event Number	807
Asset/Event Name	Earthwork, Upper Borgue
Type of Asset/Event	Earthwork
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	312863

Northing	926835
Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A bund of gravel and soil partially under grass measuring c50m by 8m and standing 0.7m tall. Appears modern in date.

Asset/Event Number	808.1
Asset/Event Name	Peat cutting, Upper Borgue
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	312883
Northing	926861
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Peat cutting cut into N facing slight slope and under heather and grass, c200m by 90m and 0.3m deep at the edge of the surveyed line. No fresh cutting but seems more pronounced at the S end and very tapered at the N end.

Asset/Event Number	808.2
Asset/Event Name	Peat cutting, Upper Borgue
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	312912
Northing	926851
Council	Highland
Condition:	Degraded
Alignment:	NE/SW

Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat cutting under heather and grass 21m long by 3.5m wide and 0.3m deep. Post-medieval or modern.

Asset/Event Number	808.3
Asset/Event Name	Peat cutting, Upper Borgue
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	312819
Northing	927707
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under heather, measuring c120m by 80m and continuing beyond survey area to E, banks are c0.3-0.5m deep.

Asset/Event Number	809
Asset/Event Name	Findspot, Upper Borgue
Type of Asset/Event	Findspot
Date and/or Period	Prehistoric
Listing No./NRHE Number	
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	312737
Northing	927087
Council	Highland
Condition:	Good
Alignment:	N/A
Importance:	Neglible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A carved stone lamp (SF01), likely Iron Age in date considering the proximity (c275 E of Borgue broch (Asset 50/SM6014) was identified during the walkover survey in a stream/drain. The stream/drain was surveyed 20m either side of the findspot to check for other artefacts but no additional finds were identified. Surrounds under tall reeds, and the lamp has likely naturally rolled down the waterway over time. A separate specialist small finds report has been produced.

Asset/Event Number	810
Asset/Event Name	Possible peat stack, Upper Borgue
Type of Asset/Event	Other
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	312726
Northing	927789
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An oval shaped mound under heather, measuring 8.5m by 5m and standing 0.7m tall. Located within an area of peat cutting (Asset 808.3), and may represent either a small island of un-excavated peat formed by peat cutting on all sides, or a degraded peat stack.

Asset/Event Number	811
Asset/Event Name	Peat cutting, Upper Borgue
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	312665
Northing	927885
Council	Highland
Condition:	Degraded
Alignment:	NNE/SSW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under heather and grass measuring 90m by 70m and up to 0.8m deep.

Asset/Event Number	812
Asset/Event Name	Peat bank, An Droichneach

Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	273191
Northing	899976
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Area of peat cutting where the edge of the Strath has been cut into to the SW along a bank c80m long. Under heather and grass and banks are 0.3m deep. Peters out to the NE.

Asset/Event Number	813
Asset/Event Name	Track, An Droichneach
Type of Asset/Event	Track
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	273408
Northing	900271
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An 8m-wide track cut into the hill side with banded banks either side 0.6m tall, under heather and grass. Extends outwith the survey corridor to the NW and SE. Modern.

Asset/Event Number	814
Asset/Event Name	Dyke, Eiden
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	B1.2
Easting	273804
Northing	900582
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass, revetted into the N-facing slope. Stands c0.8m tall on the S/roadside and c1.2m tall on the sloping N side. Spread up to 6m wide where stone has slipped down slope. Extends outwith the survey corridor to the NW and SE. Depicted on the 1st and 2nd edition OS maps. OS. 1879. Sutherland CIV, Surveyed: 1873-4, Published: 1907 OS. 1907. Sutherland CIV, Surveyed: 1904, Published: 1907

Asset/Event Number	815
Asset/Event Name	Enclosure, Eiden
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	273805
Northing	900598
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone and turf enclosure under grass, attached to stone and turf dyke Asset 814. Measures 35m by 15m, and stands to 0.5m tall. Slight curve towards E at W side of structure, where a building or pen is depicted on the 1st edition OS map but where nothing visible could be seen. Only the pen/building is depicted on the 1st edition OS map, and neither are depicted on the 2nd edition OS map. OS. 1879. Sutherland CIV, Surveyed: 1873-4, Published: 1907 OS. 1907. Sutherland CIV, Surveyed: 1904, Published: 1907

Asset/Event Number	816.1
Asset/Event Name	Quarry, Langwell
Type of Asset/Event	Quarry
Date and/or Period	Post-medieval

Listing No./NRHE Number	ND02SE 21
HER Number	MHG39438
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	309803
Northing	922510
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Quarry pits cut into side of hill overgrown with bracken and heather. c15m in diameter and 1.5m in depth.

Asset/Event Number	816.2
Asset/Event Name	Quarry, Langwell
Type of Asset/Event	Quarry
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND02SE 21
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	309810
Northing	922495
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Circular quarry cut into side of hill overgrown with bracken and heather. c.5m in diameter and 1.2m in depth with exposed bedrock can be seen on east side of features.

Asset/Event Number	817
Asset/Event Name	Borrow pit, Langwell
Type of Asset/Event	Quarry
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	MHG39431
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	309745

Northing	922512
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A borrow pit measuring 7m by 10m and 1.3m deep under grass and at the E side, cut into the base of the W facing slope of a hill, and likely related to the construction of the adjacent track to the W. The HER polygon extends over this likely based on aerial imagery study as it appears similar in this view to the hut circles in the vicinity. The low position sheltered from the S would lend support to this. Https://her.highland.gov.uk/monument/MHG39431 [note that the description below relates to the three hut circles within the Asset 72/SM6014 extent, and the HER polygon has likely been extended E to cover the above asset based on satellite imagery analysis and not ground-proofing] Situated on rising ground are the remains of three large conjoined enclosures. 'A' measures 10.3m in diameter and is formed by a strong earth-and-stone bank some 3m broad and 1m high, and is scooped into the slope on N side. The entrance, 0.9m wide, is in the SE. There is evidence of internal structures, too obscured by bracken etc for survey. 'B' abuts on to the E side of 'A'. It measures 14m in diameter and is formed by a similar strong bank, and is also scooped into the slope on N side. No obvious entrance was noted. Inside this enclosure is a small earth-and-stone mound 3m in diameter and 0.7m high; there is also evidence of other internal structures too obscured by bracken etc for survey. A slight earth-and-stone bank forms a semicircular compartment, 4m E-W, which abuts on to S side; another earth-and-stone bank extends SE from the enclosure to terminate in a small rectangular enclosure, measuring 4 by 3m. 'C' abuts on to the S side of 'A' and measures 15m in diameter. Its construction is similar to the others; its entrance, 0.7m wide, is in NE. No internal features were noted. An earth-and-stone bank extends from the entrance of 'A' to join the bank of 'C' just below its entrance. There are traces of an oval enclosure a short distance SW of 'C'. Visited by OS (W D J) 15 June 1960. (ND 0965 2253) Enclosures (NR) OS 6" map, (1964) The three 'enclosures' discovered by F1 are three contiguous massive hut circles of Kilphedir II type (see NC91NE 25), now overgrown with bracken. They are set into a gentle SE-facing slope on the edge of an associated field system. Hut circle 'A' is 7.5m in diameter within a wall, 1m high, generally spread to 2.5m broadening to 3m at entrance, in SE. The entrance passage is defined by slabs on edge 0.8m apart. The inner wall face of boulders is visible intermittently. There is much stone debris within the hut suggestive of internal structures but no pattern is discernible. 'B' is 12m E-W by 10.5m transversely within a wall similar to that of 'A'. Again, much stone in the interior may indicate subdivisions, and there is a prominent mound of stones near the centre. There is no trace of an entrance. 'C' is the best preserved, 13.5m in diameter within a wall 1.3m in maximum height, spread to 2.5m. The inner wall face is exposed intermittently; at one point the face is 1.1m high, formed by large boulders, with rubble stones wedged in the interstices. The entrance is in S where the wall thickness is 3.5m. There is much debris in the interior. The various low walls and platforms around the hut circles are as planned by the previous OS field surveyor, and appear broadly contemporary; the absence of an entrance in 'B' and the upstanding nature of the structures may indicate re-use of the site at a much later date. The associated field system occupies four hectares of a SE-facing slope and comprises scattered clearance heaps and some traces of lynchets and field walls. Revised at 1:10,000. Visited by OS (N K B) 16 November 1982. The GIS spatial data was amended in 2018 according to the depiction on the old SMR 1:10,000 map. <1> A gently curving stretch of bank, extending downhill for about 100m was recorded to S of the hut-circles during a pre-afforestation survey by Headland Archaeology (NMRS MS 899/93, no.17). The bank is probably part of the field-system associated with the hut-circles. C Moloney and L Baker (Headland Archaeology) 13 July 1998; NMRS MS 899/93, no.17

Asset/Event Number	818
Asset/Event Name	Hut circle, Langwell
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	ND02SE 21
HER Number	MHG819
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	309781
Northing	922485
Council	Highland
Condition:	Ruinous
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under grass and moss, c13m in diameter. Banks are c1m wide and stand 0.3m tall, with stones visible. Internal diameter c9m. May occupy an artificial platform as it appears abnormally flat. Https://her.highland.gov.uk/monument/MHG819 On a shelf on a SW-facing hillslope, are the remains of a massive hut circle of Kilphedir II type (see NC91NE 25), now overgrown with heather and bracken. It has been robbed, some 6m having been totally removed from the SW arc, but it appears to have been circular, about 10m in diameter within a wall, 0.8m maximum height, spread to 3m. Some three or four boulders of the inner wall face are exposed. The entrance has been destroyed. Occupying 1.5 hectares of slope NE of the hut circle are about eighteen low, turf-covered clearance heaps which are probably contemporary with the hut. This area contains a number of recent surface quarries which superficially resemble hut circles set into the slope. Surveyed at 1:10,000. Visited by OS (N K B) 16 November 1982. GIS spatial data amended in 2018 according to location as seen on 2009 Aps. <1> <1> SHG27382 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 2009. Getmapping aerial photography 2009. XY

Asset/Event Number	819.1
Asset/Event Name	Clearance cairn, Langwell
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	ND02SE 21
HER Number	MHG39438
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	309833
Northing	922487
Council	Highland

Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under grass. Measures 9.5m by 6.5m and stands 0.5m tall. Https://her.highland.gov.uk/monument/MHG39438 On a shelf on a SW-facing hillslope, are the remains of a massive hut circle of Kilphedir II type (see NC91NE 25), now overgrown with heather and bracken. It has been robbed, some 6m having been totally removed from the SW arc, but it appears to have been circular, about 10m in diameter within a wall, 0.8m maximum height, spread to 3m. Some three or four boulders of the inner wall face are exposed. The entrance has been destroyed. Occupying 1.5 hectares of slope NE of the hut circle are about eighteen low, turf-covered clearance heaps which are probably contemporary with the hut. This area contains a number of recent surface quarries which superficially resemble hut circles set into the slope. Surveyed at 1:10,000. Visited by OS (N K B) 16 November 1982. GIS spatial data amended in 2018 to location to northeast of the hut circle.

Asset/Event Number	819.2
Asset/Event Name	Clearance cairn, Langwell
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	ND02SE 21
HER Number	MHG39438
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	309827
Northing	922465
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Moss and heather covered oblong clearance cairn. C.6m in length, 2.5m in width and 0.3m in height. Occasional stone (c.o.2m) visible on surface. For HER asset description see Asset 819.1.

Asset/Event Number	819.3
Asset/Event Name	Clearance cairn, Langwell
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	ND02SE 21
HER Number	MHG39438
Status	Non-designated Heritage Asset
Section:	A1.4

Easting	309842
Northing	922445
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass. Measures 5m diameter and stands 0.6m tall. For HER asset description see Asset 819.1.

Asset/Event Number	819.4
Asset/Event Name	Clearance cairn, Langwell
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	ND02SE 21
HER Number	MHG39438
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	309852
Northing	922434
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass. Measures 5m in diameter and stands 0.6m tall. For HER asset description see Asset 819.1.

Asset/Event Number	820
Asset/Event Name	Building, Sletdale Burn
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	292050
Northing	912443
Council	Highland
Condition:	Ruinous

Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone footings for a small building c5m by 5m over walls, situated at the base of a small slope overlooking the Sletdale burn to the S, with a possible twinning pen constructed in the NE corner. The walls stand 0.8m tall at their highest along the N side and are c0.5m wide, with a possible entrance in the SE side of the S elevation. A little too distant from the watercourse to be a still bothy, it may represent the remains of a well-constructed shieling or perhaps a shepherd's bothy. Not depicted on historic maps.

Asset/Event Number	821
Asset/Event Name	Mound, Badenahauglish
Type of Asset/Event	Mound
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	291328
Northing	910936
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Small but pronounced mound under moss and turf. Measures c. 3m length, 2m in width and 0.4m in height. Aligned SW/NE. Likely a waymarker as adjacent to a track (Asset 959). Not depicted on historic maps.

Asset/Event Number	822
Asset/Event Name	Peat cutting, Badenahauglish
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	290848
Northing	910029
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Large area of peat cutting under heather. C240m long and extends outwith 200m survey corridor to the NW. Some banks are up to 0.7m deep and while there were some fresh cuts visible, the area appears to have been in use for a prolonged period given the degraded nature of some of the peat banks.

Asset/Event Number	823
Asset/Event Name	Track, Badenahauglish
Type of Asset/Event	Track
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	290706
Northing	909795
Council	Highland
Condition:	Good
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Track cut into hillside measuring 3m wide and in use with a large bank on the S side standing 1m tall and under bracken. Appears to have been improved. Not depicted on historic maps, but may follow line of a relict track that may have led to the MHG13157 (Asset 1797) settlement to the NW.

Asset/Event Number	824
Asset/Event Name	Peat cutting, Ousdale Burn
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	306283
Northing	920467
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under heather c70m by 25m excavated into the gentle S facing slope at the base of Braigh na h-Eaglais. Banks stand to a height of 0.3m. Dis-used.

Asset/Event Number	825
Asset/Event Name	Corn drying kiln, Ousdale Burn
Type of Asset/Event	Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	306745
Northing	920577
Council	Highland
Condition:	Very degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A corn drying kiln of drystone construction, mostly under grass and bracken. The stone has been robbed to its lowest courses and survives as a circular rubble wall c1m wide, 0.5m tall, and measuring c6m in diameter. Partly revetted into the S-facing slope. Not depicted on historic mapping. Falls within the HER extent for Asset 108/MHG814, but is not related as these are prehistoric.

Asset/Event Number	826
Asset/Event Name	Peat Cutting. Allt Braigh nam Meur
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	307902
Northing	920822
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Area of peat cutting under heather, measures c120m by c45m with banks standing to a height of 0.3m.

Asset/Event Number	827

Asset/Event Name	Sculpture, Kinellan Woods
Type of Asset/Event	Other
Date and/or Period	Modern
Listing No./NRHE Number	
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	246375
Northing	858740
Council	Highland
Condition:	Good
Alignment:	N/A
Importance:	Neglible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A sculpture of a skeleton riding a mountain bike, representing a modern sculpture situated along popular mountain biking trails within the Kinellan Woods.

Asset/Event Number	828
Asset/Event Name	Quarry, Achorn
Type of Asset/Event	Quarry
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	313483
Northing	930387
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small dis-used quarry cut into the NE facing slope overlooking road. The quarry face is 2m tall at its SW side, and a small structure (Asset 828) has been constructed in its SW end.

Asset/Event Number	829
Asset/Event Name	Structure, Achorn
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A

HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	313479
Northing	930384
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An L-shaped drystone wall constructed into the SE corner of quarry Asset 828, forming a rectangular structure with the quarry face. Only the long NE/SW aligned wall remains standing, to a length of 4m, 1.2m tall and 0.6m wide, with a neatly dressed end forming an entrance 0.6m wide. It defines an internal space of c3.5m by 1.4m internally with the SE side of the quarry making up the back wall. The structure would be easily roofed using the quarry bank. Likely a small shelter. Not depicted on historic mapping.

Asset/Event Number	830
Asset/Event Name	Dyke, Achorn
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	313403
Northing	930439
Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone and turf dyke measuring c50m in length, partially under grass. Stands to c0.3m all and spread up to 1.5m wide. Not depicted on historic mapping.

Asset/Event Number	831
Asset/Event Name	Dykes, Allt Tarsuinn
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	A1.4
Easting	313279
Northing	930338
Council	Highland
Condition:	Very degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone and turf dykes under heather and grass, poorly preserved and possibly affected by flooding considered they lie immediately beside the Allt Tarquin burn. The dykes stand to a height of c0.3-0.5m tall and spread up to 1.5m wide, and of various lengths (c50m long at the longest). Not depicted on historic maps.

Asset/Event Number	832
Asset/Event Name	Bank and ditch, Bad Fearna
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	313116
Northing	929357
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large cut ditch 4m wide at top tapering to 2m wide at base and up to 1.5m deep, with upcast material forming a large bank on the ditch's north side, standing 0.7m tall and spread up to 2.5m wide under heather. Recorded extent is c190m long but extends outwith survey corridor to the NE. Likely part of peat drainage management. Meets a series of possibly natural peat crevices to the W. Not depicted on historic maps.

Asset/Event Number	833.1
Asset/Event Name	Peat cutting, Bad Fearna
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset

Section:	A1.4
Easting	313279
Northing	930109
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under heather stretching across the land around Allt Tarquin to Achorn in a linear distance of c500m and extending beyond the survey corridor to the E and W. Peat banks are c. 0.25-0.5m deep and dis-used.

Asset/Event Number	833.2
Asset/Event Name	Peat cutting, Bad Fearna
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	312939
Northing	928597
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An extensive area of peat cutting under heather stretching across the flattish land between Upper Borgue and Achorn in a linear distance of c1.4km and extending beyond the survey corridor to the E and W. Peat banks are c. 0.25-0.5m deep and dis-used.

Asset/Event Number	834
Asset/Event Name	Quarry, Bad Fearna
Type of Asset/Event	Quarry
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	312923
Northing	928546

Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A ledge of flagstone protrudes from the NE facing slope of a low hill, c30m long, with several large boulders lying beside it with neat fractures indicative of quarrying rather than frost shatter erosion, most slabs are c1.5m long and wide and c0.4m thick, though smaller piles of stone are visible. Not depicted on historic maps.

Asset/Event Number	835
Asset/Event Name	Peat cutting, Loedebest Wood
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	314130
Northing	931597
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Old peat cuttings under grass and heather, much overgrown and hard to discern with banks c0.2m tall and under heather while the cut areas remain more grassy. Extends across the grazings.

Asset/Event Number	836
Asset/Event Name	Possible cairn, Loedebest
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	MHG13573
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	314311
Northing	931778
Council	Highland
Condition:	Unknown
Alignment:	NW/SE

Importance:	Medium
Description	*Recorded by AOC Archaeology during 2024 walkover survey. The HER describes a possible cairn and D-shaped enclosure in the vicinity. No enclosure was identified during the walkover survey, but a very gorse-covered mound stands along a low ridgeline that is surmounted by a post and wire fence and likely conceals the cairn. This ridgeline, although fairly low-lying, is somewhat prominent in views SE towards it from the Scheduled funerary monuments to the NW. Https://her.highland.gov.uk/monument/MHG13573 A 'D' shaped enclosure next to a mound which may be a cairn. Both are very much degraded and eroded. Oriented NW-SE. (1986) [Recorded on pdf attached to HER record]

Asset/Event Number	837.1
Asset/Event Name	Building, Braehiller
Type of Asset/Event	Building
Date and/or Period	Post-medieval/modern
Listing No./NRHE Number	N/A
HER Number	MHG13576
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	314600
Northing	932224
Council	Highland
Condition:	Ruinous
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An unroofed croft with later additions and modifications. The original building measured c17m by 6m over walls, which stand to a height of 1.3m and are 0.8m wide. Cement blocks have been used to construct a smaller partitioned room among this. Depicted as a roofed building on the 1st and 2nd edition OS maps. OS. 1877. Caithness XXXVIII, Surveyed: 1871, Published: 1877 OS. 1909. Caithness XXXVIII, Surveyed: 1905, Published: 1909 https://her.highland.gov.uk/monument/MHG13576 No description.

Asset/Event Number	837.2
Asset/Event Name	Dyke, Braehiller
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG13576
Status	Non-designated Heritage Asset
Section:	

Easting	314571
Northing	932343
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke, much degraded in parts and there under grass, runs around the farmstead Asset 837.1 forming enclosures. Stands to 1.2m tall at tallest. Depicted on the 1st and 2nd edition OS maps. OS. 1877. Caithness XXXVIII, Surveyed: 1871, Published: 1877 OS. 1909. Caithness XXXVIII, Surveyed: 1905, Published: 1909 https://her.highland.gov.uk/monument/MHG13576 No description

Asset/Event Number	840.1
Asset/Event Name	Peat cutting, Creag Thoraraidh
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	303689
Northing	919035
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Area of peat cutting under heather, c40m by 25m within access track survey corridor, with banks c0.5m deep. The peat cutting is much more extensive outwith the survey corridor to the S along the N-facing slope of Creag Thoraraidh.

Asset/Event Number	840.2
Asset/Event Name	Peat cutting, Creag Thoraraidh
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4

Easting	302682
Northing	918868
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of extensive and intensive peat cutting under heather and grass on the N-facing slope of Creag Thorariadh. Extends across an area c650m long along the corridor, and extends beyond the 200m wide corridor to the N and S. The banks are up to 1m deep, with a well-defined peat road (Asset 841) visible running through it.

Asset/Event Number	841
Asset/Event Name	Track, Creag Thoraraidh
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	302702
Northing	918929
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A relict track under heather and grass, likely used to access peat cuttings Asset 840.2. Measures 5m wide under heather and grass and recorded extent measures c630m but continues outwith survey corridor to the NW and S. Visible as a raised bank 1m in height, with a section branching off to the N. Stands c1m proud of the peat cuttings. Forms the old peat road that leads S down to Helmsdale. Depicted on the 1st edition OS map. OS. 1879. Sutherland LXXIX, Surveyed: 1871, Published: 1879

Asset/Event Number	842.1
Asset/Event Name	Peat cutting, Lower Caen
Type of Asset/Event	Peat cutting
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4

Easting	301924
Northing	918472
Council	Highland
Condition:	Fair
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A bracket-shaped cutting of peat, c90m long and less than 2m wide mostly under grass, with banks a depth of 0.4m where the NE-facing hill slope has been cut into. Fresh cuts are evident suggesting the peat bank has been cut into in recent times.

Asset/Event Number	842.2
Asset/Event Name	Peat cutting, Caen Hill
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval/Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	302165
Northing	918610
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Large area of extensive and intensive peat cutting under heather measuring 200m wide and extending outwith the 200m wide survey corridor to the N and S. Banks stand between 0.2 and 0.4m deep.

Asset/Event Number	843
Asset/Event Name	Possible platform, Caen Hill
Type of Asset/Event	Platform
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	301616
Northing	918319
Council	Highland

Condition:	Very degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible platform or terrace of scree and turf under heather, c14m wide and projecting 9m from the hill. Situated on the SW facing slope of the Caen Hill before a rock outcrop to the NE. The platform is subcircular in plan, measuring c15m in diameter and, on the downhill side, standing to a height of 1.2m. Possibly natural frost-shattering.

Asset/Event Number	844.1
Asset/Event Name	Hut circle, Caen Hill
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	MHG10128
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	301505
Northing	918259
Council	Highland
Condition:	Degraded
Alignment:	Circular
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under bracken and heather. Measures approximately 12m in diameter over banks which stand internally to a height of 0.8m, but difficult to determine the bank extent and height externally due to the vegetation and as the structure appears to be robbed along the E extent. Https://her.highland.gov.uk/monument/MHG10128 Some 600 yds N of Caen Burn bridge, are 3 circular enclosures (A, B and E) and remains of one or two others on hillside above, together with old walls. RCAHMS 1911, visited 1909. A total of 4 enclosures (A-D) and hut circle € were located during field perambulation. A further ruined enclosure at ND 0132 1816 was considered to be a sheepfold contemporary with nearby crofting structures. Visited by OS (W D J) 26 May 1960. The settlement lies on SW slopes of Caen Hill and comprises 5 hut circles. 'A' and 'C' are similar being set into hill and of a large size, with a massive wall expanding greatly on downslope side. 'A' measures 10m N-S by 8.5m internally, with entrance in S. The huts floor level is 2m below top of wall in E arc. Extending from E side of entrance is a projecting hornwork. From it low turf covered wall extends westward across face of entrance. 'C' measures 13.5m SE-NW x 10.5m within a wall which attains its greatest dimensions on S side of SE-facing entrance, where it is spread to 5.5m and is 1m high. This expansion may have been caused by addition of clearance; width of entrance of 3.5m indicates some mutilation. In NW segment of wall is a scooped area 6m x 1.7m which may possibly be remains of a collapsed souterrain, though no facing stones are visible and wall irregularity could be result

of mutilation.
Huts 'B' and 'D' are similar in construction being less strongly built than previous huts. Both have been set into slope.
'B' measures 10.5m N-S x 8.5m within wall of 2.5m average spread. Entrance in S has flanking wall on W side.
'D' is 9.5m in diameter within a spread wall of 2.5m widening to 3.5m on the revetted W side. Entrance is in SE where wall has been partially destroyed.
'E' set deeply into slope gives impression of being a stone walled hut of 7.2m internal diameter set eccentrically within a larger hut 10.5m x 9m internally. The wall increases in breadth from 1.5m in the N to 4.0m in joint W arc. The common entrance, choked with stones, is in S. Top of outer scarp in E is 1.5m above floor level.
Two segments of walling ('X' and 'Y') are suggestive of mutilated hut circles, but their condition is too fragmentary for positive classification. An extremely well preserved field system of about 5 hectares surrounds huts. It comprises plots, average size 30m by 25m, defined by lynchets, clearance heaps and ruinous field walls.
Resurveyed at 1:10,560. Visited by OS (J B) 14 June 1976.
--- SHG2657 Text/Report: RCAHMS. 1911. The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. . 111, Nos. 319, 320; fig. 38.

Asset/Event Number	844.2
Asset/Event Name	Platform, Caen Hill
Type of Asset/Event	Platform
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	MHG10128
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	301519
Northing	918232
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A platform measuring 8m by 5m under bracken and heather. The platform has been construction onto the SW -facing slope of Caen Hill, near hut circle Asset 844.1. The platform stands about c2m tall on the downhill side, but the overall upper flat surface is perhaps 0.6m tall. For HER asset description see Asset 844.1.

Asset/Event Number	845
Asset/Event Name	Bank, Allt Loch Leisgein
Type of Asset/Event	Bank
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	C1.1
Easting	261510
Northing	897834
Council	Highland
Condition:	Very degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible turf bank under bracken, very degraded and defined more by the bracken than the upstanding remains which appear to be very ephemeral, spread up to 4m wide and perhaps 0.4m tall, c60m long but continues outwith survey corridor to the N. Not depicted on historic mapping.

Asset/Event Number	847
Asset/Event Name	Dyke, Strone Achavachy
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	261869
Northing	897965
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone and turf dyke enclosure under moss and grass, stands c2m in width and 0.5m in height where encountered. Exposed stone can be seen in sections on the N high ground. Extends of c70m recorded within corridor, but the 1st edition OS map shows an enclosure c800m long, associated with the farmstead labelled Srone Achvachy outwith the survey corridor to the N (no associated HER number). Enclosure seems to dissipate to S after encountering the Allt Loch Loeisgein stream as seen on satellite imagery. OS. 1879. Sutherland CVIII, Surveyed 1874, Published: 1879

Asset/Event Number	848
Asset/Event Name	Enclosure, Lower Caen
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND01NW 117.00
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	A1.5
Easting	301391
Northing	917807
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass, stands 0.3m tall and spread 0.8m wide, forming an enclosure c40m by c24m to the E of the sheepfold Asset 849. Peters out towards its SW ends. Forms an enclosure depicted on the 1st edition OS map. OS. 1879. Sutherland LXXIX, Surveyed: 1871, Published: 1879

Asset/Event Number	849
Asset/Event Name	Sheepfold, Lower Caen
Type of Asset/Event	Sheepfold
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND01NW 117.00
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	301363
Northing	917775
Council	Highland
Condition:	Fair
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Drystone walled sheepfold measuring 36m by 17.5m over walls. Walls survive to a height of 1.4m and measure 0.9m at base, tapering to 0.5m at the top. Several internal partitions are present in the SW half of the structure. Entrance to the NE area is gained by a gate on the southern edge, with a wooden gate post still in situ. Depicted on the 1st edition OS map. OS. 1879. Sutherland LXXIX, Surveyed: 1871, Published: 1879

Asset/Event Number	850
Asset/Event Name	Building, Lower Caen
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	EHG6056 (No MON records)
Status	Non-designated Heritage Asset

Section:	A1.5
Easting	301394
Northing	917825
Council	Highland
Condition:	Very degraded
Alignment:	ENE/WSW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone footings for a rectangular building under heather and grass, measuring 19m by 5m over walls. Walls stand to 0.6m tall and spread up to c1m wide. No visible coursing. One partition situated broadly centrally, entrances not discernible. Not depicted on historic mapping. The building was excavated as part of a community excavation (EHG6056), but there is no associated HER monument record. Https://her.highland.gov.uk/event/EHG6056 A community excavation, planned to commemorate the bicentenary of the Kildonan Clearances, was undertaken by The University of The Highlands and Islands (UHI) under the direction of K Strickland in 2013 at the deserted township of Lower Caen. The township is located in the Strath of Kildonan, c2 miles upstream from the village of Helmsdale. Lower Caen is located on a river terrace above the Caen Burn. It is distinct from Upper Caen, which comprises a collection of ruins that extend north, up Caen Burn. An initial programme of topographical mapping and geophysical survey was carried out. As the structural remains were clearly visible the fluxgate gradiometer survey aimed to identify the location of hearths, middens and other possible internal features. Unfortunately, the underlying granite masked not only more subtle responses but even that from a large corn-drying kiln. As a result it was only possible to identify features already visible, such as extant walls and 'potato' pits. The topographic information was shared with a team from the University of St Andrews 'Virtual Worlds' group in order to develop an immersive 'Virtual Caen'. The first season of excavations focused upon the final phase of occupation and subsequent abandonment of a single longhouse (Structure 1) and its associated outbuilding (Structure 2). Two L-shaped trenches were laid out to provide a half-section across both structures along the N–S (Trench B) and E–W (Trench A) axes. <1> Sources/Archives (1) <1>XY SHG29410 Text/Publication/Article: Strickland, K.. 2013. Lower Caen: Excavation. Discovery and Excavation in Scotland Vol. 14 (2013). 106-7. Digital. [Mapped features: #13220 ; #13221 Trenches,]

Asset/Event Number	851.1
Asset/Event Name	Clearance cairn, Lower Caen
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND01NW 117.00
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	301381

Northing	917828
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A spread of stone, likely clearance material, under heather and grass. Spread measures 7m by 4m and stands 0.6m tall.

Asset/Event Number	851.2
Asset/Event Name	Clearance cairn, Lower Caen
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND01NW 117.00
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	301365
Northing	917791
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn partly under grass, measures 7m by 5m and stands 0.4m tall.

Asset/Event Number	852
Asset/Event Name	Marker post, Lower Caen
Type of Asset/Event	Other
Date and/or Period	Modern
Listing No./NRHE Number	
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	301377
Northing	917826
Council	Highland
Condition:	Good
Alignment:	NA
Importance:	Neglible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A square cement pillar with pyramidal top, stands 0.6m tall and measures 0.2m by 0.2m. No bench mark evident. Function uncertain.

Asset/Event Number	853
Asset/Event Name	Dyke, Lower Caen
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	EHG6056 (No MON records)
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	301375
Northing	917827
Council	Highland
Condition:	Very degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small section of stone and turf dyke or a much robbed structural wall under heather and grass. Comprises several large stones up to 0.6m long set loosely in an L shape but not appearing to continue beyond 3m of either arm. Possibly the remnants of a small kale yard or similar. Not depicted on historic mapping.

Asset/Event Number	854
Asset/Event Name	Corn drying kiln, Lower Caen
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND01NW 117.00
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	301362
Northing	917843
Council	Highland
Condition:	Degraded
Alignment:	cIrcular
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A corn drying kiln under heather, built into the SE facing slope of a small natural mound/drumlin measuring c10m in diameter. The kiln bowl measures c5m in diameter and is of drystone construction. The kiln flue is visible as a c1m wide channel aligned to the NW. Not depicted on historic mapping.

	Part of the settlement excavated as part of community project EHG6056, see Asset 850 for description.

Asset/Event Number	855
Asset/Event Name	Storage pits, Lower Caen
Type of Asset/Event	Other
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND01NW 117.00
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	301363
Northing	917808
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Two nearly conjoined circular pits under grass, rounded in form and measuring 1.5m in diameter towards the base, flaring up to 3.5m at the top, and 0.7m deep. These pits are set at the edge of a natural ridge. They are likely storage pits for vegetables. Not depicted on historic mapping. Part of the settlement excavated as part of community project EHG6056, see Asset 850 for description.

Asset/Event Number	856.1
Asset/Event Name	Clearance cairn, Cnocnagraishag
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	246090
Northing	843142
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn partially under grass and moss stands at the edge of a slight slope rising to the south. The cairn measures c. 8m by 5m and stands 1m tall. Less discrete spreads of stone are present in the wider surrounds.

Asset/Event Number	856.2
Asset/Event Name	Clearance cairn, Cnocnagraishag
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	246092
Northing	843156
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Sub rectangular clearance cairn under moss and lichen measuring c10m by 9m and between 0.5-1m tall. Consists of white lichen covered medium and smalls stones. Well defined borders to the cairn.

Asset/Event Number	857
Asset/Event Name	Building, Lower Caen
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	EHG6056 (No MON records)
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	301364
Northing	917825
Council	Highland
Condition:	Very degraded
Alignment:	Various
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A long linear building under heather and grass, measuring m by m over walls, which themselves measure c0.75m wide and stand 0.5m tall at their tallest with some coursing or roughly dressed stone evident. A partition was not evident but the building has been excavated and some disturbance may have resulted from this. Not depicted on historic mapping. Part of the settlement excavated as part of community project EHG6056, see Asset 850 for description.

Asset/Event Number	858
Asset/Event Name	Dyke, Clais na Faire
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	262371
Northing	897758
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A substantial stone dyke under moss and heather, stands 0.7m tall and spread up to 4m wide. Record extent measure c250m but continues outwith survey corridor to NE, but stops where the line stops to the W, with a gap between the next section, as depicted. Stands on the E side of the burn. Depicted on the 1st edition OS map. OS. 1879. Sutherland CVIII, Surveyed 1874, Published: 1879

Asset/Event Number	859
Asset/Event Name	Dyke, Clais na Faire
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	262397
Northing	897647
Council	Highland
Condition:	Fair
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A bank under grass at side of ditch /burn. In semi improved moorland. C0.75m width, 0.5m height. Some visible stone but mostly overgrown. Recorded extent c150m but may continue outwith survey corridor to the S. Depicted on the 1st edition OS map. OS. 1879. Sutherland CVIII, Surveyed 1874, Published: 1879

Asset/Event Number	860

Asset/Event Name	Building, Clais na Faire
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	262384
Northing	897689
Council	Highland
Condition:	Very Degraded
Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Possible long house building but very ephemeral. The asset appears as a somewhat rectangular raised area of land under heather and grass c13m long by 5m wide, with two large boulders c. 1.5m long and 1m tall situated at the S end and one on the W that may be remnants of a wall. The surrounding area is beside the burn and fairly boggy, so a structure atop a built up platform seems a likely interpretation. The dimensions are reasonable for such a structure, but no clear walls or banks were visible. Not depicted on historic mapping.

Asset/Event Number	861
Asset/Event Name	Possible kerb cairn, Clais na Faire
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	262432
Northing	897666
Council	Highland
Condition:	Degraded
Alignment:	Circular
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible prehistoric cairn under heather c14m in diameter and standing 2m tall. It forms a prominent mound with at least four boulder c1-1.2m long set along its edge (two on the NE side, one on the NW and one on the SW). These appear to be true separate stones rather than bedrock protrusions. No visible chamber. The mound sits on a possibly artificial platform visible as raised platform extending to the NE before dropping away to the natural ground level 0.7m below. The landscape setting comprises a large topographical bowl with views to the S along a wide strath and to the N along the same. A good setting for a cairn. But uncertain given the similar natural features present elsewhere, though these are generally at least double the size of this asset.

Asset/Event Number	862.1
Asset/Event Name	Peat cutting, Clais na Sinneig
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	263821
Northing	897735
Council	Highland
Condition:	Degraded
Alignment:	W/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under heather c260m by 70m with peat banks standing to a height of 0.4m. In use.

Asset/Event Number	862.2
Asset/Event Name	Peat cutting, Clais na Sinneig
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	263974
Northing	897590
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under heather c160m by 40m with peat banks standing to a height of 0.3m.

Asset/Event Number	863
Asset/Event Name	Lade, Allt A'Choire Sliogaich
Type of Asset/Event	Lade

Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	255184
Northing	875527
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A 1m wide and 1m deep lade, diverting water from the Allt a' Choire Sliggaich to the N to the artificial modern pond (Asset 865) to the S. Not depicted on historic mapping. This pond is not depicted on OS mapping up until 1973, and so it and this lade must post-date this. OS. 1973. Sheet NH 47/57 - Loch Glass; A Edition, Revised: 1965 to 1971, Published: 1973

Asset/Event Number	864
Asset/Event Name	Pond, Allt a' Choire Sliogaich
Type of Asset/Event	Peat cutting
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	255213
Northing	875402
Council	Highland
Condition:	Good
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An irregularly shaped pond c90m by 50m with a central island is located S of the Allt a; Choire Sliogaich burn, and fed by a lade (Asset 863) that runs S from the burn, and another lade (not surveyed as outwith the survey area) that runs further S into the River. This pond is not depicted on OS mapping up until 1973, and so must post-date this. OS. 1973. Sheet NH 47/57 - Loch Glass; A Edition, Revised: 1965 to 1971, Published: 1973

Asset/Event Number	865.1
Asset/Event Name	Dyke, Allt a' Choire Sliogaich
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval

Listing No./NRHE Number	NH57NE 11.01
HER Number	MHG8393
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	255195
Northing	875491
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A turf and stone dyke under grass, measures approximately 0.5m tall and up to 1m wide, c25m long. Not depicted on historic mapping. Https://her.highland.gov.uk/monument/MHG8393 On the west bank of the Allt a'Choire Sliogaich at NH 5518 7550 a level area of ground measuring about 30m by 25m is enclosed on the N,E, and S by a grassed-over earth and stone bank up to 0.4m in height and 1.5m thick. Traces of two more banks set 75m apart, the westerly on the lip of a terrace, run upslope into bracken-covered ground, but they cannot be traced beyond the drystone dyke to the N. Within this area narrow cultivation ridges 1.5m - 2m wide are visible. Visited by RCAHMS (PJD) 15 November 1989.

Asset/Event Number	865.2
Asset/Event Name	Dyke, Allt a' Choire Sliogaich
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH57NE 11.01
HER Number	MHG8393
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	255174
Northing	875507
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A turf and stone dyke under grass, measures approximately 0.5m tall and up to 1m wide, c25m long. Not depicted on historic mapping. For HER asset description see Asset 865.1.

Asset/Event Number	865.3
Asset/Event Name	Dyke, Allt a' Choire Sliogaich

Type of Asset/Event	Dyke
Date and/or Period	Post medieival
Listing No./NRHE Number	NH57NE 11.01
HER Number	MHG8393
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	255094
Northing	875552
Council	Highland
Condition:	Unknown
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke, observed on aerial photographs but not surveyed on the ground due to dense vegetation. C160m long and defines the N side of the area of rig and furrow cultivation Asset 865.4. For HER asset description see Asset 865.1.

Asset/Event Number	865.4
Asset/Event Name	Rig and furrow, Allt a' Choire Sliogaich
Type of Asset/Event	Rig and furrow
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH57NE 11.01
HER Number	MHG8393
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	255116
Northing	875532
Council	Highland
Condition:	Degraded
Alignment:	NNW/SSE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Area of rig and furrow under dense bracken c160m by 50m, visible in satellite imagery of the area as extending NNW/SSE and enclosed by the drystone dyke Asset 865.3 and turf and stone dyke Asset 865.2. For HER asset description see Asset 865.1.

Asset/Event Number	866.1
Asset/Event Name	Peat cutting, Burn of Houstry
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A

HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	315252
Northing	932669
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under heather measuring c100m by 70m and with banks up to 0.4m deep. The peat cutting in this area appears to be focused on the somewhat raised areas around the Houstry Burn.

Asset/Event Number	866.2
Asset/Event Name	Peat cutting, Burn of Houstry
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	315181
Northing	932654
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under heather c70m by 50m with banks up to 0.4m deep. The peat cutting in this area appears to be focused on the somewhat raised areas around the Houstry Burn.

Asset/Event Number	866.3
Asset/Event Name	Peat cutting, Burn of Houstry
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	315154

Northing	932765
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under heather c80m by 50m with banks up to 0.4m deep. The peat cutting in this area appears to be focused on the somewhat raised areas around the Houstry Burn.

Asset/Event Number	866.4
Asset/Event Name	Peat cutting, Burn of Houstry
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	315076
Northing	932516
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under heather c210m by 100m with banks up to 0.4m deep. The peat cutting in this area appears to be focused on the somewhat raised areas around the Houstry Burn.

Asset/Event Number	867
Asset/Event Name	Cairn, Houstry Burn
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	
HER Number	MHG28698
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	315304
Northing	932774
Council	Highland
Condition:	Unknown
Alignment:	Unknown

Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible cairn, not definitively identified during the walkover survey. Https://her.highland.gov.uk/monument/MHG28698 What are probably the remains of a second heather-grown cairn are situated about 270m SE of the cairn ND13SE 113, and is cut through by the track that extends from SE to NW up the slope from the Burn of Houstry. The cairn measures at least 13.5m in diameter and the surviving portion on the SW side of the track stands to a maximum height of 1m. Visited by RCAHMS (DE, IP) August 1997

Asset/Event Number	868
Asset/Event Name	Hut circle, Houstry Burn
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	
HER Number	MHG28699
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	315323
Northing	932796
Council	Highland
Condition:	Very degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible hut circle with poorly defined banks under heather, c10m diameter with banks spread to 3m wide. Https://her.highland.gov.uk/monument/MHG28699 What may be a small hut-circle lies in open peat moorland some 40m NNE of the cairn (ND13SE 114). It measures 6m from N to S by 8m transversely within heather-grown walls 0.5m in maximum height and spread 1.5m in thickness. Several stones are visible along the line of the wall and two large orthostats frame a possible entrance on the SE. Visited by RCAHMS (DE, IP) August 1997 The site is just about visible on vertical aerial photographs taken in 2009. <1> <1> SHG27382 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 2009. Getmapping aerial photography 2009. XY

Asset/Event Number	871.1
Asset/Event Name	Dyke, Crofts of Benachielt
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset

Section:	A1.2
Easting	318778
Northing	938518
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass and heather, spread up to 2.5m wide and stands 0.7m tall, c90m long. Part of a larger enclosure associated with the farmstead complex to the S, depicted on the 1st edition OS map. OS. 1877. Caithness XXXIII Surveyed: 1871, Published: 1877.

Asset/Event Number	871.2
Asset/Event Name	Clearance cairn, Crofts of Benachielt
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.2
Easting	318714
Northing	938466
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A spread of field clearance stones partially under grass, measures 10m by 5m and stands 0.7m tall. Potentially could conceal a structure below.

Asset/Event Number	871.3
Asset/Event Name	Pen, Crofts of Benachielt
Type of Asset/Event	Pen
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.2
Easting	318753
Northing	938378

Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular drystone pen measuring 5m by 3.5m over walls, which themselves measure 0.5m wide and stand 1m tall where best preserved. Not depicted on the 1st or 2nd edition OS maps. OS. 1877. Caithness XXXIII Surveyed: 1871, Published: 1877. OS. 1907. Caithness-shire XXXIII. Surveyed: 1905, Published: 1907.

Asset/Event Number	871.4
Asset/Event Name	Building, Crofts of Benachielt
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.2
Easting	318746
Northing	938299
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A long rectangular building measuring c24m by 6m over walls with evidence of modification and additions. Likely originally comprised a dwelling house to the E and a separate cart shed to the W, but conjoining walls were erected at a later date to join the two structures. The dwelling survives to wall head height of 2.5m and 4m at the E gable end, has a single internal partition separating the 10m long internal space into two compartments, and features an entrance in the N elevation and entrance and two windows in the S elevation. Three prominent slanted buttresses of stone extend from the S elevation between the windows and door. The cart shed measures 5m by 4.5m internally with an entrance in the S elevation, preserved only on the W side, with the E side collapsed and the interior of the structure filled with rubble. The building has perhaps been modified as a livestock pen as has been observed elsewhere, hence the conjoining of the structures with the rudimentary wall along the N building line. Consistent with a roofed building depicted on the 1st edition OS map. OS. 1877. Caithness XXXIII Surveyed: 1871, Published: 1877. OS. 1907. Caithness-shire XXXIII. Surveyed: 1905, Published: 1907.

Asset/Event Number	871.5
Asset/Event Name	Track, Crofts of Benachielt
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A

HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.2, A1.3
Easting	318761
Northing	938201
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A track, mostly under grass, measuring 2.5m wide that leads S from the croft building Asset 871.4 out past the edge of the enclosure wall Asset 871.8, before curving to the SW towards the modern A9 road. Forms the original access and is depicted on the 1st edition OS map. OS. 1877. Caithness XXXIII Surveyed: 1871, Published: 1877.

Asset/Event Number	871.6
Asset/Event Name	Building, Crofts of Benachielt
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.2
Easting	318781
Northing	938279
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Small drystone building measuring 6m by 4m over walls, which stand to a height of 1.5m tall. The building adjoins the enclosure Asset 871.8 on its E side, situated higher up the hill and overlooking the croft to the W. A small window sits in the W elevation. It is first depicted on the 2nd edition OS map. OS. 1877. Caithness XXXIII Surveyed: 1871, Published: 1877. OS. 1907. Caithness-shire XXXIII. Surveyed: 1905, Published: 1907.

Asset/Event Number	871.7
Asset/Event Name	Kale yard, Crofts of Benachielt
Type of Asset/Event	Kale yard
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A

HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.2
Easting	318747
Northing	938287
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A sub-square enclosure c15m by 15m constructed in drystone, with a raised earth interior that is c0.5m above the surrounding ground surface. The walls stand to a height of 1.2m and are c0.7m wide. No entrances identified. Depicted on the 1st and 2nd edition OS maps. OS. 1877. Caithness XXXIII Surveyed: 1871, Published: 1877. OS. 1907. Caithness-shire XXXIII. Surveyed: 1905, Published: 1907.

Asset/Event Number	871.8
Asset/Event Name	Enclosure, Crofts of Benachielt
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.2
Easting	318686
Northing	938320
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke that forms an enclosure c150m long and 100m wide surrounding the farmstead building Asset 871.4. The enclosure wall is free-standing in some parts, up to a height of 0.7m tall and spread up to 1.5m wide, but is also revetted in areas such as along the E side of the access towards the main house, opposite the kale yard (Asset 871.7). Depicted on the 1st edition OS map. OS. 1877. Caithness XXXIII Surveyed: 1871, Published: 1877. OS. 1907. Caithness-shire XXXIII. Surveyed: 1905, Published: 1907.

Asset/Event Number	872
Asset/Event Name	Dyke, Gartymore
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval

Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301054
Northing	915094
Council	Highland
Condition:	Degraded
Alignment:	NNW/SSE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone dyke partly under gorse, stands 0.9m tall and spread up to 2m wide. C 50m long. Depicted on the 1st edition OS map as part of a larger enclosure to the W. OS. 1879. Sutherland, XC, Surveyed: 1871, Published: 1879

Asset/Event Number	873.1
Asset/Event Name	Borrow pit, Creag a' Choire
Type of Asset/Event	Borrow pit
Date and/or Period	Post-medieval/Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	300804
Northing	915281
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A borrow pit under heather, measures c100m by 15m and up to 1.5m deep where the hill to the NE has been quarried.

Asset/Event Number	873.2
Asset/Event Name	Borrow pit, Creag a' Choire
Type of Asset/Event	Borrow pit
Date and/or Period	Post-medieval/Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A

Easting	300733
Northing	915343
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A borrow pit under heather, measures 15m by 6m and up to 1.5m deep where the hill to the N has been quarried.

Asset/Event Number	874.1
Asset/Event Name	Track, Creag Marail
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	300906
Northing	916141
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A track 2.5-3m wide, partly under heather, leading NW from West Helmsdale past the Creag Marail and towards Eldrable Hill. Depicted on the 1st Edition OS. OS. 1879. Sutherland, XC, Surveyed: 1871, Published: 1879

Asset/Event Number	874.2
Asset/Event Name	Track, Creag a' Choire
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	299748
Northing	916136
Council	Highland
Condition:	Degraded

Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A track 2.5-3m wide, partly under heather, leading NW from Gartymore alongside Creag a' Choire and towards Eldrable Hill. Depicted on the 1st Edition OS. A branch from the track leading from West Helmsdale past Craig Marial (Asset 874.1) connects to this. OS. 1879. Sutherland, XC, Surveyed: 1871, Published: 1879

Asset/Event Number	875
Asset/Event Name	Possible Structure, Braehiller
Type of Asset/Event	Structure
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	MHG13579
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	314750
Northing	932150
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Not surveyed as no land access granted. Https://her.highland.gov.uk/monument/MHG13579 A pile of stones, 1m in diameter, placed on a slight hilltop, easily visible from a distance. G.u survey: 1986 : db 13/5.

Asset/Event Number	876
Asset/Event Name	Standing Stone, The Dogs
Type of Asset/Event	Standing stone
Date and/or Period	Unknown
Listing No./NRHE Number	
HER Number	MHG32405
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	312810
Northing	926417
Council	Highland
Condition:	Unknown
Alignment:	N/A

Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Not observed during the walkover survey but a stone is visible in satellite imagery adjacent to the track. Https://her.highland.gov.uk/monument/MHG32405 "The Dogs" marked on both 1st & 2nd ed OS. On 1st edition they appear as two small circular features; two shaded dark features are shown on the 2nd edition. The current path curves around these features to the east. The name is still used locally. Doug Scott refers to the standing stone (ND12NW0013) to the north-west as "the Shepherd and his dogs" . These two features may therefore be the remains of similar stones. Needs checking. HAW 7/2004

Asset/Event Number	877.1
Asset/Event Name	Borrow pit, Eldrable Hill
Type of Asset/Event	Borrow pit
Date and/or Period	Post-medieval/Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	299761
Northing	916144
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A borrow pit under heather, measures 14m by 10m and up to 1.5m deep where the hill to the N has been quarried.

Asset/Event Number	877.2
Asset/Event Name	Borrow pit, Eldrable Hill
Type of Asset/Event	Borrow pit
Date and/or Period	Post-medieval/Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	299575
Northing	916207
Council	Highland
Condition:	Degraded
Alignment:	N/S

Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A borrow pit under heather, measures 20m by 20m and up to 2m deep where the hill to the N has been quarried.

Asset/Event Number	878.1
Asset/Event Name	Peat cutting, Eldrable Hill
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval/Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	298747
Northing	916275
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An extensive area of intensive peat cutting under heather, moss and grass. The peat cutting extends 1.2km along the survey corridor, and extends far outwith the survey corridor to the SW, encompassing much of the lower SW slope of Eldrable Hill and the flatter ground between it and Beinn na Mhealaich to the S.

Asset/Event Number	878.2
Asset/Event Name	Peat cutting, Eldrable Hill
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval/Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	299983
Northing	916265
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small area of peat cutting under heather c35m by 40m, with banks up to 0.4m deep.

Asset/Event Number	880
Asset/Event Name	Track, Allt Sgealbach
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	301069
Northing	916733
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A track under heather and grass, c2.5-3m wide. Appears to lead SW up the Allt Sgealbach burn from Marrel before diverting to the NW. Depicted on 1st ed OS. Recorded extent within survey corridor measures c700m long but continues outwith corridor to the NE and NW. OS. 1879. Sutherland LXXIX, Surveyed: 1871, Published: 1879.

Asset/Event Number	881
Asset/Event Name	Hut Circle, Allt Sgealbach
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	301070
Northing	916828
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under heather measuring c12m diameter over banks, which stand to a height of c0.8m and spread up to 3m. SE-facing entrance c. 1.5m wide.

Asset/Event Number	892.1
Asset/Event Name	Hut circle, Allt Sgealbach

Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	301064
Northing	917094
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle measuring c10m in diameter over banks which stand 0.3m all internally, 0.5m tall externally. Entrance not discernible. Located higher in valley but overlooking the valley to the northeast.

Asset/Event Number	892.2
Asset/Event Name	Hut circle, Creag Marail
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	301091
Northing	917138
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under grass and heather, represented by an arc of bank c25m long and open to the SE, forming a potential diameter of c12m. Possibly robbed for the adjacent structures to the SW.

Asset/Event Number	892.3
Asset/Event Name	Platform or clearance cairn, Allt Sgealbach
Type of Asset/Event	Platform
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	A1.5
Easting	301091
Northing	917097
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prominent mound under tall dense bracken stands to the SE of hut circle Asset 892.1. The mound stands perhaps 1.2m tall and measures c12m by 10m with a flattish top. No bank or characteristic depression that would indicate a hut circle could be discerned.

Asset/Event Number	894
Asset/Event Name	Track, Allt Sgealbach
Type of Asset/Event	Track
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	301146
Northing	917390
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A track c2-3m wide, difficult to discern its form due to tall dense bracken that have entirely overgrown the asset, but it appears to run W from Marrel, to the S side of the railway. Appears mostly foot worn, but local accounts describe a World War I or II logging camp in the vicinity and this may have led to it. Spans the corridor and likely continues outwith it to the E and W. Not depicted on historic maps.

Asset/Event Number	895
Asset/Event Name	Track, Loch nam Bonach
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset

Section:	E1.2
Easting	247844
Northing	848432
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A track mostly under heather but in parts well defined with some stone kerb settings, c3m wide and depressed in parts. Recorded extent c350m but continues outwith survey corridor to the E and W. Depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII, Surveyed: 1876, Published: 1881

Asset/Event Number	896
Asset/Event Name	Peat cutting, Loch nam Bonach
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	247443
Northing	847905
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An old peat cutting under grass and heather. Cut into the base of a SE-facing hill and measures c150m in length.

Asset/Event Number	898
Asset/Event Name	Peat cutting, Cnoc Dubh
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	247117
Northing	847576

Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat cut under heather, measuring c60m long.

Asset/Event Number	899
Asset/Event Name	Track, Buachaille Breige
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	246130
Northing	846237
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Track under grass and bracken, 2m wide, spanning survey corridor and continuing to the E and W. Depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII, Surveyed: 1876, Published: 1881

Asset/Event Number	900
Asset/Event Name	Peat cutting, Creag an t-Suidheachain
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	245922
Northing	846052
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large area of peat cutting c280m by 100m (extends outwith corridor the NW)along the flooded saddle of land between Buachaille Breige to the N and Creag an t-Suidheachain to the S. The cuts are varied but along the SW portion are neatly fanned out from the small stream that runs NE/SW.

Asset/Event Number	901.1
Asset/Event Name	Clearance cairn, Urchany
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	Uncertain
HER Number	Uncertain
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	245680
Northing	845725
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and bracken. Stands 0.6m tall and spread 6m by 2m set at base of small slope. Dense bracken limits visibility.

Asset/Event Number	901.2
Asset/Event Name	Clearance cairn or shieling, Urchany
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric/Post-medieval
Listing No./NRHE Number	Uncertain
HER Number	Uncertain
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	245692
Northing	845719
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible/Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stoney spread c8m by 4m with a hollow, dimensions difficult to discern due to dense vegetation. Potentially a clearance cairn modified into a shieling or small structure.

Asset/Event Number	901.3
Asset/Event Name	Clearance cairn, Urchany
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	Uncertain
HER Number	Uncertain
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	245665
Northing	845659
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Prehistoric clearance cairn partly under heather and grass. Stands 0.5m tall and spread c.4m diameter. Dense bracken prohibit visibility.

Asset/Event Number	901.4
Asset/Event Name	Hut circle, Urchany
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	Uncertain
HER Number	Uncertain
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	245629
Northing	845631
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under heather measuring c12m by 10m over banks which are poorly defined. Situated on a small but prominent knoll. Entrance not discernible, but some stone visible in the banks.

Asset/Event Number	901.5
Asset/Event Name	Hut circle and platform, Urchany

Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	MHG61222?
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	245669
Northing	845669
Council	Highland
Condition:	Degraded
Alignment:	Circular
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A platform under dense heather and grass, measures c15m in diameter but very difficult to discern due to vegetation. May correlate with MHG61222. https://her.highland.gov.uk/monument/MHG61222 Depop., cairns, etc. OS 6"map annotated by A L F Rivet (nd) Centred at NH 455 455 is a settlement of ten stone-walled huts and a field system. Hut 'E' is circular, the remainder are oval. Except for 'A', 'G' and 'H' the measurements are given between wall centres. Hut 'A', set into a SW-facing slope, is visible as a platform measuring about 12.0 m NNW-SSE by 10.0 m trans- versely, bounded by a stony build-up round the SW arc and a back scarp. The entrance is in the SSE at the change of slope. 'B', set into a W-facing slope, measures about 10.5 m NW- SE by 9.0 m transversely with the wall spread to about 2.5 m. The 'simple' entrance is in the SE, at the change of slope. 'C', adjacent to 'B', measures about 12.5 m N-S by 10.0 m transversely with the wall spread to about 2.5 m all round. The outer wall face is visible round the E arc. The 'simple' entrance, about 1.0 m wide, is in the S, at the change of slope. 'D', at the base of a knoll, measures about 10.0 m from the NNW through the 'simple' entrance in the SSE by about 9.0 m transversely with the wall spread to about 2.5 m all round. The outer wall face is visible round the S arc. Attached to the W arc of the hut and following the curve of the wall of the hut is an elongated enclosure measuring approximately 10.0 m long by 2.5 m wide within a stone wall spread to about 1.5 m. There is no apparent entrance. It is similar in appearance to the 'souterrains' described on NJ 40 SW 3. (See 1:250 plan.) 'E', built up on a S-facing slope, measures about 6.5 m in diameter with the wall spread to about 2.0 m. The entrance is not apparent. 'G' has the outer wall face visible round most of the perimeter giving overall measurements of 13.5 m NNW-SSE by 12.0 m transversely. The wall is spread to about 2.0 m all round. The S arc has been robbed and the entrance is not apparent. 'H' has the inner wall face evident round most of the perimeter giving internal measurements of 10.0 m NNW-SSE by about 8.0 m transversely. The wall is spread to an indeterminate thickness. The entrance is not apparent. 'J' is denuded and measures about 9.0 m NW-SE by 8.0 m transversely with the wall spread to about 2.0 m all round. The entrance is not apparent. 'K', set into an E-facing slope, measures about 13.5 m N-S by about 11.5 m transversely with the wall spread to some 2.5 m all round. Stone clearance has been piled over the W arc. The 'simple' entrance, about 1.3 m wide, is in the S at the change of slope. About 15 m NE of hut 'K' is a circular hollow, about 6.0 m in diameter, with traces of walling round the edge. Stone clearance has been piled within. The field system, partly overlaid by a depopulated steading, is

marked by stone clearance heaps, lynchets and walls forming fields varying in size from about 15 m by 10 m to about 50 m by 30 m.
Divorced survey at 1:10,000.
Visited by OS (R L) 17 March 1970

(Name: NH 4555 4550) Settlement & Field System (NR)
OS 1/10,000map, (1975)

This unenclosed settlement comprises the remains of four oval stone-walled houses and two scarped platforms which may represent the sites of timber houses. In the vicinity there are several other platforms of unknown function and also extensive remains of stone clearance, some of which may be of relatively recent date.
RCAHMS 1979

The suggested enclosure attached to hut circle 'D;, at NH 4550 4545 is almost certainly the line of a collapsed souterrain. Otherwise, the hut circles and field system are as described by OS surveyor.
Visited by OS (J M) 11 February 1981

This site was visited multiple times by R Spencer-Jones of NOSAS between March and June 2013. All but three of the hut circles were identifiable due to heather burning at the site (for grouse) which had made the majority of hut circles more visible. The three that were unlocated were A, J and K. The others were described as follows:
Hut B - [NH 45453 45379] The walls were only partially identifiable and were best preserved in the SW quadrant where they are spread to 2.3m and stand to 0.2m in height. The hut was deeply embedded in heather and was only just visible. The general shape was oval and it abouts hut C on the southern edge. The internal diameter across the longest NNW axis measured 10.1m x 7.6m. The external diameter measured 12.7m x 10.9m. There was a possible entrance to the south east.
Hut C - [NH 45459 45367] The walls were only partially identifiable and were best preserved on the eastern, upslope, side, where they were spread to 2.5m and stood to 0.2m in height. Again, this hut was deeply embedded in heather and was only just visible. The general shape was oval and it abuts hut B on its northern edge. The internal diameter across the longest N axis measured 10.8m x 8.1m. The external diameter measured 14.2m x 12.5m. There was a possible entrance to the south.
Hut D - [NH 45507 45451] The walls were indistinct in the south west and best seen in the east where they are spread to 1.5m and stand to 0.5m in height. Located on a gentle west facing slope, at the base of a mound to the north lies this large hut circle, with an ellipse of stone wall to the west, ie down-slope. In the original 1970 survey this is described as a souterrain, confirmed by a further OS visit in 1981. What remains of this structure is an ellipse of stones, approx 3.5-4m outwith the western side of the original hut circle. They now don't look like a souterrain, although their function is now unclear. There is a path, probably animal track, that runs through the northern part of the circle, exposing the base. The general shape is circular. The internal diameter measured 7.5m x 6.7m. The external diameter measured 10.6m x 10.2m. There was a possible entrance to the SSE.
Hut E - [NH 45601 45501] The remaining walls are best seen to the west where the remains are 1.4m thick and stand 0.3m high. Located on a gentle east facing slope, it occupies a slight knoll with a built extension to the south. The recent burning had exposed a degenerated circle of stones that could other wise have been missed. The general shape was circular. The internal diameter measured 4.7m x 4.1m. The external diameter measured 7.5m x 7.5m. An entrance was not identifiable.
Hut F - [NH 45595 45562] The remaining circular walls are indistinct apart from in the west and south east quadrants. Located on a gentle south facing slope, it has a definite entrance and entrance passageway consisting of two lines of rough large stones to the south which measured 1.3m in length, 1.5m in width and with stones standing 0.8m in height. The recent heather burning had exposed a degenerate circle that would otherwise have been missed. The general shape was circular. The internal diameter measured 7.3m x 9.75m on the north-south axis. The internal diameter measured 9.98m x 11.05m.
Hut G - [NH 45624 45556] The remaining, indistinct walls were marked by periodic stones. The wall was best seen in the west where it was spread to 1.8m and stood up to 0.5m in height. Located on a gentle south facing slope, it stands on a platform slightly built out in the

south. There was an elliptical extension, or 'annexe' on the north west arc. The recent heather burning had exposed a degenerate circle of stones that would otherwise have been missed. The general shape was circular and there was a possible entrance in the south east. The internal diameter was 9.0m x 9.0m. The external diameter measured 13.2m x 12.8m. Hut H - [NH 45664 45540] The remaining walls were very indistinct with very few stones left and one large boulder in the south west. The hut circle was very indistinct and only visible as a round depression in the peat rather than being easily identifiable by its walls. The recent heather burning had made it easier to see. The general shape was circular and there was a possible entrance in the south. The internal diameter measured 7.5m x 7.5m. The external diameter measured 9.0m x 9.0m. <1>

The North of Scotland Archaeological Society (NoSAS) undertook an archaeological survey of Urchany in 2015.

Site H02; Hut circle. Probable hut circle on recessed platform (OS Hut Circle K). Close to platform H01 (see MHG62144), this oval platform is recessed into the gentle sloping hillside to the west, above the Allt na Criche to the east. 11m NE/SW x 6.5m. The E front of the platform is buttressed with stone, part of which has spread downslope. The recessed W side of the platform is partially obscured with post abandonment boulders and colluvium. This back part of the platform had not been burnt by the 2013 muir burn, thus being further obscured by rank heather. Too little evidence remains to call this site a hut circle and more likely it is a recessed platform that may or may not have had a timber structure on it originally. <2>

Asset/Event Number	902
Asset/Event Name	Boundary wall, Urchany
Type of Asset/Event	Wall
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG23303?
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	245591
Northing	845473
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A probable boundary dyke under heather, extending E/W along the track. Possibly related to the adjacent and unsurveyed post-medieval farmstead Asset 127/MHG23303. Vegetation and time constraints prevented detailed survey. Not depicted on historic mapping.

Asset/Event Number	903
Asset/Event Name	Enclosure, Urchany
Type of Asset/Event	Enclosure
Date and/or Period	

Listing No./NRHE Number	
HER Number	MHG23303?
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	245613
Northing	845460
Council	Highland
Condition:	Degraded?
Alignment:	
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Remnants of a drystone enclosure under dense heather. Possibly related to the adjacent and unsurveyed post-medieval farmstead Asset 127/MHG23303. Vegetation and time constraints prevented detailed survey. Not depicted on historic mapping.

Asset/Event Number	950
Asset/Event Name	Building, Innis Aonar
Type of Asset/Event	Building
Date and/or Period	Unknown
Listing No./NRHE Number	
HER Number	MHG14568
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272499
Northing	898899
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. The HER records footings for a building but no upstanding remains could be discerned during the walkover survey. The locale was under tall bracken and heather which obscured visibility. Https://her.highland.gov.uk/monument/MHG14568 No description.

Asset/Event Number	951.1
Asset/Event Name	Ditch, Allt a' Choire Dhuibh
Type of Asset/Event	Ditch
Date and/or Period	Modern
Listing No./NRHE Number	N/A

HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256446
Northing	881076
Council	Highland
Condition:	Good
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat grip (drainage ditch) measuring 1-1.5m wide and c1m deep, c120m long but continues outwith survey corridor to the W, and excavated into the SE-facing slope that forms the Coire Dubh, draining the peat wetland into the Allt a' Choire Dhuibh to the SE. Still in use.

Asset/Event Number	951.2
Asset/Event Name	Ditch, Allt a' Choire Dhuibh
Type of Asset/Event	Ditch
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256454
Northing	881144
Council	Highland
Condition:	Good
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat grip (drainage ditch) measuring 1-1.5m wide and c1m deep, c120m long but continues outwith survey corridor to the W, excavated into the SE-facing slope that forms the Coire Dubh, draining the peat wetland into the Allt a' Choire Dhuibh to the SE. Still in use.

Asset/Event Number	951.3
Asset/Event Name	Ditch, Allt a' Choire Dhuibh
Type of Asset/Event	Ditch
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1

Easting	256513
Northing	881254
Council	Highland
Condition:	Good
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat grip (drainage ditch) measuring 1-2m wide and c1.3m deep, c100m long but continues outwith survey corridor to the W, excavated into the SE-facing slope that forms the Coire Dubh, draining the peat wetland into the Allt a' Choire Dhuibh to the SE. Still in use.

Asset/Event Number	951.4
Asset/Event Name	Ditch, Allt a' Choire Dhuibh
Type of Asset/Event	Ditch
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256553
Northing	881335
Council	Highland
Condition:	Good
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat grip (drainage ditch) measuring 1-1.5m wide and c1m deep, c100m long but continues outwith survey corridor to the W, excavated into the SE-facing slope that forms the Coire Dubh, draining the peat wetland into the Allt a' Choire Dhuibh to the SE. Still in use.

Asset/Event Number	951.5
Asset/Event Name	Ditch, Allt a' Choire Dhuibh
Type of Asset/Event	Ditch
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256608
Northing	881403
Council	Highland

Condition:	Good
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat grip (drainage ditch) measuring 1-1.5m wide and c1.2m deep, c120m long but continues outwith survey corridor to the W, excavated into the SE-facing slope that forms the Coire Dubh, draining the peat wetland into the Allt a' Choire Dhuibh to the SE. Still in use.

Asset/Event Number	952
Asset/Event Name	Hut circle, Creagan a' Choin Ruaidh
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256057
Northing	886368
Council	Highland
Condition:	Very degraded
Alignment:	Circular
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible hut circle under heather, measures c11m by 8m with very poorly defined banks that stand c0.3m tall and spread 1m wide. No discernible entrance.

Asset/Event Number	953
Asset/Event Name	Hut circle, Creagan a' Choin Ruaidh
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256206
Northing	886134
Council	Highland
Condition:	Very degraded
Alignment:	Circular
Importance:	Low

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible hut circle under heather, measures c12m in diamater with very poorly defined banks that stand c0.2m tall and spread c1m wide. No discernible entrance.

Asset/Event Number	954
Asset/Event Name	Clearance cairn, Muir of Fairburn
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247574
Northing	852800
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Large spread of field clearance and earth forming mound 10m in diameter and 4m tall, partially under moss and grass.

Asset/Event Number	955.1
Asset/Event Name	Ditch, Allt Buidheachean
Type of Asset/Event	Ditch
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256643
Northing	870462
Council	Highland
Condition:	Fair
Alignment:	ESE/WNW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat creep (drainage ditch) 0.5-0.8m wide and of undetermined depth, c100m long, used for draining peat into the Allt Buidheaneach to the S. These are very regular and straight in form, suggesting that they have been excavated mechanically, and may be of a younger date than those on the S side of the water course (Asset 336 group). Not depicted on historic maps.

Asset/Event Number	955.10
Asset/Event Name	Ditch, Allt Buidheachean
Type of Asset/Event	Ditch
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256831
Northing	870543
Council	Highland
Condition:	Fair
Alignment:	ESE/WNW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat creep (drainage ditch) 0.5-0.8m wide and of undetermined depth, c130m long, used for draining peat into the Allt Buidheaneach to the S. These are very regular and straight in form, suggesting that they have been excavated mechanically, and may be of a younger date than those on the S side of the water course (Asset 336 group). Not depicted on historic maps.

Asset/Event Number	955.2
Asset/Event Name	Ditch, Allt Buidheachean
Type of Asset/Event	Ditch
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256698
Northing	870461
Council	Highland
Condition:	Fair
Alignment:	ESE/WNW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat creep (drainage ditch) 0.5-0.8m wide and of undetermined depth, c235m long, used for draining peat into the Allt Buidheaneach to the S. These are very regular and straight in form, suggesting that they have been excavated mechanically, and may be of a younger date than those on the S side of the water course (Asset 336 group). Not depicted on historic maps.

Asset/Event Number	955.3
Asset/Event Name	Ditch, Allt Buidheachean
Type of Asset/Event	Ditch
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256705
Northing	870477
Council	Highland
Condition:	Fair
Alignment:	ESE/WNW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat creep (drainage ditch) 0.5-0.8m wide and of undetermined depth, c200m long, used for draining peat into the Allt Buidheaneach to the S. These are very regular and straight in form, suggesting that they have been excavated mechanically, and may be of a younger date than those on the S side of the water course (Asset 336 group). Not depicted on historic maps.

Asset/Event Number	955.4
Asset/Event Name	Ditch, Allt Buidheachean
Type of Asset/Event	Ditch
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256716
Northing	870488
Council	Highland
Condition:	Fair
Alignment:	ESE/WNW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat creep (drainage ditch) 0.5-0.8m wide and of undetermined depth, c180m long, used for draining peat into the Allt Buidheaneach to the S. These are very regular and straight in form, suggesting that they have been excavated mechanically, and may be of a younger date than those on the S side of the water course (Asset 336 group). Not depicted on historic maps.

Asset/Event Number	955.5

Asset/Event Name	Ditch, Allt Buidheachean
Type of Asset/Event	Ditch
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256737
Northing	870503
Council	Highland
Condition:	Fair
Alignment:	ESE/WNW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat creep (drainage ditch) 0.5-0.8m wide and of undetermined depth, c120m long, used for draining peat into the Allt Buidheaneach to the S. These are very regular and straight in form, suggesting that they have been excavated mechanically, and may be of a younger date than those on the S side of the water course (Asset 336 group). Not depicted on historic maps.

Asset/Event Number	955.6
Asset/Event Name	Ditch, Allt Buidheachean
Type of Asset/Event	Ditch
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256825
Northing	870473
Council	Highland
Condition:	Fair
Alignment:	ESE/WNW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat creep (drainage ditch) 0.5-0.8m wide and of undetermined depth, c60m long, used for draining peat into the Allt Buidheaneach to the S. These are very regular and straight in form, suggesting that they have been excavated mechanically, and may be of a younger date than those on the S side of the water course (Asset 336 group). Not depicted on historic maps.

Asset/Event Number	955.7
Asset/Event Name	Ditch, Allt Buidheachean

Type of Asset/Event	Ditch
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256751
Northing	870537
Council	Highland
Condition:	Fair
Alignment:	ESE/WNW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat creep (drainage ditch) 0.5-0.8m wide and of undetermined depth, c260m long, used for draining peat into the Allt Buidheaneach to the S. These are very regular and straight in form, suggesting that they have been excavated mechanically, and may be of a younger date than those on the S side of the water course (Asset 336 group). Not depicted on historic maps.

Asset/Event Number	955.8
Asset/Event Name	Ditch, Allt Buidheachean
Type of Asset/Event	Ditch
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256766
Northing	870547
Council	Highland
Condition:	Fair
Alignment:	ESE/WNW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat creep (drainage ditch) 0.5-0.8m wide and of undetermined depth, c250m long, used for draining peat into the Allt Buidheaneach to the S. These are very regular and straight in form, suggesting that they have been excavated mechanically, and may be of a younger date than those on the S side of the water course (Asset 336 group). Not depicted on historic maps.

Asset/Event Number	955.9
Asset/Event Name	Ditch, Allt Buidheachean
Type of Asset/Event	Ditch
Date and/or Period	Modern

Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256821
Northing	870532
Council	Highland
Condition:	Fair
Alignment:	ESE/WNW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat creep (drainage ditch) 0.5-0.8m wide and of undetermined depth, c130m long, used for draining peat into the Allt Buidheaneach to the S. These are very regular and straight in form, suggesting that they have been excavated mechanically, and may be of a younger date than those on the S side of the water course (Asset 336 group). Not depicted on historic maps.

Asset/Event Number	955.11
Asset/Event Name	Ditch, Allt Buidheachean
Type of Asset/Event	Ditch
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256846
Northing	870557
Council	Highland
Condition:	Fair
Alignment:	ESE/WNW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat creep (drainage ditch) 0.5-0.8m wide and of undetermined depth, c130m long, used for draining peat into the Allt Buidheaneach to the S. These are very regular and straight in form, suggesting that they have been excavated mechanically, and may be of a younger date than those on the S side of the water course (Asset 336 group). Not depicted on historic maps.

Asset/Event Number	955.12
Asset/Event Name	Ditch, Allt Buidheachean
Type of Asset/Event	Ditch
Date and/or Period	Modern
Listing No./NRHE Number	N/A

HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256858
Northing	870573
Council	Highland
Condition:	Fair
Alignment:	ESE/WNW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat creep (drainage ditch) 0.5-0.8m wide and of undetermined depth, c130m long, used for draining peat into the Allt Buidheaneach to the S. These are very regular and straight in form, suggesting that they have been excavated mechanically, and may be of a younger date than those on the S side of the water course (Asset 336 group). Not depicted on historic maps.

Asset/Event Number	955.13
Asset/Event Name	Ditch, Allt Buidheachean
Type of Asset/Event	Ditch
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256880
Northing	870578
Council	Highland
Condition:	Fair
Alignment:	ESE/WNW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat creep (drainage ditch) 0.5-0.8m wide and of undetermined depth, c60m long, used for draining peat into the Allt Buidheaneach to the S. These are very regular and straight in form, suggesting that they have been excavated mechanically, and may be of a younger date than those on the S side of the water course (Asset 336 group). Not depicted on historic maps.

Asset/Event Number	955.14
Asset/Event Name	Ditch, Allt Buidheachean
Type of Asset/Event	Ditch
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	N/A
Easting	256893
Northing	870589
Council	Highland
Condition:	Fair
Alignment:	ESE/WNW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat creep (drainage ditch) 0.5-0.8m wide and of undetermined depth, c40m long, used for draining peat into the Allt Buidheaneach to the S. These are very regular and straight in form, suggesting that they have been excavated mechanically, and may be of a younger date than those on the S side of the water course (Asset 336 group). Not depicted on historic maps.

Asset/Event Number	955.15
Asset/Event Name	Ditch, Allt Buidheachean
Type of Asset/Event	Ditch
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256909
Northing	870599
Council	Highland
Condition:	Fair
Alignment:	ESE/WNW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat creep (drainage ditch) 0.5-0.8m wide and of undetermined depth, used for draining peat into the Allt Buidheaneach to the S. These are very regular and straight in form, suggesting that they have been excavated mechanically, and may be of a younger date than those on the S side of the water course (Asset 336 group). Not depicted on historic maps.

Asset/Event Number	956
Asset/Event Name	Invershin Castle, Invershin
Type of Asset/Event	Castle
Date and/or Period	Medieval
Listing No./NRHE Number	NH59NE 2
HER Number	MHG12913
Status	Non-designated Heritage Asset

Section:	N/A
Easting	257270
Northing	896365
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Low/Medium
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large grassy mound c40m in diameter and standing to a height of c4m. This comprises the motte for the medieval castle of Invershin. As described in the NRHE/HER. Https://her.highland.gov.uk/monument/MHG12913 The Castle of Invershin or Duffus, has almost entirely disappeared. The mound on which it was placed stands on the bank above Kyle, some 14' in height on landward side. It has been surrounded by a ditch. RCAHMS 1911, visited 1909. The castle mound of Invershin Castle (name verified) occurs on S end of a gravel spur commanding flood plain of the Kyle of Sutherland; here valley is relatively narrow being an obvious crossing point. The mound, now overgrown with scrub, is of typical "motte-like" proportions, 4m maximum height, formed by upcast from dry ditch which surrounds it on 3 sides; fourth SW arc is defended by steep natural slopes of the spur. The flattened summit area is disturbed, probably by stone-robbing, and only remains of stone-walling in situ is a turf-covered fragment, 0.3m high, in NW corner. Insufficient work survives to enable positive identification as a castle. There is no local knowledge of history of Invershin Castle. The name "Castle of Duffus" (RCAHMS refers) suggests an association with Castle Duffus in Moray (NH16NE 4) a 12th century stronghold of de Moravias. A branch of this family, the forebears of the Sutherlands, settled at Dunrobin (NC80SE 1) in 12th century. On balance this work would appear to be a 12th century motte without bailey, probably surmounted by a stone castle; whether the castle would be contemporary with the erection of the mound is uncertain. Revised at 1/2500. Visited by OS (N K B) 7 .1.1977. 1st ed OS shows squarish ditch in wood, labelled "fosse" on N 7 S sides. Looks like N wall survives in centre with a tower at either end. - HAW 10/2002 Sources/Archives (4) --- SHG1131 Text/Publication/Article: Yeoman, P A. 1988. 'Mottes in Northeast Scotland', Scot Archaeol Rev Vol. 5 1988, p.125-33. Scot Archaeol Rev. 125-33. 131, no. 100. --- SHG24259 Image/Photograph(s): Highland Council Archaeology Unit. HCAU Slide Collection Sheet 8. Colour slide. . Digital (scanned). 162,169. --- SHG24360 Image/Photograph(s): Highland Council Archaeology Unit. HCAU Slide Collection Sheet 11. Colour slide. . Digital (scanned). 208, 214. --- SHG2657 Text/Report: RCAHMS. 1911. The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. . 36, No. 100.

Asset/Event Number	957
Asset/Event Name	Building, Coul Of Fairburn Farm
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	N/A
Easting	247470
Northing	853531
Council	Highland
Condition:	Good
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Private two-storey dwelling, in use as such. A roofed building is first depicted on the 1967 OS map. Measures c10m by 5m. OS. 1967. NH4653-NH4753 - AA, Revised: 1966, Published: 1967

Asset/Event Number	959
Asset/Event Name	Track, Badenahauglish
Type of Asset/Event	Track
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	291337
Northing	910928
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Track under grass and heather, measuring 2.5m wide and leading SW downhill towards the settlement of Badenahauglish. Spans the survey corridor and continues outwith it to the N and S. Not on historic maps.

Asset/Event Number	960
Asset/Event Name	Dyke, Aberscross
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG13311
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276494

Northing	900352
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass. Stands 0.6m tall and spread up to 0.5m wide, c20m long. Falls within the HER extent for MHG133311 but may be related to the track construction as only a small segment survives. Https://her.highland.gov.uk/monument/MHG13311

Asset/Event Number	961
Asset/Event Name	Dyke, Uaigh Bheag
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293646
Northing	913988
Council	Highland
Condition:	Fair
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Turf and stone dyke and bracken and grass, c100m long and stands 0.7m tall and spread up to 1m wide. Not depicted on historic mapping.

Asset/Event Number	962
Asset/Event Name	Probable Kerb Cairn, Ardochy
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH44SE 17
HER Number	MHG2741
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	245851
Northing	843290
Council	Highland

Condition:	Fair
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Possible kerb cairn. Low roughly oval mound c 8m in diameter with one or two visible stones, but otherwise overgrown by grass and heather. Located within mature forest. Some overgrown upright stones, possibly the kerb stones mentioned by the HER. Https://her.highland.gov.uk/monument/MHG2741 The cairn is situated near the top of a gentle E-facing slope in Ardochy Woods. It survives as a low mound, some 1.5m high, surrounded by an incomplete kerb of boulders some 6m in diameter. In the centre of the cairn is an overgrown hole, perhaps caused by the collapse of a lintel stone or by an early attempt at excavation. R Noble and G Harden 1987. --- SHG202 Text/Publication/Article: Noble and Harden, R and G. 1987. 'Ardochy Woods(Kilmorack parish) burial cairn', Discovery and Excavation in Scotland 1987, p.26. Discovery and Excavation in Scotland. 26. 26.

Asset/Event Number	963
Asset/Event Name	(possible) Kerb cairn, Beinn na Meilich
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	295574
Northing	916591
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Low/Medium
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A cairn under moss and heather, measures 8-10m in diameter and stands 1m tall. It appears as a small but pronounced mound situated on the steep slope midway up Bheinn Mhealaich at 260m AOD, far above the areas more suitable for cultivation in the lower lying reaches of the strath. A possible kerb of stones extends along the edges of the cairn, discerned more underfoot over the vegetation than by eye, though one larger stone clearly was visible at the NW side. The asset commands impressive views north over Strath Ullie. Tentatively interpreted as a kerb cairn, not previous recorded.

Asset/Event Number	964
Asset/Event Name	Clearance cairn, Beinn na Meilich
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric

Listing No./NRHE Number	N/A
HER Number	MHG11533(?)
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	295698
Northing	916690
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible clearance cairn under tall bracken and grass. Measures 5m by 4m and 1.3m tall.

Asset/Event Number	965.1
Asset/Event Name	Bank, Beinn Mhealaich
Type of Asset/Event	Bank
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG11533(?)
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	295732
Northing	916692
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A semicircular bank of possible stone and turf under grass and bracken, open to the NE. The bank is spread up to 3m wide and stands 1.1m tall, c14m long, and difficult to discern given the sloping ground. Possibly remnants of a very degraded structure or turf pen.

Asset/Event Number	965.2
Asset/Event Name	Mound, Beinn na Meilich
Type of Asset/Event	Mound
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	MHG11533(?)
Status	Non-designated Heritage Asset
Section:	A1.5

Easting	295737
Northing	916708
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A mound under grass measuring 4m in diameter and stands to 0.5m tall. Possibly a clearance cairn.

Asset/Event Number	965.3
Asset/Event Name	Improved ground, Beinn na Meilich
Type of Asset/Event	Field system
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG11533(?)
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	295737
Northing	916703
Council	Highland
Condition:	Very Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of improved ground under short grass c60m by 30m, likely underlying a possible settlement though up standing remains are very ephemeral (and separated into diminutives of Asset 507).

Asset/Event Number	966
Asset/Event Name	Hut circle, Beinn na Meilich
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	295950
Northing	916746
Council	Highland
Condition:	Very degraded
Alignment:	Circular

Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible hut circle under tall grass and bracken bank, c12m diameter with banks 0.7m tall and spread up to 2m wide. The bank is irregular on the NE side and reduced to ground level in a gap of c3m, possibly the original entrance that has been degraded over time.

Asset/Event Number	967
Asset/Event Name	Earthwork, Oulmsdale Burn
Type of Asset/Event	Earthwork
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	296591
Northing	916844
Council	Highland
Condition:	Very degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Possible earthwork feature built on a low mound above the Oulmsdale Burn. Under dense bracken and difficult to discern the form, perhaps 10m by 7m over the possible banks. The mound is c4m tall on the stream-ward side. Appears incongruous in the landscape. Uncertain function, and not depicted on historic mapping.

Asset/Event Number	968.1
Asset/Event Name	Peat cutting, Eldrable Burn
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval/Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	297094
Northing	916791
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Area of peat cutting under heather, c210, by 120m, banks standing to 0.8m in parts. Some fresh cutting evident.

Asset/Event Number	968.2
Asset/Event Name	Peat cutting, Eldrable Burn
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval/Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	297350
Northing	916783
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Area of peat cutting under heather, c220m by 90m (extends outwith survey corridor to N), banks standing to 0.8m in parts. Some fresh cutting evident.

Asset/Event Number	969
Asset/Event Name	Track, Eldrable Burn
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	297415
Northing	916675
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A track over peat and heather, bare peat in some sections, heading between the bealach to the SE and them curving to the NW. 2m wide. Spans the corridor and continues outwith it to the N and S. Appears to connect with the track Asset 874.2, but is not depicted on historic mapping.

Asset/Event Number	970

Asset/Event Name	Peat cutting, Lower Caen
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	301403
Northing	917686
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small rectangular area of peat cutting under heather and grass, measuring 13m by 6m and 0.25m deep. Dis-used.

Asset/Event Number	971.1
Asset/Event Name	Track, Caen
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	301505
Northing	918160
Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A track c2.5m wide, under bracken and grass, and somewhat sunken. C130m long and adjoins track Asset 971.2 and leads SE to the Caen farmstead (Asset 159). Not depicted on historic mapping.

Asset/Event Number	971.2
Asset/Event Name	Track, Caen
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	A1.5
Easting	301612
Northing	917940
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	Track c2-3m wide, under bracken and grass, and somewhat sunken. An adjacent bank on the W side stands 0.7m tall and spread perhaps 1.5m wide, likely formed from the upcast of the track construction. Spans corridor and extends outwith it the NW and SE. Track adjoins track Asset 971.1 and leads SE to the Caen farmstead (Asset 159).

Asset/Event Number	1001
Asset/Event Name	Peat cutting, Breakachy Hill
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.2 (in access track corridor to section)
Easting	244736
Northing	844021
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under heather and grass, c150m by 95m, cut NW/SE and 0.7m deep at deepest point. Dis-used. Relict track (Asset 784) appears to this from Breakachy Farm to the east.

Asset/Event Number	1002
Asset/Event Name	Boundary ditch, Achalone
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1 (in access track corridor to section)
Easting	316079

Northing	956525
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A boundary ditch under grass, measuring 3m wide and 1.5m deep with a steep-sided U-shaped profile, c270m long and also used for drainage. A stone built culvert (Asset 1006) stands at the SE end to take water below the adjacent road. Depicted on the 1st edition OS map. OS. 1877. Caithness XVIII Surveyed: 1871, Published: 1877.

Asset/Event Number	1003
Asset/Event Name	Track, Achalone
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1 (in access track corridor to section)
Easting	316088
Northing	956524
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A relict track c2m wide under heather and grass, extends c270m long alongside the ditch (Asset 1002). It leads to the modern auto racing track (Asset 1012; only partly surveyed) to the north. The adjacent ditch (Asset 1002) is depicted on the 1st edition OS map, but this track is not. OS. 1877. Caithness XVIII Surveyed: 1871, Published: 1877.

Asset/Event Number	1004
Asset/Event Name	Boundary ditch, Achalone
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1 (in access track corridor to section)
Easting	315965
Northing	956445

Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A boundary ditch under grass. Measures 3m wide and 1.5m deep with a steep-sided U-shaped profile, c270m long and also used for drainage. Depicted on the 1st edition OS map. OS. 1877. Caithness XVIII Surveyed: 1871, Published: 1877.

Asset/Event Number	1005
Asset/Event Name	Boundary ditch, Achalone
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1 (in access track corridor to section)
Easting	315706
Northing	956608
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A boundary ditch under grass, measuring 3m wide and 1.5m deep with a steep-sided U-shaped profile, continues out of survey corridor to NW. Depicted on the 1st edition OS map. Extends outwith survey corridor to the NW. OS. 1877. Caithness XVIII Surveyed: 1871, Published: 1877.

Asset/Event Number	1006
Asset/Event Name	Culvert, Banniskirk
Type of Asset/Event	Other
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1 (in access track corridor to section)
Easting	316157
Northing	956413
Council	Highland
Condition:	Good

Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone-built culvert under grass, into which the field boundary ditch Asset 1002 leads. The culvert has been constructed with flat-laid Caithness flagstone presenting a face c1.4m tall and 1.5m wide, the width of which is uncertain due to vegetation atop it, with a concrete pipe extending through it to drain water below the adjacent road. Although not depicted on the 1st edition OS map, the boundary ditch (Asset 1002) is. OS. 1877. Caithness XVIII Surveyed: 1871, Published: 1877.

Asset/Event Number	1007
Asset/Event Name	Boundary ditch, Achalone
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1
Easting	315871
Northing	956638
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A boundary ditch under grass, measuring 2.5m wide and 0.5m deep and c660m long, likely also for drainage. Depicted on the 1st edition OS map, but has a slight dog-leg at the NE end to meet ditch Asset 778 that appears to diverge from historic maps. OS. 1877. Caithness XVIII Surveyed: 1871, Published: 1877.

Asset/Event Number	1008.1
Asset/Event Name	Building, Achalone
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND15NE 21.00
HER Number	MHG19155
Status	Non-designated Heritage Asset
Section:	A1.1 (directly adjacent to access track corridor to section)
Easting	315648
Northing	956575
Council	Highland
Condition:	Degraded

Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone footings for a rectangular building under grass, measuring c25m by 5m over walls which stand up to 0.5m tall. Two internal partitions defining three rooms, possible ancillary structures along the SW elevation, and a corn-drying kiln constructed in the S end, which stands c4.5m in diameter and 1.3m tall (flue not discernible). Entrances not clearly discernible. Forms a small farmstead with building Asset 1008.3 and field system Asset 1008.2. Depicted on the 1st edition OS map as unroofed. OS. 1877. Caithness XVIII Surveyed: 1871, Published: 1877.

Asset/Event Number	1008.2
Asset/Event Name	Field system, Achalone
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND15NE 21.00
HER Number	MHG19155
Status	Non-designated Heritage Asset
Section:	A1.1 (in access track corridor to section)
Easting	315631
Northing	956560
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Remnants of a raised cultivated area under grass, measuring c50m by 40m. Entirety is somewhat elevated from the surrounds (by 0.5-0.8m), with a ditch defining the outer edge and the upcast of this forming a bank within. Forms part of a small post-medieval farmstead with associated buildings Asset 1008.1 and 1008.3 to the E. Depicted on the 1st editions OS map. OS. 1877. Caithness XVIII Surveyed: 1871, Published: 1877.

Asset/Event Number	1008.3
Asset/Event Name	Building, Achalone
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND15NE 21.00
HER Number	MHG19155
Status	Non-designated Heritage Asset
Section:	A1.1 (in access track corridor to section)
Easting	315667
Northing	956584
Council	Highland

Condition:	Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone footings for a rectangular building under grass and rushes, measuring c8m by 5m over walls. No entrances discernible. Forms part of a small farmstead with building Asset 1008.1 and cultivated area 1008.2 to W. Depicted on the 1st edition OS map as unroofed. OS. 1877. Caithness XVIII Surveyed: 1871, Published: 1877.

Asset/Event Number	1009.1
Asset/Event Name	Ditch, Achalone
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1 (in access track corridor to section)
Easting	315620
Northing	956633
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A narrow drainage ditch under grass, measures less than 0.5m wide/deep and c160m long. Visible as a series of fanning drainage ditches that lead to the main ditch Asset 1005. Although not depicted on the 1st edition OS map, these are likely associated with the larger post-medieval field enclosures there depicted, representing extensive drainage mechanisms for this farmland.

Asset/Event Number	1009.2
Asset/Event Name	Ditch, Achalone
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1
Easting	315603
Northing	956614
Council	Highland
Condition:	Degraded

Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A narrow drainage ditch under grass, measures less than 0.5m wide/deep and c115m long. Visible as a series of fanning drainage ditches that lead to the main ditch Asset 1005. Although not depicted on the 1st edition OS map, these are likely associated with the larger post-medieval field enclosures there depicted, representing extensive drainage mechanisms for this farmland.

Asset/Event Number	1009.3
Asset/Event Name	Drainage ditch, Achalone
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1 (in access track corridor to section)
Easting	315858
Northing	956565
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A narrow drainage ditch under grass, measures less than 0.5m wide/deep and c25m long. Visible as a series of fanning drainage ditches that lead to the main ditch Asset 1005. Although not depicted on the 1st edition OS map, these are likely associated with the larger post-medieval field enclosures there depicted, representing extensive drainage mechanisms for this farmland.

Asset/Event Number	1009.4
Asset/Event Name	Drainage ditch, Achalone
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1 (in access track corridor to section)
Easting	315727
Northing	956534
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A narrow drainage ditch under grass, measures less than 0.5m wide/deep and c150m long. Visible as a series of fanning drainage ditches that lead to the main ditch Asset 1005. Although not depicted on the 1st edition OS map, these are likely associated with the larger post-medieval field enclosures there depicted, representing extensive drainage mechanisms for this farmland.

Asset/Event Number	1009.5
Asset/Event Name	Drainage ditch, Achalone
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1 (in access track corridor to section)
Easting	315760
Northing	956547
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A narrow drainage ditch under grass, measures less than 0.5m wide/deep and c75m long. Visible as a series of fanning drainage ditches that lead to the main ditch Asset 1005. Although not depicted on the 1st edition OS map, these are likely associated with the larger post-medieval field enclosures there depicted, representing extensive drainage mechanisms for this farmland.

Asset/Event Number	1009.6
Asset/Event Name	Drainage ditch, Achalone
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1 (in access track corridor to section)
Easting	315804
Northing	956534
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A narrow drainage ditch under grass, measures less than 0.5m wide/deep and c65m long. Visible as a series of

fanning drainage ditches that lead to the main ditch Asset 1005. Although not depicted on the 1st edition OS map, these are likely associated with the larger post-medieval field enclosures there depicted, representing extensive drainage mechanisms for this farmland.

Asset/Event Number	1009.7
Asset/Event Name	Drainage ditch, Achalone
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1 (in access track corridor to section)
Easting	315782
Northing	956536
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A narrow drainage ditch under grass, measures less than 0.5m wide/deep and c85m long. Visible as a series of fanning drainage ditches that lead to the main ditch Asset 1005. Although not depicted on the 1st edition OS map, these are likely associated with the larger post-medieval field enclosures there depicted, representing extensive drainage mechanisms for this farmland.

Asset/Event Number	1009.8
Asset/Event Name	Drainage ditch, Achalone
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1 (in access track corridor to section)
Easting	315836
Northing	956574
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A narrow drainage ditch under grass, measures less than 0.5m wide/deep and c18m long. Visible as a series of fanning drainage ditches that lead to the main ditch Asset 1005. Although not depicted on the 1st edition OS map, these are likely associated with the larger post-medieval field

enclosures there depicted, representing extensive drainage mechanisms for this farmland.

Asset/Event Number	1009.9
Asset/Event Name	Drainage ditch, Achalone
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1 (in access track corridor to section)
Easting	315686
Northing	956504
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A narrow drainage ditch under grass, measures less than 0.5m wide/deep and c55m long. Visible as a series of fanning drainage ditches that lead to the main ditch Asset 1005. Although not depicted on the 1st edition OS map, these are likely associated with the larger post-medieval field enclosures there depicted, representing extensive drainage mechanisms for this farmland.

Asset/Event Number	1009.10
Asset/Event Name	Drainage ditch, Achalone
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1 (in access track corridor to section)
Easting	315709
Northing	956508
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A narrow drainage ditch under grass, measures less than 0.5m wide/deep and c75m long. Visible as a series of fanning drainage ditches that lead to the main ditch Asset 1005. Although not depicted on the 1st edition OS map, these are likely associated with the larger post-medieval field enclosures there depicted, representing extensive drainage mechanisms for this farmland.

Asset/Event Number	1009.11
Asset/Event Name	Drainage ditch, Achalone
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1 (in access track corridor to section)
Easting	315685
Northing	956482
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A narrow drainage ditch under grass, measures less than 0.5m wide/deep and c100m long. Visible as a series of fanning drainage ditches that lead to the main ditch Asset 1005. Although not depicted on the 1st edition OS map, these are likely associated with the larger post-medieval field enclosures there depicted, representing extensive drainage mechanisms for this farmland.

Asset/Event Number	1009.12
Asset/Event Name	Drainage ditch, Achalone
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1 (in access track corridor to section)
Easting	315651
Northing	956708
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A narrow drainage ditch under grass, measures less than 0.5m wide/deep and c50m long. Visible as a series of fanning drainage ditches that lead to the main ditch Asset 1005. Although not depicted on the 1st edition OS map, these are likely associated with the larger post-medieval field enclosures there depicted, representing extensive drainage mechanisms for this farmland.

Asset/Event Number	1010.1
Asset/Event Name	Peat cutting, Allt an Fheòir
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.2 (in access track corridor to section)
Easting	317654
Northing	947570
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A degraded peat bank under heather and grass, c60m by 5m and 0.5m deep.

Asset/Event Number	1010.2
Asset/Event Name	Peat cutting, Allt an Fheòir
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.2 (in access track corridor to section)
Easting	317687
Northing	947554
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A degraded peat bank under heather and grass, c65m long and visible as a cut against the slope c1m wide.

Asset/Event Number	1011
Asset/Event Name	Stone slab, Allt an Fheòir
Type of Asset/Event	Unknown
Date and/or Period	Unknown
Listing No./NRHE Number	N/A

HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	317647
Northing	947519
Council	Highland
Condition:	Unknown
Alignment:	N/A
Importance:	Low/Medium
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large flat stone, squarish in plan and measuring 1.5m by 1.3m and at least 0.3m thick, with possibly dressed edges, lies on a small terrace above the Allt an Fheòir, with some possible stone below. Were it not for the A9 it would command an extensive view over the broad topographic bowl to the W. Very tentatively identified as a possible cist capstone.

Asset/Event Number	1012
Asset/Event Name	Track, Achalone
Type of Asset/Event	Other
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1 (in access track corridor to section)
Easting	315855
Northing	956586
Council	Highland
Condition:	Fair
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large c6m wide stone-built track partly under grass, continuing outwith the survey corridor to the NE and NW. Extent recorded measures 160m long. Planning permission given in 2017 identifies this is an autocross track, construction for which appears to be incomplete. Planning reference: 16/04753/FUL.

Asset/Event Number	1013
Asset/Event Name	Building, Coillenaclay
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	N/A
Easting	246365
Northing	845368
Council	Highland
Condition:	Other
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Rectangular single-storey stone building measuring c35m by 5.5m over walls, the ends of which are ruinous and unroofed and partially under grass. A central portion is relatively well-preserved, measuring c20m long, stands below a pitched roof of corrugated iron sheets. Three c1.2m wide entrances are situated in the SE elevation. The building is currently in use as an agricultural store and direct access was not sought during the survey. The building is depicted on both the 1st and 2nd edition OS maps as one of two situated at the edge of an improved field, and named Coillenaclay. OS. 1876. Inverness (Mainland) X, Surveyed: 1872, Published 1876. OS. 1906. Inverness-shire - Mainland X, Surveyed: 1902:, Published: 1906.

Asset/Event Number	1014.1
Asset/Event Name	Building, Lady's Moss
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG19822
Status	Non-designated Heritage Asset
Section:	A1.1
Easting	318148
Northing	955369
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular building measuring c19m by 6m over walls, partly under grass with detritus in interior prohibiting access. Ruinous. The building is depicted as roofed on both the 1st and 2nd edition OS maps. A rectangular area of ground is depicted to the S; the kaleyard (Asset 1014.2) as described below; a well is also identified to the NE along the survey corridor but this was not identified during the walkover survey. OS. 1877. Caithness XVIII Surveyed: 1871, Published: 1877. OS. 1907. Caithness-shire XVIII. Surveyed: 1905, Published: 1907. https://her.highland.gov.uk/Monument/MHG19822 ND15NE 70 1814 5536Longhouse (ND 1815 5534). Dimensions: 18 x 6m. Tripartite rectangular structure, the NW unit containing fireplace, the remainder rubble-filled. Orientation NW-SE. Associated with a kaleyard 12 x 12m.R J Mercer, NMRS MS/828/19, 1995One building is depicted as roofed on the first edition of the OS 6-inch map (Caithness 1877, sheet xviii) and as unroofed on the current edition of the OS 1:10,560 map

(1971).Information from RCAHMS (FO) 19 March 1996A DBA and walkover survey was carried out by RPS Consultants in July 2006 in advance of a proposed wind farm development near Spittal, Caithness.Very degraded longhouse croft, only partially surviving beyond 1m above ground level. Outline of building remains clear. <1>

Asset/Event Number	1014.2
Asset/Event Name	Kale yard, Lady's Moss
Type of Asset/Event	Kale yard
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG19822
Status	Non-designated Heritage Asset
Section:	A1.1
Easting	318147
Northing	955359
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A turf and stone enclosure under grass, measuring c13m by 13m and with banks standing 0.3-0.4m tall, better defined along the SW extent, delineating a kaleyard. Depicted on the 1st and 2nd edition OS maps. See Asset 1014.1 for HER description. OS. 1907. Caithness-shire XVIII. Surveyed: 1905, Published: 1907.

Asset/Event Number	1015
Asset/Event Name	Building, possible byre - Aigas forest, Beauly
Type of Asset/Event	Building; Byre?
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG61614
Status	Non-designated Heritage Asset
Section:	
Easting	246047
Northing	842587
Council	Highland
Condition:	Unknown
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone footings for a building, possibly a byre, recorded in 2016; this asset could not be identified in dense bracken.

Https://her.highland.gov.uk/monument/MHG61614
The North of Scotland Archaeological Society (NoSAS) undertook a desk-based assessment followed by a walk-over survey at the request of Aigas Community Forest Trust in 2015/16. The forest was bought in April 2015 from the Forestry Commission under the Forestry Land Scheme. The Forest Trust was required to undertake an archaeological survey of the forest as part of its scoping for a Forest Design Plan. A variety of features were identified, many of which relate to the early years of the forest in mid-19th century.

Site 134. Building, possible byre. <1>
Note: Site not visible on aerial photographs so location approximate. (T. Blackie 4/3/20)
1st Edition OS 6" <2>
<1> SHG27485 Text/Report/Fieldwork Report: Spencer-Jones, R.. 2016. Archaeological Walk-over Survey of Aigas Community Forest. NOSAS. Digital. P.25,26. XY
<2> SHG23755 Image/Map: Ordnance Survey. 1873-6. Ordnance Survey 1st edition 6 inch map: Inverness-shire. Digital.

Asset/Event Number	1016
Asset/Event Name	Hut circle, Sgiathach
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251827
Northing	862814
Council	Highland
Condition:	Very Degraded
Alignment:	Circular
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible highly degraded hut circle, visible as a slightly circular depression defined by grass and surrounded by heather, some 8m in diameter. The banks are barely discernible, and no entrance is discernible. The asset is situated on a low mound with good views over the strath to the S.

Asset/Event Number	1017
Asset/Event Name	Farmhouse and Turbine House - Glensgaich, Fodderty
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG55845
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245957

Northing	860890
Council	Highland
Condition:	Derelict
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An abandoned two-storey house with two single-storey buildings extending from either gable end, the whole of which forms a broadly rectangular complex c30m by 6m, with modern buildings situated on the N side of the E building. The house and W building, a possible byre, are the older elements of the complex and are depicted on the 1st edition OS map. The E building is recorded as having been constructed as the turbine house for an early 20th century hydro scheme. A modern hydro scheme has been constructed in the E side. Https://her.highland.gov.uk/Monument/MHG55845 A farmhouse with adjoining turbine house at Glensgaich was visited by C Dagg during a walkover survey prior to a proposed hydro-electric scheme in 1999. It was described as a substantial farm house, though now derelict and vandalised, with a small outhouse attached to the west providing stabling. It had been extended to the rear and this intruded into the northwest corner of the turbine house. The turbine house, built for a hydro-electric scheme dating to 1904 had been constructed of granite rather than local stone. It was empty apart from two central trenches corresponding to the points of inflow and outflow at the front and back, with a small stone plinth between the two trenches. The hydro-electric scheme had been constructed for Colonel Blunt Mackenzie and although it came near to bankrupting the estate it did supply electricity for the shepherds house at Glenskaich, Castle Leod and some of the crofts along the Heights. It was subsequently bought by the Ross-shire Electrical Company and then taken over y the Grampian Electrical Company and finally the Hydro Board before falling out of use. <1> This site was noted in ARCH's Heritage Along the Kyle Line project in 2011. The house was part of a crofting township that was occupied within living memory. After 1834 the area was cleared for sheep, and later used for grouse shooting. In 1904 the Cromartie Estate installed a hydro-electric scheme, which served Castle Leod, the Heights and Strathpeffer Spa. This fell out of use, but a new hydro project built in the 1990s was providing electricity into the grid in 2011. The house at the right was the converted turbine house for this new hydro scheme. A post-medieval date was suggested as well as a grid reference of NH 45852 60914. <2> <1> SHG21516 Text/Report/Fieldwork Report: Dagg, C.. 1999. An Archaeological Survey of a proposed Hydro-Electric Scheme at Little Wyvis, Strathpeffer, Easter Ross. Unaffiliated. 18/08/1999. Paper (Original). <2> SHG25822 Dataset/Database File: Archaeology for Communities in the Highlands (ARCH). 2010-2012. Heritage Along the Kyle Line. Archaeology for Communities in the Highlands (ARCH). Yes. MDB. Site

Asset/Event Number	1018
Asset/Event Name	Enclosure, Eiden
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	273832

Northing	900663
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass, forming a broadly D-shaped enclosure in plan, c30m by 20m. Banks stand 0.3m tall and spread 1.5m wide. Depicted on the 1st edition OS map. OS. 1879. Sutherland CIV, Surveyed: 1873-4, Published: 1879

Asset/Event Number	1019
Asset/Event Name	Linear earthworks, Fanellan
Type of Asset/Event	Earthwork
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	MHG63024
Status	Non-designated Heritage Asset
Section:	
Easting	248165
Northing	842868
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Neglible
Description	*Observation by AOC Archaeology during 2024 walkover survey. No upstanding remains observed in tall grass within survey corridor. Https://her.highland.gov.uk/monument/MHG63024 The Inverness Field Club, led by Donald Coghill, surveyed a number of sites in the Aird area between 1987 and 1989. Fanellan. On a knoll and partly obscured by whins are traces of linear earthworks and on the flat ground below at the north side are the footings of a turf walled rectangular building. <1> NGR adjusted based on 1999-2001 vertical aerial photographs. <2> <1> SHG2356 Text/Manuscript: Jacks, S E (ed.). 1989. Some unrecorded sites in the Aird noted between Oct 1987 & May 1989. Inverness Field Club. Digital. Appendix 1b No.217. XY <2> SHG27491 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 1999-2001. Get Mapping colour vertical aerial photography 1999-2001 (The Millennium Map).

Asset/Event Number	1019
Asset/Event Name	Enclosure, Strath Sgitheach
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG40807; MHG8909

Status	Non-designated Heritage Asset
Section:	D1.2
Easting	252310
Northing	863782
Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A low linear bank c0.5-1m in width, and same again in height in some places, but mostly reduced to c0.25m height. Recorded extent measures c190m, but likely continues outwith survey corridor to the SE. Forms an enclosure that is depicted on the 1st edition OS map as containing improved ground. OS. 1880. Ross-shire & Cromartyshire (Mainland) LXXVI, Surveyed: 1875-6, Published: 1880 https://her.highland.gov.uk/Monument/MHG8909 This field boundary is a massive stone wall which has created a lynchet 1.5m high. This wall is 2m wide and stands between 0.5 - 1m high. It apparently relates to the nearby pre-improvement settlement (NH 56 SW 20), possibly it was the infield. Visited June 1989. Info from S T Driscoll and S M Foster (Mss, 4, No. 2.0.) 1989. https://her.highland.gov.uk/Monument/MHG40807 [Note that this appears to be a duplication of Asset 736/MHG8918 and not related to Asset 1019, despite the HER extent depiction] A three-roomed cottage, apparently of dry-stone construction, standing in cleared ground. (see also NH 56 SW 29). Visited September 1978. RCAHMS 1979, visited September 1978. A farmstead comprising an unroofed long building of three compartments and an enclosure or field are depicted on the 1st edition of the OS 6-inch map (Ross-shire and Cromartyshire 1881, sheet lxxvi). The unroofed building is shown on the current edition of the OS 1:10560 map (1969). Information from RCAHMS (SAH) 1 March 1996

Asset/Event Number	1021
Asset/Event Name	Track, Strathcarron Wood
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	C1.2
Easting	255749
Northing	891870
Council	Highland
Condition:	Degraded
Alignment:	Various

Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A track under bracken and grass, measures c3m wide but obscured by vegetation and forestry, c90m long but continues outwith survey corridor to the NW. Mounded in the middle with two shallow ditches running along either side. Appears partially consistent with a track depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) XVIII, Surveyed: 1877, Published: 1881

Asset/Event Number	1022
Asset/Event Name	Dyke, Leacdhu Beag
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	255599
Northing	891264
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A degraded stone and turf dyke under grass, measures 60m but disappears into dense vegetation to E and W. Stands 0.7m tall and spread up to 1m wide. Depicted on 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) XXVI, Surveyed: 1875, Published: 1881

Asset/Event Number	1023
Asset/Event Name	Quarry, Glensgaich
Type of Asset/Event	Quarry
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245434
Northing	860781
Council	Highland
Condition:	Fair
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large quarry pit measuring

	20m by 8m and 2m deep, under grass. It extends off the side of a modern forestry track and may be associated with its construction.

Asset/Event Number	1024
Asset/Event Name	Quarry, Muir of Fairburn
Type of Asset/Event	Quarry
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	247085
Northing	851053
Council	Highland
Condition:	Fair
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Large quarry/borrow pit, 17m by 14m and 5m deep. Situated to S of established track, possible related to track construction.

Asset/Event Number	1025
Asset/Event Name	Numerous prehistoric assets, Farley SW end
Type of Asset/Event	Various
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	Various
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	245655
Northing	845650
Council	Highland
Condition:	Unknown
Alignment:	Various
Importance:	Low/Medium
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Placeholder polygon. This area was under dense heather and bracken vegetation at the time of the survey, with limited time available for survey, and the numerous prehistoric assets within could not be accurately surveyed. Assets included are: Asset 901.4/3240/MHG61221, 3294/MHG2659, 901.3/3295/MHG62070, 3296/MHG62071, 3297/MHG62072, 901.5/3298/MHG61222, 3299/MHG62073, 3300/MHG62074, 3301/MHG62075, 3302/MHG62076, 3303/MHG62077, 3304/MHG62078, 3305/MHG62079, 3313/MHG62087, 901.1/3314/MHG62088,

	3315/MHG62089, 3341/MHG62118, 3347/MHG62125, 3364/MHG62144, 3365/MHG62145, 3366/MHG62146, 901.2/3667/MHG62090

Asset/Event Number	1026
Asset/Event Name	Numerous prehistoric assets, Farley SW end
Type of Asset/Event	Various
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	Various
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	245491
Northing	845465
Council	Highland
Condition:	Unknown
Alignment:	Various
Importance:	Low/Medium
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Placeholder polygon. This area was under dense heather and bracken vegetation at the time of the survey, with limited time available for survey, and the numerous prehistoric assets within could not be accurately surveyed. Assets included are: 3207/MHG61219, 3208/MHG61218, 3209/MHG61217, 3210/MHG61216, 3211/MHG61215, 3212/MHG61214, 3213/MHG61220, 3214/MHG61350, 3241/MHG44150, 3288/MHG23303, 3289/902/903/127/MHG2665, 3290/MHG2666, 3291/MHG62068, 3292/MHG62069, 3293/MHG62050, 3316/MHG62091, 3317/MHG62092, 3318/MHG62093, 3319/MHG62094, 3320/MHG62095, 3321/MHG62096, 3322/MHG62097, 3323/MHG62099, 3324/MHG62100, 3326/MHG62102, 3327/MHG62103, 3336/MHG62112, 3337/MHG62113, 3338/MHG62114, 3339/MHG62116, 3340/MHG62117, 3342/MHG62119, 3343/MHG62120, 3346/MHG62124, 3349/MHG62127, 3350/MHG62128, 3351/MHG62129, 3352/MHG62130, 3353/MHG62131, 3355/MHG62133, 3356/MHG62134, 3357/MHG62115, 3358/MHG62135, 3359/MHG62136, 3360/MHG62137, 3361/MHG44153, 3668/MHG62138.

Asset/Event Number	1027
Asset/Event Name	Dyke, Bridgepark
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246937
Northing	851344
Council	Highland

Condition:	Very degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A length of degraded rubble bank c20m long and arching under dense bracken and grass. Stands up to 0.3m tall and spread 1m wide, appears fairly robbed out. May have formed part of an enclosure but now mostly gone. Not depicted on historic maps.

Asset/Event Number	1028
Asset/Event Name	Farmstead, Langergill
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND15SE 58?
HER Number	MHG37500?
Status	Non-designated Heritage Asset
Section:	A1.1
Easting	318721
Northing	954924
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A farmstead is depicted on the 1st edition OS map comprising two roofed buildings, two enclosures and a well, and is similarly depicted on the 2nd edition OS map. No trace of this could be discerned during the walkover survey. It is unclear if the NRHE and HER points (MHG37500 and ND15SE 58.00; for a 'house') recorded to the SW are intended for this asset as there is no description on either. OS. 1877. Caithness XVIII Surveyed: 1871, Published: 1877. OS. 1907. Caithness-shire XVIII. Surveyed: 1905, Published: 1907.

Asset/Event Number	1500
Asset/Event Name	Sletdale Burn
Type of Asset/Event	Hut Circle Settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10025
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293435
Northing	912759
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10025

Asset/Event Number	1501
Asset/Event Name	Bridge, Carradh nan Clach
Type of Asset/Event	Arch Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10032
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293780
Northing	912710
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10032

Asset/Event Number	1502
Asset/Event Name	Hut circle, Creag Riabhach
Type of Asset/Event	Hut Circle; Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10034
Status	Non-designated Heritage Asset
Section:	N/A
Easting	294580
Northing	911430
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10034

Asset/Event Number	1503
Asset/Event Name	Homestead, Carradh Nan Clach

Type of Asset/Event	Homestead
Date and/or Period	Prehistoric/Early Historic
Listing No./NRHE Number	<Null>
HER Number	MHG10035
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293960
Northing	912560
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10035

Asset/Event Number	1504
Asset/Event Name	Homestead, Druim Dearg
Type of Asset/Event	Homestead?; Wag?; Longhouse
Date and/or Period	Prehistoric/Early Historic
Listing No./NRHE Number	<Null>
HER Number	MHG10036
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293480
Northing	913770
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10036

Asset/Event Number	1505
Asset/Event Name	Hut circle, Uaigh Bheag
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10037
Status	Non-designated Heritage Asset
Section:	N/A
Easting	294140

Northing	914370
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10037

Asset/Event Number	1506
Asset/Event Name	Hut circle? Carradh Nan Clach
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10038
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293960
Northing	912480
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10038

Asset/Event Number	1507
Asset/Event Name	Creag Riabhach
Type of Asset/Event	Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10039
Status	Non-designated Heritage Asset
Section:	N/A
Easting	294215
Northing	911100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10039

Asset/Event Number	1508
Asset/Event Name	Cairn, Carradh Nan Clach
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10041
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293980
Northing	912480
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10041

Asset/Event Number	1509
Asset/Event Name	Carradh Nan Clach
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10042
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293850
Northing	912560
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10042

Asset/Event Number	1510
Asset/Event Name	Hut circle, Coille Bad Mheasain
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10045

Status	Non-designated Heritage Asset
Section:	N/A
Easting	293680
Northing	913380
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10045

Asset/Event Number	1511
Asset/Event Name	Coille Bad Mheasain
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10046
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293896
Northing	913417
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10046

Asset/Event Number	1512
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	
Easting	
Northing	
Council	
Condition:	
Alignment:	

Importance:	
Description	VOID - number not assigned

Asset/Event Number	1513
Asset/Event Name	An Sgoltadh
Type of Asset/Event	Township; Corn Drying Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10050
Status	Non-designated Heritage Asset
Section:	N/A
Easting	267884
Northing	898544
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10050

Asset/Event Number	1514
Asset/Event Name	Puill Fhraoich
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10052
Status	Non-designated Heritage Asset
Section:	N/A
Easting	261994
Northing	898951
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10052

Asset/Event Number	1515
Asset/Event Name	Hut circle, Strone Achvachy
Type of Asset/Event	Hut Circle; Bothy

Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10053
Status	Non-designated Heritage Asset
Section:	N/A
Easting	261930
Northing	898060
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10053

Asset/Event Number	1516
Asset/Event Name	Leathad Breac
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10054
Status	Non-designated Heritage Asset
Section:	N/A
Easting	261752
Northing	897492
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10054

Asset/Event Number	1517
Asset/Event Name	Garbh-Airigh
Type of Asset/Event	Township; Rig And Furrow; Head Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10055
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263509
Northing	898785

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10055

Asset/Event Number	1518
Asset/Event Name	Bridge, Drochaid-na-Uidhe
Type of Asset/Event	Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10056
Status	Non-designated Heritage Asset
Section:	N/A
Easting	264180
Northing	895640
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10056

Asset/Event Number	1519
Asset/Event Name	Cnoc Garbh-Airigh
Type of Asset/Event	Township; Field System
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10057
Status	Non-designated Heritage Asset
Section:	N/A
Easting	262439
Northing	898641
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10057

Asset/Event Number	1520
Asset/Event Name	Coirshellach
Type of Asset/Event	Township; Head Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10058
Status	Non-designated Heritage Asset
Section:	N/A
Easting	260835
Northing	896381
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10058

Asset/Event Number	1521
Asset/Event Name	Torboll
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10066
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274101
Northing	899558
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10066

Asset/Event Number	1522
Asset/Event Name	Hut circle etc, Coire Buidhe
Type of Asset/Event	Hut Circle; Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10094
Status	Non-designated Heritage Asset

Section:	N/A
Easting	261270
Northing	895830
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10094

Asset/Event Number	1523
Asset/Event Name	Coire Buidhe
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10095
Status	Non-designated Heritage Asset
Section:	N/A
Easting	261710
Northing	896050
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10095

Asset/Event Number	1524
Asset/Event Name	Reidhbreac
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10096
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263275
Northing	896553
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG10096

Asset/Event Number	1525
Asset/Event Name	Hut circle, Clasnafaire
Type of Asset/Event	Hut Circle; Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10098
Status	Non-designated Heritage Asset
Section:	N/A
Easting	262520
Northing	898250
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10098

Asset/Event Number	1526
Asset/Event Name	Hut circle, Daliel
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10116
Status	Non-designated Heritage Asset
Section:	N/A
Easting	300700
Northing	917780
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10116

Asset/Event Number	1527
Asset/Event Name	Carn Laggie Chambered Cairn
Type of Asset/Event	Chambered Cairn
Date and/or Period	Prehistoric

Listing No./NRHE Number	<Null>
HER Number	MHG10117
Status	Non-designated Heritage Asset
Section:	N/A
Easting	302300
Northing	916500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10117

Asset/Event Number	1528
Asset/Event Name	Chambered Cairn - Salscraggie
Type of Asset/Event	Chambered Long Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10127
Status	Non-designated Heritage Asset
Section:	N/A
Easting	300150
Northing	918070
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10127

Asset/Event Number	1529
Asset/Event Name	Caen Hill
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10129
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301800
Northing	917930
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10129

Asset/Event Number	1530
Asset/Event Name	Daliel
Type of Asset/Event	Hut Circle; Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10130
Status	Non-designated Heritage Asset
Section:	N/A
Easting	300530
Northing	917880
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10130

Asset/Event Number	1531
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1532

Asset/Event Name	Hut circle and associated features - Caen Burn
Type of Asset/Event	Hut Circle; Clearance Cairn; Field Boundary
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10133
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301100
Northing	918600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10133

Asset/Event Number	1533
Asset/Event Name	Caen Burn
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10134
Status	Non-designated Heritage Asset
Section:	N/A
Easting	300930
Northing	918390
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10134

Asset/Event Number	1534
Asset/Event Name	Burnt Mound, Caen Burn
Type of Asset/Event	Burnt Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10135
Status	Non-designated Heritage Asset
Section:	N/A

Easting	301200
Northing	918250
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10135

Asset/Event Number	1535
Asset/Event Name	Broch, Strath of Kildonan
Type of Asset/Event	Broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10137
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301500
Northing	917400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10137

Asset/Event Number	1536
Asset/Event Name	Caen Hill
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10139
Status	Non-designated Heritage Asset
Section:	N/A
Easting	302110
Northing	917730
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10139

Asset/Event Number	1537
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1538
Asset/Event Name	Hut circle and souterrain - Caen Burn
Type of Asset/Event	Hut Circle; Souterrain
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10148
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301060
Northing	918500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10148

Asset/Event Number	1539
Asset/Event Name	River Helmsdale
Type of Asset/Event	Road
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG10154
Status	Non-designated Heritage Asset
Section:	N/A
Easting	300000
Northing	918160
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10154

Asset/Event Number	1540
Asset/Event Name	Battle site, Gartymore
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10156
Status	Non-designated Heritage Asset
Section:	N/A
Easting	300437
Northing	914437
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10156

Asset/Event Number	1541
Asset/Event Name	Allt an Dir
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10162
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301236
Northing	918857
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10162

Asset/Event Number	1542
Asset/Event Name	Allt an Dir
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10163
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301070
Northing	919171
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10163

Asset/Event Number	1543
Asset/Event Name	Allt an Dir
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10164
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301300
Northing	919100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10164

Asset/Event Number	1544
Asset/Event Name	Broch, Caen Burn

Type of Asset/Event	Broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10178
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301000
Northing	918000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10178

Asset/Event Number	1545
Asset/Event Name	Ulbster
Type of Asset/Event	Crofting Township; Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10182
Status	Non-designated Heritage Asset
Section:	N/A
Easting	296259
Northing	918397
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10182

Asset/Event Number	1546
Asset/Event Name	Badiepullacher
Type of Asset/Event	Farmstead; Enclosure; Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10183
Status	Non-designated Heritage Asset
Section:	N/A
Easting	295300

Northing	918500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10183

Asset/Event Number	1547
Asset/Event Name	Broch? Loch Salachaidh
Type of Asset/Event	Broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10204
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276000
Northing	903000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10204

Asset/Event Number	1548
Asset/Event Name	Holy Well - Tobar Mheasain
Type of Asset/Event	Holy Well
Date and/or Period	Medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10208
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293540
Northing	913050
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10208

Asset/Event Number	1549
Asset/Event Name	Helmsdale
Type of Asset/Event	Field System
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG10215
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301000
Northing	915000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10215

Asset/Event Number	1550
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1551
Asset/Event Name	Leadoch
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10257

Status	Non-designated Heritage Asset
Section:	N/A
Easting	285813
Northing	905215
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10257

Asset/Event Number	1552
Asset/Event Name	Daliel
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10283
Status	Non-designated Heritage Asset
Section:	N/A
Easting	300400
Northing	917920
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10283

Asset/Event Number	1553
Asset/Event Name	Caen Burn
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10285
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301061
Northing	918151
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10285

Asset/Event Number	1554
Asset/Event Name	Upper Caen Burn
Type of Asset/Event	Hut Circle; Lynchet
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10286
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301870
Northing	919330
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10286

Asset/Event Number	1555
Asset/Event Name	Allt Bad Na Muislich
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10287
Status	Non-designated Heritage Asset
Section:	N/A
Easting	302120
Northing	919490
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10287

Asset/Event Number	1556
Asset/Event Name	Hut circle, Caen Hill
Type of Asset/Event	Hut Circle

Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10288
Status	Non-designated Heritage Asset
Section:	N/A
Easting	302000
Northing	919000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10288

Asset/Event Number	1557
Asset/Event Name	Caen Burn
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10289
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301161
Northing	918248
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10289

Asset/Event Number	1558
Asset/Event Name	Salscraggie Lodge
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10293
Status	Non-designated Heritage Asset
Section:	N/A
Easting	300247
Northing	918103

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10293

Asset/Event Number	1559
Asset/Event Name	Allt Na Laraek Ruaidhe
Type of Asset/Event	Hut Circle; Lynchet
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10294
Status	Non-designated Heritage Asset
Section:	N/A
Easting	302940
Northing	919340
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10294

Asset/Event Number	1560
Asset/Event Name	Salscraggie
Type of Asset/Event	Kerb Cairn; Enclosure
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10295
Status	Non-designated Heritage Asset
Section:	N/A
Easting	300660
Northing	917890
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10295

Asset/Event Number	1561
Asset/Event Name	Loch Buidhe
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10313
Status	Non-designated Heritage Asset
Section:	N/A
Easting	267288
Northing	898592
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10313

Asset/Event Number	1562
Asset/Event Name	Loch Buidhe
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10314
Status	Non-designated Heritage Asset
Section:	N/A
Easting	266426
Northing	898713
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10314

Asset/Event Number	1563
Asset/Event Name	Meall Mor
Type of Asset/Event	Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10317
Status	Non-designated Heritage Asset

Section:	N/A
Easting	265000
Northing	896200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10317

Asset/Event Number	1564
Asset/Event Name	Meall Mor
Type of Asset/Event	Shieling Hut
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10318
Status	Non-designated Heritage Asset
Section:	N/A
Easting	265380
Northing	896330
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10318

Asset/Event Number	1565
Asset/Event Name	Leathad A' Chuailein
Type of Asset/Event	Farmstead; Enclosure; Field System; Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10319
Status	Non-designated Heritage Asset
Section:	N/A
Easting	265882
Northing	896132
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG10319

Asset/Event Number	1566
Asset/Event Name	Meall Mor
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10320
Status	Non-designated Heritage Asset
Section:	N/A
Easting	266400
Northing	896400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10320

Asset/Event Number	1567
Asset/Event Name	Leathadbreac
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10321
Status	Non-designated Heritage Asset
Section:	N/A
Easting	262580
Northing	896900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10321

Asset/Event Number	1568
Asset/Event Name	Leathadbreac
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric

Listing No./NRHE Number	<Null>
HER Number	MHG10322
Status	Non-designated Heritage Asset
Section:	N/A
Easting	262372
Northing	896810
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10322

Asset/Event Number	1569
Asset/Event Name	Leathadbreac
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10323
Status	Non-designated Heritage Asset
Section:	N/A
Easting	262417
Northing	896614
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10323

Asset/Event Number	1570
Asset/Event Name	Sleastary
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10325
Status	Non-designated Heritage Asset
Section:	N/A
Easting	264937
Northing	896395
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10325

Asset/Event Number	1571
Asset/Event Name	Clais Na Faire
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10327
Status	Non-designated Heritage Asset
Section:	N/A
Easting	262930
Northing	897560
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10327

Asset/Event Number	1572
Asset/Event Name	Claisnafaire
Type of Asset/Event	Township; Head Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10328
Status	Non-designated Heritage Asset
Section:	N/A
Easting	262503
Northing	898075
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10328

Asset/Event Number	1573

Asset/Event Name	Meall Clais Nan Each
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10329
Status	Non-designated Heritage Asset
Section:	N/A
Easting	269384
Northing	899283
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10329

Asset/Event Number	1574
Asset/Event Name	Meall Clais Nan Each
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10330
Status	Non-designated Heritage Asset
Section:	N/A
Easting	269084
Northing	899107
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10330

Asset/Event Number	1575
Asset/Event Name	Creag Caolsaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10331
Status	Non-designated Heritage Asset
Section:	N/A

Easting	268603
Northing	898947
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10331

Asset/Event Number	1576
Asset/Event Name	Meall Clais Nan Each
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10332
Status	Non-designated Heritage Asset
Section:	N/A
Easting	269987
Northing	899080
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10332

Asset/Event Number	1577
Asset/Event Name	Meall Clais Nan Each
Type of Asset/Event	Mound
Date and/or Period	Unknown
Listing No./NRHE Number	<Null>
HER Number	MHG10333
Status	Non-designated Heritage Asset
Section:	N/A
Easting	269940
Northing	899140
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10333

Asset/Event Number	1578
Asset/Event Name	Craigton
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10335
Status	Non-designated Heritage Asset
Section:	N/A
Easting	262420
Northing	897070
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10335

Asset/Event Number	1579
Asset/Event Name	Craigton
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10336
Status	Non-designated Heritage Asset
Section:	N/A
Easting	262598
Northing	896496
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10336

Asset/Event Number	1580
Asset/Event Name	Loch an Lagain
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>

HER Number	MHG10337
Status	Non-designated Heritage Asset
Section:	N/A
Easting	266010
Northing	895770
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10337

Asset/Event Number	1581
Asset/Event Name	Crannog, Loch Buidhe
Type of Asset/Event	Crannog
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10338
Status	Non-designated Heritage Asset
Section:	N/A
Easting	266920
Northing	898260
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10338

Asset/Event Number	1582
Asset/Event Name	Loch an Lagain
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10339
Status	Non-designated Heritage Asset
Section:	N/A
Easting	266359
Northing	895824
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10339

Asset/Event Number	1583
Asset/Event Name	Loch an Lagain
Type of Asset/Event	Shieling Hut
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10343
Status	Non-designated Heritage Asset
Section:	N/A
Easting	265400
Northing	896300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10343

Asset/Event Number	1584
Asset/Event Name	Meall Clais Nan Each
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10344
Status	Non-designated Heritage Asset
Section:	N/A
Easting	269870
Northing	899168
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10344

Asset/Event Number	1585
Asset/Event Name	East Kinnauld

Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10370
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274350
Northing	901750
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10370

Asset/Event Number	1586
Asset/Event Name	Hut circles, Cnoc Na Gamhna
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10396
Status	Non-designated Heritage Asset
Section:	N/A
Easting	278867
Northing	904074
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10396

Asset/Event Number	1587
Asset/Event Name	Allt Eas Nan Lair
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10397
Status	Non-designated Heritage Asset
Section:	N/A
Easting	279510

Northing	903870
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10397

Asset/Event Number	1588
Asset/Event Name	Lazy Beds, Bridge of Horn
Type of Asset/Event	Lazy Beds
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10399
Status	Non-designated Heritage Asset
Section:	N/A
Easting	279141
Northing	904881
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10399

Asset/Event Number	1589
Asset/Event Name	Strath Kildonan
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10476
Status	Non-designated Heritage Asset
Section:	N/A
Easting	295000
Northing	918000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10476

Asset/Event Number	1590
Asset/Event Name	Township, Braeval
Type of Asset/Event	Farmstead; Clearance Cairn; Enclosure; Township; Croft; Crofthouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10478
Status	Non-designated Heritage Asset
Section:	N/A
Easting	292064
Northing	908347
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10478

Asset/Event Number	1591
Asset/Event Name	Cnoc an T-Salachaidh
Type of Asset/Event	Cairnfield
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10509
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276694
Northing	903473
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10509

Asset/Event Number	1592
Asset/Event Name	Cairns w cists, 0.5 mile E of Morvich Lodge
Type of Asset/Event	Cairn; Cist
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10511

Status	Non-designated Heritage Asset
Section:	N/A
Easting	276022
Northing	900563
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10511

Asset/Event Number	1593
Asset/Event Name	Glen Cottage
Type of Asset/Event	Cairnfield
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10544
Status	Non-designated Heritage Asset
Section:	N/A
Easting	278204
Northing	905119
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10544

Asset/Event Number	1594
Asset/Event Name	Fairlaraich
Type of Asset/Event	Hut Circle; Kiln
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10554
Status	Non-designated Heritage Asset
Section:	N/A
Easting	277420
Northing	905090
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10554

Asset/Event Number	1595
Asset/Event Name	Allt Nam Sgeith
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10557
Status	Non-designated Heritage Asset
Section:	N/A
Easting	280250
Northing	903930
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10557

Asset/Event Number	1596
Asset/Event Name	Allt Nan Sgeith
Type of Asset/Event	Enclosure; Longhouse; Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10558
Status	Non-designated Heritage Asset
Section:	N/A
Easting	280061
Northing	904008
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10558

Asset/Event Number	1597
Asset/Event Name	Aberscross Burn
Type of Asset/Event	Hut Circle

Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10596
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276887
Northing	900968
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10596

Asset/Event Number	1598
Asset/Event Name	Burnt Mound, Loch Farlary
Type of Asset/Event	Burnt Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10598
Status	Non-designated Heritage Asset
Section:	N/A
Easting	277530
Northing	904960
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10598

Asset/Event Number	1599
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	

Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1600
Asset/Event Name	Sheepfolds, Morvich Lodge
Type of Asset/Event	Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10602
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275760
Northing	901300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10602

Asset/Event Number	1601
Asset/Event Name	Morvich Lodge
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10603
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275774
Northing	901030
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10603

Asset/Event Number	1602
Asset/Event Name	Hut circles, Morvich Burn
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10604
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276585
Northing	902482
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10604

Asset/Event Number	1603
Asset/Event Name	Morvich Burn
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10606
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276661
Northing	902020
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10606

Asset/Event Number	1604
Asset/Event Name	Cnoc an T-Salachaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10607
Status	Non-designated Heritage Asset

Section:	N/A
Easting	276643
Northing	902753
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10607

Asset/Event Number	1605
Asset/Event Name	Blairmore
Type of Asset/Event	Enclosure; Field System
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG10609
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274542
Northing	903665
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10609

Asset/Event Number	1606
Asset/Event Name	Burials & Dagger or Razor, E of Manse, Skaig
Type of Asset/Event	Cist; Human Remains
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10613
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274110
Northing	903400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG10613

Asset/Event Number	1607
Asset/Event Name	St. Callan's, Rogart
Type of Asset/Event	Church
Date and/or Period	Early Historic
Listing No./NRHE Number	<Null>
HER Number	MHG10618
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273871
Northing	903520
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10618

Asset/Event Number	1608
Asset/Event Name	Tumulus with Finds, Rogart
Type of Asset/Event	Burial Cairn; Cist; Burial
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10628
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273900
Northing	903400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10628

Asset/Event Number	1609
Asset/Event Name	Cnoc Bad A Chrasgaidh
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG10649
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275580
Northing	902800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10649

Asset/Event Number	1610
Asset/Event Name	Cnoc Bad A' Chrasgaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10650
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275980
Northing	902890
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10650

Asset/Event Number	1611
Asset/Event Name	Hut Circle, Millery Pool
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1073
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310568
Northing	925040
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1073

Asset/Event Number	1612
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1613
Asset/Event Name	Clearance Cairn, Berriedale Water
Type of Asset/Event	Clearance Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG1076
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311000
Northing	926200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1076

Asset/Event Number	1614

Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1615
Asset/Event Name	Leadoch
Type of Asset/Event	Enclosure
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG10796
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285450
Northing	905380
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10796

Asset/Event Number	1616
Asset/Event Name	2 Urns, Loch Brora
Type of Asset/Event	Findspot
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10798
Status	Non-designated Heritage Asset
Section:	N/A

Easting	285770
Northing	907910
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10798

Asset/Event Number	1617
Asset/Event Name	Loch Brora
Type of Asset/Event	Homestead
Date and/or Period	Prehistoric/Early Historic
Listing No./NRHE Number	<Null>
HER Number	MHG10800
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285260
Northing	906050
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10800

Asset/Event Number	1618
Asset/Event Name	Loch Brora
Type of Asset/Event	Hut Circle Settlement; Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10801
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285139
Northing	906120
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10801

Asset/Event Number	1619
Asset/Event Name	St John's Church
Type of Asset/Event	Church
Date and/or Period	Medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10802
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285500
Northing	907100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10802

Asset/Event Number	1620
Asset/Event Name	Loch Brora
Type of Asset/Event	Cairn; Cist
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10806
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285876
Northing	908082
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10806

Asset/Event Number	1621
Asset/Event Name	Allt Nam Ban
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG10807
Status	Non-designated Heritage Asset
Section:	N/A
Easting	286610
Northing	908170
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10807

Asset/Event Number	1622
Asset/Event Name	Allt Nam Ban
Type of Asset/Event	Mound
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG10808
Status	Non-designated Heritage Asset
Section:	N/A
Easting	286600
Northing	908410
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10808

Asset/Event Number	1623
Asset/Event Name	Killin
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10810
Status	Non-designated Heritage Asset
Section:	N/A
Easting	286241
Northing	907035
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10810

Asset/Event Number	1624
Asset/Event Name	Loch Brora
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10811
Status	Non-designated Heritage Asset
Section:	N/A
Easting	286151
Northing	906711
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10811

Asset/Event Number	1625
Asset/Event Name	Loch Brora
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10812
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285920
Northing	906820
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10812

Asset/Event Number	1626
Asset/Event Name	VOID - number not assigned

Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1627
Asset/Event Name	Loch Brora
Type of Asset/Event	Hut Circle; Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10817
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285768
Northing	908245
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10817

Asset/Event Number	1628
Asset/Event Name	Killin
Type of Asset/Event	Human Remains
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG10818
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285380

Northing	906990
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10818

Asset/Event Number	1629
Asset/Event Name	Killin
Type of Asset/Event	Human Remains
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG10819
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285540
Northing	906880
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10819

Asset/Event Number	1630
Asset/Event Name	Mound, Rockhead
Type of Asset/Event	Mound
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1082
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313500
Northing	925800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1082

Asset/Event Number	1631
Asset/Event Name	Crannog, Eilean nam Faoileag
Type of Asset/Event	Crannog
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10820
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285600
Northing	906000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10820

Asset/Event Number	1632
Asset/Event Name	Killin Rock
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10821
Status	Non-designated Heritage Asset
Section:	N/A
Easting	287032
Northing	906779
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10821

Asset/Event Number	1633
Asset/Event Name	Broch, Carrol
Type of Asset/Event	Broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10822

Status	Non-designated Heritage Asset
Section:	N/A
Easting	284620
Northing	906460
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10822

Asset/Event Number	1634
Asset/Event Name	Coire Aghaisgeig
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10824
Status	Non-designated Heritage Asset
Section:	N/A
Easting	284139
Northing	905981
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10824

Asset/Event Number	1635
Asset/Event Name	Carrol
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10825
Status	Non-designated Heritage Asset
Section:	N/A
Easting	284740
Northing	906930
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10825

Asset/Event Number	1636
Asset/Event Name	Possible Fort, Carrol
Type of Asset/Event	Fort
Date and/or Period	None
Listing No./NRHE Number	<Null>
HER Number	MHG10826
Status	Non-designated Heritage Asset
Section:	N/A
Easting	284000
Northing	907000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10826

Asset/Event Number	1637
Asset/Event Name	Hut Circle, Ard-Achadh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1083
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310775
Northing	925884
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1083

Asset/Event Number	1638
Asset/Event Name	Carrol
Type of Asset/Event	Enclosure

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG10833
Status	Non-designated Heritage Asset
Section:	N/A
Easting	284630
Northing	906520
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10833

Asset/Event Number	1639
Asset/Event Name	Carrol
Type of Asset/Event	Structure
Date and/or Period	Unknown
Listing No./NRHE Number	<Null>
HER Number	MHG10834
Status	Non-designated Heritage Asset
Section:	N/A
Easting	284710
Northing	906470
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10834

Asset/Event Number	1640
Asset/Event Name	Well, Ramscraigs
Type of Asset/Event	Well
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1085
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314060
Northing	926410

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1085

Asset/Event Number	1641
Asset/Event Name	Farmstead, Allt Ard Achaidh
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1087
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310910
Northing	925800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1087

Asset/Event Number	1642
Asset/Event Name	Farmstead, Meall Dhonuill
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1089
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311317
Northing	927387
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1089

Asset/Event Number	1643
Asset/Event Name	Township - Berriedale Water
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1090
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311400
Northing	926600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1090

Asset/Event Number	1644
Asset/Event Name	Hut circles, Berriedale
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1091
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310226
Northing	925017
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1091

Asset/Event Number	1645
Asset/Event Name	Cairn - Loch Brora
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10939
Status	Non-designated Heritage Asset

Section:	N/A
Easting	285989
Northing	906428
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10939

Asset/Event Number	1646
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1647
Asset/Event Name	Field System, Millery Burn
Type of Asset/Event	Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1096
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310650
Northing	925100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG1096

Asset/Event Number	1648
Asset/Event Name	Building, Berriedale Water
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1099
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310610
Northing	924680
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1099

Asset/Event Number	1649
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1650
Asset/Event Name	Site of Bridge and Inn, Berriedale
Type of Asset/Event	Inn; Bridge
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG1102
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311900
Northing	922600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1102

Asset/Event Number	1651
Asset/Event Name	Chapel, Cnoc Fionn
Type of Asset/Event	Chapel; Church
Date and/or Period	Medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1103
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311000
Northing	922000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1103

Asset/Event Number	1652
Asset/Event Name	William Moor Sutherland Memorial, Beridale
Type of Asset/Event	Commemorative Monument
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1104
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312000
Northing	922700
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1104

Asset/Event Number	1653
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1654
Asset/Event Name	Possible Smithy, Berriedale
Type of Asset/Event	Smithy
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1106
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311962
Northing	922549
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1106

Asset/Event Number	1655

Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1656
Asset/Event Name	Farmstead, Karrug settlement
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1108
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310300
Northing	923500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1108

Asset/Event Number	1657
Asset/Event Name	Nichol Memorial
Type of Asset/Event	Commemorative Monument
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG1109
Status	Non-designated Heritage Asset
Section:	N/A

Easting	312240
Northing	923090
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1109

Asset/Event Number	1658
Asset/Event Name	Cemetery, Berriedale
Type of Asset/Event	Cemetery
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1110
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312050
Northing	922720
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1110

Asset/Event Number	1659
Asset/Event Name	Achastone Township
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1111
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311400
Northing	922900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1111

Asset/Event Number	1660
Asset/Event Name	Cnoc an T-Salachaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11113
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276510
Northing	902390
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11113

Asset/Event Number	1661
Asset/Event Name	Cnoc an T-Salachaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11114
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276550
Northing	902640
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11114

Asset/Event Number	1662
Asset/Event Name	Cnoc an T-Salachaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>

HER Number	MHG11117
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276637
Northing	903078
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11117

Asset/Event Number	1663
Asset/Event Name	Kinloch
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11118
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276322
Northing	903469
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11118

Asset/Event Number	1664
Asset/Event Name	Loch Salachaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11119
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276116
Northing	903304
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11119

Asset/Event Number	1665
Asset/Event Name	Langwell Township
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1112
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311200
Northing	922400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1112

Asset/Event Number	1666
Asset/Event Name	Loch Salachaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11120
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275659
Northing	904192
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11120

Asset/Event Number	1667
Asset/Event Name	Aberscross Burn

Type of Asset/Event	Cairn; Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11121
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276590
Northing	900790
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11121

Asset/Event Number	1668
Asset/Event Name	Hut circles, Cnoc Bad A Chrasgaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11122
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275391
Northing	902548
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11122

Asset/Event Number	1669
Asset/Event Name	Dunrobin Glen
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11123
Status	Non-designated Heritage Asset
Section:	N/A
Easting	279421

Northing	904687
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11123

Asset/Event Number	1670
Asset/Event Name	Craft Township
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1113
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312100
Northing	922800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1113

Asset/Event Number	1671
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1672
Asset/Event Name	Inver Township
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1115
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311800
Northing	922400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1115

Asset/Event Number	1673
Asset/Event Name	Farmstead, Berriedale Water
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1116
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310222
Northing	924581
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1116

Asset/Event Number	1674
Asset/Event Name	Township, An Dun
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1117

Status	Non-designated Heritage Asset
Section:	N/A
Easting	310200
Northing	924900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1117

Asset/Event Number	1675
Asset/Event Name	Lang Well
Type of Asset/Event	Well
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1118
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310000
Northing	922160
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1118

Asset/Event Number	1676
Asset/Event Name	Settlement, Berriedale
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1119
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311800
Northing	922600
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1119

Asset/Event Number	1677
Asset/Event Name	Berriedale Harbour
Type of Asset/Event	Harbour
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1120
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312000
Northing	922500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1120

Asset/Event Number	1678
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1679
Asset/Event Name	Loch an Lagain
Type of Asset/Event	Enclosure; Corn Drying Kiln; Field System

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG11217
Status	Non-designated Heritage Asset
Section:	N/A
Easting	266140
Northing	895660
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11217

Asset/Event Number	1680
Asset/Event Name	Hut Circle, Tulach Bad A Choilich
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1122
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310540
Northing	924065
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1122

Asset/Event Number	1681
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	

Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1682
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1683
Asset/Event Name	Broch, Tulach Bad A Choilich
Type of Asset/Event	Broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1125
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310050
Northing	924040
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1125

Asset/Event Number	1684
Asset/Event Name	Aberscross Burn
Type of Asset/Event	Hut Circle; Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11265
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276460
Northing	900870
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11265

Asset/Event Number	1685
Asset/Event Name	Morvich Burn
Type of Asset/Event	Hut Circle; Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11266
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276640
Northing	901560
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11266

Asset/Event Number	1686
Asset/Event Name	Morvich Burn
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11268
Status	Non-designated Heritage Asset

Section:	N/A
Easting	276704
Northing	901427
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11268

Asset/Event Number	1687
Asset/Event Name	Aberscross Burn
Type of Asset/Event	Hut Circle; Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11269
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276770
Northing	901090
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11269

Asset/Event Number	1688
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	

Description	VOID - number not assigned

Asset/Event Number	1689
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1690
Asset/Event Name	Carved Stone Ball - Ben-a-Chielt
Type of Asset/Event	Findspot
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1129
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319000
Northing	937000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1129

Asset/Event Number	1691
Asset/Event Name	Croft, Red Rock
Type of Asset/Event	Croft
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG1130
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318530
Northing	936470
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1130

Asset/Event Number	1692
Asset/Event Name	Latheron Hospital
Type of Asset/Event	Hospital
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1131
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319180
Northing	935870
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1131

Asset/Event Number	1693
Asset/Event Name	Field System, Creag an Fithick
Type of Asset/Event	Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1132
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314900
Northing	931600
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1132

Asset/Event Number	1694
Asset/Event Name	Quarry, Cnoc Na Maranaich
Type of Asset/Event	Quarry
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG1133
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313207
Northing	933300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1133

Asset/Event Number	1695
Asset/Event Name	Hut circles and field system - Gylable Burn
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11357
Status	Non-designated Heritage Asset
Section:	N/A
Easting	294946
Northing	917658
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11357

Asset/Event Number	1696

Asset/Event Name	Salscraggie
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG11359
Status	Non-designated Heritage Asset
Section:	N/A
Easting	300100
Northing	918100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11359

Asset/Event Number	1697
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1698
Asset/Event Name	Hut circle, Glen Rock
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11393
Status	Non-designated Heritage Asset
Section:	N/A

Easting	280620
Northing	903960
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11393

Asset/Event Number	1699
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1700
Asset/Event Name	Mound, Ballentink
Type of Asset/Event	Homestead; Mound
Date and/or Period	Prehistoric/Early Historic
Listing No./NRHE Number	<Null>
HER Number	MHG1141
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315210
Northing	931040
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1141

Asset/Event Number	1701
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1702
Asset/Event Name	Broch, Dun Beath
Type of Asset/Event	Broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1144
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315530
Northing	930440
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1144

Asset/Event Number	1703
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	

HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1704
Asset/Event Name	Hut Circle, Minera
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1147
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315810
Northing	934670
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1147

Asset/Event Number	1705
Asset/Event Name	Cropmark, Wester Moy
Type of Asset/Event	Occupation Site
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG11470
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248000
Northing	855300
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11470

Asset/Event Number	1706
Asset/Event Name	Hut Circle, Minera
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1148
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315800
Northing	934500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1148

Asset/Event Number	1707
Asset/Event Name	Hut circle, Glen Rock
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11482
Status	Non-designated Heritage Asset
Section:	N/A
Easting	281050
Northing	903650
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11482

Asset/Event Number	1708
Asset/Event Name	VOID - number not assigned

Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1709
Asset/Event Name	Broch, Bunellich
Type of Asset/Event	Broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1150
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317730
Northing	933960
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1150

Asset/Event Number	1710
Asset/Event Name	Hut Circle, Bridge of Rhemullen
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1151
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315010

Northing	930626
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1151

Asset/Event Number	1711
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1712
Asset/Event Name	Kilphedir
Type of Asset/Event	Building
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG11531
Status	Non-designated Heritage Asset
Section:	N/A
Easting	300150
Northing	918150
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11531

Asset/Event Number	1713
Asset/Event Name	Eldrable
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG11532
Status	Non-designated Heritage Asset
Section:	N/A
Easting	298590
Northing	918310
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11532

Asset/Event Number	1714
Asset/Event Name	Oulmsdale
Type of Asset/Event	Settlement
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG11533
Status	Non-designated Heritage Asset
Section:	N/A
Easting	296000
Northing	917000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11533

Asset/Event Number	1715
Asset/Event Name	Farmstead, Creagan Mor
Type of Asset/Event	Clearance Cairn; Farmstead; Enclosure; Building; Corn Drying Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG11554

Status	Non-designated Heritage Asset
Section:	N/A
Easting	291613
Northing	908209
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11554

Asset/Event Number	1716
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1717
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	

Importance:	
Description	VOID - number not assigned

Asset/Event Number	1718
Asset/Event Name	St Callan's Chapel, Kinnauld
Type of Asset/Event	Chapel
Date and/or Period	Early Historic/Medieval
Listing No./NRHE Number	<Null>
HER Number	MHG11604
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273150
Northing	901210
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11604

Asset/Event Number	1719
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1720
Asset/Event Name	Coill'an Iarsaidh
Type of Asset/Event	Hut Circle; Field System

Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11623
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273135
Northing	898917
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11623

Asset/Event Number	1721
Asset/Event Name	Broch, Strath Carnaig
Type of Asset/Event	Broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11624
Status	Non-designated Heritage Asset
Section:	N/A
Easting	270503
Northing	899020
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11624

Asset/Event Number	1722
Asset/Event Name	Coill an Iarsaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11677
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273855
Northing	898464

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11677

Asset/Event Number	1723
Asset/Event Name	Possible Kerb Cairn, Torboll
Type of Asset/Event	Kerb Cairn?; Clearance Cairn?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11678
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273845
Northing	898438
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11678

Asset/Event Number	1724
Asset/Event Name	Swedish Man's Grave; Dalnamain
Type of Asset/Event	Standing Stone; Mound?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11679
Status	Non-designated Heritage Asset
Section:	N/A
Easting	272780
Northing	898580
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11679

Asset/Event Number	1725
Asset/Event Name	Hut Circle, Minera
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1168
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315800
Northing	934516
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1168

Asset/Event Number	1726
Asset/Event Name	Strath Carnaig
Type of Asset/Event	Mound
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG11680
Status	Non-designated Heritage Asset
Section:	N/A
Easting	272820
Northing	898490
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11680

Asset/Event Number	1727
Asset/Event Name	Dun, Torri Falaig
Type of Asset/Event	Dun
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11681
Status	Non-designated Heritage Asset

Section:	N/A
Easting	272880
Northing	898332
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11681

Asset/Event Number	1728
Asset/Event Name	Mound Junction
Type of Asset/Event	Hut Circle; Field Boundary; Lynchet
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11682
Status	Non-designated Heritage Asset
Section:	N/A
Easting	270401
Northing	898685
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11682

Asset/Event Number	1729
Asset/Event Name	Battle site? Brae Cottage
Type of Asset/Event	Cairnfield
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11683
Status	Non-designated Heritage Asset
Section:	N/A
Easting	270400
Northing	898800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG11683

Asset/Event Number	1730
Asset/Event Name	Torboll Fall
Type of Asset/Event	Hut Circle Settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11685
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274538
Northing	898883
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11685

Asset/Event Number	1731
Asset/Event Name	Creag Dail Na Meine
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11686
Status	Non-designated Heritage Asset
Section:	N/A
Easting	270765
Northing	899370
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11686

Asset/Event Number	1732
Asset/Event Name	Achtaduaig
Type of Asset/Event	Hut Circle; Clearance Cairn
Date and/or Period	Prehistoric

Listing No./NRHE Number	<Null>
HER Number	MHG11687
Status	Non-designated Heritage Asset
Section:	N/A
Easting	272940
Northing	897692
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11687

Asset/Event Number	1733
Asset/Event Name	Achtaduaig
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG11688
Status	Non-designated Heritage Asset
Section:	N/A
Easting	272690
Northing	897912
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11688

Asset/Event Number	1734
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	

Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1735
Asset/Event Name	Torri Falaig
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG11696
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273063
Northing	898338
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11696

Asset/Event Number	1736
Asset/Event Name	Brae Cottage
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG11697
Status	Non-designated Heritage Asset
Section:	N/A
Easting	270197
Northing	898920
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11697

Asset/Event Number	1737

Asset/Event Name	Allt Tigh Neill
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG11698
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273502
Northing	897028
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11698

Asset/Event Number	1738
Asset/Event Name	Hut Circle, Cnoc Sheangan
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1170
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315570
Northing	932980
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1170

Asset/Event Number	1739
Asset/Event Name	Hut Circles, Badnagie
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1171
Status	Non-designated Heritage Asset
Section:	N/A

Easting	315638
Northing	932090
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1171

Asset/Event Number	1740
Asset/Event Name	Garskelly
Type of Asset/Event	Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG11720
Status	Non-designated Heritage Asset
Section:	N/A
Easting	271721
Northing	897980
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11720

Asset/Event Number	1741
Asset/Event Name	Dalnamain
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11723
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273019
Northing	898694
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11723

Asset/Event Number	1742
Asset/Event Name	Loch Ruagaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11724
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273219
Northing	899557
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11724

Asset/Event Number	1743
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1744
Asset/Event Name	Carn Liath
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>

HER Number	MHG11727
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274079
Northing	899145
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11727

Asset/Event Number	1745
Asset/Event Name	Cairn, Cnoc Sheangan
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1173
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316170
Northing	933040
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1173

Asset/Event Number	1746
Asset/Event Name	Burnt Mound, Cnoc Sheangan
Type of Asset/Event	Burnt Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1174
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316410
Northing	933140
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1174

Asset/Event Number	1747
Asset/Event Name	Hut Circle, Cnoc Sheangan
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1175
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316464
Northing	933007
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1175

Asset/Event Number	1748
Asset/Event Name	Hut Circles, 400m N of Achnagoul
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1177
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316400
Northing	932900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1177

Asset/Event Number	1749
Asset/Event Name	Cairn, Achnagoul

Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1178
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315940
Northing	932540
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1178

Asset/Event Number	1750
Asset/Event Name	Burial Ground, Badnagie
Type of Asset/Event	Burial Ground
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1248
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315620
Northing	931840
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1248

Asset/Event Number	1751
Asset/Event Name	Suspension Bridge, Dunbeath
Type of Asset/Event	Suspension Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1249
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315486

Northing	930417
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1249

Asset/Event Number	1752
Asset/Event Name	Hut Circle, Bad Nan Glac
Type of Asset/Event	Hut Circle; Wag
Date and/or Period	Prehistoric/Early Historic
Listing No./NRHE Number	<Null>
HER Number	MHG1253
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311946
Northing	930413
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1253

Asset/Event Number	1753
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1754
Asset/Event Name	Well, Cnoc Na Maranaich
Type of Asset/Event	Well
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1258
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313190
Northing	933140
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1258

Asset/Event Number	1755
Asset/Event Name	Hut Circle, Balcraggie Lodge
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1259
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314121
Northing	930211
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1259

Asset/Event Number	1756
Asset/Event Name	Cemetery, Toch na Guall
Type of Asset/Event	Cemetery
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1260

Status	Non-designated Heritage Asset
Section:	N/A
Easting	312986
Northing	932354
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1260

Asset/Event Number	1757
Asset/Event Name	Enclosure, Dunbeath Water
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1261
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312770
Northing	932220
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1261

Asset/Event Number	1758
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	

Importance:	
Description	VOID - number not assigned

Asset/Event Number	1759
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1760
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1761
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	

Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1762
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1763
Asset/Event Name	Standing Stone, Rhianacoil
Type of Asset/Event	Standing Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1268
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318380
Northing	945120

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1268

Asset/Event Number	1764
Asset/Event Name	Township, Tacher
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1269
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316600
Northing	945300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1269

Asset/Event Number	1765
Asset/Event Name	Taker Township
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1270
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317300
Northing	945800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1270

Asset/Event Number	1766
Asset/Event Name	Rangag Township
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1271
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317400
Northing	945400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1271

Asset/Event Number	1767
Asset/Event Name	Township, Dalnachar
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1272
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316893
Northing	946786
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1272

Asset/Event Number	1768
Asset/Event Name	Causeymire Church
Type of Asset/Event	Church
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1274
Status	Non-designated Heritage Asset

Section:	N/A
Easting	317371
Northing	948319
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1274

Asset/Event Number	1769
Asset/Event Name	Township, Strath Beg
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1276
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316000
Northing	947900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1276

Asset/Event Number	1770
Asset/Event Name	Achary Township
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1278
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317100
Northing	947100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG1278

Asset/Event Number	1771
Asset/Event Name	Buildings, Bridge of Tacher
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1279
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317200
Northing	946400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1279

Asset/Event Number	1772
Asset/Event Name	Altnagar Lodge Hotel
Type of Asset/Event	Field System; Clearance Cairn; Structure
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG12883
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258441
Northing	898488
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG12883

Asset/Event Number	1773
Asset/Event Name	Axe; Invershin
Type of Asset/Event	Findspot
Date and/or Period	Prehistoric

Listing No./NRHE Number	<Null>
HER Number	MHG12885
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257000
Northing	896000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG12885

Asset/Event Number	1774
Asset/Event Name	Cnoc Breac
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG12886
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258493
Northing	898157
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG12886

Asset/Event Number	1775
Asset/Event Name	Possible Motte, Inveran Farm
Type of Asset/Event	Castle?; Motte?
Date and/or Period	Medieval
Listing No./NRHE Number	<Null>
HER Number	MHG12887
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257063
Northing	897450
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG12887

Asset/Event Number	1776
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1777
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1778

Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1779
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1780
Asset/Event Name	Ironworking, Invershin Forest
Type of Asset/Event	Iron Working Site
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG12896
Status	Non-designated Heritage Asset
Section:	N/A

Easting	258000
Northing	896300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG12896

Asset/Event Number	1781
Asset/Event Name	Invershin Forest
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG12897
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258300
Northing	897200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG12897

Asset/Event Number	1782
Asset/Event Name	Balblair Wood
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG12898
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258406
Northing	895662
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG12898

Asset/Event Number	1783
Asset/Event Name	Broch - Invershin Station area
Type of Asset/Event	Broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG12900
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257900
Northing	895300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG12900

Asset/Event Number	1784
Asset/Event Name	Slag, Inveran
Type of Asset/Event	Findspot
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG12901
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256000
Northing	897000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG12901

Asset/Event Number	1785
Asset/Event Name	Cnoc Breac
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>

HER Number	MHG12902
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258192
Northing	897908
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG12902

Asset/Event Number	1786
Asset/Event Name	Balblair
Type of Asset/Event	Shieling
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG12903
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258620
Northing	898040
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG12903

Asset/Event Number	1787
Asset/Event Name	Invershin Station
Type of Asset/Event	Railway Station
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG12906
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257950
Northing	895450
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG12906

Asset/Event Number	1788
Asset/Event Name	Invershin Forest
Type of Asset/Event	Shieling Hut
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG12908
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258500
Northing	895800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG12908

Asset/Event Number	1789
Asset/Event Name	Invershin Forest
Type of Asset/Event	Shieling Hut
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG12909
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258300
Northing	895800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG12909

Asset/Event Number	1790
Asset/Event Name	Invershin Forest

Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG12910
Status	Non-designated Heritage Asset
Section:	N/A
Easting	259900
Northing	896600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG12910

Asset/Event Number	1791
Asset/Event Name	Bloomery Mound nr Invershin Station
Type of Asset/Event	Leather Working Site
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG12911
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258170
Northing	895590
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG12911

Asset/Event Number	1792
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	

Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1793
Asset/Event Name	Burnt Mound, Invershin
Type of Asset/Event	Burnt Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM5497
HER Number	MHG12916
Status	Scheduled Monument
Section:	N/A
Easting	257870
Northing	896810
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG12916

Asset/Event Number	1794
Asset/Event Name	Burnt Mound, Henman's Burn
Type of Asset/Event	Burnt Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG12917
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258730
Northing	896490
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG12917

Asset/Event Number	1795
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1796
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1797
Asset/Event Name	Badenahauglish 2
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13157

Status	Non-designated Heritage Asset
Section:	N/A
Easting	290400
Northing	909800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13157

Asset/Event Number	1798
Asset/Event Name	Badenahauglish 1
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13158
Status	Non-designated Heritage Asset
Section:	N/A
Easting	291145
Northing	909782
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13158

Asset/Event Number	1799
Asset/Event Name	Kintradwell
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13159
Status	Non-designated Heritage Asset
Section:	N/A
Easting	291499
Northing	907945
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13159

Asset/Event Number	1800
Asset/Event Name	An T-Salainn
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13160
Status	Non-designated Heritage Asset
Section:	N/A
Easting	291372
Northing	907367
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13160

Asset/Event Number	1801
Asset/Event Name	Glen Loth
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13162
Status	Non-designated Heritage Asset
Section:	N/A
Easting	294200
Northing	915200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13162

Asset/Event Number	1802
Asset/Event Name	Gailiable
Type of Asset/Event	Settlement

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13163
Status	Non-designated Heritage Asset
Section:	N/A
Easting	294841
Northing	918387
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13163

Asset/Event Number	1803
Asset/Event Name	Grudsterry
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13168
Status	Non-designated Heritage Asset
Section:	N/A
Easting	299743
Northing	918105
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13168

Asset/Event Number	1804
Asset/Event Name	Salseraggie
Type of Asset/Event	Township; Head Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13169
Status	Non-designated Heritage Asset
Section:	N/A
Easting	299700
Northing	918300

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13169

Asset/Event Number	1805
Asset/Event Name	Standing Stone, Rangag
Type of Asset/Event	Standing Stone
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1317
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317680
Northing	944880
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1317

Asset/Event Number	1806
Asset/Event Name	Lonmore
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13170
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293198
Northing	910375
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13170

Asset/Event Number	1807
Asset/Event Name	Lothbeg
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13171
Status	Non-designated Heritage Asset
Section:	N/A
Easting	294217
Northing	910587
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13171

Asset/Event Number	1808
Asset/Event Name	Coille Bad Mheasain
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13172
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293914
Northing	912919
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13172

Asset/Event Number	1809
Asset/Event Name	Chapel etc, Ballachly
Type of Asset/Event	Chapel; Cemetery
Date and/or Period	Medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1318
Status	Non-designated Heritage Asset

Section:	N/A
Easting	319320
Northing	944780
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1318

Asset/Event Number	1810
Asset/Event Name	Bridge of Horn
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13306
Status	Non-designated Heritage Asset
Section:	N/A
Easting	279373
Northing	905163
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13306

Asset/Event Number	1811
Asset/Event Name	Rogart Glebe
Type of Asset/Event	Site
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG13308
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273900
Northing	903400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG13308

Asset/Event Number	1812
Asset/Event Name	Strath Lunndaidh
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13309
Status	Non-designated Heritage Asset
Section:	N/A
Easting	278460
Northing	901145
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13309

Asset/Event Number	1813
Asset/Event Name	Prehistoric Pine Stumps - Loch Farlary
Type of Asset/Event	Findspot
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13310
Status	Non-designated Heritage Asset
Section:	N/A
Easting	277450
Northing	904950
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13310

Asset/Event Number	1814
Asset/Event Name	Allt Horn
Type of Asset/Event	Hut Circle; Platform
Date and/or Period	Prehistoric

Listing No./NRHE Number	<Null>
HER Number	MHG13340
Status	Non-designated Heritage Asset
Section:	N/A
Easting	280120
Northing	904300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13340

Asset/Event Number	1815
Asset/Event Name	Cairn, N end of Achanarras Hill, Halkirk
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1335
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314740
Northing	955870
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1335

Asset/Event Number	1816
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	

Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1817
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1818
Asset/Event Name	Rhian House
Type of Asset/Event	Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13499
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313840
Northing	926090
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13499

Asset/Event Number	1819

Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1820
Asset/Event Name	Upper Borgue
Type of Asset/Event	Field Boundary
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13500
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312430
Northing	927150
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13500

Asset/Event Number	1821
Asset/Event Name	Upper Borgue
Type of Asset/Event	Field Boundary
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13501
Status	Non-designated Heritage Asset
Section:	N/A

Easting	312680
Northing	926750
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13501

Asset/Event Number	1822
Asset/Event Name	Possible Standing Stone, Upper Borgue
Type of Asset/Event	Standing Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13502
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312460
Northing	926890
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13502

Asset/Event Number	1823
Asset/Event Name	Upper Borgue
Type of Asset/Event	Mound
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG13503
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312620
Northing	926960
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13503

Asset/Event Number	1824
Asset/Event Name	Upper Borgue
Type of Asset/Event	Site
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13504
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312570
Northing	927010
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13504

Asset/Event Number	1825
Asset/Event Name	Rhian House
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13505
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313390
Northing	926530
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13505

Asset/Event Number	1826
Asset/Event Name	Catburn
Type of Asset/Event	Mound
Date and/or Period	Undated
Listing No./NRHE Number	<Null>

HER Number	MHG13508
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313010
Northing	925700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13508

Asset/Event Number	1827
Asset/Event Name	Upper Borgue
Type of Asset/Event	Field Boundary
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13509
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312560
Northing	926800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13509

Asset/Event Number	1828
Asset/Event Name	Rhian House
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13510
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313090
Northing	926200
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13510

Asset/Event Number	1829
Asset/Event Name	Battle Site, Skida Mire
Type of Asset/Event	Battle Site
Date and/or Period	Norse
Listing No./NRHE Number	<Null>
HER Number	MHG1352
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317708
Northing	954373
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1352

Asset/Event Number	1830
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1831
Asset/Event Name	Langwell House

Type of Asset/Event	Site
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG13523
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311077
Northing	923015
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13523

Asset/Event Number	1832
Asset/Event Name	Houstry Burn
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13524
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314840
Northing	935310
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13524

Asset/Event Number	1833
Asset/Event Name	Jock's Lodge
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13526
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318950

Northing	938920
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13526

Asset/Event Number	1834
Asset/Event Name	Latheron Park
Type of Asset/Event	Park
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13527
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318900
Northing	938300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13527

Asset/Event Number	1835
Asset/Event Name	Rusgan
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13528
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319880
Northing	938110
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13528

Asset/Event Number	1836
Asset/Event Name	Raongeal
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13529
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318450
Northing	937120
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13529

Asset/Event Number	1837
Asset/Event Name	Arrycraggan
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13530
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319870
Northing	937880
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13530

Asset/Event Number	1838
Asset/Event Name	Roskleen
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13531

Status	Non-designated Heritage Asset
Section:	N/A
Easting	316890
Northing	936240
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13531

Asset/Event Number	1839
Asset/Event Name	Flygla
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13532
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319050
Northing	936300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13532

Asset/Event Number	1840
Asset/Event Name	Longal, Newlands of Houstry
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13533
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315800
Northing	935060
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13533

Asset/Event Number	1841
Asset/Event Name	Rean
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13536
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318010
Northing	935970
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13536

Asset/Event Number	1842
Asset/Event Name	Cairn - Loedebest Wood
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13538
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313970
Northing	931740
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13538

Asset/Event Number	1843
Asset/Event Name	Standing Stone - Cnoc Na Maranaich
Type of Asset/Event	Standing Stone

Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13539
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313203
Northing	933149
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13539

Asset/Event Number	1844
Asset/Event Name	Loedebest
Type of Asset/Event	Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13540
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313220
Northing	932300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13540

Asset/Event Number	1845
Asset/Event Name	Cnoc Ma Maranaich
Type of Asset/Event	Enclosure
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13541
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312700
Northing	932600

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13541

Asset/Event Number	1846
Asset/Event Name	Loedebest
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13542
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313300
Northing	932400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13542

Asset/Event Number	1847
Asset/Event Name	Loedebest
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13543
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313400
Northing	932200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13543

Asset/Event Number	1848
Asset/Event Name	Loedebest
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13544
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313374
Northing	932402
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13544

Asset/Event Number	1849
Asset/Event Name	Loedebest
Type of Asset/Event	Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13545
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312990
Northing	932380
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13545

Asset/Event Number	1850
Asset/Event Name	Cnoc Na Maranaich
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13549
Status	Non-designated Heritage Asset

Section:	N/A
Easting	313300
Northing	932800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13549

Asset/Event Number	1851
Asset/Event Name	Loedebest
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13550
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313469
Northing	932223
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13550

Asset/Event Number	1852
Asset/Event Name	Loedebest
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13551
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313820
Northing	932310
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG13551

Asset/Event Number	1853
Asset/Event Name	Loedebest
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13552
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313892
Northing	932070
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13552

Asset/Event Number	1854
Asset/Event Name	Loedebest
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13553
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313740
Northing	932249
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13553

Asset/Event Number	1855
Asset/Event Name	Cnoc Na Maranaich
Type of Asset/Event	Hut Circle; Enclosure
Date and/or Period	Prehistoric

Listing No./NRHE Number	<Null>
HER Number	MHG13554
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313400
Northing	932900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13554

Asset/Event Number	1856
Asset/Event Name	Loedebest
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13555
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313768
Northing	932169
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13555

Asset/Event Number	1857
Asset/Event Name	Achorn
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13556
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314050
Northing	930080
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13556

Asset/Event Number	1858
Asset/Event Name	Achorn
Type of Asset/Event	Field System
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13557
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314040
Northing	930070
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13557

Asset/Event Number	1859
Asset/Event Name	Braehiller
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13558
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314800
Northing	931800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13558

Asset/Event Number	1860

Asset/Event Name	Balantrath
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13559
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314738
Northing	930636
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13559

Asset/Event Number	1861
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1862
Asset/Event Name	Balantrath
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13561
Status	Non-designated Heritage Asset
Section:	N/A

Easting	314400
Northing	930800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13561

Asset/Event Number	1863
Asset/Event Name	Creag an Fhithich
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13562
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314300
Northing	931000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13562

Asset/Event Number	1864
Asset/Event Name	Creag an Fhithich
Type of Asset/Event	Field System
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG13563
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314300
Northing	931000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13563

Asset/Event Number	1865
Asset/Event Name	Balcraggie
Type of Asset/Event	Structure
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG13564
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314050
Northing	931020
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13564

Asset/Event Number	1866
Asset/Event Name	Achorn
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13565
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314090
Northing	930070
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13565

Asset/Event Number	1867
Asset/Event Name	Achorn
Type of Asset/Event	Mound
Date and/or Period	Undated
Listing No./NRHE Number	<Null>

HER Number	MHG13566
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314060
Northing	930090
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13566

Asset/Event Number	1868
Asset/Event Name	Balantrath
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13567
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314544
Northing	930672
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13567

Asset/Event Number	1869
Asset/Event Name	Loedebest
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13568
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313839
Northing	931919
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13568

Asset/Event Number	1870
Asset/Event Name	Cairn - Loedebest
Type of Asset/Event	Cairn?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13569
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313840
Northing	931800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13569

Asset/Event Number	1871
Asset/Event Name	Boundary Bank, Loedebest
Type of Asset/Event	Boundary Bank
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG13570
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313880
Northing	931500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13570

Asset/Event Number	1872
Asset/Event Name	Loedebest

Type of Asset/Event	Bank (Earthwork)
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13571
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313850
Northing	931500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13571

Asset/Event Number	1873
Asset/Event Name	Loedebest
Type of Asset/Event	Enclosure
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13572
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314800
Northing	931300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13572

Asset/Event Number	1874
Asset/Event Name	Braehiller
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13575
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314373

Northing	932411
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13575

Asset/Event Number	1875
Asset/Event Name	Braehiller
Type of Asset/Event	Long Barrow?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13577
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314500
Northing	932200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13577

Asset/Event Number	1876
Asset/Event Name	Buoldhu
Type of Asset/Event	Hut Circle; Enclosure
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13581
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313800
Northing	933900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13581

Asset/Event Number	1877
Asset/Event Name	Crask
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13590
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316860
Northing	934260
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13590

Asset/Event Number	1878
Asset/Event Name	Blackburn
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13592
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315060
Northing	930010
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13592

Asset/Event Number	1879
Asset/Event Name	Minera
Type of Asset/Event	Quarry
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13594

Status	Non-designated Heritage Asset
Section:	N/A
Easting	315600
Northing	934300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13594

Asset/Event Number	1880
Asset/Event Name	Stone scatter, Houstry
Type of Asset/Event	Stone Heap; Non Antiquity?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13595
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315030
Northing	933080
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13595

Asset/Event Number	1881
Asset/Event Name	Clearance cairn, Houstry
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13596
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315030
Northing	934030
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13596

Asset/Event Number	1882
Asset/Event Name	Stone setting, Achnagoul
Type of Asset/Event	Stone Setting
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13603
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316000
Northing	932300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13603

Asset/Event Number	1883
Asset/Event Name	Carved stone, Penag
Type of Asset/Event	Carved Stone
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG13604
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315280
Northing	934930
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13604

Asset/Event Number	1884
Asset/Event Name	Newlands of Houstry
Type of Asset/Event	Farmstead

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13605
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315900
Northing	934800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13605

Asset/Event Number	1885
Asset/Event Name	Boultach
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13606
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317500
Northing	934700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13606

Asset/Event Number	1886
Asset/Event Name	Milton
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13607
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315400
Northing	930300

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13607

Asset/Event Number	1887
Asset/Event Name	Blackburn
Type of Asset/Event	Settlement
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG13608
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315300
Northing	930200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13608

Asset/Event Number	1888
Asset/Event Name	Stone objects, Leavad
Type of Asset/Event	Findspot
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG13610
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317200
Northing	946000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13610

Asset/Event Number	1889
Asset/Event Name	Boanbean
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13612
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319850
Northing	942810
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13612

Asset/Event Number	1890
Asset/Event Name	Bronze Age cist burial - Craig-na-Feich, Achavanich
Type of Asset/Event	Cist
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13613
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317837
Northing	943335
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13613

Asset/Event Number	1891
Asset/Event Name	Blackmire Burn
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13614
Status	Non-designated Heritage Asset

Section:	N/A
Easting	318800
Northing	940800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13614

Asset/Event Number	1892
Asset/Event Name	Clais Balgaire
Type of Asset/Event	Building
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13615
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318930
Northing	941750
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13615

Asset/Event Number	1893
Asset/Event Name	Sheepfold, Loch Stemster
Type of Asset/Event	Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13616
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318843
Northing	941907
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG13616

Asset/Event Number	1894
Asset/Event Name	Buolnabein
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13663
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320140
Northing	937850
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13663

Asset/Event Number	1895
Asset/Event Name	Golticlay
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG13694
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320100
Northing	941000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13694

Asset/Event Number	1896
Asset/Event Name	Cnoc Croit Na Maoile
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric

Listing No./NRHE Number	<Null>
HER Number	MHG14107
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248830
Northing	849120
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG14107

Asset/Event Number	1897
Asset/Event Name	Coul House
Type of Asset/Event	House; Historical Association
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG14110
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246250
Northing	856410
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG14110

Asset/Event Number	1898
Asset/Event Name	Sockach
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG14141
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257100
Northing	868300
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG14141

Asset/Event Number	1899
Asset/Event Name	Cnoc A Mhuilinn
Type of Asset/Event	Cup Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG14146
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251347
Northing	862555
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG14146

Asset/Event Number	1900
Asset/Event Name	Mill dam, Henman's Burn
Type of Asset/Event	Mill Dam
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG14152
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258490
Northing	896440
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG14152

Asset/Event Number	1901

Asset/Event Name	West Strathcarron Wood
Type of Asset/Event	Structure
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG14155
Status	Non-designated Heritage Asset
Section:	N/A
Easting	253889
Northing	892071
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG14155

Asset/Event Number	1902
Asset/Event Name	Brag Rangag Township
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1418
Status	Listed Building - Category C
Section:	N/A
Easting	317500
Northing	942100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1418

Asset/Event Number	1903
Asset/Event Name	Meeting place and market - Spittalhill
Type of Asset/Event	Moot?; Market?
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG1426
Status	Non-designated Heritage Asset
Section:	N/A

Easting	316765
Northing	955614
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1426

Asset/Event Number	4033
Asset/Event Name	St Magnus Chapel, Banniskirk
Type of Asset/Event	Chapel
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG1431
Status	Listed Building - Category C
Section:	N/A
Easting	317040
Northing	957130
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1431

Asset/Event Number	1905
Asset/Event Name	Dalnamain
Type of Asset/Event	Rig And Furrow
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG14567
Status	Listed Building - Category B
Section:	N/A
Easting	272300
Northing	898900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG14567

Asset/Event Number	1906
Asset/Event Name	Dalnamain
Type of Asset/Event	Hut Circle; Kiln
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG14569
Status	Listed Building - Category B
Section:	N/A
Easting	272130
Northing	898590
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG14569

Asset/Event Number	1907
Asset/Event Name	Dalnamain
Type of Asset/Event	Findspot
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG14570
Status	Listed Building - Category C
Section:	N/A
Easting	272450
Northing	898500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG14570

Asset/Event Number	1908
Asset/Event Name	Carrol Wood
Type of Asset/Event	Settlement
Date and/or Period	Undated
Listing No./NRHE Number	<Null>

HER Number	MHG14633
Status	Listed Building - Category C
Section:	N/A
Easting	284800
Northing	906100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG14633

Asset/Event Number	1909
Asset/Event Name	Settlement - Carrol Wood
Type of Asset/Event	Settlement
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG14634
Status	Listed Building - Category C
Section:	N/A
Easting	284600
Northing	906300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG14634

Asset/Event Number	1910
Asset/Event Name	Carrol Wood
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG14635
Status	Listed Building - Category B
Section:	N/A
Easting	285330
Northing	905900
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG14635

Asset/Event Number	1911
Asset/Event Name	Carrol Wood
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG14636
Status	Listed Building - Category C
Section:	N/A
Easting	285410
Northing	905610
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG14636

Asset/Event Number	1912
Asset/Event Name	Carrol Wood
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG14660
Status	Listed Building - Category C
Section:	N/A
Easting	284920
Northing	906350
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG14660

Asset/Event Number	1913
Asset/Event Name	2 Mill House, Berriedale

Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG14882
Status	Listed Building - Category C
Section:	N/A
Easting	311905
Northing	922633
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG14882

Asset/Event Number	1914
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1915
Asset/Event Name	The White House (Former Church of Scotland Manse), Berriedale
Type of Asset/Event	Manse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG15120
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311990

Northing	922919
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG15120

Asset/Event Number	1916
Asset/Event Name	War Memorial, Berriedale
Type of Asset/Event	War Memorial; War Memorial
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG15133
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311820
Northing	922663
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG15133

Asset/Event Number	1917
Asset/Event Name	Welbeck Estate Office, Berriedale Post Office, & Stable Range
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG15212
Status	Listed Building - Category C
Section:	N/A
Easting	311792
Northing	922742
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG15212

Asset/Event Number	1918
Asset/Event Name	1 Mill House, Berriedale
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG15245
Status	Listed Building - Category B
Section:	N/A
Easting	311893
Northing	922635
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG15245

Asset/Event Number	1919
Asset/Event Name	1 Portland Terrace, Berriedale
Type of Asset/Event	Terraced House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG15319
Status	Listed Building - Category B
Section:	N/A
Easting	311974
Northing	922515
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG15319

Asset/Event Number	1920
Asset/Event Name	Shore Cottages, Berriedale
Type of Asset/Event	Terrace; Privy House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG15332

Status	Non-designated Heritage Asset
Section:	N/A
Easting	312084
Northing	922580
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG15332

Asset/Event Number	1921
Asset/Event Name	Aigas House
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG15448
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245965
Northing	841458
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG15448

Asset/Event Number	1922
Asset/Event Name	Gate Lodge, Aigas House
Type of Asset/Event	Lodge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG15634
Status	Listed Building - Category B
Section:	N/A
Easting	246145
Northing	841633
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG15634

Asset/Event Number	1923
Asset/Event Name	Druim Cottage, Crask of Aigas
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG15733
Status	Listed Building - Category B
Section:	N/A
Easting	246768
Northing	842342
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG15733

Asset/Event Number	1924
Asset/Event Name	Beaufort Castle, West Lodge
Type of Asset/Event	Lodge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG15734
Status	Listed Building - Category C
Section:	N/A
Easting	249637
Northing	842208
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG15734

Asset/Event Number	1925
Asset/Event Name	Kilmorack Old Manse and Steading
Type of Asset/Event	Manse

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG15766
Status	Listed Building - Category C
Section:	N/A
Easting	249283
Northing	844364
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG15766

Asset/Event Number	1926
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1927
Asset/Event Name	Cists, Lower Tuftingall
Type of Asset/Event	Cist
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG161
Status	Listed Building - Category C
Section:	N/A
Easting	317550
Northing	954390

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG161

Asset/Event Number	1928
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1929
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1930
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1931
Asset/Event Name	Hut Circle, Dun Burn
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1629
Status	Non-designated Heritage Asset
Section:	N/A
Easting	309860
Northing	925150
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1629

Asset/Event Number	1932
Asset/Event Name	Homestead, Dun Burn
Type of Asset/Event	Homestead
Date and/or Period	Prehistoric/Early Historic
Listing No./NRHE Number	<Null>
HER Number	MHG1630
Status	Listed Building - Category B

Section:	N/A
Easting	309820
Northing	925010
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1630

Asset/Event Number	1933
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1934
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	

Description	VOID - number not assigned

Asset/Event Number	1935
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1936
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1937
Asset/Event Name	Strathview, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG16456
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248321
Northing	858444
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG16456

Asset/Event Number	1938
Asset/Event Name	Contin Manse
Type of Asset/Event	Manse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG16513
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245735
Northing	855652
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG16513

Asset/Event Number	1939
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	

Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1940
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1941
Asset/Event Name	Farmstead, Allt Clais Raoin
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG1671
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313750
Northing	931430
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1671

Asset/Event Number	1942

Asset/Event Name	Hut Circle, Allt Clais Raoin
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1672
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313350
Northing	931470
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1672

Asset/Event Number	1943
Asset/Event Name	Former Free Church Manse, Jamestown
Type of Asset/Event	Manse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG16722
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247892
Northing	856577
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG16722

Asset/Event Number	1944
Asset/Event Name	Former Church of Scotland Manse Walled Garden, Rogart
Type of Asset/Event	Walled Garden
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG17028
Status	Non-designated Heritage Asset
Section:	N/A

Easting	273883
Northing	903389
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG17028

Asset/Event Number	1945
Asset/Event Name	Service Court, Carbisdale Castle
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG17086
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257431
Northing	895282
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG17086

Asset/Event Number	1946
Asset/Event Name	Culrain Mains
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG17118
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257519
Northing	894735
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG17118

Asset/Event Number	1947
Asset/Event Name	6 Gartymore
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG17132
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301325
Northing	914863
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG17132

Asset/Event Number	1948
Asset/Event Name	Leathad A' Chuailein
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG17419
Status	Non-designated Heritage Asset
Section:	N/A
Easting	265459
Northing	896241
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG17419

Asset/Event Number	1949
Asset/Event Name	Borgue, Croft
Type of Asset/Event	Cruck House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG17693
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313200
Northing	926000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG17693

Asset/Event Number	1950
Asset/Event Name	Borgue, Croft
Type of Asset/Event	Cruck House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG17697
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313200
Northing	925700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG17697

Asset/Event Number	1951
Asset/Event Name	Borgue, Croft
Type of Asset/Event	Cruck House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG17862
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313200
Northing	926300
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG17862

Asset/Event Number	1952
Asset/Event Name	Kilearnan
Type of Asset/Event	General View
Date and/or Period	None
Listing No./NRHE Number	<Null>
HER Number	MHG17876
Status	Non-designated Heritage Asset
Section:	N/A
Easting	295000
Northing	918000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG17876

Asset/Event Number	1953
Asset/Event Name	Borgue
Type of Asset/Event	Cruck House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG17917
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313000
Northing	925800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG17917

Asset/Event Number	1954
Asset/Event Name	Borgue

Type of Asset/Event	Cruck House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG17918
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313000
Northing	926200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG17918

Asset/Event Number	1955
Asset/Event Name	Borgue, Croft
Type of Asset/Event	Cruck House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG17919
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313100
Northing	925700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG17919

Asset/Event Number	1956
Asset/Event Name	Borgue
Type of Asset/Event	Cruck House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18000
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312800

Northing	926000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18000

Asset/Event Number	1957
Asset/Event Name	Borgue
Type of Asset/Event	Cruck House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18128
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313700
Northing	926500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18128

Asset/Event Number	1958
Asset/Event Name	Borgue
Type of Asset/Event	Cruck House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18129
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313700
Northing	927100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18129

Asset/Event Number	1959
Asset/Event Name	Ramscraigs, Clais- Cairn
Type of Asset/Event	Cruck House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18130
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313800
Northing	927120
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18130

Asset/Event Number	1960
Asset/Event Name	Ramscraigs, Clais Cairn
Type of Asset/Event	Cruck House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18131
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313800
Northing	927200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18131

Asset/Event Number	1961
Asset/Event Name	Ramscraigs, Croft House
Type of Asset/Event	Cruck House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18136

Status	Non-designated Heritage Asset
Section:	N/A
Easting	314200
Northing	927400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18136

Asset/Event Number	1962
Asset/Event Name	Ramscraigs, Croft House
Type of Asset/Event	Cruck House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18138
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314100
Northing	927100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18138

Asset/Event Number	1963
Asset/Event Name	Cruck Frame, Borgue 8
Type of Asset/Event	Cruck House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18140
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313300
Northing	926200
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18140

Asset/Event Number	1964
Asset/Event Name	Cruck frame, Borgue 9
Type of Asset/Event	Cruck House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18141
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313600
Northing	926500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18141

Asset/Event Number	1965
Asset/Event Name	Ramscraigs, the Buaile, Croft and Kiln Barn
Type of Asset/Event	Cruck House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18174
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314100
Northing	926900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18174

Asset/Event Number	1966
Asset/Event Name	Wester Kintradwell
Type of Asset/Event	Township

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18348
Status	Non-designated Heritage Asset
Section:	N/A
Easting	291400
Northing	907400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18348

Asset/Event Number	1967
Asset/Event Name	Badbog
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18353
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263800
Northing	896130
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18353

Asset/Event Number	1968
Asset/Event Name	Craigton
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18354
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263110
Northing	896080

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18354

Asset/Event Number	1969
Asset/Event Name	Craigton
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18355
Status	Non-designated Heritage Asset
Section:	N/A
Easting	262500
Northing	896170
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18355

Asset/Event Number	1970
Asset/Event Name	Blar Na Curaich
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18356
Status	Non-designated Heritage Asset
Section:	N/A
Easting	261800
Northing	896500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18356

Asset/Event Number	1971
Asset/Event Name	Leathad Breac
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18357
Status	Non-designated Heritage Asset
Section:	N/A
Easting	261450
Northing	897080
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18357

Asset/Event Number	1972
Asset/Event Name	Coirshellach
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18358
Status	Non-designated Heritage Asset
Section:	N/A
Easting	260900
Northing	896050
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18358

Asset/Event Number	1973
Asset/Event Name	Ach' Torra' Dhamh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18367
Status	Non-designated Heritage Asset

Section:	N/A
Easting	272303
Northing	900444
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18367

Asset/Event Number	1974
Asset/Event Name	Banniskirk Moss
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18385
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315900
Northing	958600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18385

Asset/Event Number	1975
Asset/Event Name	Backlass
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18397
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320400
Northing	954000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG18397

Asset/Event Number	1976
Asset/Event Name	Possible Shieling Hut, Green Folds
Type of Asset/Event	Shieling Settlement; Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18398
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320100
Northing	950000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18398

Asset/Event Number	1977
Asset/Event Name	Craigton
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18412
Status	Non-designated Heritage Asset
Section:	N/A
Easting	262620
Northing	896290
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18412

Asset/Event Number	1978
Asset/Event Name	Spittal Hill
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG18431
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316200
Northing	955700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18431

Asset/Event Number	1979
Asset/Event Name	Ben-A-Chielt
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18440
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319800
Northing	937800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18440

Asset/Event Number	1980
Asset/Event Name	Ben-A-Chielt
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18442
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319800
Northing	937000
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18442

Asset/Event Number	1981
Asset/Event Name	Newlands of Latheron
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18446
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319000
Northing	936300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18446

Asset/Event Number	1982
Asset/Event Name	Red Rock
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18447
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318428
Northing	936559
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18447

Asset/Event Number	1983

Asset/Event Name	Buoltach
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18448
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317694
Northing	935790
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18448

Asset/Event Number	1984
Asset/Event Name	Rinsary
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18449
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311600
Northing	923420
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18449

Asset/Event Number	1985
Asset/Event Name	Berridale
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18451
Status	Non-designated Heritage Asset
Section:	N/A

Easting	311990
Northing	922470
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18451

Asset/Event Number	1986
Asset/Event Name	Flagstone Works, Spittal Quarries
Type of Asset/Event	Flagstone Works
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG185
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317200
Northing	954100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG185

Asset/Event Number	1987
Asset/Event Name	Gailiable
Type of Asset/Event	Township; Head Dyke; Enclosure; Rig And Furrow
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18623
Status	Non-designated Heritage Asset
Section:	N/A
Easting	294800
Northing	918200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18623

Asset/Event Number	1988
Asset/Event Name	Strathpeffer Station - Achterneed, Fodderty
Type of Asset/Event	Railway Station
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18655
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249100
Northing	859800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18655

Asset/Event Number	1989
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	1990
Asset/Event Name	Boath Farmstead
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG18719
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255700
Northing	875100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18719

Asset/Event Number	1991
Asset/Event Name	Achalone
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18883
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315013
Northing	955787
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18883

Asset/Event Number	1992
Asset/Event Name	Houstry
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18889
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314500
Northing	957200
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18889

Asset/Event Number	1993
Asset/Event Name	Benachie Farm
Type of Asset/Event	Enclosure; Boundary Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18890
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314800
Northing	956000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18890

Asset/Event Number	1994
Asset/Event Name	Mound, Torr an Fhidhlier
Type of Asset/Event	Mound; Broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG189
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316320
Northing	954730
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG189

Asset/Event Number	1995
Asset/Event Name	Achalone Farm

Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG18916
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314981
Northing	956748
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18916

Asset/Event Number	1996
Asset/Event Name	Inveran
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19065
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257240
Northing	897540
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19065

Asset/Event Number	1997
Asset/Event Name	Invershin
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19066
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257570

Northing	896620
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19066

Asset/Event Number	1998
Asset/Event Name	Balblair Wood
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19068
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258630
Northing	894750
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19068

Asset/Event Number	1999
Asset/Event Name	Invershin Hotel
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19069
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258300
Northing	895200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19069

Asset/Event Number	2000
Asset/Event Name	Shean
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19070
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258600
Northing	895600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19070

Asset/Event Number	2001
Asset/Event Name	Dun-Garbh-Airigh
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19071
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263701
Northing	899003
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19071

Asset/Event Number	2002
Asset/Event Name	Lonmore
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19122

Status	Non-designated Heritage Asset
Section:	N/A
Easting	293100
Northing	910400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19122

Asset/Event Number	2003
Asset/Event Name	Badenahauglish
Type of Asset/Event	Farmstead; Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19127
Status	Non-designated Heritage Asset
Section:	N/A
Easting	291100
Northing	909700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19127

Asset/Event Number	2004
Asset/Event Name	Uaigh Bheag
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19141
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293700
Northing	914400
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19141

Asset/Event Number	2005
Asset/Event Name	Achlone
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19143
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316129
Northing	956526
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19143

Asset/Event Number	2006
Asset/Event Name	Spittal Mains
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19148
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316534
Northing	954587
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19148

Asset/Event Number	2007
Asset/Event Name	Spittal Hill
Type of Asset/Event	Building

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19150
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316400
Northing	955200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19150

Asset/Event Number	2008
Asset/Event Name	Spittal Hill
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19152
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316600
Northing	955600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19152

Asset/Event Number	2009
Asset/Event Name	Achcomhairle
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19153
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316100
Northing	955900

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19153

Asset/Event Number	2010
Asset/Event Name	Banniskirk Mains
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19158
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317203
Northing	957065
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19158

Asset/Event Number	2011
Asset/Event Name	Banniskirk Mains
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19159
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317780
Northing	956926
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19159

Asset/Event Number	2012
Asset/Event Name	Ouglassy Parks
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19160
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318183
Northing	956541
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19160

Asset/Event Number	2013
Asset/Event Name	Ouglassy Parks
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19161
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318150
Northing	956433
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19161

Asset/Event Number	2014
Asset/Event Name	Ouglassy Parks
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19162
Status	Non-designated Heritage Asset

Section:	N/A
Easting	318539
Northing	956659
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19162

Asset/Event Number	2015
Asset/Event Name	Milton
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19165
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316400
Northing	957900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19165

Asset/Event Number	2016
Asset/Event Name	Paddockfield
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19168
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318837
Northing	955782
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG19168

Asset/Event Number	2017
Asset/Event Name	Toftingall
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19169
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318600
Northing	954400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19169

Asset/Event Number	2018
Asset/Event Name	Achlone
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19170
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315500
Northing	956500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19170

Asset/Event Number	2019
Asset/Event Name	Garskelly
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG19261
Status	Non-designated Heritage Asset
Section:	N/A
Easting	271600
Northing	897701
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19261

Asset/Event Number	2020
Asset/Event Name	Cnoc A' Choire Bhuidhe
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19308
Status	Non-designated Heritage Asset
Section:	N/A
Easting	260360
Northing	895570
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19308

Asset/Event Number	2021
Asset/Event Name	Uaigh Bheag, Loth Burn
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19325
Status	Non-designated Heritage Asset
Section:	N/A
Easting	294100
Northing	914300
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19325

Asset/Event Number	2022
Asset/Event Name	Uaigh Bheag, Loth Burn
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19326
Status	Non-designated Heritage Asset
Section:	N/A
Easting	294000
Northing	914100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19326

Asset/Event Number	2023
Asset/Event Name	Uaigh Bheag, Loth Burn
Type of Asset/Event	Building; Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19327
Status	Non-designated Heritage Asset
Section:	N/A
Easting	294100
Northing	914100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19327

Asset/Event Number	2024

Asset/Event Name	Loth Burn
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19356
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293800
Northing	912900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19356

Asset/Event Number	2025
Asset/Event Name	Loth Burn
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19357
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293100
Northing	912600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19357

Asset/Event Number	2026
Asset/Event Name	Eldrable Burn
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19366
Status	Non-designated Heritage Asset
Section:	N/A

Easting	298200
Northing	918200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19366

Asset/Event Number	2027
Asset/Event Name	Salzcraggie Halt
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19369
Status	Non-designated Heritage Asset
Section:	N/A
Easting	299600
Northing	918100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19369

Asset/Event Number	2028
Asset/Event Name	Grudsterry
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19370
Status	Non-designated Heritage Asset
Section:	N/A
Easting	299800
Northing	918000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19370

Asset/Event Number	2029
Asset/Event Name	Cnoc Bad A'Chrasgaidh
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19385
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275600
Northing	902400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19385

Asset/Event Number	2030
Asset/Event Name	Bridge of Horn
Type of Asset/Event	Farmstead; Corn Drying Kiln; Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19453
Status	Non-designated Heritage Asset
Section:	N/A
Easting	279400
Northing	905000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19453

Asset/Event Number	2031
Asset/Event Name	Clashgal
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG19464
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315600
Northing	958500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19464

Asset/Event Number	2032
Asset/Event Name	Blar Liath
Type of Asset/Event	Rig And Furrow
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19465
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315000
Northing	958100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19465

Asset/Event Number	2033
Asset/Event Name	Woodside
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19466
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315400
Northing	958300
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19466

Asset/Event Number	2034
Asset/Event Name	Banniskirk Moss
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19467
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316200
Northing	958100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19467

Asset/Event Number	2035
Asset/Event Name	Berriedale, the Old Smithy
Type of Asset/Event	Smithy
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19475
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311000
Northing	922000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19475

Asset/Event Number	2036
Asset/Event Name	Abercross

Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19593
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276600
Northing	900200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19593

Asset/Event Number	2037
Asset/Event Name	Loch Brora
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19599
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285000
Northing	906300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19599

Asset/Event Number	2038
Asset/Event Name	Culrain, Station
Type of Asset/Event	Railway Station
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19633
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257650

Northing	894750
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19633

Asset/Event Number	2039
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2040
Asset/Event Name	Hut circle, Shielton
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG1967
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320570
Northing	950766
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG1967

Asset/Event Number	2041
Asset/Event Name	Cruck Framed Cottage, Badereskie
Type of Asset/Event	Cruck House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19700
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320047
Northing	940062
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19700

Asset/Event Number	2042
Asset/Event Name	Glen Glass, 'Garabil'
Type of Asset/Event	Township; Head Dyke; Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19702
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256100
Northing	869000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19702

Asset/Event Number	2043
Asset/Event Name	Dunn
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19760

Status	Non-designated Heritage Asset
Section:	N/A
Easting	320100
Northing	955960
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19760

Asset/Event Number	2044
Asset/Event Name	Lady's Moss
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19765
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318200
Northing	955700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19765

Asset/Event Number	2045
Asset/Event Name	South Dunn
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19766
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319700
Northing	955500
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19766

Asset/Event Number	2046
Asset/Event Name	Crofts of Hillpark
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19768
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317760
Northing	957690
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19768

Asset/Event Number	2047
Asset/Event Name	Crofts of Hillpark
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19769
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317762
Northing	955919
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19769

Asset/Event Number	2048
Asset/Event Name	30 Gartymore
Type of Asset/Event	House

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19775
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301352
Northing	914865
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19775

Asset/Event Number	2049
Asset/Event Name	Crofts of Hillpark
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19779
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317422
Northing	955597
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19779

Asset/Event Number	2050
Asset/Event Name	Lazy Beds, Dunn
Type of Asset/Event	Lazy Beds
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19789
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320000
Northing	956000

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19789

Asset/Event Number	2051
Asset/Event Name	Banniskirk Mains
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19795
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317170
Northing	957030
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19795

Asset/Event Number	2052
Asset/Event Name	Dunn
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19799
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319600
Northing	956300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19799

Asset/Event Number	2053
Asset/Event Name	Crofts of Hillpark
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19802
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317600
Northing	956100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19802

Asset/Event Number	2054
Asset/Event Name	Backlass
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19810
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320790
Northing	953930
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19810

Asset/Event Number	2055
Asset/Event Name	Lodge Roques
Type of Asset/Event	Farmstead; Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19813
Status	Non-designated Heritage Asset

Section:	N/A
Easting	320900
Northing	953300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19813

Asset/Event Number	2057
Asset/Event Name	Backlass
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19815
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320900
Northing	953700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19815

Asset/Event Number	2058
Asset/Event Name	Balnasmurich
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19816
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319100
Northing	955200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG19816

Asset/Event Number	2059
Asset/Event Name	Toftingall
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19824
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317552
Northing	955021
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19824

Asset/Event Number	2060
Asset/Event Name	Balnasmurich
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19825
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319250
Northing	955060
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19825

Asset/Event Number	2061
Asset/Event Name	Farmsteading, Markethill
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG19827
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319258
Northing	954939
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19827

Asset/Event Number	2062
Asset/Event Name	Farmsteading, Markethill
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19828
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319226
Northing	954736
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19828

Asset/Event Number	2063
Asset/Event Name	Backlass Hill
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19829
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320010
Northing	954800
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19829

Asset/Event Number	2064
Asset/Event Name	Backlass Hill
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19830
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320150
Northing	954700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19830

Asset/Event Number	2065
Asset/Event Name	Houstry of Dunn
Type of Asset/Event	Clearance Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG19831
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320800
Northing	954800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19831

Asset/Event Number	2066

Asset/Event Name	Backlass Hill
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19832
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320130
Northing	954580
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19832

Asset/Event Number	2067
Asset/Event Name	Backlass Hill
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19833
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320500
Northing	954400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19833

Asset/Event Number	2068
Asset/Event Name	Backlass Hill
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19834
Status	Non-designated Heritage Asset
Section:	N/A

Easting	320300
Northing	950200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19834

Asset/Event Number	2069
Asset/Event Name	Tower Mains
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19843
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246940
Northing	852440
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19843

Asset/Event Number	2070
Asset/Event Name	Achalone
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19844
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315760
Northing	957020
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19844

Asset/Event Number	2071
Asset/Event Name	Milton
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19845
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316470
Northing	957920
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19845

Asset/Event Number	2072
Asset/Event Name	Milton
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19846
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316600
Northing	957800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19846

Asset/Event Number	2073
Asset/Event Name	Houstry
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG19849
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314800
Northing	957400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19849

Asset/Event Number	2074
Asset/Event Name	Banniskirk House
Type of Asset/Event	Farmstead; Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19851
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315500
Northing	957400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19851

Asset/Event Number	2075
Asset/Event Name	Achalone
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19853
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315450
Northing	957030
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19853

Asset/Event Number	2076
Asset/Event Name	Tower Mains
Type of Asset/Event	Threshing Mill
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19856
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246940
Northing	852460
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19856

Asset/Event Number	2077
Asset/Event Name	Achalone
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19882
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315442
Northing	956922
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19882

Asset/Event Number	2078
Asset/Event Name	Suspension Footbridge, Berriedale

Type of Asset/Event	Suspension Bridge; Footbridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19885
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312023
Northing	922477
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19885

Asset/Event Number	2079
Asset/Event Name	Grain Store, Kinnettas Road, Strathpeffer
Type of Asset/Event	Storehouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19888
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248080
Northing	858020
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19888

Asset/Event Number	2080
Asset/Event Name	Achalone
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19898
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315800

Northing	956380
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19898

Asset/Event Number	2081
Asset/Event Name	Achalone
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19899
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315400
Northing	956200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19899

Asset/Event Number	2082
Asset/Event Name	Spittal Hill
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19900
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316900
Northing	956200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19900

Asset/Event Number	2083
Asset/Event Name	Helmsdale Radio Station
Type of Asset/Event	Radio Station
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG19910
Status	Non-designated Heritage Asset
Section:	N/A
Easting	303800
Northing	918850
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19910

Asset/Event Number	2084
Asset/Event Name	Carnlaggie
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19945
Status	Non-designated Heritage Asset
Section:	N/A
Easting	302200
Northing	916300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19945

Asset/Event Number	2085
Asset/Event Name	Gartymore
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19948

Status	Non-designated Heritage Asset
Section:	N/A
Easting	300100
Northing	914500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19948

Asset/Event Number	2086
Asset/Event Name	West Helmsdale
Type of Asset/Event	Crofting Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19949
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301800
Northing	915300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19949

Asset/Event Number	2087
Asset/Event Name	Gartymore
Type of Asset/Event	Crofting Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19950
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301200
Northing	914600
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19950

Asset/Event Number	2088
Asset/Event Name	Creag Loisgte
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19953
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311350
Northing	927950
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19953

Asset/Event Number	2089
Asset/Event Name	Lodge Roques
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19994
Status	Non-designated Heritage Asset
Section:	N/A
Easting	321200
Northing	953300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19994

Asset/Event Number	2090
Asset/Event Name	Farmstead - Achnamoine
Type of Asset/Event	Farmstead

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20028
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317776
Northing	953827
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20028

Asset/Event Number	2091
Asset/Event Name	Acnnamoine
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20029
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318000
Northing	953700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20029

Asset/Event Number	2092
Asset/Event Name	Black Burn
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20030
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319530
Northing	953680

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20030

Asset/Event Number	2093
Asset/Event Name	Knockmartin
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20079
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256700
Northing	867060
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20079

Asset/Event Number	2094
Asset/Event Name	Allt Bog Na H-Aimhne
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20080
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254400
Northing	864100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20080

Asset/Event Number	2095
Asset/Event Name	Farm (290), Clare
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20082
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254261
Northing	865504
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20082

Asset/Event Number	2096
Asset/Event Name	Building, N of Knockantoul, Clare
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20083
Status	Non-designated Heritage Asset
Section:	N/A
Easting	253862
Northing	865391
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20083

Asset/Event Number	2097
Asset/Event Name	Building Bog Buidhe
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20087
Status	Non-designated Heritage Asset

Section:	N/A
Easting	256540
Northing	869090
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20087

Asset/Event Number	2098
Asset/Event Name	Balnarge Settlement
Type of Asset/Event	Settlement; Barn; Farmhouse; Byre; Horse Engine
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20088
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256500
Northing	868900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20088

Asset/Event Number	2099
Asset/Event Name	Lariebhuidhe
Type of Asset/Event	Farmstead; Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20089
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256900
Northing	868370
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG20089

Asset/Event Number	2100
Asset/Event Name	Houstry
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20115
Status	Non-designated Heritage Asset
Section:	N/A
Easting	321000
Northing	954100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20115

Asset/Event Number	2101
Asset/Event Name	Borgie
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20168
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312280
Northing	923120
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20168

Asset/Event Number	2102
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	

Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2103
Asset/Event Name	Langwell House
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20171
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311230
Northing	923300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20171

Asset/Event Number	2104
Asset/Event Name	Cnoc Fionn
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20172
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310600
Northing	923730
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20172

Asset/Event Number	2105
Asset/Event Name	Lower Newport
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20173
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312510
Northing	923810
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20173

Asset/Event Number	2106
Asset/Event Name	Ramscraigs
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20174
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314220
Northing	927370
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20174

Asset/Event Number	2107

Asset/Event Name	Borgue
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20175
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312960
Northing	925730
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20175

Asset/Event Number	2108
Asset/Event Name	Borgue
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20176
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313580
Northing	925680
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20176

Asset/Event Number	2109
Asset/Event Name	Berridale
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20179
Status	Non-designated Heritage Asset
Section:	N/A

Easting	312070
Northing	922680
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20179

Asset/Event Number	2110
Asset/Event Name	Millery
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20191
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310950
Northing	925390
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20191

Asset/Event Number	2111
Asset/Event Name	Site of possible shieling hut, Allt Caol
Type of Asset/Event	Shieling Hut
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20197
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318918
Northing	948077
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20197

Asset/Event Number	2112
Asset/Event Name	Tulloch Turnal
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20201
Status	Non-designated Heritage Asset
Section:	N/A
Easting	309050
Northing	922890
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20201

Asset/Event Number	2113
Asset/Event Name	Lang Well
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20202
Status	Non-designated Heritage Asset
Section:	N/A
Easting	309940
Northing	922400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20202

Asset/Event Number	2114
Asset/Event Name	Borgue Langwell
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG20203
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310270
Northing	921770
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20203

Asset/Event Number	2115
Asset/Event Name	Buoltach
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20204
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317965
Northing	935411
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20204

Asset/Event Number	2116
Asset/Event Name	Burn of Aultachlevan
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20226
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318150
Northing	941940
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20226

Asset/Event Number	2117
Asset/Event Name	Clashcrebie Beag
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20227
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319430
Northing	940800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20227

Asset/Event Number	2118
Asset/Event Name	Golticlay
Type of Asset/Event	Township; Head Dyke; Field System
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20228
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320231
Northing	940713
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20228

Asset/Event Number	2119
Asset/Event Name	Achkinloch

Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20230
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319200
Northing	942300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20230

Asset/Event Number	2120
Asset/Event Name	Stemster
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20231
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318700
Northing	944980
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20231

Asset/Event Number	2121
Asset/Event Name	Ballachly
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20233
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319650

Northing	944350
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20233

Asset/Event Number	2122
Asset/Event Name	Ben-A-Chielt
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20234
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319800
Northing	938100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20234

Asset/Event Number	2123
Asset/Event Name	Stemster
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20247
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318630
Northing	944110
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20247

Asset/Event Number	2124
Asset/Event Name	Caen
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20250
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301700
Northing	917700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20250

Asset/Event Number	2125
Asset/Event Name	River Helmsdale
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20261
Status	Non-designated Heritage Asset
Section:	N/A
Easting	300800
Northing	917600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20261

Asset/Event Number	2126
Asset/Event Name	Caen Burn
Type of Asset/Event	Township; Head Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20262

Status	Non-designated Heritage Asset
Section:	N/A
Easting	301100
Northing	918700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20262

Asset/Event Number	2127
Asset/Event Name	Building, possible mill - Langwell Plantation
Type of Asset/Event	Building; Watermill
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20269
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310700
Northing	922420
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20269

Asset/Event Number	2128
Asset/Event Name	Badrinsary
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20276
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311800
Northing	924000
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20276

Asset/Event Number	2129
Asset/Event Name	Loedebest
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20288
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313380
Northing	932390
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20288

Asset/Event Number	2130
Asset/Event Name	Loedebest
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20289
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313600
Northing	932100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20289

Asset/Event Number	2131
Asset/Event Name	Cnoc Na Maranaich
Type of Asset/Event	Building

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20290
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313320
Northing	932820
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20290

Asset/Event Number	2132
Asset/Event Name	Allt Bhuailteach
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20291
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312730
Northing	930700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20291

Asset/Event Number	2133
Asset/Event Name	Possible Shieling Hut, Cabhsair
Type of Asset/Event	Shieling Hut
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20292
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316799
Northing	948522

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20292

Asset/Event Number	2134
Asset/Event Name	Burn of Houstry
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20303
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314700
Northing	935300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20303

Asset/Event Number	2135
Asset/Event Name	Farm, Blackburn
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20316
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320078
Northing	938846
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20316

Asset/Event Number	2136
Asset/Event Name	Farmstead, Sheppardstown
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20317
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320136
Northing	939469
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20317

Asset/Event Number	2137
Asset/Event Name	Farm, Sheppardstown
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20318
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320042
Northing	939725
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20318

Asset/Event Number	2138
Asset/Event Name	Badnagie
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20326
Status	Non-designated Heritage Asset

Section:	N/A
Easting	315700
Northing	931400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20326

Asset/Event Number	2139
Asset/Event Name	Caen Burn
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20327
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301500
Northing	918800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20327

Asset/Event Number	2140
Asset/Event Name	Allt A' Bheathaich
Type of Asset/Event	Township; Head Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20328
Status	Non-designated Heritage Asset
Section:	N/A
Easting	302600
Northing	917100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG20328

Asset/Event Number	2141
Asset/Event Name	Clashcrebie Mor
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20339
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319000
Northing	940100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20339

Asset/Event Number	2142
Asset/Event Name	Badnagie
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20346
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315500
Northing	931700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20346

Asset/Event Number	2143
Asset/Event Name	Acharn
Type of Asset/Event	Building
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG20463
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258460
Northing	873900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20463

Asset/Event Number	2144
Asset/Event Name	Acharn
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20464
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258160
Northing	873830
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20464

Asset/Event Number	2145
Asset/Event Name	Easter Ballone
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20466
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258000
Northing	873400
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20466

Asset/Event Number	2146
Asset/Event Name	Allt A' Churraichd
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20467
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257000
Northing	895700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20467

Asset/Event Number	2147
Asset/Event Name	Boath
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20468
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257400
Northing	873900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20468

Asset/Event Number	2148

Asset/Event Name	Building and limekiln, Boath
Type of Asset/Event	Farmstead; Lime Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20469
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256911
Northing	873492
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20469

Asset/Event Number	2149
Asset/Event Name	Glaick
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20471
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256800
Northing	873700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20471

Asset/Event Number	2150
Asset/Event Name	Ballavoulen
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20473
Status	Non-designated Heritage Asset
Section:	N/A

Easting	257280
Northing	874140
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20473

Asset/Event Number	2151
Asset/Event Name	Boath
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20474
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257300
Northing	873900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20474

Asset/Event Number	2152
Asset/Event Name	Boath
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20475
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256600
Northing	874400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20475

Asset/Event Number	2153
Asset/Event Name	Croftwards
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20618
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254900
Northing	891400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20618

Asset/Event Number	2154
Asset/Event Name	Ruigh Na Meinne
Type of Asset/Event	Township; Head Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256000
Northing	889100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20630

Asset/Event Number	2155
Asset/Event Name	Hillton Balchrick
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG20631
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254100
Northing	891700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20631

Asset/Event Number	2156
Asset/Event Name	Berryhill
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20633
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256300
Northing	891800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20633

Asset/Event Number	2157
Asset/Event Name	Berryhill
Type of Asset/Event	Farmstead; Boundary Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20634
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256300
Northing	891800
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20634

Asset/Event Number	2158
Asset/Event Name	Achagilliosa
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20641
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257400
Northing	893000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20641

Asset/Event Number	2159
Asset/Event Name	Syall Settlement
Type of Asset/Event	Township; Head Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20642
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257200
Northing	891200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20642

Asset/Event Number	2160
Asset/Event Name	Balnahinsh

Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20643
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257900
Northing	893500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20643

Asset/Event Number	2161
Asset/Event Name	Balnahinsh Burn
Type of Asset/Event	Farmstead; Boundary Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20645
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257490
Northing	893960
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20645

Asset/Event Number	2162
Asset/Event Name	Hillton
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20646
Status	Non-designated Heritage Asset
Section:	N/A
Easting	253800

Northing	891900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20646

Asset/Event Number	2163
Asset/Event Name	Boath
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20647
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257700
Northing	873600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20647

Asset/Event Number	2164
Asset/Event Name	River Averon
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20652
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256700
Northing	875000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20652

Asset/Event Number	2165
Asset/Event Name	River Averon
Type of Asset/Event	Enclosure; Field Boundary
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20653
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255300
Northing	875200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20653

Asset/Event Number	2166
Asset/Event Name	Balmeanoch
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20656
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258780
Northing	874150
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20656

Asset/Event Number	2167
Asset/Event Name	Acharn
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20663

Status	Non-designated Heritage Asset
Section:	N/A
Easting	258280
Northing	873680
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20663

Asset/Event Number	2168
Asset/Event Name	Balinoe Wood
Type of Asset/Event	Building; Field Boundary
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20665
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257700
Northing	893800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20665

Asset/Event Number	2169
Asset/Event Name	Rhelonie
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20693
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255600
Northing	897400
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20693

Asset/Event Number	2170
Asset/Event Name	Dounie
Type of Asset/Event	Township; Head Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20694
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256300
Northing	890700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20694

Asset/Event Number	2171
Asset/Event Name	Easter Gruinards
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20695
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254200
Northing	891200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20695

Asset/Event Number	2172
Asset/Event Name	Baile Buidhe
Type of Asset/Event	Farmstead

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20696
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254200
Northing	890400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20696

Asset/Event Number	2173
Asset/Event Name	Kyle of Sutherland
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20706
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256600
Northing	896900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20706

Asset/Event Number	2174
Asset/Event Name	Eilean Dubh
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20752
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256040
Northing	868110

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20752

Asset/Event Number	2175
Asset/Event Name	Farmstead, Lynechork
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20754
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256720
Northing	867270
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20754

Asset/Event Number	2176
Asset/Event Name	Heights of Keppoch
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20760
Status	Non-designated Heritage Asset
Section:	N/A
Easting	250400
Northing	860600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20760

Asset/Event Number	2177
Asset/Event Name	Heights of Fodderty
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20761
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251000
Northing	860900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20761

Asset/Event Number	2178
Asset/Event Name	Building, Heights of Fodderty
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20763
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251357
Northing	861213
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20763

Asset/Event Number	2179
Asset/Event Name	Bog A' Bhreacaich
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20764
Status	Non-designated Heritage Asset

Section:	N/A
Easting	253025
Northing	862616
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20764

Asset/Event Number	2180
Asset/Event Name	Uig
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20770
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257200
Northing	867790
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20770

Asset/Event Number	2181
Asset/Event Name	Clare
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20783
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254800
Northing	865200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG20783

Asset/Event Number	2182
Asset/Event Name	Building, Dunruadh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20787
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254680
Northing	865780
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20787

Asset/Event Number	2183
Asset/Event Name	Dubh Chlais
Type of Asset/Event	Field System
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20789
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254500
Northing	869200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20789

Asset/Event Number	2184
Asset/Event Name	Creag Nam Fitheach
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG20790
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254630
Northing	869040
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20790

Asset/Event Number	2185
Asset/Event Name	Cnoc an Oir
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20791
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255240
Northing	868680
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20791

Asset/Event Number	2186
Asset/Event Name	Abhainn Sgitheach
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20793
Status	Non-designated Heritage Asset
Section:	N/A
Easting	253408
Northing	863775
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20793

Asset/Event Number	2187
Asset/Event Name	Glac Bhan
Type of Asset/Event	Township; Head Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20794
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254400
Northing	863500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20794

Asset/Event Number	2188
Asset/Event Name	Glac Bhan
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20795
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254840
Northing	863440
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20795

Asset/Event Number	2189

Asset/Event Name	Kilmorack Old Parish Church, Graveyard
Type of Asset/Event	Cemetery
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG21116
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249424
Northing	844340
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG21116

Asset/Event Number	2190
Asset/Event Name	Morvich Farm
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG21159
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275300
Northing	900770
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG21159

Asset/Event Number	2191
Asset/Event Name	Morvich Farm, Threshing Machine
Type of Asset/Event	Threshing Mill
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG21160
Status	Non-designated Heritage Asset
Section:	N/A

Easting	275300
Northing	900770
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG21160

Asset/Event Number	2192
Asset/Event Name	Coul House, Gardens & Parkland
Type of Asset/Event	Park
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG21530
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246120
Northing	856350
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG21530

Asset/Event Number	2193
Asset/Event Name	Contin, Smithy
Type of Asset/Event	Smithy
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG21607
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245830
Northing	855990
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG21607

Asset/Event Number	2194
Asset/Event Name	Kilmorack, Upper Falls
Type of Asset/Event	Waterfall
Date and/or Period	None
Listing No./NRHE Number	<Null>
HER Number	MHG21689
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249100
Northing	844230
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG21689

Asset/Event Number	2195
Asset/Event Name	Kilmorack, Summerhouse (site of)
Type of Asset/Event	Summerhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG21690
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249300
Northing	844240
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG21690

Asset/Event Number	2196
Asset/Event Name	Clare
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG21758
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254290
Northing	865320
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG21758

Asset/Event Number	2197
Asset/Event Name	Fairburn House, Estate
Type of Asset/Event	Estate
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG21947
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245000
Northing	853000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG21947

Asset/Event Number	2198
Asset/Event Name	Fairburn House, Curling Pond
Type of Asset/Event	Curling Pond
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG21955
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245200
Northing	853050
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG21955

Asset/Event Number	2199
Asset/Event Name	Fairburn House, Estate Cottages
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG21956
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245000
Northing	853000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG21956

Asset/Event Number	2200
Asset/Event Name	Fairburn House, Graveyard
Type of Asset/Event	Cemetery
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG21957
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245450
Northing	852810
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG21957

Asset/Event Number	2201
Asset/Event Name	Fairburn House, Kitchen Garden

Type of Asset/Event	Kitchen Garden
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG21958
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245420
Northing	852720
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG21958

Asset/Event Number	2202
Asset/Event Name	Fairburn House, Lawns
Type of Asset/Event	Garden
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG21959
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245480
Northing	853030
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG21959

Asset/Event Number	2203
Asset/Event Name	Fairburn House, Ponds
Type of Asset/Event	Pond
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG21960
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245080

Northing	852920
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG21960

Asset/Event Number	2204
Asset/Event Name	Fairburn House, Stables
Type of Asset/Event	Stable
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG21961
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245340
Northing	852850
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG21961

Asset/Event Number	2205
Asset/Event Name	Fairburn House, Waterfall
Type of Asset/Event	Waterfall
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG21962
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246830
Northing	852720
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG21962

Asset/Event Number	2206
Asset/Event Name	Waterfall - Falls of Rogie
Type of Asset/Event	Waterfall
Date and/or Period	None
Listing No./NRHE Number	<Null>
HER Number	MHG21963
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244541
Northing	858453
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG21963

Asset/Event Number	2207
Asset/Event Name	Fannyfield
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG21964
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255225
Northing	865762
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG21964

Asset/Event Number	2208
Asset/Event Name	Crofts of South Dunn
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG22578

Status	Non-designated Heritage Asset
Section:	N/A
Easting	318420
Northing	955430
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22578

Asset/Event Number	2209
Asset/Event Name	Spoilheap, Ousdale Burn
Type of Asset/Event	Burnt Mound?; Spoil Heap
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG226
Status	Non-designated Heritage Asset
Section:	N/A
Easting	306790
Northing	919250
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG226

Asset/Event Number	2210
Asset/Event Name	Ulladale, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG22609
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248223
Northing	858445
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22609

Asset/Event Number	2211
Asset/Event Name	War Memorial, Strathpeffer
Type of Asset/Event	War Memorial
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG22611
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248000
Northing	858100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22611

Asset/Event Number	2212
Asset/Event Name	Windsor Lodge, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG22612
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248361
Northing	858501
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22612

Asset/Event Number	2213
Asset/Event Name	Summerhill, Strathpeffer
Type of Asset/Event	House

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG22616
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248159
Northing	858212
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22616

Asset/Event Number	2214
Asset/Event Name	Salisbury House, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG22632
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248262
Northing	858322
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22632

Asset/Event Number	2215
Asset/Event Name	The Spa Hotel (site) Strathpeffer
Type of Asset/Event	Hotel
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG22637
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247671
Northing	857661

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22637

Asset/Event Number	2216
Asset/Event Name	Wester Moy
Type of Asset/Event	Enclosure
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG22682
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248000
Northing	855300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22682

Asset/Event Number	2217
Asset/Event Name	Balmoral Lodge, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG22699
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248251
Northing	858373
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22699

Asset/Event Number	2218
Asset/Event Name	Mound, Ousdale Burn
Type of Asset/Event	Clearance Cairn; Mound
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG227
Status	Non-designated Heritage Asset
Section:	N/A
Easting	306890
Northing	919210
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG227

Asset/Event Number	2219
Asset/Event Name	The Craig, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG22701
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248308
Northing	858498
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22701

Asset/Event Number	2220
Asset/Event Name	Birch Lodge, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG22711
Status	Non-designated Heritage Asset

Section:	N/A
Easting	248107
Northing	858171
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22711

Asset/Event Number	2221
Asset/Event Name	Club House, Strathpeffer Golf Club
Type of Asset/Event	Clubhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG22719
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248040
Northing	858578
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22719

Asset/Event Number	2222
Asset/Event Name	Craigroyston, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG22721
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248218
Northing	858290
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG22721

Asset/Event Number	2223
Asset/Event Name	Duart, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG22723
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248211
Northing	858405
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22723

Asset/Event Number	2224
Asset/Event Name	Glenesk, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG22724
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248197
Northing	858416
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22724

Asset/Event Number	2225
Asset/Event Name	Free Church of Scotland Manse, Strathpeffer
Type of Asset/Event	Manse
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG22729
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248251
Northing	858509
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22729

Asset/Event Number	2226
Asset/Event Name	1 & 2 Kinnettas Cottages, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG22730
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248044
Northing	858148
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22730

Asset/Event Number	2227
Asset/Event Name	Maybank, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG22733
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248131
Northing	858184
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22733

Asset/Event Number	2228
Asset/Event Name	Clearance Cairn, Ousdale Burn
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG228
Status	Non-designated Heritage Asset
Section:	N/A
Easting	306970
Northing	919060
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG228

Asset/Event Number	2229
Asset/Event Name	Township, Allt A' Bhurg
Type of Asset/Event	Township; Croft
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG229
Status	Non-designated Heritage Asset
Section:	N/A
Easting	306967
Northing	918676
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG229

Asset/Event Number	2230

Asset/Event Name	Cairnfield, Golticlay
Type of Asset/Event	Cairnfield
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG2293
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320312
Northing	940590
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2293

Asset/Event Number	2231
Asset/Event Name	Farmstead - Allt Foinnaidh, Urray
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG22955
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249429
Northing	849691
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22955

Asset/Event Number	2232
Asset/Event Name	Building and enclosure - Creag Na Manachuin
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG22956
Status	Non-designated Heritage Asset
Section:	N/A

Easting	249420
Northing	848020
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22956

Asset/Event Number	2233
Asset/Event Name	Cnoc Na Luibe
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG22957
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249300
Northing	848400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22957

Asset/Event Number	2234
Asset/Event Name	The Garden House, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23262
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248226
Northing	857887
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23262

Asset/Event Number	2235
Asset/Event Name	Ardochy
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23301
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246400
Northing	843200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23301

Asset/Event Number	2236
Asset/Event Name	Building - Breakachy Burn
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23304
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246026
Northing	845178
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23304

Asset/Event Number	2237
Asset/Event Name	Farley
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG23305
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247500
Northing	845100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23305

Asset/Event Number	2238
Asset/Event Name	Farmstead - Breakachy
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23308
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246847
Northing	844710
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23308

Asset/Event Number	2239
Asset/Event Name	Breakachy
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23309
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247180
Northing	844980
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23309

Asset/Event Number	2240
Asset/Event Name	Breakachy
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23311
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246200
Northing	844100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23311

Asset/Event Number	2241
Asset/Event Name	Ardochy
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23312
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246450
Northing	843670
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23312

Asset/Event Number	2242
Asset/Event Name	Allt Cuil Na Caillich

Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23313
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245400
Northing	841700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23313

Asset/Event Number	2243
Asset/Event Name	Loch an Uird
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23316
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246700
Northing	843100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23316

Asset/Event Number	2244
Asset/Event Name	Ruttle Wood
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23317
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247700

Northing	843700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23317

Asset/Event Number	2245
Asset/Event Name	Loch an Uird
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23319
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246700
Northing	843100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23319

Asset/Event Number	2246
Asset/Event Name	Mains of Aigas
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23320
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245700
Northing	841400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23320

Asset/Event Number	2247
Asset/Event Name	Culburnie
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23323
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248100
Northing	841200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23323

Asset/Event Number	2248
Asset/Event Name	Lonbuie
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23326
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248300
Northing	841800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23326

Asset/Event Number	2249
Asset/Event Name	Wester Moy
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23395

Status	Non-designated Heritage Asset
Section:	N/A
Easting	247960
Northing	855350
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23395

Asset/Event Number	2250
Asset/Event Name	Muirton Mains
Type of Asset/Event	Farm
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23412
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245460
Northing	853650
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23412

Asset/Event Number	2251
Asset/Event Name	Jamestown, Free Church
Type of Asset/Event	Church
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23711
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247778
Northing	856591
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23711

Asset/Event Number	2252
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2253
Asset/Event Name	Auchederson
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23786
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246855
Northing	850631
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23786

Asset/Event Number	2254
Asset/Event Name	Inveran Inn
Type of Asset/Event	Inn

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23787
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257368
Northing	897490
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23787

Asset/Event Number	2255
Asset/Event Name	Salzcraggie Halt, Station
Type of Asset/Event	Railway Station
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23991
Status	Non-designated Heritage Asset
Section:	N/A
Easting	299540
Northing	918140
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23991

Asset/Event Number	2256
Asset/Event Name	Langwell Lodge
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24066
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311344
Northing	922760

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24066

Asset/Event Number	2257
Asset/Event Name	Teanassie Primary School
Type of Asset/Event	School
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24072
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247550
Northing	844130
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24072

Asset/Event Number	2258
Asset/Event Name	Borgue, Croft
Type of Asset/Event	Croft
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24188
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313050
Northing	926150
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24188

Asset/Event Number	2259
Asset/Event Name	Borgue, Longall, Croft
Type of Asset/Event	Croft
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24189
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312800
Northing	926230
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24189

Asset/Event Number	2260
Asset/Event Name	Borgue, Croft
Type of Asset/Event	Croft
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24190
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312600
Northing	925800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24190

Asset/Event Number	2261
Asset/Event Name	Borgue, Croft
Type of Asset/Event	Croft
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24191
Status	Non-designated Heritage Asset

Section:	N/A
Easting	313200
Northing	925600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24191

Asset/Event Number	2262
Asset/Event Name	Borgue, Croft
Type of Asset/Event	Croft
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24192
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313400
Northing	926800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24192

Asset/Event Number	2263
Asset/Event Name	Burnt Mound, Tulloch Turnal
Type of Asset/Event	Burnt Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG2421
Status	Non-designated Heritage Asset
Section:	N/A
Easting	309160
Northing	922880
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG2421

Asset/Event Number	2264
Asset/Event Name	Hospital, Obsdale
Type of Asset/Event	Hospital
Date and/or Period	Medieval
Listing No./NRHE Number	<Null>
HER Number	MHG2422
Status	Non-designated Heritage Asset
Section:	N/A
Easting	307000
Northing	920000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2422

Asset/Event Number	2265
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2266
Asset/Event Name	The Grey Hen's Well - Latheron, Caithness
Type of Asset/Event	Well
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG2424
Status	Non-designated Heritage Asset
Section:	N/A
Easting	309130
Northing	920900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2424

Asset/Event Number	2267
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2268
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	

Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2269
Asset/Event Name	Hut circle,Bad an Achaid
Type of Asset/Event	Homestead
Date and/or Period	Prehistoric/Early Historic
Listing No./NRHE Number	<Null>
HER Number	MHG2428
Status	Non-designated Heritage Asset
Section:	N/A
Easting	308314
Northing	924019
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2428

Asset/Event Number	2270
Asset/Event Name	Hut circle, Allt A' Chriosduidhe
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG2429
Status	Non-designated Heritage Asset
Section:	N/A
Easting	309830
Northing	924700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2429

Asset/Event Number	2271

Asset/Event Name	Hut circle, Allt A' Chriosduidhe
Type of Asset/Event	Hut Circle; Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG2430
Status	Non-designated Heritage Asset
Section:	N/A
Easting	309850
Northing	924400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2430

Asset/Event Number	2272
Asset/Event Name	Ramscraigs
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24330
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314300
Northing	927470
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24330

Asset/Event Number	2273
Asset/Event Name	Allt an Ruamhair
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24400
Status	Non-designated Heritage Asset
Section:	N/A

Easting	249300
Northing	861000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24400

Asset/Event Number	2274
Asset/Event Name	Enclosure - Gleann Sgathaich, Fodderty
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24413
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245982
Northing	861255
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24413

Asset/Event Number	2275
Asset/Event Name	Heights of Inchvannie
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24414
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249300
Northing	860500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24414

Asset/Event Number	2276
Asset/Event Name	Allt a 'Choire Sliogaich
Type of Asset/Event	Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG24447
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255100
Northing	875500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24447

Asset/Event Number	2277
Asset/Event Name	Mound - Culburnie Muir, Kiltarlity
Type of Asset/Event	Mound
Date and/or Period	Medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24519
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248300
Northing	841200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24519

Asset/Event Number	2278
Asset/Event Name	Turf bank - Lonbuie Wood
Type of Asset/Event	Turf Bank
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG24522
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249400
Northing	841900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24522

Asset/Event Number	2279
Asset/Event Name	Old stone dyke - Beaufort West Lodge
Type of Asset/Event	Dyke?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24523
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249600
Northing	842200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24523

Asset/Event Number	2280
Asset/Event Name	Bottacks
Type of Asset/Event	Crofting Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24534
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248800
Northing	860300
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24534

Asset/Event Number	2281
Asset/Event Name	Allt Garbh-Airigh
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24628
Status	Non-designated Heritage Asset
Section:	N/A
Easting	260100
Northing	895700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24628

Asset/Event Number	2282
Asset/Event Name	Borgue, Croft
Type of Asset/Event	Croft
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24639
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313180
Northing	925810
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24639

Asset/Event Number	2283
Asset/Event Name	Farm, Loch Achonachie

Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24679
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244191
Northing	854494
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24679

Asset/Event Number	2284
Asset/Event Name	Borg Township
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG2471
Status	Non-designated Heritage Asset
Section:	N/A
Easting	307003
Northing	918902
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2471

Asset/Event Number	2285
Asset/Event Name	Strathan
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24713
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245470

Northing	852520
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24713

Asset/Event Number	2286
Asset/Event Name	Farmstead, Polbathaidh
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG2472
Status	Non-designated Heritage Asset
Section:	N/A
Easting	307899
Northing	919103
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2472

Asset/Event Number	2287
Asset/Event Name	Strathan
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24726
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245700
Northing	852650
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24726

Asset/Event Number	2288
Asset/Event Name	Sheepfold, Ulladale
Type of Asset/Event	Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24727
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247983
Northing	858781
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24727

Asset/Event Number	2289
Asset/Event Name	Well, Fuaran Geal
Type of Asset/Event	Well
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG2473
Status	Non-designated Heritage Asset
Section:	N/A
Easting	306042
Northing	918272
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2473

Asset/Event Number	2290
Asset/Event Name	Ulladale
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24730

Status	Non-designated Heritage Asset
Section:	N/A
Easting	247510
Northing	858660
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24730

Asset/Event Number	2291
Asset/Event Name	Ulladale
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24732
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247320
Northing	858160
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24732

Asset/Event Number	2292
Asset/Event Name	Jamestown
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24733
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248120
Northing	856390
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24733

Asset/Event Number	2293
Asset/Event Name	Auchmore Cottage
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24734
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248700
Northing	850100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24734

Asset/Event Number	2294
Asset/Event Name	Tower Wood
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24735
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246980
Northing	852270
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24735

Asset/Event Number	2295
Asset/Event Name	East Mains of Fairburn
Type of Asset/Event	Farmstead

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24736
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247350
Northing	853020
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24736

Asset/Event Number	2296
Asset/Event Name	Faebait Wood
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24739
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248100
Northing	851300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24739

Asset/Event Number	2297
Asset/Event Name	Township - Badbea, Latheron
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG2474
Status	Non-designated Heritage Asset
Section:	N/A
Easting	308653
Northing	919742

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2474

Asset/Event Number	2298
Asset/Event Name	Tighnafraoch
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24741
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246470
Northing	852740
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24741

Asset/Event Number	2299
Asset/Event Name	Strathan
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24742
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245460
Northing	852560
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24742

Asset/Event Number	2300
Asset/Event Name	Cairnfield, Ousdale Burn
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG2475
Status	Non-designated Heritage Asset
Section:	N/A
Easting	307000
Northing	919400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2475

Asset/Event Number	2301
Asset/Event Name	Braeantra
Type of Asset/Event	Lade
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG24895
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256700
Northing	877900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG24895

Asset/Event Number	2302
Asset/Event Name	Badbea
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG25057
Status	Non-designated Heritage Asset

Section:	N/A
Easting	309200
Northing	920100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG25057

Asset/Event Number	2303
Asset/Event Name	Hut circle, Allt a'Chroisduidale.Dun Burn
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG25058
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310000
Northing	924800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG25058

Asset/Event Number	2304
Asset/Event Name	Mission Chapel
Type of Asset/Event	Chapel
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG25110
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312200
Northing	923000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG25110

Asset/Event Number	2305
Asset/Event Name	Arrowhead in cairn, Boath
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG25209
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258000
Northing	873000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG25209

Asset/Event Number	2306
Asset/Event Name	Crofts of South Dunn
Type of Asset/Event	Croft
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG2523
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319000
Northing	955300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2523

Asset/Event Number	2307
Asset/Event Name	Garbh-Airigh
Type of Asset/Event	Township
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG25255
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263500
Northing	898700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG25255

Asset/Event Number	2308
Asset/Event Name	Coire Buidhe
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG25258
Status	Non-designated Heritage Asset
Section:	N/A
Easting	261400
Northing	895900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG25258

Asset/Event Number	2309
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	

Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2310
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2311
Asset/Event Name	Berriedale
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG2537
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310548
Northing	925736
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2537

Asset/Event Number	2312

Asset/Event Name	Dailyoich
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG2545
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310227
Northing	924368
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2545

Asset/Event Number	2313
Asset/Event Name	Broch, Ballachly
Type of Asset/Event	Broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG2546
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319560
Northing	944230
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2546

Asset/Event Number	2314
Asset/Event Name	Mill of Stamster
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG2547
Status	Non-designated Heritage Asset
Section:	N/A

Easting	317900
Northing	941900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2547

Asset/Event Number	2315
Asset/Event Name	Balmeanoch
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG25618
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258780
Northing	874150
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG25618

Asset/Event Number	2316
Asset/Event Name	Farmstead, Rhianacoil
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG2563
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318350
Northing	945480
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2563

Asset/Event Number	2317
Asset/Event Name	Balmeanoch
Type of Asset/Event	Horse Engine House; Threshing Mill
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG25666
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258790
Northing	874170
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG25666

Asset/Event Number	2318
Asset/Event Name	Berriedale, Langwell Water
Type of Asset/Event	Clearance Cairn; Stone Heap
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG26142
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311570
Northing	922270
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG26142

Asset/Event Number	2319
Asset/Event Name	Inver township, Berriedale, Langwell Water
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG26143
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311700
Northing	922400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG26143

Asset/Event Number	2320
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2321
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	

Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2322
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2323
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2324
Asset/Event Name	Iron Axe and Sickle - Loch Nam Bonnach

Type of Asset/Event	Findspot
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG2655
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247000
Northing	847000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2655

Asset/Event Number	2325
Asset/Event Name	Iron Working Site, Loch Nan Eun
Type of Asset/Event	Iron Working Site
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG2656
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247100
Northing	848700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2656

Asset/Event Number	2326
Asset/Event Name	Enclosure, Cnoc Na Moine
Type of Asset/Event	Enclosure
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG2657
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247800

Northing	845600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2657

Asset/Event Number	2327
Asset/Event Name	Montrose's Camp, Fairly Wood
Type of Asset/Event	Military Camp
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG2660
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248000
Northing	846000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2660

Asset/Event Number	2328
Asset/Event Name	Field System, Bealaidh Mor
Type of Asset/Event	Field System
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG2661
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248100
Northing	846300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2661

Asset/Event Number	2329
Asset/Event Name	Hut Circle, Cnoc Na Moine
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG2662
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247670
Northing	845850
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2662

Asset/Event Number	2330
Asset/Event Name	Kerb Cairn, Cnoc Na Moine
Type of Asset/Event	Kerb Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG2663
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247990
Northing	845790
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2663

Asset/Event Number	2331
Asset/Event Name	Field System, Cnoc Na Moine
Type of Asset/Event	Field System
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG2664

Status	Non-designated Heritage Asset
Section:	N/A
Easting	247899
Northing	845734
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2664

Asset/Event Number	2332
Asset/Event Name	Wall - Cragganmore
Type of Asset/Event	Wall
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG26641
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247941
Northing	840962
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG26641

Asset/Event Number	2333
Asset/Event Name	Cairn - Ruttle Wood
Type of Asset/Event	Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG26642
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247800
Northing	842300
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG26642

Asset/Event Number	2334
Asset/Event Name	Enclosure - Hughton
Type of Asset/Event	Enclosure; Structure; Mound
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG26643
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247200
Northing	841700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG26643

Asset/Event Number	2335
Asset/Event Name	Possible grouse butt - Ruttle Wood
Type of Asset/Event	Grouse Butt?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG26644
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247500
Northing	842300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG26644

Asset/Event Number	2336
Asset/Event Name	Iron Working Site, Farley
Type of Asset/Event	Iron Working Site

Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG2667
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247000
Northing	845000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2667

Asset/Event Number	2337
Asset/Event Name	Auchnagaul township
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG27034
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256800
Northing	868700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG27034

Asset/Event Number	2338
Asset/Event Name	Grouse Butt - Bendeallt
Type of Asset/Event	Grouse Butt
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG27035
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255500
Northing	871300

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG27035

Asset/Event Number	2339
Asset/Event Name	Remusaig
Type of Asset/Event	Building
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG27050
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273500
Northing	902300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG27050

Asset/Event Number	2340
Asset/Event Name	Burn of Houstry
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG27052
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315780
Northing	932450
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG27052

Asset/Event Number	2341
Asset/Event Name	Lochend
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG27070
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318180
Northing	940870
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG27070

Asset/Event Number	2342
Asset/Event Name	Lochend
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG27071
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318210
Northing	940610
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG27071

Asset/Event Number	2343
Asset/Event Name	Cnoc Dubh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG27072
Status	Non-designated Heritage Asset

Section:	N/A
Easting	318320
Northing	939890
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG27072

Asset/Event Number	2344
Asset/Event Name	Cnoc Dubh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG27073
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318260
Northing	939730
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG27073

Asset/Event Number	2345
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	

Description	VOID - number not assigned

Asset/Event Number	2346
Asset/Event Name	Grave Marker, Clach Tarrail
Type of Asset/Event	Grave Marker
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG2740
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249000
Northing	843000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2740

Asset/Event Number	2347
Asset/Event Name	Kerb Cairn, Home Farm
Type of Asset/Event	Kerb Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG2742
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249640
Northing	841880
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2742

Asset/Event Number	2348
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	

Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2349
Asset/Event Name	Farmstead - Torran
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG27554
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317048
Northing	947512
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG27554

Asset/Event Number	2350
Asset/Event Name	Burn of Tacher
Type of Asset/Event	Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG27555
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317340
Northing	946520
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG27555

Asset/Event Number	2351
Asset/Event Name	Shenvall
Type of Asset/Event	Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG27556
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316530
Northing	945480
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG27556

Asset/Event Number	2352
Asset/Event Name	Burnt Mound, Morvich Farm
Type of Asset/Event	Burnt Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28207
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275800
Northing	900950
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28207

Asset/Event Number	2353

Asset/Event Name	Ard a' Chlachain
Type of Asset/Event	Hut Circle; Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28222
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273110
Northing	901880
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28222

Asset/Event Number	2354
Asset/Event Name	Ard a' Chlachain
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28223
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273110
Northing	901880
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28223

Asset/Event Number	2355
Asset/Event Name	Ard a' Chlachain
Type of Asset/Event	Hut Circle; Rig And Furrow; Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28224
Status	Non-designated Heritage Asset
Section:	N/A

Easting	273120
Northing	901840
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28224

Asset/Event Number	2356
Asset/Event Name	Cairn, Ard a' Chlachain
Type of Asset/Event	Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG28225
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273040
Northing	901790
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28225

Asset/Event Number	2357
Asset/Event Name	Pits, Ard a' Chlachain
Type of Asset/Event	Pit
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG28226
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273100
Northing	901730
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28226

Asset/Event Number	2358
Asset/Event Name	Ard a' Chlachain
Type of Asset/Event	Curling Pond
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28231
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273350
Northing	901790
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28231

Asset/Event Number	2359
Asset/Event Name	Possible Standing Stone, Cnoc an Fhithich
Type of Asset/Event	Standing Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28232
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273580
Northing	901580
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28232

Asset/Event Number	2360
Asset/Event Name	Blairmore
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG28236
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274190
Northing	903790
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28236

Asset/Event Number	2361
Asset/Event Name	West Kinloch Farm
Type of Asset/Event	Farmstead; Rig And Furrow
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28242
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274950
Northing	903930
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28242

Asset/Event Number	2362
Asset/Event Name	Cnoc an t' Sidhein
Type of Asset/Event	Hut Circle; Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28243
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274760
Northing	903980
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28243

Asset/Event Number	2363
Asset/Event Name	Allt Bad a' Chrasgaidh
Type of Asset/Event	Township; Kiln Barn; Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28245
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274530
Northing	902600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28245

Asset/Event Number	2364
Asset/Event Name	Allt Bad a' Chrasgaidh
Type of Asset/Event	Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG28246
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274700
Northing	903250
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28246

Asset/Event Number	2365
Asset/Event Name	Little Rogart

Type of Asset/Event	Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28255
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273470
Northing	903130
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28255

Asset/Event Number	2366
Asset/Event Name	The Bank
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28258
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273710
Northing	903160
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28258

Asset/Event Number	2367
Asset/Event Name	East Kinnauld
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28261
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274120

Northing	901690
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28261

Asset/Event Number	2368
Asset/Event Name	East Kinnauld
Type of Asset/Event	Still
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28262
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274220
Northing	901510
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28262

Asset/Event Number	2369
Asset/Event Name	East Kinnauld
Type of Asset/Event	Hut
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28263
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274110
Northing	901740
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28263

Asset/Event Number	2370
Asset/Event Name	Allt Bad a' Chrasgaidh
Type of Asset/Event	Clearance Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG28264
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274340
Northing	902160
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28264

Asset/Event Number	2371
Asset/Event Name	Remusaig
Type of Asset/Event	Farmstead; Pen
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28265
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274120
Northing	902310
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28265

Asset/Event Number	2372
Asset/Event Name	Remusaig
Type of Asset/Event	Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG28266

Status	Non-designated Heritage Asset
Section:	N/A
Easting	274100
Northing	902670
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28266

Asset/Event Number	2373
Asset/Event Name	Badachrasgaidh
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274110
Northing	902900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28267

Asset/Event Number	2374
Asset/Event Name	Remusaig
Type of Asset/Event	Enclosure
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG28268
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274020
Northing	902220
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28268

Asset/Event Number	2375
Asset/Event Name	Remusaig
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28269
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273950
Northing	902250
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28269

Asset/Event Number	2376
Asset/Event Name	Cairn and Cist - Remusaig
Type of Asset/Event	Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG28270
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273940
Northing	902150
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28270

Asset/Event Number	2377
Asset/Event Name	Remusaig
Type of Asset/Event	Hut Circle

Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28271
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273800
Northing	902160
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28271

Asset/Event Number	2378
Asset/Event Name	Remusaig
Type of Asset/Event	Building
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG28272
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273640
Northing	902200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28272

Asset/Event Number	2379
Asset/Event Name	Remusaig
Type of Asset/Event	Enclosure
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28273
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273700
Northing	902080

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28273

Asset/Event Number	2380
Asset/Event Name	Possible Hut Circle, Burnt Mound and Enclosure, Remusaig
Type of Asset/Event	Hut Circle; Burnt Mound; Enclosure
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28274
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273871
Northing	901879
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28274

Asset/Event Number	2381
Asset/Event Name	East Kinnauld
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28276
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273970
Northing	901600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28276

Asset/Event Number	2382
Asset/Event Name	Milton Bank
Type of Asset/Event	Manse; Building; Clearance Cairn; Enclosure; Corn Drying Kiln
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG28296
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273881
Northing	903310
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28296

Asset/Event Number	2383
Asset/Event Name	Remusaig
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28298
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273720
Northing	902680
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28298

Asset/Event Number	2384
Asset/Event Name	Remusaig
Type of Asset/Event	Pen
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28299
Status	Non-designated Heritage Asset

Section:	N/A
Easting	273880
Northing	902750
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28299

Asset/Event Number	2385
Asset/Event Name	Remusaig
Type of Asset/Event	Hut Circle; Field System; Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28300
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273900
Northing	902460
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28300

Asset/Event Number	2386
Asset/Event Name	Burnt Mound, East Kinnauld
Type of Asset/Event	Burnt Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28308
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273970
Northing	901710
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG28308

Asset/Event Number	2387
Asset/Event Name	Milton Bank
Type of Asset/Event	Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG28310
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273820
Northing	902850
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28310

Asset/Event Number	2388
Asset/Event Name	Allt Bad a' Chrasgaidh
Type of Asset/Event	Firing Range
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28311
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274120
Northing	902980
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28311

Asset/Event Number	2389
Asset/Event Name	East Kinnauld
Type of Asset/Event	Pen
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG28312
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274380
Northing	901560
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28312

Asset/Event Number	2390
Asset/Event Name	Burnt Mounds - Allt Bad a' Chrasgaidh
Type of Asset/Event	Burnt Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28314
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274620
Northing	902480
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28314

Asset/Event Number	2391
Asset/Event Name	Standing Stone - Remusaig
Type of Asset/Event	Standing Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28315
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273800
Northing	902120
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28315

Asset/Event Number	2392
Asset/Event Name	Burnt Mounds etc (4) Marian's Rock
Type of Asset/Event	Burnt Mound; Enclosure
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28327
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274900
Northing	901200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28327

Asset/Event Number	2393
Asset/Event Name	Burnt Mound, East Kinnauld
Type of Asset/Event	Burnt Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28328
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274350
Northing	901750
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28328

Asset/Event Number	2394

Asset/Event Name	East Kinnauld
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28329
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274270
Northing	901670
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28329

Asset/Event Number	2395
Asset/Event Name	Burnt Mound, Cnoc an Fhithich
Type of Asset/Event	Burnt Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28330
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273590
Northing	901800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28330

Asset/Event Number	2396
Asset/Event Name	Burnt Mound, Remusaig
Type of Asset/Event	Burnt Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28331
Status	Non-designated Heritage Asset
Section:	N/A

Easting	273570
Northing	901890
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28331

Asset/Event Number	2397
Asset/Event Name	Hut circle, Allt Bad a' Chrasgaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28538
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275120
Northing	901870
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28538

Asset/Event Number	2398
Asset/Event Name	Dalnamein
Type of Asset/Event	Building; Rig And Furrow; Dyke; Corn Drying Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28634
Status	Non-designated Heritage Asset
Section:	N/A
Easting	272530
Northing	898600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28634

Asset/Event Number	2399
Asset/Event Name	Dalnamein
Type of Asset/Event	Corn Drying Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28635
Status	Non-designated Heritage Asset
Section:	N/A
Easting	272000
Northing	898500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28635

Asset/Event Number	2400
Asset/Event Name	Dalnamein
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28660
Status	Non-designated Heritage Asset
Section:	N/A
Easting	272130
Northing	898540
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28660

Asset/Event Number	2401
Asset/Event Name	Berriedale Water
Type of Asset/Event	Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>

HER Number	MHG28675
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310740
Northing	923180
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28675

Asset/Event Number	2402
Asset/Event Name	Langwell House
Type of Asset/Event	Wall
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28676
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310780
Northing	923000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28676

Asset/Event Number	2403
Asset/Event Name	Langwell House
Type of Asset/Event	Plantation Bank
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28677
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310760
Northing	922930
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28677

Asset/Event Number	2404
Asset/Event Name	Borgue Langwell
Type of Asset/Event	Plantation Bank
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28678
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310300
Northing	921970
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28678

Asset/Event Number	2405
Asset/Event Name	Borgue Langwell
Type of Asset/Event	Enclosure
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG28679
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310300
Northing	921880
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28679

Asset/Event Number	2406
Asset/Event Name	Trig point, Borgue Langwell

Type of Asset/Event	Triangulation Station
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28680
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310300
Northing	921290
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28680

Asset/Event Number	2407
Asset/Event Name	Langwell Water
Type of Asset/Event	Rig And Furrow
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28686
Status	Non-designated Heritage Asset
Section:	N/A
Easting	309750
Northing	921850
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28686

Asset/Event Number	2408
Asset/Event Name	Langwell Water
Type of Asset/Event	Rig And Furrow
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28688
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310110

Northing	921850
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28688

Asset/Event Number	2409
Asset/Event Name	Burnt Mound, Cnoc Sheagan
Type of Asset/Event	Burnt Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28689
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316440
Northing	933200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28689

Asset/Event Number	2410
Asset/Event Name	Cairn, Greentulloch
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28690
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316400
Northing	932100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28690

Asset/Event Number	2411
Asset/Event Name	Hut circle, W side Cnoc Sheagan
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28691
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316180
Northing	933320
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28691

Asset/Event Number	2412
Asset/Event Name	Possible Burnt Mound, Minera
Type of Asset/Event	Burnt Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28692
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315690
Northing	934750
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28692

Asset/Event Number	2413
Asset/Event Name	Minera
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28693

Status	Non-designated Heritage Asset
Section:	N/A
Easting	315640
Northing	934730
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28693

Asset/Event Number	2414
Asset/Event Name	Minera Farmstead
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28694
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315632
Northing	934592
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28694

Asset/Event Number	2415
Asset/Event Name	Buildings, Minera
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28695
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315540
Northing	934680
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28695

Asset/Event Number	2416
Asset/Event Name	Minera
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28696
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315540
Northing	934900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28696

Asset/Event Number	2417
Asset/Event Name	Burn of Houstry
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28697
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315520
Northing	932980
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28697

Asset/Event Number	2418
Asset/Event Name	Achnagoul
Type of Asset/Event	Farmstead

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28700
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316730
Northing	932910
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28700

Asset/Event Number	2419
Asset/Event Name	Achnagoul
Type of Asset/Event	Cairnfield
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28701
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315800
Northing	932500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28701

Asset/Event Number	2420
Asset/Event Name	Burn of Houstry
Type of Asset/Event	Cairnfield
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28702
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315680
Northing	932570

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28702

Asset/Event Number	2421
Asset/Event Name	Wellgreens
Type of Asset/Event	Farmstead; Pond
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG28854
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257600
Northing	892760
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28854

Asset/Event Number	2422
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2423
Asset/Event Name	Allt na Criche
Type of Asset/Event	Inn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG29193
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251926
Northing	863117
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG29193

Asset/Event Number	2424
Asset/Event Name	Rinsary Brae
Type of Asset/Event	Site (Unspecified)
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG29211
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311100
Northing	923500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG29211

Asset/Event Number	2425
Asset/Event Name	Lower Newport
Type of Asset/Event	Site (Unspecified)
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG29212
Status	Non-designated Heritage Asset

Section:	N/A
Easting	311400
Northing	923300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG29212

Asset/Event Number	2426
Asset/Event Name	Langwell House
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG29213
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311600
Northing	923000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG29213

Asset/Event Number	2427
Asset/Event Name	Berriedale Church
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG29214
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311900
Northing	923100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG29214

Asset/Event Number	2428
Asset/Event Name	River Brora
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG29234
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285801
Northing	905701
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG29234

Asset/Event Number	2429
Asset/Event Name	Hut circle, Coire Aghaisgeig
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG29305
Status	Non-designated Heritage Asset
Section:	N/A
Easting	283831
Northing	905876
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG29305

Asset/Event Number	2430
Asset/Event Name	Rangag Farm
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG29413
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317660
Northing	944080
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG29413

Asset/Event Number	2431
Asset/Event Name	Cluanie
Type of Asset/Event	Icehouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG29440
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247400
Northing	843900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG29440

Asset/Event Number	2432
Asset/Event Name	Silver Coin, Achterneed Farm
Type of Asset/Event	Findspot
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG29557
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249100
Northing	859700
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG29557

Asset/Event Number	2433
Asset/Event Name	Helmsdale Land League Memorial
Type of Asset/Event	Commemorative Monument
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG29790
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301322
Northing	915408
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG29790

Asset/Event Number	2434
Asset/Event Name	Kilmorack
Type of Asset/Event	Telephone Box
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG29992
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249310
Northing	844310
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG29992

Asset/Event Number	2435

Asset/Event Name	Hughton
Type of Asset/Event	Telephone Box
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG29993
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247670
Northing	841540
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG29993

Asset/Event Number	2436
Asset/Event Name	Banniskirk House
Type of Asset/Event	House
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG30011
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316060
Northing	957490
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30011

Asset/Event Number	2437
Asset/Event Name	Sletdale Burn
Type of Asset/Event	Enclosure; Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG30021
Status	Non-designated Heritage Asset
Section:	N/A

Easting	291595
Northing	912922
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30021

Asset/Event Number	2438
Asset/Event Name	Sletdale Burn
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG30022
Status	Non-designated Heritage Asset
Section:	N/A
Easting	291283
Northing	913083
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30022

Asset/Event Number	2439
Asset/Event Name	Loth Burn
Type of Asset/Event	Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG30025
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293582
Northing	912642
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30025

Asset/Event Number	2440
Asset/Event Name	Graveyard, Invershin
Type of Asset/Event	Cemetery
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG30198
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257534
Northing	897219
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30198

Asset/Event Number	2441
Asset/Event Name	Orrin
Type of Asset/Event	Firing Range
Date and/or Period	Post-medieval/Modern
Listing No./NRHE Number	<Null>
HER Number	MHG30246
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243600
Northing	851700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30246

Asset/Event Number	2442
Asset/Event Name	Coull
Type of Asset/Event	Firing Range
Date and/or Period	Post-medieval/Modern
Listing No./NRHE Number	<Null>

HER Number	MHG30247
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245050
Northing	857500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30247

Asset/Event Number	2443
Asset/Event Name	Strathpeffer
Type of Asset/Event	Firing Range
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG30256
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247000
Northing	858300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30256

Asset/Event Number	2444
Asset/Event Name	Pillbox (site of), Balinoe
Type of Asset/Event	Pillbox
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG30304
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257910
Northing	893680
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30304

Asset/Event Number	2445
Asset/Event Name	Cup marked stone - Clyne
Type of Asset/Event	Cup Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG30343
Status	Non-designated Heritage Asset
Section:	N/A
Easting	286831
Northing	907706
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30343

Asset/Event Number	2446
Asset/Event Name	Clyne
Type of Asset/Event	Longhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG30344
Status	Non-designated Heritage Asset
Section:	N/A
Easting	286732
Northing	907946
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30344

Asset/Event Number	2447
Asset/Event Name	Clyne Clyne

Type of Asset/Event	Longhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG30346
Status	Non-designated Heritage Asset
Section:	N/A
Easting	286707
Northing	907974
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30346

Asset/Event Number	2448
Asset/Event Name	Standing Stone - Clyne
Type of Asset/Event	Standing Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG30347
Status	Non-designated Heritage Asset
Section:	N/A
Easting	286787
Northing	907702
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30347

Asset/Event Number	2449
Asset/Event Name	Berriedale
Type of Asset/Event	Roadblock
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG30393
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311800

Northing	922600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30393

Asset/Event Number	2450
Asset/Event Name	Berridale North
Type of Asset/Event	Military Installation
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG30470
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312100
Northing	922700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30470

Asset/Event Number	2451
Asset/Event Name	Barridale South
Type of Asset/Event	Military Installation
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG30471
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311100
Northing	922000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30471

Asset/Event Number	2452
Asset/Event Name	Hut circle, Glen Loth
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG30732
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293409
Northing	914854
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30732

Asset/Event Number	2453
Asset/Event Name	Glen Loth
Type of Asset/Event	Structure
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG30733
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293389
Northing	914868
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30733

Asset/Event Number	2454
Asset/Event Name	Possible Structure, Glen Loth
Type of Asset/Event	Structure
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG30734

Status	Non-designated Heritage Asset
Section:	N/A
Easting	293271
Northing	914845
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30734

Asset/Event Number	2455
Asset/Event Name	Glen Loth
Type of Asset/Event	Longhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG30735
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293456
Northing	914972
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30735

Asset/Event Number	2456
Asset/Event Name	Possible Hut Circle, Glen Loth
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG30736
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293475
Northing	914980
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30736

Asset/Event Number	2457
Asset/Event Name	Glen Loth
Type of Asset/Event	Longhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG30737
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293884
Northing	914910
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30737

Asset/Event Number	2458
Asset/Event Name	Glen Loth
Type of Asset/Event	Longhouse; Enclosure; Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG30738
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293639
Northing	914828
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30738

Asset/Event Number	2459
Asset/Event Name	Aircraft Crash Site, Westerdale
Type of Asset/Event	Aircraft Crash Site

Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG30820
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317700
Northing	950300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30820

Asset/Event Number	2460
Asset/Event Name	Aircraft Crash Site, Dunbeath
Type of Asset/Event	Aircraft Crash Site; War Memorial
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG30826
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311000
Northing	928300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30826

Asset/Event Number	2461
Asset/Event Name	Aircraft Crash Site, Creag Riabhach
Type of Asset/Event	Aircraft Crash Site
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG30834
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293700
Northing	911900

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30834

Asset/Event Number	2462
Asset/Event Name	Aircraft Crash Site, Helmsdale
Type of Asset/Event	Aircraft Crash Site
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG30835
Status	Non-designated Heritage Asset
Section:	N/A
Easting	297500
Northing	915200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30835

Asset/Event Number	2463
Asset/Event Name	Aircraft Crash Site, Brora
Type of Asset/Event	Aircraft Crash Site
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG30845
Status	Non-designated Heritage Asset
Section:	N/A
Easting	288900
Northing	908000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30845

Asset/Event Number	2464
Asset/Event Name	Aircraft Crash Site, Glen Glass
Type of Asset/Event	Aircraft Crash Site
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG30855
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254400
Northing	868900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30855

Asset/Event Number	2465
Asset/Event Name	Steading - Rhelonie
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG30872
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255586
Northing	897441
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30872

Asset/Event Number	2466
Asset/Event Name	Brora
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG30879
Status	Non-designated Heritage Asset

Section:	N/A
Easting	288378
Northing	906609
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30879

Asset/Event Number	2467
Asset/Event Name	Whorl in Cairn, Boath
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG30948
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258000
Northing	873000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG30948

Asset/Event Number	2468
Asset/Event Name	Foundations? Marrel
Type of Asset/Event	Building; Road
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG31209
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301926
Northing	917033
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG31209

Asset/Event Number	2469
Asset/Event Name	Battle Site, Lamentation Hill
Type of Asset/Event	Battle Site
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG31215
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256458
Northing	895889
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG31215

Asset/Event Number	2470
Asset/Event Name	Sulphureous Springs, S of Shielton
Type of Asset/Event	Spring
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG31234
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320897
Northing	950498
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG31234

Asset/Event Number	2471
Asset/Event Name	Red Well & Springs; Crocan Mor
Type of Asset/Event	Well; Spring
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG31235
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320140
Northing	948850
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG31235

Asset/Event Number	2472
Asset/Event Name	Pond etc, N of Maikle Wood
Type of Asset/Event	Pond; Sluice
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG31257
Status	Non-designated Heritage Asset
Section:	N/A
Easting	259848
Northing	895162
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG31257

Asset/Event Number	2473
Asset/Event Name	Invershin Railway Station
Type of Asset/Event	Railway Station
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG31258
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257959
Northing	895357
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG31258

Asset/Event Number	2474
Asset/Event Name	Longhouses, S & W of Broch, Bridge of Rhemullen
Type of Asset/Event	Longhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG31272
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315322
Northing	930934
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG31272

Asset/Event Number	2475
Asset/Event Name	Cemetery, Berriedale Church
Type of Asset/Event	Cemetery
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG31341
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312088
Northing	923266
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG31341

Asset/Event Number	2476

Asset/Event Name	Graveyard - Kiltarlity Old Parish Church
Type of Asset/Event	Cemetery
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG31353
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249738
Northing	843924
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG31353

Asset/Event Number	2477
Asset/Event Name	Contin Parish Church, graveyard
Type of Asset/Event	Cemetery
Date and/or Period	Early Historic-Modern
Listing No./NRHE Number	<Null>
HER Number	MHG31390
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245627
Northing	855776
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG31390

Asset/Event Number	2478
Asset/Event Name	Cemetery, St. Callan's, Rogart
Type of Asset/Event	Cemetery
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG31410
Status	Non-designated Heritage Asset
Section:	N/A

Easting	273848
Northing	903524
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG31410

Asset/Event Number	2479
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2480
Asset/Event Name	Aultgowrie Corn Mill
Type of Asset/Event	Grain Mill
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG31497
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247773
Northing	851375
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG31497

Asset/Event Number	2481
Asset/Event Name	Limekiln, Carnlaggie, Helmsdale
Type of Asset/Event	Lime Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG31500
Status	Non-designated Heritage Asset
Section:	N/A
Easting	302280
Northing	916273
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG31500

Asset/Event Number	2482
Asset/Event Name	Old Limekiln (S), Carnlaggie, Helmsdale
Type of Asset/Event	Lime Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG31501
Status	Non-designated Heritage Asset
Section:	N/A
Easting	302344
Northing	916226
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG31501

Asset/Event Number	2483
Asset/Event Name	Millton, Dunbeath
Type of Asset/Event	Watermill?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG31544
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315373
Northing	930349
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG31544

Asset/Event Number	2484
Asset/Event Name	Balblair (now Broompark), SW of Jamestown
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG31576
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247568
Northing	856182
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG31576

Asset/Event Number	2485
Asset/Event Name	Kinnarhaird Farmstead
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG31577
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246948
Northing	855289
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG31577

Asset/Event Number	2486
Asset/Event Name	Boundary Dyke, Scottarie
Type of Asset/Event	Boundary Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG31823
Status	Non-designated Heritage Asset
Section:	N/A
Easting	278892
Northing	906371
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG31823

Asset/Event Number	2487
Asset/Event Name	Allt nam Ban
Type of Asset/Event	Quarry Scoop
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG32062
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285458
Northing	908356
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32062

Asset/Event Number	2488
Asset/Event Name	Allt nam Ban

Type of Asset/Event	Milestone
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG32063
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285414
Northing	908410
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32063

Asset/Event Number	2489
Asset/Event Name	Allt nam Ban
Type of Asset/Event	Quarry Scoop
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG32064
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285386
Northing	908519
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32064

Asset/Event Number	2490
Asset/Event Name	Allt nam Ban
Type of Asset/Event	Punishment Place
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG32065
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285328

Northing	908606
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32065

Asset/Event Number	2491
Asset/Event Name	Oldtown
Type of Asset/Event	Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG32066
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285222
Northing	908835
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32066

Asset/Event Number	2492
Asset/Event Name	Iron Slag - Oldtown
Type of Asset/Event	Findspot
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG32067
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285255
Northing	908780
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32067

Asset/Event Number	2493
Asset/Event Name	Rogart Cemetery
Type of Asset/Event	Cemetery
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG32104
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273763
Northing	903712
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32104

Asset/Event Number	2494
Asset/Event Name	Quarry - N of Invershin Station
Type of Asset/Event	Mound; Dun; Cairn; Quarry
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG32125
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257862
Northing	895737
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32125

Asset/Event Number	2495
Asset/Event Name	Saw mill (stone cutting), Spital Quarries
Type of Asset/Event	Saw Mill
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG32183

Status	Non-designated Heritage Asset
Section:	N/A
Easting	317225
Northing	954162
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32183

Asset/Event Number	2496
Asset/Event Name	Bruachdian Farmstead
Type of Asset/Event	Farmstead; Mill?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG32223
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256322
Northing	868846
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32223

Asset/Event Number	2497
Asset/Event Name	Building betw Balnard & Achnagoul
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG32225
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256698
Northing	868805
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32225

Asset/Event Number	2498
Asset/Event Name	Memorial to Flying Fortress Victims, Halsary
Type of Asset/Event	Commemorative Monument
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG32259
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317314
Northing	948531
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32259

Asset/Event Number	2499
Asset/Event Name	Combination Poorhouse, Wick & Latheron, A9
Type of Asset/Event	Poor House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG32270
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318183
Northing	939411
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32270

Asset/Event Number	2500
Asset/Event Name	Monument, Badbea
Type of Asset/Event	Commemorative Monument

Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG32344
Status	Non-designated Heritage Asset
Section:	N/A
Easting	308865
Northing	920099
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32344

Asset/Event Number	2501
Asset/Event Name	Bridge of Horn
Type of Asset/Event	Bridge
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG32401
Status	Non-designated Heritage Asset
Section:	N/A
Easting	279952
Northing	904782
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32401

Asset/Event Number	2502
Asset/Event Name	FAIRBURN HOUSE, KENNELS
Type of Asset/Event	Kennels
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG32439
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245430
Northing	852580

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32439

Asset/Event Number	2503
Asset/Event Name	Bus Depot, (Spa Motors), Strathpeffer
Type of Asset/Event	Garage
Date and/or Period	Post-medieval/Modern
Listing No./NRHE Number	<Null>
HER Number	MHG32482
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248133
Northing	857999
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32482

Asset/Event Number	2504
Asset/Event Name	Sheepfold, N of Inveran
Type of Asset/Event	Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG32589
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257111
Northing	897805
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32589

Asset/Event Number	2505
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2506
Asset/Event Name	Hut circle, N of Invershin
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG32591
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258393
Northing	896944
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32591

Asset/Event Number	2507
Asset/Event Name	Hut circle, N of Invershin
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG32592
Status	Non-designated Heritage Asset

Section:	N/A
Easting	258350
Northing	897176
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32592

Asset/Event Number	2508
Asset/Event Name	Hut circle, N of Invershin
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG32593
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258371
Northing	897165
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32593

Asset/Event Number	2509
Asset/Event Name	Hut circle, N of Invershin
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG32594
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258086
Northing	897441
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG32594

Asset/Event Number	2510
Asset/Event Name	Hut circle, N of Invershin
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG32595
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258061
Northing	897739
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32595

Asset/Event Number	2511
Asset/Event Name	Hut circle, N of Invershin
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG32596
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258006
Northing	897703
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32596

Asset/Event Number	2512
Asset/Event Name	Battle Site, N of Elsick House
Type of Asset/Event	Battle Site
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG32666
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247719
Northing	857587
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32666

Asset/Event Number	2513
Asset/Event Name	Cairn, Druim Dubhran
Type of Asset/Event	Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG32667
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249654
Northing	860847
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32667

Asset/Event Number	2514
Asset/Event Name	Cairn, Druim Dubhran
Type of Asset/Event	Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG32668
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249751
Northing	860894
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32668

Asset/Event Number	2515
Asset/Event Name	Sheepfold - Druim Dubhran
Type of Asset/Event	Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG32669
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249722
Northing	861265
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32669

Asset/Event Number	2516
Asset/Event Name	Tumuli Druim Dubhran
Type of Asset/Event	Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG32670
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249480
Northing	861185
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32670

Asset/Event Number	2517

Asset/Event Name	Tumuli, Druim Dubhran
Type of Asset/Event	Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG32671
Status	Non-designated Heritage Asset
Section:	N/A
Easting	250261
Northing	861245
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32671

Asset/Event Number	2518
Asset/Event Name	Berriedale
Type of Asset/Event	Road
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG32731
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311900
Northing	922700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32731

Asset/Event Number	2519
Asset/Event Name	Sheepfold, S of Loch Morie
Type of Asset/Event	Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG32824
Status	Non-designated Heritage Asset
Section:	N/A

Easting	254149
Northing	874838
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32824

Asset/Event Number	2520
Asset/Event Name	Invershin Salmon Boiling House
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG32893
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258100
Northing	894600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32893

Asset/Event Number	2521
Asset/Event Name	Portenleik Ford
Type of Asset/Event	Ford
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG32896
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257900
Northing	895200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32896

Asset/Event Number	2522
Asset/Event Name	Torboll Fish Ladder
Type of Asset/Event	Fish Ladder; Sluice; Dam
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG32925
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274348
Northing	898542
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32925

Asset/Event Number	2523
Asset/Event Name	Tor View
Type of Asset/Event	Wood; Wood
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG32929
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245737
Northing	856335
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32929

Asset/Event Number	2524
Asset/Event Name	Langergill
Type of Asset/Event	Building
Date and/or Period	Undated
Listing No./NRHE Number	<Null>

HER Number	MHG33073
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319200
Northing	954800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33073

Asset/Event Number	2525
Asset/Event Name	Spittal Mains Quarry
Type of Asset/Event	Quarry
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG33107
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316747
Northing	954673
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33107

Asset/Event Number	2526
Asset/Event Name	Banniskirk
Type of Asset/Event	Lade
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33108
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317158
Northing	957346
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33108

Asset/Event Number	2527
Asset/Event Name	Banniskirk
Type of Asset/Event	Smithy
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33109
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316667
Northing	957683
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33109

Asset/Event Number	2528
Asset/Event Name	Banniskirk Quarry
Type of Asset/Event	Quarry
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33111
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316733
Northing	956809
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33111

Asset/Event Number	2529
Asset/Event Name	Killin Rock

Type of Asset/Event	Quarry Scoop
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG33235
Status	Non-designated Heritage Asset
Section:	N/A
Easting	286013
Northing	905649
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33235

Asset/Event Number	2530
Asset/Event Name	Loch Brora
Type of Asset/Event	Quarry Scoop
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG33236
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285960
Northing	908812
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33236

Asset/Event Number	2531
Asset/Event Name	Loch Brora
Type of Asset/Event	Quarry Scoop
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG33237
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285892

Northing	905969
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33237

Asset/Event Number	2532
Asset/Event Name	Loch Brora
Type of Asset/Event	Quarry Scoop
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG33238
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285873
Northing	906066
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33238

Asset/Event Number	2533
Asset/Event Name	Loch Brora
Type of Asset/Event	Quarry Scoop
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG33239
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285856
Northing	906157
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33239

Asset/Event Number	2534
Asset/Event Name	Loch Brora
Type of Asset/Event	Quarry Scoop
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG33240
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285734
Northing	906395
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33240

Asset/Event Number	2535
Asset/Event Name	Loch Brora
Type of Asset/Event	Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33241
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285718
Northing	906395
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33241

Asset/Event Number	2536
Asset/Event Name	Loch Brora
Type of Asset/Event	Quarry Scoop
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG33242

Status	Non-designated Heritage Asset
Section:	N/A
Easting	285717
Northing	906420
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33242

Asset/Event Number	2537
Asset/Event Name	Loch Brora
Type of Asset/Event	Clearance Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG33243
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285602
Northing	906697
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33243

Asset/Event Number	2538
Asset/Event Name	Killin
Type of Asset/Event	Quarry Scoop
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG33244
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285575
Northing	906829
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33244

Asset/Event Number	2539
Asset/Event Name	Killin Rock
Type of Asset/Event	Milestone
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33245
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285560
Northing	906871
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33245

Asset/Event Number	2540
Asset/Event Name	Killin
Type of Asset/Event	Clearance Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG33246
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285563
Northing	906849
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33246

Asset/Event Number	2541
Asset/Event Name	Allt nam Ban
Type of Asset/Event	Quarry Scoop

Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG33247
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285615
Northing	907496
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33247

Asset/Event Number	2542
Asset/Event Name	Allt nam Ban
Type of Asset/Event	Quarry Scoop
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG33248
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285638
Northing	907721
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33248

Asset/Event Number	2543
Asset/Event Name	Allt nam Ban
Type of Asset/Event	Quarry Scoop
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG33249
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285631
Northing	907770

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33249

Asset/Event Number	2544
Asset/Event Name	Allt nam Ban
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG33250
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285632
Northing	907805
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33250

Asset/Event Number	2545
Asset/Event Name	Allt nam Ban
Type of Asset/Event	Clapper Bridge
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG33251
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285627
Northing	907910
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33251

Asset/Event Number	2546
Asset/Event Name	Allt nam Ban
Type of Asset/Event	Quarry Scoop
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG33252
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285620
Northing	908083
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33252

Asset/Event Number	2547
Asset/Event Name	Allt nam Ban
Type of Asset/Event	Quarry Scoop
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG33253
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285476
Northing	908280
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33253

Asset/Event Number	2548
Asset/Event Name	Farmstead, Achnagoul
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33322
Status	Non-designated Heritage Asset

Section:	N/A
Easting	316439
Northing	932562
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33322

Asset/Event Number	2549
Asset/Event Name	Farmstead, S of Greentulloch
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33323
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316347
Northing	931860
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33323

Asset/Event Number	2550
Asset/Event Name	Farmstead, N of Achravole
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33324
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315765
Northing	931540
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG33324

Asset/Event Number	2551
Asset/Event Name	Farmstead, N of Achravole
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33325
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315475
Northing	931560
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33325

Asset/Event Number	2552
Asset/Event Name	Farmsteading, N of Greentulloch
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33327
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315993
Northing	932431
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33327

Asset/Event Number	2553
Asset/Event Name	Farmsteading, N of Greentulloch
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG33328
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316444
Northing	932544
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33328

Asset/Event Number	2554
Asset/Event Name	Sheepfold, Larel
Type of Asset/Event	Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33330
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318024
Northing	957118
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33330

Asset/Event Number	2555
Asset/Event Name	Sheepfold, Larel
Type of Asset/Event	Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33331
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318645
Northing	956949
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33331

Asset/Event Number	2556
Asset/Event Name	Mill Pond, E of Banniskirk
Type of Asset/Event	Mill Pond
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33333
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317564
Northing	957183
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33333

Asset/Event Number	2557
Asset/Event Name	Sheepfold, E of Banniskirk
Type of Asset/Event	Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33334
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317286
Northing	957353
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33334

Asset/Event Number	2558

Asset/Event Name	Dubhran Tri
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33358
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249000
Northing	860700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33358

Asset/Event Number	2559
Asset/Event Name	Boundary Bank, Achility
Type of Asset/Event	Boundary Bank
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG33473
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244710
Northing	857304
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33473

Asset/Event Number	2560
Asset/Event Name	Culrain Mill
Type of Asset/Event	Grain Mill
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33546
Status	Non-designated Heritage Asset
Section:	N/A

Easting	256976
Northing	894839
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33546

Asset/Event Number	2561
Asset/Event Name	Sheepfold, W of Badgharohaidh
Type of Asset/Event	Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33614
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254102
Northing	868751
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33614

Asset/Event Number	2562
Asset/Event Name	Upper Leanassie
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33622
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247396
Northing	844813
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33622

Asset/Event Number	2563
Asset/Event Name	Corn Mill, Remusaig
Type of Asset/Event	Grain Mill
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33704
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273439
Northing	902087
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33704

Asset/Event Number	2564
Asset/Event Name	Rhidorach Farm
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33706
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256151
Northing	867681
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33706

Asset/Event Number	2565
Asset/Event Name	Building E of Fannyfield Farm
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG33707
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255450
Northing	865850
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33707

Asset/Event Number	2566
Asset/Event Name	Clach Liath
Type of Asset/Event	Stone
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG33708
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254940
Northing	865971
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33708

Asset/Event Number	2567
Asset/Event Name	Boathouse, NE end of Loch Agoo
Type of Asset/Event	Boat House
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG33709
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255686
Northing	866802
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33709

Asset/Event Number	2568
Asset/Event Name	Dun, Daileag an Loin, Strath Tollie
Type of Asset/Event	Dun?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG33711
Status	Non-designated Heritage Asset
Section:	N/A
Easting	269883
Northing	899785
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33711

Asset/Event Number	2569
Asset/Event Name	Settlement, Daileag an Loin,Strath Tollie
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33712
Status	Non-designated Heritage Asset
Section:	N/A
Easting	269923
Northing	899727
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33712

Asset/Event Number	2570
Asset/Event Name	Miltonbank, The Bank, Rogart

Type of Asset/Event	Millstone
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG33808
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273643
Northing	903213
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33808

Asset/Event Number	2571
Asset/Event Name	Aircraft Crash Site, Creag Riabhach
Type of Asset/Event	Aircraft Crash Site
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG33851
Status	Non-designated Heritage Asset
Section:	N/A
Easting	292600
Northing	911600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG33851

Asset/Event Number	2572
Asset/Event Name	Buildings (site of), Riverside, Contin
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG34118
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245559

Northing	856315
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG34118

Asset/Event Number	2573
Asset/Event Name	Kilearnan
Type of Asset/Event	General View
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG34137
Status	Non-designated Heritage Asset
Section:	N/A
Easting	294000
Northing	918000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG34137

Asset/Event Number	2574
Asset/Event Name	Oulmsdale Burn
Type of Asset/Event	General View
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG34138
Status	Non-designated Heritage Asset
Section:	N/A
Easting	295000
Northing	917000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG34138

Asset/Event Number	2575
Asset/Event Name	Strath Of Kildonan
Type of Asset/Event	General View
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG34139
Status	Non-designated Heritage Asset
Section:	N/A
Easting	295000
Northing	916000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG34139

Asset/Event Number	2576
Asset/Event Name	Stone dykes - Balnarge, Kiltearn
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG34246
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256503
Northing	869034
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG34246

Asset/Event Number	2577
Asset/Event Name	Acharn
Type of Asset/Event	Site; Farmhouse
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG34475

Status	Non-designated Heritage Asset
Section:	N/A
Easting	258440
Northing	873830
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG34475

Asset/Event Number	2578
Asset/Event Name	Badbea
Type of Asset/Event	Hut Circle; Site
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG34502
Status	Non-designated Heritage Asset
Section:	N/A
Easting	309200
Northing	920100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG34502

Asset/Event Number	2579
Asset/Event Name	Loch Salachaidh
Type of Asset/Event	Site; Lake
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG34514
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276120
Northing	903680
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG34514

Asset/Event Number	2580
Asset/Event Name	Allt Bad A' Chrasgaidh
Type of Asset/Event	Site; Building
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG34657
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275230
Northing	901350
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG34657

Asset/Event Number	2581
Asset/Event Name	Dubh-choille
Type of Asset/Event	Plantation Bank; Site
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG34847
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310300
Northing	922100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG34847

Asset/Event Number	2582
Asset/Event Name	Boundary bank - Langwell
Type of Asset/Event	Boundary Bank

Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG34850
Status	Non-designated Heritage Asset
Section:	N/A
Easting	309630
Northing	922440
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG34850

Asset/Event Number	2583
Asset/Event Name	DUN BURN
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG34851
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310000
Northing	924800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG34851

Asset/Event Number	2584
Asset/Event Name	Aberscross Hill
Type of Asset/Event	Site; Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG34882
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276950
Northing	901050

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG34882

Asset/Event Number	2585
Asset/Event Name	MORVICH LODGE
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG34883
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276550
Northing	900830
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG34883

Asset/Event Number	2586
Asset/Event Name	ABERCROSS
Type of Asset/Event	Cairnfield
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG34884
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276950
Northing	900300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG34884

Asset/Event Number	2587
Asset/Event Name	CARBISDALE CASTLE, SOUTH GATEWAY
Type of Asset/Event	Gate
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG35174
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257597
Northing	894917
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG35174

Asset/Event Number	2588
Asset/Event Name	BALINOE
Type of Asset/Event	Pillbox
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG35517
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257910
Northing	893680
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG35517

Asset/Event Number	2589
Asset/Event Name	DUNROBIN GLEN
Type of Asset/Event	Longhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG35870
Status	Non-designated Heritage Asset

Section:	N/A
Easting	279600
Northing	904900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG35870

Asset/Event Number	2590
Asset/Event Name	LON MOR
Type of Asset/Event	Rig And Furrow
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG35910
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310700
Northing	923300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG35910

Asset/Event Number	2591
Asset/Event Name	Rinsary Brae
Type of Asset/Event	Cultivation Remains; Site
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG35911
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311100
Northing	923500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG35911

Asset/Event Number	2592
Asset/Event Name	Berriedale Water
Type of Asset/Event	Cultivation Remains; Site
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG35912
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311400
Northing	923300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG35912

Asset/Event Number	2593
Asset/Event Name	LANGWELL HOUSE
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG35913
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311670
Northing	923070
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG35913

Asset/Event Number	2594
Asset/Event Name	BERRIEDALE CHURCH
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG35914
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311920
Northing	923130
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG35914

Asset/Event Number	2595
Asset/Event Name	Railway Bridge, S of Station, Culrain
Type of Asset/Event	Railway Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG35971
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257690
Northing	894670
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG35971

Asset/Event Number	2596
Asset/Event Name	FAIRBURN HOUSE, BUTLER'S COTTAGE
Type of Asset/Event	House
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG36035
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245290
Northing	852860
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG36035

Asset/Event Number	2597
Asset/Event Name	FAIRBURN HOUSE, GARDENER'S COTTAGE
Type of Asset/Event	Gardeners Lodge
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG36036
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245250
Northing	852710
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG36036

Asset/Event Number	2598
Asset/Event Name	KILMORACK POWER STATION AND DAM
Type of Asset/Event	Power Station
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG36218
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249420
Northing	844240
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG36218

Asset/Event Number	2599

Asset/Event Name	KILMORACK, HYDRO HOUSES
Type of Asset/Event	Power Station
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG36219
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248640
Northing	844720
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG36219

Asset/Event Number	2600
Asset/Event Name	AIGAS POWER STATION AND DAM
Type of Asset/Event	Power Station
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG36225
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247420
Northing	843670
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG36225

Asset/Event Number	2601
Asset/Event Name	Shin Power Station, Inveran
Type of Asset/Event	Power Station
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG36279
Status	Non-designated Heritage Asset
Section:	N/A

Easting	257340
Northing	897440
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG36279

Asset/Event Number	2602
Asset/Event Name	INVERAN, HYDRO HOUSES
Type of Asset/Event	House
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG36397
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257200
Northing	897200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG36397

Asset/Event Number	2603
Asset/Event Name	Markethill
Type of Asset/Event	Site; Cottage
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG36714
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319620
Northing	954870
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG36714

Asset/Event Number	2604
Asset/Event Name	ACHAVANICH SCHOOL AND SCHOOLHOUSE
Type of Asset/Event	School
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG36814
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317980
Northing	942700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG36814

Asset/Event Number	2605
Asset/Event Name	Rangag, General
Type of Asset/Event	General View
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG36858
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317600
Northing	944180
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG36858

Asset/Event Number	2606
Asset/Event Name	Farmstead - Leodebest
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG36868
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318312
Northing	935029
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG36868

Asset/Event Number	2607
Asset/Event Name	BANNISKIRK HOUSE
Type of Asset/Event	House
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG36872
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316070
Northing	957460
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG36872

Asset/Event Number	2608
Asset/Event Name	Heights Of Keppoch
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG36894
Status	Non-designated Heritage Asset
Section:	N/A
Easting	250350
Northing	860610
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG36894

Asset/Event Number	2609
Asset/Event Name	SIBSTER BURN FARM
Type of Asset/Event	Farm
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG37050
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314900
Northing	958080
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG37050

Asset/Event Number	2610
Asset/Event Name	WICK AND LATHERON COMBINATION POORHOUSE
Type of Asset/Event	Poor House
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG37148
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318180
Northing	939400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG37148

Asset/Event Number	2611
Asset/Event Name	Banniskirk Mains

Type of Asset/Event	Site; Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG37244
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316900
Northing	957340
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG37244

Asset/Event Number	2612
Asset/Event Name	Achtaduaig
Type of Asset/Event	Site; Field Boundary
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG37351
Status	Non-designated Heritage Asset
Section:	N/A
Easting	272500
Northing	898230
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG37351

Asset/Event Number	2613
Asset/Event Name	Toftingall
Type of Asset/Event	Site; Cottage
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG37356
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318370

Northing	954700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG37356

Asset/Event Number	2614
Asset/Event Name	AULTGOWRIE MILL
Type of Asset/Event	Mill
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG37361
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247767
Northing	851355
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG37361

Asset/Event Number	2615
Asset/Event Name	Torboll
Type of Asset/Event	Site; Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG37369
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275130
Northing	899310
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG37369

Asset/Event Number	2616
Asset/Event Name	Torboll
Type of Asset/Event	Site; Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG37372
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274660
Northing	898580
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG37372

Asset/Event Number	2617
Asset/Event Name	BANNISKIRK FARM COTTAGE
Type of Asset/Event	Farmhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG37403
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316830
Northing	957460
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG37403

Asset/Event Number	2618
Asset/Event Name	Banniskirk, Milton
Type of Asset/Event	Site; Farmhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG37429

Status	Non-designated Heritage Asset
Section:	N/A
Easting	316120
Northing	957890
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG37429

Asset/Event Number	2619
Asset/Event Name	Langergill
Type of Asset/Event	Site; House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG37500
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318660
Northing	954840
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG37500

Asset/Event Number	2620
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	

Importance:	
Description	VOID - number not assigned

Asset/Event Number	2621
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2622
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2623
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	

Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2624
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2625
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	

Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2626
Asset/Event Name	Possible Cairn, Lang Well
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG379
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310150
Northing	922010
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG379

Asset/Event Number	2627
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2628
Asset/Event Name	Possible Standing Stone, Borgue Langwell
Type of Asset/Event	Standing Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG381
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310040
Northing	921640
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG381

Asset/Event Number	2629
Asset/Event Name	Hut Circle, Dun Burn
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG383
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310010
Northing	924640
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG383

Asset/Event Number	2630
Asset/Event Name	Hut Circle, Cnoc Fionn
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG384
Status	Non-designated Heritage Asset

Section:	N/A
Easting	310750
Northing	923810
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG384

Asset/Event Number	2631
Asset/Event Name	Croft, Cnoc Na Croiche
Type of Asset/Event	Croft
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG386
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310150
Northing	921120
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG386

Asset/Event Number	2632
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	

Description	VOID - number not assigned

Asset/Event Number	2633
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2634
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2635
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	

Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2636
Asset/Event Name	Stack Stand, Inver
Type of Asset/Event	Stack Stand
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG387
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311580
Northing	922220
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG387

Asset/Event Number	2637
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	

Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2638
Asset/Event Name	Croft, Rowan Dene
Type of Asset/Event	Croft
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG388
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312480
Northing	923550
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG388

Asset/Event Number	2639
Asset/Event Name	Col-bheinn
Type of Asset/Event	Shieling
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG38884
Status	Non-designated Heritage Asset
Section:	N/A
Easting	290064
Northing	910988
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG38884

Asset/Event Number	2640

Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2641
Asset/Event Name	Cairn, Strathcarron Wood
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG38927
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256100
Northing	891900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG38927

Asset/Event Number	2642
Asset/Event Name	Platforms, West Strathcarron Wood
Type of Asset/Event	Platform
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG38928
Status	Non-designated Heritage Asset
Section:	N/A

Easting	253900
Northing	892000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG38928

Asset/Event Number	2643
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2644
Asset/Event Name	Clearance Cairn, Balcraggie Lodge
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG38948
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314200
Northing	930200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG38948

Asset/Event Number	2645
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2646
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2647
Asset/Event Name	Glen Loth
Type of Asset/Event	Head Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG39006
Status	Non-designated Heritage Asset
Section:	N/A
Easting	294200
Northing	915200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39006

Asset/Event Number	2648
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2649
Asset/Event Name	Building, N of Knockantoul Farm, Clare
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39110
Status	Non-designated Heritage Asset
Section:	N/A
Easting	253892
Northing	865448
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39110

Asset/Event Number	2650
Asset/Event Name	Saw Mill, NW of Fairburn
Type of Asset/Event	Saw Mill
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG39120
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243851
Northing	853566
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39120

Asset/Event Number	2651
Asset/Event Name	Field dyke, Hilton
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39220
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256834
Northing	893867
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39220

Asset/Event Number	2652
Asset/Event Name	Field dyke, N of Lower Hilton

Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39221
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256954
Northing	894187
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39221

Asset/Event Number	2653
Asset/Event Name	Culrain settlement
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39222
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257461
Northing	894728
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39222

Asset/Event Number	2654
Asset/Event Name	Earthworks, Culrain
Type of Asset/Event	Earthwork
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG39223
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257602

Northing	894719
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39223

Asset/Event Number	2655
Asset/Event Name	Clearance Cairn, E of Culrain
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39224
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257835
Northing	894702
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39224

Asset/Event Number	2656
Asset/Event Name	Field dyke, E of Culrain
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39225
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257730
Northing	894600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39225

Asset/Event Number	2657
Asset/Event Name	Balinoe Farm, Balnahinish
Type of Asset/Event	Farm
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39226
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257911
Northing	893725
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39226

Asset/Event Number	2658
Asset/Event Name	Mound, Balnahinsh
Type of Asset/Event	Mound
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG39227
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257917
Northing	893637
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39227

Asset/Event Number	2659
Asset/Event Name	Hut circle - NE of Chambered Cairn, Heights of Brae
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39233

Status	Non-designated Heritage Asset
Section:	N/A
Easting	251462
Northing	861572
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39233

Asset/Event Number	2660
Asset/Event Name	Star carved stone, Glen Loth
Type of Asset/Event	Carved Stone; Boundary Stone
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG39279
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293500
Northing	913800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39279

Asset/Event Number	2661
Asset/Event Name	Enclosure, Loedebest
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39358
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312400
Northing	932300
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39358

Asset/Event Number	2662
Asset/Event Name	Head Dyke, Loedebest
Type of Asset/Event	Head Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39359
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312400
Northing	932300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39359

Asset/Event Number	2663
Asset/Event Name	Clearance Cairns, Loedebest
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39360
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312300
Northing	931700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39360

Asset/Event Number	2664
Asset/Event Name	Kiln Barn, Achorn Bridge
Type of Asset/Event	Kiln Barn

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39362
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313690
Northing	931550
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39362

Asset/Event Number	2665
Asset/Event Name	Enclosure, Achorn Bridge
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39363
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313690
Northing	931550
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39363

Asset/Event Number	2666
Asset/Event Name	Head Dyke, Garbh-Leathad
Type of Asset/Event	Head Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39369
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313000
Northing	932100

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39369

Asset/Event Number	2667
Asset/Event Name	Enclosure, Garbh-Leathad
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39370
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313000
Northing	932100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39370

Asset/Event Number	2668
Asset/Event Name	Head Dyke, Loedebest
Type of Asset/Event	Head Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39379
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314000
Northing	931200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39379

Asset/Event Number	2669
Asset/Event Name	Enclosure, Loedebest
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39380
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314000
Northing	931200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39380

Asset/Event Number	2670
Asset/Event Name	Kiln, Loedebest
Type of Asset/Event	Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39384
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314000
Northing	931200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39384

Asset/Event Number	2671
Asset/Event Name	Rig and Furrow, Loedebest
Type of Asset/Event	Rig And Furrow
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39385
Status	Non-designated Heritage Asset

Section:	N/A
Easting	314000
Northing	931200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39385

Asset/Event Number	2672
Asset/Event Name	Clearance Cairn, Loedebest
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39386
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314000
Northing	931200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39386

Asset/Event Number	2673
Asset/Event Name	Hut Circles, Allt A' Bhurg
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39397
Status	Non-designated Heritage Asset
Section:	N/A
Easting	307130
Northing	918810
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG39397

Asset/Event Number	2674
Asset/Event Name	Cist with Cremation, Allt A' Bhurg
Type of Asset/Event	Cist
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39398
Status	Non-designated Heritage Asset
Section:	N/A
Easting	307130
Northing	918810
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39398

Asset/Event Number	2675
Asset/Event Name	Cremation, Allt A' Bhurg
Type of Asset/Event	Cremation
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39399
Status	Non-designated Heritage Asset
Section:	N/A
Easting	307130
Northing	918810
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39399

Asset/Event Number	2676
Asset/Event Name	Shooting Stand, Cnoc Spardain
Type of Asset/Event	Shooting Stand
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG39429
Status	Non-designated Heritage Asset
Section:	N/A
Easting	308100
Northing	922900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39429

Asset/Event Number	2677
Asset/Event Name	Cnoc Spardain
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39430
Status	Non-designated Heritage Asset
Section:	N/A
Easting	308120
Northing	922813
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39430

Asset/Event Number	2678
Asset/Event Name	Clearance Cairn, Ousdale Burn
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39434
Status	Non-designated Heritage Asset
Section:	N/A
Easting	306700
Northing	920600
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39434

Asset/Event Number	2679
Asset/Event Name	Field System, Ousdale Burn
Type of Asset/Event	Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39435
Status	Non-designated Heritage Asset
Section:	N/A
Easting	306700
Northing	920600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39435

Asset/Event Number	2680
Asset/Event Name	Clearance Cairn, Ousdale
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric/Early Historic
Listing No./NRHE Number	<Null>
HER Number	MHG39436
Status	Non-designated Heritage Asset
Section:	N/A
Easting	307730
Northing	920300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39436

Asset/Event Number	2681

Asset/Event Name	Enclosure, Allt Bad A'Choilich
Type of Asset/Event	Enclosure; Aisled Building
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39439
Status	Non-designated Heritage Asset
Section:	N/A
Easting	309600
Northing	923900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39439

Asset/Event Number	2682
Asset/Event Name	Clearance Cairns, Allt a' Chriosduidhe
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39440
Status	Non-designated Heritage Asset
Section:	N/A
Easting	309930
Northing	924720
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39440

Asset/Event Number	2683
Asset/Event Name	Clearance Cairn, Millery Pool
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39529
Status	Non-designated Heritage Asset
Section:	N/A

Easting	310500
Northing	925000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39529

Asset/Event Number	2684
Asset/Event Name	Field System, Millery Pool
Type of Asset/Event	Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39530
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310500
Northing	925000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39530

Asset/Event Number	2685
Asset/Event Name	Clearance Cairn, Rockhead
Type of Asset/Event	Clearance Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG39532
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313500
Northing	925800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39532

Asset/Event Number	2686
Asset/Event Name	Clearance Cairn, Ard-Achadh
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39533
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310790
Northing	925900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39533

Asset/Event Number	2687
Asset/Event Name	Field System, Ard-Achadh
Type of Asset/Event	Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39534
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310790
Northing	925900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39534

Asset/Event Number	2688
Asset/Event Name	Possible Corn Drying Kiln, Meall Dhonuill
Type of Asset/Event	Corn Drying Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG39536
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311317
Northing	927387
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39536

Asset/Event Number	2689
Asset/Event Name	Corn Drying Kiln, Berriedale Water
Type of Asset/Event	Corn Drying Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39537
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311400
Northing	926600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39537

Asset/Event Number	2690
Asset/Event Name	Enclosure, Berriedale Water
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39538
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311400
Northing	926600
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39538

Asset/Event Number	2691
Asset/Event Name	Clearance Cairn, Millery Burn
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39540
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310650
Northing	925100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39540

Asset/Event Number	2692
Asset/Event Name	Enclosure, Berriedale Water
Type of Asset/Event	Enclosure
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG39541
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310610
Northing	924680
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39541

Asset/Event Number	2693
Asset/Event Name	Rig and Furrow, Berriedale Water

Type of Asset/Event	Rig And Furrow
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG39542
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310610
Northing	924680
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39542

Asset/Event Number	2694
Asset/Event Name	Cemetery, Cnoc Fionn
Type of Asset/Event	Cemetery
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG39544
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311000
Northing	922000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39544

Asset/Event Number	2695
Asset/Event Name	Buildings, Berriedale Water
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39545
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310200

Northing	924500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39545

Asset/Event Number	2696
Asset/Event Name	Corn Drying Kiln, Berriedale Water
Type of Asset/Event	Corn Drying Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39546
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310200
Northing	924500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39546

Asset/Event Number	2697
Asset/Event Name	Enclosure, Berriedale Water
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39547
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310200
Northing	924500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39547

Asset/Event Number	2698
Asset/Event Name	Corn Drying Kiln, An Dun
Type of Asset/Event	Corn Drying Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39548
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310200
Northing	924900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39548

Asset/Event Number	2699
Asset/Event Name	Field System, An Dun
Type of Asset/Event	Field System
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39549
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310200
Northing	924900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39549

Asset/Event Number	2700
Asset/Event Name	Head Dyke, An Dun
Type of Asset/Event	Head Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39550

Status	Non-designated Heritage Asset
Section:	N/A
Easting	310200
Northing	924900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39550

Asset/Event Number	2701
Asset/Event Name	Field System, Tulach Bad A Choilich
Type of Asset/Event	Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39551
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310400
Northing	924100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39551

Asset/Event Number	2702
Asset/Event Name	Clearance Cairn, Tulach Bad A Choilich
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39552
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310400
Northing	924100
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39552

Asset/Event Number	2703
Asset/Event Name	Tulach Bad A Choilich
Type of Asset/Event	Lynchet
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39553
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310400
Northing	924100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39553

Asset/Event Number	2704
Asset/Event Name	Field System, Cnoc Fionn
Type of Asset/Event	Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39554
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310400
Northing	923500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39554

Asset/Event Number	2705
Asset/Event Name	Clearance Cairn, Cnoc Fionn
Type of Asset/Event	Clearance Cairn

Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39555
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310400
Northing	923500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39555

Asset/Event Number	2706
Asset/Event Name	Building, Tulach Bad A Choilich
Type of Asset/Event	Building
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39556
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310050
Northing	924040
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39556

Asset/Event Number	2707
Asset/Event Name	Burial Cairn and Clearance Cairns, Guidebest
Type of Asset/Event	Burial Cairn; Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39559
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318020
Northing	935100

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39559

Asset/Event Number	2708
Asset/Event Name	Clearance Cairn, Creag an Fithick
Type of Asset/Event	Clearance Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG39560
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314900
Northing	931600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39560

Asset/Event Number	2709
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2710
Asset/Event Name	Field System, Bridge of Rhemullen
Type of Asset/Event	Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39565
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315090
Northing	930540
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39565

Asset/Event Number	2711
Asset/Event Name	Enclosure, Bridge of Rhemullen
Type of Asset/Event	Hut Circle; Enclosure
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39566
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315090
Northing	930540
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39566

Asset/Event Number	2712
Asset/Event Name	Cnoc Sheangan
Type of Asset/Event	Sheep Fold; Pen
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39567
Status	Non-designated Heritage Asset

Section:	N/A
Easting	315880
Northing	933530
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39567

Asset/Event Number	2713
Asset/Event Name	Field System, Minera
Type of Asset/Event	Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39571
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315700
Northing	934400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39571

Asset/Event Number	2714
Asset/Event Name	Clearance Cairn, Minera
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39572
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315700
Northing	934400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG39572

Asset/Event Number	2715
Asset/Event Name	Cairnfield, Cnoc Sheangan
Type of Asset/Event	Cairnfield
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39573
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315570
Northing	932980
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39573

Asset/Event Number	2716
Asset/Event Name	Enclosure, Badnagie
Type of Asset/Event	Enclosure
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39574
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315600
Northing	932100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39574

Asset/Event Number	2717
Asset/Event Name	Bothy, Cnoc Sheangan
Type of Asset/Event	Bothy
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG39575
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316170
Northing	933040
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39575

Asset/Event Number	2718
Asset/Event Name	Clearance Cairns, 400m N of Achnagoul
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39576
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316400
Northing	932900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39576

Asset/Event Number	2719
Asset/Event Name	Enclosure, An Dun
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39584
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310200
Northing	924900
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39584

Asset/Event Number	2720
Asset/Event Name	Tulach Bad A Choilich
Type of Asset/Event	Field Boundary
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39585
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310400
Northing	924100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39585

Asset/Event Number	2721
Asset/Event Name	Shieling, Tulach Bad A Choilich
Type of Asset/Event	Shieling; Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39586
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310400
Northing	924100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39586

Asset/Event Number	2722

Asset/Event Name	Cist burial - Cor Tulloch
Type of Asset/Event	Cist; Inhumation
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39587
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315130
Northing	935530
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39587

Asset/Event Number	2723
Asset/Event Name	Clearance Cairn, Bridge of Rhemullen
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39589
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315090
Northing	930540
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39589

Asset/Event Number	2724
Asset/Event Name	Bridge of Rhemullen
Type of Asset/Event	Lynchet
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39590
Status	Non-designated Heritage Asset
Section:	N/A

Easting	315090
Northing	930540
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39590

Asset/Event Number	2725
Asset/Event Name	Bridge of Rhemullen
Type of Asset/Event	Field Boundary
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39591
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315090
Northing	930540
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39591

Asset/Event Number	2726
Asset/Event Name	Shieling, Bad Nan Glac
Type of Asset/Event	Shieling; Wheelhouse
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39600
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311900
Northing	930300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39600

Asset/Event Number	2727
Asset/Event Name	Clearance Cairn, Bad Nan Glac
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG39601
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311900
Northing	930300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39601

Asset/Event Number	2728
Asset/Event Name	Natural Feature, Bad Nan Glac
Type of Asset/Event	Natural Feature; mistaken for Wag)
Date and/or Period	None
Listing No./NRHE Number	<Null>
HER Number	MHG39602
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311900
Northing	930300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39602

Asset/Event Number	2729
Asset/Event Name	Cnoc A' Mhargadaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>

HER Number	MHG39612
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255700
Northing	866900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39612

Asset/Event Number	2730
Asset/Event Name	Cnoc A' Mhargadaidh
Type of Asset/Event	Field System
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG39613
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255700
Northing	866900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39613

Asset/Event Number	2731
Asset/Event Name	Cnoc A' Mhargadaidh
Type of Asset/Event	Cairnfield
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG39614
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255700
Northing	866900
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39614

Asset/Event Number	2732
Asset/Event Name	Cnoc A' Mhargadaidh
Type of Asset/Event	Field Boundary
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG39615
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255700
Northing	866900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39615

Asset/Event Number	2733
Asset/Event Name	Cnoc A' Mhargadaidh
Type of Asset/Event	Lynchet
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG39616
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255700
Northing	866900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39616

Asset/Event Number	2734
Asset/Event Name	Cist, Cnoc na Maranaich

Type of Asset/Event	Cist
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG39617
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313236
Northing	933078
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39617

Asset/Event Number	2735
Asset/Event Name	Red Well & Springs; Crocan Mor
Type of Asset/Event	Spring
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG39701
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320138
Northing	948923
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39701

Asset/Event Number	2736
Asset/Event Name	Lynchet, Dun Burn
Type of Asset/Event	Lynchet
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG39710
Status	Non-designated Heritage Asset
Section:	N/A
Easting	309849

Northing	925027
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39710

Asset/Event Number	2737
Asset/Event Name	Red Well & Springs; Crocan Mor
Type of Asset/Event	Spring
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG39721
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320115
Northing	949016
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39721

Asset/Event Number	2738
Asset/Event Name	Cairn, N end of Achanarras Hill, Halkirk
Type of Asset/Event	Shooting Stand
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG39765
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314740
Northing	955870
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39765

Asset/Event Number	2739
Asset/Event Name	Cemetery, St Magnus Chapel
Type of Asset/Event	Cemetery
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG39790
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317040
Northing	957130
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39790

Asset/Event Number	2740
Asset/Event Name	Kiln Barn, Allt Clais Raoin
Type of Asset/Event	Kiln Barn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39844
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313750
Northing	931430
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39844

Asset/Event Number	2741
Asset/Event Name	Enclosure, Allt Clais Raoin
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG39856

Status	Non-designated Heritage Asset
Section:	N/A
Easting	313750
Northing	931430
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG39856

Asset/Event Number	2742
Asset/Event Name	Dailyoich
Type of Asset/Event	Rig And Furrow
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG40235
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310200
Northing	924350
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG40235

Asset/Event Number	2743
Asset/Event Name	Torboll
Type of Asset/Event	Field System
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG40409
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273851
Northing	899636
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG40409

Asset/Event Number	2744
Asset/Event Name	Carn Liath
Type of Asset/Event	Field System
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG40476
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273891
Northing	899044
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG40476

Asset/Event Number	2745
Asset/Event Name	Strath Rusdale Lodge
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG40570
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257080
Northing	877380
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG40570

Asset/Event Number	2746
Asset/Event Name	The Bank
Type of Asset/Event	Enclosure

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG40597
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273710
Northing	903160
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG40597

Asset/Event Number	2747
Asset/Event Name	East Kinnauld
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG40620
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274270
Northing	901670
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG40620

Asset/Event Number	2748
Asset/Event Name	Lazy Beds, Allt Cnoc Na Gamhna
Type of Asset/Event	Lazy Beds
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG40771
Status	Non-designated Heritage Asset
Section:	N/A
Easting	279070
Northing	904000

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG40771

Asset/Event Number	2749
Asset/Event Name	Strath Sgitheach
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG40807
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252287
Northing	863753
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG40807

Asset/Event Number	2750
Asset/Event Name	Lang Well
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG40816
Status	Non-designated Heritage Asset
Section:	N/A
Easting	309940
Northing	922400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG40816

Asset/Event Number	2751
Asset/Event Name	3 cists, Croch Fionne
Type of Asset/Event	Burial
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG40879
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248000
Northing	858000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG40879

Asset/Event Number	2752
Asset/Event Name	Glac Bhan
Type of Asset/Event	Clearance Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG41341
Status	Non-designated Heritage Asset
Section:	N/A
Easting	253995
Northing	863724
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG41341

Asset/Event Number	2753
Asset/Event Name	Cnoc a' Leacachan
Type of Asset/Event	Clearance Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG41365
Status	Non-designated Heritage Asset

Section:	N/A
Easting	257611
Northing	872548
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG41365

Asset/Event Number	2754
Asset/Event Name	Old Parish Church, Kinettas, Strathpeffer
Type of Asset/Event	Cemetery
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG41436
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248034
Northing	858179
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG41436

Asset/Event Number	2755
Asset/Event Name	Balantrath
Type of Asset/Event	Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG41513
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314400
Northing	930800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG41513

Asset/Event Number	2756
Asset/Event Name	Ach' Torra' Dhamh
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG41519
Status	Non-designated Heritage Asset
Section:	N/A
Easting	272183
Northing	900471
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG41519

Asset/Event Number	2757
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2758
Asset/Event Name	Hut circles, Morvich Burn
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric

Listing No./NRHE Number	<Null>
HER Number	MHG41623
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276540
Northing	902480
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG41623

Asset/Event Number	2759
Asset/Event Name	Hut circle etc, Torr A'Bhealaidh
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG41627
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249650
Northing	848680
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG41627

Asset/Event Number	2760
Asset/Event Name	Torr Na H-Uamhaig
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG41631
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255080
Northing	868160
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG41631

Asset/Event Number	2761
Asset/Event Name	Morvich Burn
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG41643
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276670
Northing	901400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG41643

Asset/Event Number	2762
Asset/Event Name	Millery
Type of Asset/Event	Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG41756
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310950
Northing	925390
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG41756

Asset/Event Number	2763

Asset/Event Name	Allt Bhuailteach
Type of Asset/Event	Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG41782
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312730
Northing	930700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG41782

Asset/Event Number	2764
Asset/Event Name	East Kinnauld
Type of Asset/Event	Corn Drying Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG41812
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274350
Northing	901750
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG41812

Asset/Event Number	2765
Asset/Event Name	Golticlay
Type of Asset/Event	Field System
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG41818
Status	Non-designated Heritage Asset
Section:	N/A

Easting	320100
Northing	941000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG41818

Asset/Event Number	2766
Asset/Event Name	Torboll Fall
Type of Asset/Event	Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG41929
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274540
Northing	898885
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG41929

Asset/Event Number	2767
Asset/Event Name	Strath Lunndaidh
Type of Asset/Event	Field System
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG41966
Status	Non-designated Heritage Asset
Section:	N/A
Easting	278300
Northing	901200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG41966

Asset/Event Number	2768
Asset/Event Name	Chapel etc, Ballachly
Type of Asset/Event	Gravestone
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG42022
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319320
Northing	944780
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG42022

Asset/Event Number	2769
Asset/Event Name	Crouched Burial - Cists w burials, Muirton Mains
Type of Asset/Event	Burial
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG42082
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245800
Northing	854040
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG42082

Asset/Event Number	2770
Asset/Event Name	Cremation - Cists w burials, Muirton Mains
Type of Asset/Event	Cremation
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>

HER Number	MHG42086
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245800
Northing	854040
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG42086

Asset/Event Number	2771
Asset/Event Name	Contin Parish Church, graveyard
Type of Asset/Event	Cross Slab
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG42117
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245642
Northing	855750
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG42117

Asset/Event Number	2772
Asset/Event Name	Ben-A-Chielt
Type of Asset/Event	Boundary Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG42176
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319800
Northing	937000
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG42176

Asset/Event Number	2773
Asset/Event Name	Farm, Blackburn
Type of Asset/Event	Boundary Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG42179
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320078
Northing	938846
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG42179

Asset/Event Number	2774
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2775
Asset/Event Name	VOID - number not assigned

Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2776
Asset/Event Name	Puill Fhraoich
Type of Asset/Event	Corn Drying Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG42486
Status	Non-designated Heritage Asset
Section:	N/A
Easting	261900
Northing	898900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG42486

Asset/Event Number	2777
Asset/Event Name	Puill Fhraoich
Type of Asset/Event	Field System
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG42492
Status	Non-designated Heritage Asset
Section:	N/A
Easting	261900

Northing	898900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG42492

Asset/Event Number	2778
Asset/Event Name	Loedebest
Type of Asset/Event	Structure
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG42565
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314800
Northing	931300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG42565

Asset/Event Number	2779
Asset/Event Name	Fishing Store, Berriedale
Type of Asset/Event	Gear Store
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG42704
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312061
Northing	922552
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG42704

Asset/Event Number	2780
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2781
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2782
Asset/Event Name	ACHAVANICH SCHOOL
Type of Asset/Event	School
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG42764

Status	Non-designated Heritage Asset
Section:	N/A
Easting	317980
Northing	942700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG42764

Asset/Event Number	2783
Asset/Event Name	ACHAVANICH SCHOOLHOUSE
Type of Asset/Event	School House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG42790
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317980
Northing	942700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG42790

Asset/Event Number	2784
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	

Importance:	
Description	VOID - number not assigned

Asset/Event Number	2785
Asset/Event Name	Farmstead - Cnocan
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG42883
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256642
Northing	868671
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG42883

Asset/Event Number	2786
Asset/Event Name	Mission Chapel
Type of Asset/Event	Chapel
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG42982
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312200
Northing	923000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG42982

Asset/Event Number	2787
Asset/Event Name	Loedebest
Type of Asset/Event	Clearance Cairn

Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG43031
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313850
Northing	931500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG43031

Asset/Event Number	2788
Asset/Event Name	Braehiller
Type of Asset/Event	Quarry
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG43038
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314900
Northing	931800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG43038

Asset/Event Number	2789
Asset/Event Name	Clearance Cairn, Cnoc Croit Na Maoile
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG43111
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248800
Northing	849100

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG43111

Asset/Event Number	2790
Asset/Event Name	Possible Burial Cairn, Cnoc Croit Na Maoile
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG43112
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248860
Northing	849160
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG43112

Asset/Event Number	2791
Asset/Event Name	Crannog, & Hunting Lodge, Loch Kinellan
Type of Asset/Event	Wreck
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG43472
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247100
Northing	857590
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG43472

Asset/Event Number	2792
Asset/Event Name	Badnagie
Type of Asset/Event	Quarry
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG43529
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315600
Northing	932560
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG43529

Asset/Event Number	2793
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2794
Asset/Event Name	Clashcrebie Mor
Type of Asset/Event	Boundary Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG43699
Status	Non-designated Heritage Asset

Section:	N/A
Easting	319000
Northing	940100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG43699

Asset/Event Number	2795
Asset/Event Name	Ballachly
Type of Asset/Event	Boundary Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG43703
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319650
Northing	944350
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG43703

Asset/Event Number	2796
Asset/Event Name	Loedebest
Type of Asset/Event	Boundary Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG43740
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312900
Northing	932400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG43740

Asset/Event Number	2797
Asset/Event Name	Loedebest
Type of Asset/Event	Sheep Fold
Date and/or Period	post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG43743
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312900
Northing	932400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG43743

Asset/Event Number	2798
Asset/Event Name	Achkinloch
Type of Asset/Event	Head Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG43744
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319200
Northing	942300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG43744

Asset/Event Number	2799
Asset/Event Name	Achkinloch
Type of Asset/Event	Sheep Fold
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG43745
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319200
Northing	942300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG43745

Asset/Event Number	2800
Asset/Event Name	Hut circle - Bridge of Horn
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG43751
Status	Non-designated Heritage Asset
Section:	N/A
Easting	279400
Northing	905000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG43751

Asset/Event Number	2801
Asset/Event Name	Farmhouse - Carn Nan Uaigh
Type of Asset/Event	Farmhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG43811
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293466
Northing	914062
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG43811

Asset/Event Number	2802
Asset/Event Name	Hut circle,Bad an Achaid
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG43812
Status	Non-designated Heritage Asset
Section:	N/A
Easting	308350
Northing	923920
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG43812

Asset/Event Number	2803
Asset/Event Name	The Spa Hotel (site) Strathpeffer
Type of Asset/Event	Hospital
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG43813
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247671
Northing	857661
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG43813

Asset/Event Number	2804

Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2805
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2806
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	

Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2807
Asset/Event Name	Walled garden - Coul House
Type of Asset/Event	Walled Garden
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG43983
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246340
Northing	856309
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG43983

Asset/Event Number	2808
Asset/Event Name	Coul House, Gardens & Parkland
Type of Asset/Event	Glasshouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG43984
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246372
Northing	856364
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG43984

Asset/Event Number	2809
Asset/Event Name	Coul House, Gardens & Parkland
Type of Asset/Event	Sundial
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG43985
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246120
Northing	856350
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG43985

Asset/Event Number	2810
Asset/Event Name	Human remains, Bronze Age Beaker Burial - Craig-na-Feich, Achavanich
Type of Asset/Event	Human Remains
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG44025
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317837
Northing	943335
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG44025

Asset/Event Number	2811
Asset/Event Name	Loch Salachaidh
Type of Asset/Event	Field System
Date and/or Period	Undated
Listing No./NRHE Number	<Null>

HER Number	MHG44156
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276120
Northing	903300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG44156

Asset/Event Number	2812
Asset/Event Name	Loch Salachaidh
Type of Asset/Event	Shieling Hut
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG44157
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276120
Northing	903300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG44157

Asset/Event Number	2813
Asset/Event Name	Aberscross
Type of Asset/Event	Field System
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG44175
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276600
Northing	900400
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG44175

Asset/Event Number	2814
Asset/Event Name	Aberscross
Type of Asset/Event	Lime Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG44176
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276600
Northing	900400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG44176

Asset/Event Number	2815
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	

Asset/Event Number	2816
Asset/Event Name	Kinnarhaird Farmstead

Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG44225
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246912
Northing	855156
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG44225

Asset/Event Number	2817
Asset/Event Name	Kinnarhaird Farmstead
Type of Asset/Event	Sundial
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG44226
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246912
Northing	855156
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG44226

Asset/Event Number	2818
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	
Easting	

Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	

Asset/Event Number	2819
Asset/Event Name	Cup-marked stone - Kiltarlity Old Parish Church graveyard
Type of Asset/Event	Cup Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG44692
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249719
Northing	843919
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG44692

Asset/Event Number	2820
Asset/Event Name	Dalnamein
Type of Asset/Event	Enclosure
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG44738
Status	Non-designated Heritage Asset
Section:	N/A
Easting	272120
Northing	898570
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG44738

Asset/Event Number	2821
Asset/Event Name	Dalnamein
Type of Asset/Event	Metal Working Site
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG44739
Status	Non-designated Heritage Asset
Section:	N/A
Easting	272450
Northing	898500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG44739

Asset/Event Number	3706
Asset/Event Name	Boath Short (Boath Chambered Cairns)
Type of Asset/Event	Cist
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM6644
HER Number	MHG44767
Status	Scheduled Monument
Section:	N/A
Easting	258330
Northing	873950
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/apex/f?p=1505:300:::::VIEWTYPE,VIEWREF:designation,SM6644

Asset/Event Number	2823
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	

HER Number	
Status	
Section:	
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	

Asset/Event Number	2824
Asset/Event Name	Berriedale
Type of Asset/Event	Clearance Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG44827
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310500
Northing	925700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG44827

Asset/Event Number	2825
Asset/Event Name	Berriedale
Type of Asset/Event	Enclosure
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG44828
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310500
Northing	925700
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG44828

Asset/Event Number	2826
Asset/Event Name	Berriedale
Type of Asset/Event	Field System
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG44829
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310500
Northing	925700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG44829

Asset/Event Number	2827
Asset/Event Name	Clearance cairns - Loch Brora
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG44864
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285928
Northing	906355
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG44864

Asset/Event Number	2828
Asset/Event Name	Possible Corn-Drying Kiln - Cnoc A'Mhuilinn

Type of Asset/Event	Corn Drying Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG45046
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251519
Northing	862119
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG45046

Asset/Event Number	2829
Asset/Event Name	Sletdale Burn
Type of Asset/Event	Cord Rig
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG45129
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293400
Northing	912700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG45129

Asset/Event Number	2830
Asset/Event Name	Borgue Langwell
Type of Asset/Event	Wall
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG45175
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310300

Northing	921880
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG45175

Asset/Event Number	2831
Asset/Event Name	Borgue Langwell
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG45176
Status	Non-designated Heritage Asset
Section:	N/A
Easting	310300
Northing	921880
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG45176

Asset/Event Number	2832
Asset/Event Name	Carn nan Conach, Culrain
Type of Asset/Event	Cairn; Grave Marker
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG45235
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257340
Northing	893530
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG45235

Asset/Event Number	2833
Asset/Event Name	Elsick House, Strathpeffer
Type of Asset/Event	Burial Ground
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG45289
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247780
Northing	857440
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG45289

Asset/Event Number	2834
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	

Asset/Event Number	2835
Asset/Event Name	Cairnfield, Drum Dubhran
Type of Asset/Event	Cairnfield; Clearance Cairn; Burial Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG45437

Status	Non-designated Heritage Asset
Section:	N/A
Easting	249975
Northing	860996
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG45437

Asset/Event Number	2836
Asset/Event Name	Hut circle etc, Drum Dubhran
Type of Asset/Event	Rig And Furrow
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG45438
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249670
Northing	860740
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG45438

Asset/Event Number	2837
Asset/Event Name	Field boundary, Minera
Type of Asset/Event	Field Boundary
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG45469
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315690
Northing	934750
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG45469

Asset/Event Number	2838
Asset/Event Name	Altnagar Lodge Hotel
Type of Asset/Event	Rig And Furrow
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG45636
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258460
Northing	898460
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG45636

Asset/Event Number	2839
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	

Asset/Event Number	2840
Asset/Event Name	Broch, Strath Carnaig
Type of Asset/Event	Circular Enclosure

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG45710
Status	Non-designated Heritage Asset
Section:	N/A
Easting	270520
Northing	899014
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG45710

Asset/Event Number	2841
Asset/Event Name	Buildings, Minera
Type of Asset/Event	Corn Drying Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG45831
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315540
Northing	934680
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG45831

Asset/Event Number	2842
Asset/Event Name	Buildings, Minera
Type of Asset/Event	Threshing Barn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG45832
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315540
Northing	934680

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG45832

Asset/Event Number	2843
Asset/Event Name	Mill of Stamster
Type of Asset/Event	Watermill
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG45851
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317900
Northing	941900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG45851

Asset/Event Number	2844
Asset/Event Name	Allt An T-salainn
Type of Asset/Event	Shooting Stand
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG46218
Status	Non-designated Heritage Asset
Section:	N/A
Easting	290500
Northing	907800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG46218

Asset/Event Number	2845
Asset/Event Name	Well - Balno
Type of Asset/Event	Well
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG46387
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248600
Northing	851400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG46387

Asset/Event Number	2846
Asset/Event Name	Orrinside
Type of Asset/Event	Building
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG46388
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248870
Northing	851510
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG46388

Asset/Event Number	2847
Asset/Event Name	Faebait
Type of Asset/Event	Enclosure
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG46389
Status	Non-designated Heritage Asset

Section:	N/A
Easting	249120
Northing	850880
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG46389

Asset/Event Number	2848
Asset/Event Name	Cawdearg, Byre
Type of Asset/Event	Byre
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG46728
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256250
Northing	891151
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG46728

Asset/Event Number	2849
Asset/Event Name	Berriedale Bridge (2 of 2)
Type of Asset/Event	Arch Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG46757
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311814
Northing	922644
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG46757

Asset/Event Number	2850
Asset/Event Name	Contin Church Of Scotland Parish Church, Burial Ground
Type of Asset/Event	Burial Ground
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG47628
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245623
Northing	855758
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG47628

Asset/Event Number	2851
Asset/Event Name	3 Portland Terrace, Berriedale
Type of Asset/Event	Terraced House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG47726
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311981
Northing	922488
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG47726

Asset/Event Number	2852
Asset/Event Name	Fairburn Mains Cottages
Type of Asset/Event	Cottage
Date and/or Period	Undated

Listing No./NRHE Number	<Null>
HER Number	MHG48411
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247204
Northing	853538
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48411

Asset/Event Number	2853
Asset/Event Name	Coul Of Fairburn Farm
Type of Asset/Event	Farmhouse; Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG48412
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247609
Northing	853549
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48412

Asset/Event Number	2854
Asset/Event Name	Contin, New Bridge
Type of Asset/Event	Road Bridge
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG48413
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245415
Northing	856623
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48413

Asset/Event Number	2855
Asset/Event Name	Muirton Mains, Gas Street Cottages
Type of Asset/Event	Cottage
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG48421
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245710
Northing	853811
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48421

Asset/Event Number	2856
Asset/Event Name	Muirton Mains, Lodge
Type of Asset/Event	Lodge
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG48422
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245623
Northing	854138
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48422

Asset/Event Number	2857

Asset/Event Name	Fairburn House, East Lodge
Type of Asset/Event	Lodge
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG48423
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245200
Northing	853130
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48423

Asset/Event Number	2858
Asset/Event Name	Fairburn House, Saw Mill
Type of Asset/Event	Saw Mill
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG48425
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245548
Northing	852465
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48425

Asset/Event Number	2859
Asset/Event Name	Fairburn House, Estate Footbridge
Type of Asset/Event	Footbridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG48426
Status	Non-designated Heritage Asset
Section:	N/A

Easting	245401
Northing	852476
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48426

Asset/Event Number	2860
Asset/Event Name	Kiln, Stronachroe
Type of Asset/Event	Still?; Kiln?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG48427
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245772
Northing	852469
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48427

Asset/Event Number	2861
Asset/Event Name	Fairburn House, Estate Burial Ground
Type of Asset/Event	Burial Ground
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG48428
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247315
Northing	851767
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48428

Asset/Event Number	2862
Asset/Event Name	Aultgowrie
Type of Asset/Event	Farmhouse; Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG48429
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247685
Northing	851465
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48429

Asset/Event Number	2863
Asset/Event Name	Aultgowrie, Bridge Cottage
Type of Asset/Event	Cottage
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG48430
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247495
Northing	851505
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48430

Asset/Event Number	2864
Asset/Event Name	Aultgowrie Bridge
Type of Asset/Event	Road Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG48431
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247772
Northing	850933
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48431

Asset/Event Number	2865
Asset/Event Name	Clachuile
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG48432
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246389
Northing	853976
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48432

Asset/Event Number	2866
Asset/Event Name	Clachuile Cottage
Type of Asset/Event	Cottage
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG48433
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246956
Northing	853920
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48433

Asset/Event Number	2867
Asset/Event Name	Wester Balloan
Type of Asset/Event	Farmhouse; Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG48434
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247913
Northing	853908
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48434

Asset/Event Number	2868
Asset/Event Name	Wester Balloan Cottage
Type of Asset/Event	Cottage
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG48435
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247409
Northing	853840
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48435

Asset/Event Number	2869
Asset/Event Name	Achnasoul

Type of Asset/Event	Farmhouse; Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG48441
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248594
Northing	852282
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48441

Asset/Event Number	2870
Asset/Event Name	Achnasoul Cottage
Type of Asset/Event	Cottage
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG48442
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248397
Northing	852306
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48442

Asset/Event Number	2871
Asset/Event Name	Balno
Type of Asset/Event	Farmstead; Farmhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG48443
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248692

Northing	851332
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48443

Asset/Event Number	2872
Asset/Event Name	Auchmore
Type of Asset/Event	Farmstead; Farmhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG48444
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249213
Northing	850426
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48444

Asset/Event Number	2873
Asset/Event Name	Faebit Farm
Type of Asset/Event	Farmstead; Farmhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG48445
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248633
Northing	850897
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48445

Asset/Event Number	2874
Asset/Event Name	Possible hut circle - Achnasoul Wood
Type of Asset/Event	Hut Circle; Enclosure
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG48736
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248760
Northing	851870
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48736

Asset/Event Number	2875
Asset/Event Name	Achnasoul Wood
Type of Asset/Event	Bank (Earthwork)
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG48738
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248542
Northing	851646
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48738

Asset/Event Number	2876
Asset/Event Name	Culrian, Hilton
Type of Asset/Event	Pen; Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG48801

Status	Non-designated Heritage Asset
Section:	N/A
Easting	257030
Northing	893920
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48801

Asset/Event Number	2877
Asset/Event Name	Langergill
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG49292
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318540
Northing	955010
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG49292

Asset/Event Number	2878
Asset/Event Name	Heights Of Achterneed
Type of Asset/Event	Chambered Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG49769
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249248
Northing	860123
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG49769

Asset/Event Number	2879
Asset/Event Name	Margaret: Langwell, North Sea
Type of Asset/Event	Wreck
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG49808
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311000
Northing	921000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG49808

Asset/Event Number	2880
Asset/Event Name	Torr Achilty, Dam And Power Station
Type of Asset/Event	Dam
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG50629
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244623
Northing	854554
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG50629

Asset/Event Number	2881
Asset/Event Name	Torr Achilty, Dam And Power Station
Type of Asset/Event	Power Station

Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG50630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244626
Northing	854530
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG50630

Asset/Event Number	2882
Asset/Event Name	Site of Culeave House, Culeave, Ardgay
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG51183
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255245
Northing	891302
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG51183

Asset/Event Number	2883
Asset/Event Name	Mid Syall, Ardgay
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG51193
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257193
Northing	891272

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG51193

Asset/Event Number	2884
Asset/Event Name	Lanergill School
Type of Asset/Event	School; Schoolhouse; House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG51316
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319453
Northing	954931
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG51316

Asset/Event Number	2885
Asset/Event Name	Building remains, Inveran Wood
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG52635
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257391
Northing	897716
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG52635

Asset/Event Number	2886
Asset/Event Name	Steading south east of Hill of Rangag, Rangag, Latheron
Type of Asset/Event	House?; Grocers Shop; Shoe Factory; Steading
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG52648
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317777
Northing	943570
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG52648

Asset/Event Number	2887
Asset/Event Name	The Haven, Berriedale
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG52675
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312052
Northing	922532
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG52675

Asset/Event Number	2888
Asset/Event Name	The Fairy Stone - Bottacks
Type of Asset/Event	Cup Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG52913
Status	Non-designated Heritage Asset

Section:	N/A
Easting	248765
Northing	860425
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG52913

Asset/Event Number	2889
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2890
Asset/Event Name	Sheepfold, Creag Riabhach, Glen Loth
Type of Asset/Event	Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG52981
Status	Non-designated Heritage Asset
Section:	N/A
Easting	294228
Northing	912163
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG52981

Asset/Event Number	2891
Asset/Event Name	Farmstead, 19 Culburnie
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG52991
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249157
Northing	841787
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG52991

Asset/Event Number	2892
Asset/Event Name	Peat cuttings, Moss of Knockglass
Type of Asset/Event	Peat Cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG53512
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317408
Northing	950308
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53512

Asset/Event Number	2893
Asset/Event Name	Site of farmstead, Causeymire
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG53514
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317393
Northing	949816
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53514

Asset/Event Number	2894
Asset/Event Name	Former steading, Balnaird, Heights of Inchvannie, Strathpeffer
Type of Asset/Event	Steading
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG53560
Status	Non-designated Heritage Asset
Section:	N/A
Easting	250093
Northing	860154
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53560

Asset/Event Number	2895
Asset/Event Name	Clearance Cairns, Gilbert's Hill
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG53868
Status	Non-designated Heritage Asset
Section:	N/A
Easting	284108
Northing	907305
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53868

Asset/Event Number	2896
Asset/Event Name	Turf and stone bank, Strath Lunndaidh
Type of Asset/Event	Bank (Earthwork)
Date and/or Period	uNDated
Listing No./NRHE Number	<Null>
HER Number	MHG53876
Status	Non-designated Heritage Asset
Section:	N/A
Easting	278366
Northing	901500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53876

Asset/Event Number	2897
Asset/Event Name	Hut circle, Strath Lunndaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG53881
Status	Non-designated Heritage Asset
Section:	N/A
Easting	278216
Northing	901540
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53881

Asset/Event Number	2898

Asset/Event Name	Hut circle, Strath Lunndaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG53882
Status	Non-designated Heritage Asset
Section:	N/A
Easting	278273
Northing	901460
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53882

Asset/Event Number	2899
Asset/Event Name	Sheepfold and ?agricultural building, Fannyfield Farm
Type of Asset/Event	Sheep Fold; Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG54063
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255408
Northing	865770
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54063

Asset/Event Number	2900
Asset/Event Name	Sheepfold, E of Fannyfield Farm
Type of Asset/Event	Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG54064
Status	Non-designated Heritage Asset
Section:	N/A

Easting	255734
Northing	865722
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54064

Asset/Event Number	2901
Asset/Event Name	Milton Lodge Stables (Wester Swardale)
Type of Asset/Event	Farmstead; Kennels; Wind Pump
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG54066
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256112
Northing	865616
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54066

Asset/Event Number	2902
Asset/Event Name	Former Woodland, Halsary
Type of Asset/Event	Wood?
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG54170
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317097
Northing	949147
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54170

Asset/Event Number	2903
Asset/Event Name	Remains of cairn, Rogie
Type of Asset/Event	Clearance Cairn; Ring Cairn?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG54344
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244419
Northing	859061
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54344

Asset/Event Number	2904
Asset/Event Name	Burial cairn, Rogie
Type of Asset/Event	Burial Cairn?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG54345
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244433
Northing	859061
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54345

Asset/Event Number	2905
Asset/Event Name	Drystone building, Rogie
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG54346
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248462
Northing	857468
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54346

Asset/Event Number	2906
Asset/Event Name	Hut circle, Heights of Fodderty
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG54352
Status	Non-designated Heritage Asset
Section:	N/A
Easting	250674
Northing	861229
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54352

Asset/Event Number	2907
Asset/Event Name	Farmstead, enclosure and clearance cairns - Loch Achonachie
Type of Asset/Event	Farmstead; Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG54439
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243784
Northing	855024
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54439

Asset/Event Number	2908
Asset/Event Name	Rig and furrow, east of Toran Sligeach
Type of Asset/Event	Rig And Furrow; Ridge And Furrow; Field Boundary; Boundary Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG54957
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249616
Northing	860613
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54957

Asset/Event Number	2909
Asset/Event Name	Farmstead, north of Balnatink
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG55385
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315206
Northing	931221
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55385

Asset/Event Number	2910
Asset/Event Name	Fundamental bench mark, Contin

Type of Asset/Event	Fundamental Bench Mark
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG55404
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246390
Northing	855760
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55404

Asset/Event Number	2911
Asset/Event Name	Policies, Aultnagar Lodge
Type of Asset/Event	Policies; Gate Pier; Gate
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG55509
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258277
Northing	898907
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55509

Asset/Event Number	2912
Asset/Event Name	Pavilion Gardens, Strathpeffer
Type of Asset/Event	Garden
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG55612
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248365

Northing	858027
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55612

Asset/Event Number	2913
Asset/Event Name	Water pipe - north of Glensgaich, Fodderty
Type of Asset/Event	Water Pipe
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG55849
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245936
Northing	861135
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55849

Asset/Event Number	2914
Asset/Event Name	Sheepfold - near Glensgaich, Fodderty
Type of Asset/Event	Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG55850
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246392
Northing	861349
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55850

Asset/Event Number	2915
Asset/Event Name	Possible farmstead - near Glensgaich, Fodderty
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG55851
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245441
Northing	860915
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55851

Asset/Event Number	2916
Asset/Event Name	Possible farmstead - near Glensgaich, Fodderty
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG55852
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245560
Northing	860987
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55852

Asset/Event Number	2917
Asset/Event Name	Possible farmstead - near Glensgaich, Fodderty
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG55853

Status	Non-designated Heritage Asset
Section:	N/A
Easting	245711
Northing	861123
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55853

Asset/Event Number	2918
Asset/Event Name	Possible farmstead - near Glensgaich, Fodderty
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG55854
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245831
Northing	861195
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55854

Asset/Event Number	2919
Asset/Event Name	Ruined walls and clearance cairns - south of Auchmore, Urray
Type of Asset/Event	Wall; Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG55910
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249128
Northing	850095
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55910

Asset/Event Number	2920
Asset/Event Name	Farmstead - Torr a Bhealaidh, Urray
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG55911
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249895
Northing	848611
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55911

Asset/Event Number	2921
Asset/Event Name	House - Grey Cairn, Dunbeath, Latheron
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG56029
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313525
Northing	926841
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG56029

Asset/Event Number	2922
Asset/Event Name	Building - Balnatink, Latheron
Type of Asset/Event	Building

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG56038
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315059
Northing	931483
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG56038

Asset/Event Number	2923
Asset/Event Name	Farmstead - Balnatink, Latheron
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG56039
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315083
Northing	931413
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG56039

Asset/Event Number	2924
Asset/Event Name	Quarry - Raven's Rock, Fodderty
Type of Asset/Event	Quarry
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG56040
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245909
Northing	860630

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG56040

Asset/Event Number	2925
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2926
Asset/Event Name	Firing Range - near Evanton Airfield, Alness
Type of Asset/Event	Firing Range
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG56203
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255141
Northing	868841
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG56203

Asset/Event Number	2927
Asset/Event Name	Women's Timber Corp Camp - near Fannyfield, Kiltearn
Type of Asset/Event	Construction Camp
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG56249
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255239
Northing	866770
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG56249

Asset/Event Number	2928
Asset/Event Name	House - Tin Houses, Achterneed
Type of Asset/Event	House
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG56278
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248884
Northing	859620
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG56278

Asset/Event Number	2929
Asset/Event Name	Possible enclosure wall - Balnarge, Kiltearn
Type of Asset/Event	Dyke; Enclosure
Date and/or Period	Prehistoric/Medieval
Listing No./NRHE Number	<Null>
HER Number	MHG56449
Status	Non-designated Heritage Asset

Section:	N/A
Easting	256380
Northing	869158
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG56449

Asset/Event Number	2930
Asset/Event Name	Hut circle - Strath Mor
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG56491
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257553
Northing	869621
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG56491

Asset/Event Number	2931
Asset/Event Name	Hut circle - Strath Mor
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG56492
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257613
Northing	869586
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG56492

Asset/Event Number	2932
Asset/Event Name	Mound - Strath Mor
Type of Asset/Event	Mound
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG56493
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257682
Northing	869643
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG56493

Asset/Event Number	2933
Asset/Event Name	Shooting butts - Strath Mor
Type of Asset/Event	Grouse Butt
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG56496
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257098
Northing	870423
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG56496

Asset/Event Number	2934
Asset/Event Name	Eilean Aigas Spring and Well - Kilmorack, Inverness
Type of Asset/Event	Well
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG56711
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247258
Northing	842225
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG56711

Asset/Event Number	2935
Asset/Event Name	Bridge abutment - Eldrable, Kildonan
Type of Asset/Event	Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG56871
Status	Non-designated Heritage Asset
Section:	N/A
Easting	298369
Northing	918181
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG56871

Asset/Event Number	2936
Asset/Event Name	Fish Ladder - Falls of Rogie
Type of Asset/Event	Fish Ladder
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG56893
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244543
Northing	858426
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG56893

Asset/Event Number	2937
Asset/Event Name	Building - Loch Achonachie
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG57274
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244081
Northing	854380
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG57274

Asset/Event Number	2938
Asset/Event Name	Township, Loedebest
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG609
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312458
Northing	932339
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG609

Asset/Event Number	2939

Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2940
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2941
Asset/Event Name	Enclosure, Ousdale
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG622
Status	Non-designated Heritage Asset
Section:	N/A

Easting	307890
Northing	920340
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG622

Asset/Event Number	2942
Asset/Event Name	An Dun Promontory Fort
Type of Asset/Event	Promontory Fort?; Natural Feature
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG624
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314094
Northing	925669
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG624

Asset/Event Number	2943
Asset/Event Name	Site of Cairn, Clais Cairn Hill
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG625
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313760
Northing	927000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG625

Asset/Event Number	2944
Asset/Event Name	Township, Bogroy
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG626
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311377
Northing	927029
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG626

Asset/Event Number	2945
Asset/Event Name	Flint Knife - Langwell House
Type of Asset/Event	Findspot
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG628
Status	Non-designated Heritage Asset
Section:	N/A
Easting	311300
Northing	922700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG628

Asset/Event Number	2946
Asset/Event Name	Motte - Castle Leod
Type of Asset/Event	Motte
Date and/or Period	Medieval
Listing No./NRHE Number	<Null>

HER Number	MHG6283
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248600
Northing	859330
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG6283

Asset/Event Number	2947
Asset/Event Name	Crannog, & Hunting Lodge, Loch Kinellan
Type of Asset/Event	Crannog
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG6285
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247100
Northing	857590
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG6285

Asset/Event Number	2948
Asset/Event Name	Township, Garbh-Leathad
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG629
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313000
Northing	932100
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG629

Asset/Event Number	2949
Asset/Event Name	Cairn, Knock Ardaging
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG6291
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247000
Northing	858000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG6291

Asset/Event Number	2950
Asset/Event Name	Contin Bridge over River Blackwater
Type of Asset/Event	Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG6295
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245403
Northing	856672
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG6295

Asset/Event Number	2951
Asset/Event Name	Contin Mains

Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG6306
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245850
Northing	855890
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG6306

Asset/Event Number	2952
Asset/Event Name	Contin Manse, stables
Type of Asset/Event	Farmstead; Stable
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG6307
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245784
Northing	855614
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG6307

Asset/Event Number	2953
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	

Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2954
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2955
Asset/Event Name	Smithy Ridge
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG6349
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257180
Northing	874800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG6349

Asset/Event Number	2956
Asset/Event Name	An Ruigh Dreighean
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG6351
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257000
Northing	874000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG6351

Asset/Event Number	2957
Asset/Event Name	Knocklea
Type of Asset/Event	Field System; Cairnfield
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG6352
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258170
Northing	873968
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG6352

Asset/Event Number	2958
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	

Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2959
Asset/Event Name	Axe Hammer, Ballavoulen
Type of Asset/Event	Findspot
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG6355
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257380
Northing	873840
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG6355

Asset/Event Number	2960
Asset/Event Name	Wester Knocklea
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG6357
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257744
Northing	874022
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG6357

Asset/Event Number	2961
Asset/Event Name	Cairn, Strone
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG6358
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257600
Northing	874400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG6358

Asset/Event Number	2962
Asset/Event Name	Cnoc Alasdair
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG6360
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257000
Northing	873000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG6360

Asset/Event Number	2963
Asset/Event Name	Boath Chambered Cairns (Parent); Balna Crotchen
Type of Asset/Event	Chambered Cairn

Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG6361
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258130
Northing	873570
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG6361

Asset/Event Number	2964
Asset/Event Name	Township, Loedebest
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG668
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314034
Northing	931322
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG668

Asset/Event Number	2965
Asset/Event Name	Hut Circle, Allt Clais Raoin
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG669
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313400
Northing	931500

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG669

Asset/Event Number	2966
Asset/Event Name	Possible Broch - Achcomhairle
Type of Asset/Event	Cairn?; Broch?; Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG672
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315960
Northing	955660
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG672

Asset/Event Number	2967
Asset/Event Name	Broch - Allt A' Bhurg (Ousdale)
Type of Asset/Event	Broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG708
Status	Non-designated Heritage Asset
Section:	N/A
Easting	307127
Northing	918816
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG708

Asset/Event Number	2968
Asset/Event Name	Croft, Achnacraig
Type of Asset/Event	Croft
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG709
Status	Non-designated Heritage Asset
Section:	N/A
Easting	307267
Northing	919549
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG709

Asset/Event Number	2969
Asset/Event Name	Cottages opp War memorial, Contin
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7097
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245840
Northing	855780
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7097

Asset/Event Number	2970
Asset/Event Name	Coul Cottages, Contin
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7098
Status	Non-designated Heritage Asset

Section:	N/A
Easting	246270
Northing	855760
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7098

Asset/Event Number	2971
Asset/Event Name	Pits - Cnoc Croit Na Maoile
Type of Asset/Event	Pit
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG7100
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248670
Northing	848690
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7100

Asset/Event Number	2972
Asset/Event Name	Hut circle etc, Torr A'Bhealaidh
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG7101
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249650
Northing	848680
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG7101

Asset/Event Number	2973
Asset/Event Name	Clearance cairns, Cnoc Croit Na Maoile
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG7103
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248564
Northing	848819
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7103

Asset/Event Number	2974
Asset/Event Name	Hut circle, Cnoc Croit Na Maoile
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG7104
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248745
Northing	849122
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7104

Asset/Event Number	2975
Asset/Event Name	Hut circle, Cnoc Udais
Type of Asset/Event	Hut Circle; Clearance Cairn
Date and/or Period	Prehistoric

Listing No./NRHE Number	<Null>
HER Number	MHG7105
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248097
Northing	849446
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7105

Asset/Event Number	2976
Asset/Event Name	Hut circle, Cnoc Udais
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG7106
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248470
Northing	849790
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7106

Asset/Event Number	2977
Asset/Event Name	Garbhairidh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7365
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257650
Northing	884400
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7365

Asset/Event Number	2978
Asset/Event Name	Allt Coire Bhenneit
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7366
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256600
Northing	883500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7366

Asset/Event Number	2979
Asset/Event Name	Allt Coire Na Cloiche
Type of Asset/Event	Building
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG7368
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257480
Northing	881050
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7368

Asset/Event Number	2980

Asset/Event Name	Burnt Mound, Druim Dubhrain
Type of Asset/Event	Burnt Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG7774
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249710
Northing	860630
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7774

Asset/Event Number	2981
Asset/Event Name	Hut circle etc, Drum Dubhran
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG7776
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249654
Northing	860849
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7776

Asset/Event Number	2982
Asset/Event Name	Moy Bridge
Type of Asset/Event	Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7779
Status	Non-designated Heritage Asset
Section:	N/A

Easting	248200
Northing	854680
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7779

Asset/Event Number	2983
Asset/Event Name	Cists w burials, Muirton Mains
Type of Asset/Event	Short Cist
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG7781
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245800
Northing	854040
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7781

Asset/Event Number	2984
Asset/Event Name	Hut circle etc, Cul Beag
Type of Asset/Event	Hut Circle Settlement; Enclosure; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG7782
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245858
Northing	850274
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7782

Asset/Event Number	2985
Asset/Event Name	Stone, Clachuil
Type of Asset/Event	Carved Stone
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7783
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246430
Northing	853980
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7783

Asset/Event Number	2986
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	2987
Asset/Event Name	Cairns, Craigdarroch
Type of Asset/Event	Cairnfield
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>

HER Number	MHG7785
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244500
Northing	857200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7785

Asset/Event Number	2988
Asset/Event Name	Cottages, next to Smithy, Contin
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7793
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245830
Northing	855930
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7793

Asset/Event Number	2989
Asset/Event Name	Strathpeffer Town
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7794
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248000
Northing	858000
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7794

Asset/Event Number	2990
Asset/Event Name	Kinellan
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7795
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247150
Northing	857300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7795

Asset/Event Number	2991
Asset/Event Name	Contin, Holly Lodge
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7796
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245830
Northing	856000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7796

Asset/Event Number	2992
Asset/Event Name	East Lodge, Coul House Hotel

Type of Asset/Event	Lodge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7860
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247650
Northing	856700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7860

Asset/Event Number	2993
Asset/Event Name	West Lodge, Coul House
Type of Asset/Event	Lodge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7861
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245801
Northing	856145
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7861

Asset/Event Number	2994
Asset/Event Name	Tigh nam Beithe, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7862
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247775

Northing	857370
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7862

Asset/Event Number	2995
Asset/Event Name	Elsick House, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7863
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247778
Northing	857437
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7863

Asset/Event Number	2996
Asset/Event Name	Ravenscroft, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7866
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248040
Northing	857789
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7866

Asset/Event Number	2997
Asset/Event Name	New York Villa, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7867
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248090
Northing	857848
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7867

Asset/Event Number	2998
Asset/Event Name	Contin Parish Church
Type of Asset/Event	Church
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7868
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245629
Northing	855778
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7868

Asset/Event Number	2999
Asset/Event Name	The Mount, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7869

Status	Non-designated Heritage Asset
Section:	N/A
Easting	248163
Northing	857899
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7869

Asset/Event Number	3000
Asset/Event Name	Lynmhor, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7870
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247917
Northing	857596
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7870

Asset/Event Number	3001
Asset/Event Name	Glen Oran, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7871
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248135
Northing	857892
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7871

Asset/Event Number	3002
Asset/Event Name	Francis Villa and Adjacent Cottage, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7872
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248057
Northing	858162
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7872

Asset/Event Number	3003
Asset/Event Name	Elm Bank, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7873
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248107
Northing	857870
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7873

Asset/Event Number	3004
Asset/Event Name	Craigellachie, Strathpeffer
Type of Asset/Event	House

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7874
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248072
Northing	857821
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7874

Asset/Event Number	3005
Asset/Event Name	Corrie Vanie, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7875
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248021
Northing	857766
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7875

Asset/Event Number	3006
Asset/Event Name	Beechcroft, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7876
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247995
Northing	858105

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7876

Asset/Event Number	3007
Asset/Event Name	Cup marked stone, mortar, Kinnahaird
Type of Asset/Event	Cup Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG7879
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246930
Northing	855190
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7879

Asset/Event Number	3008
Asset/Event Name	Woodlands, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7880
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248181
Northing	858277
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7880

Asset/Event Number	3009
Asset/Event Name	Strathbran, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7881
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248144
Northing	858245
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7881

Asset/Event Number	3010
Asset/Event Name	Ord, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7882
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248102
Northing	858219
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7882

Asset/Event Number	3011
Asset/Event Name	Nicolson Mackenzie Memorial Hospital, Strathpeffer
Type of Asset/Event	Hospital
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7883
Status	Non-designated Heritage Asset

Section:	N/A
Easting	248025
Northing	858071
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7883

Asset/Event Number	3012
Asset/Event Name	Highfield House, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7884
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248072
Northing	858112
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7884

Asset/Event Number	3013
Asset/Event Name	Dochairn, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7885
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248068
Northing	858188
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG7885

Asset/Event Number	3014
Asset/Event Name	Chambered cairn, Clachan Corrach
Type of Asset/Event	Chambered Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG7888
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248830
Northing	856550
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7888

Asset/Event Number	3015
Asset/Event Name	Mains of Coul
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7890
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246213
Northing	856246
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7890

Asset/Event Number	3016
Asset/Event Name	Ring ditch - Urray
Type of Asset/Event	Ring Ditch
Date and/or Period	Prehistorif

Listing No./NRHE Number	<Null>
HER Number	MHG7891
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248100
Northing	855400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7891

Asset/Event Number	3017
Asset/Event Name	3 cists, Croch Fionne
Type of Asset/Event	Cist
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG7892
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248000
Northing	858000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7892

Asset/Event Number	3018
Asset/Event Name	Preas Mairi, Graveyard, Contin
Type of Asset/Event	Cemetery
Date and/or Period	Medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7893
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246080
Northing	855840
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7893

Asset/Event Number	3019
Asset/Event Name	Well, Tobar A'Chinn
Type of Asset/Event	Well
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG7894
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247730
Northing	857560
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7894

Asset/Event Number	3020
Asset/Event Name	Battle Site, Blar Nan Ceann
Type of Asset/Event	Battle Site
Date and/or Period	Post-mo
Listing No./NRHE Number	<Null>
HER Number	MHG7895
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247620
Northing	857730
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7895

Asset/Event Number	3021

Asset/Event Name	Stone Axe, Loch Kinellan
Type of Asset/Event	Findspot
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG7896
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247000
Northing	857500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7896

Asset/Event Number	3022
Asset/Event Name	Old Parish Church, Kinettas, Strathpeffer
Type of Asset/Event	Church
Date and/or Period	Medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7897
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248034
Northing	858179
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7897

Asset/Event Number	3023
Asset/Event Name	Burial Cairn, Cnoc Spardain
Type of Asset/Event	Burial Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG810
Status	Non-designated Heritage Asset
Section:	N/A

Easting	308100
Northing	922900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG810

Asset/Event Number	3024
Asset/Event Name	Hut Circle, Langwell Water
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG812
Status	Non-designated Heritage Asset
Section:	N/A
Easting	308000
Northing	922660
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG812

Asset/Event Number	3025
Asset/Event Name	Hut Circle, Ousdale
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG813
Status	Non-designated Heritage Asset
Section:	N/A
Easting	307730
Northing	920190
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG813

Asset/Event Number	3026
Asset/Event Name	Enclosure, Ousdale
Type of Asset/Event	Enclosure
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG815
Status	Non-designated Heritage Asset
Section:	N/A
Easting	307730
Northing	920300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG815

Asset/Event Number	3027
Asset/Event Name	Mound, Tulloch Field
Type of Asset/Event	Mound
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG816
Status	Non-designated Heritage Asset
Section:	N/A
Easting	307310
Northing	920030
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG816

Asset/Event Number	3028
Asset/Event Name	Mound, Ousdale
Type of Asset/Event	Mound
Date and/or Period	Undated
Listing No./NRHE Number	<Null>

HER Number	MHG817
Status	Non-designated Heritage Asset
Section:	N/A
Easting	307180
Northing	920100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG817

Asset/Event Number	3029
Asset/Event Name	Hut Circle, Allt Bad A'Choilich
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG820
Status	Non-designated Heritage Asset
Section:	N/A
Easting	309674
Northing	924120
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG820

Asset/Event Number	3030
Asset/Event Name	Hut Circle, Allt Bad A' Choilich
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG821
Status	Non-designated Heritage Asset
Section:	N/A
Easting	309600
Northing	924200
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG821

Asset/Event Number	3031
Asset/Event Name	Enclosure, Allt A' Chriosduidhe
Type of Asset/Event	Aisled Building; Enclosure
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG822
Status	Non-designated Heritage Asset
Section:	N/A
Easting	309850
Northing	924530
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG822

Asset/Event Number	3032
Asset/Event Name	Hut Circle, Allt a' Chriosduidhe
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG823
Status	Non-designated Heritage Asset
Section:	N/A
Easting	309930
Northing	924720
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG823

Asset/Event Number	3033
Asset/Event Name	Hut Circle, Allt A' Chriosduidhe

Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG824
Status	Non-designated Heritage Asset
Section:	N/A
Easting	309800
Northing	924860
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG824

Asset/Event Number	3034
Asset/Event Name	Contin Burgh,
Type of Asset/Event	Burgh
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG8303
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245800
Northing	855800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8303

Asset/Event Number	3035
Asset/Event Name	Cists, Heights of Achterneed
Type of Asset/Event	Cist; Cremation
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8304
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249280

Northing	860420
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8304

Asset/Event Number	3036
Asset/Event Name	Bothy, Tarvie Wood
Type of Asset/Event	Bothy
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG8330
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244300
Northing	858700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8330

Asset/Event Number	3037
Asset/Event Name	Hut circle, Torrachilty Forest
Type of Asset/Event	Hut Circle; Sheep Fold
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8333
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244199
Northing	858814
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8333

Asset/Event Number	3038
Asset/Event Name	Allt A'Choire Sliogaich
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8391
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255210
Northing	875330
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8391

Asset/Event Number	3039
Asset/Event Name	Allt A'Choire Sliogaich
Type of Asset/Event	Cultivation Remains
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG8392
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255070
Northing	875410
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8392

Asset/Event Number	3040
Asset/Event Name	Allt a'Choire Sliogaich
Type of Asset/Event	Site
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8394

Status	Non-designated Heritage Asset
Section:	N/A
Easting	255100
Northing	875500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8394

Asset/Event Number	3041
Asset/Event Name	Strath Rusdale Lodge
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG8398
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257080
Northing	877380
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8398

Asset/Event Number	3042
Asset/Event Name	Ceann an Locha
Type of Asset/Event	Farmstead; Kiln Barn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG8407
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255620
Northing	875100
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8407

Asset/Event Number	3043
Asset/Event Name	Innisachomair
Type of Asset/Event	Farmstead; Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG8409
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256300
Northing	879500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8409

Asset/Event Number	3044
Asset/Event Name	An Mam
Type of Asset/Event	Farmstead; Kiln Barn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG8410
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256210
Northing	875250
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8410

Asset/Event Number	3045
Asset/Event Name	Strath Rusdale Lodge
Type of Asset/Event	Farmstead; Enclosure; Kiln Barn

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG8412
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256945
Northing	877159
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8412

Asset/Event Number	3046
Asset/Event Name	VOID - Number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	

Asset/Event Number	3047
Asset/Event Name	Braeantra
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG8420
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256300
Northing	878090

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8420

Asset/Event Number	3048
Asset/Event Name	Braeantra
Type of Asset/Event	Farmstead; Enclosure; Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG8421
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256430
Northing	877620
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8421

Asset/Event Number	3049
Asset/Event Name	Crannog? Loch Morie
Type of Asset/Event	Crannog
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8889
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254570
Northing	875170
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8889

Asset/Event Number	3050
Asset/Event Name	Possible Stone Circle & Chambered cairn Strath Rusdale
Type of Asset/Event	Chambered Cairn; Stone Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8895
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256790
Northing	877930
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8895

Asset/Event Number	3051
Asset/Event Name	Bead, Strathskiach
Type of Asset/Event	Findspot
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8896
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252000
Northing	862000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8896

Asset/Event Number	3052
Asset/Event Name	Cairn, Heights of Keppoch
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8899
Status	Non-designated Heritage Asset

Section:	N/A
Easting	250000
Northing	861000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8899

Asset/Event Number	3053
Asset/Event Name	Strath Sgitheach
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8904
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252880
Northing	864020
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8904

Asset/Event Number	3054
Asset/Event Name	Strath Sgitheach
Type of Asset/Event	Farmstead; Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG8905
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252700
Northing	863600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG8905

Asset/Event Number	3055
Asset/Event Name	Strath Sgitheach
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG8907
Status	Non-designated Heritage Asset
Section:	N/A
Easting	253150
Northing	863580
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8907

Asset/Event Number	3056
Asset/Event Name	5 Hut circles & field system, Heights of Brae
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8908
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251454
Northing	861325
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8908

Asset/Event Number	3057
Asset/Event Name	Boundary Dyke, Strath Sgitheach
Type of Asset/Event	Boundary Dyke
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG8909
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252240
Northing	863730
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8909

Asset/Event Number	3058
Asset/Event Name	Strath Sgitheach
Type of Asset/Event	Enclosure
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG8910
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252370
Northing	863590
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8910

Asset/Event Number	3059
Asset/Event Name	Strath Sgitheach
Type of Asset/Event	Enclosure
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG8911
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252550
Northing	863570
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8911

Asset/Event Number	3060
Asset/Event Name	Watermill site - Cnoc A'Mhuilinn
Type of Asset/Event	Watermill; Lade
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG8912
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251556
Northing	862103
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8912

Asset/Event Number	3061
Asset/Event Name	Slochd an Tighe Dhuibh
Type of Asset/Event	Site
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG8913
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251310
Northing	861900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8913

Asset/Event Number	3062

Asset/Event Name	Heights of Brae
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG8914
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251200
Northing	861124
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8914

Asset/Event Number	3063
Asset/Event Name	Heights of Brae
Type of Asset/Event	Farmstead; Enclosure; Quarry
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG8915
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251030
Northing	861270
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8915

Asset/Event Number	3064
Asset/Event Name	Heights of Brae
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG8916
Status	Non-designated Heritage Asset
Section:	N/A

Easting	250770
Northing	861130
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8916

Asset/Event Number	3065
Asset/Event Name	Strath Sgitheach
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG8917
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254750
Northing	863620
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8917

Asset/Event Number	3066
Asset/Event Name	Chambered Cairn, Heights of Brae
Type of Asset/Event	Chambered Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8919
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251448
Northing	861529
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8919

Asset/Event Number	3067
Asset/Event Name	Cnoc nan Each
Type of Asset/Event	Cairnfield; Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8920
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252600
Northing	864900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8920

Asset/Event Number	3068
Asset/Event Name	Bronze Age hoard - Heights of Brae
Type of Asset/Event	Findspot
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8921
Status	Non-designated Heritage Asset
Section:	N/A
Easting	250999
Northing	861001
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8921

Asset/Event Number	3069
Asset/Event Name	Crioch Dhubh
Type of Asset/Event	Hut Circle; Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>

HER Number	MHG8924
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251440
Northing	862010
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8924

Asset/Event Number	3070
Asset/Event Name	Deserted settlement, Loch Morie
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG8941
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254480
Northing	874743
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8941

Asset/Event Number	3071
Asset/Event Name	Cnoc an Each
Type of Asset/Event	Cairnfield; Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8960
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252000
Northing	865000
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8960

Asset/Event Number	3072
Asset/Event Name	Badgharohaidh Township, Eileanach Lodge
Type of Asset/Event	Township; Head Dyke; Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG8963
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254163
Northing	868670
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8963

Asset/Event Number	3073
Asset/Event Name	Battle site, Blar Nan Ceann
Type of Asset/Event	Battle Site
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG8964
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256620
Northing	868660
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8964

Asset/Event Number	3074
Asset/Event Name	Urn, Glen Glass

Type of Asset/Event	Findspot
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8976
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255680
Northing	867790
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8976

Asset/Event Number	3075
Asset/Event Name	Torr Na H-Uamhaig
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8977
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255080
Northing	868160
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8977

Asset/Event Number	3076
Asset/Event Name	Swordale
Type of Asset/Event	Cup And Ring Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8978
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255000

Northing	865000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8978

Asset/Event Number	3077
Asset/Event Name	Beacon, Cnoc A' Mhargadaidh
Type of Asset/Event	Beacon
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8980
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255745
Northing	867020
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8980

Asset/Event Number	3078
Asset/Event Name	Gruinards House
Type of Asset/Event	House
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9154
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254880
Northing	890810
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9154

Asset/Event Number	3079
Asset/Event Name	Broch, Gruinards
Type of Asset/Event	Broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9156
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254900
Northing	890800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9156

Asset/Event Number	3080
Asset/Event Name	Broch, An Dun
Type of Asset/Event	Broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9158
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256690
Northing	890980
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9158

Asset/Event Number	3081
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	

Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3082
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3083
Asset/Event Name	Schoolhouse, Culrain
Type of Asset/Event	School House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG9164
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257310
Northing	894680
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9164

Asset/Event Number	3084
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3085
Asset/Event Name	Carn nan Conach, Culrain
Type of Asset/Event	Burial Ground
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG9180
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257340
Northing	893530
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9180

Asset/Event Number	3086
Asset/Event Name	Peat Bodies, Culrain
Type of Asset/Event	Human Remains

Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG9182
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257380
Northing	894670
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9182

Asset/Event Number	3087
Asset/Event Name	Cist, Aodann Mhor
Type of Asset/Event	Cist
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9183
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255950
Northing	891130
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9183

Asset/Event Number	3088
Asset/Event Name	Hut Circle and Shieling Hut - Glen Rock
Type of Asset/Event	Hut Circle; Shieling Hut
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9291
Status	Non-designated Heritage Asset
Section:	N/A
Easting	280730
Northing	903420

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9291

Asset/Event Number	3089
Asset/Event Name	Shieling - Glen Rock
Type of Asset/Event	Shieling
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG9292
Status	Non-designated Heritage Asset
Section:	N/A
Easting	280720
Northing	903390
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9292

Asset/Event Number	3090
Asset/Event Name	Cnoc Breac
Type of Asset/Event	Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9297
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258076
Northing	898083
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9297

Asset/Event Number	3091
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3092
Asset/Event Name	Hut Circle - Glen Rock
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9299
Status	Non-designated Heritage Asset
Section:	N/A
Easting	280900
Northing	903400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9299

Asset/Event Number	3093
Asset/Event Name	Allt Na Cist Duibhe
Type of Asset/Event	Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9300
Status	Non-designated Heritage Asset

Section:	N/A
Easting	258399
Northing	896939
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9300

Asset/Event Number	3094
Asset/Event Name	Cnoc Breac
Type of Asset/Event	Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9301
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258090
Northing	897440
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9301

Asset/Event Number	3095
Asset/Event Name	Battle Site, Loch Salachaidh
Type of Asset/Event	Battle Site
Date and/or Period	Medieval
Listing No./NRHE Number	<Null>
HER Number	MHG9362
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276000
Northing	903700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG9362

Asset/Event Number	3096
Asset/Event Name	Eldrable
Type of Asset/Event	Homestead
Date and/or Period	Prehistoric/Early Historic
Listing No./NRHE Number	<Null>
HER Number	MHG9421
Status	Non-designated Heritage Asset
Section:	N/A
Easting	298510
Northing	918130
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9421

Asset/Event Number	3097
Asset/Event Name	Loch Farlary
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9433
Status	Non-designated Heritage Asset
Section:	N/A
Easting	277030
Northing	904400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9433

Asset/Event Number	3098
Asset/Event Name	Field system - Loch Salachaidh
Type of Asset/Event	Field System
Date and/or Period	Prehistoric

Listing No./NRHE Number	<Null>
HER Number	MHG9434
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276923
Northing	904128
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9434

Asset/Event Number	3099
Asset/Event Name	Morvich Burn
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9436
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276440
Northing	901620
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9436

Asset/Event Number	3100
Asset/Event Name	Morvich Farm
Type of Asset/Event	Hut Circle Settlement; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9437
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275888
Northing	901117
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9437

Asset/Event Number	3101
Asset/Event Name	Morvich Burn
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9438
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276189
Northing	901387
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9438

Asset/Event Number	3102
Asset/Event Name	Morvich Lodge
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9439
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275922
Northing	900735
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9439

Asset/Event Number	3103

Asset/Event Name	Morvich Burn
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9440
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275736
Northing	901941
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9440

Asset/Event Number	3104
Asset/Event Name	Tower House? Aberscross
Type of Asset/Event	Tower House
Date and/or Period	Medieval
Listing No./NRHE Number	<Null>
HER Number	MHG9441
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276000
Northing	900000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9441

Asset/Event Number	3105
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A

Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3106
Asset/Event Name	Tobar Nan Deantaig
Type of Asset/Event	Mound
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG9554
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293530
Northing	913930
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9554

Asset/Event Number	3107
Asset/Event Name	Hut circle, Allt Horn
Type of Asset/Event	Hut Circle; Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9586
Status	Non-designated Heritage Asset
Section:	N/A
Easting	280020
Northing	904310
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9586

Asset/Event Number	3108
Asset/Event Name	Chambered Cairn, Achnagoul
Type of Asset/Event	Chambered Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG963
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315680
Northing	932470
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG963

Asset/Event Number	3109
Asset/Event Name	Clearance Cairn, Longall
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG966
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312840
Northing	926050
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG966

Asset/Event Number	3110
Asset/Event Name	Eldrable Burn
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>

HER Number	MHG9752
Status	Non-designated Heritage Asset
Section:	N/A
Easting	297830
Northing	917770
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9752

Asset/Event Number	3111
Asset/Event Name	Eldrable Burn
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9753
Status	Non-designated Heritage Asset
Section:	N/A
Easting	297777
Northing	917404
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9753

Asset/Event Number	3112
Asset/Event Name	Oulmsdale Burn
Type of Asset/Event	Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9754
Status	Non-designated Heritage Asset
Section:	N/A
Easting	296432
Northing	917261
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9754

Asset/Event Number	3113
Asset/Event Name	Oulmsdale Burn
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9755
Status	Non-designated Heritage Asset
Section:	N/A
Easting	295834
Northing	917407
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9755

Asset/Event Number	3114
Asset/Event Name	Oulmsdale Burn
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9756
Status	Non-designated Heritage Asset
Section:	N/A
Easting	296115
Northing	917424
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9756

Asset/Event Number	3115
Asset/Event Name	Oulmsdale Burn

Type of Asset/Event	Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9757
Status	Non-designated Heritage Asset
Section:	N/A
Easting	296319
Northing	917863
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9757

Asset/Event Number	3116
Asset/Event Name	Ulbster
Type of Asset/Event	Hut Circle Settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9758
Status	Non-designated Heritage Asset
Section:	N/A
Easting	296790
Northing	918138
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9758

Asset/Event Number	3117
Asset/Event Name	Torrish Burn
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9761
Status	Non-designated Heritage Asset
Section:	N/A
Easting	296540

Northing	918770
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9761

Asset/Event Number	3118
Asset/Event Name	Earth House & Runic Inscript, Cos Ceumach
Type of Asset/Event	Souterrain; Rune Stone; Midden
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9779
Status	Non-designated Heritage Asset
Section:	N/A
Easting	291860
Northing	907650
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9779

Asset/Event Number	3119
Asset/Event Name	Kintradwell
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9786
Status	Non-designated Heritage Asset
Section:	N/A
Easting	291312
Northing	907776
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9786

Asset/Event Number	3120
Asset/Event Name	Creagan Mor
Type of Asset/Event	Farmstead; Field System
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG9788
Status	Non-designated Heritage Asset
Section:	N/A
Easting	292680
Northing	908671
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9788

Asset/Event Number	3121
Asset/Event Name	Hut circles etc, Wester Kintradwell
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9790
Status	Non-designated Heritage Asset
Section:	N/A
Easting	291646
Northing	907396
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9790

Asset/Event Number	3122
Asset/Event Name	Clynemilton
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9798

Status	Non-designated Heritage Asset
Section:	N/A
Easting	290883
Northing	907587
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9798

Asset/Event Number	3123
Asset/Event Name	Badiepullacher
Type of Asset/Event	Hut Circle; Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9851
Status	Non-designated Heritage Asset
Section:	N/A
Easting	295310
Northing	918610
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9851

Asset/Event Number	3124
Asset/Event Name	Kilphedir Burn
Type of Asset/Event	Hut Circle Settlement; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9854
Status	Non-designated Heritage Asset
Section:	N/A
Easting	299294
Northing	918742
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9854

Asset/Event Number	3125
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3126
Asset/Event Name	Torrish
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9859
Status	Non-designated Heritage Asset
Section:	N/A
Easting	297320
Northing	918780
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9859

Asset/Event Number	3127
Asset/Event Name	Broch, Eldrable
Type of Asset/Event	Broch

Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9863
Status	Non-designated Heritage Asset
Section:	N/A
Easting	298330
Northing	918160
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9863

Asset/Event Number	3128
Asset/Event Name	Torrish Lodge
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9864
Status	Non-designated Heritage Asset
Section:	N/A
Easting	297900
Northing	918650
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9864

Asset/Event Number	3129
Asset/Event Name	Eldrable Burn
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9865
Status	Non-designated Heritage Asset
Section:	N/A
Easting	297709
Northing	917238

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9865

Asset/Event Number	3130
Asset/Event Name	Eldrable Burn
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9866
Status	Non-designated Heritage Asset
Section:	N/A
Easting	297876
Northing	917805
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9866

Asset/Event Number	3131
Asset/Event Name	Grudsterry
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9867
Status	Non-designated Heritage Asset
Section:	N/A
Easting	299540
Northing	917990
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9867

Asset/Event Number	3132
Asset/Event Name	Torrish
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9868
Status	Non-designated Heritage Asset
Section:	N/A
Easting	297100
Northing	918000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9868

Asset/Event Number	3133
Asset/Event Name	Ulbster
Type of Asset/Event	Hut Circle Settlement; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9869
Status	Non-designated Heritage Asset
Section:	N/A
Easting	296566
Northing	918064
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9869

Asset/Event Number	3134
Asset/Event Name	Ulbster
Type of Asset/Event	Cairnfield
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9870
Status	Non-designated Heritage Asset

Section:	N/A
Easting	296296
Northing	918154
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9870

Asset/Event Number	3135
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3136
Asset/Event Name	Ulbster
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9874
Status	Non-designated Heritage Asset
Section:	N/A
Easting	296179
Northing	918741
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG9874

Asset/Event Number	3137
Asset/Event Name	Torrish
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9875
Status	Non-designated Heritage Asset
Section:	N/A
Easting	297270
Northing	918810
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9875

Asset/Event Number	3138
Asset/Event Name	Hut circle - Kilearnan
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9878
Status	Non-designated Heritage Asset
Section:	N/A
Easting	295150
Northing	917120
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9878

Asset/Event Number	3139
Asset/Event Name	Kilearnan
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric

Listing No./NRHE Number	<Null>
HER Number	MHG9879
Status	Non-designated Heritage Asset
Section:	N/A
Easting	295070
Northing	918180
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9879

Asset/Event Number	3140
Asset/Event Name	Eldrable Burn
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9881
Status	Non-designated Heritage Asset
Section:	N/A
Easting	298430
Northing	918190
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9881

Asset/Event Number	3141
Asset/Event Name	Eldrable Burn
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9884
Status	Non-designated Heritage Asset
Section:	N/A
Easting	298071
Northing	917554
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9884

Asset/Event Number	3142
Asset/Event Name	Burnt Mound, Badiepullacher
Type of Asset/Event	Burnt Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9886
Status	Non-designated Heritage Asset
Section:	N/A
Easting	295110
Northing	918200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9886

Asset/Event Number	3143
Asset/Event Name	Ulbster
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9887
Status	Non-designated Heritage Asset
Section:	N/A
Easting	295949
Northing	917781
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9887

Asset/Event Number	3144

Asset/Event Name	Ulbster
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9890
Status	Non-designated Heritage Asset
Section:	N/A
Easting	295980
Northing	918660
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9890

Asset/Event Number	3145
Asset/Event Name	Eldrable Burn
Type of Asset/Event	Hut Circle; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9891
Status	Non-designated Heritage Asset
Section:	N/A
Easting	297834
Northing	918153
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9891

Asset/Event Number	3146
Asset/Event Name	Cist & Burial, Ulbster
Type of Asset/Event	Cist; Burial
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9893
Status	Non-designated Heritage Asset
Section:	N/A

Easting	296140
Northing	918670
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9893

Asset/Event Number	3147
Asset/Event Name	Carved Stone Ball, Eldrable
Type of Asset/Event	Findspot
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9894
Status	Non-designated Heritage Asset
Section:	N/A
Easting	298000
Northing	918000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9894

Asset/Event Number	3148
Asset/Event Name	Brass Brooch, Salscraggie Lodge
Type of Asset/Event	Findspot
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG9896
Status	Non-designated Heritage Asset
Section:	N/A
Easting	299000
Northing	918000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9896

Asset/Event Number	3149
Asset/Event Name	Souterrain & Finds, Torrish
Type of Asset/Event	Souterrain
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9897
Status	Non-designated Heritage Asset
Section:	N/A
Easting	297000
Northing	918000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9897

Asset/Event Number	3150
Asset/Event Name	Torrish Castle
Type of Asset/Event	Castle
Date and/or Period	Medieval
Listing No./NRHE Number	<Null>
HER Number	MHG9898
Status	Non-designated Heritage Asset
Section:	N/A
Easting	297000
Northing	918000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9898

Asset/Event Number	3151
Asset/Event Name	Badiepullacher
Type of Asset/Event	Hut Circle Settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>

HER Number	MHG9899
Status	Non-designated Heritage Asset
Section:	N/A
Easting	295000
Northing	918600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9899

Asset/Event Number	3152
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3153
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	

Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3154
Asset/Event Name	Druim Dearg
Type of Asset/Event	Enclosure; Souterrain; Enclosure
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9940
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293286
Northing	914190
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9940

Asset/Event Number	3155
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3156
Asset/Event Name	Broch, Gailiable

Type of Asset/Event	Broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9956
Status	Non-designated Heritage Asset
Section:	N/A
Easting	294870
Northing	918230
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9956

Asset/Event Number	3157
Asset/Event Name	Hut circles - Gylable Burn
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9962
Status	Non-designated Heritage Asset
Section:	N/A
Easting	294600
Northing	917300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9962

Asset/Event Number	3158
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	

Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3159
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3160
Asset/Event Name	Hut circle, Eldrable
Type of Asset/Event	Hut Circle; Rig And Furrow
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9988
Status	Non-designated Heritage Asset
Section:	N/A
Easting	298570
Northing	918180
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9988

Asset/Event Number	3161
Asset/Event Name	Battle Site, Druim Dearg
Type of Asset/Event	Battle Site
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG9992
Status	Non-designated Heritage Asset
Section:	N/A
Easting	292000
Northing	914000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9992

Asset/Event Number	3162
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3163
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	

Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3164
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3165
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	

Importance:	
Description	VOID - number not assigned

Asset/Event Number	3166
Asset/Event Name	Late C19 Fish farm structures - Carrol, Strath Brora
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG29779
Status	Scheduled Monument
Section:	N/A
Easting	285037
Northing	906631
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG29779

Asset/Event Number	3167
Asset/Event Name	Salmon hatchery - Coire Aghaisgeig
Type of Asset/Event	Fish Farm
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG29870
Status	Non-designated Heritage Asset
Section:	N/A
Easting	284551
Northing	906296
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG29870

Asset/Event Number	3168
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	

Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3169
Asset/Event Name	Hut circle - Creag Buaille Dorach
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG28684
Status	Non-designated Heritage Asset
Section:	N/A
Easting	309601
Northing	921881
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG28684

Asset/Event Number	3170
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	

Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3171
Asset/Event Name	Milestone - Invershin
Type of Asset/Event	Milestone
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG58266
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258007
Northing	895103
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG58266

Asset/Event Number	3172
Asset/Event Name	Air Shaft - Orrin
Type of Asset/Event	Ventilation Shaft
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG58729
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243575
Northing	853967
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG58729

Asset/Event Number	3173
Asset/Event Name	Orrin Power Station
Type of Asset/Event	Power Station
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG58730
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243606
Northing	854571
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG58730

Asset/Event Number	3174
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3175
Asset/Event Name	Clearance cairn, Strath Lunndaidh
Type of Asset/Event	Clearance Cairn; Natural Feature?
Date and/or Period	Unknown
Listing No./NRHE Number	<Null>
HER Number	MHG53883
Status	Non-designated Heritage Asset

Section:	N/A
Easting	278183
Northing	901491
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53883

Asset/Event Number	3176
Asset/Event Name	Platforms, Military Camp - Contin
Type of Asset/Event	Platform; Military Camp
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG59076
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245954
Northing	856641
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59076

Asset/Event Number	3177
Asset/Event Name	Sheep Dip and Enclosure - Contin
Type of Asset/Event	Enclosure; Sheep Fold; Sheep Dip
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG59077
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245829
Northing	856827
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG59077

Asset/Event Number	3178
Asset/Event Name	Farmstead - SW of Coire Cnoc na Gamhna
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG59244
Status	Non-designated Heritage Asset
Section:	N/A
Easting	277562
Northing	902558
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59244

Asset/Event Number	3179
Asset/Event Name	Enclosure - SW of Coire Cnoc na Gamhna
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG59245
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276659
Northing	903634
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59245

Asset/Event Number	3180
Asset/Event Name	Enclosure - SW of Coire Cnoc na Gamhna
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG59246
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276500
Northing	903604
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59246

Asset/Event Number	3181
Asset/Event Name	Farmstead - Kinloch, E of Loch Salachaidh
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG59247
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276654
Northing	903652
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59247

Asset/Event Number	3182
Asset/Event Name	Possible hut circle - Kinloch, E of Loch Salachaidh
Type of Asset/Event	Hut Circle?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG59249
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276698
Northing	903662
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59249

Asset/Event Number	3183
Asset/Event Name	Possible hut circle - Kinloch, E of Loch Salachaidh
Type of Asset/Event	Hut Circle?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG59250
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276548
Northing	903536
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59250

Asset/Event Number	3184
Asset/Event Name	Hut circle - Kinloch
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11116
Status	Non-designated Heritage Asset
Section:	N/A
Easting	277031
Northing	903684
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11116

Asset/Event Number	3185

Asset/Event Name	Enclosure - Kinloch, Rogart
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG59253
Status	Non-designated Heritage Asset
Section:	N/A
Easting	277195
Northing	903795
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59253

Asset/Event Number	3186
Asset/Event Name	Hut circle - NE of Loch Salachaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG59254
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276742
Northing	904224
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59254

Asset/Event Number	3187
Asset/Event Name	Hut circle - NE of Loch Salachaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG59256
Status	Non-designated Heritage Asset
Section:	N/A

Easting	276764
Northing	904202
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59256

Asset/Event Number	3188
Asset/Event Name	Hut circle - NE of Loch Salachaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG59258
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276785
Northing	904172
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59258

Asset/Event Number	3189
Asset/Event Name	Hut circle - NE of Loch Salachaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG59259
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276867
Northing	904123
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59259

Asset/Event Number	3190
Asset/Event Name	Hut circle - NE of Loch Salachaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG59260
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276979
Northing	904170
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59260

Asset/Event Number	3191
Asset/Event Name	Hut circle - NE of Loch Salachaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG59261
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276959
Northing	904152
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59261

Asset/Event Number	3192
Asset/Event Name	Hut circle - NE of Loch Salachaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>

HER Number	MHG59265
Status	Non-designated Heritage Asset
Section:	N/A
Easting	277070
Northing	903892
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59265

Asset/Event Number	3193
Asset/Event Name	Hut circle - Kinloch, Rogart
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG59267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276873
Northing	903975
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59267

Asset/Event Number	3194
Asset/Event Name	Hut circle - Kinloch, Rogart
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG59268
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276890
Northing	903982
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59268

Asset/Event Number	3195
Asset/Event Name	Hut circle - Kinloch, Rogart
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG59269
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276732
Northing	904258
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59269

Asset/Event Number	3196
Asset/Event Name	Hut circle - Loch Farlary
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10510
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276683
Northing	904387
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10510

Asset/Event Number	3197
Asset/Event Name	Hut circle - Loch Farlary

Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG59296
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276721
Northing	904452
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59296

Asset/Event Number	3198
Asset/Event Name	Clearance cairns - Loch Farlary
Type of Asset/Event	Clearance Cairn; Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG41270
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276709
Northing	904466
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG41270

Asset/Event Number	3199
Asset/Event Name	Possible hut circle - Loch Farlary
Type of Asset/Event	Hut Circle?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG59299
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276800

Northing	904481
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59299

Asset/Event Number	3200
Asset/Event Name	Hut circle or enclosure - Loch Brora
Type of Asset/Event	Enclosure; Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10943
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285861
Northing	906233
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10943

Asset/Event Number	3201
Asset/Event Name	Hut circle or enclosure - Loch Brora
Type of Asset/Event	Hut Circle?; Enclosure?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG44863
Status	Non-designated Heritage Asset
Section:	N/A
Easting	285850
Northing	906274
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG44863

Asset/Event Number	3202
Asset/Event Name	Former A9 Road Bridge - Ord of Caithness
Type of Asset/Event	Road Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG59664
Status	Non-designated Heritage Asset
Section:	N/A
Easting	305222
Northing	918153
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59664

Asset/Event Number	3203
Asset/Event Name	Hut circle - E of former Causeymire Church
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG60905
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317411
Northing	948324
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG60905

Asset/Event Number	3204
Asset/Event Name	Hut circle - E of former Causeymire Church
Type of Asset/Event	Hut Circle?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG60906

Status	Non-designated Heritage Asset
Section:	N/A
Easting	317552
Northing	948293
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG60906

Asset/Event Number	3205
Asset/Event Name	Enclosure - Achnamoine
Type of Asset/Event	Enclosure
Date and/or Period	Prehistoric/Early Historic
Listing No./NRHE Number	<Null>
HER Number	MHG60952
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317755
Northing	953694
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG60952

Asset/Event Number	3206
Asset/Event Name	Roundhouse - Fanellan
Type of Asset/Event	Round House (Domestic)
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG61055
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248636
Northing	843147
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61055

Asset/Event Number	3207
Asset/Event Name	Hut circle - Breakachy Burn 'G'
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG61219
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245621
Northing	845565
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61219

Asset/Event Number	3208
Asset/Event Name	Hut circle - Breakachy Burn 'F'
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG61218
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245595
Northing	845572
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61218

Asset/Event Number	3209
Asset/Event Name	Hut circle - Breakachy Burn 'E'
Type of Asset/Event	Hut Circle

Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG61217
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245597
Northing	845539
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61217

Asset/Event Number	3210
Asset/Event Name	Hut circle - Breakachy Burn 'D'
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG61216
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245504
Northing	845463
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61216

Asset/Event Number	3211
Asset/Event Name	Hut circle - Breakachy Burn 'C'
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG61215
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245454
Northing	845379

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61215

Asset/Event Number	3212
Asset/Event Name	Hut circle - Breakachy Burn (B)
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG61214
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245451
Northing	845393
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61214

Asset/Event Number	3213
Asset/Event Name	Hut circle - Breakachy Burn (H)
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG61220
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245663
Northing	845550
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61220

Asset/Event Number	3214
Asset/Event Name	Hut circle - Breakachy Burn
Type of Asset/Event	Hut Circle; Pit
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG61350
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245327
Northing	845316
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61350

Asset/Event Number	3215
Asset/Event Name	Annular Brooch - Loch Kinellan
Type of Asset/Event	Findspot
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61403
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247046
Northing	857551
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61403

Asset/Event Number	3216
Asset/Event Name	Jadeite Axehead - Lower Newport, Berridale
Type of Asset/Event	Findspot
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG61416
Status	Non-designated Heritage Asset

Section:	N/A
Easting	312400
Northing	923500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61416

Asset/Event Number	3217
Asset/Event Name	Burial ground - Castle Leod
Type of Asset/Event	Cemetery
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG32665
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248546
Northing	859236
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32665

Asset/Event Number	3218
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	

Description	VOID - number not assigned

Asset/Event Number	3219
Asset/Event Name	Possible standing stone, Castle Leod
Type of Asset/Event	Standing Stone?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG54214
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248720
Northing	859186
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54214

Asset/Event Number	3220
Asset/Event Name	Gardens, Castle Leod - Strathpeffer
Type of Asset/Event	Garden; Summerhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG25203
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248575
Northing	859282
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG25203

Asset/Event Number	3221
Asset/Event Name	Boundary wall, Castle Leod - Strathpeffer
Type of Asset/Event	Boundary Wall
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG61442
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248530
Northing	859892
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61442

Asset/Event Number	3222
Asset/Event Name	Meallers Houses, Castle Leod - Strathpeffer
Type of Asset/Event	Estate Cottage
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61444
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247792
Northing	859023
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61444

Asset/Event Number	3223
Asset/Event Name	Orchard/Garden, Castle Leod - Strathpeffer
Type of Asset/Event	Orchard; Garden
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61445
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248726
Northing	859492
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61445

Asset/Event Number	3224
Asset/Event Name	Turf Banks - An Caladh Croft
Type of Asset/Event	Bank (Earthwork)
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG58319
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252110
Northing	862184
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG58319

Asset/Event Number	3225
Asset/Event Name	Hut circle - Urchany (Allt na Criche)
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG61451
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245221
Northing	845611
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61451

Asset/Event Number	3226

Asset/Event Name	Hut circle - Urchany (Allt na Criche)
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG61452
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245207
Northing	845618
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61452

Asset/Event Number	3227
Asset/Event Name	Hut circle - Urchany (Allt na Criche)
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG61453
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245150
Northing	845543
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61453

Asset/Event Number	3228
Asset/Event Name	Orchard, garden, pets graveyard at Castle Leod - Strathpeffer
Type of Asset/Event	Orchard; Garden; Animal Cemetery
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG61454
Status	Non-designated Heritage Asset
Section:	N/A

Easting	248699
Northing	859402
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61454

Asset/Event Number	3229
Asset/Event Name	Mill lade tail race at Castle Leod - Strathpeffer
Type of Asset/Event	Lade
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61455
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248664
Northing	859648
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61455

Asset/Event Number	3230
Asset/Event Name	Building at Castle Leod - Strathpeffer
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61456
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248586
Northing	859655
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61456

Asset/Event Number	3231
Asset/Event Name	Old wall at Castle Leod - Strathpeffer
Type of Asset/Event	Wall
Date and/or Period	Medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61459
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248576
Northing	859454
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61459

Asset/Event Number	3232
Asset/Event Name	Old road/trackway at Castle Leod - Strathpeffer
Type of Asset/Event	Road
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61458
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248437
Northing	859642
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61458

Asset/Event Number	3233
Asset/Event Name	Stone quarry or coal pit at Castle Leod - Strathpeffer
Type of Asset/Event	Quarry?; Colliery?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG61461
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248167
Northing	859897
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61461

Asset/Event Number	3234
Asset/Event Name	Possible coal or shale workings at Castle Leod - Strathpeffer
Type of Asset/Event	Quarry?; Colliery?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61462
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248443
Northing	859143
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61462

Asset/Event Number	3235
Asset/Event Name	Building and platform at Castle Leod - Strathpeffer
Type of Asset/Event	Building; Platform
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61463
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248740
Northing	859168
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61463

Asset/Event Number	3236
Asset/Event Name	Building at Castle Leod - Strathpeffer
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61464
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248440
Northing	859666
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61464

Asset/Event Number	3237
Asset/Event Name	Kennels at Castle Leod - Strathpeffer
Type of Asset/Event	Kennels
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61465
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248408
Northing	859657
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61465

Asset/Event Number	3238
Asset/Event Name	Game Larder at Castle Leod - Strathpeffer

Type of Asset/Event	Game Larder
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61466
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248562
Northing	859621
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61466

Asset/Event Number	3239
Asset/Event Name	Well at Castle Leod - Strathpeffer
Type of Asset/Event	Well
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61467
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248532
Northing	859390
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61467

Asset/Event Number	3240
Asset/Event Name	Hut circle - Breakachy Burn (J)
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG61221
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245631

Northing	845633
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61221

Asset/Event Number	3241
Asset/Event Name	Field system, Creagh Dubh
Type of Asset/Event	Field System
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG44150
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245536
Northing	845497
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG44150

Asset/Event Number	3242
Asset/Event Name	Pits at Castle Leod - Strathpeffer
Type of Asset/Event	Pit
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61468
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248527
Northing	859416
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61468

Asset/Event Number	3243
Asset/Event Name	Boundary wall at Castle Leod - Strathpeffer
Type of Asset/Event	Boundary Wall
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61469
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248003
Northing	859332
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61469

Asset/Event Number	3244
Asset/Event Name	Old Track and possible ford at Castle Leod - Strathpeffer
Type of Asset/Event	Ford?; Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61470
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248758
Northing	859335
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61470

Asset/Event Number	3245
Asset/Event Name	CASTLE LEOD, POSSIBLE GOLF COURSE
Type of Asset/Event	Golf Course?
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG34684

Status	Non-designated Heritage Asset
Section:	N/A
Easting	248633
Northing	858971
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG34684

Asset/Event Number	3246
Asset/Event Name	Site of the Hanging tree, Castle Leod - Strathpeffer
Type of Asset/Event	Execution Site?; Tree
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61472
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248664
Northing	859259
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61472

Asset/Event Number	3247
Asset/Event Name	Site of pond, Castle Leod - Strathpeffer
Type of Asset/Event	Ducking Pond?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61478
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248589
Northing	859257
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61478

Asset/Event Number	3248
Asset/Event Name	Well at Castle Leod - Strathpeffer
Type of Asset/Event	Cup Marked Stone?; Well
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG61479
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248532
Northing	859535
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61479

Asset/Event Number	3249
Asset/Event Name	Aigas Mains farmhouse - Aigas, Beauly
Type of Asset/Event	Farmhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61610
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245895
Northing	841751
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61610

Asset/Event Number	3250
Asset/Event Name	Possible crofthouse - Aigas forest, Beauly
Type of Asset/Event	Crofthouse?; Shelter

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61612
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244670
Northing	842567
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61612

Asset/Event Number	3251
Asset/Event Name	Building, possible furnace - Aigas forest, Beauly
Type of Asset/Event	Building; Furnace?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61613
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246387
Northing	842050
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61613

Asset/Event Number	3252
Asset/Event Name	Bridge - Aigas forest, Beauly
Type of Asset/Event	Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61615
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245331
Northing	841912

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61615

Asset/Event Number	3253
Asset/Event Name	Bridge - Aigas forest, Beauly
Type of Asset/Event	Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61617
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245583
Northing	842120
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61617

Asset/Event Number	3254
Asset/Event Name	Perforated Pebble - Kinellan, Strathpeffer
Type of Asset/Event	Findspot
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG61616
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247305
Northing	857540
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61616

Asset/Event Number	3255
Asset/Event Name	Bridge - Aigas forest, Beauly
Type of Asset/Event	Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61618
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245332
Northing	841748
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61618

Asset/Event Number	3256
Asset/Event Name	Palstave Mould - Strathpeffer
Type of Asset/Event	Findspot
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG61619
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248000
Northing	858000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61619

Asset/Event Number	3257
Asset/Event Name	Possible shooting butt - Aigas forest, Beauly
Type of Asset/Event	Structure; Shooting Stand?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61625
Status	Non-designated Heritage Asset

Section:	N/A
Easting	245448
Northing	842351
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61625

Asset/Event Number	3258
Asset/Event Name	Possible shooting butt - Aigas forest, Beauly
Type of Asset/Event	Structure; Shooting Stand?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61628
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245498
Northing	842408
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61628

Asset/Event Number	3259
Asset/Event Name	Site of summerhouse - Aigas forest, Beauly
Type of Asset/Event	Summerhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61629
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246882
Northing	842829
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG61629

Asset/Event Number	3260
Asset/Event Name	Structure - Aigas forest, Beauly
Type of Asset/Event	Building?; Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245605
Northing	842430
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61630

Asset/Event Number	3261
Asset/Event Name	Field clearance - Aigas forest, Beauly
Type of Asset/Event	Clearance Cairn; Cairnfield
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61632
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245545
Northing	842048
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61632

Asset/Event Number	3262
Asset/Event Name	Field clearance - Aigas forest, Beauly
Type of Asset/Event	Clearance Cairn; Cairnfield
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG61633
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246265
Northing	842310
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61633

Asset/Event Number	3263
Asset/Event Name	Clearance cairn- Aigas forest, Beauly
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61634
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244562
Northing	842529
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61634

Asset/Event Number	3264
Asset/Event Name	Clearance cairn- Aigas forest, Beauly
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61635
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244727
Northing	842618
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61635

Asset/Event Number	3265
Asset/Event Name	Clearance cairns- Aigas forest, Beauly
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61637
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244644
Northing	842382
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61637

Asset/Event Number	3266
Asset/Event Name	Possible clearance cairn - Aigas forest, Beauly
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61638
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244537
Northing	842510
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61638

Asset/Event Number	3267

Asset/Event Name	Possible clearance cairn - Aigas forest, Beauly
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61639
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244672
Northing	842391
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61639

Asset/Event Number	3268
Asset/Event Name	Possible clearance cairn - Aigas forest, Beauly
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61640
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244689
Northing	842641
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61640

Asset/Event Number	3269
Asset/Event Name	Clearance cairn - Aigas forest, Beauly
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61641
Status	Non-designated Heritage Asset
Section:	N/A

Easting	244712
Northing	842658
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61641

Asset/Event Number	3270
Asset/Event Name	Clearance stones and ditch - Aigas forest, Beauly
Type of Asset/Event	Linear Clearance Cairn; Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61642
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245443
Northing	842193
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61642

Asset/Event Number	3271
Asset/Event Name	Clearance cairn - Aigas forest, Beauly
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61643
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245460
Northing	842047
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61643

Asset/Event Number	3272
Asset/Event Name	Clearance cairn - Aigas forest, Beauly
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61644
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245318
Northing	841889
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61644

Asset/Event Number	3273
Asset/Event Name	Clearance cairn - Aigas forest, Beauly
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61645
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245677
Northing	842331
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61645

Asset/Event Number	3274
Asset/Event Name	Clearance cairn - Aigas forest, Beauly
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG61646
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245490
Northing	842009
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61646

Asset/Event Number	3275
Asset/Event Name	Clearance cairn - Aigas forest, Beauly
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61647
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245579
Northing	842065
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61647

Asset/Event Number	3276
Asset/Event Name	Clearance cairn - Aigas forest, Beauly
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61648
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245643
Northing	842076
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61648

Asset/Event Number	3277
Asset/Event Name	Clearance cairn - Aigas forest, Beauly
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61650
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245068
Northing	841921
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61650

Asset/Event Number	3278
Asset/Event Name	Clearance cairn - Aigas forest, Beauly
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61651
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245090
Northing	841918
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61651

Asset/Event Number	3279
Asset/Event Name	Possible clearance cairn - Aigas forest, Beauly

Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61652
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246281
Northing	842316
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61652

Asset/Event Number	3280
Asset/Event Name	Clearance cairn - Aigas forest, Beauly
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61653
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246102
Northing	842190
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61653

Asset/Event Number	3281
Asset/Event Name	Clearance cairn - Aigas forest, Beauly
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61654
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245704

Northing	841904
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61654

Asset/Event Number	3282
Asset/Event Name	Clearance cairn - Aigas forest, Beauly
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61655
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245723
Northing	841918
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61655

Asset/Event Number	3283
Asset/Event Name	Possible clearance cairn - Aigas forest, Beauly
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61657
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246300
Northing	842309
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61657

Asset/Event Number	3284
Asset/Event Name	Longhouse - Torbreck, Loch Bhuide
Type of Asset/Event	Longhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG61685
Status	Non-designated Heritage Asset
Section:	N/A
Easting	264880
Northing	898041
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61685

Asset/Event Number	3285
Asset/Event Name	Stray Finds - Culour, Breakachy
Type of Asset/Event	Findspot
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG61718
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246000
Northing	844000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61718

Asset/Event Number	3286
Asset/Event Name	Unprovenanced Finds - Caithness
Type of Asset/Event	Findspot
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG60981

Status	Non-designated Heritage Asset
Section:	N/A
Easting	316330
Northing	948430
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG60981

Asset/Event Number	3287
Asset/Event Name	Spindle Whorl - Contin
Type of Asset/Event	Findspot
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG60681
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247000
Northing	855000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG60681

Asset/Event Number	3288
Asset/Event Name	Farmstead, Allt na Criche, Breakachy Burn, Urchany
Type of Asset/Event	Farmstead; Enclosure; Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23303
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245624
Northing	845475
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23303

Asset/Event Number	3289
Asset/Event Name	Kerb Cairn - Urchany (Allt na Criche)
Type of Asset/Event	Kerb Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG2665
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245610
Northing	845464
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2665

Asset/Event Number	3290
Asset/Event Name	Hut circle (A) - Breakachy Burn, Urchany
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG2666
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245369
Northing	845519
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2666

Asset/Event Number	3291
Asset/Event Name	Hut circle - Urchany (Allt na Criche)
Type of Asset/Event	Hut Circle

Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62068
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245316
Northing	845541
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62068

Asset/Event Number	3292
Asset/Event Name	Hut circle - Urchany (Allt na Criche)
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62069
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245362
Northing	845471
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62069

Asset/Event Number	3293
Asset/Event Name	Building - Allt na Criche, Urchany
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62050
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245645
Northing	845557

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62050

Asset/Event Number	3294
Asset/Event Name	Possible cairn - Tighnaleac
Type of Asset/Event	Cairn?; Clearance Cairn?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG2659
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245600
Northing	845600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2659

Asset/Event Number	3295
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62070
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245668
Northing	845662
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62070

Asset/Event Number	3296
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62071
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245661
Northing	845671
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62071

Asset/Event Number	3297
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62072
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245668
Northing	845672
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62072

Asset/Event Number	3298
Asset/Event Name	Hut circle - Breakachy Burn, Urchany (K)
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG61222
Status	Non-designated Heritage Asset

Section:	N/A
Easting	245677
Northing	845670
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG61222

Asset/Event Number	3299
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62073
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245644
Northing	845671
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62073

Asset/Event Number	3300
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62074
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245655
Northing	845662
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG62074

Asset/Event Number	3301
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62075
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245674
Northing	845635
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62075

Asset/Event Number	3302
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62076
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245656
Northing	845617
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62076

Asset/Event Number	3303
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG62077
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245635
Northing	845593
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62077

Asset/Event Number	3304
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62078
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245634
Northing	845681
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62078

Asset/Event Number	3305
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62079
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245615
Northing	845691
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62079

Asset/Event Number	3306
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62080
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245231
Northing	845857
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62080

Asset/Event Number	3307
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62081
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245223
Northing	845828
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62081

Asset/Event Number	3308

Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62082
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245244
Northing	845814
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62082

Asset/Event Number	3309
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62083
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245213
Northing	845814
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62083

Asset/Event Number	3310
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62084
Status	Non-designated Heritage Asset
Section:	N/A

Easting	245213
Northing	845821
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62084

Asset/Event Number	3311
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62085
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245158
Northing	845853
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62085

Asset/Event Number	3312
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62086
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245136
Northing	845856
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62086

Asset/Event Number	3313
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62087
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245665
Northing	845604
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62087

Asset/Event Number	3314
Asset/Event Name	Clearance cairn or shieling hut - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?; Shieling Hut?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62088
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245679
Northing	845729
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62088

Asset/Event Number	3315
Asset/Event Name	Clearance cairn or shieling hut - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?; Shieling Hut?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG62089
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245680
Northing	845718
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62089

Asset/Event Number	3316
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62091
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245402
Northing	845369
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62091

Asset/Event Number	3317
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62092
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245390
Northing	845368
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62092

Asset/Event Number	3318
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62093
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245437
Northing	845380
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62093

Asset/Event Number	3319
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62094
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245491
Northing	845395
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62094

Asset/Event Number	3320
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)

Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62095
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245514
Northing	845404
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62095

Asset/Event Number	3321
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62096
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245644
Northing	845422
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62096

Asset/Event Number	3322
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62097
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245508

Northing	845427
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62097

Asset/Event Number	3323
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62099
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245448
Northing	845448
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62099

Asset/Event Number	3324
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62100
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245436
Northing	845459
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62100

Asset/Event Number	3325
Asset/Event Name	Standing stone - near Clach Mhic Mhios, Glen Loth
Type of Asset/Event	Standing Stone?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62101
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293952
Northing	915086
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62101

Asset/Event Number	3326
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62102
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245378
Northing	845414
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62102

Asset/Event Number	3327
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62103

Status	Non-designated Heritage Asset
Section:	N/A
Easting	245389
Northing	845433
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62103

Asset/Event Number	3328
Asset/Event Name	Clearance cairn - Urchany (Coul na Bottach)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62104
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245003
Northing	845777
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62104

Asset/Event Number	3329
Asset/Event Name	Clearance cairn - Urchany (Coul na Bottach)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62105
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245015
Northing	845776
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62105

Asset/Event Number	3330
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62106
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245249
Northing	845588
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62106

Asset/Event Number	3331
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62107
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245274
Northing	845580
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62107

Asset/Event Number	3332
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62108
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245220
Northing	845591
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62108

Asset/Event Number	3333
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62109
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245170
Northing	845522
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62109

Asset/Event Number	3334
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62110
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245207
Northing	845516

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62110

Asset/Event Number	3335
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62111
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245242
Northing	845540
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62111

Asset/Event Number	3336
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62112
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245463
Northing	845496
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62112

Asset/Event Number	3337
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62113
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245494
Northing	845572
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62113

Asset/Event Number	3338
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62114
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245603
Northing	845546
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62114

Asset/Event Number	3339
Asset/Event Name	Cist and possible burial cairn- Urchany (Allt na Criche)
Type of Asset/Event	Cist; Burial Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62116
Status	Non-designated Heritage Asset

Section:	N/A
Easting	245512
Northing	845554
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62116

Asset/Event Number	3340
Asset/Event Name	Kerb burial cairn - Urchany (Allt na Criche)
Type of Asset/Event	Kerb Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62117
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245419
Northing	845543
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62117

Asset/Event Number	3341
Asset/Event Name	Kerb burial cairn - Urchany (Allt na Criche)
Type of Asset/Event	Kerb Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62118
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245672
Northing	845577
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG62118

Asset/Event Number	3342
Asset/Event Name	Kerb burial cairn - Urchany (Allt na Criche)
Type of Asset/Event	Kerb Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62119
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245430
Northing	845545
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62119

Asset/Event Number	3343
Asset/Event Name	Burial cairn - Urchany (Allt na Criche)
Type of Asset/Event	Burial Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62120
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245428
Northing	845518
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62120

Asset/Event Number	3344
Asset/Event Name	Burial cairn - Urchany (Coulnabottach)
Type of Asset/Event	Burial Cairn?
Date and/or Period	Prehistoric

Listing No./NRHE Number	<Null>
HER Number	MHG62122
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245232
Northing	845819
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62122

Asset/Event Number	3345
Asset/Event Name	Burial cairn - Urchany (Coulnabottach)
Type of Asset/Event	Burial Cairn?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62123
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245231
Northing	845838
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62123

Asset/Event Number	3346
Asset/Event Name	Burial cairn - Urchany (Allt na Criche)
Type of Asset/Event	Burial Cairn?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62124
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245604
Northing	845546
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62124

Asset/Event Number	3347
Asset/Event Name	Burial cairn - Urchany (Allt na Criche)
Type of Asset/Event	Burial Cairn?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62125
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245546
Northing	845589
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62125

Asset/Event Number	3348
Asset/Event Name	Possible burial cairn - Urchany (Allt na Criche)
Type of Asset/Event	Burial Cairn?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62126
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245822
Northing	845633
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62126

Asset/Event Number	3349

Asset/Event Name	Burial cairn - Urchany (Allt na Criche)
Type of Asset/Event	Burial Cairn?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62127
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245490
Northing	845324
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62127

Asset/Event Number	3350
Asset/Event Name	Burial cairn - Urchany (Allt na Criche)
Type of Asset/Event	Burial Cairn?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62128
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245380
Northing	845477
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62128

Asset/Event Number	3351
Asset/Event Name	Burial cairn - Urchany (Allt na Criche)
Type of Asset/Event	Burial Cairn?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62129
Status	Non-designated Heritage Asset
Section:	N/A

Easting	245476
Northing	845553
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62129

Asset/Event Number	3352
Asset/Event Name	Burial cairn - Urchany (Allt na Criche)
Type of Asset/Event	Burial Cairn?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62130
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245460
Northing	845573
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62130

Asset/Event Number	3353
Asset/Event Name	Burial cairn - Urchany (Allt na Criche)
Type of Asset/Event	Burial Cairn?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62131
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245465
Northing	845573
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62131

Asset/Event Number	3354
Asset/Event Name	Pit - Urchany (Allt na Criche)
Type of Asset/Event	Pit
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62132
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245137
Northing	845712
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62132

Asset/Event Number	3355
Asset/Event Name	Recessed platform with revetment wall - Urchany (Allt na Criche)
Type of Asset/Event	Platform; Revetment
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62133
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245344
Northing	845518
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62133

Asset/Event Number	3356
Asset/Event Name	Recessed platform - Urchany (Allt na Criche)
Type of Asset/Event	Platform
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>

HER Number	MHG62134
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245589
Northing	845522
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62134

Asset/Event Number	3357
Asset/Event Name	Clearance cairn - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62115
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245576
Northing	845528
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62115

Asset/Event Number	3358
Asset/Event Name	Kiln - Urchany (Allt na Criche)
Type of Asset/Event	Lime Kiln?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62135
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245548
Northing	845560
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62135

Asset/Event Number	3359
Asset/Event Name	Well- Urchany (Allt na Criche)
Type of Asset/Event	Well
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62136
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245590
Northing	845555
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62136

Asset/Event Number	3360
Asset/Event Name	Lime kiln - Urchany (Allt na Criche)
Type of Asset/Event	Lime Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62137
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245470
Northing	845400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62137

Asset/Event Number	3361
Asset/Event Name	Souterrain - Hut Circle D, Creagh Dubh, Urchany

Type of Asset/Event	Souterrain?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG44153
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245498
Northing	845463
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG44153

Asset/Event Number	3362
Asset/Event Name	Cairn - Allt na Criche, Urchany
Type of Asset/Event	Burial Cairn?; Clearance Cairn?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62139
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245642
Northing	846438
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62139

Asset/Event Number	3363
Asset/Event Name	Cairn - Allt na Criche, Urchany
Type of Asset/Event	Burial Cairn?; Clearance Cairn?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62140
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245645

Northing	846421
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62140

Asset/Event Number	3364
Asset/Event Name	Probable hut circle on recessed platform - Allt na Criche, Urchany
Type of Asset/Event	Hut Circle?; Platform
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62144
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245694
Northing	845671
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62144

Asset/Event Number	3365
Asset/Event Name	Recessed platform - Allt na Criche, Urchany
Type of Asset/Event	Platform
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG62145
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245668
Northing	845698
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62145

Asset/Event Number	3366
Asset/Event Name	Possible burial cairn- Urchany (Allt na Criche)
Type of Asset/Event	Burial Cairn?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62146
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245545
Northing	845596
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62146

Asset/Event Number	3367
Asset/Event Name	Small building, possible sheiling hut - Allt na Criche, Urchany
Type of Asset/Event	Building; Shieling Hut?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62147
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245536
Northing	845744
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62147

Asset/Event Number	3368
Asset/Event Name	Small building, possible sheiling hut - Allt na Criche, Urchany
Type of Asset/Event	Building; Shieling Hut?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62148

Status	Non-designated Heritage Asset
Section:	N/A
Easting	245237
Northing	845933
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62148

Asset/Event Number	3369
Asset/Event Name	Stone and turf building, - Allt na Criche, Urchany
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62149
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245635
Northing	845879
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62149

Asset/Event Number	3370
Asset/Event Name	Still bothy and dam - Allt na Criche, Urchany
Type of Asset/Event	Still; Bothy; Dam
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62150
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245724
Northing	846028
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62150

Asset/Event Number	3371
Asset/Event Name	Still bothy - Allt na Criche, Urchany
Type of Asset/Event	Still; Bothy
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62151
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245709
Northing	845938
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62151

Asset/Event Number	3372
Asset/Event Name	Still hut - Allt na Criche, Urchany
Type of Asset/Event	Still; Hut
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62152
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245712
Northing	845893
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62152

Asset/Event Number	3373
Asset/Event Name	Hideout or bothy - Allt na Criche, Urchany
Type of Asset/Event	Bothy; Lookout?

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62154
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245561
Northing	845867
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62154

Asset/Event Number	3374
Asset/Event Name	Farmstead, byre and enclosure - Coulnabottach, Urchany
Type of Asset/Event	Farmstead; Byre?; Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62155
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244780
Northing	845762
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62155

Asset/Event Number	3375
Asset/Event Name	Enclosure - Old Coulnabottach, Urchany
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62157
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244795
Northing	845821

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62157

Asset/Event Number	3376
Asset/Event Name	Enclosure - Old Coulnabottach, Urchany
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62156
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244843
Northing	845872
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62156

Asset/Event Number	3377
Asset/Event Name	Building - Old Coulnabottach, Urchany
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62158
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244850
Northing	845828
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62158

Asset/Event Number	3378
Asset/Event Name	Possible building - Old Coulnabottach, Urchany
Type of Asset/Event	Building?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62159
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244845
Northing	845851
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62159

Asset/Event Number	3379
Asset/Event Name	Corn drying kiln - Old Coulnabottach, Urchany
Type of Asset/Event	Corn Drying Kiln?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62160
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244821
Northing	845859
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62160

Asset/Event Number	3380
Asset/Event Name	Corn drying kiln - Old Coulnabottach, Urchany
Type of Asset/Event	Corn Drying Kiln?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62161
Status	Non-designated Heritage Asset

Section:	N/A
Easting	244792
Northing	845839
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62161

Asset/Event Number	3381
Asset/Event Name	Building - Old Coulnabottach, Urchany
Type of Asset/Event	Building?; Byre?; Enclosure?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62162
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244910
Northing	845832
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62162

Asset/Event Number	3382
Asset/Event Name	Kiln - Old Coulnabottach, Urchany
Type of Asset/Event	Kiln?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62163
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244843
Northing	845823
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG62163

Asset/Event Number	3383
Asset/Event Name	Late Victorian hydro scheme - Orrin Falls, Urray
Type of Asset/Event	Hydroelectric Power Station
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG62164
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246877
Northing	851696
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62164

Asset/Event Number	3384
Asset/Event Name	Pit - Old Coulnabottach, Urchany
Type of Asset/Event	Pit
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62165
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244924
Northing	845749
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62165

Asset/Event Number	3385
Asset/Event Name	Enclosure - Reinadoul, Urchany
Type of Asset/Event	Stock Enclosure
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG62166
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244483
Northing	845387
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62166

Asset/Event Number	3386
Asset/Event Name	Enclosure - Reinadoul, Urchany
Type of Asset/Event	Lambing Pen?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62167
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244486
Northing	845404
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62167

Asset/Event Number	3387
Asset/Event Name	Enclosure - Reinadoul, Urchany
Type of Asset/Event	Lambing Pen?; Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62168
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244251
Northing	845121
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62168

Asset/Event Number	3388
Asset/Event Name	Building - Reinadoul, Urchany
Type of Asset/Event	Building; Stone Heap
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62169
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244339
Northing	845124
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62169

Asset/Event Number	3389
Asset/Event Name	Clearance cairn - Reinadoul, Urchany
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62170
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244243
Northing	845044
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62170

Asset/Event Number	3390

Asset/Event Name	Clearance cairn - Coulnabottach, Urchany
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62171
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244966
Northing	845614
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62171

Asset/Event Number	3391
Asset/Event Name	Clearance cairn - Reinadoul, Urchany
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62172
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244161
Northing	845035
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62172

Asset/Event Number	3392
Asset/Event Name	Building - Claiginn, Urchany
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62173
Status	Non-designated Heritage Asset
Section:	N/A

Easting	244169
Northing	845473
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62173

Asset/Event Number	3393
Asset/Event Name	Building - Claiginn, Urchany
Type of Asset/Event	Building; Byre?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62174
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244160
Northing	845482
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62174

Asset/Event Number	3394
Asset/Event Name	Building - Claiginn, Urchany
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62175
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244143
Northing	845468
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62175

Asset/Event Number	3395
Asset/Event Name	Building - Claiginn, Urchany
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62176
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244140
Northing	845476
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62176

Asset/Event Number	3396
Asset/Event Name	Building or enclosure - Claiginn, Urchany
Type of Asset/Event	Building?; Enclosure?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62177
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244133
Northing	845485
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62177

Asset/Event Number	3397
Asset/Event Name	Building - Claiginn, Urchany
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG62178
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244175
Northing	845407
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62178

Asset/Event Number	3398
Asset/Event Name	Building - Claiginn, Urchany
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62179
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244282
Northing	845501
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62179

Asset/Event Number	3399
Asset/Event Name	Building/byre - Claiginn, Urchany
Type of Asset/Event	Building; Byre?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62180
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244302
Northing	845505
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62180

Asset/Event Number	3400
Asset/Event Name	Building/byre - Claiginn, Urchany
Type of Asset/Event	Building; Byre?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62181
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244306
Northing	845508
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62181

Asset/Event Number	3401
Asset/Event Name	Enclosure - Claiginn, Urchany
Type of Asset/Event	Enclosure; Burial Ground?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62182
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244302
Northing	845526
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62182

Asset/Event Number	3402
Asset/Event Name	Building - Claiginn, Urchany

Type of Asset/Event	Building; Lookout?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62183
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244012
Northing	845509
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62183

Asset/Event Number	3403
Asset/Event Name	Building - Claiginn, Urchany
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62184
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244016
Northing	845503
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62184

Asset/Event Number	3404
Asset/Event Name	Building - Claiginn, Urchany
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62185
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244247

Northing	845566
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62185

Asset/Event Number	3405
Asset/Event Name	Building - Claiginn, Urchany
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62186
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244251
Northing	845554
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62186

Asset/Event Number	3406
Asset/Event Name	Buildings - Claiginn, Urchany
Type of Asset/Event	Building; Byre?; Outbuilding?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62187
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244225
Northing	845540
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62187

Asset/Event Number	3407
Asset/Event Name	Buildings - Claiginn, Urchany
Type of Asset/Event	Building; Byre?; Outbuilding?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62188
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244296
Northing	845632
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62188

Asset/Event Number	3408
Asset/Event Name	Building - Claiginn, Urchany
Type of Asset/Event	Building; Outbuilding?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62189
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244336
Northing	845643
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62189

Asset/Event Number	3409
Asset/Event Name	Building - Claiginn, Urchany
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62190

Status	Non-designated Heritage Asset
Section:	N/A
Easting	244412
Northing	845647
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62190

Asset/Event Number	3410
Asset/Event Name	Tin Church - Contin
Type of Asset/Event	Church
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG32508
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245829
Northing	855828
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG32508

Asset/Event Number	3411
Asset/Event Name	Kiln barn, with corn-drying kiln - Claiginn, Urchany
Type of Asset/Event	Kiln Barn; Corn Drying Kiln; Threshing Barn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62193
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244213
Northing	845437
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62193

Asset/Event Number	3412
Asset/Event Name	Probable lime kiln - Claiginn, Urchany
Type of Asset/Event	Lime Kiln?; Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62194
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244270
Northing	845732
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62194

Asset/Event Number	3413
Asset/Event Name	Probable still house - Claiginn, Urchany
Type of Asset/Event	Still House?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62196
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243987
Northing	845428
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62196

Asset/Event Number	3414
Asset/Event Name	Clearance cairn - Claiginn, Urchany
Type of Asset/Event	Clearance Cairn

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62197
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244152
Northing	845461
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62197

Asset/Event Number	3415
Asset/Event Name	Clearance cairn - Claiginn, Urchany
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62198
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244141
Northing	845440
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62198

Asset/Event Number	3416
Asset/Event Name	Clearance cairn - Claiginn, Urchany
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62199
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244222
Northing	845669

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62199

Asset/Event Number	3417
Asset/Event Name	Clearance cairn - Claiginn, Urchany
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62200
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244307
Northing	845633
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62200

Asset/Event Number	3418
Asset/Event Name	Clearance cairn - Claiginn, Urchany
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62201
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244171
Northing	845378
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62201

Asset/Event Number	3419
Asset/Event Name	Clearance cairn - Claiginn, Urchany
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62202
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244069
Northing	845301
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62202

Asset/Event Number	3420
Asset/Event Name	Clearance cairn - Claiginn, Urchany
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62203
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244289
Northing	845548
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62203

Asset/Event Number	3421
Asset/Event Name	Clearance cairn - Claiginn, Urchany
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62204
Status	Non-designated Heritage Asset

Section:	N/A
Easting	244370
Northing	845542
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62204

Asset/Event Number	3422
Asset/Event Name	Clearance cairn - Claiginn, Urchany
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62205
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244293
Northing	845500
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62205

Asset/Event Number	3423
Asset/Event Name	Clearance cairn - Claiginn, Urchany
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62206
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244103
Northing	845370
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG62206

Asset/Event Number	3424
Asset/Event Name	Clearance cairn - Claiginn, Urchany
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62207
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244105
Northing	845390
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62207

Asset/Event Number	3425
Asset/Event Name	Farmstead building - Gillie Phaeton, Breakachy Burn, Urchany
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG22965
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243985
Northing	844655
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22965

Asset/Event Number	3426
Asset/Event Name	Farmstead building - Gillie Phaeton, Breakachy Burn, Urchany
Type of Asset/Event	Building
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG62208
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244007
Northing	844670
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62208

Asset/Event Number	3427
Asset/Event Name	Dwelling with outbuildings - Chisholm Land, Breakachy Burn, Urchany
Type of Asset/Event	Building; Outbuilding
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62209
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244106
Northing	844508
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62209

Asset/Event Number	3428
Asset/Event Name	Building - Chisholm Land, Breakachy Burn, Urchany
Type of Asset/Event	Building; Threshing Barn?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG22908
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244314
Northing	844439
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22908

Asset/Event Number	3429
Asset/Event Name	Kiln - Chisholm Land, Breakachy Burn, Urchany
Type of Asset/Event	Corn Drying Kiln?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62211
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244309
Northing	844437
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62211

Asset/Event Number	3430
Asset/Event Name	Enclosure - Chisholm Land, Breakachy Burn, Urchany
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62210
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244330
Northing	844450
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62210

Asset/Event Number	3431

Asset/Event Name	Shelter, lookout or pen - Chisholm Land, Breakachy Burn, Urchany
Type of Asset/Event	Structure; Shelter?; Pen?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62212
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244300
Northing	844661
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62212

Asset/Event Number	3432
Asset/Event Name	Animal enclosure - Gillie Phaeton, Breakachy Burn, Urchany
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62213
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243969
Northing	844730
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62213

Asset/Event Number	3433
Asset/Event Name	Probable lime kiln - Gillie Phaeton, Breakachy Burn, Urchany
Type of Asset/Event	Pit; Lime Kiln?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62214
Status	Non-designated Heritage Asset
Section:	N/A

Easting	243988
Northing	844672
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62214

Asset/Event Number	3434
Asset/Event Name	Lime kiln - Chisholm Land, Breakachy Burn, Urchany
Type of Asset/Event	Lime Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62215
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244172
Northing	844619
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62215

Asset/Event Number	3435
Asset/Event Name	Possible lime kiln - Gillie Phaeton, Breakachy Burn, Urchany
Type of Asset/Event	Lime Kiln?; Pit
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62216
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244066
Northing	844877
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62216

Asset/Event Number	3436
Asset/Event Name	Clearance cairn - Gillie Phaeton, Breakachy Burn, Urchany
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62217
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244001
Northing	844885
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62217

Asset/Event Number	3437
Asset/Event Name	Clearance cairn - Gillie Phaeton, Breakachy Burn, Urchany
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62218
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243998
Northing	844656
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62218

Asset/Event Number	3438
Asset/Event Name	Clearance cairn - Gillie Phaeton, Breakachy Burn, Urchany
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG62219
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244010
Northing	844662
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62219

Asset/Event Number	3439
Asset/Event Name	Clearance cairn - Gillie Phaeton, Breakachy Burn, Urchany
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62220
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243950
Northing	844700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62220

Asset/Event Number	3440
Asset/Event Name	Clearance cairn - Gillie Phaeton, Breakachy Burn, Urchany
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62221
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244082
Northing	844911
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62221

Asset/Event Number	3441
Asset/Event Name	Clearance cairn - Gillie Phaeton, Breakachy Burn, Urchany
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62222
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244125
Northing	844886
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62222

Asset/Event Number	3442
Asset/Event Name	Clearance cairn - Gillie Phaeton, Breakachy Burn, Urchany
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62223
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244125
Northing	844894
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62223

Asset/Event Number	3443
Asset/Event Name	Cup-marked Stone - Breakachy Burn, Urchany (4)

Type of Asset/Event	Cup Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62226
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244235
Northing	845368
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62226

Asset/Event Number	3444
Asset/Event Name	Cup Marked Stone - Coulnabottach, Urchany (6)
Type of Asset/Event	Cup Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62227
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244695
Northing	845689
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62227

Asset/Event Number	3445
Asset/Event Name	Cup-marked stone - Coulnabottach, Urchany (Urchany 1)
Type of Asset/Event	Cup Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG2650
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244799

Northing	845769
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG2650

Asset/Event Number	3446
Asset/Event Name	Township - Claiginn, Urchany
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23302
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244206
Northing	845465
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23302

Asset/Event Number	3447
Asset/Event Name	Marrel
Type of Asset/Event	Crofting Township; Head Dyke; Field System
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG20258
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301889
Northing	916876
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG20258

Asset/Event Number	3448
Asset/Event Name	Cairn, Cnoc Udais
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG7099
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248090
Northing	849831
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7099

Asset/Event Number	3449
Asset/Event Name	Field system - Cnoc Croit Na Maoile
Type of Asset/Event	Field System; Clearance Cairn; Enclosure
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG43081
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249098
Northing	848983
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG43081

Asset/Event Number	3450
Asset/Event Name	Hut circle - Cnoc Croit Na Maoile
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG7102

Status	Non-designated Heritage Asset
Section:	N/A
Easting	249170
Northing	848954
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7102

Asset/Event Number	3451
Asset/Event Name	Walled garden - Nutwood, Strathpeffer
Type of Asset/Event	Walled Garden
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248394
Northing	858619
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62267

Asset/Event Number	3452
Asset/Event Name	Nutwood House - Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG55623
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248442
Northing	858598
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55623

Asset/Event Number	3453
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3454
Asset/Event Name	Dyke - west of Orrin Power Station, Urray
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG55909
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243405
Northing	854493
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55909

Asset/Event Number	3455
Asset/Event Name	Possible boundary dyke - NW of Cnoc, Liatair
Type of Asset/Event	Boundary Dyke?

Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62270
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243199
Northing	852899
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62270

Asset/Event Number	3456
Asset/Event Name	Oval earthwork, possible shooting butt - W of Creag Mhor
Type of Asset/Event	Enclosure?; Shooting Stand?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62271
Status	Non-designated Heritage Asset
Section:	N/A
Easting	242688
Northing	853561
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62271

Asset/Event Number	3457
Asset/Event Name	Valve House - Orrin
Type of Asset/Event	Valve House
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG58728
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243594
Northing	854208

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG58728

Asset/Event Number	3458
Asset/Event Name	Possible farmstead - Cul Beg
Type of Asset/Event	Farmstead?; Rig And Furrow?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62277
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245410
Northing	851029
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62277

Asset/Event Number	3459
Asset/Event Name	Possible farmstead? - S of Allt Goibhre
Type of Asset/Event	Farmstead?; Building; Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62284
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246077
Northing	849743
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62284

Asset/Event Number	3460
Asset/Event Name	Farmstead or small settlement? - N of Allt Goibhre
Type of Asset/Event	Farmstead?; Building; Enclosure; Settlement?; Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62285
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246644
Northing	850362
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62285

Asset/Event Number	3461
Asset/Event Name	Possible hut circle - Allt Goibhre
Type of Asset/Event	Hut Circle?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62287
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246483
Northing	850265
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62287

Asset/Event Number	3462
Asset/Event Name	Cottages - Spittal Mains
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG186
Status	Non-designated Heritage Asset

Section:	N/A
Easting	316681
Northing	954359
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG186

Asset/Event Number	3463
Asset/Event Name	Hut circle - Cnoc Udais
Type of Asset/Event	Hut Circle; Building
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8302
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248591
Northing	849694
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8302

Asset/Event Number	3464
Asset/Event Name	Dyked enclosure - Spittal, Caithness
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62306
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316629
Northing	955283
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG62306

Asset/Event Number	3465
Asset/Event Name	Farmstead - Spittal Hill
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG19149
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316565
Northing	955140
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19149

Asset/Event Number	3466
Asset/Event Name	Farmstead - Toftinghall
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62307
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317340
Northing	954442
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62307

Asset/Event Number	3467
Asset/Event Name	Farmstead - Spittal Hill
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG19151
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315886
Northing	955457
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG19151

Asset/Event Number	3468
Asset/Event Name	Still bothy - Loch nam Bonnach
Type of Asset/Event	Bothy
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62333
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247476
Northing	847737
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62333

Asset/Event Number	3469
Asset/Event Name	Possible hut circle - near Loch Nam Bonnach
Type of Asset/Event	Hut Circle?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62334
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247161
Northing	847952
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62334

Asset/Event Number	3470
Asset/Event Name	Shieling huts and associated features - near Loch Nam Bonnach
Type of Asset/Event	Shieling Hut?; Platform?; Dairy?; Shieling Settlement?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62335
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247140
Northing	847972
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62335

Asset/Event Number	3471
Asset/Event Name	Burnt Mound - Kilearnan
Type of Asset/Event	Burnt Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9877
Status	Non-designated Heritage Asset
Section:	N/A
Easting	295346
Northing	917479
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9877

Asset/Event Number	3472

Asset/Event Name	Burnt Mound - Kilearnan
Type of Asset/Event	Burnt Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62354
Status	Non-designated Heritage Asset
Section:	N/A
Easting	294927
Northing	918186
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62354

Asset/Event Number	3473
Asset/Event Name	Burnt Mound - Kilearnan
Type of Asset/Event	Burnt Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG11361
Status	Non-designated Heritage Asset
Section:	N/A
Easting	294928
Northing	918148
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG11361

Asset/Event Number	3474
Asset/Event Name	Military road - Torrachility Forest
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG54625
Status	Non-designated Heritage Asset
Section:	N/A

Easting	245141
Northing	857783
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54625

Asset/Event Number	3475
Asset/Event Name	Cup and ring marked stone - Clash Vaan Croft, Heights of Fodderty
Type of Asset/Event	Cup And Ring Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG55106
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251060
Northing	860714
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55106

Asset/Event Number	3476
Asset/Event Name	Commemorative Stone - Contin
Type of Asset/Event	Commemorative Stone
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG59082
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245871
Northing	855784
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG59082

Asset/Event Number	3477
Asset/Event Name	Still Bothy - Allt na Crionnaiche
Type of Asset/Event	Still House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62528
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245041
Northing	849994
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62528

Asset/Event Number	3478
Asset/Event Name	Watermill/sawmill - Contin
Type of Asset/Event	Watermill; Timber Mill
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG21722
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245935
Northing	855598
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG21722

Asset/Event Number	3479
Asset/Event Name	Cornmill - Contin
Type of Asset/Event	Corn Mill; Watermill
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG62537
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245960
Northing	855564
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62537

Asset/Event Number	3480
Asset/Event Name	Contin Manse Bridge - Contin
Type of Asset/Event	Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG7859
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245946
Northing	855563
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7859

Asset/Event Number	3481
Asset/Event Name	Lade - Contin
Type of Asset/Event	Lade
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62538
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245912
Northing	855632
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62538

Asset/Event Number	3482
Asset/Event Name	Farm steading - Redburn
Type of Asset/Event	Steading
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG22354
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257163
Northing	867035
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG22354

Asset/Event Number	3483
Asset/Event Name	Cultivation remains/furrows - Cul Beag/Allt na Crionaiche
Type of Asset/Event	Cultivation Remains
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62674
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245369
Northing	849975
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62674

Asset/Event Number	3484
Asset/Event Name	Platform - Cul Beag/Allt na Crionaiche

Type of Asset/Event	Platform; Building?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62675
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245375
Northing	849952
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62675

Asset/Event Number	3485
Asset/Event Name	Hut circle - Strath Sgitheach
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62693
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252547
Northing	863277
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62693

Asset/Event Number	3486
Asset/Event Name	Hut circle - Strath Sgitheach
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62696
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252483

Northing	863287
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62696

Asset/Event Number	3487
Asset/Event Name	Hut circle - Strath Sgitheach
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62697
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252107
Northing	863397
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62697

Asset/Event Number	3488
Asset/Event Name	Hut circle - Strath Sgitheach
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62698
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252295
Northing	863480
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62698

Asset/Event Number	3489
Asset/Event Name	Hut circle - Strath Sgitheach
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62699
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252457
Northing	863357
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62699

Asset/Event Number	3490
Asset/Event Name	Farmstead - Strath Sgitheach
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62701
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252443
Northing	863468
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62701

Asset/Event Number	3491
Asset/Event Name	Corn-drying kiln - Strath Sgitheach
Type of Asset/Event	Corn Drying Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62702

Status	Non-designated Heritage Asset
Section:	N/A
Easting	252453
Northing	863480
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62702

Asset/Event Number	3492
Asset/Event Name	Farmstead - Strath Sgitheach
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62703
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252002
Northing	863419
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62703

Asset/Event Number	3493
Asset/Event Name	Enclosure - Strath Sgitheach
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62704
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252174
Northing	863027
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62704

Asset/Event Number	3494
Asset/Event Name	Dam - Strath Sgitheach
Type of Asset/Event	Dam
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62705
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252742
Northing	863041
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62705

Asset/Event Number	3495
Asset/Event Name	Enclosure - Strath Sgitheach
Type of Asset/Event	Enclosure; Pond?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62706
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252219
Northing	863365
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62706

Asset/Event Number	3496
Asset/Event Name	Kerb Cairn - Strath Sgitheach
Type of Asset/Event	Kerb Cairn

Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8902
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252347
Northing	863986
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8902

Asset/Event Number	3497
Asset/Event Name	Hut circle - Glac Bhan
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62710
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254046
Northing	863768
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62710

Asset/Event Number	3498
Asset/Event Name	Hut circle - Glac Bhan
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62711
Status	Non-designated Heritage Asset
Section:	N/A
Easting	254067
Northing	863719

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62711

Asset/Event Number	3499
Asset/Event Name	Hut circle - Glac Bhan
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8927
Status	Non-designated Heritage Asset
Section:	N/A
Easting	253878
Northing	863726
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8927

Asset/Event Number	3500
Asset/Event Name	Hut circle - Glac Bhan
Type of Asset/Event	Hut Circle?; Enclosure?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62712
Status	Non-designated Heritage Asset
Section:	N/A
Easting	253954
Northing	863653
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62712

Asset/Event Number	3501
Asset/Event Name	Hut circle - Ausdale, NE of Bonar Bridge
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62729
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263170
Northing	895678
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62729

Asset/Event Number	3502
Asset/Event Name	Possible hut circle - Leathad A' Chuailein
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62730
Status	Non-designated Heritage Asset
Section:	N/A
Easting	265519
Northing	896296
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62730

Asset/Event Number	3503
Asset/Event Name	Possible hut circle - Leathad A' Chuailein
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62731
Status	Non-designated Heritage Asset

Section:	N/A
Easting	265354
Northing	896387
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62731

Asset/Event Number	3504
Asset/Event Name	Possible hut circle - E of Sleastary
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62732
Status	Non-designated Heritage Asset
Section:	N/A
Easting	264811
Northing	896520
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62732

Asset/Event Number	3505
Asset/Event Name	Possible hut circle - E of Sleastary
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62733
Status	Non-designated Heritage Asset
Section:	N/A
Easting	264822
Northing	896532
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG62733

Asset/Event Number	3506
Asset/Event Name	Possible hut circle - E of Sleastary
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62734
Status	Non-designated Heritage Asset
Section:	N/A
Easting	264831
Northing	896376
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62734

Asset/Event Number	3507
Asset/Event Name	Possible hut circle - E of Sleastary
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62735
Status	Non-designated Heritage Asset
Section:	N/A
Easting	264851
Northing	896337
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62735

Asset/Event Number	3508
Asset/Event Name	Two hut circles - E of Sleastary
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric

Listing No./NRHE Number	<Null>
HER Number	MHG62736
Status	Non-designated Heritage Asset
Section:	N/A
Easting	264532
Northing	896372
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62736

Asset/Event Number	3509
Asset/Event Name	Hut circle - Sleastary
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62737
Status	Non-designated Heritage Asset
Section:	N/A
Easting	264234
Northing	896537
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62737

Asset/Event Number	3510
Asset/Event Name	Possible hut circle - Sleastary
Type of Asset/Event	Hut Circle?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62738
Status	Non-designated Heritage Asset
Section:	N/A
Easting	264213
Northing	896541
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62738

Asset/Event Number	3511
Asset/Event Name	Hut circle - N of Sleastary
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62739
Status	Non-designated Heritage Asset
Section:	N/A
Easting	264182
Northing	896632
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62739

Asset/Event Number	3512
Asset/Event Name	Hut circle - N of Sleastary
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62740
Status	Non-designated Heritage Asset
Section:	N/A
Easting	264210
Northing	896640
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62740

Asset/Event Number	3513

Asset/Event Name	Hut circle - Rosebank Cottage, Culrain
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG9177
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256944
Northing	894448
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG9177

Asset/Event Number	3514
Asset/Event Name	Clearance cairns - Rosebank Cottage, Culrain
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62765
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256929
Northing	894478
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62765

Asset/Event Number	3515
Asset/Event Name	Enclosure - Culrain
Type of Asset/Event	Enclosure
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG62767
Status	Non-designated Heritage Asset
Section:	N/A

Easting	257433
Northing	894978
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62767

Asset/Event Number	3516
Asset/Event Name	Farmhouse - Tighnaleac, Breakachy
Type of Asset/Event	Farmhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62790
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246072
Northing	844505
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62790

Asset/Event Number	3517
Asset/Event Name	Buildings - Tighnaleac, Breakachy
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62791
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246079
Northing	844427
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62791

Asset/Event Number	3518
Asset/Event Name	Kiln barn - Tighnaleac, Breakachy
Type of Asset/Event	Kiln Barn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62792
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246091
Northing	844386
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62792

Asset/Event Number	3519
Asset/Event Name	Building - Tighnaleac, Breakachy
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62793
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246039
Northing	844388
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62793

Asset/Event Number	3520
Asset/Event Name	Building - Tighnaleac, Breakachy
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG62794
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246007
Northing	844194
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62794

Asset/Event Number	3521
Asset/Event Name	Building - Tighnaleac, Breakachy
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62795
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245990
Northing	844202
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62795

Asset/Event Number	3522
Asset/Event Name	Building - Breakachy
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23318
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245816
Northing	844381
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23318

Asset/Event Number	3523
Asset/Event Name	Farmstead - Breakachy
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23307
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245987
Northing	844651
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23307

Asset/Event Number	3524
Asset/Event Name	Farmstead - Breakachy
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62796
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245892
Northing	844672
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62796

Asset/Event Number	3525
Asset/Event Name	Building - near Tighnaleac, Breakachy

Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62797
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246014
Northing	844902
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62797

Asset/Event Number	3526
Asset/Event Name	Building and enclosure - near Tighnaleac, Breakachy
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62798
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246190
Northing	845028
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62798

Asset/Event Number	3527
Asset/Event Name	Building - near Tighnaleac, Breakachy
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62799
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246228

Northing	844921
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62799

Asset/Event Number	3528
Asset/Event Name	Farmstead - Breakachy
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG23306
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246289
Northing	844853
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG23306

Asset/Event Number	3529
Asset/Event Name	Building - near Tighnaleac, Breakachy
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62800
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246240
Northing	845131
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62800

Asset/Event Number	3530
Asset/Event Name	Building - near Tighnaleac, Breakachy
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62801
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246079
Northing	845051
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62801

Asset/Event Number	3531
Asset/Event Name	Building - near Tighnaleac, Breakachy
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62802
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246014
Northing	844812
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62802

Asset/Event Number	3532
Asset/Event Name	Corn drying kiln - near Tighnaleac, Breakachy
Type of Asset/Event	Building; Corn Drying Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62803

Status	Non-designated Heritage Asset
Section:	N/A
Easting	245979
Northing	844692
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62803

Asset/Event Number	3533
Asset/Event Name	Building - Breakachy Burn, Strath Glass
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62826
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246260
Northing	845490
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62826

Asset/Event Number	3534
Asset/Event Name	Clearance or burial cairn - Breakachy Burn, Strath Glass
Type of Asset/Event	Clearance Cairn?; Burial Cairn?
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG62827
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245944
Northing	845634
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62827

Asset/Event Number	3535
Asset/Event Name	Clearance or burial cairn - Breakachy Burn, Strath Glass
Type of Asset/Event	Clearance Cairn?; Burial Cairn?
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG62828
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245838
Northing	845622
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62828

Asset/Event Number	3536
Asset/Event Name	Hut circle - Breakachy Burn, Strath Glass
Type of Asset/Event	Hut Circle?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62829
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246003
Northing	845673
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62829

Asset/Event Number	3537
Asset/Event Name	Hut circle or enclosure - Breakachy Burn, Strath Glass
Type of Asset/Event	Hut Circle?; Enclosure?

Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62830
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246720
Northing	846179
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62830

Asset/Event Number	3538
Asset/Event Name	Enclosure - Kiltarlity Cottages
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG14545
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249345
Northing	844016
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG14545

Asset/Event Number	3539
Asset/Event Name	Field system - Cnoc Alasdair
Type of Asset/Event	Field System; Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG38974
Status	Non-designated Heritage Asset
Section:	N/A
Easting	259387
Northing	872983

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG38974

Asset/Event Number	3540
Asset/Event Name	Sheep fold - W of Loch Buidhe
Type of Asset/Event	Sheep Fold?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62913
Status	Non-designated Heritage Asset
Section:	N/A
Easting	264983
Northing	898533
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62913

Asset/Event Number	3541
Asset/Event Name	Sheep fold - SW of Loch Buidhe
Type of Asset/Event	Sheep Fold?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62914
Status	Non-designated Heritage Asset
Section:	N/A
Easting	265067
Northing	898206
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62914

Asset/Event Number	3542
Asset/Event Name	Field system - Dun-Garbh-Airigh
Type of Asset/Event	Field System
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG40419
Status	Non-designated Heritage Asset
Section:	N/A
Easting	264595
Northing	898753
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG40419

Asset/Event Number	3543
Asset/Event Name	Hut circle - Dun-Garbh-Airigh 'A'
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG10324
Status	Non-designated Heritage Asset
Section:	N/A
Easting	264357
Northing	898853
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG10324

Asset/Event Number	3544
Asset/Event Name	Hut circle - Dun-Garbh-Airigh 'B'
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62915
Status	Non-designated Heritage Asset

Section:	N/A
Easting	264549
Northing	898723
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62915

Asset/Event Number	3545
Asset/Event Name	Hut circle - Dun-Garbh-Airigh 'C'
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62916
Status	Non-designated Heritage Asset
Section:	N/A
Easting	264641
Northing	898703
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62916

Asset/Event Number	3546
Asset/Event Name	Enclosure - Ruttle Wood.
Type of Asset/Event	Enclosure; Cairn?
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG62933
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248165
Northing	844081
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG62933

Asset/Event Number	3547
Asset/Event Name	Cairn - south of Cnoc a' Chinn.
Type of Asset/Event	Cairnfield
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG62954
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249500
Northing	843900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62954

Asset/Event Number	3548
Asset/Event Name	Earthwork - Lonbuie Wood
Type of Asset/Event	Earthwork
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG62964
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248042
Northing	842400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62964

Asset/Event Number	3549
Asset/Event Name	Building - Lonbuie Wood
Type of Asset/Event	Building
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG62965
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248061
Northing	842422
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62965

Asset/Event Number	3550
Asset/Event Name	Stone bank - Beaufort
Type of Asset/Event	Bank (Earthwork)
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG62969
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249896
Northing	843364
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62969

Asset/Event Number	3551
Asset/Event Name	Bothy - Lonbuie Wood.
Type of Asset/Event	Bothy
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62978
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249400
Northing	841700
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62978

Asset/Event Number	3552
Asset/Event Name	Hut circle - Lonbuie Wood.
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62983
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249208
Northing	841816
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62983

Asset/Event Number	3553
Asset/Event Name	Turf wall and dyke - Fanellan
Type of Asset/Event	Wall; Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62985
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249600
Northing	843300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62985

Asset/Event Number	3554

Asset/Event Name	Stone dyke - Fanellan
Type of Asset/Event	Wall; Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62986
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249600
Northing	842900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62986

Asset/Event Number	3555
Asset/Event Name	Bothy - Lonbuie Wood.
Type of Asset/Event	Bothy
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62998
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249500
Northing	841800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62998

Asset/Event Number	3556
Asset/Event Name	Cairnfield - Culburnie
Type of Asset/Event	Cairnfield
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG63000
Status	Non-designated Heritage Asset
Section:	N/A

Easting	248200
Northing	841300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63000

Asset/Event Number	3557
Asset/Event Name	Linear earthwork - Fanellan Wood
Type of Asset/Event	Linear Earthwork
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG63008
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249271
Northing	842429
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63008

Asset/Event Number	3558
Asset/Event Name	Possible standing stone - Culburnie
Type of Asset/Event	Standing Stone?; Wall
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG63009
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248500
Northing	841598
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63009

Asset/Event Number	3559
Asset/Event Name	Sunken road or track - Fanellan
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG63016
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249500
Northing	843301
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63016

Asset/Event Number	3560
Asset/Event Name	Cairns - Fanellan
Type of Asset/Event	Cairn
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG63018
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249482
Northing	843083
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63018

Asset/Event Number	3561
Asset/Event Name	Township - Sleastary (Sleasdairidh)
Type of Asset/Event	Township
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG18352
Status	Non-designated Heritage Asset
Section:	N/A
Easting	264363
Northing	896414
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG18352

Asset/Event Number	3562
Asset/Event Name	Shelter - Ardnagrask
Type of Asset/Event	Shelter
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG63027
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249623
Northing	848460
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63027

Asset/Event Number	3563
Asset/Event Name	Dyke - near Loch Bhuide
Type of Asset/Event	Boundary Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG63032
Status	Non-designated Heritage Asset
Section:	N/A
Easting	264699
Northing	897569
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63032

Asset/Event Number	3564
Asset/Event Name	Dyke - near Loch Bhuide
Type of Asset/Event	Boundary Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG63033
Status	Non-designated Heritage Asset
Section:	N/A
Easting	264964
Northing	898137
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63033

Asset/Event Number	3565
Asset/Event Name	Boulder wall - Culbirnie Muir
Type of Asset/Event	Wall
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG63048
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248904
Northing	841576
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63048

Asset/Event Number	3566
Asset/Event Name	Mound - Culbirnie Muir

Type of Asset/Event	Mound
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG63049
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248939
Northing	841661
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63049

Asset/Event Number	3567
Asset/Event Name	Still - Dun Garbhlaich
Type of Asset/Event	Still House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG63082
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246359
Northing	846573
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63082

Asset/Event Number	3568
Asset/Event Name	Still - Dun Garbhlaich
Type of Asset/Event	Still House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG63083
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246452

Northing	846348
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63083

Asset/Event Number	3569
Asset/Event Name	Hut circle or enclosure - Dun Garbhlaich
Type of Asset/Event	Hut Circle?; Enclosure?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG63084
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246503
Northing	846300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63084

Asset/Event Number	3570
Asset/Event Name	Shelter or enclosure - Dun Garbhlaich
Type of Asset/Event	Shelter; Enclosure
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG63085
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246609
Northing	846369
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63085

Asset/Event Number	3571
Asset/Event Name	Cup marked stone - A Clach Phollach (Achterneed Wood 1)
Type of Asset/Event	Cup Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG7775
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249226
Northing	859701
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG7775

Asset/Event Number	3572
Asset/Event Name	Cup Marked Stone - Strath Sgitheach Allt Na Criche (1)
Type of Asset/Event	Cup Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG8926
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252221
Northing	862919
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG8926

Asset/Event Number	3573
Asset/Event Name	Hut circles - Buoldhu
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG13583

Status	Non-designated Heritage Asset
Section:	N/A
Easting	314863
Northing	934921
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG13583

Asset/Event Number	3574
Asset/Event Name	Cup Marked Stone - Strath Sgitheach Allt Na Criche (2)
Type of Asset/Event	Cup Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG63114
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252130
Northing	862977
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63114

Asset/Event Number	3575
Asset/Event Name	Cup-marked Stone (Urchany 2) - Breakachy Burn, Urchany
Type of Asset/Event	Cup Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62224
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244278
Northing	845611
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62224

Asset/Event Number	3576
Asset/Event Name	Cup and ring marked stone - Heights of Fodderty (2)
Type of Asset/Event	Cup And Ring Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG63142
Status	Non-designated Heritage Asset
Section:	N/A
Easting	250833
Northing	860844
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63142

Asset/Event Number	3577
Asset/Event Name	Cup marked stone - A Clach Phollach (Achterneed Wood 2)
Type of Asset/Event	Cup Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG63148
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249200
Northing	859734
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63148

Asset/Event Number	3578
Asset/Event Name	Cup Marked Stone - Strath Sgitheach Allt Na Criche (3)
Type of Asset/Event	Cup Marked Stone

Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG63161
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252123
Northing	862974
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63161

Asset/Event Number	3579
Asset/Event Name	Cup-marked Stone - Breakachy Burn, Urchany (3)
Type of Asset/Event	Cup Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG62225
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244274
Northing	845613
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62225

Asset/Event Number	3580
Asset/Event Name	Cup marked stone - Heights of Fodderty (3)
Type of Asset/Event	Cup Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG63168
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251143
Northing	860803

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63168

Asset/Event Number	3581
Asset/Event Name	Cup Marked Stone - Strath Sgitheach Allt Na Criche (5)
Type of Asset/Event	Cup Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG63172
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252019
Northing	862980
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63172

Asset/Event Number	3582
Asset/Event Name	Cup Marked Stone - Strath Sgitheach Allt Na Criche (6)
Type of Asset/Event	Cup Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG63175
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252013
Northing	863010
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63175

Asset/Event Number	3583
Asset/Event Name	Cup Marked Stone - Breakachy Burn, Urchany (5)
Type of Asset/Event	Cup Marked Stone?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG63178
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244272
Northing	845610
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63178

Asset/Event Number	3584
Asset/Event Name	Cup Marked Stone - Strath Sgitheach Allt Na Criche (8)
Type of Asset/Event	Cup Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG63187
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252483
Northing	862943
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63187

Asset/Event Number	3585
Asset/Event Name	Cup marked stone at a Ring cairn - Culburnie
Type of Asset/Event	Cup Marked Stone?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG63203
Status	Non-designated Heritage Asset

Section:	N/A
Easting	249184
Northing	841799
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63203

Asset/Event Number	3586
Asset/Event Name	Strath Lunndaidh
Type of Asset/Event	Head Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG41961
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256523
Northing	869098
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG41961

Asset/Event Number	3587
Asset/Event Name	Estate Track and Borrow Pit, Gilbert's Hill
Type of Asset/Event	Trackway; Quarry
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG53869
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256762
Northing	869092
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG53869

Asset/Event Number	3588
Asset/Event Name	Boundary wall, Rogie
Type of Asset/Event	Boundary Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG54339
Status	Non-designated Heritage Asset
Section:	N/A
Easting	278411
Northing	901259
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54339

Asset/Event Number	3589
Asset/Event Name	Boundary wall, Rogie
Type of Asset/Event	Boundary Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG54343
Status	Non-designated Heritage Asset
Section:	N/A
Easting	273882
Northing	904128
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54343

Asset/Event Number	3590
Asset/Event Name	Standing stone, Halsary Moss
Type of Asset/Event	Standing Stone
Date and/or Period	Prehistoric

Listing No./NRHE Number	<Null>
HER Number	MHG1273
Status	Scheduled Monument
Section:	N/A
Easting	317731
Northing	949653
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5301

Asset/Event Number	3591
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3592
Asset/Event Name	Camster, Caithness Central Belt
Type of Asset/Event	Site
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG45940
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320000
Northing	940000
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG45940

Asset/Event Number	3593
Asset/Event Name	Cawdearg, Weaving Shed
Type of Asset/Event	Site; Weaving Shed
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG46729
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256271
Northing	891163
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG46729

Asset/Event Number	3594
Asset/Event Name	Contin Mains
Type of Asset/Event	Site; Non Antiquity
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG47485
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246530
Northing	855010
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG47485

Asset/Event Number	3595

Asset/Event Name	Fairburn House, Strathan
Type of Asset/Event	Site; Estate Building
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG48424
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245272
Northing	852540
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48424

Asset/Event Number	3596
Asset/Event Name	West Beauly Water Mains
Type of Asset/Event	Site
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG48645
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247300
Northing	844880
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48645

Asset/Event Number	3597
Asset/Event Name	Hotspot Group 6 Water Mains
Type of Asset/Event	Site
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG48648
Status	Non-designated Heritage Asset
Section:	N/A

Easting	257160
Northing	894600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG48648

Asset/Event Number	3598
Asset/Event Name	Dunbeath, Tohorrie
Type of Asset/Event	Site
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG49964
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315420
Northing	930860
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG49964

Asset/Event Number	3599
Asset/Event Name	New Black Croft, Lower Smerral
Type of Asset/Event	Crofthouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG51227
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317426
Northing	934222
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG51227

Asset/Event Number	3600
Asset/Event Name	Croft, Braehungie
Type of Asset/Event	Crofthouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG51236
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318442
Northing	937758
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG51236

Asset/Event Number	3601
Asset/Event Name	CULRAIN
Type of Asset/Event	Bungalow
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG51697
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257400
Northing	894700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG51697

Asset/Event Number	3602
Asset/Event Name	Old School,Evanton
Type of Asset/Event	School
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG52738
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256919
Northing	867212
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG52738

Asset/Event Number	3603
Asset/Event Name	Steading Byre
Type of Asset/Event	Byre
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG52739
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257045
Northing	890710
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG52739

Asset/Event Number	3604
Asset/Event Name	The Bungalow
Type of Asset/Event	Bungalow
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG52740
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257047
Northing	890738
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG52740

Asset/Event Number	3605
Asset/Event Name	Farmstead, Houstry Road
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG52813
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315747
Northing	931380
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG52813

Asset/Event Number	3606
Asset/Event Name	Farmstead
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG52814
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315883
Northing	932271
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG52814

Asset/Event Number	3607
Asset/Event Name	Findspot of mortar or grinding stone, 19 Culburnie

Type of Asset/Event	Findspot
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG52990
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249154
Northing	841808
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG52990

Asset/Event Number	3608
Asset/Event Name	Berriedale, Langwell, Home Guard 'secret Hideout'
Type of Asset/Event	Observation Post
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG53203
Status	Non-designated Heritage Asset
Section:	N/A
Easting	309270
Northing	922520
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53203

Asset/Event Number	3609
Asset/Event Name	Cup marked stone, Fodderty
Type of Asset/Event	Cup Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG53626
Status	Non-designated Heritage Asset
Section:	N/A
Easting	250690

Northing	860990
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53626

Asset/Event Number	3610
Asset/Event Name	Hut circle, Gilbert's Hill
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG53866
Status	Non-designated Heritage Asset
Section:	N/A
Easting	284345
Northing	907293
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53866

Asset/Event Number	3611
Asset/Event Name	Cairn, Gilbert's Hill
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG53867
Status	Non-designated Heritage Asset
Section:	N/A
Easting	284254
Northing	907309
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53867

Asset/Event Number	3612
Asset/Event Name	Clearance cairn, Gilbert's Hill
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG53870
Status	Non-designated Heritage Asset
Section:	N/A
Easting	284146
Northing	907554
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53870

Asset/Event Number	3613
Asset/Event Name	Clearance cairn, Strath Lunndaidh
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG53872
Status	Non-designated Heritage Asset
Section:	N/A
Easting	278356
Northing	901655
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53872

Asset/Event Number	3614
Asset/Event Name	Clearance cairn, Strath Lunndaidh
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG53873

Status	Non-designated Heritage Asset
Section:	N/A
Easting	278350
Northing	901640
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53873

Asset/Event Number	3615
Asset/Event Name	Clearance cairn, Strath Lunndaidh
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG53874
Status	Non-designated Heritage Asset
Section:	N/A
Easting	278327
Northing	901567
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53874

Asset/Event Number	3616
Asset/Event Name	Hut circle, Strath Lunndaidh
Type of Asset/Event	Hut Circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG53875
Status	Non-designated Heritage Asset
Section:	N/A
Easting	278345
Northing	901518
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53875

Asset/Event Number	3617
Asset/Event Name	Clearance cairn, Strath Lunndaidh
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG53877
Status	Non-designated Heritage Asset
Section:	N/A
Easting	278405
Northing	901507
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53877

Asset/Event Number	3618
Asset/Event Name	Clearance cairn, Strath Lunndaidh
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG53878
Status	Non-designated Heritage Asset
Section:	N/A
Easting	278414
Northing	901523
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53878

Asset/Event Number	3619
Asset/Event Name	Clearance cairn, Strath Lunndaidh
Type of Asset/Event	Clearance Cairn

Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG53879
Status	Non-designated Heritage Asset
Section:	N/A
Easting	278396
Northing	901577
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53879

Asset/Event Number	3620
Asset/Event Name	Clearance cairn, Strath Lunndaidh
Type of Asset/Event	Clearance Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG53880
Status	Non-designated Heritage Asset
Section:	N/A
Easting	278278
Northing	901641
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53880

Asset/Event Number	3621
Asset/Event Name	Clearance cairn, Strath Lunndaidh
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG53884
Status	Non-designated Heritage Asset
Section:	N/A
Easting	278213
Northing	901468

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53884

Asset/Event Number	3622
Asset/Event Name	Clearance cairns, Strath Lunndaidh
Type of Asset/Event	Clearance Cairn?
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG53885
Status	Non-designated Heritage Asset
Section:	N/A
Easting	278654
Northing	901208
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53885

Asset/Event Number	3623
Asset/Event Name	Clearance cairn, Loch Lunndaidh
Type of Asset/Event	Clearance Cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG53897
Status	Non-designated Heritage Asset
Section:	N/A
Easting	278638
Northing	900969
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG53897

Asset/Event Number	3624
Asset/Event Name	Stone, Woodland at Fannyfield Farm
Type of Asset/Event	Stone
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG54065
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256070
Northing	865380
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54065

Asset/Event Number	3625
Asset/Event Name	Cairn, Drum Dubhran
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG54354
Status	Non-designated Heritage Asset
Section:	N/A
Easting	250567
Northing	861221
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54354

Asset/Event Number	3626
Asset/Event Name	Cairn, Drum Dubhran
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG54355
Status	Non-designated Heritage Asset

Section:	N/A
Easting	250442
Northing	861083
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54355

Asset/Event Number	3627
Asset/Event Name	Contin, War Memorial
Type of Asset/Event	War Memorial
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG54437
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245849
Northing	855842
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54437

Asset/Event Number	3628
Asset/Event Name	Contin, Footbridge
Type of Asset/Event	Footbridge
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG54438
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245790
Northing	855855
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG54438

Asset/Event Number	3629
Asset/Event Name	Smerral
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG54747
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316770
Northing	933870
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54747

Asset/Event Number	3630
Asset/Event Name	Smerral
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG54748
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316718
Northing	933606
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54748

Asset/Event Number	3631
Asset/Event Name	Smerral
Type of Asset/Event	Building
Date and/or Period	Post-medieval

Listing No./NRHE Number	<Null>
HER Number	MHG54749
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316974
Northing	933947
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54749

Asset/Event Number	3632
Asset/Event Name	Smerral
Type of Asset/Event	Farmstead; Farm; Farmhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG54750
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316963
Northing	933669
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54750

Asset/Event Number	3633
Asset/Event Name	Smerral
Type of Asset/Event	Building; Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG54751
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317077
Northing	933972
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54751

Asset/Event Number	3634
Asset/Event Name	Smerral
Type of Asset/Event	Building
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG54752
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317001
Northing	933315
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54752

Asset/Event Number	3635
Asset/Event Name	Smerral
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG54754
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316781
Northing	934008
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54754

Asset/Event Number	3636

Asset/Event Name	Upper Smerral
Type of Asset/Event	Farmstead; Farm; Farmhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG54755
Status	Non-designated Heritage Asset
Section:	N/A
Easting	317160
Northing	933160
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54755

Asset/Event Number	3637
Asset/Event Name	Newlands Of Houstry
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG54756
Status	Non-designated Heritage Asset
Section:	N/A
Easting	316037
Northing	934689
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54756

Asset/Event Number	3638
Asset/Event Name	Uaigh Bheag
Type of Asset/Event	Building
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG54758
Status	Non-designated Heritage Asset
Section:	N/A

Easting	293729
Northing	913950
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54758

Asset/Event Number	3639
Asset/Event Name	Uaigh Bheag
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG54759
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293729
Northing	913950
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54759

Asset/Event Number	3640
Asset/Event Name	Uaigh Bheag
Type of Asset/Event	Boundary Marker; Boundary Stone; Carved Stone
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG54760
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293500
Northing	913800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54760

Asset/Event Number	3641
Asset/Event Name	Uaigh Bheag
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG54761
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293987
Northing	914204
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54761

Asset/Event Number	3642
Asset/Event Name	Uaigh Bheag
Type of Asset/Event	Sheep Fold
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG54762
Status	Non-designated Heritage Asset
Section:	N/A
Easting	294172
Northing	914110
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54762

Asset/Event Number	3643
Asset/Event Name	Uaigh Bheag
Type of Asset/Event	Farmstead; Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>

HER Number	MHG54763
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293414
Northing	914603
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54763

Asset/Event Number	3644
Asset/Event Name	Uaigh Bheag
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG54764
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293630
Northing	914820
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54764

Asset/Event Number	3645
Asset/Event Name	Uaigh Bheag
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG54765
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293880
Northing	914910
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54765

Asset/Event Number	3646
Asset/Event Name	Crask Of Aigas, Aigas Golf Course
Type of Asset/Event	Golf Course
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG54774
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246215
Northing	841821
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54774

Asset/Event Number	3647
Asset/Event Name	Helmsdale, Golf Road, Helmsdale Golf Course
Type of Asset/Event	Golf Course
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG54807
Status	Non-designated Heritage Asset
Section:	N/A
Easting	302334
Northing	916208
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG54807

Asset/Event Number	3648
Asset/Event Name	The Anchorage, Strathpeffer

Type of Asset/Event	Quarry Scoop
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG55587
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247984
Northing	857762
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55587

Asset/Event Number	3649
Asset/Event Name	Kinnettas Square tennis courts, Strathpeffer
Type of Asset/Event	Tennis Court
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG55589
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248102
Northing	858071
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55589

Asset/Event Number	3650
Asset/Event Name	Jubilee Pond Curling Pond and Pavilion, Strathpeffer
Type of Asset/Event	Curling Pond; Pavilion
Date and/or Period	Post-medieval/Modern
Listing No./NRHE Number	<Null>
HER Number	MHG55591
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247981

Northing	857266
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55591

Asset/Event Number	3651
Asset/Event Name	Jublilee Pond saw mill, Strathpeffer
Type of Asset/Event	Saw Mill
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG55592
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247940
Northing	857320
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55592

Asset/Event Number	3652
Asset/Event Name	Saw mill workers' huts, Strathpeffer
Type of Asset/Event	Hut
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG55593
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247960
Northing	857310
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55593

Asset/Event Number	3653
Asset/Event Name	Carriage Drive, Strathpeffer
Type of Asset/Event	Road
Date and/or Period	Post-medieval/Modern
Listing No./NRHE Number	<Null>
HER Number	MHG55594
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247781
Northing	857496
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55594

Asset/Event Number	3654
Asset/Event Name	'The Shoppie', Strathpeffer
Type of Asset/Event	Shop
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG55595
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247880
Northing	857580
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55595

Asset/Event Number	3655
Asset/Event Name	Cairngorm, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG55601

Status	Non-designated Heritage Asset
Section:	N/A
Easting	248180
Northing	858370
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55601

Asset/Event Number	3656
Asset/Event Name	The Orchard, Strathpeffer
Type of Asset/Event	Garden
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG55610
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247980
Northing	858140
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55610

Asset/Event Number	3657
Asset/Event Name	Site of Victory Hall, Strathpeffer
Type of Asset/Event	Village Hall
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG55611
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248110
Northing	857990
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55611

Asset/Event Number	3658
Asset/Event Name	Ord Wood Carriage Track, Strathpeffer
Type of Asset/Event	Path
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG55613
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247780
Northing	858180
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55613

Asset/Event Number	3659
Asset/Event Name	Kinellan Drive Pond, Strathpeffer
Type of Asset/Event	Pond
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG55615
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247500
Northing	857300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55615

Asset/Event Number	3660
Asset/Event Name	Site of drill Hall, Strathpeffer
Type of Asset/Event	Drill Hall

Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG55618
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248110
Northing	857990
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55618

Asset/Event Number	3661
Asset/Event Name	Site of Nutwood Cottage, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG55622
Status	Scheduled Monument
Section:	N/A
Easting	248300
Northing	858600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55622

Asset/Event Number	3662
Asset/Event Name	Well, Newhouse Croft, Heights of Inchvannie
Type of Asset/Event	Well
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG55624
Status	Scheduled Monument
Section:	N/A
Easting	249800
Northing	860500

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55624

Asset/Event Number	3663
Asset/Event Name	Loch Kinellan Curling Pond
Type of Asset/Event	Curling Pond
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG55625
Status	Scheduled Monument
Section:	N/A
Easting	246958
Northing	857474
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG55625

Asset/Event Number	3664
Asset/Event Name	Dyke - Balnatink, Latheron
Type of Asset/Event	Dyke
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG56035
Status	Scheduled Monument
Section:	N/A
Easting	315484
Northing	930919
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG56035

Asset/Event Number	3665
Asset/Event Name	Dyke - Balnatink, Latheron
Type of Asset/Event	Dyke
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG56037
Status	Scheduled Monument
Section:	N/A
Easting	315119
Northing	931490
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG56037

Asset/Event Number	3666
Asset/Event Name	Dykes - Cnoc a' Leacachan
Type of Asset/Event	Dyke
Date and/or Period	Undated
Listing No./NRHE Number	<Null>
HER Number	MHG56489
Status	Scheduled Monument
Section:	N/A
Easting	257621
Northing	872555
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG56489

Asset/Event Number	3667
Asset/Event Name	Clearance cairn or shieling hut - Urchany (Allt na Criche)
Type of Asset/Event	Clearance Cairn?; Shieling Hut?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62090
Status	Scheduled Monument

Section:	N/A
Easting	245692
Northing	845719
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62090

Asset/Event Number	3668
Asset/Event Name	Farmstead pond, Allt na Criche, Breakachy Burn, Urchany
Type of Asset/Event	Pond?
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG62138
Status	Scheduled Monument
Section:	N/A
Easting	245601
Northing	845497
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG62138

Asset/Event Number	3669
Asset/Event Name	Contin Bridge WW2 Earthworks/Trenches - Contin
Type of Asset/Event	Practice Trench
Date and/or Period	Modern
Listing No./NRHE Number	<Null>
HER Number	MHG62653
Status	Scheduled Monument
Section:	N/A
Easting	245030
Northing	856839
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/Monument/MHG62653

Asset/Event Number	3670
Asset/Event Name	Possible site of Old Kiltarlity manse and garden - Kiltarlity
Type of Asset/Event	Manse?; Garden?; Cemetery?; Sheep Dip
Date and/or Period	Post-medieval
Listing No./NRHE Number	<Null>
HER Number	MHG63011
Status	Scheduled Monument
Section:	N/A
Easting	248639
Northing	842472
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63011

Asset/Event Number	3671
Asset/Event Name	Cup Marked Stone - Strath Sgitheach Allt Na Criche (7)
Type of Asset/Event	Cup Marked Stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	<Null>
HER Number	MHG63181
Status	Scheduled Monument
Section:	N/A
Easting	251944
Northing	863239
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63181

Asset/Event Number	3672
Asset/Event Name	Eileanach Lodge,settlement & field system 550m WSW of
Type of Asset/Event	Secular: settlement, including deserted, depopulated and townships
Date and/or Period	Post-medieval

Listing No./NRHE Number	SM4707
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	253977
Northing	868724
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM4707

Asset/Event Number	3673
Asset/Event Name	Chapel of Dunn, chapel, 300m SW of Oldhall House
Type of Asset/Event	Ecclesiastical: chapel
Date and/or Period	Medieval
Listing No./NRHE Number	SM5732
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	320238
Northing	956025
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5732

Asset/Event Number	3674
Asset/Event Name	St Magnus' church,burial ground and hospital
Type of Asset/Event	Ecclesiastical: burial ground, cemetery, graveyard; Secular: hospital, hospice
Date and/or Period	Medieval
Listing No./NRHE Number	SM5413
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	315881
Northing	954875
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5413

Asset/Event Number	3675
Asset/Event Name	Achorn Bridge,settlements 1400m WSW of
Type of Asset/Event	Prehistoric domestic and defensive: settlement; Secular: shieling
Date and/or Period	Prehistoric/Post-medieval
Listing No./NRHE Number	SM5092
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	311940
Northing	930325
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5092

Asset/Event Number	3676
Asset/Event Name	Loedebest,settlement 1500m WNW of
Type of Asset/Event	Secular: settlement, including deserted, depopulated and townships
Date and/or Period	Post-medieval
Listing No./NRHE Number	SM5199
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	312363
Northing	932629
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5199

Asset/Event Number	3677

Asset/Event Name	Balcraggie Lodge,settlement 700m N of
Type of Asset/Event	Secular: settlement, including deserted, depopulated and townships
Date and/or Period	Post-medieval
Listing No./NRHE Number	SM5230
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	314058
Northing	931281
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5230

Asset/Event Number	3678
Asset/Event Name	Culburnie,ring cairn & stone circle
Type of Asset/Event	Prehistoric ritual and funerary: ring cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM2425
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	249180
Northing	841810
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM2425

Asset/Event Number	3679
Asset/Event Name	Ballachly,chapel and graveyard 90m SW of
Type of Asset/Event	Ecclesiastical: chapel
Date and/or Period	Early Historic
Listing No./NRHE Number	SM2704
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A

Easting	315693
Northing	930359
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM2704

Asset/Event Number	3680
Asset/Event Name	Achanarras,cairn 800m NW of
Type of Asset/Event	Prehistoric ritual and funerary: cairn (type uncertain)
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM2400
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	314538
Northing	955753
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM2400

Asset/Event Number	3681
Asset/Event Name	Achanarras,cairn 800m NW of
Type of Asset/Event	Prehistoric ritual and funerary: cairn (type uncertain)
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM2401
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	314464
Northing	955754
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM2401

Asset/Event Number	3682
Asset/Event Name	Achanarras,hut circle
Type of Asset/Event	Prehistoric domestic and defensive: hut circle, roundhouse
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM2402
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	314756
Northing	955772
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM2402

Asset/Event Number	3683
Asset/Event Name	Loch Kinellan,crannog
Type of Asset/Event	Secular: crannog (with post-prehistoric use)
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM3987
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	247111
Northing	857588
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM3987

Asset/Event Number	3684
Asset/Event Name	Langwell Castle or Achastle,230m E of Langwell House
Type of Asset/Event	Secular: castle
Date and/or Period	Medieval
Listing No./NRHE Number	SM3437

HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	311628
Northing	922719
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM3437

Asset/Event Number	3685
Asset/Event Name	Berriedale Castle
Type of Asset/Event	Secular: castle
Date and/or Period	Medieval
Listing No./NRHE Number	SM3438
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	312101
Northing	922428
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM3438

Asset/Event Number	3686
Asset/Event Name	Berriedale,hut circles & enclosure on S bank of Allt-Ardachaidh
Type of Asset/Event	Prehistoric domestic and defensive: enclosure (domestic or defensive)
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM3476
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	310593
Northing	925713
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM3476

Asset/Event Number	3687
Asset/Event Name	Golsary, broch on W bank of Burn of Golsary, Rumster Forest
Type of Asset/Event	Prehistoric domestic and defensive: broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM550
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	320566
Northing	937487
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM550

Asset/Event Number	3688
Asset/Event Name	Fairy Hillock,chambered cairn SE of Spittal Mains
Type of Asset/Event	Prehistoric ritual and funerary: chambered cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM528
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	316374
Northing	954386
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM528

Asset/Event Number	3689
Asset/Event Name	Knockglass,broch E of

Type of Asset/Event	Prehistoric domestic and defensive: broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM561
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	317614
Northing	953289
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM561

Asset/Event Number	3690
Asset/Event Name	Spittal Farm, broch 180m E of
Type of Asset/Event	Prehistoric domestic and defensive: broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM582
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	317558
Northing	954387
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM582

Asset/Event Number	3691
Asset/Event Name	Guidebest, stone circle, Latheronwheel Burn
Type of Asset/Event	Prehistoric ritual and funerary: stone circle or ring
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM453
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	318025

Northing	935110
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM453

Asset/Event Number	3692
Asset/Event Name	Langwell House,cairn 400m SW of,Berriedale
Type of Asset/Event	Prehistoric ritual and funerary: cairn (type uncertain)
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM460
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	311019
Northing	922449
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM460

Asset/Event Number	3693
Asset/Event Name	Borgue Langwell, broch, outworks and later settlement, Berriedale
Type of Asset/Event	Prehistoric domestic and defensive: broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM524
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	310267
Northing	921818
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM524

Asset/Event Number	3694
Asset/Event Name	Borgue Langwell, homestead 150m NW of broch, Berriedale
Type of Asset/Event	Prehistoric domestic and defensive: homestead
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM525
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	310164
Northing	921920
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM525

Asset/Event Number	3695
Asset/Event Name	Rinsary, broch and post-medieval farmstead 300m SSW of, Berriedale
Type of Asset/Event	Prehistoric domestic and defensive: broch; Secular: farmstead
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM577
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	311691
Northing	923349
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM577

Asset/Event Number	3696
Asset/Event Name	Allt a'Bhurg,broch,Ord of Caithness
Type of Asset/Event	Prehistoric domestic and defensive: broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM515
HER Number	<Null>

Status	Scheduled Monument
Section:	N/A
Easting	307130
Northing	918815
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM515

Asset/Event Number	3697
Asset/Event Name	Dun Beath,broch,Dunbeath
Type of Asset/Event	Prehistoric domestic and defensive: broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM546
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	315536
Northing	930450
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM546

Asset/Event Number	3698
Asset/Event Name	Latheronwheel House,broch 500m W of
Type of Asset/Event	Prehistoric domestic and defensive: broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM566
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	317636
Northing	932518
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM566

Asset/Event Number	3699
Asset/Event Name	Smerral, broch to E of Bunellich
Type of Asset/Event	Prehistoric domestic and defensive: broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM581
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	317811
Northing	933792
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM581

Asset/Event Number	3700
Asset/Event Name	Invershin Station,chambered cairn 400m N of
Type of Asset/Event	Prehistoric ritual and funerary: chambered cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM1792
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	257935
Northing	895851
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM1792

Asset/Event Number	3701
Asset/Event Name	Clach an Tiompain, symbol stone
Type of Asset/Event	Crosses and carved stones: symbol stone

Date and/or Period	Early Historic
Listing No./NRHE Number	SM1676
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	248487
Northing	858511
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM1676

Asset/Event Number	3702
Asset/Event Name	Morvich Lodge,cairns,hut circles & clearance cairns 400m E of
Type of Asset/Event	Prehistoric domestic and defensive: hut circle, roundhouse; Prehistoric ritual and funerary: c
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM1809
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	275989
Northing	900611
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM1809

Asset/Event Number	3703
Asset/Event Name	Allt Breac,stone rows 320m sw of bridge
Type of Asset/Event	Prehistoric ritual and funerary: stone rows
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM1763
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	295503
Northing	918569

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM1763

Asset/Event Number	3704
Asset/Event Name	Torrish,cairn WNW of
Type of Asset/Event	Prehistoric ritual and funerary: cairn (type uncertain)
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM1821
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	296824
Northing	918810
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM1821

Asset/Event Number	3705
Asset/Event Name	Carn Bran,broch on E bank of Loch Burn
Type of Asset/Event	Prehistoric domestic and defensive: broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM1842
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	294210
Northing	912208
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM1842

Asset/Event Number	3706
Asset/Event Name	Boath, three chambered cairns NE and NNE of Easter Ballone Farm
Type of Asset/Event	Prehistoric ritual and funerary: chambered cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM6644
HER Number	<Null>
Status	Listed Building - Category A
Section:	N/A
Easting	258151
Northing	873843
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM6644

Asset/Event Number	3707
Asset/Event Name	Urchany, barrow 595m SW of
Type of Asset/Event	Prehistoric ritual and funerary: barrow
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM13523
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	244268
Northing	845507
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM13523

Asset/Event Number	3708
Asset/Event Name	Heights of Brae, chambered cairn 375m NNW of Firth View
Type of Asset/Event	Prehistoric ritual and funerary: chambered cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM2312
HER Number	<Null>
Status	Listed Building - Category C

Section:	N/A
Easting	251445
Northing	861528
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM2312

Asset/Event Number	3709
Asset/Event Name	Clachan Corrach, chambered cairn 375m E of Beallach Farm
Type of Asset/Event	Prehistoric ritual and funerary: chambered cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM2466
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	248840
Northing	856544
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM2466

Asset/Event Number	3710
Asset/Event Name	Berriedale Water, cairn 250m NNW of Millery
Type of Asset/Event	Prehistoric ritual and funerary: cairn (type uncertain)
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM422
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	310829
Northing	925611
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://portal.historicenvironment.scot/designation/SM422

Asset/Event Number	3711
Asset/Event Name	An Dun, broch, Berriedale
Type of Asset/Event	Prehistoric domestic and defensive: broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM518
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	310340
Northing	924912
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM518

Asset/Event Number	3712
Asset/Event Name	Dun Burn, cairn 200m NE of An Dun Broch
Type of Asset/Event	Prehistoric ritual and funerary: cairn (type uncertain)
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM447
HER Number	<Null>
Status	Listed Building - Category A
Section:	N/A
Easting	310511
Northing	925022
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM447

Asset/Event Number	3713
Asset/Event Name	Achnasoul, medieval earthwork 440m SSE of
Type of Asset/Event	Secular: earthwork
Date and/or Period	Medieval

Listing No./NRHE Number	SM13629
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	248808
Northing	851821
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM13629

Asset/Event Number	3714
Asset/Event Name	Ballachly,broch 360m S of,Stemster
Type of Asset/Event	Prehistoric domestic and defensive: broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM520
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	319556
Northing	944229
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM520

Asset/Event Number	3715
Asset/Event Name	Shin Bridge, Inveran
Type of Asset/Event	Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB265
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	257496
Northing	897533
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB265

Asset/Event Number	3716
Asset/Event Name	Salmon Fishing Station, Invershin
Type of Asset/Event	Fish farm
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB267
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	257365
Northing	896639
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB267

Asset/Event Number	3717
Asset/Event Name	Shin Railway Viaduct
Type of Asset/Event	Viaduct
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB279
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	257893
Northing	895274
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB279

Asset/Event Number	3718

Asset/Event Name	Manse, Contin
Type of Asset/Event	Manse
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB1768
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	245735
Northing	855652
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB1768

Asset/Event Number	3719
Asset/Event Name	West Lodge, Coul House
Type of Asset/Event	Hotel
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB1770
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	245800
Northing	856142
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB1770

Asset/Event Number	3720
Asset/Event Name	Mains Of Coul
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB1771
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A

Easting	246227
Northing	856246
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB1771

Asset/Event Number	3721
Asset/Event Name	Free Church Manse, Jamestown
Type of Asset/Event	Manse
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB1772
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	247892
Northing	856578
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB1772

Asset/Event Number	3722
Asset/Event Name	Kinellan Farmhouse
Type of Asset/Event	Farmhouse
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB1773
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	247490
Northing	857541
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB1773

Asset/Event Number	3723
Asset/Event Name	Old Bridge, Contin
Type of Asset/Event	Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB1789
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	245403
Northing	856672
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB1789

Asset/Event Number	3724
Asset/Event Name	Burial Ground, Contin Church Of Scotland Parish Church
Type of Asset/Event	Church and burial ground
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB1790
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	245623
Northing	855758
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB1790

Asset/Event Number	3725
Asset/Event Name	Morvich Lodge
Type of Asset/Event	Lodge
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7021

HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	275449
Northing	900749
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7021

Asset/Event Number	3726
Asset/Event Name	Eileanaigas House
Type of Asset/Event	Country house
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7117
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	246889
Northing	841864
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7117

Asset/Event Number	3727
Asset/Event Name	Old Burial Ground, Kilmorack
Type of Asset/Event	Burial ground
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7123
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	249343
Northing	844285
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7123

Asset/Event Number	3728
Asset/Event Name	Kilmorack Steading
Type of Asset/Event	Manse and steading
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7124
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	249282
Northing	844386
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7124

Asset/Event Number	3729
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3730
Asset/Event Name	VOID - number not assigned

Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3731
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3732
Asset/Event Name	Carbisdale Castle
Type of Asset/Event	Castle; Gate
Date and/or Period	Modern
Listing No./NRHE Number	LB7165
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	257448

Northing	895457
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7165

Asset/Event Number	3733
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3734
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3735
Asset/Event Name	Cawdearg
Type of Asset/Event	Croft house
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7180
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	256260
Northing	891158
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7180

Asset/Event Number	3736
Asset/Event Name	Helmsdale Station
Type of Asset/Event	Railway station
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7184
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	302385
Northing	915482
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7184

Asset/Event Number	3737
Asset/Event Name	Ice House, Helmsdale
Type of Asset/Event	Ice house
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7195
HER Number	<Null>

Status	Listed Building - Category C
Section:	N/A
Easting	302547
Northing	915375
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7195

Asset/Event Number	3738
Asset/Event Name	War Memorial, Helmsdale
Type of Asset/Event	War Memorial (WWI and WWII)
Date and/or Period	Modern
Listing No./NRHE Number	LB7196
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	302510
Northing	915387
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7196

Asset/Event Number	3739
Asset/Event Name	The Old Manse, Stittenham Road, Helmsdale
Type of Asset/Event	Church; wall; gate piers
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7201
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	302628
Northing	915628
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7201

Asset/Event Number	3740
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3741
Asset/Event Name	Castle Leod
Type of Asset/Event	Castle
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7826
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	248603
Northing	859325
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7826

Asset/Event Number	3742
Asset/Event Name	Gate Lodge, Castle Leod
Type of Asset/Event	Lodge; gate piers; gate piers

Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7827
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	248855
Northing	858773
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7827

Asset/Event Number	3743
Asset/Event Name	Fodderty And Strathpeffer Church Of Scotland Parish Church, Strathpeffer
Type of Asset/Event	Church
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7832
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	248196
Northing	857997
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7832

Asset/Event Number	3744
Asset/Event Name	Upper Pump Room, Strathpeffer
Type of Asset/Event	Pump room
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7833
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	248353
Northing	858065

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7833

Asset/Event Number	3745
Asset/Event Name	Station, Strathpeffer
Type of Asset/Event	Railway station
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7834
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	248589
Northing	858388
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7834

Asset/Event Number	3746
Asset/Event Name	Spa Cottage, Strathpeffer
Type of Asset/Event	Cottage
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7835
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	248334
Northing	858122
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7835

Asset/Event Number	3747
Asset/Event Name	Spa Pavilion, Strathpeffer
Type of Asset/Event	Pavilion
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7836
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	248405
Northing	858094
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7836

Asset/Event Number	3748
Asset/Event Name	Strathpeffer Hotel, Strathpeffer
Type of Asset/Event	Hotel
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7837
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	248395
Northing	858288
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7837

Asset/Event Number	3749
Asset/Event Name	Kildonan, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7838
HER Number	<Null>
Status	Listed Building - Category C

Section:	N/A
Easting	248313
Northing	858437
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7838

Asset/Event Number	3750
Asset/Event Name	The Red House, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7839
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	248526
Northing	858459
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7839

Asset/Event Number	3751
Asset/Event Name	Timaru House Hotel, Strathpeffer
Type of Asset/Event	Hotel
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7840
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	248464
Northing	858441
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://portal.historicenvironment.scot/designation/LB7840

Asset/Event Number	3752
Asset/Event Name	Timuka, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7841
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	248477
Northing	858469
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7841

Asset/Event Number	3753
Asset/Event Name	Gate Piers, Ben Wyvis Hotel, Strathpeffer
Type of Asset/Event	Gate piers
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7852
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	248433
Northing	858289
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7852

Asset/Event Number	3754
Asset/Event Name	Craigvar, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval

Listing No./NRHE Number	LB7853
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	248408
Northing	858153
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7853

Asset/Event Number	3755
Asset/Event Name	Dunnichen, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7854
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	248271
Northing	858467
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7854

Asset/Event Number	3756
Asset/Event Name	Dunraven Lodge, Strathpeffer
Type of Asset/Event	Lodge
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7855
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	248183
Northing	858503
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7855

Asset/Event Number	3757
Asset/Event Name	Eaglestone House, Strathpeffer
Type of Asset/Event	Cottage
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7856
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	248427
Northing	858483
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7856

Asset/Event Number	3758
Asset/Event Name	St Anne's Episcopal Church, Strathpeffer
Type of Asset/Event	Church
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7857
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	248331
Northing	858037
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7857

Asset/Event Number	3759

Asset/Event Name	Strathpeffer Free Church Of Scotland Church, Strathpeffer
Type of Asset/Event	Church
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7858
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	248317
Northing	858306
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7858

Asset/Event Number	3760
Asset/Event Name	1-2 Hamilton House, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7859
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	248268
Northing	858050
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7859

Asset/Event Number	3761
Asset/Event Name	Heatherlie, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Modern
Listing No./NRHE Number	LB7860
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A

Easting	248292
Northing	858211
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7860

Asset/Event Number	3762
Asset/Event Name	Highland Hotel, Strathpeffer
Type of Asset/Event	Hotel
Date and/or Period	Modern
Listing No./NRHE Number	LB7861
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	248256
Northing	858110
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7861

Asset/Event Number	3763
Asset/Event Name	Holly Lodge Hotel, Strathpeffer
Type of Asset/Event	Lodge
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7862
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	248280
Northing	858408
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7862

Asset/Event Number	3764
Asset/Event Name	Kinnettas House, Strathpeffer
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7863
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	248179
Northing	858053
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7863

Asset/Event Number	3765
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3766
Asset/Event Name	Sawmill, Mill Road, Berriedale
Type of Asset/Event	Sawmill
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7922

HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	311942
Northing	922615
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7922

Asset/Event Number	3767
Asset/Event Name	2 Portland Terrace, Berriedale
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7923
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	311976
Northing	922501
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7923

Asset/Event Number	3768
Asset/Event Name	Shore Cottages, Berriedale
Type of Asset/Event	Cottage
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7924
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	312082
Northing	922575
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7924

Asset/Event Number	3769
Asset/Event Name	Ice House And Fishing Store, Berriedale
Type of Asset/Event	Ice house; store
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7925
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	312045
Northing	922564
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7925

Asset/Event Number	3770
Asset/Event Name	Parish Church, Berriedale
Type of Asset/Event	Church
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7926
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	312103
Northing	923275
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7926

Asset/Event Number	3771
Asset/Event Name	VOID - number not assigned

Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3772
Asset/Event Name	North Tower, Berriedale Navigation Beacons
Type of Asset/Event	Beacon
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7931
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	311971
Northing	922332
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7931

Asset/Event Number	3773
Asset/Event Name	Berriedale Post Office And Stable/Byre Range, Welbeck Estate Office, Berriedale
Type of Asset/Event	Post office; stable
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7932
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	311801

Northing	922752
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7932

Asset/Event Number	3774
Asset/Event Name	1 Mill House, Berriedale
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7933
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	311893
Northing	922633
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7933

Asset/Event Number	3775
Asset/Event Name	Bridge, Berriedale
Type of Asset/Event	Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB7968
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	311813
Northing	922691
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB7968

Asset/Event Number	3776
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3777
Asset/Event Name	Ousdale Bridge
Type of Asset/Event	Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB8001
HER Number	<Null>
Status	Listed Building - Category B
Section:	N/A
Easting	306576
Northing	920344
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB8001

Asset/Event Number	3778
Asset/Event Name	Ousdale Farm
Type of Asset/Event	Farm house
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB8002
HER Number	<Null>

Status	Listed Building - Category C
Section:	N/A
Easting	307055
Northing	920055
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB8002

Asset/Event Number	VOID - number not assigned
Asset/Event Name	
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	3780
Asset/Event Name	Home Farm Steading, Beaufort Castle
Type of Asset/Event	Farm house
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB8073
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	249932
Northing	842166
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB8073

Asset/Event Number	3781
Asset/Event Name	Eskadale House
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB8104
HER Number	<Null>
Status	Listed Building - Category C
Section:	N/A
Easting	246639
Northing	841148
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB8104

Asset/Event Number	3782
Asset/Event Name	White Lodge, Strathpeffer
Type of Asset/Event	Lodge
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB10949
HER Number	<Null>
Status	Inventory Garden and Designed Landscape
Section:	N/A
Easting	248310
Northing	858185
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB10949

Asset/Event Number	3783
Asset/Event Name	Nicolson Mackenzie Memorial Hospital, Strathpeffer
Type of Asset/Event	Hospital

Date and/or Period	Post-medieval
Listing No./NRHE Number	LB13238
HER Number	<Null>
Status	Inventory Garden and Designed Landscape
Section:	N/A
Easting	248031
Northing	858067
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB13238

Asset/Event Number	3784
Asset/Event Name	Nutwood Steading, Strathpeffer
Type of Asset/Event	Steading
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB13239
HER Number	<Null>
Status	Event
Section:	N/A
Easting	248410
Northing	858594
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB13239

Asset/Event Number	3785
Asset/Event Name	286 Rogart, Rogart
Type of Asset/Event	House
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB14915
HER Number	<Null>
Status	Event
Section:	N/A
Easting	272627
Northing	902092

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB14915

Asset/Event Number	3786
Asset/Event Name	Church Of Scotland Mission Hall, Causeymire
Type of Asset/Event	Church
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB14977
HER Number	<Null>
Status	Event
Section:	N/A
Easting	317370
Northing	948321
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB14977

Asset/Event Number	3787
Asset/Event Name	St Callan's Church, Rogart
Type of Asset/Event	Church
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB17441
HER Number	<Null>
Status	Event
Section:	N/A
Easting	273884
Northing	903518
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB17441

Asset/Event Number	3788
Asset/Event Name	St Callans Old Manse, Rogart
Type of Asset/Event	Manse
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB17442
HER Number	<Null>
Status	Event
Section:	N/A
Easting	273855
Northing	903464
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB17442

Asset/Event Number	3789
Asset/Event Name	Smithy Cottage, Crask Of Aigas
Type of Asset/Event	Cottage
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB49020
HER Number	<Null>
Status	Event
Section:	N/A
Easting	246740
Northing	842263
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB49020

Asset/Event Number	3790
Asset/Event Name	Ivy Cottage
Type of Asset/Event	Cottage
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB50836
HER Number	<Null>
Status	Event

Section:	N/A
Easting	311801
Northing	922766
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB50836

Asset/Event Number	3791
Asset/Event Name	Torr Achilty Power Station And Dam, Conon Valley Hydro Electric Scheme
Type of Asset/Event	Power station; dam
Date and/or Period	Modern
Listing No./NRHE Number	LB51709
HER Number	<Null>
Status	Event
Section:	N/A
Easting	244630
Northing	854525
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB51709

Asset/Event Number	3792
Asset/Event Name	Former Signal Box, Rogart South
Type of Asset/Event	Signal box
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB52062
HER Number	<Null>
Status	Event
Section:	N/A
Easting	272462
Northing	902006
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://portal.historicenvironment.scot/designation/LB52062

Asset/Event Number	3793
Asset/Event Name	Castle Leod
Type of Asset/Event	Designed landscape
Date and/or Period	Post-medieval
Listing No./NRHE Number	GDL00094
HER Number	<Null>
Status	Event
Section:	N/A
Easting	248626
Northing	859329
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/GDL00094

Asset/Event Number	3794
Asset/Event Name	Beaufort Castle
Type of Asset/Event	Beaufort Castle
Date and/or Period	Post-medieval
Listing No./NRHE Number	GDL00052
HER Number	<Null>
Status	Event
Section:	N/A
Easting	250734
Northing	842925
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/GDL00052

Asset/Event Number	3795
Asset/Event Name	Additional Sections Strathpeffer etc
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>

Listing No./NRHE Number	<Null>
HER Number	EHG1014
Status	Event
Section:	N/A
Easting	248893
Northing	854815
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1014

Asset/Event Number	3796
Asset/Event Name	Additional Strathpeffer
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1015
Status	Event
Section:	N/A
Easting	248027
Northing	856536
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1015

Asset/Event Number	3797
Asset/Event Name	DBA and walkover survey - Novar Wind Farm Extension
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1021
Status	Event
Section:	N/A
Easting	254387
Northing	871090
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1021

Asset/Event Number	3798
Asset/Event Name	Contin Bridge, Contin
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1050
Status	Event
Section:	N/A
Easting	245409
Northing	856646
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1050

Asset/Event Number	3799
Asset/Event Name	Mulbuie Water Supply Project Phases 2 & 3
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1062
Status	Event
Section:	N/A
Easting	249514
Northing	852966
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1062

Asset/Event Number	3800

Asset/Event Name	Hughton water mains renewal
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1072
Status	Event
Section:	N/A
Easting	242827
Northing	840440
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1072

Asset/Event Number	3801
Asset/Event Name	Walkover survey - proposed Kilbraur Windfarm
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1090
Status	Event
Section:	N/A
Easting	279491
Northing	904792
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1090

Asset/Event Number	3802
Asset/Event Name	Trial trenching - Buolfruich, Houstry, Dunbeath, Caithness
Type of Asset/Event	Excavation extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1091
Status	Event
Section:	N/A

Easting	315513
Northing	935642
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1091

Asset/Event Number	3803
Asset/Event Name	Docharty Water Mains Renewal Project
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1160
Status	Event
Section:	N/A
Easting	248985
Northing	859502
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1160

Asset/Event Number	3804
Asset/Event Name	Walkover survey - Dunrobin Glen
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1164
Status	Event
Section:	N/A
Easting	279360
Northing	905090
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1164

Asset/Event Number	3805
Asset/Event Name	DBA & walkover survey - Beauly West Water Mains Renewal
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1167
Status	Event
Section:	N/A
Easting	248135
Northing	836502
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1167

Asset/Event Number	3806
Asset/Event Name	DBA and walkover survey - Kintradwell
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG12
Status	Event
Section:	N/A
Easting	291807
Northing	908488
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG12

Asset/Event Number	3807
Asset/Event Name	Gartymore Water Mains
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>

HER Number	EHG1211
Status	Event
Section:	N/A
Easting	301622
Northing	914567
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1211

Asset/Event Number	3808
Asset/Event Name	Test pitting - Elsick House, Strathpeffer
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1239
Status	Event
Section:	N/A
Easting	247783
Northing	857428
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1239

Asset/Event Number	3809
Asset/Event Name	Telecommunications Ord Hill
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1240
Status	Event
Section:	N/A
Easting	248054
Northing	849823
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1240

Asset/Event Number	3810
Asset/Event Name	Earthwork survey - Achnasoul Wood, Marybank
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1271
Status	Event
Section:	N/A
Easting	248792
Northing	851836
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1271

Asset/Event Number	3811
Asset/Event Name	Tigh na Mullach SFGS, Fodderty
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1323
Status	Event
Section:	N/A
Easting	251050
Northing	861107
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1323

Asset/Event Number	3812
Asset/Event Name	Watching brief at Tohorrie, by Dunbeath

Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1328
Status	Event
Section:	N/A
Easting	315416
Northing	930869
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1328

Asset/Event Number	3813
Asset/Event Name	Geophysical survey - Rosebank Cottage, Culrain
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1350
Status	Event
Section:	N/A
Easting	256979
Northing	894563
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1350

Asset/Event Number	3814
Asset/Event Name	Evaluation - Rosebank, Culrain
Type of Asset/Event	Excavation extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1364
Status	Event
Section:	N/A
Easting	256959

Northing	894574
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1364

Asset/Event Number	3815
Asset/Event Name	The Bungalow, Culrain
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1465
Status	Event
Section:	N/A
Easting	257414
Northing	894730
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1465

Asset/Event Number	3816
Asset/Event Name	House Plots North of Strathpeffer Primary School
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1471
Status	Event
Section:	N/A
Easting	247849
Northing	857979
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1471

Asset/Event Number	3817
Asset/Event Name	Black Rock Gorge Hydro Scheme, Envir. Impact Ass.
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1495
Status	Event
Section:	N/A
Easting	258382
Northing	866828
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1495

Asset/Event Number	3818
Asset/Event Name	DBA and walkover survey - Novar Estate
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG159
Status	Event
Section:	N/A
Easting	255446
Northing	871562
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG159

Asset/Event Number	3819
Asset/Event Name	New Road at Kinellan Farm, Strathpeffer (Phase 1)
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1598

Status	Event
Section:	N/A
Easting	247099
Northing	856897
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1598

Asset/Event Number	3820
Asset/Event Name	Field survey - Kintradwell, Loth
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG174
Status	Event
Section:	N/A
Easting	292250
Northing	908419
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG174

Asset/Event Number	3821
Asset/Event Name	Walkover Survey - Langwell-Rinsary Braes, Berriedale
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG175
Status	Event
Section:	N/A
Easting	310959
Northing	923539
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG175

Asset/Event Number	3822
Asset/Event Name	Watching brief - Muir of Ord Hill
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG188
Status	Event
Section:	N/A
Easting	248328
Northing	850025
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG188

Asset/Event Number	3823
Asset/Event Name	Photographic survey - Culeave House, Kincardine
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG2691
Status	Event
Section:	N/A
Easting	255245
Northing	891302
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG2691

Asset/Event Number	3824
Asset/Event Name	Photographic survey - Mid Syall, Kincardine
Type of Asset/Event	Survey extent

Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG2693
Status	Event
Section:	N/A
Easting	257196
Northing	891268
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG2693

Asset/Event Number	3825
Asset/Event Name	Photographic survey of New Black Croft, Lower Smerral
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG2736
Status	Event
Section:	N/A
Easting	317414
Northing	934240
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG2736

Asset/Event Number	3826
Asset/Event Name	Photographic survey - The Croft, Braehungie
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG2749
Status	Event
Section:	N/A
Easting	318442
Northing	937758

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG2749

Asset/Event Number	3827
Asset/Event Name	Survey of memorials in Invershin Cemetery
Type of Asset/Event	Survey
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG2840
Status	Event
Section:	N/A
Easting	257535
Northing	897228
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG2840

Asset/Event Number	3828
Asset/Event Name	Scotland's Rural Past Strathconon Project: Phase 1
Type of Asset/Event	Survey
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG2875
Status	Event
Section:	N/A
Easting	240008
Northing	854943
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG2875

Asset/Event Number	3829
Asset/Event Name	Photographic survey - Elsick House, Strathpeffer
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG2930
Status	Event
Section:	N/A
Easting	247787
Northing	857427
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG2930

Asset/Event Number	3830
Asset/Event Name	DBA - Free Church, Jamestown, Strathpeffer
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG2939
Status	Event
Section:	N/A
Easting	247780
Northing	856594
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG2939

Asset/Event Number	3831
Asset/Event Name	Desk-based assessment and walkover survey for Cassley to Shin overhead line refurbishment
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3016
Status	Event

Section:	N/A
Easting	254440
Northing	912997
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3016

Asset/Event Number	3832
Asset/Event Name	Photographic survey of buildings at Rangag, Latheron
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3028
Status	Event
Section:	N/A
Easting	317777
Northing	943570
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3028

Asset/Event Number	3833
Asset/Event Name	Desk-based assessment and walkover survey, Knockinnon, Houstry
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3053
Status	Event
Section:	N/A
Easting	315042
Northing	933322
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/event/EHG3053

Asset/Event Number	3834
Asset/Event Name	Desk-based assessment and walkover survey, blocks of land at Houstry and Smerral
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3063
Status	Event
Section:	N/A
Easting	316481
Northing	933700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3063

Asset/Event Number	3835
Asset/Event Name	Photographic survey and watching brief at 19 Culburnie, Kiltarlity
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3133
Status	Event
Section:	N/A
Easting	249153
Northing	841805
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3133

Asset/Event Number	3836
Asset/Event Name	Phase 2 watching brief, Kilbraur Windfarm, Strath Brora
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>

Listing No./NRHE Number	<Null>
HER Number	EHG3179
Status	Event
Section:	N/A
Easting	279518
Northing	907379
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3179

Asset/Event Number	3837
Asset/Event Name	Desk-based assessment and walkover survey - Halsary Windfarm
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3194
Status	Event
Section:	N/A
Easting	318156
Northing	950118
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3194

Asset/Event Number	3838
Asset/Event Name	Survey of township remains at Rogie, near Contin, Ross-shire
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3197
Status	Event
Section:	N/A
Easting	244117
Northing	859708
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3197

Asset/Event Number	3839
Asset/Event Name	Desk-based assessment and walkover survey, eastern access route, Gordonbush Wind Farm
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3207
Status	Event
Section:	N/A
Easting	286408
Northing	905234
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3207

Asset/Event Number	3840
Asset/Event Name	Desk-based assessment and walkover survey, Drynie Farm, Dingwall
Type of Asset/Event	Whole site extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3215
Status	Event
Section:	N/A
Easting	254323
Northing	862713
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3215

Asset/Event Number	3841

Asset/Event Name	Photographic survey at Former steading, Balnaird, Heights of Inchvannie, Strathpeffer
Type of Asset/Event	Survey
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3249
Status	Event
Section:	N/A
Easting	250093
Northing	860154
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3249

Asset/Event Number	3842
Asset/Event Name	Walkover Survey - Glen Loth
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG33
Status	Event
Section:	N/A
Easting	293325
Northing	914582
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG33

Asset/Event Number	3843
Asset/Event Name	East Sutherland Coastal Zone Assessment Survey
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3315
Status	Event
Section:	N/A

Easting	282971
Northing	898331
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3315

Asset/Event Number	3844
Asset/Event Name	Desk based assessment and walkover survey, Gilbert's Hill, Carrol
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3328
Status	Event
Section:	N/A
Easting	283957
Northing	907459
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3328

Asset/Event Number	3845
Asset/Event Name	Walkover survey at Strath Lunndaidh
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3331
Status	Event
Section:	N/A
Easting	278735
Northing	901116
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3331

Asset/Event Number	3846
Asset/Event Name	Archaeological Desktop & Walkover Survey For a Proposed Development at Ard a'Chlachain,
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3347
Status	Event
Section:	N/A
Easting	272969
Northing	901831
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3347

Asset/Event Number	3847
Asset/Event Name	Desk-based assessment and walkover survey - Beauly-Dounreay 275kV Overhead Transmissi
Type of Asset/Event	Desk-based assessment; Walkover Survey
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3360
Status	Event
Section:	N/A
Easting	274379
Northing	901812
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3360

Asset/Event Number	3848
Asset/Event Name	Watching brief, new road at Kinellan
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>

HER Number	EHG3376
Status	Event
Section:	N/A
Easting	246822
Northing	857178
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3376

Asset/Event Number	3849
Asset/Event Name	DBA and walkover survey - Fannyfield Farm, Evanton
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3378
Status	Event
Section:	N/A
Easting	255683
Northing	865625
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3378

Asset/Event Number	3850
Asset/Event Name	Watching brief at Wester Moy, Ross and Cromarty
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3379
Status	Event
Section:	N/A
Easting	247986
Northing	855230
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3379

Asset/Event Number	3851
Asset/Event Name	Field Reconnaissance, Cnoc na Moine and Cnoc Alasdair
Type of Asset/Event	Walkover survey
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3427
Status	Event
Section:	N/A
Easting	259797
Northing	872780
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3427

Asset/Event Number	3852
Asset/Event Name	Carrol Wood, Strath Brora
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG344
Status	Event
Section:	N/A
Easting	284703
Northing	906399
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG344

Asset/Event Number	3853
Asset/Event Name	Desk based assessment and walkover survey - proposed Cambusmore substation

Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3466
Status	Event
Section:	N/A
Easting	265443
Northing	897868
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3466

Asset/Event Number	3854
Asset/Event Name	Watching brief - Novar II Windfarm
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3467
Status	Event
Section:	N/A
Easting	254198
Northing	870451
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3467

Asset/Event Number	3855
Asset/Event Name	Walkover survey - Garve to Strathpeffer Water Main Renewal
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3486
Status	Event
Section:	N/A
Easting	243923

Northing	859436
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3486

Asset/Event Number	3856
Asset/Event Name	Desk-based assessment and walkover survey - proposed Braemore Wind Farm
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3487
Status	Event
Section:	N/A
Easting	255180
Northing	901325
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3487

Asset/Event Number	3857
Asset/Event Name	Whinny Knowe
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3508
Status	Event
Section:	N/A
Easting	295305
Northing	911321
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3508

Asset/Event Number	3858
Asset/Event Name	Watching brief, land east of Strathcarrick House, Heights of Inchvannie
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3553
Status	Event
Section:	N/A
Easting	249575
Northing	860587
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3553

Asset/Event Number	3859
Asset/Event Name	Desk based assessment and walkover survey - Coire Na Cloiche Wind Farm, Strath Rusdale
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3568
Status	Event
Section:	N/A
Easting	259466
Northing	880710
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3568

Asset/Event Number	3860
Asset/Event Name	Afforestable Land Survey: Rogart
Type of Asset/Event	Walkover survey
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3615

Status	Event
Section:	N/A
Easting	270512
Northing	906351
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3615

Asset/Event Number	3861
Asset/Event Name	Watching brief, Balnatink, Dunbeath
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3622
Status	Event
Section:	N/A
Easting	315167
Northing	931215
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3622

Asset/Event Number	3862
Asset/Event Name	Rapid survey, farmstead north of Balnatink, Dunbeath
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3623
Status	Event
Section:	N/A
Easting	315192
Northing	931210
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3623

Asset/Event Number	3863
Asset/Event Name	Desk-based assessment and walkover survey - Bank, Rogart
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3647
Status	Event
Section:	N/A
Easting	274124
Northing	902958
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3647

Asset/Event Number	3864
Asset/Event Name	DBA and walkover survey - Beauly-Denny overhead line replacement
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3730
Status	Event
Section:	N/A
Easting	238716
Northing	802706
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3730

Asset/Event Number	3865
Asset/Event Name	DBA and walkover survey - Beauly-Mossford OHL replacement
Type of Asset/Event	Survey extent

Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3750
Status	Event
Section:	N/A
Easting	242847
Northing	854800
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3750

Asset/Event Number	3866
Asset/Event Name	DBA and Walkover Survey - Grey Cairn, Dunbeath, Latheron
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3768
Status	Event
Section:	N/A
Easting	313416
Northing	926770
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3768

Asset/Event Number	3867
Asset/Event Name	DBA and Walkover Survey - Dunbeath, Latheron
Type of Asset/Event	Whole site extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3769
Status	Event
Section:	N/A
Easting	315197
Northing	931212

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3769

Asset/Event Number	3868
Asset/Event Name	Topographic survey - Urchany, Kilmorack
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3790
Status	Event
Section:	N/A
Easting	244266
Northing	845505
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3790

Asset/Event Number	3869
Asset/Event Name	DBA & Walkover survey - proposed wind farm, Achkeepster, Caithness
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG381
Status	Event
Section:	N/A
Easting	315640
Northing	950356
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG381

Asset/Event Number	3870
Asset/Event Name	DBA and walkover survey - Novar Estate Woodland Creation Scheme
Type of Asset/Event	Desk-based assessment; Walkover Survey
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3818
Status	Event
Section:	N/A
Easting	258330
Northing	870567
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3818

Asset/Event Number	3871
Asset/Event Name	Photographic survey - Tin Houses, Achterneed
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3836
Status	Event
Section:	N/A
Easting	248884
Northing	859620
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3836

Asset/Event Number	3872
Asset/Event Name	DBA and walkover survey - proposed A9 improvements, Helmsdale to Ord of Caithness
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG384
Status	Event

Section:	N/A
Easting	304597
Northing	917339
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG384

Asset/Event Number	3873
Asset/Event Name	DBA and walkover survey - Achork, by Rogart
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3863
Status	Event
Section:	N/A
Easting	277081
Northing	904390
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3863

Asset/Event Number	3874
Asset/Event Name	DBA and walkover survey - Achany Glen, Achinduich, Lairg, Sutherland
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3864
Status	Event
Section:	N/A
Easting	257553
Northing	900754
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/event/EHG3864

Asset/Event Number	3875
Asset/Event Name	Photographic recording - Farmhouse at Balno, Muir of Ord
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3937
Status	Event
Section:	N/A
Easting	248692
Northing	851332
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3937

Asset/Event Number	3876
Asset/Event Name	Field survey - Caithness Coastal Survey 1980-82
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG405
Status	Event
Section:	N/A
Easting	325297
Northing	973203
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG405

Asset/Event Number	3877
Asset/Event Name	DBA and walkover survey - proposed Bad a' Cheo Windfarm, Watten
Type of Asset/Event	Survey extent
Date and/or Period	<Null>

Listing No./NRHE Number	<Null>
HER Number	EHG4081
Status	Event
Section:	N/A
Easting	316892
Northing	948828
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4081

Asset/Event Number	3878
Asset/Event Name	DBA and walkover survey - Upper Smerral
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4094
Status	Event
Section:	N/A
Easting	316311
Northing	934170
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4094

Asset/Event Number	3879
Asset/Event Name	Lairg Survey 1978
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG412
Status	Event
Section:	N/A
Easting	259099
Northing	897077
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG412

Asset/Event Number	3880
Asset/Event Name	DBA & walkover survey - Clynemilton, Clyne, Sutherland
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4129
Status	Event
Section:	N/A
Easting	290384
Northing	907194
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4129

Asset/Event Number	3881
Asset/Event Name	DBA and walkover survey - Castle Leod, Strathpeffer, Ross-shire
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4162
Status	Event
Section:	N/A
Easting	248285
Northing	859418
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4162

Asset/Event Number	3882

Asset/Event Name	Geophysical Survey - Spittal AC & DC Converter Substation
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4168
Status	Event
Section:	N/A
Easting	315512
Northing	955503
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4168

Asset/Event Number	3883
Asset/Event Name	DBA - Glen Loth, Sutherland
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4194
Status	Event
Section:	N/A
Easting	294071
Northing	914152
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4194

Asset/Event Number	3884
Asset/Event Name	DBA and walkover survey - Loch Farlary to Bridge of Horn, Golspie
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4206
Status	Event
Section:	N/A

Easting	278703
Northing	905099
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4206

Asset/Event Number	3885
Asset/Event Name	DBA & walkover survey - Auchmore Farm, Muir of Ord Hydro Scheme
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4209
Status	Event
Section:	N/A
Easting	248976
Northing	849853
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4209

Asset/Event Number	3886
Asset/Event Name	Trial Trenching - Spittal AC & DC Convertor Substation
Type of Asset/Event	Trenches
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4269
Status	Event
Section:	N/A
Easting	315534
Northing	955686
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4269

Asset/Event Number	3887
Asset/Event Name	DBA and walkover survey - proposed Spittal Hill Wind Farm
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4314
Status	Event
Section:	N/A
Easting	317559
Northing	956130
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4314

Asset/Event Number	3888
Asset/Event Name	Desk based assessment - proposed Forse Wind Farm, Caithness
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4329
Status	Event
Section:	N/A
Easting	319439
Northing	942734
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4329

Asset/Event Number	3889
Asset/Event Name	DBA and walkover survey - proposed Strath Brora Wind Farm, Sutherland
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>

HER Number	EHG4336
Status	Event
Section:	N/A
Easting	279284
Northing	904930
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4336

Asset/Event Number	3890
Asset/Event Name	DBA and walkover survey - proposed Dunbeath Wind Farm
Type of Asset/Event	Desk-based assessment; Walkover Survey
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4346
Status	Event
Section:	N/A
Easting	311824
Northing	930969
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4346

Asset/Event Number	3891
Asset/Event Name	Watching brief - Am Baile by Invershin, Lairg
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4347
Status	Event
Section:	N/A
Easting	257878
Northing	895754
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4347

Asset/Event Number	3892
Asset/Event Name	DBA and walkover survey - Cambusmore Estate Wind Farm
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4350
Status	Event
Section:	N/A
Easting	266238
Northing	899345
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4350

Asset/Event Number	3893
Asset/Event Name	DBA and walkover survey - proposed Spittal Hill II Wind Farm
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4360
Status	Event
Section:	N/A
Easting	318050
Northing	956261
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4360

Asset/Event Number	3894
Asset/Event Name	DBA and walkover survey - Kilbraur Wind Farm section 36 extension

Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4381
Status	Event
Section:	N/A
Easting	278338
Northing	906678
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4381

Asset/Event Number	3895
Asset/Event Name	Walkover survey - Kilbraur Wind Farm North Borrow Pit
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4388
Status	Event
Section:	N/A
Easting	281348
Northing	904287
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4388

Asset/Event Number	3896
Asset/Event Name	Photographic survey - The Portland Hall, Borgue, Berriedale
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4414
Status	Event
Section:	N/A
Easting	312169

Northing	923093
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4414

Asset/Event Number	3897
Asset/Event Name	Rescue excavation and photographic survey - Craig-Na-Feich, Achavanich, Caithness
Type of Asset/Event	Excavation extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4423
Status	Event
Section:	N/A
Easting	317837
Northing	943335
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4423

Asset/Event Number	3898
Asset/Event Name	Watching brief - Auchmore Farm, Muir of Ord Hydro Scheme
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4451
Status	Event
Section:	N/A
Easting	248875
Northing	849757
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4451

Asset/Event Number	3899
Asset/Event Name	DBA and walkover survey - proposed Glenmorie Wind Farm
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4464
Status	Event
Section:	N/A
Easting	252422
Northing	882339
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4464

Asset/Event Number	3900
Asset/Event Name	Watching Brief - Beauly to Mossford OHL Replacement T71-78
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4482
Status	Event
Section:	N/A
Easting	247775
Northing	852459
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4482

Asset/Event Number	3901
Asset/Event Name	DBA and walkover survey - proposed Clach Liath Wind Farm
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4486

Status	Event
Section:	N/A
Easting	253179
Northing	866586
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4486

Asset/Event Number	3902
Asset/Event Name	DBA and Walkover Survey - Loth Burn Hydro Development
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4494
Status	Event
Section:	N/A
Easting	294465
Northing	910768
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4494

Asset/Event Number	3903
Asset/Event Name	Walkover survey - Auchinduich, Sutherland
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4519
Status	Event
Section:	N/A
Easting	261095
Northing	898115
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4519

Asset/Event Number	3904
Asset/Event Name	Dochcarty, nr Dingwall
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG452
Status	Event
Section:	N/A
Easting	251925
Northing	860536
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG452

Asset/Event Number	3905
Asset/Event Name	Morvich, Proposed Woodland
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG454
Status	Event
Section:	N/A
Easting	275505
Northing	900981
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG454

Asset/Event Number	3906
Asset/Event Name	DBA and Walkover Survey - Land At Woodlands, Dingwall, IV15 9TT
Type of Asset/Event	Survey extent

Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4542
Status	Event
Section:	N/A
Easting	255362
Northing	862479
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4542

Asset/Event Number	3907
Asset/Event Name	DBA and Walkover Survey - Caorach Hydro Scheme, Wyvis Estate, Evanton
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4571
Status	Event
Section:	N/A
Easting	252227
Northing	867588
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4571

Asset/Event Number	3908
Asset/Event Name	Test Pitting Evaluation - Castle Leod, Strathpeffer
Type of Asset/Event	Excavation extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4589
Status	Event
Section:	N/A
Easting	248613
Northing	859303

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4589

Asset/Event Number	3909
Asset/Event Name	DBA and Walkover Survey - Land to south of existing substation, Dounreay Nuclear Research
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4611
Status	Event
Section:	N/A
Easting	307434
Northing	964533
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4611

Asset/Event Number	3910
Asset/Event Name	DBA - West Garty Proposed Wind Farm, West Garty Estate, Helmsdale
Type of Asset/Event	Whole site extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4627
Status	Event
Section:	N/A
Easting	297598
Northing	913460
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4627

Asset/Event Number	3911
Asset/Event Name	DBA and Walkover Survey - Morvich Estate
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4632
Status	Event
Section:	N/A
Easting	276731
Northing	900409
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4632

Asset/Event Number	3912
Asset/Event Name	Photographic Survey - Land 180M West Of Houstry Of Dunn, Watten
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4635
Status	Event
Section:	N/A
Easting	320539
Northing	954828
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4635

Asset/Event Number	3913
Asset/Event Name	DBA and Walkover Survey - Proposed Power Transmission Cable from Grabhair, Isle of Lewis,
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4644
Status	Event

Section:	N/A
Easting	229419
Northing	873240
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4644

Asset/Event Number	3914
Asset/Event Name	DBA and Walkover Survey - Gartymore Wind Farm
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4648
Status	Event
Section:	N/A
Easting	298842
Northing	915279
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4648

Asset/Event Number	3915
Asset/Event Name	DBA and Walkover Survey - Gartymore Wind Farm Access Route
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4649
Status	Event
Section:	N/A
Easting	299955
Northing	914387
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/event/EHG4649

Asset/Event Number	3916
Asset/Event Name	Walkover survey - proposed West Garty Windfarm, near Helmsdale
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4652
Status	Event
Section:	N/A
Easting	297046
Northing	914090
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4652

Asset/Event Number	3917
Asset/Event Name	Topographic and field Survey - Strath of Kildonan
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4669
Status	Event
Section:	N/A
Easting	287635
Northing	919921
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4669

Asset/Event Number	3918
Asset/Event Name	Walkover Survey - Achormlarie Hill, Dornoch
Type of Asset/Event	Survey extent
Date and/or Period	<Null>

Listing No./NRHE Number	<Null>
HER Number	EHG4684
Status	Event
Section:	N/A
Easting	268358
Northing	896284
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4684

Asset/Event Number	3919
Asset/Event Name	Photographic Survey - Skiag, Rogart
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4700
Status	Event
Section:	N/A
Easting	274188
Northing	903817
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4700

Asset/Event Number	3920
Asset/Event Name	Bridge Inspection - An Uidh Bridge
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4702
Status	Event
Section:	N/A
Easting	264190
Northing	895650
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4702

Asset/Event Number	3921
Asset/Event Name	DBA and Walkover Survey - Uppat Farm Hydro Scheme
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4703
Status	Event
Section:	N/A
Easting	284572
Northing	907150
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4703

Asset/Event Number	3922
Asset/Event Name	DBA and Walkover Survey - Lairg-Rhaoine 33kV Overhead Line Refurbishment
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4713
Status	Event
Section:	N/A
Easting	268079
Northing	904100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4713

Asset/Event Number	3923

Asset/Event Name	Walkover Survey - Strath Sgitheach Forestry Survey
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4729
Status	Event
Section:	N/A
Easting	251703
Northing	862589
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4729

Asset/Event Number	3924
Asset/Event Name	Watching brief and excavation - Beauly-Denny OHL Tower BF8, Fanellan, Beauly
Type of Asset/Event	Excavation extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4773
Status	Event
Section:	N/A
Easting	248296
Northing	842774
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4773

Asset/Event Number	3925
Asset/Event Name	Watching brief and excavation - Beauly-Denny OHL Tower BF7, Fanellan, Beauly
Type of Asset/Event	Excavation extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4774
Status	Event
Section:	N/A

Easting	248629
Northing	843135
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4774

Asset/Event Number	3926
Asset/Event Name	DBA and Watching Brief - Redlesburn 150m NW of Rhian Cottage, Berriedale, Caithness
Type of Asset/Event	Whole site extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4792
Status	Event
Section:	N/A
Easting	313125
Northing	926186
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4792

Asset/Event Number	3927
Asset/Event Name	Trial Trenching and Photographic Survey - Land NE of Lyndale, Kiltarlity
Type of Asset/Event	Excavation extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4799
Status	Event
Section:	N/A
Easting	247720
Northing	841470
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4799

Asset/Event Number	3928
Asset/Event Name	DBA and Walkover Survey - A9 at Berriedale Braes
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4804
Status	Event
Section:	N/A
Easting	312030
Northing	922878
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4804

Asset/Event Number	3929
Asset/Event Name	DBA and Walkover Survey - Berriedale Woodland Grant Scheme
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4807
Status	Event
Section:	N/A
Easting	310020
Northing	922007
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4807

Asset/Event Number	3930
Asset/Event Name	Inveran, Achany Wood
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>

HER Number	EHG483
Status	Event
Section:	N/A
Easting	256828
Northing	898134
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG483

Asset/Event Number	3931
Asset/Event Name	Survey and excavation - Kilearnan Hill, Sutherland
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4867
Status	Event
Section:	N/A
Easting	294954
Northing	917402
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4867

Asset/Event Number	3932
Asset/Event Name	Photographic Survey - Thornfield, Strathpeffer
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4905
Status	Event
Section:	N/A
Easting	249057
Northing	859998
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4905

Asset/Event Number	3933
Asset/Event Name	Photographic Survey - St Callans Old Manse, Rogart
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4930
Status	Event
Section:	N/A
Easting	273975
Northing	903404
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4930

Asset/Event Number	3934
Asset/Event Name	Photographic Survey - Ivy Cottage, Berriedale
Type of Asset/Event	Survey
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4955
Status	Event
Section:	N/A
Easting	311798
Northing	922766
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4955

Asset/Event Number	3935
Asset/Event Name	Walkover Survey - Halsary Windfarm, Mybster

Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4966
Status	Event
Section:	N/A
Easting	318165
Northing	950117
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4966

Asset/Event Number	3936
Asset/Event Name	Walkover Survey - Aigas Community Forest
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4968
Status	Event
Section:	N/A
Easting	245650
Northing	842340
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4968

Asset/Event Number	3937
Asset/Event Name	Docherty Water Pipeline Renewal
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG538
Status	Event
Section:	N/A
Easting	251049

Northing	860930
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG538

Asset/Event Number	3938
Asset/Event Name	Water Supply Upgrading & Mains Replacement, Rogart
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG539
Status	Event
Section:	N/A
Easting	271552
Northing	903822
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG539

Asset/Event Number	3939
Asset/Event Name	Walkover survey - proposed route of water main, Backies to Helmsdale
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG540
Status	Event
Section:	N/A
Easting	292884
Northing	908326
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG540

Asset/Event Number	3940
Asset/Event Name	DBA & walkover survey - proposed Hydro-Electric Scheme, Wyvis, Strathpeffer
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG547
Status	Event
Section:	N/A
Easting	245672
Northing	863212
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG547

Asset/Event Number	3941
Asset/Event Name	WGS 3478 Ruttle Wood
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG601
Status	Event
Section:	N/A
Easting	247393
Northing	842206
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG601

Asset/Event Number	3942
Asset/Event Name	Dunrobin Glen
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG612

Status	Event
Section:	N/A
Easting	279826
Northing	904130
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG612

Asset/Event Number	3943
Asset/Event Name	DBA and walkover survey - Buolfruich, Houstry
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG626
Status	Event
Section:	N/A
Easting	315791
Northing	935540
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG626

Asset/Event Number	3944
Asset/Event Name	Trial trenching and watching brief - Buolfruich, Houstry
Type of Asset/Event	Excavation extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG633
Status	Event
Section:	N/A
Easting	315514
Northing	935689
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG633

Asset/Event Number	3945
Asset/Event Name	Spittal, Watten, Extension to Flagstone Quarry
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG640
Status	Event
Section:	N/A
Easting	317191
Northing	954251
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG640

Asset/Event Number	3946
Asset/Event Name	Abhainn Sgitheach, Dingwall
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG642
Status	Event
Section:	N/A
Easting	250992
Northing	862973
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG642

Asset/Event Number	3947
Asset/Event Name	Watching brief - Novar Windfarm access tracks and compound
Type of Asset/Event	Watching brief extent

Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG704
Status	Event
Section:	N/A
Easting	256472
Northing	869075
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG704

Asset/Event Number	3948
Asset/Event Name	Clynemilton, Brora, Highland
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG764
Status	Event
Section:	N/A
Easting	289940
Northing	907809
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG764

Asset/Event Number	3949
Asset/Event Name	Muir of Ord, Water Mains Renewal Project
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG771
Status	Event
Section:	N/A
Easting	249496
Northing	850745

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG771

Asset/Event Number	3950
Asset/Event Name	Photographic survey - Lynechork farmstead, Glen Glass
Type of Asset/Event	Survey extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG780
Status	Event
Section:	N/A
Easting	256710
Northing	867263
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG780

Asset/Event Number	3951
Asset/Event Name	Loch Farlary, near Golspie
Type of Asset/Event	Whole site extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG818
Status	Event
Section:	N/A
Easting	277460
Northing	904910
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG818

Asset/Event Number	3952
Asset/Event Name	DBA and walkover survey - Navidale Farm, Helmsdale
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG883
Status	Event
Section:	N/A
Easting	305218
Northing	917368
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG883

Asset/Event Number	3953
Asset/Event Name	Glen Glass Hydro Scheme
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG905
Status	Event
Section:	N/A
Easting	255068
Northing	868141
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG905

Asset/Event Number	3954
Asset/Event Name	Mulbuie Water Supply Zone Mains Renewals Design
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG912
Status	Event

Section:	N/A
Easting	251245
Northing	851352
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG912

Asset/Event Number	3955
Asset/Event Name	Contin and Strathpeffer, Water Mains Replacements
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG917
Status	Event
Section:	N/A
Easting	248355
Northing	858231
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG917

Asset/Event Number	3956
Asset/Event Name	Walkover Survey - Dunbeath Estate
Type of Asset/Event	Watching brief extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG98
Status	Event
Section:	N/A
Easting	315420
Northing	930467
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/event/EHG98

Asset/Event Number	3957
Asset/Event Name	Trial trenching and watching brief - Buolfruich, Houstry, Caithness
Type of Asset/Event	Excavation extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG997
Status	Event
Section:	N/A
Easting	315670
Northing	935348
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG997

Asset/Event Number	3958
Asset/Event Name	Photographic Survey - East Kinnauld, Rogart
Type of Asset/Event	Survey
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5030
Status	Event
Section:	N/A
Easting	273971
Northing	901161
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5030

Asset/Event Number	3959
Asset/Event Name	Walkover Survey - Torrish Woodlands, Kildonan, Sutherland
Type of Asset/Event	Walkover survey
Date and/or Period	<Null>

Listing No./NRHE Number	<Null>
HER Number	EHG5036
Status	Event
Section:	N/A
Easting	294255
Northing	917862
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5036

Asset/Event Number	3960
Asset/Event Name	Watching Brief - Glen Loth Hydro Scheme, Kintradwell, Sutherland
Type of Asset/Event	Watching brief
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5041
Status	Event
Section:	N/A
Easting	294128
Northing	912185
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5041

Asset/Event Number	3961
Asset/Event Name	Watching Brief - Land 500m NW of Carrol Cottage, Brora
Type of Asset/Event	Monitored areas
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5039
Status	Event
Section:	N/A
Easting	284450
Northing	907224
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5039

Asset/Event Number	3962
Asset/Event Name	Walkover Survey - Navidale Wind Farm
Type of Asset/Event	Walkover survey
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5067
Status	Event
Section:	N/A
Easting	304486
Northing	918505
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5067

Asset/Event Number	3963
Asset/Event Name	Desk-based assessment - proposed Auchmore Wind Turbine
Type of Asset/Event	Desk-based assessment
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4460
Status	Event
Section:	N/A
Easting	247427
Northing	849031
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4460

Asset/Event Number	3964

Asset/Event Name	Walkover Survey - Allt Dearg Hydro
Type of Asset/Event	Walkover survey
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5119
Status	Event
Section:	N/A
Easting	246408
Northing	861527
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5119

Asset/Event Number	3965
Asset/Event Name	Photographic Survey - East Kinnauld, Rogart
Type of Asset/Event	Survey
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5140
Status	Event
Section:	N/A
Easting	273971
Northing	901161
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5140

Asset/Event Number	3966
Asset/Event Name	Excavation at Adam's Croft
Type of Asset/Event	Excavation extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5187
Status	Event
Section:	N/A

Easting	252108
Northing	862170
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5187

Asset/Event Number	3967
Asset/Event Name	Watching Brief - Coire na Cloiche Wind Farm
Type of Asset/Event	Watching brief
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5203
Status	Event
Section:	N/A
Easting	259538
Northing	880824
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5203

Asset/Event Number	3968
Asset/Event Name	Field Survey - Allt A' Bhurg Brock, Ousdale
Type of Asset/Event	Walkover survey
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5259
Status	Event
Section:	N/A
Easting	307129
Northing	918816
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5259

Asset/Event Number	3969
Asset/Event Name	Watching Brief - Kiltarlity Mains Rehabilitation Project
Type of Asset/Event	Watching brief
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5280
Status	Event
Section:	N/A
Easting	249114
Northing	841822
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5280

Asset/Event Number	3970
Asset/Event Name	Conservation and Excavation - Dunbeath Broch
Type of Asset/Event	Conservation; Excavation
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5310
Status	Event
Section:	N/A
Easting	315536
Northing	930450
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5310

Asset/Event Number	3971
Asset/Event Name	Trial Trenching - A9 Berriedale Braes, Berriedale, Caithness
Type of Asset/Event	Trial trench
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>

HER Number	EHG5318
Status	Event
Section:	N/A
Easting	312058
Northing	922794
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5318

Asset/Event Number	3972
Asset/Event Name	Watching Brief - A9 Berriedale Braes, Berriedale, Caithness
Type of Asset/Event	Watching brief
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5319
Status	Event
Section:	N/A
Easting	312074
Northing	922682
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5319

Asset/Event Number	3973
Asset/Event Name	Excavation Phase 1 - A9 Berriedale Braes, Berriedale, Caithness
Type of Asset/Event	Excavation extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5320
Status	Event
Section:	N/A
Easting	312144
Northing	922759
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5320

Asset/Event Number	3974
Asset/Event Name	Watching brief and evaluation - Dounreay-Mybster OHL mitigation works
Type of Asset/Event	Monitored areas
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5327
Status	Event
Section:	N/A
Easting	316005
Northing	954726
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5327

Asset/Event Number	3975
Asset/Event Name	Watching brief - Bad a' Cheo Wind Farm, Achkeepster
Type of Asset/Event	Watching brief
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5333
Status	Event
Section:	N/A
Easting	317041
Northing	947636
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5333

Asset/Event Number	3976
Asset/Event Name	Salvage Recording and Watching Brief - Land South of No 1 Beaufort Farm Cottages, Kiltarlity

Type of Asset/Event	Watching brief
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5338
Status	Event
Section:	N/A
Easting	249675
Northing	842081
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5338

Asset/Event Number	3977
Asset/Event Name	Trial Trenching - Land South of No 1 Beaufort Farm Cottages, Kiltarlity
Type of Asset/Event	Trial trench
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5339
Status	Event
Section:	N/A
Easting	249673
Northing	842080
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5339

Asset/Event Number	3978
Asset/Event Name	Excavation - Torbreck Longhouse, Loch Bhuide
Type of Asset/Event	Excavation extent
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5376
Status	Event
Section:	N/A
Easting	264881

Northing	898041
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5376

Asset/Event Number	3979
Asset/Event Name	Walkover and topographic surveys - Urchany
Type of Asset/Event	Desk-based assessment; Walkover Survey
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5395
Status	Event
Section:	N/A
Easting	244852
Northing	845518
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5395

Asset/Event Number	3980
Asset/Event Name	Walkover survey - proposed Loch Bhuide substation
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5398
Status	Event
Section:	N/A
Easting	265202
Northing	897966
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5398

Asset/Event Number	3981
Asset/Event Name	DBA and walkover survey - Mybster-Sealky Head
Type of Asset/Event	Desk-based assessment; Walkover Survey
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5402
Status	Event
Section:	N/A
Easting	332960
Northing	953198
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5402

Asset/Event Number	3982
Asset/Event Name	DBA and walkover survey - proposed Moray Firth Hub & Caithness HVDC Connection convert
Type of Asset/Event	Desk-based assessment; Walkover Survey
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5401
Status	Event
Section:	N/A
Easting	315505
Northing	955568
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5401

Asset/Event Number	3983
Asset/Event Name	Topographic survey - Orrin Falls Hydro scheme
Type of Asset/Event	Survey
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5404

Status	Event
Section:	N/A
Easting	246875
Northing	851695
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5404

Asset/Event Number	3984
Asset/Event Name	Watching brief - Beauly-Mossford OHL replacement T61-64 (Loch Achonachie)
Type of Asset/Event	Watching brief
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5420
Status	Event
Section:	N/A
Easting	244820
Northing	853998
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5420

Asset/Event Number	3985
Asset/Event Name	Watching brief - Beauly-Mossford OHL replacement T86-97 (Corry Wood)
Type of Asset/Event	Monitored area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5421
Status	Event
Section:	N/A
Easting	249462
Northing	849751
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5421

Asset/Event Number	3986
Asset/Event Name	Watching brief - Beauly-Mossford OHL replacement
Type of Asset/Event	Watching brief
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5423
Status	Event
Section:	N/A
Easting	239152
Northing	858816
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5423

Asset/Event Number	3987
Asset/Event Name	Walkover survey - Beauly-Mossford OHL replacement
Type of Asset/Event	Walkover survey
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5435
Status	Event
Section:	N/A
Easting	239142
Northing	858204
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5435

Asset/Event Number	3988
Asset/Event Name	Watching Brief - Cnoc Udais
Type of Asset/Event	Trenches

Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG140
Status	Event
Section:	N/A
Easting	248169
Northing	849867
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG140

Asset/Event Number	3989
Asset/Event Name	DBA and walkover Survey - Fairburn Wind Farm extension
Type of Asset/Event	Desk-based assessment; Walkover Survey
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4530
Status	Event
Section:	N/A
Easting	243438
Northing	850699
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4530

Asset/Event Number	3990
Asset/Event Name	Archaeological assessment - Fairburn Windfarm, Urray
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1284
Status	Event
Section:	N/A
Easting	241995
Northing	852298

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1284

Asset/Event Number	3991
Asset/Event Name	Walkover survey - proposed Fairburn Windfarm, Dingwall
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3060
Status	Event
Section:	N/A
Easting	242006
Northing	852288
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3060

Asset/Event Number	3992
Asset/Event Name	Photographic record - Redburn Steading
Type of Asset/Event	Survey
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5605
Status	Event
Section:	N/A
Easting	257166
Northing	867033
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5605

Asset/Event Number	3993
Asset/Event Name	Trial trenching - proposed new housing, Kinellan Drive, Strathpeffer
Type of Asset/Event	Trenches
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5675
Status	Event
Section:	N/A
Easting	247632
Northing	857560
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5675

Asset/Event Number	3994
Asset/Event Name	DBA and walkover survey - proposed South Kilbraur Wind Farm
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5687
Status	Event
Section:	N/A
Easting	276709
Northing	904577
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5687

Asset/Event Number	3995
Asset/Event Name	DBA and walkover survey - proposed Garvary Wind Farm
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5700
Status	Event

Section:	N/A
Easting	261418
Northing	899674
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5700

Asset/Event Number	3996
Asset/Event Name	Walkover survey - proposed Garvary Wind Farm
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5701
Status	Event
Section:	N/A
Easting	261418
Northing	899674
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5701

Asset/Event Number	3997
Asset/Event Name	DBA and walkover survey - proposed Wind turbine (Tacher A)
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5713
Status	Event
Section:	N/A
Easting	317311
Northing	947371
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://her.highland.gov.uk/event/EHG5713

Asset/Event Number	3998
Asset/Event Name	DBA and walkover survey - proposed Wind turbine (Tacher B)
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5714
Status	Event
Section:	N/A
Easting	317329
Northing	947294
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5714

Asset/Event Number	3999
Asset/Event Name	DBA and walkover survey - water main replacement, Burn of Houstry, Dunbeath
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5764
Status	Event
Section:	N/A
Easting	315527
Northing	930694
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5764

Asset/Event Number	4000
Asset/Event Name	DBA and walkover survey - Lairg-Loch Buidhe OHL reinforcement
Type of Asset/Event	Study area
Date and/or Period	<Null>

Listing No./NRHE Number	<Null>
HER Number	EHG5778
Status	Event
Section:	N/A
Easting	261170
Northing	899566
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5778

Asset/Event Number	4001
Asset/Event Name	Building assessment and interpretation - Fairburn Tower, Muir of Ord
Type of Asset/Event	Study area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5782
Status	Event
Section:	N/A
Easting	246946
Northing	852351
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5782

Asset/Event Number	4002
Asset/Event Name	Historic building recording - Fairburn Tower, Muir of Ord
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5783
Status	Event
Section:	N/A
Easting	246943
Northing	852348
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5783

Asset/Event Number	4003
Asset/Event Name	Geophysical survey - Fairburn Tower, Muir of Ord
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5784
Status	Event
Section:	N/A
Easting	246943
Northing	852332
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5784

Asset/Event Number	4004
Asset/Event Name	Watching brief - glamping pod development, Strathcarrick House, Heights of Inchvannie
Type of Asset/Event	Monitored areas
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5787
Status	Event
Section:	N/A
Easting	249632
Northing	860565
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5787

Asset/Event Number	4005

Asset/Event Name	Watching brief and trial trenching - Fairburn Tower, Muir of Ord
Type of Asset/Event	Trenches
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5785
Status	Event
Section:	N/A
Easting	246952
Northing	852341
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5785

Asset/Event Number	4006
Asset/Event Name	Desk-based assessment - proposed Bad Fearn Wind Farm
Type of Asset/Event	Desk-based assessment
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5843
Status	Event
Section:	N/A
Easting	312266
Northing	931639
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5843

Asset/Event Number	4007
Asset/Event Name	Walkover survey - woodland creation scheme, Fairburn Estate, Muir of Ord
Type of Asset/Event	Survey areas
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5869
Status	Event
Section:	N/A

Easting	243373
Northing	850758
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5869

Asset/Event Number	4008
Asset/Event Name	DBA and walkover survey - proposed Kintradwell Wind Farm
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5878
Status	Event
Section:	N/A
Easting	291188
Northing	910982
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5878

Asset/Event Number	4009
Asset/Event Name	Walkover Survey - Strath Sgitheach
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5928
Status	Event
Section:	N/A
Easting	252357
Northing	863188
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5928

Asset/Event Number	4010
Asset/Event Name	Watching brief - geotechnical test pits, Fairburn Tower
Type of Asset/Event	Test pits
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5945
Status	Event
Section:	N/A
Easting	246952
Northing	852307
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5945

Asset/Event Number	4011
Asset/Event Name	Watching brief - new housing development, Kinellan Drive, Strathpeffer
Type of Asset/Event	Monitored areas
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5946
Status	Event
Section:	N/A
Easting	247545
Northing	857623
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5946

Asset/Event Number	4012
Asset/Event Name	Trial trenching - new house plot, Culrain, Ardgay
Type of Asset/Event	Trenches
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>

HER Number	EHG5950
Status	Event
Section:	N/A
Easting	256931
Northing	894464
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5950

Asset/Event Number	4013
Asset/Event Name	DBA and walkover survey - proposed wind turbine, Torranan Slèibh, Evanton
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5980
Status	Event
Section:	N/A
Easting	253716
Northing	867225
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5980

Asset/Event Number	4014
Asset/Event Name	Watching brief - new house plot, Clash Vaan Croft, Heights of Fodderty
Type of Asset/Event	Monitored areas
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5988
Status	Event
Section:	N/A
Easting	251043
Northing	860717
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5988

Asset/Event Number	4015
Asset/Event Name	Watching brief - test pits, West of Orkney Wind Farm onshore investigations
Type of Asset/Event	Trial pits
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG5994
Status	Event
Section:	N/A
Easting	309313
Northing	963802
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG5994

Asset/Event Number	4016
Asset/Event Name	Metal detection survey - Community Hall extension, Culrain, Ardgay
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG6002
Status	Event
Section:	N/A
Easting	257622
Northing	894787
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG6002

Asset/Event Number	4017
Asset/Event Name	Trial trenching - Community Hall extension, Culrain, Ardgay

Type of Asset/Event	Trenches
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG6003
Status	Event
Section:	N/A
Easting	257624
Northing	894778
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG6003

Asset/Event Number	4018
Asset/Event Name	Trial trenching - community excavation, Lower Caen, Kildonan (Translocation; Excavating the
Type of Asset/Event	Trenches
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG6056
Status	Event
Section:	N/A
Easting	301357
Northing	917814
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG6056

Asset/Event Number	4019
Asset/Event Name	Trial trenching - new house plot, Heights of Inchvannie
Type of Asset/Event	Trenches
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG6057
Status	Event
Section:	N/A
Easting	249370

Northing	860427
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG6057

Asset/Event Number	4020
Asset/Event Name	DBA and walkover survey - proposed telecommunications mast, Acharn Wood
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG6085
Status	Event
Section:	N/A
Easting	259247
Northing	873072
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG6085

Asset/Event Number	4021
Asset/Event Name	DBA and walkover survey - proposed Abhainn Dubh Wind Farm
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG6109
Status	Event
Section:	N/A
Easting	253719
Northing	865559
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG6109

Asset/Event Number	4022
Asset/Event Name	Walkover survey - proposed substation, Spittal
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG6121
Status	Scheduled Monument
Section:	N/A
Easting	315875
Northing	956838
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG6121

Asset/Event Number	4023
Asset/Event Name	Watching brief - geotechnical test pitting, proposed substation, Spittal
Type of Asset/Event	Test pits
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG6122
Status	Conservation Area
Section:	N/A
Easting	316209
Northing	956498
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG6122

Asset/Event Number	4024
Asset/Event Name	DBA and walkover survey - proposed battery storage facility, Loch Toftinghall, Mybster
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG6129

Status	Event
Section:	N/A
Easting	318092
Northing	951842
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG6129

Asset/Event Number	4025
Asset/Event Name	Watching brief and rescue recording - Achavanich Stone Setting, Caithness
Type of Asset/Event	Watching Brief; Rescue Excavation
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG1047
Status	Event
Section:	N/A
Easting	318776
Northing	941750
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG1047

Asset/Event Number	4026
Asset/Event Name	DBA and walkover survey - proposed inderground cabling, Golticlay-Stemster
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG6176
Status	Event
Section:	N/A
Easting	318153
Northing	942535
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG6176

Asset/Event Number	4027
Asset/Event Name	Watching brief - ground investigations, new substation, Loch Buidhe
Type of Asset/Event	Test pits and boreholes
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG6156
Status	Event
Section:	N/A
Easting	265428
Northing	897558
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG6156

Asset/Event Number	4028
Asset/Event Name	Walkover survey - proposed Golticlay wind farm
Type of Asset/Event	Survey area
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG4964
Status	Event
Section:	N/A
Easting	322296
Northing	940515
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG4964

Asset/Event Number	4029
Asset/Event Name	Trial trench, Culrain
Type of Asset/Event	Trial trench

Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG2929
Status	Event
Section:	N/A
Easting	257400
Northing	894700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG2929

Asset/Event Number	4030
Asset/Event Name	Trial trenching - Fairburn Wind Farm
Type of Asset/Event	Trial trench
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3061
Status	Event
Section:	N/A
Easting	245629
Northing	854156
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3061

Asset/Event Number	4031
Asset/Event Name	Watching Brief and Site Visits: Lairg 33kv Overhead Line Renewal
Type of Asset/Event	Watching Brief; Site Visits
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3396
Status	Event
Section:	N/A
Easting	274561
Northing	901129

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3396

Asset/Event Number	4032
Asset/Event Name	Watching brief - Novar II Windfarm
Type of Asset/Event	Watching brief
Date and/or Period	<Null>
Listing No./NRHE Number	<Null>
HER Number	EHG3436
Status	Event
Section:	N/A
Easting	255542
Northing	870037
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/event/EHG3436

Asset/Event Number	4033
Asset/Event Name	Loedebest,settlement 1300m W of
Type of Asset/Event	Secular: settlement, including deserted, depopulated and townships
Date and/or Period	Post-medieval
Listing No./NRHE Number	SM5189
HER Number	<Null>
Status	Scheduled Monument
Section:	N/A
Easting	312458
Northing	312458
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/apex/f?p=1505:300:::::VIEWTYPE,VIEWREF:designation,SM5186

Asset/Event Number	4034
Asset/Event Name	Strathpeffer Conservation Area
Type of Asset/Event	Conservation Area
Date and/or Period	Post-medieval
Listing No./NRHE Number	CA123
HER Number	<Null>
Status	Conservation Area
Section:	N/A
Easting	248335
Northing	858225
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	http://www.legislation.gov.uk/ukpga/1997/9

Appendix 1: Gazetteer of Heritage Assets and Events

Asset/Event Number	1
Asset/Event Name	Buolacrabher, settlement 1170m S of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM6014; ND13SE 43
HER Number	MHG1169; MHG1169
Status	Scheduled Monument
Section:	N/A
Easting	315467
Northing	933512
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM6014 The monument consists of a prehistoric settlement of 2 hut circles and associated traces of cultivation. The SW hut measures about 5.5m in diameter with a wall 0.2m high and spread to about 2m. The entrance is to the SSE. The E hut measures 7m in diameter with a wall 0.3m high and 2 to 2.5m wide. This hut incorporates a large quantity of stone in its construction and several stones may indicate radial partitions of the interior. The entrance to this hut appears to be to the NW. There are 2 clearance cairns immediately to the N of the huts and the area around the cairns and between the cairns is flat and appears to have been cultivated. The area to be scheduled measures 85m E-W by 80m N-S, to include the hut circles and cairns and an area around in which traces of activities associated with these structures may survive. The edge of the scheduled area to the N is defined by an old area of peat cutting. To the E an old track which ascends the hill slope is excluded from the scheduled area. To the S the scheduled area extends 20m beyond the hut circles, while to the W the edge of the area is marked by the steep slope 10m W of the W hut circle. The area proposed for scheduling is shown in red on the attached map. Statement of National Importance The site is of national importance for its potential to contribute to an understanding of prehistoric settlement and agriculture. The hut circles incorporate important information about prehistoric round house construction and evidence for the domestic life of their inhabitants. The cairns and area of arable land constitute information on later prehistoric farming practices. References RCAHMS records the monument as ND 13 SE 43.
Asset/Event Number	2
Asset/Event Name	Minera, hut circles 330m SSE of, 370m ESE of and 270m E of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM6015; ND13SE 42
HER Number	Various
Status	Scheduled Monument

Section:	N/A
Easting	315760
Northing	934449
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM6015 The monument consists of a number of prehistoric hut circles on W- facing moorland. A group of 4 hut circles and associated clearance cairns are centred at ND157344, 2 further hut circles at ND158345 and a single hut circle at ND15813467. Three areas are to be scheduled: The S area measures 150m E-W by 170m SSE-NNW, the E area measures 95m SW-NE by 50m NW-SE and the N area 40m in diameter. These three areas cover the hut circles and associated clearance cairns and are shown in red on the attached map. Statement of National Importance This monument is of national importance for its potential contribution to our understanding of prehistoric settlement and land use. The hut circles incorporate information about the architecture of prehistoric buildings and also evidence for the domestic life of their occupants. The fields include evidence about the agricultural economy of the settlement. Parts of the settlement are heavily peat covered and in these areas the evidence will be particularly well preserved. References RCAHMS records the monument as ND 13 SE 20, 21 and 42.
Asset/Event Number	3
Asset/Event Name	Cnoc Fionn, hut circle 250m SSW of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM3537; ND12SW 8
HER Number	MHG1124; MHG1124
Status	Scheduled Monument
Section:	N/A
Easting	310444
Northing	923542
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM3537 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/8110/cnoc-fionn. This is the same description for Asset 4/SM3559. Asset 3 is hut circle A described below. At ND 1053 2351 [Asset 4/SM3559] and ND 1044 2354 [Asset 3/SM3537], on a NE-facing slope above the Berriedale Water are the slight remains of two heather-clad oval enclosures or hut circles, scooped into the hillside on the W, and formed by earth and stone banks up to 1.3m high externally in the N. The entrances, 1.0m wide, are in the E. The huts measure 12.0 by 10.0m and 11.4 by 9.5m respectively. Visited by OS (R L), 29 February 1968.

	There is a further hut circle at ND 1013 2364, some 300 m to the W. It is similar to the others, measuring some 11.0 by 9.0m, and with an entrance in the E. There is a small field system in the vicinity, but field boundaries are not obvious, only evidenced by low stone clearance heaps. Hut circles surveyed at 1:2500. Visited by OS (R L) 29 February 1968. (A: ND 1053 2351 [Asset 4/SM3559]; B: ND 1044 2354 [Asset 3/SM3537]) Hut Circles (NR) (C: ND 1013 2364) Hut Circle (NR) OS 25" map, (1969) A settlement of three hut circles (A-C) and an associated field system. The huts are set into the slope and are heather and peat covered. They measure: 'A' - 9.0 by 7.0m; 'B' - 10.5 by 7.5m; and 'C' - 9.0 by 7.5m, within wall-spreads ranging from 2.5 to 4.0m by 0.6 to 0.9m high. Entrances are in the E or SE, on the line of the main axis in each case. The minor field system is delineated by a scatter of stone clearance heaps. Visited by OS (J M), 23 November 1982. Three hut-circles, a platform and eleven small cairns were recorded during a pre-afforestation survey of Langwell-Rinsary Braes, Berriedale. The platform lies to the SE of the hut-circles noted previously. Bisected by a drystone dyke, the platform is semi-circular and measures 12m in diameter. There are no visible traces of the platform within the improved ground to the SW of the dyke. The small cairns are concentrated between the hut-circles at ND 1053 2351 and ND 1044 2354. References Carter, S. (1999h) 'Langwell-Rinsary Braes (Latheron parish), pre-afforestation survey', Discovery Excav Scot, 1999. Page(s): 57
Asset/Event Number	4
Asset/Event Name	Cnoc Fionn, hut circle 250m SW of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM3559; ND12SW 8
HER Number	MHG1124
Status	Scheduled Monument
Section:	N/A
Easting	310534
Northing	923514
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM3537 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/8110/cnoc-fionn. This is the same description for Asset 3/SM3537. Asset 4 is hut circle B described therein.
Asset/Event Number	5
Asset/Event Name	Bridge of Rhemullen, broch 180m SW of
Type of Asset/Event	Broch
Date and/or Period	Iron Age
Listing No./NRHE Number	SM5088; ND13SE 11

HER Number	MHG1139; MHG31272
Status	Scheduled Monument
Section:	N/A
Easting	315329
Northing	930969
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5088 This monument consists of the remains of a broch and an associated prehistoric settlement. The broch survives as a turf-covered, level- topped mound, approximately 20m in diameter and 1.6m high. On the SE edge of the mound the upper part of the broch entrance and a stretch of the external face of the broch wall have been exposed. The broch mound rises out of an irregular, extensive mound, about 50m N-S by 40m E-W, enclosed by an early-modern field wall. On the surface of this outer mound are traces of a number of small circular stone-walled buildings. These structures indicate an extensive settlement which may have originated at the time when the broch was occupied but probably continued in occupation after the abandonment of the broch. The area to be scheduled measures 80m NW-SE by 80m SW-NE, to include the broch mound, the outer mound and an area around in which traces of activities associated with the construction and occupation of the broch and settlement may survive. The external settlement extends as far as the modern walled enclosure which surrounds the broch and the scheduled area extends outside this walled enclosure in order to protect associated structures which probably once extended into the improved pasture. The area to be scheduled is shown in red on the attached map. Statement of National Importance This monument is of national importance for its potential contribution to our understanding of prehistoric settlement and domestic life. The broch is well preserved and there is an extensive associated prehistoric settlement. The broch is an example of a high-status Iron Age dwelling and incorporates evidence for defensive architecture, the domestic organisation of its inhabitants and their farming practices. With the exception of the excavation of the entrance passageway, it appears that the broch has not been investigated in recent times and this suggest that the wall structure, internal organisation and chronological sequence of development on this site will be particularly well preserved. The association of the broch with an extensive settlement of possible contemporary and later date is also important. Brochs in Caithness and Orkney are often associated with settlements of this type, but this example appears to be particularly well preserved. References RCAHMS records the monument as ND 13 SE 11.
Asset/Event Number	6
Asset/Event Name	Buolacrabher, chambered cairn 1350m SSW of
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM5224; ND13SE 25
HER Number	MHG1152
Status	Scheduled Monument
Section:	N/A

Easting	315019
Northing	933370
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5224 The monument consists of the remains of a chambered cairn of Neolithic/Bronze Age date. The cairn is about 14.6m in diameter; a number of slabs of stone protrude through the turf in the approximate centre of the cairn and indicate the existence of a chamber. The cairn is crossed by a modern sheep shelter. The 2 longest slabs on the S of the shelter are 0.3m above the present ground level, while the 2 at right angles to the shelter and the slab to the N of them are 0.6m high. There is evidence for thick peat growth in the area around this chambered cairn and it is probable that much of the cairn and chamber remain in situ. The area to be scheduled measures 45m in diameter, to include the chambered cairn and an area around it in which traces of activities associated with its construction and use may survive, as shown in red on the attached map. Statement of National Importance The monument is of national importance for its potential contribution to an understanding of prehistoric ritual and burial practices. The monument also contains important information about the structure of Neolithic/Bronze Age tombs. References RCAHMS records the monument as ND 13 SE 25.
Asset/Event Number	7
Asset/Event Name	Invershin Primary School, settlement 760m NE of and 750m ENE of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM5462; NH59NE 13
HER Number	MHG9297; MHG12902
Status	Scheduled Monument
Section:	N/A
Easting	258055
Northing	898148
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5462 This monument consists of the remains of the foundations of several round houses and also traces of associated field systems in two forestry clearings on a W-facing hill slope. The NW clearing contains the remains of 2 stone-walled houses and an associated field system. One house is visible as an oval platform measuring about 15m by 12m bounded by the ill-defined traces of a stone wall. The foundations of the second house are about 12.5m in diameter between the centres of a wall spread to roughly 3m. The entrance is in the S. In close proximity are a number of cairns and lynchets indicating an area of former cultivation. The SE clearing contains a single house, which is set into the slope and measures 12m in diameter. The wall is 2.5m wide at the rear and splays to 3.5m to either side of the entrance, which is to the SSW. In this area there are traces of former cultivation, indicated by several

	clearance cairns. Two areas are to be scheduled: the NW area measures 155m N-S by 75m E-W, the SE area is 110m NNE-SSW by 75m WNW-ESE, to include the hut circles, field systems and an area around in which traces of activities associated with the building and use of the huts will survive, as shown in red on the attached map. Statement of National Importance The monument is of national importance for its potential to contribute to an understanding of prehistoric agricultural organisation and domestic life. References RCAHMS records the monument as NH 59 NE 9 and 13.
Asset/Event Number	8
Asset/Event Name	Invershin Farm, settlement and burnt mound 1200m E of
Type of Asset/Event	Prehistoric settlement; burnt mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM5470
HER Number	MHG32590; MHG32590; MHG12917
Status	Scheduled Monument
Section:	N/A
Easting	258641
Northing	896626
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5470 This monument consists of a hut circle and a burnt mound situated in 2 forestry clearings on a SW-facing hill slope. The hut circle is situated on a low rise and is a circular heather-covered platform about 13m in diameter. There are traces of a wall defining the edge of the hut circle around the edge of the platform. The position of the entrance is not clear. The burnt mound is about 150m to the SE on the N bank of a small burn. It is roughly oval in ground plan, about 12m E-W by 7m and about 1m high. The mound is almost divided in half along its shorter axis by a depression 1.5m wide, that opens out into the burn. It is recorded that it 1976 some animal scrapes revealed black earth and burnt stone. Two areas are to be scheduled: The NW area is 80m NW-SE by 60m NE-SW, the SE area is 40m NW-SE by 50m WSW-ENE, to include the hut circle, burnt mound and areas around in which traces of activities associated with the construction and use of these monuments may survive, as shown in red on the attached map. Statement of National Importance The monument is of national importance for its potential contribution to our understanding of prehistoric domestic life and land use. The burnt mound is a well preserved example and will contain important information on the uses to which these enigmatic monuments were put by our prehistory ancestors. References RCAHMS records the monument as NH 59 NE 11 and 23.
Asset/Event Number	9
Asset/Event Name	Invershin Farm, settlement and burnt mound 500m E of
Type of Asset/Event	Prehistoric settlement; burnt mound; cairn
Date and/or Period	Prehistoric

Listing No./NRHE Number	SM5497; NH59NE 19; NH59NE 12; NH59NE 22
HER Number	MHG12916; MHG12912; MHG9298
Status	Scheduled Monument
Section:	N/A
Easting	257881
Northing	896619
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5497 This monument consists of a hut circle, a burnt mound and a cairn on a W-facing hill slope. The hut circle survives as an ill-defined platform about 10m in diameter, with traces of walling on the E, S and W. There are several stone clearance cairns in the area around the hut which indicate the location of prehistoric cultivation. About 70m NE of the hut is a cairn, measuring 6m in diameter and 0.6m high. It is edged with a kerb of stones. To the SW is a 'horn'-like projection about 4m long, of uncertain origin. About 180m NNW of the cairn is a burnt mound. It is about 13m diameter and 1m high and the crescent-shaped E side faces onto wettish ground. Records indicate that animal burrows in this burnt mound have revealed blackened earth and burnt stone. Two areas, about 140m apart, are to be scheduled. The S area measures 125m SSW-NNE by 85m NNW-SSE and the N area 60m N-S by 40m E-W, to include the hut circle, cairn, burnt mound and areas around in which traces of activities associated with the construction and use of the monuments may survive, as shown in red on the attached map. Statement of National Importance The monument is of national importance for its potential to contribute to an understanding of prehistoric burial practices, domestic life and land use. The cairn is likely to be a small prehistoric burial monument, while the burnt mound will contain important information about the uses to which prehistoric communities put these enigmatic structures. References RCAHMS records the monument as NH 59 NE 12, 19 and 22.
Asset/Event Number	10
Asset/Event Name	Invershin Primary School, settlement 600m E of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM5498; NH59NE 10; NH59NE 41; NH59NE 11
HER Number	Various
Status	Scheduled Monument
Section:	N/A
Easting	258215
Northing	897353
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://portal.historicenvironment.scot/designation/SM5498 This monument consists of an extensive area of prehistoric settlement on a W-facing hillslope to either side of a E-W running burn. There are remains of 3 hut circles to the N of the Allt na Ciste Duibhe. Associated with the hut circles are lynchets, field walls and clearance heaps which indicate the location of prehistoric cultivation. To the S of the burn are traces of three hut circles associated with field walls and clearance cairns. The area to be scheduled measures a maximum of 1030m NNW-SSE by a maximum of 555m WSW-ENE, to include the hut circles and traces of cultivation, as shown in red on the attached map. Statement of National Importance This monument is of national importance for its potential contribution to an understanding of prehistoric domestic organisation, settlement patterns and land use. References RCAHMS records the monument as NH 59 NE 10 and 11.
Asset/Event Number	11
Asset/Event Name	Dun Mor, fort
Type of Asset/Event	Fort
Date and/or Period	Iron Age
Listing No./NRHE Number	SM4979; NH44NE 8
HER Number	MHG2651
Status	Scheduled Monument
Section:	N/A
Easting	245737
Northing	845150
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM4979 The monument known as Dun Mor is a sub-oval fort of the Iron Age measuring c 22m NNE-SSW by 16m within a tumbled wall between 4.5m and 6.0m wide with outer and inner faces sporadically visible around most of the perimeter. The entrance is in the south east. Within the north side of the interior is a natural platform. Below the fort on the south and east are the remains of two further outer walls. The area to be scheduled measures 100m N-S by 80m E-W to include the fort and the outer defences, and an area around them in which traces of activity associated with their construction and use will survive, as marked in red on the attached map. Statement of National Importance The monument is of national importance as a well preserved example of a prehistoric fort; it is of particular interest because of the existence of additional outer defences on the most accessible sides. It has the potential to enhance considerably our understanding of prehistoric settlement and defensive structures. References RCAHMS records the monument as NH 44 NE 8.
Asset/Event Number	12
Asset/Event Name	Dun Fhamhair, fort
Type of Asset/Event	Fort
Date and/or Period	Iron Age

Listing No./NRHE Number	SM5212; NH44NE 7
HER Number	MHG2652
Status	Scheduled Monument
Section:	N/A
Easting	248416
Northing	847068
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5212 The monument comprises the remains of an oval fort of the Iron Age, measuring 43m N-S by 35m within a wall up to 3.5m across with outer facing stones visible for most of the perimeter. Outside the fort to the north east there is a 55m long rampart and ditch with an entrance through its centre. The area to be scheduled measures 100m in diameter to include the fort and the rampart, and an area around them in which traces of activities associated with their use will survive, as marked in red on the attached map. Statement of National Importance The monument is of national importance as a well preserved example of a stone walled Iron Age fortification; it is of particular interest because of the existence of an outer defence work. The monument has the potential to enhance considerably our understanding of prehistoric defensive structures and settlement activity. References RCAHMS records the monument as NH 44 NE 7.
Asset/Event Number	13
Asset/Event Name	Achorn Bridge, settlements 1100m NNE of
Type of Asset/Event	Prehistoric settlement; post-medieval settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM5150; Various
HER Number	Various
Status	Scheduled Monument
Section:	N/A
Easting	313581
Northing	931464
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5150 This monument consists of areas of prehistoric settlement and a post medieval settlement situated to either side of the Allt Clais Raoin [NRHE: ND13SW 36-ND13SW 40]. The prehistoric features include a cairnfield of at least four cairns at about ND13453149. The largest of these cairns is about 4 by 3m and about 1m high. At ND13353147 is an irregular stone-built structure, possibly a hut circle. At ND13443150 is a well preserved hut circle about 8m in diameter and with an entrance which is on the SE.

	The wall of this hut is up to 1.7m wide and 0.5m high, with evidence of stone facing on both inner and outer wall faces. The post medieval settlement includes 3 clusters of buildings. At ND13853143 are 3 buildings on either side of a burn. These include a kiln barn and 2 rectangular buildings. At ND13693155 are 2 very well preserved buildings - a long house and a kiln barn. At ND13453143 is a small ruinous rectangular house attached to an oval enclosure. The foundations of a further rectangular building survive at ND13413144 and there are a number of stone dykes in the area between the 3 settlement clusters. The area to be scheduled measures 470m WSW-ENE by a maximum of 250m N-S, to include the prehistoric and post medieval features, as shown in red on the attached map. Statement of National Importance The monument is of national importance for its potential to contribute to an understanding of prehistoric and post medieval settlement and land use. The hut circles and clearance cairns incorporate important information on the way of life and agricultural economy of a prehistoric community. The post medieval settlements contain evidence for the domestic organisation and farming practices of a community and also important information on the process of the Clearances in this area of Caithness. The buildings in the NE cluster are particularly well preserved and important architectural details survive.
Asset/Event Number	14
Asset/Event Name	Loedebest, chambered cairn 400m WNW of
Type of Asset/Event	Chambered cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM5163; ND13SW 9
HER Number	MHG1267
Status	Scheduled Monument
Section:	N/A
Easting	313389
Northing	932300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5163 This monument consists of a chambered cairn which is cut by the Loedebest-Achnaclyth road. The cairn appears to have been about 13m in diameter, although to the S it has been cut into by the roadside ditch. This roadside ditch has exposed stone and it is evident that the cairn survives to a height of 0.5m at this point. In the centre the remains of five pointed slabs, about 0.7m high, indicate the location of the chamber. The plan of the chamber is difficult to interpret, but it was evidently divided by transverse slabs. There is no obvious entrance passageway. The area to be scheduled measures 43m E-W by 26m N-S, to include the chambered cairn and an area around it to the W, N and E in which traces of activities associated with its construction and use may survive, as shown in red on the attached map. To the S the road and roadside ditch are excluded from the scheduled area. Statement of National Importance The monument is of national importance for its potential to contribute to an understanding of Neolithic/Bronze Age ritual beliefs and burial practices. Information about the construction methods of tombs survives at this site. References RCAHMS records the monument as ND 13 SW 9.

Asset/Event Number	15
Asset/Event Name	Loedebest, cairn 500m SSE of
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM5191; ND13SW 13
HER Number	MHG1256; MHG38946
Status	Scheduled Monument
Section:	N/A
Easting	313935
Northing	931703
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5191 The monument consists of a cairn with a cist in the centre. The cairn is about 5m in diameter and 0.6m high and a number of slabs are visible forming an edge to the cairn. A cist formed by three stone slabs is exposed in the centre. The cist is 0.9m E-W by 0.4m wide and 0.2m deep. The area to be scheduled measures 25m in diameter, to include the cairn and an area around in which traces of activities associated with its construction and use may survive, as shown in red on the attached plan. Statement of National Importance The monument is of national importance for its potential to contribute to an understanding of prehistoric ritual and funerary practices. References RCAHMS records the monument as ND 13 SW 13.

Asset/Event Number	16
Asset/Event Name	Loedebest, prehistoric settlement and post medieval enclosure 1400m WSW
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM5254; ND13SW 22
HER Number	MHG610
Status	Scheduled Monument
Section:	N/A
Easting	312427
Northing	931784
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://portal.historicenvironment.scot/designation/SM5254 The monument consists of 3 prehistoric hut circles and traces of associated cultivation on sloping moorland to the S of Dunbeath Water. Hut circle 'A' is located at ND12393179 and is about 9.5m in diameter. The walls that define the hut circle are about 2m wide and 0.5m high and some facing stones are visible on both the inside and outside of the wall. There is a possible entrance to the SE of the hut. Hut 'B' is located at ND12473180 and is about 9m NW-SE by 6.5m SW-NE. The wall is spread to about 1.5m wide and is about 0.5m high. The entrance to this house is to the SE and 3 large loose stones have been dumped in the entrance presumably after the abandonment of the hut. Hut 'C' is at ND12393178 and was probably originally about 8m in diameter. The N portion of the hut wall has been destroyed at some time in the past by the construction of the track which skirts the settlement to the E. Where it is best preserved the wall of this hut is about 1.7m wide and 0.5m high. The position of the entrance is unclear. A length of turf-covered stone field wall extends for 20m to the NW of hut 'A' and there are a number of possible stone clearance cairns around these hut circles. To the S of the hut circles an area of land has been cleared of stone and enclosed within a stone wall presumably during the post medieval period. The area to be scheduled measures a maximum of 165m SW-NE by 130m NNW-SSE, to include the prehistoric hut circles, field wall, possible cairns and the post medieval enclosure, as shown in red on the attached plan. Statement of National Importance The monument is of national importance for its potential contribution to an understanding of prehistoric settlement and land use. The hut circles incorporate information on the architecture of prehistoric houses. The post medieval enclosure is presumably connected with the important group of abandoned post medieval settlements in Dunbeath Strath.
Asset/Event Number	17
Asset/Event Name	Bridge of Badnagie, settlement 400m NW of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM5186; ND13SE 45
HER Number	Various
Status	Scheduled Monument
Section:	N/A
Easting	315613
Northing	932131
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5186 The monument is a prehistoric settlement consisting of a number of hut circles on a natural shelf above the E bank of the Burn of Houstry. Hut circle 'A' (ND15593215) measures 7m in diameter internally and has an entrance to the S. The wall, where best preserved, is 2m wide and 0.3m high. Hut 'B' (ND15633211) has bare stone walls and a profusion of stony debris in the interior and this probably indicates that the hut had substantial stone walls. This hut is about 7.5m in diameter internally and has a S entrance. To the W of the entrance, the wall of the hut expands to 3m in width and it is possible that this represents a well preserved souterrain running outside the wall of the house on its SW and W side. Hut 'C' (ND1563208) measures 8.5m NNW-SSE by 6.5m transversely with heather covered walls 2m wide and 0.2m high. The entrance is in the SSE. A cross wall in the

	interior of this hut may indicate a secondary hut 5.5m in diameter, with an entrance in common with the larger hut. 22m to the N of hut 'A' is a small circular enclosure or hut circle. The area to be scheduled measures 170m NW-SE by 45m NE-SW, to include the hut circles, enclosure and an area around in which traces of activities associated with the construction and use of the hut circles may survive. The scheduled area extends 20m beyond the edge of the archaeological structures except to the N of hut 'A', where the area extends to the break of slope (12m to the SW of the hut) and is shown in red on the attached map. Statement of National Importance The monument is of national importance as a well preserved prehistoric settlement which has the potential to considerably increase our understanding of the domestic life and farming practices of its inhabitants. The association of a possible souterrain with one of the hut circles is of particular importance. The hut circles vary in form and contain evidence for the architecture of Iron Age domestic dwellings. References RCAHMS records the monument as ND 13 SE 45.
Asset/Event Number	18
Asset/Event Name	Greentulloch, broch 180m NE of
Type of Asset/Event	Broch
Date and/or Period	Iron Age
Listing No./NRHE Number	SM5089; ND13SE 14
HER Number	MHG1142; MHG39562
Status	Scheduled Monument
Section:	N/A
Easting	316271
Northing	932336
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5089 The monument comprises a broch which is estimated to be about 17m in diameter and incorporated into a mound which is about 23m in diameter and 1.5m high. A small trench has been excavated at some time in the past on the SE of the mound and this has exposed the lintelled entrance to the broch and a curved stretch of the outer wall face 8m long. The outer mound extends someway beyond the wall of the broch on the SW and it is probable that ancillary structures outside the broch wall will survive in this area. The area to be scheduled measures 65m SW-NE by 50m SE-NW, to include the broch, the outer mound and an area around in which traces of activities associated with the building and occupation of the broch may survive, as depicted in red on the attached map. This area excludes the roofless long house to the SE, is defined by the modern wall to the SW and extends 20m beyond the walled enclosure on the NW and NE. Statement of National Importance The monument is of national importance for its potential to contribute to our understanding of prehistoric settlement and domestic life. The broch is fairly well preserved and will incorporate information about Iron Age defensive architecture, while the settlement contains evidence for the farming activities and domestic life of its inhabitants. References

	RCAHMS records the monument as ND 13 SE 14.
Asset/Event Number	19
Asset/Event Name	Bridge of Badnagie, standing stone 600m N of
Type of Asset/Event	Standing stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM5304; ND13SE 29
HER Number	MHG1156
Status	Scheduled Monument
Section:	N/A
Easting	316016
Northing	932570
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5304 This monument is a prehistoric standing stone. The stone is situated on flat moorland and is 1.6m high, 1.5m wide and 0.6m thick. There are packing stones at the base of the standing stone. The area to be scheduled measures 20m in diameter, to include the standing stone and an area around in which traces of activities associated with its erection may survive, as shown in red on the attached map. Statement of National Importance The monument is of national importance for its potential contribution to our understanding of prehistoric ritual beliefs. References RCAHMS records the monument as ND 13 SE 29.
Asset/Event Number	20
Asset/Event Name	Dun Garbhlaich, fort, Kilmorack
Type of Asset/Event	Fort
Date and/or Period	Iron Age
Listing No./NRHE Number	SM2422; NH44NE 5
HER Number	MHG2654
Status	Scheduled Monument
Section:	N/A
Easting	246605
Northing	846572
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description

https://portal.historicenvironment.scot/designation/SM2422
No description available from HES. Description taken from Canmore https://canmore.org.uk/site/12375.

(NH 4662 4657) Dun Garbhlaich (NAT) Fort (NR) OS 6"map,(1957)
Dun Garbhlaich, a fort, situated on the uneven rocky summit of an isolated crag. It is roughly D-shaped on plan measuring c.35.0m E to W by c. 28.0m transversely with a drystone wall which is completely tumbled on the N and SE, but well preserved in the SW where the outer face stands to a maximum height of c. 1.5m, and the inner face to a maximum height of c. 1.0m giving a wall thickness varying between 3.8m and 2.3m. In the NE the outer face is evident amidst tumble to a maximum height of c.0.8m. The entrance passage, 4.5m long and 1.1m wide is in the S at the easiest point of access and is faced by upright slabs towards the inner end. Within the fort in the E is a ruinous stone-lined well c.3.0m diameter.

The plan by Wallace (T D Wallace 1921) is almost worthless. The outwork shown to the S of the fort is tumble from the main wall.

Depicted at 1/10000 scale. Planned at 1/1250 Visited by OS (R L) 6 April 1970; Visited by RCAHMS 1957

Activities
Field Visit (31 August 1943) RCAHMS Emergency Survey (Archaeology)
Dun Garbhlaich is perched on a crag about 1030 ft OD that is an isolated SW outlier of the higher and often precipitous ridge of the Urchany & Farley Forest. The core of the site is formed by a ridge of naked rock some 36 ft [11m] wide precipitous on the N and W but sloping away more gently on the uphill NE side to a low col. Some 15 ft below the crest of this rocky spine on the SE is a broad platform some 48 ft [14.6m] wide that again falls away in sheer cliffs on the S & W. Both the ridge crest and the platform are included within the protection of a drystone wall. This runs nearly straight along the edge of the precipice on the N for about 105 ft [32m] but from each end of the spine sweeps out in a rough semi-circle to embrace the level terrace below, running downhill across the slope of naked rock in the SW quadrant. In this segment both inner and outer faces are exposed, 3 ft to 5 ft [0.9m to 1.5m] of almost vertical masonry being visible where the outer face traverses a cleft in the rock. In the S there is an entrance passage 3 ft 8 in [1.1m] wide at its inner end and traceable for 15ft [4.6m] on the W side but 14 ft [4.3m] further W from the inner corner the rampart seems only 11 ft [3.4m] thick. At the foot of the central ridge in the SE quadrant, just within the rampart, is a spring or well that still contained water when visited. Some good sections of outer face neatly adjusted to rock out crops are visible also on the E, but along the cliff edge to the N as well as to the SE the rampart is overgrown with peat and heather.
Visited by RCAHMS (VGC) 31 August 1943. (T.I.S.S, viii, 119 (plan))

Note (1951 - 1958) RCAHMS Marginal Land Survey
This fort is situated at a height of 1030 feet OD on a rocky eminence that stands up from the higher and broken ground N. of Farley, three- and three-quarter miles W of Beauly. The upper part of the knoll is formed by a ridge of naked rock, the N and W flanks of which are precipitous, while to the NE a gentle slope leads to a col from which the main massif is reached. Some 15 feet below to the SE. is a broad platform the S and W. flanks of which are precipitous. The fort, which encloses both ridge and platform, is D-shaped on plan, measuring 80 feet [24m] in width from E. to W. by 60 [18m] transversely within the ruined stone wall. Sections of both faces are visible, indicating that the wall varies in thickness from 11 feet to 15 feet [3.3m to 4.6m]. The entrance is in the S. A well lies just within the E sector of the wall but the interior is otherwise featureless.
Information from RCAHMS c.1951-8

Field Visit (March 1979) RCAHMS: The Archaeological Sites and Monuments of North East Inverness
Dun Garbhlaich NH 466 465 NH44NE 5 This D-shaped fort measures 27m by 23m within a wall up to 3.8m thick which encloses both the summit of a crag and a shelf some 4.5m below on the SE side: considerable portions of wall-face survive where the wall descends to the lower level. The entrance lies on the S.

RCAHMS 1979, visited March 1979 (Wallace 1886, 342-3) Note (4 March 2015 - 31 May 2016)

Atlas of Hillforts of Britain and Ireland
This small fort is situated on a rocky hillock rising from a S-facing hillside above Farley. D-shaped on plan, it measures about 35m from ENE to WSW along the chord extending along the crag on the NNW by 28m transversely within a wall from 2.3m to 4.5m in thickness. Long runs of the outer face are visible in the tumbled rubble everywhere except on the NNW, standing up to 1.5m high on the SW, where the inner face also survives to a height of about 1m. The wall is thickest to either side of the entrance, which is on the S; faced with upright slabs, the inner edge of the passage measures 1.1m wide and in 1943 was sketched with checks by RCAHMS investigators, though there is no hint in their description that these were actually visible. Much of the interior is bare rock, but there is what may be a well immediately within the line of the wall on the E.
Information from An Atlas of Hillforts of Great Britain and Ireland – 31 May 2016. Atlas of Hillforts SC2874

References
RCAHMS. (1979c) The archaeological sites and monuments of North-east Inverness, Inverness District, Highland Region, The archaeological sites and monuments of Scotland series no 8. Edinburgh. Page(s): 16, No. 95 RCAHMS Shelf Number: A.1.2.ARC(8)
RCAHMS. (1942-3) Emergency Survey of archaeological monuments in military training areas, 1981, 2v. Typescripts. Page(s): TS 56, MS 143 RCAHMS Shelf Number: A.1.1.SUR
RCAHMS. (1950-9) Marginal Land Survey (unpublished typed site descriptions), 3 volumes. Page(s): v2 RCAHMS Shelf Number: A.1.1.MAR
Wallace, T. (1921a) 'Archaeological notes', Trans Inverness Sci Soc Fld Club, vol. 8, 1912-18. Page(s): 119 plan 120 RCAHMS Shelf Number: Ref

Asset/Event Number	21
Asset/Event Name	Dun a Chliabhain, fort
Type of Asset/Event	Fort
Date and/or Period	Iron Age
Listing No./NRHE Number	SM2424; NH44NE 5
HER Number	MHG2653
Status	Scheduled Monument
Section:	N/A
Easting	247701
Northing	846069
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM2424 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/12376/dun-a-chliabhain. (NH 4770 4606) Dun a' Chliabhain (NAT) Fort (NR) OS 6"map, (1957) Dun a' Chliabhain, a fort, occupies a steep-sided rocky boss. It is 77 ft by 48 ft within a stone wall up to 12 ft thick, with an entrance on the E. An outer wall covers this in the NE (2). Wallace gives the wall thick- ness as 6 ft 6 ins and adds that the S side is defended by a 5 ft broad ditch, gradually becoming wider towards the SE. R W Feachem 1963; T D Wallace 1921 Dun a' Chliabhain, a fort, is situated on the SW extremity of a ridge which protrudes SW

from the higher ground above Drumindorsair; the NW, SW and SE flanks of the ridge are steep and in parts precipitous, but the approach from the NE is gradual. Sub-oval on plan, the fort measures 23.5 m NW-SE by about 11.0 m within a wall averaging 3.6 m in thickness. Inner and outer wall faces, to a maximum height of three courses, can be traced amid tumble in all but the NW arc where the wall has slipped over the cliff. A shooting butt has been built into the wall in the S. The entrance passage, in the E, measures 3.8 m in length by 2.2 m in width; it is reduced to its lowest two courses. The interior of the fort is featureless. The wall barring the easiest approach from the NE survives as a discontinuous line of outer facing-stones with three inner facing-stones evident at the S end giving a wall thickness of 2.2 m. Outside the fort in the SW is a stony bank, about 1.5 m wide and 0.3 m high, with an internal ditch some 1.5 m wide and 0.3 m deep, which terminates on level ground at the SE end. It is possible that this is an unfinished outer defence. Outside the bank are the vestiges of another wall, of uncertain purpose.
Planned at 1/1250. Visited by OS (R L) 2 April 1970

Dun a' Chliabhain: This oval dun measures about 21.5 m by 11 m within a wall about 3.6 m thick, with an entrance on the E. The outer wall recorded by Feachem (R W Feachem 1963) does not appear to form part of the defences. This is a dun and is as described in the previous field report, but the 'uncertain wall' across the SW approach is an outwork.
RCAHMS 1979

Activities
Field Visit (31 August 1943) RCAHMS Emergency Survey (Archaeology)
This site was included within the RCAHMS Emergency Survey (1942-3), an unpublished rescue project. Site descriptions, organised by county, vary from short notes to lengthy and full descriptions and are available to view online with contemporary sketches and photographs. The original typescripts, manuscripts, notebooks and photographs can also be consulted in the RCAHMS Search Room.
Information from RCAHMS (GFG) 10 December 2014. Field Visit (March 1979)

RCAHMS: The Archaeological Sites and Monuments of North East Inverness Dun a' Chliabhain NH 477 460 NH44NE 6
This oval dun measures about 21.5m by 11 m within a wall about 3.6m thick, with an entrance on the E. An outer wall recorded by Feachem does not appear to form part of the defences.
RCAHMS 1979, visited March 1979 (Wallace 1886, 342; Feachem 1977, 127-8)

Note RCAHMS Marginal Land Survey
Undated description within v2. of Marginal Land Survey typescripts.

Asset/Event Number	22
Asset/Event Name	Kilphedir, hut circles & field system 750m NNE of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM2807; NC91NE 25
HER Number	MHG9858
Status	Scheduled Monument
Section:	N/A
Easting	299051
Northing	919408
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description

https://portal.historicenvironment.scot/designation/SM2807
No description available from HES. Description taken from Canmore https://canmore.org.uk/site/6998/kilphedir.

(NC 990 194) (5) Enclosures (NR) (Undated) annotation on OS map. A settlement of five hut circles (I-V) excavated by Fairhurst between 1963 and 1968. Two types of huts were distinguished, type I and type II. The first occupation of the site was about 500 BC.
RCAHMS 1911; H Fairhurst 1971; H Fairhurst and D B Taylor 1974.

Each of the four type I huts consisted of a low perimeter wall in which had rested the ends of the rafters of a conical roof supported on a ring of posts half way between the wall and the hut centre. There was no evidence of central posts. In, or near, the centre of each was a hearth. Internal diameters were between 20ft and 40ft. Coarse, generally flat rimmed, pottery was found. Hut V, the only type II hut, was found to incorporate the remnants of one of the earlier type I huts, and was dated to c. 130BC. It had a higher, thicker wall, lined on the inside with slabs, which expanded at the entrance to form a passage 5.0m long. Finds included potsherds of a smoother harder ware, one with an everted rim, a saddle quern, and pounders and rubbing stones. Contemporary agriculture is evidenced by clearance heaps, and stony banks edging plots. Fairhurst (1971) implies that the clearance cairns were possibly contemporary with the type I huts, and the stony banks with the type II house, suggesting a change in cultivation methods.
E W MacKie 1969; Visited by OS (W D J) 20 May 1960.

This is a settlement of five huts (I-V) in association with a field system as described by Fairhurst. Re-surveyed at 1:10,560.
Visited by OS (W D J) 20 October 1976.

References
Armit and Ralston, I and I B M. (2003) 'The Iron Age', in Edwards, K J and Ralston, I B M, Scotland after the Ice Age: environment, archaeology and history 8000BC - AD 1000. 2nd. Edinburgh. Page(s): 188
Armit, I. (1992b) 'The Atlantic Scottish Iron Age: five levels of chronology', Proc Soc Antiq Scot, vol. 121, 1991. Page(s): 208
Armit, I. (1998i) Scotland's hidden history. Stroud, Gloucestershire. Page(s): 107-9 fig 63 RCAHMS Shelf Number: E.2.1.ARM
Armit, I. (1996) The archaeology of Skye and the Western Isles. Edinburgh. Page(s): 134 RCAHMS Shelf Number: E.2.1.ARM
Close-Brooks, J. (1995a) The Highlands, Exploring Scotland's Heritage series, ed. by Anna Ritchie. 2nd. Edinburgh. Page(s): no.93), 134, 135, 136, 149-50 RCAHMS Shelf Number: A.1.4.HER
Davidson and Carter, D A and S P. (2003) 'Soils and their evolution', in Edwards, K J and Ralston, I B M, Scotland after the Ice Age: environment, archaeology and history 8000BC - AD 1000. 2nd. Edinburgh. Page(s): 54-55, 57
Fairhurst and Taylor, H and D B. (1974) 'A hut-circle settlement at Kilphedir, Sutherland', Proc Soc Antiq Scot, vol. 103, 1970-1. Page(s): 65-99 plans
Fairhurst, H. (1971c) 'Kilphedir and hut circle sites in northern Scotland', Scot Archaeol Forum, vol. 3, 1971. Page(s): 1-10
Halliday, S. (1999g) 'Hut-circle settlements in the Scottish landscape', in Frodsham, P, Topping, P and Cowley, D, 'We were always chasing time.' Papers presented to Keith Blood, Northern Archaeol (Spec Edition, vol. 17/18, 1999. Page(s): 49 RCAHMS Shelf Number: E.2.1.BLO
MacKie, E W. (1969c) 'Radiocarbon dates and the Scottish Iron Age', Antiquity, vol. 43, 1969. Page(s): 17, 24 RCAHMS Shelf Number: E.9.1.MAC.P
RCAHMS. (1911a) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. Edinburgh. Page(s): 113-14, No. 325 fig. 40 RCAHMS Shelf Number: A.1.1.INV(2)
Romans and Robertson, J C C and L. (1975) Soils and archaeology in Scotland, in Evans, J G, Limbrey, S and Cleere, H, The effects of man on the landscape: the highland zone, Council for British Archaeology research report no.11. London. Page(s): 38

Asset/Event Number	23
Asset/Event Name	Kilphedir, hut circle 480m NNE of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM2808; NC91NE 28
HER Number	MHG9855
Status	Scheduled Monument
Section:	N/A
Easting	299145
Northing	919081
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM2808 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/7001/allt-cille-pheadair. This is the same description for Asset 67/SM1872. Asset 23 is the hut circle B described below. (Centred NC 991190) Enclosures (NR) (Three shown A-C) (NC 9913 1903) Earth House (NR). OS 6" map, 1964. There are two hut circles (A [Asset 67/SM1872] and B [Asset 23/SM2808]) of which one (A [Asset 67/SM1872) incorporates an earth-house. J M Joass 1873; RCAHMS 1911. Three enclosures (A-C) can be identified. Visited by OS (W D J) 20 May 1960. On a gentle W-facing moorland slope, above the gorge of Allt Cille Pheadair on the E side, is a settlement of three hut circles (A-C). Hut A [Asset 67/SM1872], the best-preserved, measures 10.0m diameter within a massive wall, 1.5m maximum height, which is spread to 3.0m broad, widening to 5.0m at the entrance in the SSE arc. This entrance is club-shaped and choked with debris. Occasional slabs on edge indicate the remains of the inner wall face. The souterrain as described by RCAHMS is virtually complete and accessible along its whole length of 10.0m. It is of dry-stone construction roofed with flags. It measures 0.7m wide and 0.9m high at the entrance on the SW side of the hut, increasing to a maximum of 1.3 wide and 1.4m high. Towards the end of the passage, an opening has been cleared in the roof. The other huts are less substantial and peat-overgrown. B, set into the slope is 12.0m in diameter within a mutilated wall spread to 2.0m broad. A slight dip in the wall in the SW arc probably indicates the entrance. C measures 10.5m N-S by 8.5m within a wall spread to 3.0m broad. It is set into a W-facing slope. The entrance was presumably in the S but no details survive. There is no trace of cultivation plots, and apart from a ruckle of stones nearby, no clearance. However the surrounding ground is smooth and relatively stone-free suggesting some form of cultivation. Visited by OS (N K B) 19 July 1976. Scheduled as 'Kilphedir, hut circle and souterrain...' Information from Historic Scotland, scheduling document dated 8 November 2000. Publication Account (1995) RCAHMS: Exploring Scotland's Heritage - The Highlands, 1995 The broch [Asset 65/SM1870] is on the hill east of the burn but cannot be seen from the road by the bridge. A sheep track just east of the bridge leads up the hill, bearing slightly right, and passes through a deserted crofting settlement under the line of the electricity poles; there are the foundations of a longhouse, and some smaller buildings and a kiln barn. From the first skyline the broch is visible on the hillside above, some 15 or 20 minutes walk

from the road. The broch is set on a prominent knoll with good views up and down the valley. It is ruinous, and appears as a great mass of rubble spilling down the hill, but it has a particularly impressive set of outer defences, now all covered with heather so that the stone walls look like banks. There are terraces east and west of the broch defended by an inner rampart, a deep ditch and a stout outer rampart. At the west end, the entrance is protected by an extra short stretch of rampart. Just below the broch is a good path along the side of the hill; follow it west to find three hut circles on the edge of the ravine above the burn (NC 991190). One hut circle (A [Asset 67/SM1872]) has much thicker walls than the other two, and this one has a souterrain leading out of it beneath its wall. The far end has been broken into, so light comes in, but it may be full of water and gumboots are needed. A muddy hole, originally provided with steps, drops down into the narrow souterrain passage; the latter has drystone walls and a lintelled roof and is about 9.50m long.

There are more hut circles up the burn and on the west bank. Some of the latter were excavated in the 1960s, and shown to have interior posts that supported their thatched roofs, while radiocarbon dates from two huts suggest they were occupied in the last few centuries BC. A number of clearance cairns round these and other hut circles are probably of the same date and show that some patches of ground were cultivated. Many other hut circles can be seen on the hill slopes along the north side of the Strath of Kildonan, some indicated on the OS map, and at least six other souterrains have been found, three still attached to hut circles. Part of one at Suisgill (NC 897250) is close to the east side of the road; only the far end survives, with lintelled roof and a curved end-wall, in which is a small built-in recess or cupboard.
Information from 'Exploring Scotland's Heritage: The Highlands', (1995).

Asset/Event Number	24
Asset/Event Name	Kilphedir, hut circles & field system 150m-600m E of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM2809; NC91NE 29
HER Number	MHG9854
Status	Scheduled Monument
Section:	N/A
Easting	299268
Northing	918678
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM2809 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/7002. (Centred NC 994 186) Hut Circles (NR) (Even shown) (A: NC 9904 1880) Enclosure (NR) OS 6" map, 1964. To the N of the road bridge over Allt Cille Pheadair, is a circular enclosure (A) formed by a single line of contiguous boulders. At the NE, a mound about 14' in diameter lies partly on the circumference. A number of mounds, several apparently excavated, and some hut circles lie nearby. Amongst these mounds are the remains of old banks or walls, in some instances connecting with small circular enclosures. One, 350 yards SSW of the broch (See NC91NE 27) is 9' internal diameter with a S entrance. Attached to it on the S is an oval enclosure measuring 15' by 11' internally.

RCAHMS 1911, visited 1909.

A total of five hut circles (A, B, D, E and F) an enclosure ©, a sub-rectangular structure (G) and a scooped shieling-type structure (H) were locate during field perambulation.
Visited by OS (W D J) 21 May 1960.

Centred at NC 993 187 on an undulating SW-facing slope in open moorland, is a settlement of five stone-walled huts (A-E) within a well-preserved field system. Huts C and E are more massive than the others, being broadly similar to Kilphedir type II (See NC91NE 25) whereas A, B and D can be equated with the earlier type 1 hut. F cannot be located.

Of the denuded hut A, 12.5m overall diameter, little more than the outer face of stones on edge can be seen. The mound overlying the wall in the NW is a clearance heap. B measures 7.0m N-S by 6.0m internally within a wall of 1.1m estimated thickness. Some outer facing stones are visible. C is 12.5m NW-SE by 10.0m within a wall now 0.8m internal height which is spread to 3.0m broad widening to 4.0m at the entrance which is clubbed. Hut D adjacent to C is 5.5m NW-SE by 5.0m within a wall spread to 2.0m broad, and E is 8.0m NW-SE by 7.0m within a wall of 2.0m estimated breadth widening to 3.0m at the entrance where one portal stone is extant. The entrance to each hut is in the S or SE arc, and, with the exception of C is of simple form. The field system occupies an area of about 15 hectares, best-preserved in the vicinity of huts A and B where a number of contiguous cultivation plots, 25.0m by 15.0m average size, are discernible. These plots are delineated by clearance, heaped and linear, and stony lynchets.

The 'sub-rectangular structure' (G) cannot be located, and the structure (H), as described by previous OS field investigator, is possibly a shieling.
Re-surveyed at 1:10,560
Visited by OS (N K B) 26 July 1976.

References
RCAHMS. (1911a) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. Edinburgh. Page(s): 116, Nos. 329-31 RCAHMS Shelf Number: A.1.1.INV(2)

Asset/Event Number	25
Asset/Event Name	Kilphedir, hut circle 830m NNE of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM2810; NC91NE 3
HER Number	919453
Status	Scheduled Monument
Section:	N/A
Easting	299174
Northing	919453
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM2810 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/7003/allt-cille-pheadair. This is the same description for Asset 66/SM1871. Asset 25 is the hut circle A described below.

Due E of a hut circle group (NC91NE 25 [Asset 22/SM2807]), on the opposite bank of Allt Cille Pheadair, are two hut circles. The more southerly example (B [Asset 66/SM1871]) appears to be placed within an oval enclosure. On the W side of the entrance is a small chamber entered through a passage, with a lintel at its inner end. This may be the entrance to an earth-house.
RCAHMS 1911, visited 1909.

Two hut circles as described.
Visited by OS (W D J) 20 May 1960.

On a gentle S-facing slope in open moorland, are two well-preserved stone-walled huts within an associated field system. The huts appear to be broadly similar in size and construction. 'A' [Asset 25/SM2810] measures 9.0m NW-SE by 8.5m transversely within a heather-covered wall, 2.8m thick all round, which is faced inside and out with large stones on edge. The 'simple' entrance is in the SE arc. Hut 'B' [Asset 66/SM1871] (at corrected grid reference NC 99201941) is 9.0m internal diameter within a rubble wall about 2.0m to 3.0m thick, faced internally with a crude uncoursed wall of large stones, 1.0m high, the flatter side of the stone facing the inside of the hut. The wall thickens at the entrance in the SE arc to 4.0m; portal stones indicate the passage was 1.1m wide with parallel sides. The depression in the wall on the W side of the entrance may be the tumbled remains of a souterrain, but an absence of visible wall facing renders this uncertain. The hut appears to have been built within an earlier hut which was set into the hillslope and measured approximately 11.0m NW-SE by 9.5m within a heather-covered wall spread, where visible, to 2.5m. Two inner facing slabs are visible in the NW arc. The huts appear to share a common entrance in the SE.

The associated field system of 1 1/2 hectares comprises cleared plots, average size 40.0m by 30.0m defined mainly by lynchets and one or two field walls. There is little evidence of clearance heaps.
Re-surveyed at 1:10,560.
Visited by OS (N K B) 21 October 1976.

References
RCAHMS. (1911a) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. Edinburgh. Page(s): 114-15, Nos. 326, 327 fig.49 RCAHMS Shelf Number: A.1.1.INV(2)

Asset/Event Number	26
Asset/Event Name	Kilphedir, hut circles & field system 1260m NNE of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM2811; NC91NE 30
HER Number	MHG9852
Status	Scheduled Monument
Section:	N/A
Easting	299227
Northing	919826
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://portal.historicenvironment.scot/designation/SM2811 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/7004/allt-cille-pheadair. On the E side of the Cille Pheadair burn, about 1 mile N of its junction with the Helmsdale River, is a group of three contiguous enclosures, two of which appear to have been cattle or sheep folds. A horn projects on the W side of the entrance to the most easterly one. An opening has been broken through the banks of this and the northerly enclosure, apparently at a later date. Near the three enclosures are a dozen or so small mounds. Some 30 yards N, on the end of a slight knoll, is a cup-shaped hollow, with an opening to the S, 10' in diameter and apparently lined with stones. Some 30 yards S is a circular enclosure with traces of an inner compartment. RCAHMS 1911, visited 1909. The three contiguous enclosures comprise a hut circle (A) an enclosure (B), and a semi-enclosed area. In the interior of the hut are traces of two small compartments. Some 40.0m W of hut A is another hut circle (C) that is almost certainly the last enclosure noted by the RCAHMS. The cup-shaped hollow could not be identified. The mounds are probably field clearance heaps. Visited by OS (W D J) 20 May 1960. There are three stone-walled houses (A-C) in association with a field system. The situation is rising moorland open to the S. The huts are reduced and heather-covered but seem broadly similar. 'A' is 9.0m diameter inside a wall of main width 2.0m broadening to 3.0m at an obscure entrance from the SSE. The ground to the rear of the hut is partially enclosed on the N and E sides, by a low scarp scooped from the ascending slope and joining to the NE arc of the hut. 'B' is 9.5m diameter internally. The wall has a general spread of 3.0m that increases to 4.5m at a clubbed entrance, 3.0m wide, from the S. A form of forecourt precedes the entrance, evidenced by a seemingly built-up and levelled crescentic area 4.5m by 3.0m, partially enclosed on the S and W sides, by a low curving bank that connects in the W of the entrance. 'C' is 9.0m inside diameter. The wall, at a choked entrance, from the SSE, is spread to 3.5m but in the NNW has been broken through, and elsewhere is vague. The alleged traces of inner compartments in huts A and C are too tenuous to be conclusive. In the slope some 90.0m N of hut C is a low depression, Approximately 3.5m diameter, inside a vaguely suggested bank. No stone is apparent. This may be the cup-shaped hollow referred to but it seems natural or at best a surface quarry. The field system occupying four hectares, is best distinguished by a stone-free close-cropped appearance marked with scattered field clearance heaps, except to the N of hut B where there is an appreciable concentration. There are occasional substantial lynchets, and in the vicinity of the huts, indecisive signs of a pattern of field banks. Re-surveyed at 1:10,560. Visited by OS (J M) 1 July 1976. References RCAHMS. (1911a) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. Edinburgh. Page(s): 116-17, No. 332 RCAHMS Shelf Number: A.1.1.INV(2)
Asset/Event Number	27
Asset/Event Name	Kilphedir, hut circle 1260m NE of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM2812; NC91NE 34

HER Number	MHG9900
Status	Scheduled Monument
Section:	N/A
Easting	299468
Northing	919748
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM2812 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/7008/allt-cille-pheadair. Asset 27 is the hut circle A described below. A hut circle (A) was found during field work. Visited by OS (J L D) 9 June 1960. There are two reduced and peat-covered stone-walled hut circles (A and B) - 'A' [Asset 27/SM2812] now at correct plan position NC 9947 1974 and 'B' located at NC 9945 1969 - set in the lower reaches of a westerly facing hillside. There are no signs of associated agriculture. Both huts are levelled into the slope, and a simple entrance in each is from the S on the line of the longer axis. 'A' [Asset 27/SM2812] is about 9.0m by 7.5m inside a wall spread to 3.0m. 'B' is about 8.5m by 7.5m within a wall spread on average to 3.0m. Surveyed at 1:10,560. Visited by OS (J M) 1 July 1976
Asset/Event Number	28
Asset/Event Name	Kilphedir, hut circle 740m ESE of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM2814; NC91NE 33
HER Number	MHG9901
Status	Scheduled Monument
Section:	N/A
Easting	299594
Northing	918491
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM2814 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/7007/kilphedir. A small sub-rectangular enclosure abutting the S side of an old track. Visited by OS (W D J) 21 May 1960. This is a reduced, circular stone-walled hut circle occupying a sheltered position in rising

broken ground open to the SE. The hut is about 9.5m diameter internally. The wall, peat-covered generally, is vague in the N arc but otherwise indicates a main width of 1.2m that expands to 1.8m at an entrance from the E. Some largish stones are evident in the wall construction particularly in its exterior in the S half. Associated agriculture is noted by occasional mound and ruckles of field clearance on the hillside ascending from the S - no cultivation plots are discernible. About 45.0m S of the hut, on the slope, is a level circular patch, 11.0m diameter, slightly raised from its surround and with some stone in evidence, which may be remains of another hut circle.
Revised at 1/10,000.
Visited by OS (J M) 8 July 1976.

Asset/Event Number	29
Asset/Event Name	Allt Cille Pheadair, hut circles & clearance cairns
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM2841; NC92SE 1
HER Number	MHG9531
Status	Scheduled Monument
Section:	N/A
Easting	298838
Northing	920073
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM2841 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/7149/allt-cille-pheadair. A settlement of three hut-circles (A-C) accompanied by a few field clearance heaps and field banks, lying on a SE- facing slope. RCAHMS 1911, visited 1909. 'A' has originated as a 'simple' oval hut, measuring 12.1m by 8.7m within an earth and stone bank 0.4m high and spread to 2.6m, and having an entrance in the SE on the line of the longer axis. Inside the hut and partially overlaying the SE wall arc is a secondary circular stone hut of Kilphedir type II (4), 7.3m diameter within a wall of main width 1.1m An entrance passage, splayed and extending into the entrance of the original hut, is 2.4m long 0.9m to 1.2m wide and is flanked by large stones. The remains of a stone wall spring from the back of the secondary structure, and runs for a distance of about 20.0m passing through the wall of the original hut. A slight earth and stone bank springs from the east side of the latter turning sharply to the SE after a few metres. 'B' has been a 'simple' hut some 10.0m diameter internally but only a slight turf bank 0.1m high and 1.7m wide is now visible, with a red grit boulder standing in the east side. An entrance may be indicated by a slight depression in the south. 'C' is a 'simple' hut, slightly scooped out of the slope in the NW and measuring 10.5m by 8.5m internally. A wall width of 2.0m is estimated at a 1.0m wide entrance in the SE on the line of the longer dimension; elsewhere the wall is spread to 1.5m. Using the Kilphedir excavation as an analogy (H Fairhurst and D B Taylor 1974) the sequence of occupation for this site would appear to be a settlement of three 'simple' huts, with associated field clearance heaps, dating about 500 BC, followed by a re-occupation and

reconstruction of a single hut of about 130 BC with associated field banks.
Visited by OS (W D J) 8 December 1976

Details as in previous report. The associated agriculture is heavily masked by peat-silting and cultivation plots are not discernible.
Visited by OS (J M) 8 December 1976.

References
Fairhurst and Taylor, H and D B. (1974) 'A hut-circle settlement at Kilphedir, Sutherland', Proc Soc Antiq Scot, vol. 103, 1970-1. Page(s): 65-99
RCAHMS. (1911a) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. Edinburgh. Page(s): 117, No. 333 RCAHMS Shelf Number: A.1.1.INV(2)

Asset/Event Number	30
Asset/Event Name	Balcraggie Lodge, four hut circles 300m SSE of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM3521; ND13SW 2
HER Number	MHG1259
Status	Scheduled Monument
Section:	N/A
Easting	314246
Northing	930258
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM3521

Statement of National Importance
The monument is of national importance for its potential contribution to an understanding of prehistoric and post-medieval settlement and land use and the process of the Clearances in this area of the Highlands. The hut foundations are well-preserved and may retain information on the architecture of prehistoric houses.

https://canmore.org.uk/site/8212/balcraggie-lodge

A quarter of a mile SSE of Balcraggy Lodge and about 100 yds from the road is a hut circle, measuring some 28ft in diameter within a much broken-down bank of turf and stone. An old stone wall has at one time run along the N side of it, and stones appear to have been taken from the inner face of the bank.
RCAHMS 1911, visited 1910.

Centred ND 142 302 are four enclosures or hut circles, formed by earth-and-stone banks 0.6m in average height, and varying from 10.0 to 12.0m in diameter. The entrances are in the E sides, except for the hut at ND 1424 3024, which has its entrance in the N. The hut at ND 1429 3023 is that described by the RCAHMS (1911) and noted as a cairn on OS 6" map, Caithness, 2nd ed., (1909)
Visited by OS (W D J) 25 June 1960.

A settlement of four hut circles as described by the previous OS field surveyor. About six scattered stone clearance heaps remain. Further evidence of contemporary cultivation has

probably been destroyed by more recent cultivation.
Surveyed at 1:2500.
Visited by OS (R L) 15 March 1968.

(ND 142 302) Settlement (NR)
OS 25" map, (1970)

A settlement of four hut circles (A - D) accompanied by half a dozen stone clearance heaps. The huts are heather or turf-covered and in the case of both 'A' and 'B' there is a thick growth of bracken.

'A', at ND 1429 3023, measures 9.0m in diameter within a wall spread from 2.5 to 3.0m and varying from 0.5 to 0.9m high; the entrance is in the E. The N arc of the hut has been overlaid by an old field wall.

'B', at ND 1424 3024, measures 8.5m in diameter within a wall spread from 2.0 to 2.5m and up to 0.7m high. The only suggestion of an entrance is a depression in the N, but it is highly suspect as this arc of the hut has been overlaid by an old field wall.

'C', at ND 1420 3022, measures 10.5 by 9.5m within a wall spread from 2.5 to 3.0m and, in the W, up to 0.9m high. The entrance is in the E, on the line of the main axis, and has a lining slab in situ on the N edge. 'D', at ND 1412 3021, measures an estimated 9.5m in diameter within a wall spread from 2.5 to 3.0m and up to 0.5m high. The entrance has probably been in the now mutilated E side.
Visited by OS (J M) 19 August 1982.

References
RCAHMS. (1911b) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Third report and inventory of monuments and constructions in the county of Caithness. London. Page(s): 65, No. 239 RCAHMS Shelf Number: A.1.1.INV(3).R

Asset/Event Number	31
Asset/Event Name	Rinsary, homestead 500m WNW of,Berriedale
Type of Asset/Event	Prehistoric/early historic settlement
Date and/or Period	Prehistoric/Early Historic
Listing No./NRHE Number	SM3473; ND12SW 5
HER Number	MHG1121
Status	Scheduled Monument
Section:	N/A
Easting	311267
Northing	923858
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM3473 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/8107/rinsary. ND 1127 2385. Situated on a knoll in arable land, about 500m WNW of Rinsary, are the remains of a double-ditched enclosure. A shallow gully flanks it on the NW, and a small stream on the SE. A causeway, 5.2m broad, crosses the ditches on the E side. These ditches do not appear to

be palisade trenches, being 2 to 3m wide by 0.2m deep, and enclose a central area measuring some 24m E-W by 18.5m transversely. Within the enclosure and on the highest part of the knoll, are traces of a ring-groove hut circle, 7.0m in diameter, the trench being 0.4m wide by 0.1m deep. Some 5.0m beyond the main ditches, on the S and E, are traces of a palisade trench 0.4m wide by 0.1m deep, with an appropriate break at the causewayed entrance, and widening into an evident ditch towards the gully on the W.
Visible on RAF air photographs CPE/Scot/UK 179: 1308-9.
Visited by OS (J L D) 15 June 1960.

(ND 1127 2385) Earthwork (NR)
OS 6" map, (1964)

Generally as described by previous OS field surveyor, except that only a small portion of the ring-ditch hut on its SE quadrant is now evident; and no trace can now be seen of the palisade trench between the short stretch of ditch close by the gully and another similar ditch beside the entrance.
Surveyed at 1:2500.
Visited by OS (R L) 7 March 1968.

(ND 1127 2385) Homestead (NR)
OS 25" map, (1969)

Situated on the summit of a glacial knoll in what is essentially a non-defensive position are the remains of a double-ditched enclosure. It is generally as described by previous OS field surveyor (R L), except that there is some doubt as to the authenticity of the ring-groove hut. The groove does not form a regular curving circle, and it encloses a mounded area 0.2m high. There is no trace of banks or stone-built ramparts associated with the ditches, and it may therefore have been a palisaded enclosure; as such it would be unique in Caithness. It is almost certainly some form of homestead.
Visited by OS (N K B) 24 March 1983.

Asset/Event Number	32
Asset/Event Name	Tulach Bad a'Choilich, hut circles, settlement and cairns 400m ENE of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM3475; ND12SW 6
HER Number	MHG1122
Status	Scheduled Monument
Section:	N/A
Easting	310469
Northing	924191
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM3475 The monument comprises a group of at least 6 prehistoric hut circles or enclosures, 2 later rectangular foundations, traces of field walling and a scatter of field clearance cairns. It was partially scheduled in 1974, as two separate groups of small protected areas, but these were inadequate to cover even the most visible of these archaeological remains. This extension rectifies the situation. The monument lies on a hill shoulder which protrudes into Strath Cuil from the E, at a height of between 320m and 400m above sea level. The hut circles are round or oval on plan, and

	measure between 8m and 13m across. 5 of the six lie in the S end of the area proposed for scheduling, together with a small number of field clearance cairns. The 6th hut circle lies towards the N end, and is bracketed by 2 later, rectangular, dwelling foundations. This northern area has rather more field clearance cairns and also traces of boundary walling. All of the remains are covered by moorland heather. The area now to be scheduled is irregular on plan. It measures a maximum of 420m NW-SE by 320m NNE-SSW, to include all of the features mentioned above and an area between and around them in which evidence relating to their construction and use is likely to survive. The area is indicated in red on the accompanying map extract.
Asset/Event Number	33
Asset/Event Name	Tulach Bad a Choilich, broch 670m NW of Cnoc Fionn
Type of Asset/Event	Broch
Date and/or Period	Iron Age
Listing No./NRHE Number	SM3477; ND12SW 9
HER Number	MHG1125; MHG39556
Status	Scheduled Monument
Section:	N/A
Easting	310055
Northing	924046
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM3477 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/8111/tulach-bad-a-choilich. Broch, 'Tulach Bad a Choilich': On a spit of land E of the Allt Bad a' Choilich, beside the path up the Berriedale Water, and about a mile NW of Langwell House, are the ruins of a small broch. Towards the river, but nowhere else, the lower face of the wall is visible; no measurements, however, are obtainable. RCAHMS 1911. All that remains of this broch is a large earth-and-stone mound measuring approximately 19.0m E-W by 15.0m transversely, and 3.0m high above the slope on the E. On this side, a small portion of the outer wall face can be seen, and there is also a slight depression on the top of the mound. It was not possible to obtain any measurements of the broch structure. The remains of an earth and stone bank, 1.7m broad and 0.4m high, were noted at the S edge of the mound, but it is not clear if it is contemporary with, or later than, the broch. On the opposite side of the path from the broch are the footings of a building some 15.0m long by 4.0m wide, divided into two compartments, with a wall now 0.6m high. Visited by OS (W D J), 4 July 1960. The remains of a broch, as described by the previous authorities. Visited by OS (N K B), 10 November 1982. Publication Account (2007) Euan W Mackie Broch Corpus 2 ND12 5 TULACH BAD a' CHOIL-ICH ('Berriedale Water 2', 'Langwell House 2') ND/1005 2404 Possible broch in Latheron, Caith-ness, in the form of a wrecked mound standing on a spit of

	land east of the stream Allt Bad a' Choilich. Traces of the outer face are visible towards the river. Sources: 1. NMRS site no. ND 12 SW 9: 2. RCAHMS 1911b, 53-4, no. 202. E W MacKie 2007 References MacKie, E W. (2007) The Roundhouses, Brochs and Wheelhouses of Atlantic Scotland c.700 BC-AD 500: architecture and material culture, the Northern and Southern Mainland and the Western Islands, BAR British series 444(II), 444(1), 2 V. Oxford. Page(s): 427 RCAHMS Shelf Number: E.9.1.MAC RCAHMS. (1911b) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Third report and inventory of monuments and constructions in the county of Caithness. London. Page(s): 53-4, No. 202 RCAHMS Shelf Number: A.1.1.INV(3).R
Asset/Event Number	34
Asset/Event Name	Tulloch Turnal, broch 500m WNW of Turnal Rock, Langwell
Type of Asset/Event	Broch
Date and/or Period	Iron Age
Listing No./NRHE Number	SM3440; ND02SE 4
HER Number	MHG2425; MHG20201
Status	Scheduled Monument
Section:	N/A
Easting	309040
Northing	922854
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM3440 The monument comprises the remains of a broch, a drystone-built, fortified dwelling of Iron Age date. It is already scheduled, but the scheduled area does not cover all of the area of archaeological importance. This proposal rectifies the position. The broch stands immediately to the S of an estate track. It stands about 2m high and is about 14m in diameter. Two courses of the outer wall face can be seen in places. No detail is visible in the interior, although a slight depression hints at the entrance being on the S side. There is an external ditch and bank on the E side, and this may once have extended around the N side of the broch, although its traces have been removed by later construction activity. The area now to be scheduled is semi-circular, 60m in diameter, with the S side of the track as its N edge. This includes the broch and the slight traces of outer defences as well as an area around them in which evidence relating to their construction and use may survive. The area is marked in red on the accompanying map extract.
Asset/Event Number	35
Asset/Event Name	Langwell Tulloch, broch 400m SE of Turnal Rock
Type of Asset/Event	Broch
Date and/or Period	Iron Age
Listing No./NRHE Number	SM3441; ND02SE 10
HER Number	MHG1508

Status	Non-designated Heritage Asset
Section:	A1.4
Easting	309739
Northing	922315
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	High
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Remains of a broch under dense vegetation, grass and small trees, situated on the edge of a terrace overlooking the Langwell Water. As described below.* https://portal.historicenvironment.scot/designation/SM3441 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/7525/langwell-tulloch. On the S side of the road up the Langwell Water and some 200 yds W of the wall which divides the woodlands from the moor beyond the garden, are the very confused remains of a construction. Much stone has been removed from it, and its original character is not apparent. It is known as 'Langwell Tulloch'. RCAHMS 1911, visited 1910. The mutilated remains of a broch, now a shapeless mass of rubble measuring approximately 28.0 by 32.0m. Part of the face of the outer wall of the broch is visible on the S side and a wall, probably later, forming an outer enclosure or annexe, encloses the broch on the W, S and E. Visited by OS (W D J), 15 June 1960. This broch is generally as described by the previous OS field investigator. Although it has been extensively robbed, the common Caithness 'mound on mound' profile is evident. The broch mound measures approximately 16.0m NE-SW by 14.5m and is 1.5m high. Visited by OS (J B), 3 September 1982. This broch was visited by Headland Archaeology in the course of a pre-afforestation survey (NMRS MS 899/15, no.16). A large stone and turf enclosure, extending N from the outer broch enclosure was recorded in addition to the broch remains previously noted by RCAHMS (1911). C Moloney and L Baker (Headland Archaeology) 13 July 1998; NMRS, MS/899/93, no.17. Site recorded during a survey undertaken of c.2 sq km of land either side of the Langwell Water, by Berriedale. ND 0974 2231 Broch Sponsor: Historic Scotland, C Moloney and L Baker 1998. Publication Account (2007) Euan W Mackie Broch Corpus 2 ND02 1 LANGWELL TULLOCH ('Langwell Water 1') ND/0974 2231 A probable broch in Latheron, Caithness, in the valley of the Langwell Water, and now a much-mutilated mass of rubble; part of the curved outer face of the wall is visible on the south [1]. The remains of the structure appear to be sited on an artificial mound [1]. A large stone- and-turf enclosure next to the broch was recorded later [3]. Sources: 1. NMRS site no. ND 02 SE 10: 2. RCAHMS 1911a, 83, no. 301: 3. Moloney and Baker 1998, 56-7. E W MacKie 2007 References MacKie, E W. (2007) The Roundhouses, Brochs and Wheelhouses of Atlantic Scotland c.700 BC-AD 500: architecture and material culture, the Northern and Southern Mainland and the

Western Islands, BAR British series 444(II), 444(1), 2 V. Oxford. Page(s): 404 RCAHMS Shelf Number: E.9.1.MAC
Moloney and Baker, C and L. (1998) 'Langwell Estate, Berriedale (Latheron parish), pre-afforestation survey', Discovery Excav Scot, 1998. Page(s): 56-57
RCAHMS. (1911b) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Third report and inventory of monuments and constructions in the county of Caithness. London. Page(s): 83, No. 301 RCAHMS Shelf Number: A.1.1.INV(3).R

Asset/Event Number	36
Asset/Event Name	Torboll Farm, cairn 1450m WSW of
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM1819; NH79NW 14
HER Number	MHG45299
Status	Scheduled Monument
Section:	N/A
Easting	273975
Northing	898444
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM1819

The monument comprises a prehistoric burial cairn, between 4500 and 3500 years old, sitting on the eastern edge of a knoll in rough open moorland, just within a birch wood.

The cairn is roughly circular, measuring about 17.3 m from N to S, by 16.6 m transversely, and up to 2 m in height on the E side, which would have given this cairn pronounced visual emphasis when viewed from the E. Around the base of the cairn is a kerb of large contiguous boulders, averaging about 0.3 m in height and 0.4 m to 0.6 m in length. On top of the cairn is a slight circular depression, approximately 2 m in diameter. The main body of the cairn is composed of small stones covered in heather, grass and a small number of birch trees; a pheasant pen has also been constructed on the SE corner.

The monument was first scheduled in 1935, but an incorrect area was defined. The present rescheduling rectifies this. Furthermore, no legal documentation supporting the original scheduling survives.

The area to be scheduled is circular on plan, to include the cairn and an area around in which associated evidence for its construction and use may survive, as marked in red on the accompanying map. The above-ground parts of the pheasant pen fence-posts are to be excluded from the scheduling, to allow for their maintenance.

Statement of National Importance
Cultural Significance
The monument's archaeological significance can be expressed as follows:

Intrinsic characteristics: There is a strong likelihood that the characteristic structural features that define this class of monument, and the internal and external archaeological deposits associated with this particular monument, remain well preserved, despite the encroachment of trees and heather. The height of the mound and the survival and remaining conspicuousness of the kerb, a distinctive feature of this particular cairn, would appear to confirm this.

Contextual characteristics: The monument occupies a prominent position in the landscape with wide views over the surrounding moorland, where there is evidence for prehistoric settlement and associated field systems. It would have formed a significant place within the landscape of this area throughout later prehistory.

Few burial mounds in the eastern part of Sutherland have been identified in similar contexts, close by settlements, clearance cairns and agricultural activity. The majority are also either small with few distinctive architectural features, or much larger chambered cairns. This moderately large cairn with distinctive features is therefore a rare typological example that provides an opportunity for future study of how the spheres of life, agriculture and death interacted in the live of prehistoric societies within this region.

National Importance
This monument is of national importance because it is a well-preserved example of a rare cairn form. It has the potential to inform future research about the dating and development of differing cairn types, and about the various ways in which these different forms may have been used, perceived and encountered. Its prominence suggests that it would have formed an intrinsic part of the prehistoric landscape in this area, coming to be incorporated into, and reverenced within, an agricultural and settled landscape in later prehistory. Its loss would affect our ability to understand this monument class as well as the surrounding landscape.

References
The monument is recorded by RCAHMS as NH79NW 14.
RCAHMS 1911, SECOND REPORT AND INVENTORY OF MONUMENTS AND CONSTRUCTIONS IN THE COUNTY OF SUTHERLAND, Edinburgh.

Asset/Event Number	37
Asset/Event Name	Firth View, settlement 1300m NW of
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM4728; NH 56 SW 10
HER Number	MHG8929
Status	Scheduled Monument
Section:	N/A
Easting	250833
Northing	862320
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM4728 The monument comprises a group of four hut circles and an area around them containing evidence of agricultural activity. Two of the hut circles are already scheduled; this re-scheduling proposal extends protection to the other two and to a larger surrounding area. The hut circles - the foundations for prehistoric timber houses - are loosely grouped together at around 250m OD on a SE-facing hillslope, overlooking upper Strath Sgitheach. The most easterly circle (which lies about 25m from the edge of a large forestry plantation) measures about 11m by 13m, with an entrance on the SSE side. Just over 100m to the NNE lies a second hut circle, of similar size but with no apparent entrance. Some 180m to the NE of the first circle lie another two hut circles, only 1m apart, one about

	12m by 9m with an entrance on the SSE, and the other about 17m by 15m with an entrance on the S. Around these hut circles, especially noticeable by the first (most easterly) circle, lies a scatter of small cairns of field-cleared stone, indicating contemporary agricultural activity. The area now to be scheduled is an irregular oval, with a straight section on the WSW side, parallel to the edge of the forestry plantation. The area measures a maximum of 290m NE-SW by a maximum of 175m transversely, to include all four hut circles and an area around them scattered with small cairns, as marked in red on the accompanying map. Statement of National Importance The monument is of national importance as a well-preserved late pre-historic settlement, which has the potential to provide information about prehistoric domestic and agriculture activities. References RCAHMS records the monument as NH 56 SW 10.
Asset/Event Number	38
Asset/Event Name	Strath Sgitheach, settlement NW of Cnoc a'Mhuilinn
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM10495; NH56SW 11
HER Number	MHG8928
Status	Scheduled Monument
Section:	N/A
Easting	251412
Northing	862747
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM10495 The monument comprises the remains of an extensive prehistoric settlement on a SE-facing slope above Strath Sgitheach. The settlement contains at least eight hut circles, the circular foundations of prehistoric timber houses, set in areas of small cairns of field-cleared stones on a heather-clad hillside, just above forestry planting. There are also at least three cup-marked boulders within the area, of unknown purpose but presumed prehistoric date, and more may well exist. The hut circles have dimensions ranging from 13m by 11m to 9m by 7m, and where entrances can be seen these are all in the SE or S arcs. The most easily visible hut circles are a loose group of three on the SW bank of the Allt nan Raichean. The area to be scheduled is a very irregular figure-of eight shape on plan, measuring a maximum of 640m NE-SW by a maximum of 260m transversely. This area includes the hut circles, the field clearance cairns and the cup-marked boulders, as well as an area of land around and among these features in which evidence relating to their construction and use is likely to survive. The area is indicated in red on the accompanying map. Statement of National Importance The monument is of national importance as a well-preserved late prehistoric settlement which has the potential to provide information about prehistoric domestic and agricultural activities and land-use changes. The close association of a settlement with a number of cup-

	marked boulders is unusual, although the significance of this is not known. References Bibliography RCAHMS records the monument as NH 56 SW 11. RCAHMS (1979) The Royal Commission on the Ancient and Historical Monuments of Scotland. The archaeological sites and monuments of Easter Ross, Ross and Cromarty District, Highland Region, The archaeological sites and monuments of Scotland series no. 6, Edinburgh, 18, 21, Nos. 132, 172.
Asset/Event Number	39
Asset/Event Name	Kilphedir, hut circles & chambered cairns 700m E of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM290; NC91NE 32
HER Number	Various
Status	Scheduled Monument
Section:	N/A
Easting	299563
Northing	918691
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM290 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/7006/kilphedir. On the edge of a small plateau SE of the broch (Asset 65/SM1870/NC91NE 27) are two cairns (A and B) discovered during field investigation - one possibly chambered. Visited by OS (W D F) 21 May 1960. Of the two cairns, 'A' is roughly circular and chambered, measuring about 56ft NW-SE by 51ft transversely and 4 or 5ft high. Three large slabs are exposed, probably the back slab, a divisional or portal slab, and the NE portal at the passage entrance, indicating a chamber orientated NW-SE and entered from the SE. Cairn 'B' measure about 70ft by 55ft and 3ft high. Parts of a boulder kerb or possibly two concentric kerbs together with several large earthfast slabs, are visible. As the plan is not evident, the classification of this cairn is uncertain. A S Henshall 1972, visited 1963. As described by Henshall, cairn 'A' is chambered, but insufficient details of 'B' are exposed to enable it to be classified as a chambered cairn, though the presence of large stones in the body of the cairn render this highly probable. Re-surveyed at 1:10,560. Visited by OS (N K B) 29 November 1976.
Asset/Event Number	40
Asset/Event Name	Achkinloch, stone setting SW of,Loch Stemster
Type of Asset/Event	Standing stone
Date and/or Period	Prehistoric

Listing No./NRHE Number	SM420; ND14SE 2
HER Number	MHG1315
Status	Scheduled Monument
Section:	N/A
Easting	318790
Northing	941779
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM420 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/8271/achkinloch. A setting of stones in the form of a truncated oval, open to the SE, which shows no sign of ever having been a completed oval. It measures 225ft long by 100ft and may originally have comprised about sixty stones of which about a third have either weathered or been removed. The stones are thick slabs of flag, standing to an average height of 5ft and set at intervals of about 8ft with their broad faces towards each another, not along the line. A cist measuring 5ft by 3ft 9ins, formed by four slabs set on edge stands against the most northerly stone of the setting. This monument, which can be compared only with the example at Broubster (ND06SW 19), should probably be assigned to the earlier part of the Bronze Age. J Anderson 1886; RCAHMS 1911; R W Feachem 1963. An unusual setting of standing stones generally as described and planned. One or two stones along the E side outside the uprights, particularly in the NE corner suggest that there may have been a retaining kerb on this side, which is on the edge of an escarpment. The cist, roughly oriented N-S, is of the dimensions noted by the RCAHMS (1911), but is not composed of four slabs. The E side is composed of four upright slabs and one similar slab on the W side suggests that this side has been the same. There is no trace of the end stones. Elsewhere the tops of a few other stones in a similar position immediately outside the line of uprights suggests the presence of similar structures as yet uncovered. Surveyed at 1:10,000. Visited by OS (I S S) 20 April 1972. A horse-shoe setting possibly comparable to the arrangement known within some stone circles, including Croft Moraig (NN74NE 12) and Broubster (ND06SW 19) as well as Stonehenge, although its opening to the SSE instead of the SW is untypical. H A W Burl 1973. Thirty-six flat, thin stones and snapped-off stumps. In fine weather the conspicuous Mt Morven is visible in the S over the nearby ridge and seems to be indicated by some of the stones. It may well be an astronomical foresight. E W MacKie 1975. No change to the previous field report. Visited by OS (N K B) 6 December 1982. Activities Field Visit (30 July 1910) RCAHMS County Inventory: Caithness At the SW. corner of Loch Stemster, about ½ m. SW of Achkinloch, is a remarkable setting of

standing-stones (pl. XXX.). In form the monument is an irregular oval, broader at one end than the other, and like a horseshoe, having the setting discontinued across one end and that the narrow one. The main axis is N. and S. with the open end towards the latter direction. The total length is 226ft, the width in the middle from side to side, interior measurement, 110ft, and at the open extremity 85ft. The stones are placed with their broad faces at right angles to the direction of the setting, and are on an average from 4' to 5' in height, the highest stone-that at the SW. termination-measuring 6' 4" in height. In breadth they vary from 3' to 5', and in thickness from 8" to 20". They have been placed at distances of 8' or 9' from each other. There are a number of gaps, and presuming that the intervals were regular and that the stones from these gaps have been removed, the number of stones originally forming the monument would be fifty-four. There now remain in situ thirty-four, of which two are mere stumps, and there lie prostrate other three. Abutting against a high stone at the NE. of the monument, and on the outside, is a cist-like construction formed of four slabs set in the ground and measuring 5' X 3' 9" interiorly. There is no evidence of an interment having been found in it.

This monument was surveyed by Sir Henry Dryden in 1871,and his plan was reproduced by Dr Joseph Anderson in his work referred to below.
See Anderson, The Bronze and Stone Ages, p. 132 (plan).
RCAHMS 1911, visited 30 July 1911
OS 6" map (1907) 'Standing Stones'

Publication Account (1995) RCAHMS: Exploring Scotland's Heritage - The Highlands, 1995
A remarkable setting of large stones, arranged in an unusual way as a long U-shape with one open end. Some 36 slabs or stumps survive, but some stones are missing, and there may originally have been around 54. The average size of the stones is about 1.2m to 1.5m, and the tallest is nearly 2m high. Many of the stones have been taller, but their tops have weathered and split off. The broad faces of the stones are set at right angles to the perimeter of the setting, in contrast to the practice at stone circles. Only one comparable monument is known, a ruinous U-shaped setting at Broubster, Caithness (ND 047608) [Canmore ID 7945]. The purpose of these settings is unknown, but their date is thought to be Bronze Age from their general similarity to stone circles.

Just outside the stones, close to their northeast corner and also along the east side, are some small slabs set on edge, which may be the remains of cist graves, perhaps added to the monument long after its initial purpose was forgotten. A short distance southeast of the stones, on a low hillock, are the remains of an earlier Neolithic round cairn with traces of a central chamber.
Information from 'Exploring Scotland's Heritage: The Highlands', (1995).

References
Anderson, J. (1886a) Scotland in pagan times: the bronze and stone ages: the Rhind lectures in archaeology for 1882. Edinburgh. Page(s): 133 Vol. 1 RCAHMS Shelf Number: E.2.AND
Burl, {H} A {W}. (1973b) 'Stone circles and ring-cairns', Scot Archaeol Forum, vol. 4, 1972. Page(s): 72
Close-Brooks, J. (1986a) Exploring Scotland's heritage: the Highlands, Exploring Scotland's heritage series. Edinburgh. Page(s): 160-1 No. 89 RCAHMS Shelf Number: A.1.4.HER
Close-Brooks, J. (1995a) The Highlands, Exploring Scotland's Heritage series, ed. By Anna Ritchie. 2nd. Edinburgh. Page(s): 157 No. 97 RCAHMS Shelf Number: A.1.4.HER
Feachem, R. (1963b) A guide to prehistoric Scotland. 1st. London. Page(s): 74 RCAHMS Shelf Number: E.2.FEA
MacKie, E W. (1975a) Scotland: an archaeological guide: from the earliest times to the twelfth century. London. Page(s): 223 RCAHMS Shelf Number: E.2.MAC
RCAHMS. (1911b) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Third report and inventory of monuments and constructions in the county of Caithness. London. Page(s): 80 No. 293 RCAHMS Shelf Number: A.1.1.INV(3).R

Asset/Event Number	41
Asset/Event Name	Cairn Liath, long cairn and round cairn
Type of Asset/Event	Cairn

Date and/or Period	Prehistoric
Listing No./NRHE Number	SM438; ND13SW 7 and 8
HER Number	MHG631; MHG1266
Status	Scheduled Monument
Section:	N/A
Easting	314028
Northing	932077
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM438 The monument consists of 2 prehistoric chambered cairns. The larger is a long cairn known as 'Cairn Liath'. This cairn is orientated WSW-ENE and is wider and higher at the latter end. It measures 58m long and is 18.3m wide to the ENE and 11.3 to the WSW. At its ENE end the cairn is about 1.5m high and there are faint traces of horn-like projections. There are also horn-like projections at its WSW end. There are traces of one chamber in the ENE end and three further chambers along the length of the cairn. About 30m NW of the long cairn are the remains of a circular cairn about 13.4m in diameter. Much of the cairn has been robbed, but three large upright stones in the centre indicate the presence of a chamber. The area proposed for scheduling measures a maximum of 90m NW-SE by 80m SW-NE to include the long cairn, the round cairn and an area around in which traces of activities associated with the construction and use of the cairns will survive. Statement of National Importance The monument is of national importance for its potential to contribute to an understanding of Neolithic/Bronze Age ritual and burial practices. The association of a circular and long cairn is important in the understanding of sequential development of cairn types in Scotland. There are indications that the chambers of the long cairn have not been robbed and it is probable that the burial deposits are complete. References Bibliography The monument is RCAHMS number ND 13 SW 7 and 8.
Asset/Event Number	42
Asset/Event Name	Cnoc na Maranaich, chambered cairn,burial cist and standing stone
Type of Asset/Event	Chambered cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM443; ND13SW 19
HER Number	Various
Status	Scheduled Monument
Section:	N/A
Easting	313222
Northing	933110
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM443 This monument consists of a chambered cairn, a burial cist, a standing stone and an area of stone quarrying which may be contemporary with the chambered cairn and cist. The chambered cairn is about 19m in diameter and 2m high and is partly turf covered. The central area has been disturbed and this has revealed a number of slabs which once formed part of a chamber. 4 modern cairns surmount the chambered cairn and an old sheep shelter has been constructed on its NE side. 7m to the E is a standing stone formed of a slab of rectangular cross section, pointed at the top and about 2.6m high. About 75m SSE of the chambered cairn is a burial cist with the capping stone still in position. The capping stone measures about 1.2 by 0.9m and beneath its corner can be seen the upright slab of a cist. The interior appears to be untouched. Immediately to the N and NW of the burial cist are traces of quarrying which could be contemporary with the construction of the 2 burial monuments. Two or more large flat stones have been intentionally wedged with blocks of stone in an attempt to loosen them from a natural rock stratum. These stones appear similar to the capping stone used in the cist. The area to be scheduled measures 160m NNW-SSE by 65m NNE-SSW, to include the chambered cairn, the cist, the standing stone and the evidence for quarrying, as shown in red on the attached map.
Asset/Event Number	43
Asset/Event Name	Achorn, broch 200m NW of
Type of Asset/Event	Broch
Date and/or Period	Iron Age
Listing No./NRHE Number	SM511; ND13SW 3
HER Number	MHG1262
Status	Scheduled Monument
Section:	N/A
Easting	313696
Northing	930504
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM511 This monument consists of the remains of a broch. The surviving remains form a large mutilated mound of earth and stone measuring 30m N-S by 27m E-W and about 3.5m high on the N side. A small trench has been dug about 6m SE from the centre of the mound and this has revealed one side of a gallery, or room, in the width of the broch wall. The area to be scheduled measures 50m in diameter, to include the broch and an area around in which traces of activities associated with its construction and occupation will survive. Statement of National Importance The monument is of national importance for its potential contribution to an understanding of prehistoric settlement and defensive architecture. References Bibliography The site is RCAHMS number ND 13 SW 3.
Asset/Event Number	45
Asset/Event Name	Balantrath, broch 135m WNW of
Type of Asset/Event	Broch

Date and/or Period	Iron Age
Listing No./NRHE Number	SM522; ND13SW 6
HER Number	MHG1265; MHG13560
Status	Scheduled Monument
Section:	N/A
Easting	314394
Northing	930718
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM522 This monument is a broch situated on a rocky outcrop on the left bank of the Dunbeath Water. The site consists of a large mound of earth and stone situated on the edge of a short vertical cliff. The mound measures approximately 23m NW-SE by 15m NE-SW and is about 3m high. There is some loose stone on top of the mound and a ruined stretch of the outer wall of the broch is exposed on the N side. There are traces of 2 possible sub rectangular structures at the base of the mound to the SW and SE and traces of a ditch can be seen on the NE and SE side of the broch. The area to be scheduled measures a maximum of 50m NW-SE by 35m NE-SW, to include the broch, the associated structures, the ditch and an area around in which traces of activities associated with the construction and use of the broch will survive, as shown in red on the attached map.
Asset/Event Number	46
Asset/Event Name	Wag Hill, prehistoric settlement 1300m NE of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM600; ND13SW 10
HER Number	MHG1254
Status	Scheduled Monument
Section:	N/A
Easting	311886
Northing	932955
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM600 The monument is a Post Medieval settlement which consists of a range of structures. These include 5 rectangular houses, 6 small oval shielings and 8 other irregular foundations, possibly shielings. The buildings vary in size from 3m across to 15m by 3.5m and survive in a variety of conditions which may indicate a fairly long period of occupation. There is also a stone-built sheepfold 14m in diameter to the S of the site. This settlement would appear to represent part of a 'cottar town', many of which were destroyed during the clearances of the late eighteenth and early nineteenth centuries. The area to be scheduled measures a maximum of 300m N-S and 240m E-W, to include the buildings and an area around them in which traces of activities associated with their use will survive, as shown in red on the attached plan. A recent forestry track and adjacent tipping is excluded from the area to be scheduled.

	Statement of National Importance This monument is of national importance for its potential to contribute to an understanding of prehistoric settlement and land use. This site incorporates important information on the domestic life and economic organisation of a prehistoric community. In addition the building contain evidence of prehistoric domestic architecture. References The monument is RCAHMS number ND 13 SW 10.
Asset/Event Number	47
Asset/Event Name	Wag Hill, prehistoric settlement 1050m NNW of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM603; ND13SW 5
HER Number	MHG1264
Status	Scheduled Monument
Section:	N/A
Easting	310651
Northing	933057
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM603 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/8217/wag. Galleried Dwelling, 'The Wag', Achnaclyth: About 3/4 mile SE of Achnaclyth, on the low ground by the side of the Wag Burn, and adjoining a large sheepfold are the remains of three or four galleried houses bearing the name of 'The Wag'. They all appear to have been oblong on plan, with rounded ends. The best preserved, which lies E-W, measures some 34ft in length and 15ft in breadth. The entrance appears to have been through the S wall, 23ft from the W end. The thickness of the wall has been about 6ft 6ins. The pillars, several of which remain in situ, have been placed at from 3ft to 3ft 9ins from the side walls, and at distances of from 4 ft 9ins and 6ft from each other in the rows. The space in the centre between the rows of pillars measures 5ft 8ins across. Ony two of the covering stones remain in position, one on each side. That on the N is 6ft in length and 2ft 8ins in breadth; that on the S, 5ft 9ins long and 2ft 6ins broad. They are both about 8ins thick. The greatest height of wall remaining exposed is 3ft, and the highest pillar measures 2ft 8ins above ground. Outside, as also at the E end, there are the indefinite remains of building. The walls, as usual in these structures, are built of large, flat stones, carefully laid. RCAHMS 1911, visited 1910. ND 1063 3308. Generally as described by the RCAHMS. There would appear to be three 'wags', two abutting nearest the sheepfolds; the middle one of the three is the best preserved and is as described above. There are the indefinite remains of possible buildings at the E end of the group. The third one is indistinct and consists of a mound some 1.4m high and measuring 20.0 by 9.0m over all; a large quantity of stone lies over the site, the whole being in a very dilapidated state. Within an area of pasture associated with a now-deserted crofting settlement, are two adjacent homesteads contained within separate mounds of debris, to which some later stone clearance has been added.

The SW mound contains two aisled rectangular houses (A and B). House 'A' is as described by the RCAHMS; 'B' is less well defined, but a single pillar stone and two stretches of inner wall-face are exposed. Its dimensions cannot be ascertained. Immediately to the E of 'A' is a mass of debris which may obscure a further structure, and E of 'B' are four probable pillar stones protruding through the mound, which may represent the remains of a further aisled house.
The NE mound (C) measures 22.0m E-W by 8.5m transversely and 0.6m

high, and contains fragments of an aisled rectangular house. There is much slab-stone in evidence, and towards the E end, which has been quarried, is an upright in situ, 0.7m high. The only other structural detail visible is a length of outer wall face near the W end of the mound. Dimensions of the house are not recoverable.
Revised at 1:10560.
Visited by OS (NKB), 22 December 1982.

References
RCAHMS. (1911b) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Third report and inventory of monuments and constructions in the county of Caithness. London. Page(s): 70, No. 257 illust RCAHMS Shelf Number: A.1.1.INV(3).R

Asset/Event Number	48
Asset/Event Name	Clais-Cairn, chambered cairn 550m SW of
Type of Asset/Event	Chambered cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM424; ND12NW 10
HER Number	MHG1074; MHG24192
Status	Scheduled Monument
Section:	N/A
Easting	313361
Northing	926807
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM424 The monument is a chambered cairn and consists of a low stone cairn with traces of a chamber in the centre. The cairn measures 17.5m N-S by 15m E-W and on the N side survives to a maximum height of 1.6m. The cairn is grass-grown, but where the cairn material can be observed it appears to consist of horizontal thin slabs. The entrance passageway to the chamber cannot be traced, but it probably ran from the SE side. A pair of large upright slabs facing in this direction have the appearance of portal stones. 5 or 6 other upright stones form part of the chamber, which may have been as much as 7m long. The area to be scheduled measures 40m SW-NE by 45m SE-NW, to include the chambered cairn and an area around in which traces of activities associated with the construction and use of the cairn will survive Statement of National Importance The monument is of national importance for its potential contribution to an understanding of Neolithic and Bronze Age burial and ritual practices. Much of the chamber and cairn survive at this site and information on the architecture of prehistoric tombs and burial deposits are preserved.

	References The site is RCAHMS number ND 12 NW 10.
Asset/Event Number	49
Asset/Event Name	Upper Borgue, standing stone 410m SSE of
Type of Asset/Event	Standing stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM502; ND12NW 13
HER Number	MHG1077
Status	Scheduled Monument
Section:	N/A
Easting	312636
Northing	926649
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM502 A high standing stone on the moor at Borgue. This is a slab rising 3.8m above the ground, pointed at its upper extremity, 1.7m broad at greatest bredth, 1m wide at base and 0.5m in thickness. It faces W by N and E by S. The area to be scheduled measures 20m in diameter to include the standing stone and an area around in which traces of activities associated with its erection will survive, as shown in red on the attached map.
Asset/Event Number	50
Asset/Event Name	Upper Borgue, broch
Type of Asset/Event	Broch
Date and/or Period	Iron Age
Listing No./NRHE Number	SM596; ND12NW 7
HER Number	MHG1095
Status	Scheduled Monument
Section:	N/A
Easting	312434
Northing	927089
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM596 Immediately behind the disused farm of Upper Borgue are the ruins of a large broch. The broch was built on a natural hillock and includes a large mound with an accompanying outer wall. The mound measures 25 by 26m and is about 4.5m high. There is a large depression on the summit of the mound. The entrance is to the ESE and has been partly opened up at some time in the past, although it is now filled with debris. A portion of the outer facing wall is exposed on the S side of the broch. The broch has been defended from the S round to the NW by a wall which survives as a broad bank. This wall is located about 6.4m from the base of the mound. There are traces of 2 possible associated buildings between the broch and

	the wall on the N of the site. The area to be scheduled measures 65m WSW-ENE by 50m SSE-NNW, to include the broch, wall and associated structures. The modern building to the SE of the broch is excluded from the scheduled area, which is shown in red on the attached map.
Asset/Event Number	51
Asset/Event Name	Cnoc Bad Asgaraidh, chambered cairn 570m E of, Langwell
Type of Asset/Event	Chambered cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM423; ND02SE 5
HER Number	MHG2426
Status	Scheduled Monument
Section:	N/A
Easting	309148
Northing	922244
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM423 The monument comprises a prehistoric chambered burial cairn, situated about 10m E of the Allt Bad Asgaraidh. It is already scheduled, but an inadequate area was included to protect all of the area of archaeological importance, hence this extension. The cairn is about 16m E-W by 12m N-S overall. Much of the cairn material has been removed, and the chamber is exposed at the E end of the cairn. It is sub-divided into two by upright stones. At the E, the cairn abuts a stone wall of much more recent date, and a turf and stone bank runs N-S across the centre of the cairn. Both probably incorporate stone removed from the cairn. The area now to be scheduled is circular, 40m in diameter, to include the cairn, portions of the wall and bank, and an area around in which evidence relating to construction and use may survive, as marked in red on the accompanying map extract.
Asset/Event Number	52
Asset/Event Name	Caen, long cairn 530m NW of,Helmsdale
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM432; ND01NW 5
HER Number	MHG10145
Status	Scheduled Monument
Section:	N/A
Easting	301249
Northing	918022
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://portal.historicenvironment.scot/designation/SM432 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/7467/caen-burn-north. On the W side of the Caen Burn are the remains of a long cairn. The cairn is much dilapidated, but no chamber is exposed. It lies ENE and WSW and measures about 100' in length, some 35' in breadth at the E end and 27' at the W. RCAHMS 1911, visited 1909; A S Henshall 1963; Visited by OS (W D J) 24 May 1960. This cairn is as generally described by the previous authorities. It consists of bare stones and rises to 1.0m near the E end, with part of this extremity destroyed by an old track and erosion. Several excavation pits have failed to reveal a chamber. Near the W end, to the S of centre is a rectangular flat-topped, heather covered mound with its axis parallel to that of the cairn. It measures 4.0m by 2.8m by 0.3m. Apparent wall coursing is visible on the E, N and S sides. It is a later feature possibly the result of piled excavation debris. Denuded field walls run from the SW and NW corners of the cairn; they are probably contemporary with the early modern ruins in the vicinity. Visited by OS (J B) 7 May 1976. References Henshall, A S. (1963a) The chambered tombs of Scotland, vol. 1. Edinburgh. Page(s): 311, SUT 14 RCAHMS Shelf Number: E.7.1.HEN RCAHMS. (1911a) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. Edinburgh. Page(s): 126, No. 358 RCAHMS Shelf Number: A.1.1.INV(2)
Asset/Event Number	53
Asset/Event Name	Bridge of Rhemullen, broch 450m NW of
Type of Asset/Event	Broch
Date and/or Period	Iron Age
Listing No./NRHE Number	SM574; ND13SE 12
HER Number	MHG1140
Status	Scheduled Monument
Section:	N/A
Easting	315086
Northing	931354
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM574 The monument consists of a broch with a closely associated settlement. The surviving remains of the broch consist of a turf- covered, level-topped mound, 19m in diameter and 1.3m high. In the NW edge of the mound there is a length of wall one course high which is part of the outer face of the broch wall. The broch is in the centre of a more extensive mound about 49m NW-SE by 41m NE-SW. There are faint traces of archaeological structures in this mound and it appears to represent the remains of a settlement associated with the broch. The area to be scheduled measures 80m NW-SE by 75m NE-SW, to include the broch and the associated settlement. The remains of a post medieval house lie just to the SW of the broch and this is included in the scheduled area in order to provide full protection for the broch and settlement. The area to be scheduled is marked in red on the attached map.
Asset/Event Number	54

Asset/Event Name	Bridge of Badnagie, chambered cairn 610m NNW of
Type of Asset/Event	Chambered cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM425; ND13SE 2
HER Number	MHG963
Status	Scheduled Monument
Section:	N/A
Easting	315680
Northing	932470
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM425 This monument consists of the remains of a Neolithic/Bronze Age chambered cairn. The remains include traces of the round cairn, which was probably originally about 21m in diameter, and 7 upright stones which indicate the position and plan of internal chambers and an entrance passageway. The entrance was from the SSE, the outer end probably being marked by a small slab 3m within the apparent cairn edge. The outer chamber was 1.5m long, the centre one about 2.7m by 2.1m; no visible remains survive of the inner chamber. The area to be scheduled measures 45m in diameter, to include the chambered cairn and an area around in which traces of activities associated with its construction and use will survive, as shown in red on the attached map.
Asset/Event Number	55
Asset/Event Name	Minera, standing stone 470m S of
Type of Asset/Event	Standing stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM457; ND13SE 22
HER Number	N/A
Status	Scheduled Monument
Section:	N/A
Easting	315537
Northing	934235
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM457 The monument is a tall standing stone on moorland. The stone is a slab 2.4m in height, 0.7m wide and 0.4m thick. It is pointed at the top and faces E-W. There are a number of loose stones which pack the standing stone at its base. The area to be scheduled measures 20m in diameter to include the standing stone and an area around in which traces of activities associated with its erection may survive, as shown in red on the attached map.
Asset/Event Number	56

Asset/Event Name	Minera, broch 90m SSE of
Type of Asset/Event	Broch
Date and/or Period	Iron Age
Listing No./NRHE Number	SM568; ND13SE 19
HER Number	MHG1146
Status	Scheduled Monument
Section:	N/A
Easting	315581
Northing	934611
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM568 The monument consists of a turf-covered stony mound approximately 24m in diameter and about 3m high. Near the foot of the mound to the NW a trench has revealed the outer face of the broch and a depression running to the centre of the mound from the W has lintel-like slabs at its outer end and probably marks the line of an entrance passage. The broch rises from a lower mound which contains the remains of an associated settlement. On the S side is a curving wall of stones which represents the enclosure which contained the outbuildings. The site is enclosed with an early modern wall. The area to be scheduled measures 70m E-W by 60m N-S, to include the broch, associated settlement and an area around in which traces of activities associated with the building and occupation of the settlement may survive, as shown in red on the attached map.
Asset/Event Number	57
Asset/Event Name	Carn Liath, cairn & chambered cairn 1200m WNW of Torboll
Type of Asset/Event	Cairns
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM1772; NH79NW 1; NH79NW 7
HER Number	Various
Status	Scheduled Monument
Section:	N/A
Easting	273878
Northing	899581
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM17724 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/14795/craig-a-bhlair [north cairn; Asset 57.1] and https://canmore.org.uk/site/14829/carn-liath [south cairn; Asset 57.2; NH79NW 7] North cairn (Asset 57.1; NH79NW 1) On the lowest slope of An Droighneach, at its extreme E end, lies an oval cairn, with its longest axis SE and NW, measuring 60' x 49'. Though much excavation has been done on it, neither cist not chamber is exposed.

RCAHMS 1911.

This cairn is formed by a large mound of bare stones 19.0m NW-SE by 16.0m transversely having a height of about 0.8m on its N side and a height of about 1.5m on its S side. Its top is mutilated but in the centre is a large slab set on edge which may indicate a chamber or its passage.
Visited by OS (W D J) 6 April 1964.

The dimensions of the cairn are as described by the previous OS field investigator. On the summit protruding through the cairn material are three, possibly four, upright slabs, the disposition of which suggest the back-slab and portal stone(s) of an Orkney-Cromarty type chamber. The entrance passage would have been from the SE arc; there is a hollow extending from this arc to the chamber, but no stones in situ are visible. The cairn is similar in all respects to Carn Liath (NH79NW 7 [Asset 57.2]), a chambered cairn visible some 500 m to the SE.
Revised at 1/10,000.
Visited by OS (N K B) 14 October 1980.

References
RCAHMS. (1911a) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. Edinburgh. Page(s): 48, No. 135 RCAHMS Shelf Number: A.1.1.INV(2)

South cairn (Asset 57.2; NH79NW 7)
Torboll (Carn Liath): A round chambered cairn. The steep-sided cairn is of bare stones and has a diameter of 60ft. The line of the outer half of the passage is seen as a hollow running through the cairn material. The chamber is complete except for the roof.
RCAHMS 1911; A S Henshall 1963.

In 1860 when collecting stones from this cairn a large stone cup with perforated handle was found in this cairn and is now deposited in the museum at Dunrobin Castle.
Name Book 1873.

A large chambered cairn, generally as described above. It measures about 19.0m in diameter and has an average height of about 2.3m. The passage and chamber are well-defined.
Visited by OS (W D J) 7 April 1964.

Carn Liath, a chambered cairn, as described and planned by Miss Henshall, now preserved in a clearing in a forestry plantation.

In Dunrobin Museum is a steatite bowl from Torboll (Accession no: X 56) which may be the 'large stone cup with perforated handle' noted in the Ordnance Survey Name Book (ONB, 1873), but the date of accession is not known. It measures 6.7ins in diameter and 3.4ins high. (see also NH79NE 37)
Revised at 1:10,000.
Visited by OS (N K B) 15 November 1980.

References
Henshall, A S. (1963a) The chambered tombs of Scotland, vol. 1. Edinburgh. Page(s): 332, SUT 58 plan RCAHMS Shelf Number: E.7.1.HEN
Ordnance Survey (Name Book. (1848-1878) Object Name Books of the Ordnance Survey (6 inch and 1/2500 scale). Page(s): Book No. 9, 118 RCAHMS Shelf Number: Ref
RCAHMS. (1911a) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. Edinburgh. Page(s): 47-8, No. 134 RCAHMS Shelf Number: A.1.1.INV(2)

Asset/Event Number 58

Asset/Event Name Brae Cottage, two hut circles 120m and 200m ESE of

Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM1830; NH79NW 19
HER Number	MHG11682
Status	Scheduled Monument
Section:	N/A
Easting	270406
Northing	898677
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM1830 The monument comprises the remains of two later prehistoric houses, usually referred to as hut circles. The monument was originally scheduled in 1935, but a mapping error led to the protected areas being located in the wrong position. The current proposal rectifies this. The hut circles lie at around 110m OD, in an area of gently sloping ground on the S side of Srath Carnaig, close to the junction of Abhainn an t-Sratha Charnaig and Allt Lochan Iain Bhuidhe. The northernmost hut circle measures approximately 18m in diameter with walls spread up to 3.5m and standing up to 1m high. The walls are thickest around the entrance in the ESE and traces of a bank or lynchet have been recorded running from the N side of the entrance. The second hut circle lies 80m to the SE and measures 15.5m in diameter over walls standing around 1m high and spread up to 3m wide. This hut circle also has an ESE-facing entrance, and possible elements of a field boundary have also been recorded next to the walls. The two areas to be scheduled are shown in red on the attached map extract. The first is circular, 40m in diameter centred on the NW hut circle; the second is circular, 35m in diameter, minus a chord on its SW side, centred on the SE hut circle.
Asset/Event Number	59
Asset/Event Name	Brae, broch, Strath Carnaig W of Mound Junction
Type of Asset/Event	Broch
Date and/or Period	Iron Age
Listing No./NRHE Number	SM1840; NH79NW 11
HER Number	MHG11624; MHG45709
Status	Scheduled Monument
Section:	N/A
Easting	270502
Northing	899016
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description

https://portal.historicenvironment.scot/designation/SM1840
No description available from HES. Description taken from Canmore

https://canmore.org.uk/site/14797/strath-carnaig.
The ruins of a broch with a circular enclosure abutting on its ENE side.
RCAHMS 1911, visited 1909.

A broch, surviving as a hollowed mound, c.2.0m high, on a rise above a flood-plain. The inner face, 1.2m maximum height, and the outer face, 0.4m high, are visible for most of the periphery, giving an internal diameter of c.8.3m within a wall c.4.3m thick in the ENE widening to c.5.7m in the WSW. According to OS (W D J) in 1963 there was an entrance, 1.5m wide in the WSW, and although this cannot be verified as it is obscured by tumble, the increased thickness of the wall and a hollow in the rim of the mound suggest that it was in this arc. There is a gap, 0.7m wide, in the inner face of the broch on the N side, probably the entrance to a mural gallery, the inner face of which is discernible for a short distance in the S. The central court is obscured by debris. Abutting on the E arc of the broch is a circular stone-walled enclosure of uncertain date and purpose. It measures 16.0m in diameter between the centres of a wall spread to c.2.5m wide, which is overlaid by a modern wall. No entrance is apparent. There are traces of a smaller enclosure on the NW side of the broch. They may both be associated with depopulated buildings in the vicinity.

Some 8.0m from the broch on the slopes to the S and W is a discontinuous line of stones, possible part of a revetment.
Visited by OS (W D J) 17 June 1963 and (N K B) 10 November 1969.

Activities
Field Visit (12 August 1909)
RCAHMS County Inventory: Sutherland
107. Broch, Brae.
On the left bank of the Allt Lochan Ianan Bhuidhe, ¼ m. above its junction with the Carnaig River, are the ruins of a broch. The situation is near the base of the hill, on the top of a bank whence the ground slopes sharply to the flat land by the river. The broch now occupies the upper end of a large walled enclosure. It is a complete ruin, and has been greatly pillaged. The interior diameter is 27'. The greatest height of walling visible in the interior is about 5', and externally the wall is reduced to the foundation. The position of the entrance is uncertain, but it appears to have been from the WSW. The thickness of the wall at that point is 19', while on the ENE. It is 14'. A large circular enclosure abuts on the broch towards the ENE.
OS 6-inch map, Sutherland, Sheet civ.
RCAHMS 1911, visited (AOC) 12th August 1909.

Publication Account (2007) Euan W Mackie Broch Corpus 2
NH79 1 BRAE ('Strath Carnaig') NH/7050 9903 (visited in 1989)
Probable broch in Dornoch, Sutherland, in the form of a crater-like mound of rubble on a rise above a flood plain; there is turf growing in the interior. The structure is badly ruined although both wall faces are visible throughout most of the circuit. These indicate an internal diameter of about 8.3m with the wall thickness varying from 4.3m to c. 5.7m.

An entrance was reported on the west-south-west in 1963 but later visitors, including the author, could not see it [1]. A gap 0.7m wide in the inner face on the north side was thought to be the entrance to an intramural gallery and by 1989 a fragment of this gallery had become exposed. A small section of scarcement can also be seen now.

Dimensions: internal diameter c. 8.3m, wall thickness 4.3m thick in the east-north-east, and c. 5.7m in the west-south-west. The overall diameter should therefore be about 18.3m (60.0 ft) along that diameter but is perhaps less elsewhere. In 1989 an accurate survey of the inner wall face was undertaken and showed it to have been set out close to a true circle with a radius of 4.05 +/-- 0.11m (a diameter of 8.10 m, or 26.56 ft) .
Sources: 1. NMRS site no. NH 79 NW 11: 2. RCAHMS 1911a, 38, no. 107.
E W MacKie 2007

	References MacKie, E W. (2007) The Roundhouses, Brochs and Wheelhouses of Atlantic Scotland c.700 BC-AD 500: architecture and material culture, the Northern and Southern Mainland and the Western Islands, BAR British series 444(II), 444(1), 2 V. Oxford. Page(s): 783 RCAHMS Shelf Number: E.9.1.MAC RCAHMS. (1911a) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. Edinburgh. Page(s): 38, No. 107 RCAHMS Shelf Number: A.1.1.INV(2)
Asset/Event Number	60
Asset/Event Name	Invershin Farm,standing stone 220m ENE of
Type of Asset/Event	Standing stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM1791; NH59NE 3
HER Number	MHG12888
Status	Scheduled Monument
Section:	N/A
Easting	257610
Northing	896741
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM1791 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/13012/invershin-farm. 'A quadrangular standing stone facing north-south and measuring 5'5" in height above ground, 2'6" in breadth at base, and 1'5" near the upper end, and 1'4" in thickness. Some 4' to the S of it a stone, 5' in length and 7" to 8" in thickness, hog-backed in form, protrudes to a height of about 1' from the ground.' RCAHMS 1911. The stone is as described as is the stone 4ft to the south of it. Visited by OS (E G C) 8 June 1963. These stones are as described by previous authorities. According to the farmer, (Mr Donald MacKay, Invershin Farm) large quantities of quartz are found in the vicinity of the stones whilst ploughing; much quartz was visible on the surface of the field which was under stubble at the time of investigation. Visited by OS (N K B) 20 December 1976. Activities Field Visit (5 October 1909) RCAHMS County Inventory: Sutherland 96. Standing-Stone, Invershin Mains. In a cultivated field at Invershin Mains about ½ m. S. of Inveran Inn, and 100 yards W. of the high road, is a standing-stone. It faces N. and S., is quadrangular in section, measuring 5' 5" in height above ground, 2' 6" in breadth at base, and 1' 5" near the upper end, and 1' 4" in thickness. Some 4' to the S. of it a stone, 5' in length and 7" to 8" in thickness, hog-backed in form, protrudes to a height of about 1' from the ground. OS 6-inch map, Sutherland, Sheet cvii. (unnoted). RCAHMS 1911, visited (AOC) 5th October 1909.

	References RCAHMS. (1911a) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. Edinburgh. Page(s): 35, No. 96 RCAHMS Shelf Number: A.1.1.INV(2
Asset/Event Number	61
Asset/Event Name	East Kinnauld, fort 1000m NE of Eiden
Type of Asset/Event	Fort
Date and/or Period	Iron Age
Listing No./NRHE Number	SM1861; NC70SW 17
HER Number	MHG11556
Status	Scheduled Monument
Section:	N/A
Easting	274216
Northing	901455
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM1861 The monument consists of a prehistoric or early historic fort on the summit of a commanding bluff. The fort consists of an inner enclosure with outworks. The inner enclosure measures about 37m from NE to SW by 29m from NW to SE and is defined by walls about 3m thick. Within this enclosure is a small circular enclosure about 9m in diameter. The fort is surrounded with outworks. The bottom of a low cliff facing the W side of the fort has been scarped to form a ditch and outer bank. A natural trench across the steep N approach to the fort has been scarped and heightened on the N side to give added defence. Extending from the SW side of the fort in a S direction down the slope to end on a rock outcrop is a stony bank some 33m in length with an entrance gap. Tenuous traces indicate that the bank continued round to the E and then N to terminate on the NE side of the fort or on the rocky slope close by it. On the E side an elongated mass of stones represent the remains of another bank The area to be scheduled measures 120m N-S by 105m E-W, to include the fort and outworks and an area around the fort in which traces of activities associated with the construction and occupation of the fort may survive, as shown in red on the attached map.
Asset/Event Number	62
Asset/Event Name	East Kinnauld School,broch NE of
Type of Asset/Event	Broch
Date and/or Period	Iron Age
Listing No./NRHE Number	SM1862; NC70SW 5
HER Number	MHG9446
Status	Scheduled Monument
Section:	N/A
Easting	274385
Northing	901596
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM1862 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/6005/east-kinnauld. The remains of a broch situated on a rocky peak and commanding an extensive view. It is much dilapidated, but the wall stands to a considerable height, beneath debris, all round. The interior diameter is 31ft and the wall thickness 17ft. The entrance, 2ft 9ins wide at the exterior and 3ft wide at the interior end, is in the west and has an orthodox guard-chamber in the south wall. Another chamber opens into the north wall, forward of the guard-chamber, its end being linked to the interior of the broch by a passage, at right angles to the chamber. The debris in the courtyard obscures the entrance to the staircase but the gallery is visible in the arc NW-NNE. The maximum height of wall visible above the debris on both the outside and the inside is 4ft. (RCAHMS 1911, visited 1909). The broch is as described and planned by the RCAHMS, except that the gallery is traceable round most of the circuit and short sections of the scarcement are visible on the inner wall-face of the south arc. Resurveyed at 1:2500. Visited by OS (R B) 28 February 1966. A broch 9.5m diameter within a wall 4.1m thick in the E arc increasing to 5.1m in the sides of the entrance passage, door-checked, from the west. There are traces of a mural gallery in the north half only, and no sign of a scarcement. Other features are as described in the RCAHMS report. Revised at 1:10,000. Visited by OS (J M) 18 March 1981. Activities Field Visit (6 June 1995) RCAHMS Afforestable Land Survey, Rogart This broch is situated on a rocky hill about 200m NE of East Kinnauld fort (NC70SW 17). The court measures 9.4m in diameter within a rubble wall, 5.2m thick and up to 3m high. The entrance-passage lies on the W, the internal opening of which is surmounted by a triangular lintel, and guard-chambers open off either side of the passage. An intra-mural gallery is visible within the N arc of the wall. (ROG95 541) Visited by RCAHMS (PJD) 6 June 1995 Publication Account (2007) Euan W Mackie Broch Corpus 2 NC70 1 EAST KINNAULD 1 NC/7438 0159 This broch in Rogart, Sutherland, stands in a very remote position, high among the crags on the north side of and overlooking Strath Fleet – a fertile valley with many modern farms (visited 11/7/63 and 9/7/85). The structure, now a vast heap of stones, is built of irregular blocks of igneous or metamorphic rock and is full of its own debris. It stands about 122m (400ft) above the sea. The entrance is on the west and fairly clear of debris at the outer end. There is an oval guard cell on its right, choked with debris but apparently 3.05m (10ft) deep; the lintel of the doorway to this cell is visible, immediately behind a built door-check at a distance of 2.74m (9ft) from the exterior. The passage is 5.19m (17ft) long and 84cm (2ft 9in) wide at the outer end. Three lintels are still in position over the outer part of the passage, starting at the door-checks. On the left of the passage is the curved wall of another mural cell with a doorway to the

interior of the broch, capped with a small triangular lintel [2, fig. 65] It is not clear exactly what this is, but it is unlikely to be a second guard cell; such rarely communicate with the interior (but see Clachtoll – NC02 1). However the Commission also saw what seemed to be the edge of a doorway leading from this cell to the entrance passage, but this feature is now obscured. Thus the broch may have two guard cells.

Traces of a mural gallery are visible in places all round the wallhead. At 7-8 o'clock it is higher than the entrance lintels, so it should be an upper gallery at this point. Yet it continues round to 12 o'clock where it looks as if it is at ground level since the natural rock surface outside the broch is much higher at this point. However at 8 o'clock there is a void from the gallery to the interior, the sill of which is exposed; thus the gallery here ought to be an upper one. The author saw no trace of a scarcement on the exposed inner wallface in 1963, but one was reported in 1966 and denied in 1981 [1]. The inner face is well built in spite of the coarse nature of the stone.

Dimensions (author's measurements): 6-12 o'clock, overall diameter 18.61m (61ft); internal diameter 9.61m (31ft31 6in). The wall is therefore c. 4.42m thick and the wall proportion would then be about 48.4% (the entrance passage was found to be only 4.88m (16ft) long, not 5.19m (17ft)). More recently the wall was stated to vary in thickness from 4.1m on the east to 5.1min the sides of the entrance on the west [1]. This last measurement conflicts with the author's.
Sources: 1 NMRS site no. NC 70 SW 5: 2. RCAHMS 1911a, 164-5, no. 477.
E W MacKie 2007.

References
MacKie, E W. (2007) The Roundhouses, Brochs and Wheelhouses of Atlantic Scotland c.700 BC-AD 500: architecture and material culture, the Northern and Southern Mainland and the Western Islands, BAR British series 444(II), 444(1), 2 V. Oxford. Page(s): 632 RCAHMS Shelf Number: E.9.1.MAC
RCAHMS. (1911a) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. Edinburgh. Page(s): 164-5, No. 477 plan RCAHMS Shelf Number: A.1.1.INV(2)
Romankiewicz, T. (2011) The Complex Roundhouses of the Scottish Iron Age: An architectural analysis of complex Atlantic roundhouses (brochs and galleried duns) with reference to wheelhouses and timber roundhouses, BAR British series 550 (I), 550 (II), 2 V. Oxford. Page(s): 213-215 RCAHMS Shelf Number: E.9.1.ROM

Asset/Event Number	63
Asset/Event Name	Carrol, broch 600m SSW of,Loch Brora
Type of Asset/Event	Broch
Date and/or Period	Iron Age
Listing No./NRHE Number	SM1846; NC80NW 1
HER Number	MHG10822; MHG10833; MHG10834
Status	Scheduled Monument
Section:	N/A
Easting	284665
Northing	906460
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description

https://portal.historicenvironment.scot/designation/SM1846
No description available from HES. Description taken from Canmore https://canmore.org.uk/site/6493/carrol.

The Broch of Carrol, measuring between 30ft 6ins and 31ft internal diameter and surviving to an average height of 10ft, has been excavated. The entrance in the ESE with two door checks and a guard chamber is still roofed, at this point the wall is 14ft thick. In the SW arc is an entrance to a ground floor chamber and to steps rising to first floor level. A first floor gallery is discernible in the NE arc.

The broch is surrounded by an outer wall 7 to 8 ft thick, with a ditch or trench outside it about 20ft wide. The entrance through this outer defence is in line with that of the broch, and a walled passage 5ft wide connects the two.

Finds from the excavation, now in Dunrobin Museum, include a steatite cup with side handle, a rude shale ring and a concave oval plate of ox horn with four rivet holes at one end and two iron rivets in situ.

J M Joass 1873; RCAHMS 1911, visited 1909.

A broch generally as described by RCAHMS (1911), the outer face being obscured by debris from the cleared interior. The existence of a walled passage between the entrances of the broch and outer defences is uncertain due to debris. The occasional earthfast stone protruding through the turf between broch and outer wall indicates secondary structures. Revised at 1/10,000.
Visited by OS (W D J) 24 April 1964 and (N K B) 3 November 1975.

The Accession no's of the finds from the broch, in Dunrobin Museum, are: 1868.51-4; sherd 1890.1; pebble tool 1891.3.
Information contained in TS of Catalogue of Dunrobin Museum by A S Henshall.

Field Visit (25 September 1909) RCAHMS County Inventory: Sutherland
27. Broch, Carrol. On the W. side of Loch Brora, about ¾ m. S. of Carrol Rock and 4½ m. NW. of Brora, at an elevation of about 200' above the level of the loch, is situated the broch of Carrol. The entrance is from the ESE. through a passage 14' in length, 2' 9" wide at the outer end, and 3' 9" at the inner. The passage has been protected by two doors, the checks of which occur at 3' 4" and 9' 1" from the outside. Within the outer checks the passage is 3' 10" wide. Its greatest height is 5' 8", and the roofing remains almost complete, only two slabs being a wanting. Behind the inner jambs are bar holes at 2' and 2' 4" respectively from present ground level. That on the W. side passes through the wall into the chamber to the S. of the stair. At a distance of 2' behind the outer checks, or 5' 11" from the outside, on the right of the passage, is the entrance to a guard-chamber 2' wide, 3' 6" long, and 3' 11" high. The chamber closely resembles that at Kintradwell. It is oval, 8' 6" long by 6' 4" wide, and 9' 6" high. The roof is entire, except for an aperture in the apex about 2' square. The diameter of the interior of the broch is from 30' 6" to 31'. At 19' distant from the W. side of the doorway on the interior is the entrance to a chamber and stair 3' 6" above the present floor level, through a passage 6' long, 2' 10" wide at the entrance, and 3' 7" in the interior. The stair rises to the right for 11'. Thirteen steps are visible, varying from 2' 6" to 3' 3" in length, 7" to 8" across the tread, and 4" Lo 5" in height. To the left a narrow passage 18' long and about 2’ 6” wide leads to a chamber some 7' 6" long and 4' wide at the back, which is straight. Only a small portion of the roof remains at the back of the chamber, which is 9' high above present floor level. The steps which have been described as leading to this chamber are now obscured with debris. The breadth of wall across the top of the stair is 14' 8". The greatest height of wall above the present floor level in the interior is 13', and the average height about 10'. Some 9' above floor level is a scarcement about 1' 6" wide. The greatest height of wall visible on the exterior is 5'. From a point 7' distant from the side of the entrance passage towards the E. a portion of a gallery remains for 25', with a width of from l' 8" to 2'. The width of the opening on to the interior above the entrance passage is about 2' 11".

Outside the broch a well-built wall from 7' to 8' thick surrounds it at a distance of about 23'

on the N., 28' on the NW., and 13' on the S., having a ditch or trench outside it about 20' in width. The approach through these defences is in line with the entrance to the broch. The main wall, where it passes through it, is some 38' distant; and an outer wall, 7' thick, which here takes the place of the counterscarp of the ditch, is about 52' distant. From the main or inner wall, a passage 5' wide, walled on either side, leads to the broch. Some 53' to the S. of the entrance a small passage leads through the wall on the inner side of the ditch under a lintel, 3' wide, and, from present level, 2' high. The moor to the W. is marshy, and, in consequence, the ditch appears to have been discontinued in that direction. The setting of flagstones inside the broch on the left of the entrance, measuring 7' by 3', is in rather a ruinous state, and the flags are getting displaced. Lying in the interior is a round stone, with a circular depression on the top, in which the pivot of a door has evidently worked.

The broch has been excavated, and the relics found are preserved in the Museum at Dunrobin. These included a steatite cup, with a side handle; a rude shale ring; and a concave oval plate of ox horn, like the bowl of a large spoon, with four rivet holes at one end and two iron rivets in situ (fig. 2 and Pl. II.).

Some 40 yards to the N. of the broch is an ill-defined enclosure measuring about 66' in length by 33' at the W. end and considerably less at the E.

The shallow weem-like structure noted in Arch. Scot., 8' in diameter at top, and with well-built wall, is visible about 80 yards to the SE. of the entrance to the broch. The walling around it is now almost obscured by grass. The trench running NE. from it is still apparent, and is also visible running towards the bank of the Allt Coire Aghaisgeig on the SW.
See Arch. Scot., v. pt. i. p. 107; (relics illus.).

OS 6-inch map: Sutherland Sheet xcvii.
RCAHMS 1911, visited (AOC) 25th September 1909.

Publication Account (2007) Euan W Mackie Broch Corpus 2
NC80 3 CARROL ('Craig Carril') NC/8462 0646

This solid-based broch in Clyne, Sutherland, is situated on the west side of Strath Brora overlooking the Loch Brora and about 61m (200ft) above it (visited 11/7/63, 1971 and 10/7/85: in 2002 it was behind a deer fence).

Description
The site, a huge heap of stones when seen from a distance, stands on a broad, level platform or plateau projecting from the shallowly ascending side of the valley. It is invisible from the water's edge. An outer wall, with traces of a ditch beyond, surrounds the broch and there are signs of a gateway in this in line with the broch entrance. This broch was cleared out by order of the Duke of Sutherland probably in about 1870 and "during the visit at Dunrobin of a distinguished lady associate of the Society of Antiquaries of Scotland" [2, 107] (This might have been Christine MacLaglan of Stirling (see Scott Archaeol Journ 27.1 (2005), 102-4)). A short description of the results of the work was published by the local minister, the Rev. J M Joass [2]. Most of the outer face is still buried by the debris which was thrown out of the interior at that time. The finds are in the museum in the grounds of Dunrobin Castle [3].

Thick bushes were growing in the interior of the broch in 1971 and were cut down by the author in that year for a theodolite and tape survey. They have since grown up again, sheltered by the massive wall which still stands 3.6m (12ft) high most of the way round. The entrance passage is on the east-south-east and is 4.27m (14ft) long, 84cm (2ft 9in) wide at the outer end and 1.14m (3ft 9in) at the inner [3, fig. 2]. Traces of the lower parts of the sides of the chamber over the entrance, opening only to the interior, are clearly visible above the lintels and confirm that the structure is a hollow-walled broch. The passage does not seem to have been any better preserved at the beginning of the 20th century.

There are two door-frames at distances of 1.0m (3ft 4in) and 2.77m (9ft 1in) from the outside, and both sets of checks are faced with massive stone slabs set at right angles to the walls. The front checks are formed by the passage widening to 1.17m (3ft 10in) behind them

but the rear ones are formed of slabs projecting from straight walls. All except two of the passage lintels are in situ and their height above the floor (which seems to be the original one, though strewn with rubble) is 1.73m (5ft 8in). A bar-hole and socket are behind the inner checks at heights of 60cm (2ft) and 71cm (2ft 4in) above the passage floor respectively.

A guard cell opens off the right of the passage 61cm (2ft) behind the outer checks; its doorway is 1.20m (3ft 11in) high and contrasts with the height of the almost complete corbelled cell behind, which is 2.90m (9.5ft).

The doorway to the mural stair is at 9 o'clock and its sill is at least 91cm (3ft) above the floor. The stair rises to the right and in 1909 13 steps were preserved up to a height of 3.3m (11ft) to the wallhead; the same number can be seen now and there could be more at the base of the flight hidden by rubble. The uppermost three steps of the flight are rising at a more inward angle than the rest, as if there was a shallow corner in the stairway here.

Three steps lead down to the left of the doorway into the stair-foot guard cell which is in fact a long stretch of mural gallery running for 5.80m (19ft), almost as far as the entrance passage and not far above ground level. This cell or gallery is now almost completely unroofed although it was apparently found with half the roof – described as “corbelled” [2] – intact. Joass describes how the bar-hole in the entrance passage mentioned earlier runs 91cm (3ft) back from the entrance passage to the end of this long cell, but the author omitted to look for this feature during his last visit; it does not appear on the relevant photograph (though the inner quarter of the end is invisible on this).

Because of the length of the stair-foot cell the broch might be classified as a hybrid form between the ground-galleried and solid-based types; however the remainder of the wall base is completely solid and in every way a standard northern structure.

A scarcement of the ledge type is preserved on the interior wallface from about 1 to 5 o'clock and 2.75m (9ft) above the floor; its width is about 40-46cm (15-18in). Part of the upper mural gallery is visible at about 5 o'clock, going anti-clockwise for some distance and on top of the massive solid wall base; it is about 46cm (18in) wide and its present base is at about scarcement level. The lintels for the stair-foot gallery would have been at about the same height. The upper gallery also runs over the guard cell, making use of the capstone of the latter in its floor, and it must be at least 91cm (3ft) higher than the entrance lintels here. The sides of the chamber over the entrance show no trace of the gallery, which presumably was blocked by it.

The outer wall is 2.14 - 2.44m (7 - 8ft) thick and its distance from the broch varies from 3.97 - 8.54m (13 - 28ft) ; there is a ditch 6.10m (20ft) wide beyond. The outer entrance is in line with that of the broch and a walled passage 1.53m (5ft) wide connects the two features; it is protected by a forework wall about 3.05m (10ft) further out, instead of by the ditch. There were various presumably secondary flagged structures inside the broch which were considerably dilapidated in 1909.

The excavations
The description of the excavations [2] is brief and simply refers to 91cm (3ft) of “unctuous earth” found lying on the floor of the central court, presumably covered by rubble. One extended human skeleton was found on the floor (presumably on top of the earth mentioned) to the right of the entrance, and another on the landing at the foot of the intra-mural stair; a copper finger-ring was found with the former, and both were presumably burials put in place shortly after the broch was abandoned.

Few traces of obvious secondary occupation were reported (there was no secondary wall around the central court, for example), though one might assume that the human burials were such. One might also suppose – judging from comparable deposits in more skilfully explored brochs – that the “unctuous earth” itself belonged to a later stage of the occupation of the tower but because of the primitive methods of exploration used decisive evidence is lacking.

Structural analysis

That this is a definite hollow-walled broch is shown by the remains of the chamber over the entrance passage and by those of the upper intra-mural gallery in the north-east arc. No further details are preserved so one cannot know, for example, if the stairway led up to a landing with a door-sized opening leading from it inwards to the scarcement.

Finds [2, 108 - 9] (in Dunrobin Castle Museum)
The internal deposits of the broch consisted of 91cm (3ft) of "unctuous earth" and ashes lying directly on the floor and surmounted by stony debris.
Evidence of iron consisted of 2 fragments of slag (outside the broch) and the 2 rivets mentioned below.
Bronze objects included 1 finger ring (with the human skeleton mentioned above, which was either put down through the "unctuous earth" or laid on top of it).
Objects of bone and antler included 1 horn oval plate with 4 rivet holes and with 2 iron rivets still in position, and 1 deer's horn handle with a pin-hole.
Stone objects included a few hammerstones, 2 mortars, some quern frag-ments (presumably rotary), a sandstone disc (diam. 17.5cm or 7in), 1 steatite handled cup (Illus. 7.383) and 1 crude jet ring 6.5cm (2.5in) in diameter.
Other items: there were also 1 amber bead, broken, 2 flint flakes and 1 chert flake.
Pottery: in the museum are 5 small, plain wall sherds (ARC 501B).

Dimensions
Internal diameter 9.30 - 9.46m (30.5 - 31ft); external diameter not measurable but should be about 18.0m (59ft) if the whole wall is the same thickness as the length of the entrance, that is 4.42m (14.5ft). In this case the wall proportion would be about 51.6%. In 1971 a fresh survey of the central court showed that the plan of this was almost exactly circular, and that the radius of the circle that fits it best is 4.69 +/- 0.06m. The internal diameter is thus close to 9.396m (30.81ft) .
Sources: 1. NMRS site no. NC 80 NW 1: 2. Joass 1890, 107 - 9: 3. RCAHMS 1911a, 9 - 11, no. 27, fig. 2 and pl. II: 4. Close-Brooks 1995, 134.
E W MacKie 2007.

References
Close-Brooks, J. (1995a) The Highlands, Exploring Scotland's Heritage series, ed. by Anna Ritchie. 2nd. Edinburgh. Page(s): 134 RCAHMS Shelf Number: A.1.4.HER
Joass, J M. (1873) 'The brochs or "Pictish Towers" of Cinn-Trolla, Carn-Liath, and Craig-Carril, in Sutherland, with notes on other northern brochs', Archaeol Scot, vol. 5, 1, 1873. Page(s): 107
MacKie, E W. (2007) The Roundhouses, Brochs and Wheelhouses of Atlantic Scotland c.700 BC-AD 500: architecture and material culture, the Northern and Southern Mainland and the Western Islands, BAR British series 444(II), 444(1), 2 V. Oxford. Page(s): 643-645 RCAHMS Shelf Number: E.9.1.MAC
RCAHMS. (1911a) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. Edinburgh. Page(s): 9-10, No. 27 plan, illust RCAHMS Shelf Number: A.1.1.INV(2)
Romankiewicz, T. (2011) The Complex Roundhouses of the Scottish Iron Age: An architectural analysis of complex Atlantic roundhouses (brochs and galleried duns) with reference to wheelhouses and timber roundhouses, BAR British series 550 (I), 550 (II), 2 V. Oxford. Page(s): 208-209 RCAHMS Shelf Number: E.9.1.ROM

Asset/Event Number	64
Asset/Event Name	Eldrable, broch SW of
Type of Asset/Event	Broch
Date and/or Period	Iron Age
Listing No./NRHE Number	SM1863; NC91NE 20
HER Number	MHG9863
Status	Scheduled Monument
Section:	N/A

Easting	298332
Northing	918169
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM1863 The monument comprises the remains of a broch, an Iron Age fortified dwelling. It was scheduled in 1938, but the original documentation is defective and the area covered was much too small to include all of the area of archaeological importance, hence this extension. The most prominent feature of this monument is the remains of the broch itself, a mass of drystone masonry standing well over 1.5m tall. Over half of the outer wall face is visible, as well as stretches of the inner wall face, suggesting an inner diameter of 7.5m and a wall thickness of from 3.5 to 4.5m. The entrance has been on the ESE side. Outside the broch there are traces of external buildings and a possible rampart and ditch, particularly on the N and W sides, although these are obscured by vegetation. A later wall runs approximately E-W across the site, incorporating some of the broch walling into itself, and a track crosses the area to the W of the broch, running over some of the possible outer works. The area now to be scheduled is circular, 50m in diameter, centred approximately on the outer wallface of the broch in its NW sector. This area includes the broch itself and the outer works to N and W as well as an area around these in which further evidence relating to the construction and use of the broch is likely to survive. The area is marked in red on the accompanying map extract.
Asset/Event Number	65
Asset/Event Name	Kilphedir, broch 540m ENE of,Helmsdale
Type of Asset/Event	Broch
Date and/or Period	Iron Age
Listing No./NRHE Number	SM1870; NC91NE 27
HER Number	MHG9856
Status	Scheduled Monument
Section:	N/A
Easting	299439
Northing	918907
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM1870 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/7000/kilphedir. Situated on the summit of a hillock is a broch measuring 33' NE-SW by 32' transversely, within a wall 7' average height and 12'6" thick, widening to 15'6" at the entrance which is 3' wide at the exterior, and 4'10" at the interior It is checked for a door, but no entrance to a guard chamber is visible. Opposite the entrance there is a passage giving access to the stairway and a ground floor mural chamber.

The commanding position of the broch is strengthened by outworks, probably the most impressive in Sutherland. The base of the hillock is encircled by a ditch 9' deep below an outer rampart 14' broad. A short outer ditch runs parallel with the inner one for about 20' at the N end. A small oval enclosure is contained in the outer rampart to the W side of the broch. The course of the ditch is broken on the N side by the approach which passes between its open ends.

A quartzite pebble from the broch is in Dunrobin Museum Acc No: 1869.5 (Information from TS of Catalogue of Dunrobin Museum, by A S Henshall).
J M Joass 1865; J Nicol 1910; RCAHMS 1911, visited 1909; R W Feachem 1963; A Young 1964; E W MacKie 1975.

This broch has remained unaltered since the visit by the RCAHMS.
Re-surveyed at 1:10560
Visited by OS (W D J) 20 May 1960 and (N K B) 6 October 1976.

Activities
Publication Account (1995) RCAHMS: Exploring Scotland's Heritage - The Highlands, 1995

The broch is on the hill east of the burn but cannot be seen from the road by the bridge. A sheep track just east of the bridge leads up the hill, bearing slightly right, and passes through a deserted crofting settlement under the line of the electricity poles; there are the foundations of a longhouse, and some smaller buildings and a kiln barn. From the first skyline the broch is visible on the hillside above, some 15 or 20 minutes walk from the road.

The broch is set on a prominent knoll with good views up and down the valley. It is ruinous, and appears as a great mass of rubble spilling down the hill, but it has a particularly impressive set of outer defences, now all covered with heather so that the stone walls look like banks. There are terraces east and west of the broch defended by an inner rampart, a deep ditch and a stout outer rampart. At the west end, the entrance is protected by an extra short stretch of rampart.

Just below the broch is a good path along the side of the hill; follow it west to find three hut circles on the edge of the ravine above the burn (NC 991190). One hut circle has much thicker walls than the other two, and this one has a souterrain leading out of it beneath its wall. The far end has been broken into, so light comes in, but it may be full of water and gumboots are needed. A muddy hole, originally provided with steps, drops down into the narrow souterrain passage; the latter has drystone walls and a lintelled roof and is about 9.50m long.

There are more hut circles up the burn and on the west bank. Some of the latter were excavated in the 1960s, and shown to have interior posts that supported their thatched roofs, whi le radiocarbon dates from two huts suggest they were occupied in the last few centuries BC. A number of clearance cairns round these and other hut circles are probably of the same date and show that some patches of ground were cultivated. Many other hut circles can be seen on the hill slopes along the north side of the Strath of Kildonan, some indicated on the OS map, and at least six other souterrains have been found, three still attached to hut circles. Part of one at Suisgill (NC 897250) is close to the east side of the road; only the far end survives, with lintelled roof and a curved end-wall, in which is a small built-in recess or cupboard .

Information from ‘Exploring Scotland’s Heritage: The Highlands’, (1995).

Publication Account (2007) Euan W Mackie Broch Corpus 2
NC91 7 KILPHEDIR ('Kilphedir Tower') NC/9943 1891
This probable broch in Kildonan stands high up on the moor overlooking the valley of the river Helmsdale, with a clear view up and down the strath (visited 12/7/63). It stands on a natural knoll which has been entirely surrounded at its base by a formidable ditch 2.75m (9ft) deep within an earthen rampart 4.27m (14ft) wide. There is a short outer ditch, parallel with the inner and about 6.10m (20ft) long, at the north end, facing the river where the approach is over flat ground. On the south-west a causeway crosses the main surrounding

ditch and Swanson describes a ramp on the north-west which she thinks was the main approach to the broch[8].

The broch itself is almost completely hidden under a vast pile of stones which look as though they have never been disturbed. Several features are visible however. The entrance is on the north-west (facing the ramp) with three lintels still in position: it is 4.73m (15.5ft) long, 92cm (3ft) wide at the outer end, 1.48m (4ft 10in) at the inner and with 15cm (6in)-deep door-checks at a distance 3.05m (10ft) in; these are presumably built rebates but were not noted by the author in 1963, though Swanson saw the one on the right [8, 780]. No signs of a guard cell are visible.

At 12 o'clock can be seen the doorway from the interior to an intra-mural gallery which probably contains the stair: this was in fact seen here, together with a stair-foot guard cell, in 1909, but there were no signs of the steps in 1963 even though the gallery – 76-92cm (2.5 - 3ft) wide – is exposed down to 61cm (2ft) below the present wallhead. A short stretch of the inner face of a mural gallery is visible at 10 o'clock but no signs of a scarcement ledge are apparent on the interior wallface. Three lintels are in position over the gallery in the arc from 2-5 o'clock. A quartzite pebble from the broch was in the collection of the Dunrobin Castle Museum [1].

This is another site which seems to have been somewhat better preserved in the recent past. Stuart visited it in about 1866 and stated that "The present example has walls of about fifteen feet in thickness, containing chambers which enter from the central open space." He also noted that "A flight of stairs, formed of flags in the centre of the wall, is yet entire." [7, 290]. The drawing from the early 1860s shows this better preservation well.

Dimensions: the broch's internal diameter is 10.07m (33ft) from north-east to south-west (on the 6-12 o'clock axis) and 9.76m (32ft) transversely. Swanson gives it as 9.6m north-south [8]. The wall thickness at the entrance is 4.27m (14ft) (4.73m, or 15.5ft, according to the Commission) and the total diameter here is 18.15m (59.5ft): the wall proportion would thus be 45.5%.
Sources: 1. NMRS site no. NC 91 NE 27: 2. Joass 1864, 246: 3. RCAHMS 1911a, 104-05, no. 307, fig. 35 and pl. III: 4. Young 1962, 186: 5. Feachem 1963, 173: 6. MacKie 1975, 218: 7. Stuart 1868: 8. Swanson (ms) 1985, 779-82: 9. Close-Brooks 1995, 152-3, no. 84: 10. Armit 2003, 36, 80: 11. Dockrill 2002, 160.
E W MacKie 2007

Note (7 February 2015 - 18 October 2016) Atlas of Hillforts of Britain and Ireland
The Kilphedir broch is situated in a commanding position overlooking the Strath of Kildonan, occupying the crest of a hillock high up on the northern flank. Around the foot of the hillock, however, there is also a substantial earthwork comprising a ditch up to 6m in breadth, with a counterscarp rampart standing up to 2.5m above its bottom. In places, particularly around the eastern half of the circuit, there are also traces of a bank on the inner lip of the ditch, but this detaches itself from this line on the SE and appears to be forming a smaller enclosure on the crest of the hillock. A gap in the ditch on the NW marks the position of the entrance, and is flanked on the E by a short length of an outer ditch with a counterscarp bank. The area enclosed measures about 60m from NNW to SSE by up to 32m transversely (0.16ha), though aerial photographs suggest that there may also be a rather smaller enclosure occupying the crest of the hillock. The interior around the broch is otherwise featureless. The broch itself, which is largely choked with rubble, measures about 10m in diameter within a wall about 4.3m in thickness, its features including a gallery on the S and a checked entrance passage on the NW.
Information from An Atlas of Hillforts of Great Britain and Ireland – 18 October 2016. Atlas of Hillforts SC2797

References
Armit, I. (1998i) Scotland's hidden history. Stroud, Gloucestershire. Page(s): 107-9 fig 63
RCAHMS Shelf Number: E.2.1.ARM
Armit, I. (2003) Towers in the North: the Brochs of Scotland. London. Page(s): 36, 80
RCAHMS Shelf Number: E.9.1.ARM

Close-Brooks, J. (1986a) Exploring Scotland's heritage: the Highlands, Exploring Scotland's heritage series. Edinburgh. Page(s): 152-3, No. 84 RCAHMS Shelf Number: A.1.4.HER
Close-Brooks, J. (1995a) The Highlands, Exploring Scotland's Heritage series, ed. by Anna Ritchie. 2nd. Edinburgh. Page(s): 149-50 No. 93 RCAHMS Shelf Number: A.1.4.HER
Davidson, Cowley, Barneveld and Ferguson, J L, D C, J and L M. (1999) 'Archaeological mapping in the north of Scotland', in Frodsham, P, Topping, P and Cowley, D, 'We were always chasing time.' Papers presented to Keith Blood, Northern Archaeol (Spec Edition, vol. 17/18, 1999. Page(s): 18 RCAHMS Shelf Number: E.2.1.BLO
Dockrill, S. (2002) 'Brochs, economy and power', in Ballin Smith, B and Banks, I, In the shadow of the brochs: the Iron Age in Scotland, A celebration of the work of Dr. Euan Mackie on the Iron Age of Scotland. Stroud. Page(s): 160
Feachem, R. (1963b) A guide to prehistoric Scotland. 1st. London. Page(s): 173 RCAHMS Shelf Number: E.2.FEA
Joass, J M. (1865a) 'Two days' diggings in Sutherlandshire', Proc Soc Antiq Scot, vol. 5, 1862-4. Page(s): 246
MacKie, E W. (1975a) Scotland: an archaeological guide: from the earliest times to the twelfth century. London. Page(s): 218 RCAHMS Shelf Number: E.2.MAC
MacKie, E W. (2007) The Roundhouses, Brochs and Wheelhouses of Atlantic Scotland c.700 BC-AD 500: architecture and material culture, the Northern and Southern Mainland and the Western Islands, BAR British series 444(II), 444(1), 2 V. Oxford. Page(s): 651-652 RCAHMS Shelf Number: E.9.1.MAC
Nicol, J. (1910) Orkney and Shetland miscellany. Page(s): 107-10
RCAHMS. (1911a) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. Edinburgh. Page(s): 104-5 No. 307 RCAHMS Shelf Number: A.1.1.INV(2)
Romankiewicz, T. (2011) The Complex Roundhouses of the Scottish Iron Age: An architectural analysis of complex Atlantic roundhouses (brochs and galleried duns) with reference to wheelhouses and timber roundhouses, BAR British series 550 (I), 550 (II), 2 V. Oxford. Page(s): 219-221 RCAHMS Shelf Number: E.9.1.ROM
Young, A. (1964) 'Brochs and duns', Proc Soc Antiq Scot, vol. 95, 1961-2. Page(s): 186

Asset/Event Number	66
Asset/Event Name	Kilphedir, hut circle 800m NNE of,Helmsdale
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM1871; NC91NE 3
HER Number	MHG9853
Status	Scheduled Monument
Section:	N/A
Easting	299211
Northing	919411
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM1871 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/7003/allt-cille-pheadair. This is the same description for Asset 25/SM2810. Asset 66 is the hut circle B described therein.

Asset/Event Number	67
Asset/Event Name	Kilphedir, hut circle and souterrain 450m NNE of

Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM1872; NC91NE 28
HER Number	MHG9855
Status	Scheduled Monument
Section:	N/A
Easting	299133
Northing	919034
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM1872 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/7001/allt-cille-pheadair. This is the same description for Asset 23/SM2808. Asset 67 is the hut circle A and souterrain described below.

Asset/Event Number	68
Asset/Event Name	Salscraggie Lodge,souterrain 40m SW of
Type of Asset/Event	Souterrain
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM1884; NC91NE 26
HER Number	MHG9857
Status	Scheduled Monument
Section:	N/A
Easting	299879
Northing	918279
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM1884 The monument consists of a souterrain, filled in many years ago, but with masonry surviving underground. The souterrain was discovered when an earthen mound, about 7.5m in diameter and 2m high, was being cleared away. This mound may have been the remains of a hut circle. The souterrain was entered by a flight of 6 steps leading into a covered passage. The passage was 6.7m long, about 1m wide and 1.4m high. The sides were built of boulders and the roof flagged. Within the souterrain were found a human arm bone, and parts of 3 querns. A slight mound now marks the site of the souterrain and possible hut circle. The area to be scheduled measures 40m in diameter, to include the souterrain, hut circle and an area around in which traces of activities associated with the construction and use of the souterrain may survive, as shown in red on the attached map. https://canmore.org.uk/site/6999/salscraggie-lodge In the centre of the lawn in front of Salscaggie Lodge is a souterrain, the entrance to which was discovered when an earthen mound, some 25' in diameter and 6' to 8' high, possibly the r remains of a hut circle, was being cleared away. It is entered by a flight of six steps, 2' wide, leading to a covered passage 3' wide and 4' to 5' high, its extreme length being 22'.

	The sides are built of boulders and the roof is flagged. Within the gallery, when it was cleared, were found a "human arm bone", a rotary quern, a portion of another, and a saddle quern, all of which with the exception of the first item, are lying around the entrance. A B Scott 1899; RCAHMS 1911, visited 1909. This souterrain was filled in many years ago, and there are now no surface indications. Visited by OS (W D J) 20 May 1960 and (N K B) 19 November 1976 References RCAHMS. (1911a) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. Edinburgh. Page(s): 112, No. 324 fig. 34 RCAHMS Shelf Number: A.1.1.INV(2) Scott, A B. (1899) 'The earth-houses of Kildonan, Sutherland', The Scot Antiq Northern Notes Queries, vol. 13, 52, 1899, April. Page(s): 55-60
Asset/Event Number	69
Asset/Event Name	Clach Mhic Mhios,standing stone,Glen Loth 4000m N of Lothbeg Bridge
Type of Asset/Event	Standing stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM1778; NC91NW 11
HER Number	MHG9980
Status	Scheduled Monument
Section:	N/A
Easting	294040
Northing	915080
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM1778 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/7059/clach-mhic-mhios. Situated on a slight eminence on the moor, to the E of the hill road from Loth to Kildonan, is a standing stone of red sandstone. It is 11' high, 4' 11" broad where broadest about 7' from the ground, 2' 9" broad at the base, and 1'3" thick. It faces ESW and WNW. It is known as the 'Clach Mhic Mhios'. Near the large standing stone are two stones of smaller size erected "in the same manner". Statistical Account (OSA) 1793; RCAHMS 1911. This stone is as described above. The two smaller stones mentioned were not located. Visited by OS (E G C) 4 June 1961 and (J B) 20 April 1976. References OSA. (1791-9) The statistical account of Scotland, drawn up from the communications of the ministers of the different parishes, in Sinclair, J (Sir. Edinburgh. Page(s): Vol. 6, 321 RCAHMS Shelf Number: B.2.2.STA RCAHMS. (1911a) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. Edinburgh. Page(s): 163, No. 474 illust RCAHMS Shelf Number: A.1.1.INV(2) Ruggles, C L N (ed.. (1988a) Records in stone: papers in memory of Alexander Thom. Cambridge. RCAHMS Shelf Number: E.7.RUG

Asset/Event Number	70
Asset/Event Name	Caen, long cairn 460m NNW of
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM1771; ND01NW 13
HER Number	MHG10227
Status	Scheduled Monument
Section:	A1.4
Easting	301473
Northing	918157
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	High
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A pronounced mound of stone extending along a low terrace mid-way up the slope of the NE side of the Caen burn's glen. Tall and dense bracken surrounds the cairn and partially overgrows it on the periphery, distorting the dimensions. Https://portal.historicenvironment.scot/designation/SM1771 The monument is a prehistoric chambered burial cairn. The monument is a long cairn, 41m WNW-ESE and varying from 7m to 9m transversely. It has been built into a hillslope and is a maximum of 1.3m tall. The remains of a ruined field wall associated with a nearby depopulated settlement extend from either end of the cairn. The area to be scheduled measures a maximum of 80m WNW-ESE by 45m N- S, to include the chambered cairn and an area around it in which traces of activities associated with its construction and use may survive, as indicated in red on the accompanying map. Statement of National Importance The monument is of national importance for its potential contribution to an understanding of prehistoric ritual, religious behaviour and burial practices. There is no indication of the location of the chamber of this cairn, which may indicate that any burials associated with the monument are undisturbed. References The monument is recorded in the RCAHMS as ND 01 NW 13.

Asset/Event Number	71
Asset/Event Name	Greysteil Castle, broch, Loch Rangag
Type of Asset/Event	Broch
Date and/or Period	Iron Age
Listing No./NRHE Number	SM555; ND14SE 4
HER Number	MHG1588
Status	Scheduled Monument
Section:	N/A
Easting	317941
Northing	941677
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM555 The monument comprises the remains of a partially-excavated broch. The monument was first scheduled in 1938 but an inadequate area was included to protect all of the archaeological remains. The present rescheduling rectifies this. The monument is situated on a partly artificial peninsula on the E side of Loch Rangag. It survives as a turf-covered mound approximately 20m in diameter and 4m in height. A guard chamber is visible on the N side of the debris-filled entrance passage in the E. Part of a mural chamber is visible in the NW. On the landward side of the peninsula is a heather-covered stone bank approximately 1m in height and 3-4m wide, extending N-S for a distance of 26m. About 11m from the N end of the bank is a gap with a turf-covered causeway extending from it across the isthmus to terminate on the broch. However, the causeway is off-set from the broch entrance and may not be contemporary with the broch. Stonework is evident extending into the loch for a distance of several meters. The area to be scheduled is a circle 55m in diameter centred on the centre of the broch to include the broch and an area around (including under water) in which evidence relating to its construction and use may survive, as marked in red on the accompanying map. Statement of National Importance This monument is of national importance as the remains of an Iron Age broch which the partial excavation demonstrates has the potential to provide information on the nature of settlement and defensive architecture during this period of prehistory. Significant archaeological remains - perhaps some waterlogged - will survive in and around the broch. References The monument is recorded by RCAHMS as ND 14SE 4. RCAHMS 1911, THIRD REPORT AND INVENTORY OF MONUMENTS AND CONSTRUCTIONS IN THE COUNTY OF CAITHNESS, Edinburgh, HMSO, 60-1, No. 222.
Asset/Event Number	72
Asset/Event Name	Turnal Rock, hut circle complex 250m NW of Langwell Tulloch broch.
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM13631; ND02SE 13
HER Number	MHG811; MHG39431
Status	Scheduled Monument
Section:	N/A
Easting	309624
Northing	922540
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM13631 The monument comprises a complex of three conjoined roundhouses or hut circles, likely to date to the Iron Age (between 500 BC and AD 500). The monument is located approximately 90m above sea level on rising ground on a southeast facing slope above Langwell Water.

The hut circles form a roughly trefoil grouping; the smallest positioned at the north with one to the northeast and another to the south. Each structure is roughly circular and survives as low stone and turf walls up to 3m wide and 1.25m high. The hut circles measure between 10.5m and 15.5m in diameter. Each hut circle has an entrance approximately 1m wide facing into a small enclosed yard. The yard is to the southeast of the hut circles and is defined by a low stone wall, measuring 4m in length and running between the south and northeast circles, with a break for an entrance. The hut circle to the northeast contains a substantial mound of stones in the centre measuring up to 3.5m in diameter and 1m high. A low wall runs southeast from the northeast hut circle and terminates at a sub-rectangular enclosure measuring 6m by 4.5m. This low wall may be contemporary with the hut circles and the enclosure is possibly of later date. Abutting and possibly cutting the northeast hut circle, on the east side, is a sub-oval enclosure, perhaps of a later date.

The scheduled area is rectangular in shape and includes the remains described above and an area around them within which evidence relating to the monument's construction, use and abandonment is expected to survive, as shown in red on the accompanying map.

Statement of National Importance
The monument is of national importance as an example of a well-preserved prehistoric settlements. It has an inherent potential to make a significant addition to our understanding of the past, in particular the design, construction and use of hut circles in northern Scotland and the Caithness region. There is high potential for well-preserved archaeological remains to survive within and immediately outside the buildings. Unusually for this type of monument, the three hut circles are conjoined with a related connecting yard forming a rare and interesting complex. Its value is enhanced as one of a group of monuments in a remote upland landscape with possibly contemporary defended sites in close proximity. The loss of the monument would significantly diminish our future ability to appreciate and understand late prehistoric domestic buildings in Scotland and the relationship between other sites such as single houses and brochs in the Iron Age.

References
Royal Commission on the Ancient and Historical Monuments of Scotland: http://www.rcahms.gov.uk/canmore.html CANMORE ID 7528.

Highland Council HER reference MHG9852.

Fairhurst, H and Taylor, D (1970), 'A hut circle settlement at Kilphedir, Sutherland', Proc Soc Antiq Scot, 103, 65-103.

Asset/Event Number	73
Asset/Event Name	Carn nan Uaigh, prehistoric settlement
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM13627; NC91SW 1
HER Number	MHG9941; MHG43811
Status	Scheduled Monument
Section:	N/A
Easting	293476
Northing	914054
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance: N/A

Description https://portal.historicenvironment.scot/designation/SM13627

The monument consists of the upstanding remains of a later prehistoric or early historic settlement, consisting of two aisled buildings known as 'wags', probably dating to between around 100 BC and AD 600. They are visible as two long buildings, set around 10m apart, defined by low turf banks with pairs of edge-set slabs in the interior. The settlement lies 170m above sea level, on the sloping ground of the valley side, overlooking the Loth Burn.

The southeast most structure is rectangular on plan, defined by low turf banks measuring about 13m east-west by 6.6m transversely, though the west end is overlain by a later wall. In the interior two parallel rows of edge-set stones define a central space around 2m wide. The second structure lies around 10m to the northwest and measures about 13m east-west by 5.8m transversely with upright slabs in the interior. The west end is overlain by the foundations of a later structure, and the north wall line has been robbed and is indistinct, with large displaced stones visible.

The scheduled area is irregular on plan, to include the remains described above and an area around within which evidence relating to the monument's construction and use is expected to survive as shown in red on the accompanying map. To the northwest, the scheduled area extends up to, but excludes, a later stone wall.

Statement of National Importance
Cultural Significance

The cultural significance of the monument has been assessed as follows:

Intrinsic Characteristics

The monument is visible as two rectangular structures defined by low turf covered banks with edge set slabs in the interior. The east structure appears the better preserved of the two and is visible as turf covered banks representing the outer walls. Pairs of edge-set slabs set two metres apart are visible within the interior. It is overlain by a later wall at the west end. The west structure is overlain by the later foundations of a probable farmhouse and the north wall line has been robbed in the past.

Both structures have been disturbed by later buildings but the structures are in relatively good, stable condition at present, with their plans discernible. Furthermore there is good potential for the survival of archaeological deposits, including occupation and abandonment debris, floor deposits, artefacts and environmental remains such as charcoal or pollen within, beneath and around the upstanding structures. The settlement therefore has the potential to add to our understanding of settlement and economy during the later Iron Age and early historic periods.

Only two 'wag' settlements have been excavated, both before the advent of modern scientific techniques, so no radiocarbon dates have been obtained. From the excavated finds and sequences uncovered, and on the basis associated structures, it would appear that 'wag' settlements were constructed and in use during the later Iron Age or early medieval period. The precise function of such buildings is unclear but the stalls suggest that they have housed livestock. It has been further suggested that they were storehouses for produce, potentially in the form of cattle, the collection of which related to local networks of tribute (Baines 1999, 358).

At Carn Nan Uaigh, there is no clear indication whether the settlement had an extended development sequence or what its precise function was. Scientific study of the structure of the settlement would enhance our understanding of the development sequence and function of this site and of 'wag' settlements in general.

Contextual Characteristics

Wags are a rare class of monument, found only in Caithness and Sutherland. Around 20 examples are currently known. Carn Nan Uaigh is one of a group of 'wag' sites identified within Glen Loth. Two structures lie around 210m northeast at Uiagh Bheag (Canmore ID 7110), a second 'wag' is recorded around 270m to the south (Canmore ID 7131) and a further two about 1.5km southeast (Canmore ID 7132).

The group within Glen Loth is of significance as it lies at the southernmost extent of the known distribution of this site type and is the only known concentration of these sites away from the 'wag' sites further north in Caithness. All four sites are in a similar landscape context and this context contrasts with earlier Iron Age settlement in the area. The proximity of these monuments can give important insights into the late Iron Age and early historic landscape and add to our understanding of settlement patterns, social organisation, land division and land-use. There is high potential for comparative study of this monument with other settlements in the area to better understand the function of such monuments, their interrelationship and place within contemporary society and economy.

The structures are situated on sloping ground on the valley side, overlooking the Loth Burn. They stands at 170m above sea level, in the upper reaches of Glen Loth.

Associative Characteristics

At this time, there are no known associative characteristics which significantly contribute to the site's cultural significance.

Statement of National Importance

This monument is of national importance because it makes a significant addition to our understanding of the past, in particular of late Iron Age and early historic society in north Scotland and the construction, use and development of 'wag' settlements. Such settlements are restricted to Caithness and Sutherland. The survival of outer walls as well as internal features means that the monument can significantly expand our understanding of domestic buildings, agriculture and economy. As an example of a rare form of domestic settlement, this monument represents an important component of the wider late Iron Age and early historic landscape of settlement and agriculture. The loss or damage of the monument would diminish our ability to appreciate and understand the character of late Iron Age and early historic settlements, as well as society and economy during these periods.

References

Historic Environment Scotland http://www.canmore.org.uk reference number CANMORE ID 7108 (accessed on 5/9/16).
The Highland Council Environment Record reference is MHG43811(accessed on 5/9/16).
Baines, A C W 1999 An archaeology of Iron Age domestic settlement in northern Scotland, Unpublished PhD thesis, University of Glasgow.

Canmore
https://canmore.org.uk/site/7108/
HER/SMR Reference
http://her.highland.gov.uk/SingleResult.aspx?uid=MHG43811

Asset/Event Number	74
Asset/Event Name	Bail A' Chairn, broch
Type of Asset/Event	Broch
Date and/or Period	Iron Age
Listing No./NRHE Number	SM13634; ND25SW 8
HER Number	MHG1981
Status	Scheduled Monument
Section:	N/A

Easting	322816
Northing	951715
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM13634

The monument is a broch, a complex stone-built substantial roundhouse, dating to the Iron Age (between 600 BC and AD 400). The monument is visible as an oval mound up to 5.5m high with a terrace approximately 4m wide running round it. To its north are the remains of a slight ditch and bank. It is located approximately 60m above sea level and is surround by level, open ground approximately 190m west of the Burn of Acharole.

The mound on which the broch is located is artificial or, if natural, has been significantly altered. The terrace rises from ground level by around 3m as it circles the mound from the southwest to the southeast in a clockwise direction. The broch is visible as a smaller turf-covered mound but excavation in 1904 has shown that the broch was 17.5m in diameter with the wall approximately 4m thick at the entrance located on the east side. Excavation also revealed internal details such as doorways, internal upright flagstone partitions, recesses and intramural stairways. The broch entrance has an extended passage way, a secondary feature.

The scheduled area is circular in shape, with the exception of a small segment to the southeast, includes the remains described above and an area around them within which evidence relating to the monument's construction, use and abandonment is expected to survive, as shown in red on the accompanying map. The following are excluded from the scheduling; the top 30cm of the track to the southeast and east and any post and wire fences.

Statement of National Importance
Cultural Significance
The cultural significance of the monument has been assessed as follows:

Intrinsic Characteristics
The monument is a broch, visible as a grass-covered mound sitting on a larger mounded feature with a terrace approximately 4m wide running around its circumference. The upper mound is an accumulation of collapsed building material over the lower levels of the broch structure and its flooring, while the lower mound, if not wholly artificial, has been significantly altered. This lower mound is likely to retain evidence of subsidiary buildings. To its north are the remains of a slight ditch and bank which would have surround the mound but has been reduced through agricultural activity.

The site was excavated by Sir Francis Tress Barry in 1904. This revealed the walls of the broch and internal features. An extended entrance passage running 6.7m east from the broch entrance was also discovered. This passage contains evidence of two doorways and an intramural cell on its north, indicating the presence of other structures on the lower mound. The site was backfilled in 1904 but a series of contemporary watercolours and sketches by John Nicholson of Lybster recorded the results of the excavation and show that the interior of the broch was only partially excavated and the exterior mound not at all. The drawings also demonstrate that the broch structure is well-preserved within the mound with its walls surviving to around first floor level, and that it was surrounded by a bank and ditch, of which only slight remains survive. The extended entrance passage and the potential presence of outbuildings on the lower mound indicates this site may have had a complex development sequence. Scientific investigation would allow us to develop a better understanding of the chronology of the site, its date of origin, state of completeness, survival of outer works and outbuildings or related structures, and any development sequence.

By analogy with other excavated brochs, the broch mound, the lower mound and surrounding bank and ditch are likely to contain deposits rich in occupation debris, artefacts and paleoenvironmental evidence that can tell us about how people lived, their trade and exchange contacts, and their social status, as well as provide information about broch architecture and construction methods. A drawing by John Nicholson of Lybster shows finds from the excavation of the broch. These include a stone spindle whorl for textile making, a piece of pottery, a piece of antler which may have been a handle, a tooth from a wolf or dog, and two other bone objects of unknown function, demonstrating the survival of artefacts, including those made from bone.

Brochs in Caithness are typically thought to date from the mid first millennium BC to the early part of the first millennium AD. They are a specific development of complex Atlantic roundhouses and were large complex structures that would have had numerous purposes and a multifaceted role in prehistoric society. They could have accommodated either an extended family or a small community and the construction of broch towers is often understood in terms of elite settlement. Some interpretations have stressed a role as fortified or defensive sites, possibly serving a community across a wider area.

Contextual Characteristics
Brochs are a widespread class of monument across northern Scotland. This example is one of a larger local/regional group in Caithness. It follows the typical Caithness broch pattern of 'mound on mound', where the upper mound is an accumulation of collapsed building material over the lower levels of the broch structure, while the lower mound may retain evidence of subsidiary buildings and/or defences. The extended entrance passage is a feature found at other Caithness brochs such as at Achvarasdal House broch (scheduled monument reference SM514, Canmore ID 7373).

Location is a significant factor in understanding brochs, as too is intervisibility and relative position with other examples. This monument is within a small group of brochs in the Watten area, mostly located along the burns that feed Loch Watten. These include Carn A' Chladha (scheduled monument reference SM13632, Canmore ID 8805), Achingale broch (Canmore ID 8783) and Nether Banks broch (scheduled monument reference SM609, Canmore ID 8782) located 700m, 2.3km and 2.6km respectively north northeast of Bail a' Chairn. Together they offer the potential to study a group of brochs within a distinct geographic area (along the course of the Scouthal Burn) and draw comparisons with evidence from other brochs around the locality and in Caithness more widely.

Associative Characteristics
There are no known associative characteristics which contribute to the site's cultural significance.

Statement of National Significance
The monument is of national importance because it contributes to our understanding of the past, in particular of Iron Age society in Caithness and the function, use and development of brochs. It is a well-preserved example of a broch with surviving elements of the structure, occupation material and associated remains indicated by the substantial mound and surrounding bank and ditch. Excavation has demonstrated that the broch structure survives within the upper mound to a marked degree and that there is potential for remains of associated buildings on the lower mound. The broch is a prominent feature in the landscape and adds to our understanding of the siting of such monuments in the landscape. This in turn can help our understanding of settlement patterns and social structure during the Iron Age in Caithness. This potential is enhanced by the proximity of other brochs. The informative and significant early archaeological drawings of the excavation of the monument by John Nicholson of Lybster adds to the understanding of the monument. The loss of the monument would significantly diminish our future ability to appreciate and understand the development, use and re-use of brochs, and the nature of Iron Age society, economy and social hierarchy in the north of Scotland.

References
Historic Environment Scotland http://www.canmore.org.uk reference number CANMORE ID

8805 (accessed on 27/06/2016).
The Highland Council Historic Environment Record reference is MHG 1981 (accessed on 27/06/2016).
Feachem, R, 1963, A guide to prehistoric Scotland. London.
MacKie, E W, 2007, The Roundhouses, Brochs and Wheelhouses of Atlantic Scotland c. 700 BC - AD 500: architecture and material culture. Part 2 The Mainland and the Western Islands. BAR, vol 444. Oxford.
RCAHMS, 1911, The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Third report and inventory of monuments and constructions in the county of Caithness. London.

Canmore
https://canmore.org.uk/site/8805/
HER/SMR Reference
MHG1981

Asset/Event Number	75
Asset/Event Name	Carn A' Chladha, broch
Type of Asset/Event	Broch
Date and/or Period	Iron Age
Listing No./NRHE Number	SM13632; ND25SW 4
HER Number	MHG1977
Status	Scheduled Monument
Section:	N/A
Easting	323148
Northing	952336
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM13632 The monument is a broch, a complex stone-built substantial roundhouse, dating to the Iron Age (between 600 BC and AD 400). It is visible as a grass-covered stony mound 3m high and about 21m in diameter. The monument is located approximately 50m above sea level, on the southwest end of a narrow spur of rising land and lies approximately 100m west of Scouthal Burn. The broch is prominently sited on an artificially altered mound at the southwest end of natural spur that rises from ground level at it northeast end. This spur appears to have formed the approach to the broch which sits on a levelled mound approximately 1m high with a terrace between 1m and 3.5m wide running round it which broadens out at the approach to the broch. The broch is approximately 21m in diameter with grass covered collapsed walls standing to 3m in height. A stretch of outer facing stones are visible for approximately 3.5m at the south southeast arc of the broch. The scheduled area is irregular in shape, includes the remains described above and an area around them within which evidence relating to the monument's construction, use and abandonment is expected to survive, as shown in red on the accompanying map. The following are excluded from the scheduling; the top 30cm of the track to the southeast and east and any post and wire fences. Statement of National Importance Cultural Significance The cultural significance of the monument has been assessed as follows:

Intrinsic Characteristics
The monument is a broch, visible as a prominent grass-covered mound with some exposed outer walling. The mound is an accumulation of collapsed building material over the lower levels of the broch structure and its flooring. It appears relatively undisturbed and surviving features are likely to include the broch walls, intramural cells and stairs, hearths and internal partitions. In addition, there may be later structures within or around the abandoned broch tower. By analogy with a number of excavated brochs, this broch and any associated structures will contain deposits rich in occupation debris, artefacts and paleoenvironmental evidence that can tell us about how people lived, their trade and exchange contacts, and their social status, as well as provide information about broch architecture and construction methods.

The siting of the broch at the end of a long, narrow, spur is of significance. The highest point has been adapted to provide a level platform for the broch, while the tail of the spur would have served as an approach to the broch and may itself have been adapted for this purpose. Further research could establish the relationship between the broch and the natural feature, and how it was altered for the purposes of siting the broch. The location of the broch and terracing around the broch may indicate that it is the site of an earlier dun with the defences being re-used and altered by the broch builders. The larger terraced area to the north could be a later addition to the site or relate to an earlier phase of development. Scientific investigation would allow us to develop a better understanding of the chronology of the site, its development sequence and the extent that the natural spur was altered as part of the construction of the broch.

Brochs in Caithness are typically thought to date from between 600 BC and AD 400. They are a specific development of complex Atlantic roundhouses and were large complex structures that would have had numerous purposes and a multifaceted role in prehistoric society. They could have accommodated either an extended family or a small community and the construction of broch towers is often understood in terms of elite settlement. Some interpretations have stressed a role as fortified or defensive sites, possibly serving a community across a wider area. The location of Carn a' Chladha supports the view that defensive considerations could be a factor in the location of brochs but the choice of such prominent sites in the landscape could also relate to control over land and route ways and/or conspicuous demonstrations of status.

Contextual Characteristics
Brochs are a widespread class of monument across northern Scotland. This example is within a small group of brochs in the Watten area, mostly located along the burns that feed Loch Watten. These include Bail a' Chairn broch (scheduled monument reference SM13634, Canmore ID 8805) located 700m to the southwest, Achingale broch (Canmore ID 8783) and Nether Banks broch (scheduled monument reference SM609, Canmore ID 8782), 1.7km and 1.9km respectively north northeast of Carn a' Chladha. Together they offer the potential to study a group of brochs within a distinct geographic area (along the course of the Scouthal Burn) and draw comparisons with evidence from other brochs around the locality and in Caithness more widely.

Many broch towers were deliberately sited to be focal points in the landscape, and is Carn a' Chladha broch is such an example; it is sited in an elevated position on a spur above what may have been a routeway along the Scouthal Burn.

Associative Characteristics
There are no known associative characteristics which contribute to the site's cultural significance.

Statement of National Importance
The monument is of national importance because it contributes to our understanding of the past, in particular of Iron Age society in Caithness and the function, use and development of brochs. This large intact mound will contain the buried remains of a substantial broch. Features such as terraces and wall facings are clearly visible. The adaption of a natural feature, a long and narrow spur, is a significant aspect of the importance of this site,

	demonstrating how topography was in some instances exploited and accentuated by those building brochs. Carn a' Chladha broch is located in close proximity to a number of other brochs located along the Scouthal Burn and damage or loss of the monument would diminish our future ability to appreciate and understand the development, use and re-use of brochs, and the nature of Iron Age society, economy and social hierarchy in this area and further afield. References Historic Environment Scotland http://www.canmore.org.uk reference number CANMORE ID 8801 (accessed on 27/06/2016). The Highland Council Historic Environment Record reference is MHG 1977 (accessed on 27/06/2016). Feachem, R, 1963, A guide to prehistoric Scotland. London. MacKie, E W, 2007, The Roundhouses, Brochs and Wheelhouses of Atlantic Scotland c. 700 BC - AD 500: architecture and material culture. Part 2 The Mainland and the Western Islands. BAR, vol 444. Oxford. RCAHMS, 1911, The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Third report and inventory of monuments and constructions in the county of Caithness. London. Canmore https://canmore.org.uk/site/8801/ HER/SMR Reference MHG1977
Asset/Event Number	76
Asset/Event Name	Caen, hut circles and souterrain 982m, 1035m and 1083m NNW of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM1841; ND01NW 29; ND01NW 30; ND01NW 6
HER Number	Various
Status	Scheduled Monument
Section:	N/A
Easting	301092
Northing	918669
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM1841 The monument is the remains of three roundhouses and a souterrain, probably dating to the Late Bronze Age or Iron Age (between 1500 BC and AD 400). They are visible as the turf-covered upstanding remains of three roundhouses, defined by substantial turf and stone walls. The entrance to a souterrain is visible within the southernmost roundhouse, and the footings of three post-medieval buildings lie adjacent to the northernmost roundhouse. The monument lies at around 90m above sea level, on the hillside above the Caen Burn. The most northerly of the roundhouses measures about eight metres in diameter within walls up to four metres wide and one metre high, increasing in height to about 1.5m around the southeast facing entrance. This entrance is filled with rubble, and wall facings noted within the tumbled south section of the wall west of this entrance may represent the remains of a souterrain. The footings of three post-medieval buildings, the largest measuring 12.5m in length and three metres across, lie adjacent to this roundhouse and appear to have disturbed its western section. The second roundhouse lies around 59m to the south. It is

terraced into the slope and measures about nine metres in diameter within banks around 1.7m in height and 1.5m in width, with an entrance on the southeast. The southernmost roundhouse lies around 102m to the south-southwest and measures around 10m in diameter within a turf and stone bank measuring about 0.75m in height and 1.5m in width, increasing to around three metres wide towards the entrance on the southeast. The entrance to a souterrain is visible within the internal wall face in the eastern arc of this roundhouse. The passage runs under and extends beyond the wall of the roundhouse.

The scheduled area is in three parts, two of which are circular on plan and the third irregular, to include the remains described above and an area around within which evidence relating to the monument's construction, use and abandonment is expected to survive as shown in red on the accompanying map. The monument was first scheduled in 1934 and the documentation does not conform to current standards. The present amendment rectifies this.

Statement of National Importance
This monument is of national importance because it can make a significant addition to our understanding of the past, in particular of Bronze Age and Iron Age society and the construction, use and development of settlement in the north of Scotland. It is a good example of later prehistoric settlement that retains its field characteristics and there is good potential for the survival of archaeological deposits within and around the roundhouses. As a well-preserved example it can significantly expand understanding of domestic buildings, agriculture and economy. The monument's importance is enhanced by its association with a wider cluster of later prehistoric remains and with later settlement. The loss or damage of the monument would diminish our ability to appreciate and understand the character and development of later prehistoric settlements in Sutherland, society and economy during this period, as well as the long-term use and development of the landscape.

References
Historic Environment Scotland http://www.canmore.org.uk reference number CANMORE ID 7444, 7446, 7478 (accessed on 11/05/2016).
The Highland Council HER references are MHG10131, MHG10133, MHG10148.
Fairhurst, H. and Taylor, D. B. (1974) A hut-circle settlement at Kilphedir, Sutherland, Proceedings of the Society of Antiquaries of Scotland, vol. 103, 1970-1.
MacIntyre, A. (1998) Survey and excavation at Kilearnan Hill, Sutherland, 1982-3. Proceedings of the Society of Antiquaries of Scotland, vol. 128, 167-201.
RCAHMS (1911) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. Edinburgh.
RCAHMS (1993) Strath of Kildonan: an archaeological survey. RCAHMS: Edinburgh.

Canmore
https://canmore.org.uk/site/7444/
https://canmore.org.uk/site/7446/
https://canmore.org.uk/site/7478/
HER/SMR Reference
MHG10131
MHG10133
MHG10148

Asset/Event Number	77
Asset/Event Name	Caen, long cairn and round cairn 470m and 490m W of
Type of Asset/Event	Cairns
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM1770; ND01NW 3; ND01NW 25; ND01NW 67
HER Number	MHG10132; MHG10292; MHG10161
Status	Scheduled Monument
Section:	N/A

Easting	301224
Northing	917759
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	*Recorded by AOC Archaeology during 2024 walkover survey. The main element of the Scheduling, the long cairn, extends into the NW periphery of the corridor, while the round cairn and hut circle lie outwith the survey corridor. The long cairn is highly visible as a pronounced extended mound of stone, whereas the hut circle and round cairn stand below heather.* https://portal.historicenvironment.scot/designation/SM1770 The monument is a chambered long cairn dating from the Neolithic period, probably built between 3800 BC and 2500 BC, a round cairn, probably Bronze Age in date (between 2500 BC and 800 BC), and a roundhouse, likely dating to the Late Bronze Age or Iron Age (between 1500 BC and AD 400). The long cairn is visible as a substantial trapezoidal cairn of exposed stone. The round cairn visible as a small mound of earth and stone, the roundhouse as a small upstanding structure defined by a penannular bank of turf and stone. The monument is located on a level terrace on the hillside overlooking the Strath of Kildonan, about 38m above sea level. The long cairn measures about 53m in length by 19.5m in width at the east end, narrowing to around 10m at the west end. It reaches a maximum height of about 3m near the eastern edge, reducing in height towards the west end which is parallel-sided and squared. The cairn has been robbed and disturbed in places, and the presence of a chamber is indicated by two large parallel slabs visible in the disturbance at the eastern end. The round cairn and roundhouse both lie about 10m south of the west end of the long cairn, set around 4m apart. The round cairn lies to the west and measures about 5m in diameter and about 0.6m in height, while the roundhouse is around 3m in diameter within low turf and stone walls with an entrance on the southwest. The scheduled area is irregular on plan, to include the remains described above and an area around them within which evidence relating to the monument's construction, use and abandonment is expected to survive, as shown in red on the accompanying map. Statement of National Importance The monument is of national importance because it has an inherent potential to make a significant addition to our understanding of the past, in particular the design and construction of burial monuments, and the nature of burial practices and their significance in Neolithic society, as well as Bronze Age and Iron Age society, agriculture and economy in the north of Scotland. The long cairn is a visually impressive monument that retains its field characteristics and demonstrates a complex development sequence. It can be compared with a varied group of other long cairns that survive in the vicinity. The burial cairn and roundhouse are good examples of a burial monument and later prehistoric settlement located with reference to an earlier ritual monument. Chambered cairns are often our main source of evidence for the Neolithic in Scotland, and can enhance our understanding of Neolithic society and economy, as well as the nature of burial practices and belief systems. They are an important component of the wider prehistoric landscape of settlement, agriculture and ritual. Round cairns and roundhouses can significantly expand our understanding of burial practices and belief systems, domestic buildings, agriculture and economy during later prehistory. The monument's importance is enhanced by its association with a wider cluster of later prehistoric remains. The loss of the monument would diminish our ability to appreciate and understand the meaning and importance of death and burial in the Neolithic and Bronze Age and the placing of cairns within the landscape, as well as our understanding of Bronze Age and Iron Age settlements, society and economy and the influence of Neolithic ritual monuments on the siting of later prehistoric ritual and domestic sites.

	References Royal Commission on the Ancient and Historical Monuments of Scotland: http://www.rcahms.gov.uk/canmore.html CANMORE ID 7486, 7440, 7445 The Highland Council HER references are MHG10161, MHG10292, MHG10132. Fairhurst, H. and Taylor, D. B. (1974) A hut-circle settlement at Kilphedir, Sutherland, Proceedings of the Society of Antiquaries of Scotland, vol. 103, 1970-1. Henshall, A S. (1963) The chambered tombs of Scotland, vol. 1. Edinburgh. Henshall, A.S. and Ritchie J.N.G. (1995) The chambered cairns of Sutherland. Edinburgh University Press: Edinburgh. MacIntyre, A. (1998) Survey and excavation at Kilearnan Hill, Sutherland, 1982-3. Proceedings of the Society of Antiquaries of Scotland, vol. 128, 167-201. RCAHMS. (1911) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. Edinburgh. Canmore https://canmore.org.uk/site/7445/ https://canmore.org.uk/site/7440/ https://canmore.org.uk/site/7486/ HER/SMR Reference MHG10132 MHG10292 MHG10161
Asset/Event Number	78
Asset/Event Name	Caen Burn West, 935m WNW of Caen
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM13647; ND01NW 2
HER Number	MHG10122
Status	Scheduled Monument
Section:	N/A
Easting	300766
Northing	917835
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM13647 The monument is the remains of a long cairn dating from the Neolithic period, probably built and in use between 3800 BC and 2500 BC. It survives as a substantial trapezoidal cairn located on a level terrace on the hillside overlooking the Strath of Kildonan, about 38m above sea level. The cairn measures about 44m in length by around 17m in width at the east end, narrowing to about 12m at the west end. It measures around 1m in height. The eastern end of the cairn narrows gently from east to west, while the western end is parallel sided with a squared end. Remains of a possible kerb are visible on the north side. The cairn has been disturbed and much of the stone removed from the centre of the monument. A later enclosure, likely constructed from robbed cairn material, overlies and extends to the east of the cairn. The scheduled area is irregular on plan, to include the remains described above and an area

around them within which evidence relating to the monument's construction, use and abandonment is expected to survive, as shown in red on the accompanying map.

Statement of National Importance
This monument is of national importance because it has an inherent potential to make a significant addition to our understanding of the past, in particular the design and construction of burial monuments, and the nature of burial and ritual practices and their significance in Neolithic society. The long cairn is an impressive monument and can be compared with a group of other long cairns that survive in the vicinity. Long cairns can enhance our understanding of Neolithic society and economy, as well as the nature of burial practices and belief systems. They are an important component of the wider prehistoric landscape of settlement, agriculture and ritual. The loss of the monument would diminish our ability to appreciate and understand the meaning and importance of death, burial and ritual in the Neolithic and the placing of cairns within the landscape.

References
Historic Environment Scotland http://www.canmore.org.uk reference number CANMORE ID 7434 (accessed on 29/04/2015).
The Highland Council HER reference is MHG10122 (accessed on 29/4/2015)
Henshall, A S. (1963) The chambered tombs of Scotland, vol. 1. Edinburgh.
Henshall, A.S. and Ritchie J.N.G. (1995) The chambered cairns of Sutherland. Edinburgh University Press: Edinburgh.
RCAHMS. (1911) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. Edinburgh.

Canmore
https://canmore.org.uk/site/7434/
HER/SMR Reference
MHG10122

Asset/Event Number	79
Asset/Event Name	Achkinloch, chambered cairn 755m SW of, Loch Stemster
Type of Asset/Event	Chambered cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM419; ND14SE 1
HER Number	MHG1313
Status	Scheduled Monument
Section:	N/A
Easting	318862
Northing	941718
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM419 The monument is the remains of a chambered cairn dating from the Neolithic period (between 3800 and 2500 BC) and is visible as a stone and turf covered oval mound from which large edge set slabs protrude. The cairn lies 160m above sea level on a small knoll overlooking Loch Stemster with good views in all directions. The monument is an Orkney-Cromarty type chambered cairn, which are typically made up of a single long chamber, divided into stall-like "compartments" by stone uprights. The cairn is approximately 24m in diameter and survives to 1.7m in height. There are three large edge

set slabs visible near the centre of the cairn, and they likely represent the remains of the multiple compartments which would have been set off the main east-west aligned chamber.

The scheduled area is circular on plan, 35m in diameter and centred on the monument, to include the remains described and an area around within which evidence relating to the monument's construction, use and abandonment is expected to survive, as shown in red on the accompanying map. The monument was first scheduled in 1933, but the documentation does not meet current standards: the present amendment rectifies this.

Statement of National Importance
Cultural significance

The monument's cultural significance has been assessed as follows:

Intrinsic Characteristics
The monument has been denuded of most of its cairn material exposing the key structural features of the chamber and passage. However, the monument is in a stable condition at present. The extent of the surrounding cairn is defined by a well-defined turf covered mound of stones measuring approximately 24m in diameter. The large, exposed stones of the chamber form a visually impressive monument. Although the chamber and passage are exposed, excavations of chambered cairns elsewhere show that there is potential for undisturbed deposits, including human burials, artefacts and environmental remains such as charcoal or pollen, within, beneath and around the upstanding structure of the cairn.

This cairn has potential to add to our understanding of ritual and funerary practices during the Neolithic period, and to provide information about contemporary agriculture, economy and environment. Few radiocarbon dates have been obtained for Orkney-Cromarty chambered cairns because many of them were excavated before the advent of modern scientific techniques. However, from the dates available, and on the basis of typological study of the pottery found at such sites, it appears that chambered cairns were constructed and in use between around 3800 and 2500 BC.

At Achkinloch, there is no clear visible evidence of an extended development sequence. However, it is likely that this tomb was in use through several or many generations. Scientific study of the tomb's form and construction techniques compared with other tombs would enhance our understanding of the development sequence of this site and of chambered cairns in general. The monument was a place of burial and ritual during the Neolithic and is likely to have been a prominent place within a group's territory as well as a focal point in the landscape.

Contextual Characteristics
Orkney-Cromarty cairns are found only in north and west Scotland, with the greatest concentration in Orkney. Their design is particularly interesting because the shape and form, with subdivisions formed by upright slabs, is comparable with contemporary house forms such as Knap of Howar, Orkney. It is likely that this was deliberate, with the tombs representing 'houses for the dead'. Achkinloch is an interesting and impressive example with massive stones delineating a large chamber.

While there are few other cairns in the vicinity of Achkinloch cairn, it is located around 50m to the southeast of an impressive horseshoe shaped stone setting which is likely to be related to the cairn (scheduled monument reference number SM420, Canmore ID 8271). Spatial and landscape analysis of this cairn in comparison to other prehistoric monuments in the vicinity could enhance our understanding of the placing of such sites in the landscape and the organisation, division and use of land in the Neolithic.

Chambered cairns are often placed in conspicuous locations within the landscape, at the edge of arable land and overlooking or inter-visible with other ritual monuments. Achkinloch is located on a small knoll overlooking an important north-south route way in Caithness. The cairn overlooks the Loch of Sternster and, of great significance, has a relationship with the large horseshoe shaped stone setting to the northwest.

Associative Characteristics
There are no known associative characteristics which contribute to the site's cultural significance.

Statement of National Importance
The monument has potential to make a significant contribution to our understanding of the past, in particular the design and construction of burial monuments and the nature of burial practices and belief systems in the Neolithic. Ritual and funerary monuments are often our main source of evidence for human activity during the Neolithic in Scotland. They are particularly important for enhancing our understanding of Neolithic society, its organisation, economy, religion and demography. This monument retains its field characteristics to a marked degree. The large upright stones of the chamber are visually impressive and the form of the monument, with evidence for multiple chambers, can contribute to our understanding of the development and architecture of chambered cairns. Chambered cairns are an important component in understanding the prehistoric landscape of land-use, settlement and ritual. The orientation and position of Achkinloch cairn within the landscape and its close spatial relationship with the nearby stone setting is likely to be significant. The loss of the monument would diminish our ability to appreciate and understand the meaning and importance of death and burial in prehistory.

References
Historic Environment Scotland http://www.canmore.org.uk reference number CANMORE ID 8269 (accessed on 27/05/2016).
The Highland Council Historic Environment Record reference: MHG1313
Davidson, J L and Henshall, A S. (1991) The chambered cairns of Caithness: an inventory of the structures and their contents. Edinburgh: 89.
Henshall, A S. (1963) The chambered tombs of Scotland, vol. 1. Edinburgh: 257.
RCAHMS. (1911) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Third report and inventory of monuments and constructions in the county of Caithness. London: 76, No. 278.

Canmore
https://canmore.org.uk/site/8269/
HER/SMR Reference
MHG1313

Asset/Event Number	80
Asset/Event Name	Carrol, fish farm 430m SE, 410m SSE, 660m and 890m SSW of
Type of Asset/Event	Fish farm
Date and/or Period	Post-medieval
Listing No./NRHE Number	SM13617
HER Number	MHG29870
Status	Scheduled Monument
Section:	N/A
Easting	284620
Northing	906344
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM13617 The monument is a late 19th century fish farm, visible as the earthwork remains of three groups of artificial ponds with feeder and collector lades, set around 220m and 470m apart along the Allt Coire Aghaisgeig, along with the footings of a rectangular building. The

monument is located on the hillside on the western side of Strath Brora, between about 30m and 100m above sea level.

The fish farm was built before 1878 and in use between 1878 and 1921. The first group of ponds comprise three straight parallel ponds measuring around three metres in width, 55m in length and about 0.8m in depth. A fourth pond, which is less well defined and at least five metres wide, lies to the northeast. The remains of at least one sluice are visible. The second group of ponds lie around 220m downstream to the northeast and comprise a half hexagon arrangement of narrow ponds, together with a bypass lade. At least three parallel ponds around three metres in width are visible to the south and two ponds about five metres wide lie to the north. Edge set slabs, probably for controlling the flow of water, are visible at the outflow. The third set of ponds lie a further 470m downstream, close to the shore of Loch Brora, and comprise two parallel ponds around 25m long and five metres wide. The footings of a rectangular building lie about 55m west-southwest.

The scheduled area is in four parts, one of which is rectangular in plan and the others irregular, to include the remains described above and an area around them within which evidence relating to the monument's construction, use and abandonment is expected to survive, as shown in red on the accompanying map.

Statement of National Importance
The monument is of national importance because it has an inherent potential to contribute to our understanding of the establishment and growth of fish farming in Sutherland and Scotland during the late 19th century and early 20th century. It is a good example of an early fish farm that retains its field characteristics. As a well preserved example it can significantly expand our understanding of fish farming, its operation and development within the economy of Scotland. As many of the techniques of artificial fish propagation were first developed in game hatcheries in Scotland, it can enhance our understanding of the role of game hatcheries in the development of modern aquaculture and the fish farming industry in Scotland and more widely. It is notable for the survival of a range of features, including sluices and lades. The loss or damage of this monument would diminish our ability to understand the development and operation of fish farming in Sutherland and across Scotland during the late 19th century and early 20th century, as well as the place of game hatcheries in the development of modern aquaculture.

References
The Highland Council HER reference is MHG29870.
Calderwood, W. L. 1921 The Salmon Rivers and Lochs of Scotland. E Arnold: London.
The Fishery Board for Scotland. 1901 Report for 1900, part II. HMSO: Glasgow.
Hodgson, William Earl. 1906 Salmon Fishing: With a Frontispiece By Joseph Farquharson, A Facsimile in colours of a model set of flies for Scotland, Ireland, England and Wales, illustrations of angling scenes characteristic of these parts of the United Kingdom, and pictures of salmon passes. Adam and C Black: London.

HER/SMR Reference
MHG29870

Asset/Event Number	81
Asset/Event Name	Carradh nan Clach,two standing stones
Type of Asset/Event	Standing stones
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM1775; NC91SW 4
HER Number	MHG10029
Status	Scheduled Monument
Section:	N/A
Easting	293736
Northing	912736

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM1775 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/7138/glen-loth. Two standing stones 21ft apart and facing NNE-SSW, on top of the bank above the confluence of two burns. The more easterly stone is a flat slab 4ft 11ins high, 3ft 6ins across the base and 5ins thick. The other stone is square in section, 4ft 8ins high, 1ft 6ins across the front and 1ft 2ins thick. Two or three flat slabs lie on the slope to the SE. These may have formed part of the construction which is known as 'Carradh nan Clach'. RCAHMS 1911, visited 1909. The standing stones are as described. Visited by OS (E G C), 3 June 1961. No change to previous field report. The name 'Carradh nan Clach' cannot be verified. Visited by OS (J M), 17 February 1976. References RCAHMS. (1911a) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. Edinburgh. Page(s): 163, No. 473 RCAHMS Shelf Number: A.1.1.INV(2)
Asset/Event Number	82
Asset/Event Name	Buolacrabher,chambered cairn 1550m S of
Type of Asset/Event	Chambered cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM445; ND13SE 1
HER Number	MHG1138
Status	Scheduled Monument
Section:	N/A
Easting	315312
Northing	933148
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM445 The monument consists of a heel-shaped chambered cairn of Neolithic/Bronze Age date. The chambered cairn is about 17m N-S by 21m E-W. The chamber is indicated by the tops of 5 stone slabs which protrude through the cairn. There was a passage to the S side of the cairn and on the S side some digging has revealed a straight kerb of drystone walling 3 courses high and about 10m long. The entrance is visible just off centre in the S kerb. The area to be scheduled measures 45m in diameter, to include the chambered cairn and an area around in which traces of activities associated with the building and use of the cairn may survive, as shown in

	red on the attached map.
Asset/Event Number	83
Asset/Event Name	Carn na Buaile, fort 750m NNW of Comrie, Contin
Type of Asset/Event	Fort
Date and/or Period	Iron Age
Listing No./NRHE Number	SM11056; NH45NW 5
HER Number	MHG7789
Status	Scheduled Monument
Section:	N/A
Easting	241151
Northing	856690
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM11056 The monument consists of a multi-period hill-top fort, situated at around 180m OD in coniferous woodland. The origins of the fort are probably in the Bronze Age, with continued use into the Iron Age through to modern times, with the ruins of a shepherd's cairn within the interior. The monument is approximately oval on plan, measuring internally 27m ENE-WSW by 16.5m transversely. It is defined by a tumbled stone wall, best preserved in the E where it defends the eastern approach through natural rises in the topography. Here, inner and outer wall faces survive up to two courses in height and a maximum width of 3.3m. To the NW, W and S the wall has largely slipped down the slope. The entrance is in the SE and its S side is visible for c1.5m. The N side of the entrance has collapsed but there are indications that the passageway was around 1.5m wide. The interior is featureless apart from a ruinous cairn, probably erected by shepherds, lying towards the W. The area to be scheduled is irregular on plan, measuring a maximum of 65m E-W and 50m transversely. This area includes the fort and a small area around within which evidence relating to the occupation and use of the site is expected to survive, as marked in red on the accompanying map extract. Statement of National Importance This monument is of national importance as the remains of a multi-period fort which has the potential to provide valuable information on defensive architecture, as well as the nature of settlement and economy, from a number of different periods. References RCAHMS records the monument as NH45NW 5.
Asset/Event Number	84
Asset/Event Name	Preas Mairi,chambered cairn
Type of Asset/Event	Chambered cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM2397; NH45NE 5
HER Number	MHG6308; MHG7893
Status	Scheduled Monument

Section:	N/A
Easting	246084
Northing	855847
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM2397 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/12447/preas-mairi-contin. Contin Mains (Pris Maree): This Orkney-Cromarty, rectangular, chambered cairn has been almost entirely removed, only some stones of the chamber remaining. The entrance has been from the E and two portal stones survive, 3' and 3 1/2' high and 2' 4" apart, with a low sill between them. Only the N slab of the outer compartment remains; on its upper edge are three cup marks from 9" - 10" in diameter and 1 1/2" - 5" deep. Two transverse slabs sub-divide the chamber whose inner compartment is formed of two slabs; the northern is 2'3" high and the southern 3'4". N of the entrance is a prostrate slab over 7' long; 30' W of the chamber two small parallel slabs 1' apart are exposed - possibly these are slightly displaced and belong to a cist. A S Henshall 1963 The remains of this chambered cairn are as described above. Resurveyed at 1/2500. Visited by OS (R D) 20 January 1965 There is no trace of the alleged cist. Otherwise as described. Visited by OS (A A) 23 April 1975 No change. Visited by RCAMS (JRS) March 1989. Field Visit (29 August 1943) RCAHMS Emergency Survey (Archaeology) This site was recorded as part of the RCAHMS Emergency Survey, undertaken by Angus Graham and Vere Gordon Childe during World War 2. The project archive has been catalogued during 2013-2014 and the material, which includes notebooks, manuscripts, typescripts, plans and photographs, is now available online. Information from RCAHMS (GF Geddes) 4 December 2014. Note (11 November 2019) Scotland's Rock Art Project Date Fieldwork Started: 11/11/2019 Compiled by: NOSAS Location Notes: The panel is situated within the small family burial ground of the Mackenzies of Coul. The burial ground is enclosed by a stone wall and is accessed by gates on the W side. The burial ground also contains the remains of a chambered cairn (SM 2397) in the SE part of the enclosed area. The panel is one of the seven remaining stone slabs of the cairn chamber. It is part of the bipartite chamber, located is on the NE side slab of the cairn, just to the W of the 2 portal stones and to the E of the inner portal stones. The vegetation in the burial ground is not being controlled in any way and ivy covers the ground and many of the memorials and the cairn stones. There are some very large trees and ornamental shrubs which make access limited. Prior to the building of the wall around the burial ground there would have been views over the confluence of the Black Water and the River Conon to the S. There is at least one other cup marked stone in the nearby area, Coul Woods. There are other chambered cairns in the area and a henge and crannog. Panel Notes: This is a large schist slab measuring 1.8 x 0.4m wide and 0.8m high on the S side and 0.6m on the N side. The 3 large cups are on the top of the slab, they are all about 25cm across. The western-most cup is about 15cm deep, the central cup is 11cms deep and

	the E cup is very shallow in comparison only 5cm deep with no clear edge. The central cup has an upper overflowing lip on the N side. On the day of the visit the two deep cups were full of water and locally the water from the cups is still thought to be able to cure warts. Whether this belief, which may have considerable antiquity, has encouraged the deepening of the original cups is not clear, but there is no suggestion that there have been any modern changes in the shape of the cups. References Henshall, A S. (1963a) The chambered tombs of Scotland, vol. 1. Edinburgh. Page(s): Vol. 1, 346, (ROS 19) plan 347 RCAHMS Shelf Number: E.7.1.HEN RCAHMS. (1942-3) Emergency Survey of archaeological monuments in military training areas, 1981, 2v. Typescripts. Page(s): Ross 37 RCAHMS Shelf Number: A.1.1.SUR
Asset/Event Number	85
Asset/Event Name	Balnacrae, chambered cairn 230m WSW of
Type of Asset/Event	Chambered cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM2396; NH56SW 1
HER Number	MHG8930
Status	Scheduled Monument
Section:	N/A
Easting	253350
Northing	864635
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM2396 The monument is the remains of a chambered cairn dating from the Neolithic period, probably built between 3800 and 2500 BC. It is visible as a group of large upstanding stones defining a chamber and an entrance passage, and is surrounded by a slight scarp that probably indicates the original extent of the cairn. The cairn lies 245m above sea level, part way up the northwest side of Strath Sgitheach. The River Sgitheach is about 600m to the south southeast and there are long views up the strath to the south southwest. The monument is an Orkney-Cromarty type chambered cairn with the chamber aligned northeast by southwest and is defined by several large stones, some upright or leaning, others slumped. The chamber measures about 7m long by 4m wide. At the northeast end there are two low, transverse portal stones that give access to the chamber from a passage about 5.5m long and 1.5m wide. The remains of a low scarp surrounding the stones of the chamber and passage suggest the original cairn measured about 27m in diameter. The scheduled area is circular on plan, measuring 40m in diameter, centred on the north corner of the chamber, to include the remains described above and an area around them within which evidence relating to the monument's construction, use and abandonment is expected to survive, as shown in red on the accompanying map. The monument was first scheduled in 1964, but the documentation did not meet current standards: the present amendment rectifies this. Statement of National Importance The monument has the potential to enhance understanding of the past, in particular the design and construction of burial monuments and the nature of burial practices and belief systems. Ritual and funerary monuments are often our main source of evidence for human activity during the Neolithic in Scotland. They are particularly important for enhancing our

	understanding of Neolithic society, its organisation, economy, religion and demography. This monument retains its field characteristics to a marked degree. The large upright stones of the chamber are visually impressive and the form of the monument can contribute to our understanding of the development and architecture of chambered cairns. Chambered cairns are an important surviving component of the wider prehistoric landscape of land-use, settlement and ritual and the position of Balnacrae within the landscape. The loss of the monument would diminish our ability to appreciate and understand the meaning and importance of death and burial in prehistoric times and the placing of cairns within the landscape. References Historic Environment Scotland http://www.canmore.org.uk reference number CANMORE ID 12919 (accessed on 27/04/2016). The Highland Council Historic Environment Record reference is MHG8930 (accessed on 27/04/2016). Henshall, A S 1963, The chambered tombs of Scotland. Vol 1. Edinburgh. P.334-335 Davidson, J L and Henshall, A S 1989, The chambered cairns of Orkney: an inventory of the structures and their contents, Edinburgh. Canmore https://canmore.org.uk/site/12919/ HER/SMR Reference http://her.highland.gov.uk/SingleResult.aspx?uid=MHG8930
Asset/Event Number	86
Asset/Event Name	Blairmore, hut circles & field system 590m NE of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM1838; NC70SW 6
HER Number	Various
Status	Scheduled Monument
Section:	N/A
Easting	274658
Northing	904229
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM1838 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/6006/blairmore. On the N slope of a low hill at Blairmore, is a large group of small mounds. Some 100 yards NE of the hill are the remains of a hut circle of the ordinary character with entrance from the SE, and a group of ten or twelve mounds lying near. One mound lies directly opposite the entrance and within 20ft of it. Some 30ft SW of the entrance is a long low mound lying N-S, measuring 27ft by 16ft tapering towards each end, and 2 1/2ft high. About 40ft S is another, not quite so high, lying N-S and measuring 22ft by 9ft. On the E flank of the hill are a further two hut circles. The larger of the two measures 33ft by 34ft internally, with entrance, 4ft across, from the SE. Some 30ft S is another hut circle measuring 18ft by 15ft internally with entrance, 3 1/2ft wide, in the SE. In both huts the banks, 6ft to 8ft across and some 3 1/2ft high, project to flank the entrances on the NE. RCAHMS 1911, visited 1909.

Three hut circles (A, B and C) and an associated field system. Huts A and B are as described by the RCAHMS.

Hut 'C' (probably the first mentioned) is 9.0m in diameter internally, with a turf-covered wall 4.0m thick and 1.0m high. The entrance, 1.0m wide, is in the SE.

The field system, approximately 160m NW-SE by 90m transversely, is delimited by lynchets, field banks, and clearance heaps.
Hut circles surveyed at 1:2500.
Visited by OS (N K B) 15 February 1966.

(NC 746 042) Settlement (NR) (Three hut circles, A-C)
OS 1:10,000 map, (1971)

On the E flank of a hill is a settlement of three hut circles (A-C) accompanied by a field system.

'A', heather-covered, measures 11.0m in diameter inside a collapsed wall 0.6m high with a general spread of 3.0m expanding to 4.0m in the sides of a slubbed entrance in the SE.

'B', set into the slope and completely heather-blanketed, measures 5.0m in diameter within a wall spread to 2.5m on average and up to 0.5m high; the entrance is in the SE.

'C', levelled back into the slope and turf-covered, measures 20.0m N-S overall; the E wall arc is mutilated and only a conjectural, transverse length of 17.0m is indicated. The entrance is in the SE. Large blocks are evident in the hut build, in particular two contiguous slabs in the N, one up to 1.0m high, that may be inner facing-stones in situ. The collapsed walling where not disturbed is 4.0m broad and up to 1.0m high. In comparison with huts A and B, hut C, notwithstanding the poor state of preservation, presents a markedly more robust construction.

The field system is evident in numerous field clearance heaps, spaced on average from 8.0m to 20.0m apart, No measurable plots are discernible. Interspersed with occasional signs of lynchets and banks.
Revised at 1:10,000.
Visited by OS (J M) 12 March 1981.

Field Visit (21 March 1995) RCAHMS Afforestable Land Survey, Rogart
There are three hut-circles, a burnt mound, and a field-system and small cairns on a heather-covered hill to the E of Blairmore.

The three hut-circles lie on a terrace on the E of the hill. One of the huts (ROG95 415) is much smaller than the other two; oval on plan, it measures about 5m from WNW to ESE by 4m transversely within a stony bank spread to 2.5m in thickness and up to 0.5m in height with an entrance in the ESE. The other two are both about 10m in diameter. The wall of the E hut-circle (ROG95 417) are up to 3.2m thick and 1m high; there is a probable entrance gap on the SSE and a second gap on the NW. The W hut-circle (ROG95 416) comprises a stony bank 2.4m thick and 0.5m high; the entrance lies on the ESE and there is a water-filled hollow in the centre of the interior.

The burnt mound lies a short distance to the E (ROG95 419, NC 7474 0422) on the opposite side of the track from the hut-circles. Set against the slope of the hill, the oval-shaped mound measures 6.2m from N to S by 4.5m transversely and 1m in height. There is no trough visible, but there are exposures of burnt, shattered small stones in the body of the mound.

The spread of small cairns (ROG95 418) extends in a strip about 100m wide over the whole of the hill from the road at the W to the track in the E, a distance of 300m. The cairns are up to 5m across by 0.5m high with occasional banks of stone visible, especially where the heather is burnt off.

	(ROG95 415-419) Visited by RCAHMS (PJD) 21 March 1995. References RCAHMS. (1911a) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. Edinburgh. Page(s): 170, No. 489-90 plan RCAHMS Shelf Number: A.1.1.INV(2)
Asset/Event Number	87
Asset/Event Name	Killin,chambered cairn 800m N of,Loch Brora
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM1794; NC80NE 4
HER Number	MHG10815
Status	Scheduled Monument
Section:	N/A
Easting	285659
Northing	907840
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM1794 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/6486 (NC 857 077) Allt name Ban: Orkney-Cromarty with a Camster type chamber. The cairn lies in a thin birch wood gently sloping down to the E shore of Loch Brora and close to the left bank of the burn at 200ft OD. It is composed of small rounded boulders, has been greatly disturbed and a large part of it carted away for road metal but the N half of a tripartite chamber remains backed by cairn material which still reaches a height of 6ft. The cairn has been oval in plan and now appears to measure about 66ft by 47ft, but when seen in a less ruined state by RCAHMS (1911) he judged the length to be about 54ft. The chamber is orientated E - W along the main axis. The entrance has been from the W side which faces the loch. The S wall of the passage, built of large slabs set on end, still survives, 27ft long. The entrance into the chamber is between transversely set portal stones 2ft 6ins high and 2ft apart. Two lintels remain, the inner over the portal stones but resting on an intervening stone on each side which serves to increase the height of the entrance; the outer lintel rests on the passage walls, here 2ft 7ins apart. The height of the lintel is 2 - 3ft above the present floor level. The chamber has three compartments, with a total length of 15ft. The N wall of drystone, attains a maximum height of 4ft but the S wall is virtually destroyed. RCAHMS 1911, visited 1909; Antiq J 1928; W D Simpson 1936; A S Henshall 1963, visited 1957. The cairn is generally as described above. Due to the birch and dense bracken it is not possible to determine the exact dimensions of the cairn but it appears to have measured 24.0m E to W by 20.0m N to S. Only parts of the N and W sides remain, together with the tripartite chambers. The S wall of the entrance passage is not now apparent.

The maximum height of the cairn is 1.7m, measured on the N side, this side being a mass of rubble.

There are several field clearance mounds in the vicinity.
Visited by OS (E G C) 16 July 1961

No change since report of 16 July 1961.

Revised at 1/10,000.
Visited by OS (J B) 10 November 1975.

Field Visit (25 August 1909) RCAHMS County Inventory: Sutherland
44. Chambered Cairn, Allt nam Ban. On the left bank of the Allt nam Ban, which flows into the middle one of the three divisions of Loch Brora, near the centre of the E. bank and about 30 yards back from the road, in a birch wood, are the remains of an excavated chambered cairn. The passage which approaches the chamber from the W. has been removed almost up to the lintel covering the entrance, which is at 20' from what appears to have been the outside. The passage exists for the last 3' 8", including the part covered by the lintel, and is 3' wide. The portals which support the lintel are 2' high and have on the top of each an additional stone, raising them to 2' 9". The lintel is 5' long, 1' 8" deep, and 1' 4" across. The chamber appears to have been tripartite. The first compartment is 5' long: the S. side has fallen, but the width has been about 7'. The sides have been curved, and are entirely built instead of having large upright slabs forming a portion of the walls. Two partition stones 3' long by 1' thick and 3' in height, as far as exposed, and about 2' apart, separate the first and second compartments. The second compartment, which is also built, is 4' 9" in length by 8' 3' in breadth. At the back are two other division stones 1' 9" apart: that on the N. 3' 6" long, that on the S. 3'. They are in great measure covered with debris, and no part of the chamber beyond is visible. The diameter of the cairn along the line of the direction of the chamber from E. to W. has been about 54' and across the chamber about 46'. The remains of the cairn are covered with moss and fern.
OS 6-inch map, Sutherland, Sheet xcvii. (unnoted).
RCAHMS 1911, visited (AOC) 25th August 1909.

References
Henshall, A S. (1963a) The chambered tombs of Scotland, vol. 1. Edinburgh. Page(s): 307-8, SUT 6 plan RCAHMS Shelf Number: E.7.1.HEN
RCAHMS. (1911a) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Second report and inventory of monuments and constructions in the county of Sutherland. Edinburgh. Page(s): 17-18, No. 44 RCAHMS Shelf Number: A.1.1.INV(2)
Simpson, W D. (1936c) Scottish archaeological studies. Aberdeen. Page(s): 171-4
Simpson, W D. (1928) 'A Chambered Cairn at Allt-nam-Ban, Strathbrora, Sutherland', Antiquaries' Journal, vol. 8, 1928. Page(s): 485-8

Asset/Event Number	88
Asset/Event Name	Langwell Plantation, souterrain 130m W of Kennels
Type of Asset/Event	Souterrain
Date and/or Period	Iron Age
Listing No./NRHE Number	SM3436; ND12SW 7
HER Number	MHG1123
Status	Scheduled Monument
Section:	N/A
Easting	310166
Northing	922410
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM3436 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/8109. Some 200 yds W of the gamekeeper's house at Langwell, within the wood and close to the park railings, is an earth-house. Access is gained to it by a hole broken through the roof towards its inner end, the portion towards the entrance being unopened. At the aperture it is 5ft 3ins in width. It extends inwards for a distance of 10ft 6ins in, expands to 6ft at greatest width, and measures at highest, 4ft 7ins above the debris that covers the floor. The sides are built of boulders, the end is rounded, and the roof formed of flagstones. Near the opening an upright stone set in the floor 2ft out from the N wall forms a pillar for support of the flag above it. RCAHMS 1911, visited 1910. This earth-house has been completely destroyed. Only a few stones, and a cavity covered by a fallen tree, mark the site. Visited by OS (J L D), 29 June 1960. (ND 1016 2240) Earth-house (NR) (site of) OS 6" map, (1964) The area has been ploughed and planted with trees. There are no recoverable traces of the souterrain and no local knowledge in respect of it. Visited by OS (J M), 23 November 1982. References RCAHMS. (1911b) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Third report and inventory of monuments and constructions in the county of Caithness. London. Page(s): 66, No. 246 RCAHMS Shelf Number: A.1.1.INV(3).R
Asset/Event Number	89
Asset/Event Name	Burg Ruaidh, or Borgue Roy, broch, Berriedale Water
Type of Asset/Event	Broch
Date and/or Period	Iron Age
Listing No./NRHE Number	SM526; ND12NW 6
HER Number	MHG1094
Status	Scheduled Monument
Section:	N/A
Easting	311611
Northing	928529
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM526 The monument comprises the remains of a broch, a drystone-built, fortified dwelling of Iron Age date. It is already scheduled, but the scheduled area does not cover all of the area of archaeological importance. This proposal rectifies the position. The broch stands 3.5m high, and is about 16m in internal diameter. The outer wall face is visible for the majority of its circuit, and is especially well-preserved on the N and NE. The entrance was probably on the SW, but this area is obscured by tumbled stone. There are

	traces of intra-mural chambers or galleries within the thickness of the wall. Internally the broch is filled with rubble, and the inner wall-face is not clear at any point. Around the broch are a series of traces of other structures, including an outer enclosure wall, which is clearest on the E and S sides, and a number of other field or enclosure walls on the W. A modern shelter and a heap of piled stones on the W side of the broch are also included, as they are probably constructed of stone taken from the broch. The area now to be scheduled is a circle of diameter 100m, to include the broch, shelter and outer walling, and an area of ground around and between these features in which evidence for their construction and use may survive, as marked in red on the accompanying map extract.
Asset/Event Number	90
Asset/Event Name	Cor Tulloch,prehistoric settlement
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM543; ND13NE 1
HER Number	Various
Status	Scheduled Monument
Section:	N/A
Easting	315141
Northing	935535
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM543 This monument consists of the well preserved remains of a prehistoric settlement which survives as a turf-covered mound of stones, 32m NW- SE by 30m NE-SW and 1.5m high. This mound contains the remains of 3 structures. Two structures are aisled rectangular houses - these have evidence for displaced pillar stones and lintel slabs and in one case a number of roofing slabs remain in situ. Three upright slabs forming part of a third structure are visible at the centre of the mound. On the S of the site are traces of a boulder-faced wall. This probably once surrounded the settlement, but the margins of the mound have been disturbed by ploughing and robbing. The area to be scheduled measures a maximum of 70m WSW-ENE by 65m N-S, to include the mound with houses and an area around in which traces of activities associated with the construction and occupation of the settlement will survive, as shown in red on the attached map.
Asset/Event Number	91
Asset/Event Name	Tiantulloch, broch, prehistoric and post-medieval settlements
Type of Asset/Event	Broch
Date and/or Period	Iron Age
Listing No./NRHE Number	SM585; ND13NE 2
HER Number	MHG1127
Status	Scheduled Monument
Section:	N/A
Easting	315251
Northing	935223

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM585 The monument consists of the remains of a prehistoric broch with the closely associated remains other contemporary buildings. The broch appears to have been about 17m in diameter and survives to 3m high. The broch mound rises from a larger mound which contains the outbuildings of an associated settlement. The latter mound is faced by walling 1.3m high which abuts the SW end on the outside of the broch. Removal of some stones near the broch end of the wall has revealed the corbelled roof of an outbuilding and an apparently lintelled passage or gallery leading off it. The area to be scheduled measures 60m NW-SE by 50m SW-NE to include the broch and associated mound containing outbuildings. This area includes the remains of the post medieval croft of Tiantulloch. This building is of no great antiquity, but is in very close proximity to the edge of the broch mound and the broch cannot be fully protected unless the post medieval building is scheduled. The area to be scheduled is marked in red on the attached map.
Asset/Event Number	92
Asset/Event Name	Rangag, standing stone by Latheron to Thurso Road,750m N of
Type of Asset/Event	Standing stones
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM473; ND14SE 5
HER Number	MHG1317
Status	Scheduled Monument
Section:	N/A
Easting	317678
Northing	944875
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM473 No description available from HES. Description taken from Canmore https://canmore.org.uk/site/8274/rangag. A four-sided stone pillar, about 2ft 9ins square, standing to a height of 9ft 5ins above ground level. It seems to face E, and is tilted slightly towards the W. On its S face, near the W edge and about 3ft above ground level, are some raised markings which have the appearance of sculpture, but are probably natural. RCAHMS 1911; R W Feachem 1963. As described above. Visited by OS (R L) 9 May 1967. No change to the previous reports. Visited by OS (N K B) 6 December 1982. References Close-Brooks, J. (1995a) The Highlands, Exploring Scotland's Heritage series, ed. By Anna Ritchie. 2nd. Edinburgh. Page(s): 154 RCAHMS Shelf Number: A.1.4.HER

	Feachem, R. (1963b) A guide to prehistoric Scotland. 1st. London. Page(s): 74 RCAHMS Shelf Number: E.2.FEA RCAHMS. (1911b) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Third report and inventory of monuments and constructions in the county of Caithness. London. Page(s): 78, No. 284 RCAHMS Shelf Number: A.1.1.INV(3).R
Asset/Event Number	93
Asset/Event Name	Halsary,standing stones 450m WNW of and 620m NW of
Type of Asset/Event	Standing stones
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM5301; ND14NE 2 and 3
HER Number	N/A
Status	Scheduled Monument
Section:	N/A
Easting	317639
Northing	949228
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5301 This monument consists of 2 standing stones which have been left in clearings in a forestry plantation. The S stone is a grey schistose slab, now split vertically into 3 portions and leaning slightly to the SE. It faces NW-SE and measures 1.4m high by 0.8m to 1m broad and 0.4m thick. The stone sits in a hollow about 0.3m deep and a number of packing stones are visible around the base. The N stone is about 0.6m high, 0.7m broad and 0.3m thick. This stone is set in a low and ill-defined mound. The two areas to be scheduled measure 10m in diameter, to include the stones and areas around both stones in which traces of activities associated with their erection may survive, as shown in red on the attached map. Statement of National Importance These monuments are of national importance for their potential contribution to an understanding of prehistoric ritual beliefs. The stones are set in thick peat and significant archaeological remains may survive in the area around the base of both stones. References Bibliography RCAHMS records the monument as ND 14 NE 2 and 3
Asset/Event Number	94
Asset/Event Name	Gallow Hillock, cairn on Backlass Hill
Type of Asset/Event	Cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	SM450; ND25SW 2
HER Number	MHG1965
Status	Scheduled Monument
Section:	N/A
Easting	320493

Northing	954115
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM450 The monument is a prehistoric cairn visible as a grass covered mound. The monument was first scheduled in 1938, but an inadequate area was included to protect all of the archaeological remains: the present rescheduling rectifies this. The monument is visible as a grass-covered mound situated at 110m OD on the top of Backlass Hill. It is circular, 1.2m in height with maximum dimensions 24m NE-SW by 21m transversely. The mound rises to a flat top with a diameter of c.11m. Historical mapping shows the presence of an old market stance, and it may be that the cairn was indeed reused as a gallows hill in the Middle Ages, as part of an area used for markets and the administration of justice. The area to be scheduled is a circle 40m in diameter centred on the centre of the cairn, to include the cairn and an area around in which evidence relating to its construction and use may survive, as marked in red on the accompanying map. The above-ground portion of the triangulation pillar, situated on the NE side of the cairn, is excluded from scheduling. Statement of National Importance This monument is of national importance because of its potential to contribute to our understanding of prehistoric ritual and funerary practices: it is likely to contain at least one central burial as well as secondary burials dug into the mound. A mound of this size should also cover an area of prehistoric land surface, which would have the potential to enhance considerably our understanding of prehistoric environmental conditions. References The monument is recorded by RCAHMS as ND25SW2. RCAHMS 1911, THIRD REPORT AND INVENTORY OF MONUMENTS AND CONSTRUCTIONS IN THE COUNTY OF CAITHNESS, Edinburgh, HMSO, 133, No 482.
Asset/Event Number	95
Asset/Event Name	Scouthal Burn, chapel & The Clow
Type of Asset/Event	Chapel; burial ground
Date and/or Period	Post-medieval
Listing No./NRHE Number	SM721; ND25SW 3; ND25SW 3.01; ND25SW 3.02
HER Number	Various
Status	Scheduled Monument
Section:	N/A
Easting	323302
Northing	952412
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description

https://portal.historicenvironment.scot/designation/SM721
No description available from HES. Description taken from Canmore https://canmore.org.uk/site/8800/clow-chapel (ND25SW 3), https://canmore.org.uk/site/90913/the-clow (ND25SW 3.01) and https://canmore.org.uk/site/90914/the-clow (ND25SW 3.02).

ND25SW 3
ND25SW 3.00 2331 5245
ND25SW 3.01 ND 233 524 Farmstead
ND25SW 3.02 ND 2328 5232 Mill (possible)
(ND 2331 5245) Chapel (NR) (Remains of)
(ND 2331 5246) Grave Yard (NR) (Site of)
(ND 2323 5242) Red Well (NR) (Chalybeate)
OS 6" map, Caithness, 2nd ed., (1907)

These are the remains of St Mary's Chapel, standing in its graveyard with St Mary's Well on the opposite side of the Scouthal Burn.

Only fragments remain of the chapel, which appears to have consisted of a chancel, 14 by 10ft, and a nave, about 26 by 16ft. The walls, apparently unmortared, have been some 4ft thick.

In 1726, the chapel is described as having been 'ruinous before our time', and was used as a burial place only of strangers and unbaptised children. It seems to have been abandoned altogether about 1770. The Scouthal Burn is said to occasionally disclose stones and bones belonging to the graveyard. The area is known as 'The Clow', probably from 'Cladh' - a church-yard.

To the W of the chapel is an old enclosure with the foundations of several old rectangular buildings around it.

The Red Well is described by the ONB (1871) as a healing well of great popularity in the neighbourhood, and was believed to have been a holy well.

Name Book 1871; W Macfarlane 1906-8; D Beaton 1909; RCAHMS 1911, visited 1910; A MacKay 1914.

St Mary's Chapel is as described above. The interior wall face survives to a maximum height of 0.5m in the NE of the nave, and the exterior wall face is exposed only in the SE. There is no trace of the graveyard. There are no structural remains of the 'Red Well' and the only indication is a small marshy area, reddish in colour.

In the vicinity of the chapel are four ruined buildings, one of which contains a corn-drying kiln, and several enclosures (The Clow).
Survey of St Mary's Chapel revised at 1:2500.
Visited by OS (N K B) 22 October 1965.

(ND 2331 5245) Chapel (NR) (rems of)
(ND 2322 5246) Red Well (NR) (site of)
OS 1:10,000 map, (1976)

Extensive documentary search failed to locate any early reference to the site. Excavation in 1975-7 indicated that the nave was secondary and that the chancel is the only remnant of a unicameral structure whose proportions of roughly four to one suggest a later date than the Early Christian. A line of burning towards the S wall of the nave, which was thought to suggest the presence of an earlier timber church, proved to be only a slight scatter of charcoal; but an L-shaped arrangement of large stones, possibly indicating an earlier foundation, was located a little to the E of the entrance, which was confirmed towards the E end of the S side of the nave.

A slight ridge to the N of the nave suggested a churchyard enclosure, but a cut failed to

locate this and the only feature of interest was a series of skulls neatly placed in small cists. Decapitation had taken place, a wide range was represented, and some skulls showed evidence of re-burial.

Excavation of the settlement nearby, which included a mill, showed it to be 18th and 19th century.
E Talbot 1977; Information from Ts of E Talbot's excavation report.

A further season of excavation has yielded more burials of skulls with the upper seven vertebrae, and fragments of a possible 13th century jug were found close to the foundations of the nave wall.
E Talbot 1980.

The chapel remains are generally as described. There is no sign of the graveyard. The area of the excavations has been backfilled. The Red Well, at ND 2323 5248, is across the Southal Burn and on the W side of the road. It is set into the face of a natural bank and shows an open side, 0.6m wide by 0.4m high. The slab roofing of the well is partly collapsed.
Surveyed at 1:10,000.
Visited by OS (J M) 11 March 1982

Longhouse farm (ND 2330 5240), comprising;
A: Chapel, St Mary's. Dimensions: 10.5 x 7m. Rectangular structure with porch 5 x 5m on the NE wall. Orientation NE-SW.
B-D: See ND25SW 3.01
E: See ND25SW 3.02
R J Mercer, NMRS MS/828/19, 1995

An unroofed building is shown on both the first edition 6-inch map (Caithness 1877, sheet xiii) and the current edition of the OS 1:10,000 map (1994).

Information from RCAHMS (FO) 27 March 1996.

References
Beaton, D. (1909) Ecclesiastical history of Caithness and annals of Caithness parishes. Wick. Page(s): 57 RCAHMS Shelf Number: D.6.11.BEA
Clark, J. (1981) 'Medieval Britain in 1980. II. post-conquest', Medieval Archaeology, vol. 25. Page(s): 199
Close-Brooks, J. (1995a) The Highlands, Exploring Scotland's Heritage series, ed. by Anna Ritchie. 2nd. Edinburgh. Page(s): 29, 121 RCAHMS Shelf Number: A.1.4.HER
Dobie, W. (1887) 'On an old grave containing two skeletons covered by a slab at Ladykirk Church', Hist Berwickshire Natur Club, vol. 11, 1, 1885-6. Page(s): 109
MacKay, A. (1914) History of the Province of Caithness and Sutherland from the Earliest Times to 1615, in Beaton, D. Wick. Page(s): 37
Macfarlane, W. (1906-8) Geographical collections relating to Scotland, in Mitchell, A and Clark, J T, 3v. Edinburgh. Page(s): Vol. 1, 180 RCAHMS Shelf Number: D.20.MAC.R
Ordnance Survey (Name Book. (1848-1878) Object Name Books of the Ordnance Survey (6 inch and 1/2500 scale). Page(s): Book No. 12, 109 RCAHMS Shelf Number: Ref
RCAHMS. (1911b) The Royal Commission on the Ancient and Historical Monuments and Constructions of Scotland. Third report and inventory of monuments and constructions in the county of Caithness. London. Page(s): 126, No. 460 RCAHMS Shelf Number: A.1.1.INV(3).R
Talbot, E. (1977) 'Watton, Clow, chapel', Discovery Excav Scot, 1977. Page(s): 11
Talbot, E. (1980a) 'Clow (Watten p) chapel',anan p) Motte', Discovery Excav Scot, 1980. Page(s): 17
Talbot, E J. (1978) 'Excavations at Clow Chapel, Watten, ND 233 524', Caithness Fld Club Bull, vol. 2, 3, 1978, April. Page(s): 93-4
Webster and Cherry, L E and J. (1976) 'Medieval Britain in 1975', Medieval Archaeology, vol. 20, 1976. Page(s): 183-4
Webster and Cherry, L E and J. (1978) 'Medieval Britain in 1977', Medieval Archaeology, vol. 22, 1978. Page(s): 167

	ND25SW 3.01 Longhouse farm (ND 2330 5240), comprising; A: See ND25SW 3.00 B: Longhouse. Dimensions: 21 x 5m. Rectangular structure divided into five compartments. Associated with an enclosure 45 x 7m. It lies 14m W of A. Orientation E-W. C: Kiln. Dimensions: 9 x 4m. Rectangular structure with a corn-drying kiln 2.5m in diameter attached to the NE end. It lies 2m S of B and with it forms part of an enclosure 25 x 7m. Orientation E-W. D: Structure. Dimensions: 5 x 4m. Rectangular construction. Orientation E-W. E: See ND25SW 3.02 R J Mercer, NMRS MS/828/19, 1995 A farmstead comprising three unroofed buildings, three enclosures and a length of wall are depicted on the 1st edition of the OS 6-inch map (Caithness 1877, sheet xxiii). Three unroofed buildings and an enclosure are shown on the current edition of the OS 1:10000 map (1994). Information from RCAHMS (SAH) 24 November 1995 ND25SW 3.02 Longhouse farm (ND 2330 5240), comprising; A-D: See ND25SW 3.00 & 3.01 E: Longhouse. Dimensions: 18 x 5m. Rectangular bipartite structure, possibly with a kiln at the NW end. Orientation NW-SE. R J Mercer, NMRS MS/828/19, 1995 An unroofed long building of two compartments is shown on the 1st edition of the OS 6-inch map (Caithness 1877, sheet xxiii) and is similarly depicted on the current edition of the OS 1:10000 map (1994). Information from RCAHMS (SAH) 24 November 1995 The first edition of the OS 6-inch map (Caithness 1877, sheet xxiii) does not show any trace of a mill lade, sluice or mill dam and the building may be part of the farmstead at ND25SW 3.01. Information from RCAHMS (FO) 27 March 1996
Asset/Event Number	96
Asset/Event Name	Fairburn Tower
Type of Asset/Event	Tower house
Date and/or Period	Medieval; Post-medieva;
Listing No./NRHE Number	LB14030; NH45SE 1
HER Number	MHG7784
Status	Listed Building - Category A
Section:	N/A
Easting	246952
Northing	852356
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB14030 Fairburn Tower is a 16th century tower-house with early 17th century additions, located on a ridge between the Rivers Conon and Orrin. Restored, 2020-22. The narrow, square plan tower has four stories (including vaulted basement) and an attic.

The walls are of lime pointed and harled rubble. There are gun-loops at the ground floor level. A projecting tower containing a broad circular stair was added to the south side during the 17th-century. The attic level has crow-stepped gables and corbelled-out turrets on the northeast and southwest angles. There is a corniced apex chimney stack to the stair tower.

The vaulted basement was not initially accessible from the exterior and was reached from a straight stair within the north wall. The projecting stair tower masks the earlier first-floor entrance doorway with plain moulded surround. The first floor contains the main hall and several mural closets or wall chambers. Each of the upper floors consists of one room of the same size as the hall, again with several wall chambers.

The tower was restored as holiday accommodation by Simpson and Brown Architects for the Landmark Trust (2020-2022). The spiral staircase and the conical roof turrets have been reintroduced, and the roof recovered with grey slate.

Adjoining the east wall of the tower is the roofless remains (2022) of a two-roomed thatched cottage containing a large arched fireplace with an oven which appears to have been from an earlier kitchen wing.

Statement of Special Interest
The tower occupies a commanding position on a hilltop ridge overlooking Strathconon and the Orri valley. A former stronghold of the Mackenzies, the tower was probably built for Murdo Mackenzie after he received a charter for the lands with the understanding that he built a house there.

Listed Building Record revised 2022.

References
Canmore: http://canmore.org.uk/ CANMORE ID: 12479
Gifford J (1992) The Buildings of Scotland, Highlands and Islands, London, p.412.
MacGibbon D and Ross T (1887) The Castellated and Domestic Architecture of Scotland, Edinburgh, Vol. 3, pp.462-465.
Stell G (1986) 'Architecture and Society in Easter Ross before 1707', in Firthlands of Ross and Sutherland, Edinburgh, pp.116-18.
Tranter N (1970) The Fortified House in Scotland: South West Scotland, Edinburgh, Vol. 5, pp.156-7.
Fairburn Tower, The Landmark Trust - Fairburn Tower | The Landmark Trust [accessed 2022]

Asset/Event Number	97
Asset/Event Name	Fairburn House
Type of Asset/Event	Mansion house
Date and/or Period	1878
Listing No./NRHE Number	LB14031; NH45SE 21
HER Number	MHG16666
Status	Listed Building - Category B
Section:	N/A
Easting	245507
Northing	853014
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://portal.historicenvironment.scot/designation/LB14031 Wardrop and Reid, 1877-78 (house dated 1878). Scottish Baronial mansion house; stugged and sneck coursed rubble, contrasting tooled ashlar dressings. Mainly 3 storeys, blocks of varying height group round taller entrance bay and tower. Off-centre crenelated tower on south elevation, 5 storeys with corbelled circular angle stair turret in re-entrant angle former with entrance bay, conical roof and weathervane above crenelations. Projecting near-centre gabled 3-storey entrance bay in south elevation with round-headed doorway and initialled plaque above; angle bartizans. Elsewhere asymmetrical design with angle drum towers, bipartites and tripartites; 2- and 3-storey canted bay windows, crowsteps and gabletted dormers. 2-pane glazing throughout. Ridge and end corniced stacks; slate roof. Interior: entrance hall with stone Baronial chimneypiece to medieval design and wide wooden staircase rising to 1st floor and principal rooms. Drawing room with pendant plaster ceiling and 2 marble chimney-pieces. Dining room with panelled dado and ceiling, all with lozenge detailing; high carved and panelled wooden chimney piece with inserted portrait. Further wooden staircase with heavy balusters rising to 2nd floor and principal bedrooms. Nursery suite with decorative preses, one having illustrations from Barrie's PETER PAN. Statement of Special Interest Built and owned by Stirling family from 1878-1982. References Original drawings with owner. Copies in National Monument Record of Scotland.
Asset/Event Number	98
Asset/Event Name	Gate Lodge, Aultgowrie Lodge, Fairburn House
Type of Asset/Event	Gate lodge
Date and/or Period	1877
Listing No./NRHE Number	LB14032; NH45SE 21.04
HER Number	MHG42732; MHG42726; MHG16683
Status	Listed Building - Category B
Section:	N/A
Easting	247668
Northing	851714
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB14032 Wardrop and Reid, 1877. Arts and Crafts. Cruciform plan; single storey and dormerless attic; asymmetrical coursed stugged rubble, contrasting polished ashlar dressings. Centre door on south and flanking narrow recessed windows under deep timber framed gable supported on 4 wooden columns on stone plinths to give verandah. 4-light window in centre of gable; large canted bay window in east gable; decorative bargeboards with carved foliage and apex finials at south and east (facing drive and road), simple bargeboards elsewhere. Centre ridge battery of 4 corniced stacks. Multi-pane glazing in attic casements, and in upper lights of sashes, 2- and 4-pane in lower sashes. Gate piers and gates; 2 pairs octagonal ashlar gate piers with shallow pyramidal caps linked to similar end piers by low coped quadrants; single large wooden carriage gate; flanking matching pedestrican gates. Statement of Special Interest

	Initials JS for John Stirling who bought the estate of Fairburn from Seaforth and Muirton from Robert Ainslie in 1865. Present Fair-Burn House Built on or near site of former Muirton House. References Original drawings at Estate Office.
Asset/Event Number	99
Asset/Event Name	Coul House
Type of Asset/Event	Villa
Date and/or Period	1821
Listing No./NRHE Number	LB1769; NH45NE 80
HER Number	MHG14110
Status	Listed Building - Category A
Section:	N/A
Easting	246249
Northing	856404
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB1769 1821, additions Alexander Ross, 1860. Unusual villa of 1821 centred on 2 octagons, 1 to south of 2 storeys with 2-bay wings. Sympathetically enlarged in 1860 in identical masonry style. Now 2-storey, of varying heights, 7 bays with further 2-storey, 3-bay service wing to south gable Pinned rubble, contrasting tooled and polished ashlar dressings and base course. West front; tall octagonal central core projects as semi-octagon with octagonal piended roof; tall corniced ground floor windows and small square windows in 1st floor on 3 faces, all with moulded architraves; flanking 2-storey 2-bay wings with original ground floor windows as octagon; 2nd floor either re-windowed or raised in 1860. East entrance front; centre entrance in semi-octagonal porch, leading to octagonal hall, with pedimented portice; supported by painted Roman Doric columns; moulded eaves cornice and shallow leaded roof. Porch flanked by slightly advanced piended outer bays, to right (west) containing stairwell (which appoears to date from 1821) 1860 2-storey, 2-bay extensions flank west front, extending east to form outer wings. Tall flat-headed ground floor windows, and segmental headed 1860 windows in 1st floor (except front octagon); later 19th century rectangular bay window at ground floor immediately right of centre octagon; later 19th century 2-storey 3-bay gabled service wing to south gable. Some lying-pane glazing survives in ground floor windows; multi-pane in 1st floor; square corniced end and ridge stacks, single and in batteries of 2 and 4; shallow slated roof with projecting eaves. Interior; semi-octagonal pilastered entrance hall; octagonal drawing room with ornate plaster ceiling with central roundel decorated with acanthus leaves, key-patterned panels radiate to cornice; original black marble chimney piece. Flanking ground floor rooms (present dining room and bar) again with central acanthus roundels and circular panels with anthemion and palmette detailing to ceilings, moulded cornices Simple side staircase with plain cast iron balustrade and continuous polished wooden handrail; simple panelling with moulded plaster dados; corniced ceiling to stair-well. Statement of Special Interest Former mansion of Mackenzies of Coul. In 1837 described as handsome and commodious" and "surrounding grounds. Tastefully laid out, garden of … superior style "An elegant

	mansion, the seat of Sir George Mackenzie, Bart". (c. 1858). Precise original Lay out difficult to ascertain without plan or without documentation on 1860 alterations. South 2-storey, 3-bay service wing may be of 1860 date or slightly later; appears on 1st edition OS of 1877. References NEW STATISTICAL ACCOUNT (1837) xiv, p.238. IMPERIAL GAZETTEER OF SCOTLAND (circa 1858) p.299 N.M.R.S.
Asset/Event Number	100
Asset/Event Name	Orrin Bridge, Aultgowrie
Type of Asset/Event	Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	LB14020; NH45SE 26
HER Number	MHG16375
Status	Listed Building - Category B
Section:	N/A
Easting	247642
Northing	851570
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/LB14020 Mid 19th century; high, single span bridge; coursed rubble, dressed rubble arch ring; ashlar coped parapet with shaped terminals; splayed approach; shallow end buttresses. References THE STATISTICAL ACCOUNT, vii, (1793) p.251. A.R.B. Haldane, NEW WAYS THROUGH THE GLENS (1962 and 1973) pp.121-2, 140
Asset/Event Number	101
Asset/Event Name	Fairburn
Type of Asset/Event	Garden and Designed Landscape
Date and/or Period	Post-medieval
Listing No./NRHE Number	GDL00174
HER Number	N/A
Status	Inventory Garden and Designed Landscape
Section:	N/A
Easting	246349
Northing	852719
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description

https://portal.historicenvironment.scot/designation/GDL00174
Dating from the late 18th / early 19th century, the designed landscape consists of gardens, woodland and architectural features, and together makes an impressive impact on the local scenery. Fairburn is famous for its trees, especially conifers planted by John Stirling in the 1870s.

*Minor corrections to Inventory record in 2024. The inventory site as a whole has not been reviewed.

Artistic Interest Level of interest: Little
The designed landscape at Fairburn has a little value as a Work of Art.

Historical Level of interest: Some
Fairburn has some Historical value although there is limited evidence of its development.

Horticultural Level of interest: Outstanding
The range and size of the conifers in the woodland garden provide Fairburn House with outstanding Horticultural value.

Architectural Level of interest: High
The policies are of high Architectural value as they provide the setting to buildings recognised for their special architectural or historic interest.

Archaeological Level of interest: Not Assessed
Scenic Level of interest: Outstanding
The woodland canopy and open parkland of the designed landscape make an outstanding contribution to the surrounding scenery.

Nature Conservation Level of interest: Little
The woodland flora provides a little Nature Conservation interest.

Location and Setting
Fairburn House is situated about 6 miles (9.5km) north-west of Muir of Ord. The policies lie along the south side of Strathconon. To the north they run down to the River Conon, and to the south, to a tributary river of the Conon called the Orrin. Upland scenery dominates the landscape to the west and south where the hills lead up to Beinn an Rubha Riabhaich and the Cabaan Forest. To the north the land slopes to the Conon valley and is farmed, mainly with grazing livestock. The soil is mostly boulder clay and some sandy gravel on the low ground with peat soils in areas of poor drainage. The climate is mild and the annual rainfall is about 35" (890mm). There are extensive views north across Strathconon to Ben Wyvis 3,233' (1,060m). The mature woodland canopy and the open pasture of the park are significant in the wider landscape especially from the valley.

Fairburn House lies within 2,000 acres (445ha) of designed landscape. Documentary evidence of the designed landscape is provided by General Roy's map of c.1750, the 1st edition OS map of c.1860 and the 2nd edition OS map of c.1910. They show that the original designed landscape was extended considerably to the west and south between 1750-1850. Embellishments were made in the 1870s and the policies were further extended to the east when the driveway was extended from Muirton Lodge to the Marybank/Aultgowrie road.

Site History
The present designed landscape was established in the late 18th/early 19th century. It was redesigned and extended in the late 19th century by John Stirling when the house was rebuilt. There are no known designers.

The name of Fairburn was taken from a 16th century tower house, built as a Mackenzie stronghold (Fairburn Tower, (LB14030)). It stands to the south-east of the present Fairburn House. In around 1800, the Mackenzies built Muirton House, which was later demolished by a subsequent owner - John Stirling (1820-1907). John Stirling bought the estate in c.1872. Following the demolition of Muirton House, he commissioned the building of the present Fairburn House on the same site between 1877-78.

In the surrounding grounds, John Stirling made a fine woodland garden and planted many exotic species. He also extended the east drive and established the beech hedge and woodland which flanks it today. His son inherited in 1908. The house was used as a convalescent home during World War I and foreign servicemen on leave were welcomed into the Stirlings' home during World War II. Sir John Stirling KT handed the estate over to his son as a wedding present in 1963. Sir John remained as tenant of Fairburn House until his death in 1975. The house was let for a short period thereafter but was sold, with some 80 acres of ground, in 1982. It was subsequently used as a private nursing home.

Landscape Components
Architectural Features
Fairburn House (LB14031) was designed by Wardrop & Reid between 1877-78 and built in the Scottish Baronial style in Tarradale stone. Fairburn Tower (LB14030) is a 16th century tower house, with early 17th century additions. It stands on a hilltop ridge overlooking the Strathconon and Orri valleys. It was restored in 2020-22. Aultgowrie Lodge (LB14032) stands on the south drive on the River Orrin and was also designed by Wardrop & Reid in 1877. The stable-block is also by Wardrop & Reid; it has been converted into homes for the staff in the nursing home. The curling pond, built in 1886, still has its original stones and the necessary facilities required, including floodlights. An ice house, situated near the Curling Pond, is now overgrown. The walled garden and ancillary buildings were built c.1880. Other buildings and estate offices include a Fire Station, Gardener's Cottage, Butler's Cottage, two kennels and a sawmill. The family burial ground is enclosed by iron railings and is situated to the north of the south drive near Aultgowrie Lodge.

Parkland
The parkland extends to the north and east of the house. Much of the wider landscape was improved during the early part of the 19th century when the shelterbelt strips were planted and the land drained. At this time, these outlying areas of parkland belonged to Lord Seaforth of Brahan. They were acquired by John Stirling c.1873. There are one or two specimen trees remaining in the inner parkland including some oak and beech. A plantation of Scots pine, established c.1800 by the Mackenzies, accents the rising hill to the east. Hardwood clumps in the parkland were established by John Stirling, partly for amenity and partly as pheasant cover. Over the past decade, these have gradually been replanted.

Woodland
Fairburn is famous for its trees and, in particular, for conifers planted by John Stirling in the 1870s. Many are planted around the house and along the Orrin (South) Drive and these will be described under the woodland garden. The policy woodlands extend to the west of the house and were originally planted c.1800. The outlying mature and semi-mature commercial woodlands on the higher ground were felled in World War I and II. Sections of the policy woodlands were replanted in 1920 mainly with Scots pine but the majority of the woodlands were not planted until after World War II under a Forestry Commission Dedication Scheme, with Scots pine and Sitka spruce, although there are some small pockets of oak, ash and beech.

Woodland Garden
The woodland garden extends from the house southwards around the kitchen garden and along the Orrin Drive. The exotic specimen trees were mainly planted by John Stirling. Although the majority of the trees are amenity planting, some have always been considered as a commercial crop. There is a planting list dated 1872 and many of the larger specimens can be identified. Alan Mitchell measured 120 trees in 1982; 60 were over 100 ft high and 10 over 150 ft high. The tallest is a grand fir (Abies grandis) over 185 ft high. Some of the finest trees grow around the burial ground; in particular some tall grand firs, a Calocedrus decurrens, a 175 ft tall Pseudotsuga menziesii, and a large Wellingtonia (Sequoiadendron giganteum). A small pinetum was planted along the drive and includes many interesting Chamaecyparis varieties including a large Chamaecyparis nootkatensis 'Pendula'. The pinetum is underplanted with species rhododendrons. Other specimen trees were planted in the old garden and along the drive. The garden extends to the river and alongside the spectacular Orrin Falls.

The Gardens
The formal gardens around the house are partly evident, with overgrown hedges, grass terraces and paths indicating the original design (1987). On the west side of the house, a path, lined with yew trees, leads to the site of a rock garden which was laid out by the grandmother of Mr Stirling. There are several interesting trees including one enormous Picea sitchensis planted in 1874 which has a large skirt reaching down to the ground, and three large Monkey puzzles. Double white Narcissus and pheasant eye are established in the understorey in large numbers.

Walled Gardens
The walled garden was laid out by John Stirling c.1874. It extends over some one and a half acres. Soil was imported from neighbouring areas and a deep drainage system was installed. Lean-to glasshouses, with a central conservatory, lined an inner face of the north wall. Under this glass, fruit and flowers were grown, whilst pot plants were grown in the conservatory.

A rose garden was sited adjacent to the conservatory, covering approximately a quarter of an acre. A Caithness stone path led to a large stone font in the centre. The rose garden was removed in 1976. Vegetable plots lay beyond the rose garden. They were enclosed by a row of apple trees, then a border in which grew Primulas, irises and daffodils. Around this border was a gravel path with a box hedge. Between the path and the wall was a perimeter bed filled with flowers for cutting, bedding plants, vegetables and soft fruit.

Outside the west wall of the garden was an orchard which extended over an acre. Outside the south wall was an area of more fruit and flower production. Beyond the east wall an area was set aside in the later 20th century as the 'Children's Gardens.'

Before World War II some lilies, Meconopsis and flowers for cutting were grown commercially. After the war, production was considerably increased including tomatoes, carnations, lettuce, soft fruit, vegetables and cut flowers. Lady Stirling raised daffodils acquired from Brodie Castle which she sent to Covent Garden for sale. Production at this level ceased in 1971 and, following Sir John's death in 1975, the garden was leased to Highland Liliums.

References
Sales Particulars, June 1982
A. Mitchell, Tree Survey, 1982
NMRS, Photographs

Asset/Event Number	102
Asset/Event Name	The Spa Gardens, Strathpeffer
Type of Asset/Event	Garden and Designed Landscape
Date and/or Period	19th century
Listing No./NRHE Number	GDL00370
HER Number	N/A
Status	Inventory Garden and Designed Landscape
Section:	N/A
Easting	248366
Northing	858024
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description

https://portal.historicenvironment.scot/designation/GDL00370
Strathpeffer Spa Gardens comprise an unusual example of pleasure grounds laid out as part of a 19th century health resort. They illustrate a contemporary acknowledgement of the important curative role of landscape and gentle recreation.

Type of Site: Picturesque pleasure grounds and ornamental walks, part of a Spa development.
Main Phases of Landscape Development: Mid 19th century – mid 20th century.
Artistic Interest Level of interest: High: The design of the picturesque pleasure grounds skillfully integrates a variety of amenity requirements on a comparatively small site. Its picturesque character is significant in the Strathpeffer townscape and essential to the locality.
Historical Level of interest: High: The gardens are an important aspect of the development of Strathpeffer Spa as a premier health resort. They are interesting for their associated social and economic history, and constitute an unusual example of a specific type of pleasure grounds.
Horticultural Level of interest: High: The collection of exotic specimen trees gives this site high Horticultural value.
Architectural Level of interest: High: The Spa Gardens are a prominent feature in the Strathpeffer townscape and are integral to the picturesque landscape character of the town.
Scenic Level of interest: High: The Spa Gardens have high Scenic value due to their important contribution to the townscape, as well as the overall landscape character of Strath Peffer itself.
Nature Conservation Level of interest: Some: The Spa Gardens provide a variety of wildlife habitats, particularly birds. This gives the site some Nature Conservation value.

Location and Setting
The Spa Gardens are in the centre of Strathpeffer, on the south side of the A834. They are laid out on a north-facing hillside and bounded to the south by the fields of Park Farm. The Peffer enters the gardens from the west and runs eastwards, parallel to the A834, through the north part of the gardens.

Views out from the gardens extend into the town. The gardens are an important component of the Strathpeffer townscape.

The gardens expanded eastwards to accommodate new bowling greens in 1904. They have retained the same boundaries since that time and measure c 2.2ha (5 acres).

Site History
Strathpeffer belonged to the Cromartie Estate (see Castle Leod; Tarbat House; Cromarty House). The value of 'Castle Leod Waters', as the mineral springs were then known, was recounted to the Royal Society in London in 1772. Thereafter, in 1777, Colin Mackenzie, factor to Cromartie Estate, suggested to the Board of Commissioners for the Forfeited Estates the value in building a house nearby to attract visitors. The wells were enclosed to prevent cattle fouling them, but his suggestion came to nothing. It was in 1819 that a wooden Pump Room was constructed, over one of the wells. The work was supervised by Dr Morrison, who moved from Aberdeenshire to Strathpeffer after being cured of chronic rheumatism by the sulphurous waters (Fortescue-Fox, 1896).

Thereafter, the reputation of the Spa grew. Dr Morrison, who recommended a stay of six weeks and three to four tumblerfuls of spa water both morning and afternoon, strictly supervised visitors' diets. By the mid 1800s, the Cromartie Estate again turned its attention to the potential attractions of the waters, which were 'so beastly as to prove there must be some virtue/reality in it' (Andrew Scott, the factor in 1857 quoted in Landscape Conservation Studio, 1996). The 1850s saw plans for the building of a harled Poor's House and a stone house over the Upper Well, wooden bridges over the burn and gravelled walks through the adjacent plantations – gentle exercise being part of the regime. By this time there were three wells, the Upper Well being within the gardens. The walks were constructed in 1853 at a cost of 13/4d per linear yard and the plantation was enclosed with a wire fence.

The 1860s saw the promotion of the Spa in earnest. The impetus came from George Granville Sutherland-Leveson-Gower (1828-92), created 3rd Duke of Sutherland in 1861. The Spa was the catalyst for the development of the settlement at Strathpeffer and the landscape of the Strath itself. This was then serviced by the main Dingwall-Strome Ferry railway line opened in 1869 (Close-Brookes, 1995). The estate commissioned the architect George Devey to plan the proposed expansion but, although the layout of the roads relate to his proposals, his full scheme was not adopted. Altogether, the Duke spent about £2,500 in capital to lay out a new Pump Room (which replaced the original wooden one) and Bath House, a Well-Keeper's House, shops, post office and Postmaster's house. By 1876 the Pump Room (demolished 1950) was complemented by a latrine block, screened by shrub planting (1876, OS 6").

The 1880s saw the further expansion of activities and facilities. Renewed impetus was given to the Spa with the arrival of the Dingwall-Strathpeffer branch line of the railway (1885), new Ladies Baths and experimental peat baths. Explorations for new springs in the shale strata resulted in new wells in 1884 and 1886, which increased the volume of sulphurous waters from 279 gallons (1867) to 1482 (1886). A fourth well, named Lady Cromartie's Well or the Challis Spring, was exploited in 1889. Strathpeffer Spa Pavilion, designed by William Joass, was built 1879-81. It was designed to be the social focus of the Spa, as opposed to the medical and curative centre at the Upper Pump Room. It provided a refreshment room, tearoom, billiard table and games room. The central concert hall was overlooked by a gallery, which housed a reading room, and the whole building was surrounded by a covered verandah. An octagonal Bandstand (removed when the main road frontage was fenced in, c 1908), stood at the entrance to the complex, in view of the town centre.

From early on in the planning and promotion of the Spa, the pleasure grounds and drives were recognised as important aspects of the town's promotion. John Martin, assistant factor, renewed the plantations in 1864 by interplanting many evergreens in the belts and transplanting trees from a plantation along the public road, to form an approach. The walks were planted and path junctions were highlighted with 'clumps of evergreens with a spiral or weeper plant in the middle to relieve the mass' (SRO, GD305/2/1858 p.39).

In 1867, William Gunn of Nutwood, successor to Andrew Scott, wrote about 'the constant brushing up during the Season required by the Spa Beltings and Sundry plots of fancy plantation, together with the gravelling & Keeping in order of all the public roads & walks around the Spa …'. The Spa Gardens were considered integral with the Spa itself. Gunn recalled in 1889 that the Strathpeffer estate had been 'exceedingly bare of Wood, and with no Hedges' when he had started in post. He was responsible for extensive planting and woodland improvement throughout Strath Peffer as far as Castle Leod. A major feature was a walk made in 1888 for visitors to reach the summit of Ord Hill and admire the views. In 1898-1900, a pleasure drive was made through Blackmuir Wood, a 93ha (230 acres) pinewood planted c 1820, by way of the Knockfarrell vitrified Fort. Other walks, furnished with rustic rain-shelters, were laid out through the Kinettas Plantation, Ord Hill.

A tennis/croquet terrace behind the Pavilion (1882) provided recreation within the gardens. A four-rink curling pond (1890) was followed, in 1904, by a Bowling Green incorporated into an eastward extension to the gardens. These facilities all necessitated terracing the hillside with stone-retaining walls.

In 1908 the Spa Syndicate Limited acquired the rights to the Spa wells. The Spa facilities were run on more commercial lines, thus the gardens were enclosed and an entrance fee charged. Park Farm Road, which led through the middle of the gardens, from north to south, was removed, and the garden paths adjusted to accommodate this and further changes. Summer entertainments were important to the venture, so the Curling Rink was converted into tennis courts and curling moved to the Jubilee Pond. A major change in 1909 was replacing the 1870s Pump Room with the present Upper Pump Room.

Thereafter, from 1914 to 1949, there were few changes in the gardens. A leaflet of c 1925 describes the:
'spacious pleasure gardens, charmingly laid out with lawns, pergolas of roses, parterres of flowers, noble trees and dainty summer houses, while a picturesque note is supplied by a

little burn which wimples over falls or broadens into little lakes…' (Landscape Conservation Studio, 1996).
In 1949 the gardens were sold to the owner of the Ben Wyvis Hotel. Subsequently, the Spa manager's house was demolished, the fountain pool infilled and the tennis court area redeveloped for curling. Management of the gardens was abandoned due to costs, in 1970. The Highland Council now owns the gardens.

Landscape Components
Architectural Features
The Spa Pavilion, designed by Joass in 1879, was subsequently altered and extended. It is harled with applied timber framing. A large multi pane lunette-window fills the north gable facing the town square. The slate roof has a ridge skylight and the eaves are coved and barge-boarded. A continuous, originally fully open verandah supported by timber columns, skirts the building. The verandah also has a slate roof and dogtooth eaves decoration.

The Pump Room, (originally known as the Upper Pump Room) built in 1909, is constructed of rubble masonry with dressed quoins and margins. It has a complex slate roof and a verandah on its north-eastern elevation. Other architectural features within the gardens include retaining walls, steps and ramps associated with the garden terraces and the Band House and a number of small pavilions associated with recreational facilities.

Paths & Walks
The main entrance from the public road leads into a yard between the Upper Pump Room and the Pavilion. From here, a drive leads between two Wellingtonias, to climb uphill to the Curling Rink terrace, the Band House and the rear of the Pavilion. A network of informal footpaths leads through the gardens at different levels along the hillside. Ramps and steps link the terraces. Footpaths were originally gravel surfaced, and boulder-edgings survive in certain locations. Although benches and small summerhouses once located along the path network have not survived, seating recesses still remain.

Woodland Garden
The gardens are essentially wooded pleasure grounds. Some notable specimen conifers remain, including Wellingtonias, deodar cedars, Douglas and noble firs planted c 1870-80. The earliest surviving planting is from c 1850 and includes some large deciduous specimens, notably beech, oak and sycamore. Later plantings included lime, horse chestnut, Norway maple, copper beech, poplar and many Lawson cypress. Laurel and Rhododendron are surviving shrubs, although there is some snowberry and remnants of more recent shrub planting, including cornus, fuschia and lilac. Patches of herbaceous and groundcover plants are found, but in general the garden has suffered from overshading, waterlogging and the regeneration of invasive species. Early 20th century photographs illustrate the then extent of open lawn in the grounds, which enabled a more open aspect. The terraced areas for recreation are important within the garden design. The site of the Curling Rink, redeveloped as a concrete platform (1960) remains intact. It occupies one of the hillside terraces retained by dry-stone walls and with bench recesses overlooking the rink. Behind the Pavilion is another terrace, previously used for croquet, bowls, tennis and putting. The large Bowling Green to the east of the Pavilion is still in use.

References
1876 survey, 1st edition OS 1:10560 (6"), published 1881
1904 survey, 2nd edition OS 1:2500 (25"), published 1906
Scottish Record Office: RHP 45180; RHP 34705
Close-Brookes, J. Exploring Scotland's Heritage The Highlands (1995), pp.22-3
Fortescue-Fox, R. Strathpeffer Spa, Its Water and Climate (1896)
Historic Scotland on Behalf of the Scottish Ministers, The List of Buildings of Special Architectural or Historic Interest
Landscape Conservation Studio. The Spa Gardens, Strathpeffer. Report to The Highland Council (September 1996)
Old Statistical Account, Statistical Account of the Parish of Fodderty, vol. 7, (1793), p.410

Asset/Event Number 103

Asset/Event Name	Battle of Carbisdale
Type of Asset/Event	Battlefield
Date and/or Period	1650
Listing No./NRHE Number	BTL19
HER Number	Various
Status	Inventory Battlefield
Section:	N/A
Easting	257307
Northing	894431
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/BTL19 Overview and Statement of Significance Carbisdale is significant as the last battle of James Graham, the 1st Marquis of Montrose, in support of the Royalist cause. Widely thought to be one of Scotland's finest ever military commanders, Montrose is a highly significant figure within Scottish history. After Carbisdale, he was finally apprehended by the Covenanters and unceremoniously executed. Carbisdale also marks the end of the internal struggles within Scotland as part of the Wars of the Three Kingdoms, as with the Covenanters' subsequent agreement with Charles II, they come into open conflict with Oliver Cromwell and the Protectorate, rather than Royalist supporters in their own lands. Following his defeat at Philiphaugh in 1645, Montrose had fled abroad, only to return in 1650 as the Captain-General of the forces of Charles II. The battle was a decisive victory for the Covenanter forces arrayed against Montrose, with his forces routed almost without firing a shot. Montrose himself escaped the field but he was handed over to the Covenanters a few days later and taken to Edinburgh for his trial and subsequent execution. Inventory Boundary The Inventory boundary defines the area in which the main events of the battle are considered to have taken place (landscape context) and where associated physical remains and archaeological evidence occur or may be expected (specific qualities). The landscape context is described under battlefield landscape: it encompasses areas of fighting, key movements of troops across the landscape and other important locations, such as the positions of camps or vantage points. Although the landscape has changed since the time of the battle, key characteristics of the terrain at the time of the battle can normally still be identified, enabling events to be more fully understood and interpreted in their landscape context. Specific qualities are described under physical remains and potential: these include landscape features that played a significant role in the battle, other physical remains, such as enclosures or built structures, and areas of known or potential archaeological evidence. The Inventory boundary for the Battle of Carbisdale is defined on the accompanying map and includes the following areas: The low passage between the river and the high ground to the north of the area along which Montrose entered onto the flood plain from the north. This also takes in the craggy peak which accommodates Carbisdale Castle and the southern portion of the craggy ground known as Creag a' Choineachan, which has been translated as Lamentation Hill, a place name which may be related to the battle. The eastern side of the area runs along the western bank of the river, in which numbers of troops are reported to have drowned during the rout. The southern limit of the area takes in the pass of low ground along which Strachan's men advanced, continuing to the south of Balinoe. It also takes in the higher ground to the west

which may have provided a less obvious line of advance for at least some of his men. The western limit of the area takes in the slope which bounds the western edge of the flood plain and accommodates the area of woodland to the north-west into which Montrose's men fled. The boundary joins with the northern boundary at the eastern end of the lochan from which the Culrain Burn flows.

Historical Background

Following the execution of Charles I in 1649, his son Charles II became the leader of the Royalist cause. In 1650, he appointed James Graham, the Marquis of Montrose to be Lieutenant ' Governor of Scotland and Captain ' General of the Crown's forces. Montrose's first task was to gain support for an invasion from the other crowned heads of Europe, but he only had limited success in this area.

Undeterred by this, in March 1650 Montrose headed to Orkney, where he took command of a force of Danish troops who had been deployed there since the previous September, along with local levies raised from the islands, giving him a total force of at most around 1500 men. Montrose and his army crossed to the mainland at John O' Groats on 12 April, possibly after sending a vanguard of around 500 men to secure the landing. Once on the mainland, Montrose moved swiftly, besieging and taking Dunbeath Castle and within six days Montrose had advanced as far as Strathoykel in Sutherland. He subsequently moved south to Carbisdale where he made camp and awaited reinforcements, although none were forthcoming.

As Montrose waited, he would once more be let down by the inadequate scouting and poor intelligence which were so characteristic of many of his battles, and he failed to determine the presence nearby of a Covenanter force under the command of Colonel Archibald Strachan. Strachan, upon learning of Montrose's position, quickly advanced upon Ferne, a mile and a half from Montrose's camp, with his own force of around 200 cavalry, along with a small troop of around 30 musketeers and about 400 infantry from local levies of the Monro and Ross clans (although sources indicate these levies may not have been wholly committed or even sympathetic to Strachan's cause).

Once the Covenanter's had reached Ferne, Strachan's scout, Captain Andrew Monro, reported back that Montrose had deployed 40 horse on patrol and suggested Strachan send a small force forward while keeping the remainder hidden, in an attempt to draw Montrose to battle and set an ambush. As some evidence suggests Montrose had his forces within a fortified camp in a strong position, it would seem that Strachan wished to draw him out into the open rather than risk assaulting his defences.

Whether or not Montrose's camp was well defended, the ruse by Strachan appears to have worked, with Montrose deploying a vanguard to the field under Sir John Hurry and taking command of the remainder of the army himself. When the remainder of the Covenanter force sprang their ambush and began advancing on Montrose, he appears to have attempted an orderly withdrawal towards the wooded and rocky slopes at his rear, which would have been ill-suited to Strachan's cavalry. Seeing this, Strachan attacked with around 200 of his cavalry, overtaking the Royalists just as they reached the woods and turning the retreat into a rout. Montrose's Danish troops appear to have been the only elements of his force to play any part in the fighting, managing to fire a single volley of musket fire before they too were driven off. While Montrose himself escaped with a few others, the remainder of his force was not so lucky. The pursuit of his army was a brutal affair and the slaughter in the wood continued for another two hours, with around 200 Royalists drowned while trying to cross the Kyle of Sutherland in a desperate bid to escape the massacre and another 400 captured.

The Armies

The Royalist forces were commanded by James Graham, the Marquis of Montrose, and the government forces by Colonel Archibald Strachan. Sallagh's account is alone in assigning joint command of the Covenanters to Strachan and Hackett (Sallagh 1813).

Numbers

Royalists: Sallagh does not give numbers for Montrose's forces (Sallagh 1813). Balfour quotes Royalist prisoners as saying they had 1200 men (Balfour 1825). Gardiner claims that

Montrose had 1200 foot and 40 horse (Gardiner 1903). Reid uses the same figures adding, that some of the foot were Danish mercenaries but most of them Orcadians (Reid 1990). Cowan states that the charters of Kirkwall show that the town supplied 60 fully armed men, and 800 from the rest of Orkney travelled south. He believes the force could barely have exceeded 1600 and adds that the slowness of the march south was dictated by the speed of transporting cannon (Cowan 1977). No mention is made of Royalist artillery in other sources. Williams says the original expeditionary force numbered 1500, of whom nearly 1000 were Orcadians (Williams 2001). Roberts says he had 1600 men at most with hardly any cavalry (Roberts 2000).

Covenanters: Sallagh says that the Covenanters had five troops of cavalry; Strachan's, Montgomerie's, Cullace's Irish troop, Ker's and Hackett's, plus Monro and Ross foot 'not passing four hundreth' (Sallagh 1813). Balfour has the same five troops, which he numbers as 230 horse, and also mentions 36 musketeers of Lawers' regiment and 80 Ross foot (Balfour 1825). Williams gives the same composition for the cavalry, but calculates the number of horse at 256, and the number of musketeers at 36. He emphasises that Strachan's forces were experienced, well mounted and under competent officers. They were also joined by 400 Rosses and Monros, who may have been on their way to join Montrose but decided to throw in their lot with the government forces when they encountered them. Strachan did not mention this large force in his despatch following the battle (Williams 2001).

Reid differs significantly, saying that Strachan had only three troops of cavalry; Colonel Gilbert Carr's two troops of cavalry under his personal command, and a third troop under Lieutenant Colonel Robert Hackett. In addition he had 36 musketeers of Campbell of Lawers' regiment under Captain Collace, and a force of 400 local levies (Reid 1990). Cowan gives the same composition, specifying that the 400 were Monros and Rosses (Cowan 1977). Roberts says Strachan had 200 cavalry but does not give the make-up of this number. He also has 36 musketeers and 400 levies raised by the Monros. He comments that it is believed that the Monros waited to see the likely outcome of any fighting before declaring their allegiance (Roberts 2000). Gardiner records that Strachan had 220 horse and 30 musketeers 'to say nothing of 400 Rosses and Monros upon whom no dependence could be placed.' (Gardiner 1903).

Losses
Sallagh gives no total figure for Royalists killed, but says 200 were drowned, 400 were taken, and only a few escaped. The only Covenanter casualty was one trooper drowned in pursuing the Orcadians who were trying to escape by swimming the Kyle (Sallagh 1813).

Balfour on Royalist losses says ten of their best commanders were killed and most of their officers and 386 common soldiers taken. He says only 100 were not killed, drowned or captured from a total of 1200. The only Covenanter casualties were the drowned trooper and two wounded. He also lists the Royalist officers killed and captured (Balfour 1825).

Other, secondary, sources say that 400 Royalist troops were killed, and another 450 were captured, while 200 Orcadians drowned, trying to swim the Kyle (Cowan 1977; Roberts 2000). Two other sources put the number of killed at 450, and the captured at 400 in addition to the 200 drowned (Stevenson 1977; Williams 2001). There is no advance in these sources on the one dead Covenanter.

Action
Although the sources differ on whether Montrose was on the march or encamped, and on the precise sequence of events, they all agree, other than Balfour, that Montrose was successfully ambushed by Strachan, in part at least, because his scouting and intelligence was poor, as it had been many times in the past. His army was shattered and he fled, only to be handed over to the Covenanters a few days later.

Balfour, a contemporary source, says that Strachan, on learning that Montrose was marching to Carbisdale, divided his forces into three parties; the first of 100 horse led by himself, a second of more than 80 horse led by Lieutenant Colonel Hackett and a third of about 40 horse led by Captain Hutcheson along with 36 musketeers of Lawers' regiment to

be led by Quartermaster Shaw. After prayers they marched at about 3pm towards the enemy who were drawn up near a hill of 'Scrogie Wood' to which they quickly retired. Strachan pursued them into the wood and at the first charge 'made them all to rune'. Two Ross officers joined in with 80 foot and gave good service (Balfour 1825).

According to Sallagh, another contemporary source, the Covenanters marched to Ferne, where they hid in the broom a mile and a half from the Royalists. Their scout, Captain Andrew Monro, reported that Montrose had sent out 40 horse on patrol and he suggested that Strachan send out one troop to be seen and keep the rest hidden so that Montrose would not realise the size of their force. Upon getting this information Montrose put Hurry in charge of the vanguard and took command of the remainder. He then ordered a retreat to 'a wood and craggie mountain which was not far distant'. Strachan and Cullace then attacked with a vanguard of 200 horse, with Hackett and the rest close behind, trying to prevent the Royalists reaching the wood and the craggy rocks. Strachan overtook the Royalists just as they were entering the woods. The Danish mercenaries stood and delivered a volley which did very little harm, then began to flee to the woods, but were intercepted by Hackett's force and entirely dispersed. The Monro and Ross foot entered the wood and the killing went on for two hours. Two hundred Royalists were drowned while trying to escape across the river and about 400 prisoners were taken, although Montrose and a few others escaped (Sallagh 1813).

Gardiner gives a shorter but similar account, but also points out the difference between Sallagh's view that Montrose was at Carbisdale for some days, and Balfour's, who claims Montrose only arrived there on the day of the battle. Gardiner is inclined to believe Balfour, whose account is based on a despatch, believed to be Strachan's (Gardiner 1903).

Cowan also takes this line, arguing that, although Sallagh's account states that Montrose camped for some days at Carbisdale, a newspaper, 'The True Relation', probably based upon Strachan's own report of the battle, says the Royalists had marched from Strathoykel to Carbisdale. He believes that this is more likely, as if Montrose had been camped he would have had entrenchments which would have allowed him to mount a stronger resistance to Strachan's attack. He thinks it likely that Montrose was fording the Oykel, just west of the point where it is joined by the Cassley, to march along the south bank of the river. He says that Strachan exposed only 100 horse, since the Covenanters seem to have known that Montrose was already aware of the presence of only one troop of horse in the area; possibly Montrose was betrayed or misled by his own Monro scouts. The hundred charged Lisle's forty Royalist horse, whilst the Royalist foot retreated to the woods, but the Royalist cavalry broke, pushing back against their own infantry. Hurry in the centre tried to make a stand but only the Danish mercenaries attempted a volley. Local tradition has it that before the fighting the Monros and Rosses advanced up Strathcarron to shelter behind the ridge of Feith Tharsuinn to await the outcome of the battle and then joined in once they saw the way it was going (Cowan 1977).

Roberts' account (2000) is similar and he too believes that Montrose was on the move. He adds that Strachan, advancing north from Tain, learnt on the afternoon of Saturday 27 April that Montrose was moving south and advanced quickly to engage because he did not want to fight on the Sabbath. Stevenson (1977) also believes that Montrose was on the move.

Williams, however, like Sallagh, takes the view the Montrose was encamped. 'With the hills to the north and the Kyle estuary to the east, the burn enclosed a triangle of level ground admirably suited to cavalry. At the northern point of this triangle was Carbisdale Loch, and, beyond, a narrow defile overhung by Creag a' Choineachan. Here, in the jaws of the pass was Montrose's camp. His left flank rested on the Kyle. His right and rear were protected by the hills and on the bluff facing south-east towards the open ground the Royalists had thrown up a formidable breastwork. The position was a strong one and could not be taken by cavalry in a frontal assault.' Strachan realised he had to tempt Montrose out, so sent out the single troop of horse which he knew Montrose was aware of, to act as a decoy. Williams then has Montrose ordering Lisle to halt his horse and advancing with his main army towards the Covenanter cavalry, rather than retreating to the woods. Once Montrose was committed in the open Strachan charged with the cavalry concealed in the broom followed by Hackett with 80 dragoons. The Royalist horse was driven back on to the foot and a

number of the gentlemen who made up the cavalry were killed. The Orcadians panicked and fled, and although the Danish mercenaries stood and fired a volley they were soon overwhelmed. At this point the Monros and Rosses, who had previously detached and taken up position in the lea of the hills flanking Carbisdale to see what would happen, fell upon the fleeing and defeated Royalists (Williams 2001).

Aftermath & Consequences
Montrose escaped from the battlefield with a few companions and after wandering for several days reached Assynt. According to Sallagh, he was discovered, together with a Major Sinclair, by a patrol sent out by Neil MacLeod, Laird of Assynt, in response to a letter from Andrew Monro, Strachan's scout. He was brought to Ardvreck Castle and handed over to Major-General Holbourne (later to command the Scottish infantry at the Battle of Inverkeithing in 1651). Other versions differ slightly, in having Montrose seeking food and shelter and being taken to MacLeod, who handed him over to the Covenanters in return for the reward which had been put on Montrose's head in 1644 (Williams 2001). Whether or not this constituted a 'betrayal' as Royalist literature alleged, the result was the same. On 21 May in Edinburgh, Montrose was executed by hanging.

Montrose remained loyal to Charles until his death; unfortunately his loyalty was not reciprocated. On 12 April it was reported that Charles had all but agreed terms in the negotiations with the Covenanters which had started again in mid-March although on 26 April it seems Charles was still trying to prolong negotiations to allow Montrose time to make progress with his invasion. On May 1, apparently without any knowledge of the battle or its outcome, Charles accepted the terms offered the previous year in what both he and the Covenanters recognised to be a hollow agreement, and he later signed the Solemn League and Covenant on 23 June. Shortly after this, the Covenanters invaded England on his behalf. On 3 May Charles sent Montrose orders to disband without having any idea what his situation was and he later denied any involvement in the invasion. '...there is every indication that he abandoned Montrose with the same cynicism which allowed him to accept the solemn league' (Cowan 1977). Essentially, the outcome of the battle which cost the life of Montrose and hundreds of men was politically irrelevant.

Events & Participants
Although the battle itself could be regarded as a fairly minor event with no more than 2000 men on the field, it is notable as the last action in which the by then legendary Montrose was engaged. He escaped the field but was captured within a couple of days and held in Ardvreck Castle, after which he was tried and executed for treason in Edinburgh. Charles II is generally held to have behaved in a somewhat duplicitous fashion with regard to Montrose, encouraging him to lead an invasion into Scotland against the Covenanters, while also negotiating with them for his return as King of Scotland. Even at the end of it all, Charles did nothing to save Montrose from execution.

James Graham was the fifth Earl of Montrose and the first Marquis of Montrose. He was the chief of Clan Graham. Montrose had been a supporter and signatory of the National Covenant in 1638, but had then become a Royalist, although he was driven by motives other than a desire to impose the Divine Right of Kings upon Scotland. He and Archibald Campbell, the eighth Earl of Argyll, were bitter rivals, and Montrose believed that the Covenant had become nothing more than a vehicle for Argyll's ambition. Always a moderate among the Covenanters, Montrose considered that the agreement in 1641 with Charles that had removed episcopacy from Scotland had fulfilled the demands of the Covenant and that to continue in opposition to him would be breaking that agreement. Following the signing of the Solemn League and Covenant in September 1643, Montrose presented himself to Charles I service at his headquarters in Oxford. On behalf of the King, he then fought a campaign intended to draw Covenanter forces away from supporting the Parliamentarians in England, and in this it was a success. Montrose fought a series of seven battles against Covenanter armies across the Highlands in 1644 and 1645, beginning with Tippermuir and ending at Philiphaugh, where he suffered his only defeat He attempted to do the same on behalf of Charles II in 1650, but on this occasion fought only a single battle at Carbisdale. After his defeat there, he was captured and brought to Edinburgh for trial. On 21 May 1650, he was hanged and then beheaded. His head was fixed to a spike on Edinburgh's Tollbooth, his body quartered, and his limbs were displayed in Stirling, Glasgow, Perth and Aberdeen.

Following the Restoration of Charles II as king in 1660, Montrose's remains were collected together once more and were interred in the High Kirk of St Giles in Edinburgh in May 1661.

Sir John Hurry was in command of Montrose's vanguard in the battle. Hurry had fought in Germany as a young man before returning to Scotland. He had a chequered career, switching sides repeatedly. He first came to prominence in the so-called 'Incident' when Royalists plotted to kidnap the Marquis of Argyll, the Marquis of Hamilton and the Earl of Lanark, who were the leading Covenanter nobles; Hurry betrayed the plot to the Covenanters and joined the Covenanter cause. He fought for the Parliamentarians at Edgehill and Brentford before switching sides to the Royalists for whom he fought at the Battle of Chalgrove Field and at Marston Moor. He switched sides again, and it was as a Covenanter that he led the army sent to bring down Montrose in the Spring of 1645 that was utterly defeated at Auldearn. After losing at Auldearn to Montrose, he drifted back into the Royalist cause, joining the Engagers; this was a faction of Covenanters who signed an agreement with Charles I in 1647 to fight for him against the English Parliamentarians. He was one of the few Covenanter officers to join the Duke of Hamilton's expedition into England and was captured at the Battle of Preston in 1648. He escaped to the Continent, where he fell in with Montrose, and accompanied him on his last adventures; like Montrose, it ended in his execution in Edinburgh, on 29 May 1650.

Archibald Strachan, commander of the Covenanter forces at Carbisdale, is little remembered today but had an eventful career as a dragoon officer during the Wars of the Three Kingdoms. Born in Musselburgh, he fought on the Parliamentarian side at the Battle of Lansdown, outside Bath, in July 1643, after which he was promoted to major. By 1645 he had returned to Scotland and joined the Covenanter army and was noted for his religious conviction. In 1649 he was promoted to the rank of Lieutenant-Colonel in Ker's Regiment. He distrusted Charles II in his dealings with the Covenanters but fought well at the second Battle of Dunbar against Cromwell in 1650; it was his regiment on the Scots' right flank halted Lambert's initial cavalry charge. He was a member of the Remonstrant party that after Dunbar pledged neutrality in the war against Cromwell until or unless Charles repented and genuinely embraced the Covenant. Strachan himself went even further and defected to Cromwell with a small group of men. He was excommunicated from the Kirk for this in January 1651. He died in November 1652.

Context
In 1638 the National Covenant was signed by many in Scotland, pledging opposition to the reforms proposed by Charles I, the King of the two separate nations of England and Scotland. Amongst other proposals Charles wanted to replace the democratic Presbyterian system with a hierarchy of bishops and create a church modelled on High Anglican lines, and to finance his reforms by re-possessing the former land holdings of the Catholic Church which had been sold on at the Reformation and now formed the basis of many landowners' status and wealth. In 1639 and 1640 Charles was defeated in the two Bishop's Wars. Desperately short of finance, Charles was forced to recall the English Parliament, the so-called Long Parliament, and they reached a peace with the Covenanters in the Treaty of London in 1641. However, Charles and the English Parliament remained at odds over who should control the army, and the first English Civil War began in 1642. Initially the Royalists and the Parliamentarians were relatively evenly matched, and the Parliamentarians opened negotiations with the Covenanters for their assistance in breaking the deadlock. In 1643, under the terms of the Solemn League and Covenant, the Covenanter government of Scotland allied itself with the English Parliament and entered the war in England in early 1644, marking a major turning point in the war. Charles attempted unsuccessfully to foment rebellion in Scotland and the Scottish army went on to make a major impact in the campaign for the north of England. Following crushing defeat at Marston Moor on 2 July 1644 the King tried again, appointing James Graham, the 5th Earl of Montrose, as his military commander in Scotland. Montrose had been part of the abortive rebellion and was a former Covenanter himself who had joined the King in 1643. On 28 August 1644, Montrose raised the royal standard and embarked on a campaign against the Covenanter forces in the Highlands (Reid 2003).

In the next two years, Montrose, with forces which changed constantly in size and composition, won a series of victories over the Covenanters under a number of different

commanders, including: Tippermuir (1 September 1644), Aberdeen (13 September 1644), Inverlochy (2 February 1645), Auldearn (9 May 1645), Alford (2 July 1645) and Kilsyth (16 August 1645) and was elevated to 1st Marquis of Montrose by Charles as reward. However, he was defeated at Philiphaugh near Selkirk on 13 September 1645 by much superior Covenanter forces commanded by Lieutenant-General David Leslie. He endeavoured to carry on his campaign in the North-East, and also tried to threaten Glasgow, but lack of co-operation and poor relations between the leading Royalist commanders meant that they achieved little success and Montrose's campaign petered out in early May when his forces besieging Inverness were taken by surprise by Major-General Middleton's advance and fled without a fight. Although Huntly, another Royalist commander, stormed Aberdeen on 14 May, a few weeks later Charles, who had surrendered at Newark on 5 May, ordered his forces in Scotland to lay down their arms. Although Montrose was reluctant to do so, he finally disbanded his forces at Rattray on 30 July after agreeing terms with Middleton and then fled abroad (Reid 2003).

After the executions of Charles I in January 1649 and the Marquis of Huntly in March, Royalist unrest allied to hatred of the extreme Covenanter government led to rebellion in the Highlands which was put down by Sir Archibald Strachan who routed the rebels at Balvenie Castle near Dufftown on 8 May 1649. In the meantime, the Covenanter government had proclaimed the exiled Charles II as King of Scotland and attempted to negotiate with him in Holland, hoping to get him to accept the Covenants and abandon his father's ideas of establishing an Episcopal church and re-possessing land once belonging to the Catholic Church. Charles had, however, appointed Montrose to be Lieutenant-Governor of Scotland and Captain-General of the Crown's forces and sent him to seek military assistance from the monarchs of Europe in mounting an invasion of Scotland. He had only limited success, but got enough support from Sweden and Denmark to obtain arms, ammunition and ships and money enough to employ several hundred mercenaries. An advance party reached Orkney in September 1649 under the command of the Earl of Kinnoul, consisting of 80 officers and 100 Danish soldiers. Although Kinnoul died, he was replaced by his younger brother. More reinforcements reached Orkney in the spring, but two supply ships were lost on the voyage. When Montrose arrived in March 1650, he found that Charles had agreed to enter further negotiations with the Covenanters. However, Charles still encouraged Montrose to proceed with invasion, perhaps hoping that success would allow him to ignore the Covenanters completely or at least allow him to extract concessions (Roberts 2000).

Once Montrose had arrived at Kirkwall in Orkney with reinforcements of a mixed group of Royalist exiles and Danish mercenaries, he began to prepare for an invasion of the mainland. Reid states that Montrose was on very shaky ground and a more prudent general might have waited in Kirkwall to see the outcome of negotiations being conducted between the Covenanter government and Charles (Reid 1990). Gordon of Sallagh , a contemporary and a follower of the Covenanter Earl of Sutherland, stated that Montrose landed in Caithness with one thousand six hundred and fifty, not exceeding fifteen hundred men (presumably 'men' refers to foot soldiers, rather than gentlemen and horse). He then comments 'With ane arrogant pride, he thought with that number to overrun this kingdome, which a man of his experience would not have undertaken, without the assurance of friends in Scotland' (Sallagh1813). Events were to prove that Montrose's hopes of raising support were groundless.

According to Sallagh, Montrose sent Sir John Hurry, once a Covenanter commander, across with an advance guard of 500 to secure the Ord of Caithness, a narrow defile separating Caithness from Sutherland, Montrose landed near John O'Groats on 12 April, and then moved south, besieging and taking the surrender of Dunbeath castle, before moving into Sutherland. The Earl of Sutherland, lacking horse, gave ground before Montrose, but left strong garrisons in the castles of Dunrobin, Skelbo, Skibo and Dornoch. Sallagh says that Montrose arrived at Strathoykel on the sixth day after landing and moved to Carbisdale, where he waited in vain for the recruits he hoped would join from Strathnaver (Sallagh 1813). Throughout this campaign, his attempts to recruit had very limited success because of the hold the Covenanting nobility had over the area (Roberts 2000). Cowan says that Montrose had completely failed to appreciate that the balance of power in the north had shifted to the Covenanters in the shape of the Earl of Sutherland and the few gentlemen

who joined him were those who had already lost out from Sutherland's rise and had little left to risk (Cowan 1977).

Unknown to Montrose, whose intelligence and scouting, not for the first time, was woefully deficient, a sizeable government force under Colonel Archibald Strachan was in the area and was well aware of Montrose's presence. Montrose, on the other hand, believed that there was only one cavalry troop in the area (Reid 1990). Sallagh says it was agreed in a council of war that the Earl of Sutherland should return to Sutherland to protect his lands from possible attack by Harry Graham, the brother of Montrose, who had been detached to raise recruits in Caithness and whom they feared might be joined by recruits from Strathnaver, and that the government forces should move to meet Montrose. This they did on 27 April 1650 at the Battle of Carbisdale (Sallagh 1813).

Battlefield Landscape
Montrose entered the area of the battle, on the wide flood plain, from the north, having marched through the narrow pass between the high ground on which Carbisdale Castle now stands and the river. Although a source of debate within the sources, the presence of earthworks at the eastern end of the village of Culrain suggests that he was here for several days and did fortify his camp. Although the earthworks have not been subject to any form of detailed investigation, the angled bank and ditch in the field to the south of the village hall does bear a striking similarity to a ravelin. If this interpretation is correct, then it places Carbisdale within a very small number of battlefields in Scotland, and indeed in Britain, with associated earthwork defences.

Strachan and his Covenanters approached from the south, though it is difficult to be certain about the deployment of his men, given that the accounts describe his attack as an ambush carried out by three groups. It seems likely that the battle took place on the flood plain, possibly in front of the camp, with Montrose's men quickly retiring into the woods, which can still be seen, on the slopes to the west of Culrain village.

Location
A number of detailed descriptions of the site of the battle are given in the various sources.

One contemporary source says the battle took place at 'Craigchoynechan', beside Carbisdale. (Sallagh 1813). Another says only that they were drawn up in a place near a 'Scrogie Wood' (Balfour 1825). Reid describes the Royalists being ambushed by Strachan on the open strath at Carbisdale, near the present day village of Culrain (Reid 1990). Roberts puts the action at Kincardine, just south of Ardgay, on the flat ground just north of the Culrain Burn (Roberts 2000).

Cowan gives a more detailed picture. He believes Montrose was on the move, fording the Oykel, just west of the point where it is joined by the Cassley, to march along the south bank of the river. He puts the present day village of Culrain in the middle of the battlefield, situated in the middle of level ground roughly triangular in shape, bounded to the north and west by the densely wooded slopes of Craig a' Choineachan and the low wooded slopes of the 'Scroggie Wood', on the east by the Kyle and on the south by the Culrain Burn. He believes that Montrose marched through the narrow pass between the Creag and the Kyle into the centre of the triangle, facing south-eastwards towards Bonar Bridge and the Dornoch Firth (1977).

Another very detailed suggestion is made by Williams:

'With the hills to the north and the Kyle estuary to the east, the burn enclosed a triangle of level ground admirably suited to cavalry. At the northern point of this triangle was Carbisdale Loch, and, beyond, a narrow defile overhung by Craig-caoinichean. Here, in the jaws of the pass was Montrose's camp. His left flank rested on the Kyle. His right and rear were protected by the hills and on the bluff facing south-east towards the open ground the Royalists had thrown up a formidable breastwork. The position was a strong one and could not be taken by cavalry in a frontal assault.'(Williams 2001).
The location is considered in Highland Council's Historic Environment Record MHG9159, which nominally places the battle site at Lamentation Hill, Carbisdale, Grid Ref. NH5680

9450. Scroggie Wood is not mentioned on current or 19th century maps. If Montrose was indeed entrenched as some sources claim,

'There are no current indications of location of the entrenchments, the lower flat lands above the river are heavily improved and now cut by the railway-the only earthworks (slight) are opposite Mains Farm and these do not appear defensive. The lower slopes have seen various levels of agricultural improvement, but in a general check of the area no early earthwork features were seen. Only structures are dyke walls (ruinous) abutting some of the road.'
This record also says that, according to some sources, the dead from the battle were buried in the Carn non Conach (NH59SE0004) at Rhelonie, which is some distance away to the south. It also says there are reports of undated bodies from the peat (laid out in rows) 'at Culrain'. The record also suggests that if the hidden cavalry at Wester Fearn attacked Montrose's army as they approached onto the flat area and skirmishing stretched back as far as Carbisdale farm and also on to the Rhelonie area then the battle will have occurred over an extremely large area.

The Record quotes The National Statistical Account 1845 (Rev H Allan),

'Montrose was surprised on level ground, near a pass called Invercharron (Invercharron Hill - NH 5791), on Saturday, 27 April 1650. Montrose tried to reach a wooded, craggy hill in his rear but was overtaken and defeated by Lt-Col. Strachan. The ground where the battle was fought ... took its present name, Craigcaoineadhan, which may be translated the Rock of Lamentation, - from the event ...'.
The record goes on to say that

'Creag a'Choineachan is the name applied to the area on the Ross-shire OS 6" map 1907 which is named Lamentation Hill, etc. on OS 6" 1881. If Lamentation Hill is indeed the hill towards which Montrose was retreating the 1907 OS site could well be that of final engagement, and could thus be accepted as the site of the battle, the 1881 OS site being more commemorative than factual.'
Terrain
The battlefield is centred on the low lying plain to the west of the river which debouches into the loch (this is most likely a raised beach). The main action is likely to have been contained within the area to the north of burn which cuts across the plain from the south east to the north west, creating a triangle of flat ground. Montrose appears to have chosen his location at the north end of the plain, at the foot of the crags, as this would allow him to observe the approach of any force from the south, across the plain. It is difficult to envisage how Strachan's force managed to surprise Montrose, who was securely placed behind what appears to be field fortifications, unless the attack came once Montrose had left the cover of his camp and was moving his army south across the plain. It is possible that Strachan moved his men into the cover of the depression which accommodates the burn under cover of darkness and also across the higher ground to the west after approaching from the south.

The gentle wooded slope which fringes the north western edge of the plain is consistent with Montrose's retreat to 'Scroggie Wood', while some of his force appears to have fled to the east and come to grief in the river.

Condition
The open plain to the south of Culrain is almost entirely given over to improved grazing, with large fields bounded by fences. The gentle slopes to the north-west, which appears to represent Scroggie Woods is occupied by mixed deciduous woodland and therefore may retain some of the character of the 1650 landscape. The village of Culrain was not present in 1650 and represents a mix of late nineteenth/early twentieth century and modern dwellings. There has been some recent development in the form of house construction but this has thus far been very limited.

The possible field fortifications present in the field just to the south of the village hall are relatively clear, their good condition probably reflecting their pronounced character when freshly constructed: they appear to be a ravelin. A later track has been driven through the eastern flank of this feature, and this may represent an earlier continuation of the road as it

leaves the bridge across the railway, to the east of the feature.

To the rear (north) of the village hall, is the area where the main camp would be expected, if the triangular shaped feature on the south side of the hall is the tip of a ravelin. There is a deep ditch running along the western side of the road where it runs north to south to the north of the village hall, and this may represent part of the camp defences, and indeed judging from its angle may be a continuation, with the ditch better preserved but the bank lost, of the ravelin to the south.

It was noted on the field visit that there has been recent tree planting in the area which may represent the camp and this is likely to have had an impact on any buried archaeology in that area.

Archaeological & Physical Remains and Potential
The question of physical remains above ground was considered in the Highland Council Historic Environment Record (HER) MHG9159, discussed in detail below under Battlefield Landscape. This concluded that further work comparing historical accounts with features on the ground would be required.

The area of the battle, on the flat ground to the west of the river is a relatively open landscape, with the village of Culrain having a fairly small footprint. The initial actions of the battle are likely to have taken place on the plain to the south of the village, with the Royalists then retreating to the wooded hills to the north-west. The potential for battle archaeology within this area is therefore good, with metal objects including musket shot, probably existing in the topsoil.

As noted above, there has in the past been doubt about the status of upstanding remains in the vicinity of the village. However, following a site visit in association with the compilation of the Inventory of Historic Battlefields it is now clear that an earthwork located in the field immediately to west of the road bridge over the railway, on the outskirts of the village, may well represent an arrowhead-shaped ravelin. This feature, which is represented by linear banks and ditches coming to a point which projects to the south, is typical of sixteenth century field fortifications and was probably located in advance of a fortified camp or other position. The orientation of the feature, which is at odds with all the later field boundaries, is in keeping with an earthwork sitting in advance of Montrose's camp, in the expectation that an attacking force will be advancing from the south, across the flood plain, which appears to have been the case.

The clear implication of this feature is that Montrose did indeed have a camp at this location, which given the scale of the fortifications, appears to have been occupied for at least several days prior to the battle. There are some banks and ditches to the rear (north) of the ravelin, behind the village hall, which may represent defensive works associated with the main part of the camp.

Cultural Association
The battle is not particularly well known today and there are no known poems or ballads about the engagement, although it is briefly referred to in The Braes of Sutherland, a ballad of the Highland Clearances by the contemporary Scottish folk-rock band Wolfstone. There is one place name which may be associated with the battle. This is Creag a' Choineachan; the hill to the north of the flood plain on which the initial encounter seems to have taken place. The Gaelic name of the hill is commonly translated as Lamentation Hill, which may refer to the retreat and defeat of Montrose and his Royalists.

Commemoration & Interpretation
In autumn 2009, the 1st Marquis of Montrose Society was considering establishing a memorial in tribute to the sacrifices made by many Orcadians during and prior to the battle of Carbisdale. (Kirkwall and St Ola Community Council minutes 29 August 2009).

References
Bibliography
Cowan, E. J. 1977. Montrose for Covenant and King. Weidenfeld and Nicholson, London.

	280-91. Reid, S. 1990. The Campaigns of Montrose. The Mercat Press, Edinburgh. 177-78.
Asset/Event Number	104
Asset/Event Name	Loedebest,settlement 650m W of
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	SM5145; ND13SW 33
HER Number	MHG629
Status	Scheduled Monument
Section:	N/A
Easting	313140
Northing	932167
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5145 This settlement consists of three buildings, associated dykes and field systems. One building (at Grid Ref. ND12883204) is small and rectangular and isolated some way to the W of the main settlement. The other two buildings include one small rectangular building and a long house. The long house has stone walls attached to the NW and NE; the wall to the NE forms part of a stone walled enclosure. There are faint traces of wall foundations to the SE of the long house and this could indicate the existence of an earlier settlement on this site. There is evidence for rig cultivation alongside the river. Two areas are proposed for scheduling. One measures 30m SW-NE by 30m SE-NW and covers the isolated rectangular building. The second area measures a maximum of 250m WNW-ESE by 110m WSW-ENE to include the other buildings, linear dykes and rig and furrow. The areas proposed for scheduling are shown in red on the attached map. Statement of National Importance This monument is of national importance for its potential to contribute to an understanding of post medieval settlement, land use and the process of the Clearances in this area of Caithness. The buildings are well preserved and incorporate architectural information.
Asset/Event Number	105
Asset/Event Name	Loedebest,settlement
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval; possible medieval
Listing No./NRHE Number	SM5152; ND13SW 44
HER Number	Various
Status	Scheduled Monument
Section:	N/A
Easting	313599
Northing	932200
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5152 This monument consists of four clusters of houses with associated arable fields. A settlement has probably existed here since at least the later sixteenth century, as Timothy Pont's map marks 'Lybuster' which probably relates to Loedebest. The settlement is also recorded in charters of 1619 ('Lodubiste') and 1624 and is marked on Roy's map of 1747-1752 as 'Lodbas'. At ND13853195 are the foundations of three long houses, two kiln barns and a number of enclosures. At ND13393240 are the foundations of a long house, a kiln house, a rectangular building which has been reused as a sheepfold and enclosures. At ND13463225 are the more substantial remains of three long houses, a kiln barn and a field system. At ND13913205 are the foundations of two long houses, a rectangular building, a kiln barn and a field system. At ND13743223 are the foundations of a rectangular building and field system. The field systems of the post medieval and modern farms surround all of these settlement clusters. The area to be scheduled measures 1060m NW-SE by a maximum of 550m N-S, to include the house clusters and field systems. The road from Loedebest to Achnaclyth is excluded from the scheduled area, as is the recently abandoned farmhouse and farmyard at Loedebest. The chambered cairn 400m WNW of Loedebest is also excluded as this is subject to a separate scheduling proposal. The area proposed for scheduling is shown in red on the attached map. Statement of National Importance The monument is of national importance for its potential to contribute to our understanding of post medieval settlement, land use and the process of the Clearances in this area of Caithness. The settlement areas and field systems form an extensive and well preserved landscape of post medieval settlement. The documentary references indicate early occupation on this site and some of the less substantial foundations could represent buildings of early post medieval or earlier date.
Asset/Event Number	106
Asset/Event Name	Loedebest,settlement 1300m W of
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	SM5189; ND13SW 34
HER Number	Various
Status	Scheduled Monument
Section:	N/A
Easting	312458
Northing	932336
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5189 This site is a post medieval settlement with the remains of 6 buildings, associated enclosures and an extensive area of rig cultivation. The 6 buildings include 4 which survive as turf-covered foundations and 2 better preserved structures. A fairly long period of occupation is probably indicated on this site. The enclosure to the E of the settlement is oval in shape.

	Associated linear dykes and field systems occur on all sides of the settlement. The area to be scheduled measures 600m E-W by a maximum of 300m N-S, to include the buildings, other structures and the field system of this settlement, as shown in red on the attached map. Statement of National Importance This monument is of national importance for its potential to contribute to our understanding of post medieval settlement and land use and the process of the Clearances in this area of Caithness. The settlement appears to show evidence for a long phase of occupation. The less well preserved buildings may indicate an early phase of occupation on this site, while the buildings of the presumed later phase are well preserved and incorporate important architectural information.
Asset/Event Number	107
Asset/Event Name	Loedebest,settlement 900m WNW of
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	SM5198; ND13SW 32
HER Number	Various
Status	Scheduled Monument
Section:	N/A
Easting	312929
Northing	932435
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://portal.historicenvironment.scot/designation/SM5198 This post medieval settlement consists of the remains of a long house, an enclosure, an oval mound and a sheepfold. The long house is 32m long and 5.5m wide. The walls are defined by lines of boulders, 2 or 3 courses high in places and about 1m thick. The building is divided into 3 compartments, each with an entrance from the E. The enclosure is 22m by 28m is three-sided and attached to the long house. The walls are much denuded. Nearby are the remains of an oval mound about 13m by 6.5m which consists of a low earth bank heavily overgrown with heather and with a hollow in the centre. Nearby is a circular stone walled sheepfold. The whole complex is defined by a dyke. The area to be scheduled measures 280m NW-SE by 125m NE-SW, to include the long house, enclosure, mound, sheepfold and dyke. The area is defined to the S by the Achnaclyth-Loedebest road and on the other sides is taken 15m beyond the dyke which defines the settlement area. The roadstone quarry beside the road is excluded from the scheduled area. The area to be scheduled is shown in red on the attached map. Statement of National Importance The site is of national importance for its potential to contribute to an understanding of post medieval settlement, land use and the process of the Clearances in this area of Caithness. References The monument is number DB18/18 in Dr A Morrison's survey of Dunbeath Estate
Asset/Event Number	108
Asset/Event Name	Ousdale
Type of Asset/Event	Hut Circle(s)

Date and/or Period	Prehistoric
Listing No./NRHE Number	ND02SE 16.00
HER Number	MHG814
Status	Non-designated Heritage Asset
Section:	N/A
Easting	306700
Northing	920600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	*Recorded by AOC Archaeology during 2024 walkover survey - see sub-elements of Asset 108 for details.* https://canmore.org.uk/site/7531/ Centred at ND 067 206 and levelled into a S-facing slope are two circular, stone-walled huts. Hut 'A' [Asset 108.1] measures 8.0m in diameter between the centres of a wall spread to 2.5m all round. Several inner facing-stones are visible in the N and E arcs and an occasional measurements or wall thickness. The simple entrance is in the SSE. Hut 'B' [Asset 108.3] measures 7.0m in diameter between the centres of a peat-covered wall spread to about 3.0m. The simple entrance is in the S. There are several heavily peat-covered stone clearance heaps and traces of probably contemporary walls in the area, but peat growth hides details of cultivation plots. Visited by OS (I S S) 21 April 1972. The hut circles (A and B) are as described by the previous OS field surveyor. At ND 0670 2059 is a further example [Asset 108.4], measuring 6.5m NW-SE by 5.5m transversely within a heather-covered wall 0.2m average height and spread to 2.0m. The entrance, of simple form, is in the SE. Huts A-C surveyed at 1:2500. Visited by OS (N K B) 8 November 1982.
Asset/Event Number	109
Asset/Event Name	Morvich Burn
Type of Asset/Event	Cairnfield (Period Unassigned)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 24.00
HER Number	MHG11115
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275260
Northing	902180
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	*Recorded by AOC Archaeology during 2024 walkover survey - see Assets 384 and 385.1-385.5 for details* https://canmore.org.uk/site/5933/ NC 752 021 Fringing a later depopulated settlement to the SW is an area of scattered stone clearance heaps, most numerous in the SE, and of the type usually associated with hut circles though none are evident. Visited by OS (J M) 31 July 1975. The small cairns extend W and merge into the area of small cairns associated with the three hut-circles (NC70SW 34) to the E of the Allt Bad a' Chrasgaidh. Information from RCAHMS (PM) 4 December 1997
Asset/Event Number	111
Asset/Event Name	Loch Farlary
Type of Asset/Event	Hut Circle(s) (Prehistoric)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 29.00
HER Number	MHG59296; MHG41270
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276600
Northing	904300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/5938/ NC 7667 0438; NC 7672 0445. Two hut circles 'A' and 'B' respectively. 'A', of unusual definity though peat-overgrown, is 13.0m in diameter between wall centres. An earthfast stone slab 0.7m high edges the W side of a well-defined entrance gap in the S. 'B', ill-defined and obscured by peat, is 11.0m NW-SE by 9.5m between centres of a wall, much depleted around SE arc. The wall appears to expand to 5.0m at a probable entrance gap in the S though this effect could be due to tumble. About 20.0m to the NE of hut 'B' an arc of peat-overgrown rubble and a large slab on edge in the S arc may indicate the remains of a hut with portal stone. Contemporary cultivation is marked by one or two stone clearance heaps around hut 'B'. Surveyed at 1:10,000. Visited by OS (J M) 11 August 1975.
Asset/Event Number	112
Asset/Event Name	Loch Farlary
Type of Asset/Event	Hut Circle (Prehistoric)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 30.00
HER Number	MHG9433
Status	Non-designated Heritage Asset
Section:	N/A
Easting	277030

Northing	904400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/5940/ NC 7703 0440. A hut circle measuring 9.0m in diameter between centres of a peat-overgrown wall, with an entrance in the SE. There are no indications of contemporary cultivation. Surveyed at 1:10,000. Visited by OS (J M) 11 August 1975.
Asset/Event Number	113
Asset/Event Name	Achork
Type of Asset/Event	Field System (Period Unassigned), Hut Circle(s) (Prehistoric)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 36.00
HER Number	MHG11120
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275600
Northing	904200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/5946/ NC70SE 36 756 042. ('A' NC 7460 0429) Undescribed sub-circular feature. OS 1:10,000 map, (1970) NC 756 042. A settlement of three oval huts ('A'-'C') set within a contemporary field system well marked by stone clearance heaps particularly around the S half, and some wasted field walls. Hut dimensions are between wall centres. 'A' is 11.0m NE-SW by 9.5m with an entrance in the SW. 'B', the best preserved, is 14.0m NNE-SSW by 12.0m with an entrance in the SSW. 'C' is 11.0m NNW-SSE by 9.0m with an entrance in the SSE. Hut 'A' revised at 1:2500. Huts 'B' and 'C' surveyed at 1:2500. Visited by OS (J M) 12 August 1975.
Asset/Event Number	114
Asset/Event Name	Dunrobin Glen
Type of Asset/Event	Cairnfield (Period Unassigned), Hut Circle (Prehistoric)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 39.00
HER Number	MHG11123

Status	Non-designated Heritage Asset
Section:	N/A
Easting	279410
Northing	904690
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/5949/ NC70SE 39 7941 0469. At NC 7941 0469, towards the base of a steepening south-facing slope is a peat-silted hut circle measuring 10.5m N-S by 8.0m E-W within a tumbled wall 0.4m maximum height and spread to 2.0m. The entrance of simple form is in the south quarter. In the vicinity are a number of stone clearance heaps and one or two lynchets which are associated with the hut. Surveyed at 1:10 000. Visited by OS (N K B) 15 May 1981.
Asset/Event Number	115
Asset/Event Name	Dunrobin Glen
Type of Asset/Event	Cairnfield (Period Unassigned), Hut Circle(s) (Prehistoric)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 40.00
HER Number	MHG10597
Status	Non-designated Heritage Asset
Section:	N/A
Easting	279544
Northing	904515
Council	Highland
Condition:	Various
Alignment:	Various
Importance:	Negligible/Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey - see sub-elements of Asset 115 for details.* https://canmore.org.uk/site/5951/ NC70SE 40 795 045. At NC 795 045, at the base of a steepening south-facing slope, is a close group of three similar hut circles (A-C), now overgrown with heather. They measure from 13.0m by 11.5m to 12.5m by 10.5m within tumbled walls spread from 2.5m to 3.5m, and up to 0.6m high. The entrance in each case is in the south or south-south-east on the line of the longer axis. There is no definite evidence of cultivation around the huts, but some 200m to the NE are several stone clearance heaps and cleared ground, which are probably contemporary with the huts. Surveyed at 1:10,000. Visited by OS (N K B) 15 May 1981. References Harden, J. (1990) 'Survey Dunrobin Glen (Golspie parish)', Discovery Excav Scot, 1990. Page(s): 28
Asset/Event Number	116

Asset/Event Name	Allt Bad A' Chrasgaidh
Type of Asset/Event	Field System (Prehistoric), Hut Circle(s) (Prehistoric)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274920
Northing	902520
Council	Highland
Condition:	Various
Alignment:	Various
Importance:	Negligible/Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey - see sub-elements of Asset 116 for details.* https://canmore.org.uk/site/5990/ NC70SW 34 centred on 7488 0249 (A:NC 7488 0249) Hut Circle (NAT) OS 1:10,000 map, (1971) Centred on NC 749 024, along a hillside shelf, is a settlement of three hut circles (A-C) accompanied by a field system. Huts B and C are newly located. 'A', turf-covered, measures 9.0m diameter within a wall spread from 2.0 to 2.5m and up to 0.6m high. The entrance is no longer evident but was probably in the S. 'B', heather covered, measures about 11.0m diameter inside a wall spread to 2.0m and 0.3m high. The entrance is in the S but there is some indication of a break in the wall in the E. 'C' measures some 9.0m diameter internally. The wall is reduced to an ill-defined spread. There is a possible entrance in the W side. The field system is evident in numerous clearance heaps, spaced from 10.0 to 25.0m apart, and occasional ruckles of cleared stone; no measurable plots are discernible. South and west of hut A there is some intrusion of 18/19th century strip cultivation. Revised at 1:10,000. Huts B and C surveyed at 1:10 000. Visited by OS (J M) 13 March 1981.
Asset/Event Number	117
Asset/Event Name	Allt Bad A Chrasgaidh
Type of Asset/Event	Building (Post Medieval), Enclosure (Period Unknown), Settlement (Prehistoric)(Possible)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SW 35.00
HER Number	MHG10631
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274670
Northing	902050
Council	Highland
Condition:	Various

Alignment:	Various
Importance:	Negligible/Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey - see sub-elements of Asset 117 for details.* https://canmore.org.uk/site/5991/ NC70SW 35 7467 0205. (NC 7467 0205) Stone Circles (NAT) OS 1:10,000 map, (1971) This is a homestead on an exposed rise in high ground. It is sub-circular, and measures approximately 13.0m across within a wall ranging in thickness from 1.4m to 1.6m, and distinguished by a fairly complete inner face, up to 0.7m high, of contiguous slabs. There is an entrance in the south south east. Encircling the homestead at a distance of 4.0m to 9.0m are the remains of a wall; in the east margin between the homestead and this wall, and outside the latter in the north west, are further walling remains. Extending from the north east sector of the encircling wall in a sinuous north west direction, is the peat covered course of a field wall. A stony mound overlies the homestead wall in the north. Some 15.0m south south east down the slope is what appears to be another homestead, but it is almost certainly later, probably contemporary with a deserted post Medieval settlement to the east. It comprises a 'D' shaped enclosure 10.0m by 7.0m internally, and recessed in the straight north side. A sub circular enclosure measuring 4.0m across internally abuts on the east, and no entrance is evident in either. The walling is of boulder slab construction but is now mainly visible as a peat covered spread 1.0m to 1.3m broad and up to 0.5m high. About 25.0m west is a sub oval enclosure of similar mature appearance but slight build, it measures 9.5m by 3.5m within a peat covered wall spread from 0.7m to 0.8m and 0.2m high. It too may be associated with the neighbouring settlement. Planned at 1:500. Surveyed at 1:10,000. Visited by OS (J M) 18 March 1981. Field Visit (6 June 1995) RCAHMS Afforestable Land Survey, Rogart An unusual enclosure, possibly a homestead, occupies the top of a heather-covered, craggy knoll to the SW of the Allt Bad a' Chrasgaidh. An irregular two-compartment enclosure and a building lie on the SE and S slopes of the knoll respectively. The homestead (ROG95 538-9), which may never have been completed, is defined by two concentric circles of orthostatic stones, 1.5m apart and up to 0.6m high, measuring 13m in diameter within the inner ring, with a lined entrance on the E. An oval heap of stones, measuring about 6.5m from E to W by 4.5m transversely and 1m in height, overlies the outer ring of stones on the N arc. Outside the enclosure there is an another ring of stones, which is not concentric to the main structure, but it may have been intended as an outwork to the homestead. The irregular enclosure comprises two unequal compartments, of which the larger is D-shaped and measures 9.1m from NE to SW by 5.2m transversely within stony banks spread to 1.5m in thickness, with a small recess like a bedneuk on the W, 2.3m in length by 1.3m in breadth. The second compartment adjoins it to the SW and measures 4m across, but displays no visible method of access (ROG95 537). The building measures 9m from NNE to SSW by 3m transversely within faced-rubble walls, 0.7m thick by 0.4m high, with what may be an entrance on the ESE (ROG95 135). It may be an outlying structure of the township to the NE (NC70SE 55.01). (ROG95 135, 537-9) Visited by RCAHMS (PJD) 6 June 1995
Asset/Event Number	118
Asset/Event Name	Hut circle, Glen Sletdale
Type of Asset/Event	Hut circle

Date and/or Period	Prehistoric
Listing No./NRHE Number	NC91SW 18.00
HER Number	MHG10049
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	292600
Northing	912529
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under grass and heather is situated on an edge of a somewhat high riverine terrace overlooking the Sletdale burn. Measures c16m in diameter with banks surviving up to 0.6m tall and spread 2.5m wide. Entrance appears to be in the SE. Slightly depressed interior. Https://canmore.org.uk/site/7117/ NC91SW 18 9255 1252. NC 9255 1252. A stone-walled hut-circle was discovered during field investigation on an old river terrace. It measures 10.5m in diameter within an overgrown wall, 0.7m high and spread to 3m, which has an entrance in the east. There is no sign of contemporary cultivation but the smooth appearance of the level area which extends about 100m ENE from the hut suggests early clearance. Surveyed at 1:10,560. Visited by OS (J M) 14 January 1976.
Asset/Event Number	119
Asset/Event Name	Glen Sleatdale
Type of Asset/Event	Field System (Period Unassigned), Hut Circle(s) (Prehistoric)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC91SW 19.00
HER Number	MHG10048
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	292866
Northing	912761
Council	Highland
Condition:	Various
Alignment:	Various
Importance:	Negligible/Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey - see Assets 119.3-119.11 for details.* https://canmore.org.uk/site/7118/ Centred NC 928 127. A settlement of four stone-walled hut-circles ('A'-'D') and an associated enclosure within a small field system were discovered during field investigation on the lower slopes of a SE-facing hillside. The huts are similar in form and condition, each set into the slope with an entrance in the SE

	arc, but peat growth obscures structural details. The sizes vary from 9.0m to 11.0m internal diameter within a wall of about 1.6m estimated thickness. A single portal stone remains at the entrance to hut 'A'. Closing on the SE arc of hut 'B' is a roughly circular enclosure about 13.0m in diameter within a wall spread to 2.5m broad. There is an entrance in the SE. The field system occupies 3/4 hectare around the huts, and comprises an area of cleared ground bounded by four or five stone clearance heaps and some lynchets. One plot 20.0m by 10.0m is visible. Surveyed at 1:10,560. Visited by OS (J M) 13 May 1976.
Asset/Event Number	120
Asset/Event Name	Hut Circle, Sletdale Burn
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC91SW 7.00
HER Number	MHG10027
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	292930
Northing	912700
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey - see Assets 119.1 and 119.2 for details.* https://her.highland.gov.uk/monument/MHG10027 A track constructed has damaged one side of one of the hut circles. Pottery was discovered and reported to Inverness Museum and Art Gallery and was found to be generally of Iron Age in date. Finder and photographer, N G Lindsay. A M Fox, Highland Council, 27.04.01 The pottery bears general comparison with material recovered from upland sites(principally hut circles) in Northern Scotland. See assoc. docs. File for Pottery descriptions. J Aitken : 19/06/01. NC91SW 7 9293 1270 to 9304 1269. (A - NC 9292 1269 : B - NC 9304 1268) Enclosures (NR) OS 6"map, (1963) Two circular enclosures were found during fieldwork. Visited by OS (E G C) 1 June 1961. Two stone-walled hut circles (A and B) at corrected grid references NC 9293 1270 and NC 9304 1269 respectively, situated in open heathland to the north of an old river terrace. 'A', on the edge of a slope, is about 10m diameter within an ill-defined wall surviving a sparse band of overgrown rubble spread to 2m; the wall has been further obscured by a rough track crossing north arc. A depression in the east arc may indicate an entrance. 'B', levelled into a low rise and peat overgrown, is well preserved. It is 11m NNW-SSE by 10.5m inside a wall spread to 3m. The east side of an entrance in the SSE still retains a lining of stone slabs, indicating a wall thickness of about 2.0m at this point. A break in the wall in the ESE is a modern mutilation. About 120m to the ESE are ruins of a dwelling and enclosures of 18th/ 19th century abandoned settlement. Contemporary cultivation is

	restricted to a well-defined lynchet about 55m south of hut 'A' crossing the slope, and containing between it and the hut an elongated area, of smooth, heather-covered ground free of stone. Revised at 1/10,000. Visited by OS (J M) 15 January 1976.
Asset/Event Number	121
Asset/Event Name	Broch, Killin
Type of Asset/Event	Broch
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC80NE 3.00
HER Number	MHG10805
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	286736
Northing	907623
Council	Highland
Condition:	Ruinous
Alignment:	N/A
Importance:	Medium
Description	https://canmore.org.uk/site/6475/ NC80NE 3 8673 0761. (NC 8673 0761) Broch (NR). OS 6" map, (1964) The ruins of a broch, now a structureless mass of stones. What was probably the entrance is exposed towards the WNW as is one side of the passage for about 10ft. At the inner end of the wall face, placed at right angles to its line of direction, is a slab standing 5ft 4ins above present level, and 3ft broad by 6ins to 8ins thick, which may have formed one of the jambs of the doorway. A very small portion of the wall is visible for a foot or two of its height on the N and a part of the outer wall of a chamber on the S. The inner face of the broch wall is in no place exposed and without excavation it is not possible to obtain accurate measurements. The massive rampart which protects the broch on the W, some 200 yards distant, appears to be of natural formation. RCAHMS 1911, visited 1909. The broch is generally as described above, reduced to a massive heap of stones, up to 1.0m in height. Short portions of the outer face are visible around the periphery giving an overall diameter of 19.6m and a length of inner face is exposed in the ENE indicating a wall thickness of about 4.7m at this point. In the SW the outer wall of a chamber is visible. Connecting this chamber to the outside face of the broch is what appears to be a secondary entrance, 0.9m wide, which is partially exposed in the tumble, suggesting the broch was re-used at a later date. The only evidence of outworks are two upright slabs on line on the level area W of the broch. Re-surveyed at 1/10,560. Visited by OS (E G C) 16 July 1961 and (J B) 11 November 1975. Field Visit (24 August 1909) RCAHMS County Inventory: Sutherland 26. Broch, Killin. About 1¼ m. SE. of Oldtown and ¼ m. back from the old road leading

	thence to Wester Clynekirkton, at an elevation of some 650' above the sea, are the ruins of a broch, now a structureless mass of stones. What was probably the entrance is exposed towards the WNW. By one side of the passage for a distance of about 10'. At the inner end of the wall face, placed at right angles to the line of its direction, is a remarkable slab standing 5' 4" above present level and 3' broad by 6" to 8" thick, which may have formed one of the jambs of the doorway. A very small portion of the outer wall is visible for a foot or two of its height on the N. and a part of the outer wall of a chamber on the S. The inner face of the broch wall is in no place exposed, and without excavation it is not possible to obtain accurate measurements. The massive rampart which protects the broch on the W., some 200 yards distant, appears to be of natural formation. OS 6-inch map: Sutherland Sheet xcvii. RCAHMS 1911, visited (AOC) 24th August 1909. Publication Account (2007) Euan W Mackie Broch Corpus 2 NC80 7 KILLIN ('Loch Brora') NC/8673 0761 This probable broch stands about 198m (650ft) above the sea and was already a structureless mass of stones in 1909 [2]. The entrance is probably on the west side where one side of a passage is exposed for 3.05m (10ft) . A very large slab – at least 1.63m (5ft 4in) in height, 91cm (3ft) wide and 15 - 20cm (6 - 8in) thick – may be a door-check. Short lengths of the outer wallface are visible, suggesting that the overall diameter is 19.6m, and the wall of a mural cell can be seen on the south-west [1]. There seems to be a secondary doorway connecting this chamber to the exterior [1]. Sources: 1. NMRS site no. NC 80 NE 3: 2. RCAHMS 1911a, 9, no. 26. E W MacKie 2007
Asset/Event Number	123
Asset/Event Name	Caen
Type of Asset/Event	Hut Circle (Prehistoric)
Date and/or Period	Prehistoric
Listing No./NRHE Number	ND01NW 67.00
HER Number	MHG10161
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301220
Northing	917730
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	*Observation by AOC Archaeology during 2024 walkover survey. Hut circle, part of the Scheduled asset SM6014 (Asset 77); did not fall within the survey corridor* https://canmore.org.uk/site/7486/ ND01NW 67 0122 1773 Situated 500m W of Caen. Information from SDD record map (1:10,000)
Asset/Event Number	124
Asset/Event Name	Dunbeath Water, Graveyard
Type of Asset/Event	Burial Ground (Period Unassigned)
Date and/or Period	Post-medieval

Listing No./NRHE Number	ND13SW 20.00
HER Number	MHG1260
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312985
Northing	932354
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/8213/ A graveyard in which interments still take place. It is said to date from the mid 17th century and is the property of the people of the district. (Two names 'Toch na Guall' and 'Toit na Gualainn', and their translation, 'Heap of the Shoulder' have been cancelled and 'Grave Yard' substituted.) OS Name Book 1871. https://her.highland.gov.uk/Monument/MHG1260 'Caithness Monumental Inscriptions', pre 1855 Monumental inscription survey completed by A.S.Cowper & I.Ross. The survey may not include inscription information after 1855 and each inscription transcribed does not give the full details that appear on the stones, abbreviations used. Some omissions and inaccuracies. Published 1992. J Aitken : 20/12/02
Asset/Event Number	125
Asset/Event Name	Creagan Reamhar
Type of Asset/Event	Clearance Cairn (Period Unassigned)
Date and/or Period	Undated
Listing No./NRHE Number	ND12NW 19.00
HER Number	MHG966
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312840
Northing	926050
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/8049/ (ND 1284 2605). A clearance heap 10.2 by 12 by 1m high, with an upright slab. Visited by OS (W D J) 23 June 1960. Modern field clearance. Visited by OS (R L) 6 March 1968.
Asset/Event Number	126
Asset/Event Name	Breakachy Burn
Type of Asset/Event	Clearance Cairn(s) (Prehistoric) - (Post Medieval), Field System (Prehistoric), Hut Circle(s) (Pre

Date and/or Period	Prehistoric
Listing No./NRHE Number	NH44NE 10.00
HER Number	MHG44150
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	245510
Northing	845450
Council	Highland
Condition:	Unknown
Alignment:	N/A
Importance:	Unknown
Description	*Observation by AOC Archaeology during 2024 walkover survey. Asset and surrounds under tall bracken/dense heather, no detailed survey undertaken. Https://canmore.org.uk/site/12356/ Clearance Cairn(S) (Prehistoric) - (Post Medieval), Field System (Prehistoric), Hut Circle(S) (Prehistoric), Souterrain (Prehistoric) (NH 4545) Depop., cairns, etc. OS 6"map annotated by A L F Rivet (nd) Centred at NH 455 455 is a settlement of ten stone-walled huts and a field system. Hut 'E' is circular, the remainder are oval. Except for 'A', 'G' and 'H' the measurements are given between wall centres. Hut 'A', set into a SW-facing slope, is visible as a platform measuring about 12.0 m NNW-SSE by 10.0 m trans- versely, bounded by a stony build-up round the SW arc and a back scarp. The entrance is in the SSE at the change of slope. 'B', set into a W-facing slope, measures about 10.5 m NW- SE by 9.0 m transversely with the wall spread to about 2.5 m. The 'simple' entrance is in the SE, at the change of slope. 'C', adjacent to 'B', measures about 12.5 m N-S by 10.0 m transversely with the wall spread to about 2.5 m all round. The outer wall face is visible round the E arc. The 'simple' entrance, about 1.0 m wide, is in the S, at the change of slope. 'D', at the base of a knoll, measures about 10.0 m from the NNW through the 'simple' entrance in the SSE by about 9.0 m transversely with the wall spread to about 2.5 m all round. The outer wall face is visible round the S arc. Attached to the W arc of the hut and following the curve of the wall of the hut is an elongated enclosure measuring approximately 10.0 m long by 2.5 m wide within a stone wall spread to about 1.5 m. There is no apparent entrance. It is similar in appearance to the 'souterrains' described on NJ40SW 3. (See 1:250 plan.) 'E', built up on a S-facing slope, measures about 6.5 m in diameter with the wall spread to about 2.0 m. The entrance is not apparent. 'G' has the outer wall face visible round most of the perimeter giving overall measurements of 13.5 m NNW-SSE by 12.0 m transversely. The wall is spread to about 2.0 m all round. The S arc has been robbed and the entrance is not apparent. 'H' has the inner wall face evident round most of the perimeter giving internal measurements of 10.0 m NNW-SSE by about 8.0 m transversely. The wall is spread to an indeterminate thickness. The entrance is not apparent. 'J' is denuded and measures about 9.0 m NW-SE by 8.0 m transversely with the wall spread to about 2.0 m all round. The entrance is not apparent. 'K', set into an E-facing slope, measures about 13.5 m N-S by about 11.5 m transversely with the wall spread to some 2.5 m all round. Stone clearance has been piled over the W arc. The 'simple' entrance, about 1.3 m wide, is in the S at the change of slope. About 15 m NE of hut 'K' is a circular hollow, about 6.0 m in diameter, with traces of walling round the edge. Stone clearance has been piled within. The field system, partly overlaid by a depopulated steading, is marked by stone clearance heaps, lynchets and walls forming fields varying in size from about 15 m by 10 m to about 50 m by 30 m.

Divorced survey at 1:10,000.
Visited by OS (R L) 17 March 1970

(Name: NH 4555 4550) Settlement & Field System (NR)
OS 1/10,000map, (1975)

The suggested enclosure attached to hut circle 'D;, at NH 4550 4545 is almost certainly the line of a collapsed souterrain. Otherwise, the hut circles and field system are as described by OS surveyor.
Visited by OS (J M) 11 February 1981.

Field Visit (March 1979)

RCAHMS: The Archaeological Sites and Monuments of North East Inverness
Tighnaleac NH 455 455 NH44NE 10
This unenclosed settlement comprises the remains of four oval stone-walled houses and two scarped platforms which may represent the sites of timber houses. In the vicinity there are several other platforms of unknown function and also extensive remains of stone clearance, some of which may be of relatively recent date.
RCAHMS 1979, visited March 1979

References
Feachem, R W. (1973a) 'Ancient agriculture in the highland of Britain', Proc Prehist Soc, vol. 39, 1973. Page(s): 344 fig. 12
RCAHMS. (1979c) The archaeological sites and monuments of North-east Inverness, Inverness District, Highland Region, The archaeological sites and monuments of Scotland series no 8. Edinburgh. Page(s): 20, No. 130 RCAHMS Shelf Number: A.1.2.ARC(8)

Asset/Event Number	127
Asset/Event Name	Breakachy Burn
Type of Asset/Event	Burial Cairn (Prehistoric)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH44NE 11.00
HER Number	MHG2665
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	245609
Northing	845465
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Unknown
Description	*Observation by AOC Archaeology during 2024 walkover survey. Asset and surrounds under tall bracken/dense heather, no detailed survey undertaken. Https://canmore.org.uk/site/12357/ At NH 4560 4546, on a knoll and within a field system (NH 44 NE10) are the remains of a cairn measuring about 9.0m in diameter and about 0.5m high. A kerb of eleven contiguous stones survives around the SW arc. The N and E arcs of the cairn are encroached upon by a depopulation steading. Divorced survey at 1/10,000 scale. Visited by OS (R L) 17 March 1970 Activities Field Visit (March 1979) RCAHMS: The Archaeological Sites and Monuments of North East Inverness

	Tighnaleac 1 NH 456 454 NH44NE 11 This cairn measures about 9m in diameter and 0.5m in height and is bounded by a low kerb of bounded by a low kerb of boulders on the Sand W. RCAHMS 1979, visited March 1979 References RCAHMS. (1979c) The archaeological sites and monuments of North-east Inverness, Inverness District, Highland Region, The archaeological sites and monuments of Scotland series no 8. Edinburgh. Page(s): 11, No. 46 RCAHMS Shelf Number: A.1.2.ARC(8)
Asset/Event Number	128
Asset/Event Name	Tighnaleac
Type of Asset/Event	Burial Cairn (Prehistoric)(Possible)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH44NE 21.00
HER Number	MHG62118
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	245690
Northing	845600
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/12368/ No cairn is identified in the area. There is a scatter of stones at NH 4557 4563, but this is almost certainly stone clearance associated with the hut circles and field system described on NH44NE 10. Visited by OS (J M) 11 February 1981. Field Visit (March 1979) RCAHMS: The Archaeological Sites and Monuments of North East Inverness Tighnaleac 2 NH 456 456 NH44NE A mutilated cairn measuring about 11 m in diameter is situated on the summit of a knoll about 160m N of cairn NH44NE 11. This cairn, and NH44NE 11 both fall within the settlement and field system described on NH44NE 10. RCAHMS 1979, visited March 1979 References RCAHMS. (1979c) The archaeological sites and monuments of North-east Inverness, Inverness District, Highland Region, The archaeological sites and monuments of Scotland series no 8. Edinburgh. Page(s): 11, No. 47 RCAHMS Shelf Number: A.1.2.ARC(8)
Asset/Event Number	129
Asset/Event Name	Dun Fionn
Type of Asset/Event	Dun (Prehistoric)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH44SE 10.00
HER Number	MHG2748
Status	Non-designated Heritage Asset
Section:	N/A

Easting	247159
Northing	842884
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Medium
Description	https://canmore.org.uk/site/12382/ (NH 4716 4290) Dun Fionn (NR) Vitrified (NAT) Excavated by Lord Lovat about 60 or 70 years ago, who cut two sections through this vitrified fort, which defaced its original appearance and rendered it difficult to determine its dimensions. On the N side there was until recently a wall from 1 ft to 5 ft high. Outwith the fort there are four circles, two of which measure 4 yds in diameter, one 5 yds, and the other, 2 yds. There is also an oblong or oval space of the same character as the circle. T Wallace 1921 Fort, Dun Fionn: On approaching the remains from the NE along the saddle which unites their site to the hillside beyond, a grass-grown rampart can be seen running athwart the line of approach, a gap in it possibly representing the original entrance. To the S of the gap the rampart runs for about 200 ft before turning W and fading out. From the other side the rampart fades out almost at once, though a distinct low broad ridge runs on what might have been its course to meet the brink of the precipitous descent to the river. Numerous masses of vitrified matter can be seen among the ruins of the rampart. It is probable that the structure was originally oval on plan, measuring about 200 ft NW-SE by a little less transversely. Visited by RCAHMS 1957 Dun Fionn overlooks the River Beauly and is flanked by wooded slopes to the E, S and W, with an easy approach from the NE. The RCAHM description bears little relationship to what can now be seen. The knoll occupied by Dun Fionn measures over all about 38.0 m NNE-SSW by 34.0 m and is about 3.0 m high with a level top measuring some 20.0 m by 18.0 m. Around the NE arc are traces of a wall containing vitrified material. Lord Lovat's excavation remains as a T-shaped trench with no trace of excavation on the W side as depicted by WAllace, whose plan is worthless. The knoll is otherwise featureless. There is no trace of the 'rampart' described by the RCAHMS. Between about 3.0 m and 6.0 m outside the base of the knoll and encircling it is a terrace, some 2.0 m wide, well-defined around the S and E arcs but almost obliterated elsewhere; this is probably the remains of an additional defence. There is no trace of Wallace's circular or oval features but halfway down the slope to the S is an oval platform measuring about 7.0 m N-S by 9.0 m. Visited by OS (R L) 19 March 1965 A small amount of vitrification was observed in the 19th century excavation, at this visit. At the base of the hill in the S are two ditches with outer ramparts abutting on to steep slopes in the W, with traces of a possible third outside them, denuded by timber operations. These defences are only 20.0 m long and possibly represent an unfinished defence. Traces of a terrace, 3.5 m wide where best preserved, occur along the E flank of the hill. This possibly joins the inner ditch and rampart, but soil slip and mutilation by timber operations have virtually destroyed it at this point. Between the ramparts and the main fort, and set into the S-facing slope is an eyebrow-shaped platform some 11.0 m E-W by 7.0 m; this is probably a timber hut platform. Published survey (25") revised. Visited by OS (A A) 13 January 1972

Dun Fionn: A severely mutilated dun occupies a slight knoll at the SW end of a steep-sided spur on the E side of the River Beauly. The summit of the knoll measures about 18 m by 16 m and is defined by a scarp which represents the remains of a vitrified wall; a further scarp on the NE probably represents the remains of an outwork.
RCAHMS 1979

A dun is the appropriate classification. A blanket cover of dead bracken at the time of visit made proper ground inspection impossible. However, authorities 2, 3 and 4 seem to have distinguished the same outer rampart despite varying descriptions. Authority 5 has obviously seen a second outer defence which he conjectures may have joined with an unmistakeable series of succeeding ditches and banks at the foot of the hill; the latter is puzzling in that being so removed from the accepted citadel area it appears superfluous to any defensive requirement in that respect. A natural trench across the NE approach may be a significant link in the defensive network. An uprooted tree on the SW edge of the citadel area has uncovered some reddened fragments of stone and a small piece of vitrification. There is no trace of any circles or platforms; in the hillside are one or two small shelves probably formed by uprooted trees.

There are some unresolved features about the site, particularly the series of ditches and banks at the foot of the hill, and it may be that the first outwork constitutes the fort proper and that Dun Fionn itself is a separate phase. The site could be likened to that at Langwell in Strath Oykell (NC40SW 3).
Visited by OS (JM) 9 February 1981

Activities
Field Visit (21 August 1943) RCAHMS Emergency Survey (Archaeology)
This site was recorded as part of the RCAHMS Emergency Survey, undertaken by Angus Graham and Vere Gordon Childe during World War 2. The project archive has been catalogued during 2013-2014 and the material, which includes notebooks, manuscripts, typescripts, plans and photographs, is now available online.
Information from RCAHMS (GF Geddes) 12 November 2014.
Field Visit (10 April 1957)
RCAHMS Marginal Land Survey

This site was included within the RCAHMS Marginal Land Survey (1950-1962), an unpublished rescue project. Site descriptions, organised by county, are available to view online - see the searchable PDF in 'Digital Items'. These vary from short notes, to lengthy and full descriptions. Contemporary plane-table surveys and inked drawings, where available, can be viewed online in most cases - see 'Digital Images'. The original typecripts, notebooks and drawings can also be viewed in the RCAHMS search room.
Information from RCAHMS (GFG) 19 July 2013.

Field Visit (March 1979) RCAHMS: The Archaeological Sites and Monuments of North East Inverness
Dun Fionn NH 471 429 NH44SE 10
A severely mutilated dun occupies a slight knoll at the SW end of a steep-sided spur on the E side of the River Beauly. The summit of the knoll measures about 18m by 16m and is defined by a scarp which represents the remains of a vitrified wall; a further scarp on the NE probably represents the remains of an outwork.
RCAHMS 1979, visited March 1979
(Stat. Acct, xiii 1794, 524; Wallace 1886, 346)

Note (5 March 2015 - 25 November 2016) Atlas of Hillforts of Britain and Ireland
The defences of Dun Fionn, which occupies a hillock at the SW end of a low ridge with steep slopes dropping away to the River Beauly on the W and SW, comprise two elements: an inner dun with a massively vitrified wall; and a series of outer defences which though possibly no more than outworks, might equally be the remains of a free-standing enclosure. The dun occupies the summit of the hillock, which is slightly oval and measures about 18m from NE to SW by 16m transversely and is defined by a scarp formed by the ruin of a

vitrified wall. The full extent and plan of the outer defences is uncertain, and the observations contained in the descriptions of successive investigators vary widely. In 1957, RCAHMS investigators observed the remains of a rampart crossing the spine of the ridge on the NE, noting numerous vitrified masses along its line and suggesting that it enclosed an area up to 60m across from NW to SE (about 0.23ha). This is perhaps the terrace 2m wide noted by the OS in 1965 enclosing an area in the order of 47m from NNE to SSW by 43m transversely (0.15ha), but in a later visit Alan Ayre of the OS also found at the foot of the slope on the S at least two ditches with external banks extending for a distance of no more than 20m from the steep slopes on the W; he speculated that these may be the remains of an unfinished circuit of defences.
Information from An Atlas of Hillforts of Great Britain and Ireland – 25 November 2016. Atlas of Hillforts SC2877.

References
RCAHMS. (1979c) The archaeological sites and monuments of North-east Inverness, Inverness District, Highland Region, The archaeological sites and monuments of Scotland series no 8. Edinburgh. Page(s): 17, No. 104 RCAHMS Shelf Number: A.1.2.ARC(8)
RCAHMS. (1942-3) Emergency Survey of archaeological monuments in military training areas, 1981, 2v. Typescripts. Page(s): TS 26, MS 111 RCAHMS Shelf Number: A.1.1.SUR
RCAHMS. (1950-9) Marginal Land Survey (unpublished typed site descriptions), 3 volumes. Page(s): v2 RCAHMS Shelf Number: A.1.1.MAR
Wallace, T. (1921a) 'Archaeological notes', Trans Inverness Sci Soc Fld Club, vol. 8, 1912-18. Page(s): 103-5 plan 104 RCAHMS Shelf Number: Ref

Asset/Event Number	131
Asset/Event Name	Invershin
Type of Asset/Event	Axehead (Stone)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH59NE 26.00
HER Number	MHG12885
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257000
Northing	896000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG12885 The butt of a flint axe from Invershin (NH 57 96) is in Dunrobin Museum, possibly received in 1875. (Acc. No. 1875.1). Info from A S Henshall (Dunrobin Museum catalogue) to OS 1966. This GR is seriously wrong as gives location W of the river instead of E. - HAW 10.2002 The axehead was catalogued during an inventory of Dunrobin Castle Museum's collection in 2019 by ARCH. Listed under Acc. No. 1875.1 and ARC 11.Is it stored in one of the cupboards. See attached photos. <1> SHG28514 Collection/Finds Collection: Archaeology for Communities in the Highlands (ARCH). 2019. Finds Collection At Dunrobin Castle Museum. 1875.1 and ARC 11.

Asset/Event Number	132
Asset/Event Name	Cnoc A' Mhargadaidh
Type of Asset/Event	Beaker (Prehistoric)(Possible)
Date and/or Period	Prehistoric

Listing No./NRHE Number	NH56NE 14.00
HER Number	MHG8976
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255680
Northing	867790
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	*SW *27/08/2024 *Cnoc a' Mhargadaidh is a mis-spelling of Cnoc a' Mhargaidh Dhuibh (Hill of the Black Market) References Ross and Cromarty OS Name Books, 1848-1876. OS1/28/1/28. https://canmore.org.uk/site/12877/ NH56NE 14 5568 6779 According to Mr Munro-Fergusson (Novar House, Alness), an ornamented urn was found at NH 5568 6799 during the construction of a forestry road about 1965. It crumbled away when picked up. Fergusson didn't see it, but from a workman's description believes it was a beaker. Visited by OS (I S S) 29 August 1972 (2010) Area known locally as Cnoc an Each, Swordale. Norman Macrae (Romance of a royal burgh: Dingwall's story of a thousand years, 1923) identified the area as a cairnfield, but without cists or finds. However, in the 1960s a cist containing a beaker was found while bulldozing a forest road, but the beaker disintegrated on exposure to the open air. Information from the ARCH Community Timelines Course, 2010. References MacRae, N. (1923) The romance of a royal burgh: Dingwall's story of a thousand years. Dingwall. RCAHMS Shelf Number: D.6.43.DIN RCAHMS. (1979a) The archaeological sites and monuments of Easter Ross, Ross and Cromarty District, Highland Region, The archaeological sites and monuments of Scotland series no 6. Edinburgh. Page(s): 15, No. 95 RCAHMS Shelf Number: A.1.2.ARC(6)
Asset/Event Number	133
Asset/Event Name	Strath Sgitheach Allt Na Criche 2
Type of Asset/Event	Cup Marked Rock (Neolithic) - (Bronze Age)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH56SW 13.00
HER Number	MHG63114
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252130
Northing	862976
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://her.highland.gov.uk/Monument/MHG63114 NH56SW 13 522 630. Centred around NH 522630 are eight cup marked rocks ('A' - 'H'). 'A' is a boulder measuring 3.1m x 1.9m x 0.6 m high with at least fifteen shallow cup marks on its upper surface. 'B' a large block 3.6m x 1.8m x 1.0m maximum height. It is largely earth-covered. It has twenty-three cup marks on its two outer edges. 'C' a boulder 1.8m x 1.2m x 0.6m high with six cup marks. 'D' a boulder 2.4m x 1.0m x 0.6m high with seven small shallow cup marks. 'E' a small boulder 1.1m x 0.7m x 0.3m high with two probable cup marks. 'F' a boulder lying close by has seven shallow cup marks upon it. 'G', a boulder, 2.8m x 1.5m x 0.6m, lying on the bank of a stream, has probably slipped from its original position due to erosion. It has six extremely shallow cup marks on its upper surface. 'H' is a slab 2.2m x 1.3m lying flush with the ground; it has three probable cup marks on its surface. Surveyed at 1:10 000. Visited by OS (J B) 16 November 1976 Field Visit (September 1978) RCAHMS: The Archaeological Sites and Monuments of Easter Ross Strath Sgitheach 2 NH 522 630 NH56SW 13 Eight outcrops of rock with shallow cup-marks. RCAHMS 1979, visited September 1978 Note (7 August 2018) Scotland's Rock Art Project Date Fieldwork Started: 07/08/2018 Compiled by: NOSAS Location Notes: THIS IS CANMORE PANEL B AND IS THE FIRST OF THIS SET RECORDED The panel is located on the lower S facing open slopes of Meall a'Ghuail, overlooking the river Sgitheach. It is one of a group of 8 panels (7 located at the time of writing) close to the Allt an Criche, in rough gazing interspersed with pine trees and patches of heath. A track crosses the river Sgitheach (ford and stepping stones) and heads NW and passes 60m W of the panel. There is a large broken down pine tree 2m E of the panel, and its roots are visible in places around the panel. Rigg is visible in the ground immediately S of the panel. The area generally has a number of hut circles, field systems and burnt mounds, including those identified in Canmore 12921 about 0.6km to the SW. Panel 3 (C in Canmore) is 5m to the W and is part of the same rock outcrop. Panel Notes: The panel is an L-shaped outcrop, up to 1.1m high, and with a S face 3.7m long and an E face 1.7m long. There are deep cracks separating a section of the panel at the 'corner'. There are 29 cups, along the two edges of the outcrop. The carved surface slopes at about 20degrees to the N, and disappears under turf. Some turf was lifted and no cups more than 0.3m from the exposed edges were found. References RCAHMS. (1979a) The archaeological sites and monuments of Easter Ross, Ross and Cromarty District, Highland Region, The archaeological sites and monuments of Scotland series no 6. Edinburgh. Page(s): 18, No. 133 RCAHMS Shelf Number: A.1.2.ARC(6) https://her.highland.gov.uk/monument/MHG63114 This panel was recorded as part of the ScRAP (Scotland's Rock Art project) by members of NoSAS in August 2018. This is panel B and is the first of the set to be recorded. The panel is located on the lower south facing open slopes of Meall a'Ghuail, overlooking the river Sgitheach. It is one of a group of 8 panels (7 located at the time of writing) close to the Allt an Criche, in rough gazing interspersed with pine trees and patches of heath. A track crosses the river Sgitheach (ford and stepping stones) and heads northwestand passes 60m west of

	the panel. There is a large broken down pine tree 2m east of the panel, and its roots are visible in places around the panel. Rigg is visible in the ground immediately south of the panel. The area generally has a number of hut circles, field systems and burnt mounds, including those identified in Canmore 12921 about 0.6km to the southwest. Panel 3 (C in Canmore) is 5m to the west and is part of the same rock outcrop. The panel is an L-shaped outcrop, up to 1.1m high, and with a south face 3.7m long and an east face 1.7m long. There are deep cracks separating a section of the panel at the 'corner'. There are 29 cups, along the two edges of the outcrop. The carved surface slopes at about 20 degrees to the north, and disappears under turf. Some turf was lifted and no cups more than 0.3m from the exposed edges were found. <1> NGR adjusted based on 2018 vertical aerial photographs. <2> --- SHG2670 Text/Report: RCAHMS. 1979. The Royal Commission on the Ancient and Historical Monuments of Scotland. The archaeological sites and monuments of Easter Ross, Ross and Cromarty District, Highland Region. . 18, No. 133. <1> SHG28055 Interactive Resource/Online Database: Historic Environment Scotland. 2017-. Scotland's Rock Art (ScRAP). ScRAP ID 613. <2> SHG28282 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 2018. Getmapping aerial photography 2018. XY
Asset/Event Number	134
Asset/Event Name	Strath Sgitheach
Type of Asset/Event	Corn Drying Kiln (Period Unassigned), Settlement (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH56SW 31.00
HER Number	MHG8906
Status	Non-designated Heritage Asset
Section:	N/A
Easting	253500
Northing	864100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	*Recorded by AOC Archaeology during 2024 walkover survey - see sub-elements of Asset 134 for details.* https://canmore.org.uk/site/12943/ NH56SW 31 535 641 This pre-improvement settlement survives as low stone wall spreads (1.0 - 2.0m wide), which are completely grassed over. The settlement is focused on a long house (33.0m by 5.0m) oriented NE-SW with two internal partitions. At its SW end is a second smaller house or byre (14.0 by 5.0m), which was oriented NW-SE. Nearby, to the SW, is a probable grain drying kiln and to the NE a substantial stone enclosure which measures 24.0 by 14.0m and is oriented NW-SE. A number of less prominent field walls extend from the settlement away from the river. Visited June 1989. Information from S T Driscoll and S M Foster (Mss, 5, No. 4.1.) 1989. Project (June 1989) Pre-afforestation Short Notice Surveys Pre-afforestation archaeological survey undertaken in Strath Sgitheach, funded by HBM SDD. S T Driscoll and S M Foster, 1989.

Asset/Event Number	135
Asset/Event Name	Cup-marked stone, Sgitheach
Type of Asset/Event	Cup-marked stone
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH56SW 36.00
HER Number	MHG8901
Status	Non-designated Heritage Asset
Section:	N/A
Easting	253202
Northing	863808
Council	Highland
Condition:	Fair
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A cup-marked stone on a prominent small knoll within the enclosure Asset 260.2. The rock art comprises four shallow cupmarks on the NW side edge and three deep cupmarks on the NE side. Panel continues below sediment and moss that has accrued, and field clearance cairn Asset 260.3 has built up on the SW side.* https://canmore.org.uk/site/12948 NH56SW 36 5320 6381 The rock outcrop at this spot has 7 good cup-marks and presumably others are obscured by the large modern clearance heap which covers much of the outcrop. Visited June 1989. Information from S T Driscoll and S M Foster (Mss, 7, No. 8.1.) 1989. Activities Project (June 1989) Pre-afforestation Short Notice Surveys Pre-afforestation archaeological survey undertaken in Strath Sgitheach, funded by HBM SDD. S T Driscoll and S M Foster, 1989. Note (7 August 2018) Scotland's Rock Art Project Date Fieldwork Started: 07/08/2018 Compiled by: NOSAS Location Notes: The outcrop which faces E is in a prominent mound of moss and grass covered stones, and is near the western end of an enclosure around a ruined farmstead. Panel Notes: The exposed part of the panel is an outcrop of schist about 0.7m high and roughly triangular at the top. At the NW edge of the top (carved surface) are four cups in a gentle arc. Towards the S edge is a row of three larger, deeper and very clearly defined cups.

Asset/Event Number	136
Asset/Event Name	Alltan-Riabhach
Type of Asset/Event	Corn Drying Kiln (Period Unassigned), Farmstead (Period Unassigned), Field System(s) (Period
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH69NE 24.00
HER Number	MHG10342
Status	Non-designated Heritage Asset
Section:	N/A
Easting	267442
Northing	898080
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	*Recorded by AOC Archaeology during 2024 walkover survey - see sub-elements of Asset 136 for details.* https://canmore.org.uk/site/13934/ Corn Drying Kiln (Period Unassigned), Farmstead (Period Unassigned), Field System(S) (Period Unassigned) NH69NE 24 674 980. Farmstead, including corn-drying kiln, fields: noted during pre-afforestation survey. D Ross 1983. The long rectangular building foundation at Alltan-Riabhach measures 15.5m by 2.8m internally with an annexe, a corn-drying kiln and 'fields'. To the SW lie a contemporary rectangular building and a sheepfold. Information from D W Ross, S E Finlay and P Ashmore 1983, NMRS MS/578/1, 7) A farmstead, comprising two roofed buildings and an enclosure is depicted on the 1st edition of the OS 6-inch map (Sutherland 1879-81, cviii). One roofed building, one unroofed building, a field and an enclosure are shown on the current edition of the OS 1:10,000 map (1990). Information from RCAHMS (AKK) 22 November 1995. References Ross, D. (1983) 'Achormlaire Hill (Creich and Dornoch p) survey', Discovery Excav Scot, 1983. Page(s): 15-16
Asset/Event Number	137
Asset/Event Name	Strath Of Kildonan
Type of Asset/Event	General View
Date and/or Period	N/A
Listing No./NRHE Number	NC91NE 0.04
HER Number	MHG34139
Status	Non-designated Heritage Asset
Section:	N/A
Easting	295000
Northing	916000

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/87626/ No description. [General view - not an archaeological feature in and of itself.]

Asset/Event Number	138
Asset/Event Name	Allt Cnoc Na Gamhna
Type of Asset/Event	Farmstead (Period Unassigned)(Possible)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 50.00
HER Number	MHG10395
Status	Non-designated Heritage Asset
Section:	N/A
Easting	279000
Northing	903920
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	*Recorded by AOC Archaeology during 2024 walkover survey - see sub-elements of Asset 138 for details.* https://canmore.org.uk/site/72864/ NC70SE 50 7900 0392. 'Post-medieval settlement - enclosures, subrectangular structure, wall' noted during pre-afforestation survey and to be avoided when planting. No details given. J Harden 1990. References Harden, J. (1990) 'Survey Dunrobin Glen (Golspie parish)', Discovery Excav Scot, 1990. Page(s): 28

Asset/Event Number	139
Asset/Event Name	Allt Cnoc Na Gamhna
Type of Asset/Event	Building(s) (Period Unassigned), Corn Drying Kiln (Period Unassigned), Quern
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 49.00
HER Number	MHG10398
Status	Non-designated Heritage Asset
Section:	N/A
Easting	279070
Northing	904000

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	*Recorded by AOC Archaeology during 2024 walkover survey - see sub-elements of Asset 139 for details.* https://canmore.org.uk/site/72863/ NC70SE 49 7907 0400. 'Medieval, post-medieval settlement - long houses, dykes, kiln, lazy beds, rotary quern, rectangular structures' noted during pre-afforestation survey and to be avoided when planting. No details given. J Harden 1990.
Asset/Event Number	140
Asset/Event Name	Allt Na Cruaiche
Type of Asset/Event	Bank (Earthwork) (Post Medieval), Track (Post Medieval)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH57NE 13.00
HER Number	MHG8418
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255700
Northing	875400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/68518/ Field Visit (14 November 1989) RCAHMS Afforestable Land Survey, Strathrusdale NH57NE 13 5570 7540 On the N bank of the River Averon to the E of the Allt na Cruaiche, a trackway cuts the river terrace on an E-W axis; to the N a heather-grown stony bank runs for 17m uphill into the conifer plantation. The trackway may be part of an old route leading to Coire Sliogaich along the N bank of the River Averon; further traces of trackways were observed between this location and Coire Sliogaich. Visited by RCAHMS (PJD) 14 November 1989.
Asset/Event Number	141
Asset/Event Name	Ceann An Locha
Type of Asset/Event	Farmstead (Medieval) - (18Th Century), Kiln Barn (Medieval) - (18Th Century)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH57NE 24.00
HER Number	MHG8407
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255620

Northing	875100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/68529/ Field Visit (15 November 1989) RCAHMS Afforestable Land Survey, Strathrusdale NH57NE 24 5562 7510 This farmstead is shown abandoned on the 1st ed OS 6" map of Ross-shire (1880,52) and is identified as Kinloch by Roy (1747-55, sheet 26/1). It is situated on the hillocks which form part of the glacial meltwater terraine between a forestry plantation and the River Averon. The farmstead comprises three buildings, a kiln-barn and several small enclosures; there are also a number of ruinous stone dykes which may be coeval with the farmstead. At the core of the farmstead there is an E-W, two-compartment building standing up to 1m in height; midway along the S wall it has a bedneuk, which measures 3.5m in external length by 1.75m transversely with an entrance 1m to the W. An outshot is appended to the N wall. A second two-compartment building is set at right-angles to the first on the N; its grass-grown rubble footings stand up to 0.35m high and there are also the footings of an attached enclosure on the W. Some 30m E there is a square enclosure with banks 0.6m high and in between there is a bank which stops at a stone revetment 0.3m high, just short of the building with the bedneuk. Several hollow trackways lead down towards a second knoll to the NNE, into which a kiln-barn with walls still up to 2m high has been built. To the W of the kiln-barn the knoll has been hollowed out to a depth of 0.65m, possibly with an entrance on the W. A further 10m to the W there is a two-compartment building; its drystone walls stand about 1m in height and within the E compartment, against the E gable, it has a raised platform 0.25m in height. A sinuous trackway leads from here to the river. On a knoll to the W of the core of the farmstead is a second, larger, scooped out hollow, 1m in depth with an entrance to the S and an internal entrance to one of a pair of appended folds on the N. Visited by RCAHMS (PJD) 15 November 1989. Note (23 February 1996) RCAHMS First Edition Survey Project Five unroofed buildings are depicted on the 1st edition of the OS 6-inch map (Ross-shire and Cromartyshire 1880, sheet lii) and on the current edition of the OS 1:10000 map (1986). Information from RCAHMS (SAH) 23 February 1996 References Roy, W. (1747-55) Military Survey of Scotland.
Asset/Event Number	142
Asset/Event Name	Dunrobin Glen
Type of Asset/Event	Enclosure(s) (Post Medieval), Farmstead (Post Medieval), Hut Circle (Prehistoric)(Possible), L
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 47.00
HER Number	MHG10399
Status	Non-designated Heritage Asset
Section:	N/A
Easting	279150
Northing	904850
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/72861/ NC70SE 47 7915 0485. Post-medieval settlement, dykes, lazy-beds' noted by Harden. (A number of unroofed buildings and enclosures are shown on OS 1:10,000 map, 1970 in the area indicated.) J Harden 1990. A field is depicted on the 1st edition of the OS 6-inch map (Sutherland 1879, sheet xcvii). Three unroofed buildings, two enclosures and two fields are shown on the current edition of the OS 1:10,000 map (1970). Information from RCAHMS (SAH) 1 November 1995 Activities Desk Based Assessment (1 April 2014) An archaeological desk-based assessment and walkover survey was carried out on 1 April 2014 on behalf of Scottish Water from Loch Farlary to Bridge of Horn, Golspie in advance of the proposed construction of a new water main. The work was undertaken to assess the nature and extent of any archaeology likely to be directly affected by the proposed development in order to inform recommendations for the protection and management of any sites identified. Seven archaeological sites, two of which will be directly impacted by the current development layout, were recorded. These included a burnt mound, hut circles and Post Medieval structures. Information from OASIS ID: rosscrom1-177267 (L Fraser and M Peteranna) 2014 Field Visit (1 April 2014) A complex of mostly Post Medieval buildings, enclosures and clearance cairns. There were three irregularly-shaped enclosures all constructed from large stones and boulders. Site 1a had been cut through by a previous water pipeline. Sites 1c and 1d appeared to be folds or pens within enclosures 1a and 1b. Site 1k also formed part of a possible pen. A dyke (Site 1i) running off the south corner of Site 1l may have been part of a head dyke. Three buildings were recorded: the largest (Site 1f) measured approximately 20m x 3m and had a small porch on the south-southwest side. Site 1g was a small sub-rectangular building with two compartments. To the south of site 1g was another building (Site 1h), which was interpreted as a kiln-barn due to the circular nature of its northern compartment (Plate 1). Sites 1m-q were recorded as clearance cairns, although some presented as ‘lumps’ and may have been natural features. The presence of cairns is indicative of former cultivation practices; the lazy beds previously recorded at this site were not visible. Site 2 (NC 79258 04870), located to the northeast of site 1, was a sub-circular, turf-covered stone structure revetted into the slope on the north side with an entrance on the south side. It was interpreted as a possible hut circle. Information from OASIS ID - rosscrom1-177267 (L Fraser and M Peteranna) 2014 Field Visit (1 April 2014) An archaeological desk-based assessment and walkover survey was carried out on 1 April 2014 on behalf of Scottish Water from Loch Farlary to Bridge of Horn, Golspie in advance of the proposed construction of a new water main. The work was undertaken to assess the nature and extent of any archaeology likely to be directly affected by the proposed development in order to inform recommendations for the protection and management of any sites identified. Seven archaeological sites, two of which will be directly impacted by the current development layout, were recorded. These included a burnt mound, hut circles and Post Medieval structures. Information from OASIS ID: rosscrom1-177267 (L Fraser and M Peteranna) 2014 References Harden, J. (1990) 'Survey Dunrobin Glen (Golspie parish)', Discovery Excav Scot, 1990. Page(s): 28

Asset/Event Number	143
Asset/Event Name	Building, Garbhairidh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH58SE 3
HER Number	MHG7367
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257530
Northing	883808
Council	Highland
Condition:	Good
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular modified bothy building that has been constructed from the remnants of the building shown on the 1st edition OS map, which depicts an unroofed structure or pen with a roofed structure to the S. In total the building measures 19m by 5m over walls, and the roofed portion measures 12m long, encompassing the S part. The walls of this stand 2m tall and 0.5m wide, and gable ends stand c6m tall. Entrance in the E elevation with windows flanking the doorway and a fireplace in S gable. The walls to the N stand between 0.3 and 1.5m tall and are constructed from roughly shaped river stones. Possibly a small pen constructed along the N end from the tumbled stone. OS. 1881. Ross-shire & Cromartyshire (Mainland) XXXIX, Surveyed: 1875, Published: 1881. https://canmore.org.uk/site/68474/ Field Visit (14 November 1989) RCAHMS Afforestable Land Survey, Strathrusdale NH58SE 3 575 838 The remains of at least two buildings and several enclosure banks lie in the vicinity of the deserted cottage at Garbhairidh. The first lies 80m NE of the cottage (NH 5757 8387) and measures at least 7.5m by 4.2m over grass-grown walls about 0.6m in height and spread to about 1.5m in thickness. Its S end is truncated by an old stream channel. The second building is attached to a bank 105m N of the cottage (NH 5751 8391); it measures 6.5m from N to S by 4.5m over grass-grown footings spread 1.3m in thickness and from 0.2m to 0.4m in height. What may be fragments of a third building, truncated by the stream, are visible a further 20m to the NW, while a possible fourth lies at the junction of three banks midway between the third building and the deserted cottage. Visited by RCAHMS (SPH) 14 November 1989. Note (21 February 1996) RCAHMS First Edition Survey Project Two unroofed buildings are depicted on the 1st edition of the OS 6-inch map (Ross-shire 1881, sheet xxxix), but they are not shown on the current edition of the OS 1:10000 map (1986). Information from RCAHMS (AKK) 21 February 1996.

Asset/Event Number	144
Asset/Event Name	Garbh-Leathad
Type of Asset/Event	Building (Period Unassigned), Farmstead (Period Unassigned), Rig And Furrow (Medieval) - (P
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND13SW 33.00

HER Number	MHG39370
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313000
Northing	932100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/72002/ Building (Period Unassigned), Farmstead (Period Unassigned), Rig And Furrow (Medieval) ND13SW 33 130 321. Situated S of the Dunbeath Water, 650m W of Loedebest is a post medieval settlement comprising three buildings, associated dykes and field systems. One building (at ND 1288 3204) is small and rectangular and isolated some way to the W of the main settlement. The other two buildings include one small rectangular building and a long house. The long house has stone walls attached to the NW and NE; the wall to the NE forms part of a stone walled enclosure. There are faint traces of wall foundations to the SE of the long house and this could indicate the existence of an earlier settlement on this site. There is evidence for rig cultivation alongside the river. Information from Historic Scotland July 1992. A farmstead comprising one unroofed long building and two enclosures is depicted on the 1st edition of OS 6-inch map (Caithness 1877, sheet xxxviii), but the building at ND 1288 3204 is not shown. Two unroofed buildings and two enclosures are shown on the current edition of the OS 1:10,560 map (1962). Information from RCAHMS (AKK) 5 January 1996.
Asset/Event Number	145
Asset/Event Name	Borgue
Type of Asset/Event	Cruck Framed Cottage (Post Medieval)
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND12NW 29.00
HER Number	MHG18000
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312791
Northing	926030
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/86609/ ND12NW 29 128 260 NGR (ND 128 260) cited by Stell probably refers to open rectangles on 1:10,560 OS map (1965 ed.) at ND 1280 2603. Information from RCAHMS (RJCM), 23 September 1985. References Stell, G. (1981a) 'Crucks in Scotland: a provisional list', in Alcock, N W, Cruck construction:

	An introduction and catalogue, Council for British Archaeology Research Report no.42). London. Page(s): 82 RCAHMS Shelf Number: J.2.ALC.P
Asset/Event Number	146
Asset/Event Name	Bridge Of Horn
Type of Asset/Event	Corn Drying Kiln (Period Unassigned), Enclosure(s) (Period Unassigned), House (Period Unassi
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70NE 50.00
HER Number	MHG19453
Status	Non-designated Heritage Asset
Section:	N/A
Easting	279400
Northing	905000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/91629/ Corn Drying Kiln (Period Unassigned), Enclosure(S) (Period Unassigned), House (Period Unassigned), Hut Circle (Prehistoric)(Possible), Rig And Furrow (Medieval) NC70NE 50 Centred NC 794 050. The footings of a house, enclosures, a corn-drying kiln, numerous clearance heaps and a possible hut circle are on this SW-facing hillside, within a still evident head dyke and foot dyke. There are also signs of rig cultivation, but the site is infested with bracken and heather, making mapping of the features impossible at date of visit. M Macdonald 1994k. Activities Ground Survey (1 April 2014) NC 78764 05100 (centred on) A desk-based assessment and walkover survey were carried out on 1 April 2014 from Loch Farlary to Bridge of Horn, in advance of the proposed construction of a new water main. Seven sites including a burnt mound, hut circles and post-medieval settlement, were recorded. The settlement, located under dense bracken and high grasses, was a complex of buildings on the NE side of the Allt nan Sgeith. It included a probable kiln, pen, enclosures and dykes that appeared to predate the 1872 Ordnance Survey of the area. Within the settlement, one hut circle was recorded along with small clearance cairns, which may be associated with the extensive prehistoric settlement in the glen. The other hut circle and the burnt mound surveyed had been previously identified by the Ordnance Survey. Report: Highland HER, OASIS and RCAHMS (intended) Funder: Scottish Water Lynn Fraser and Mary Peteranna – Ross and Cromarty Archaeological Services (Source: DES) References Fraser and Peteranna, L and M. (2015) Highland, Bridge of Horn, Desk-based assessment and walkover survey, Discovery Excav Scot, New, vol. 15, 2014. Cathedral Communications Limited, Wiltshire, England. Page(s): 108 Macdonald, M. (1994k) 'Bridge of Horn, Dunrobin Glen (Golspie parish): settlement', Discovery Excav Scot, 1994. Page(s): 44
Asset/Event Number	147

Asset/Event Name	Allt Na H-Innse Aonar
Type of Asset/Event	Farmstead (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH79NW 38.00
HER Number	MHG19237
Status	Non-designated Heritage Asset
Section:	N/A
Easting	272500
Northing	899100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	*Recorded by AOC Archaeology during 2024 walkover survey - see sub-elements of Asset 147 and 471 for details. The farmstead is shown as abandoned by the time of the 1st edition OS map. OS. 1879. Sutherland, Sheet CIV, Survey date: 1873-74, Publication date: 1879. https://canmore.org.uk/site/91343/ NH79NW 38 7250 9910 A farmstead, comprising one unroofed building and an enclosure within a field is depicted on the 1st edition of the OS 6-inch map (Sutherland 1879, sheet civ). One unroofed building and one enclosure are shown on the current edition of the OS 1:10560 map (1969). Information from RCAHMS (AKK) 21 November 1995. Innis Aonar. Footings of enclosures noted on the 6''OS map, and of a cruciform building and well-preserved corn-drying kiln were found (Macdonald 1995, fig 18). NH 725 992 The long axis of the cruciform building is c16.5m by 2m, with the extensions being 4m by 2m and 3m by 2m, and slightly offset. NH 725 991 Corn-drying kiln, with 1.5m bowl, flue opening to SE. NH 724 991 Oval outline of stones 4.6m by 2m. Sponsor: Tain Archaeological Group 1995. M Macdonald 1995. References Macdonald, M. (1995l) 'Dalnamein (Dornoch parish), multi-period', Discovery Excav Scot, 1995. Page(s): 47 Fig 18 Ordnance Survey (Name Book. (1848-1878) Object Name Books of the Ordnance Survey (6 inch and 1/2500 scale). Page(s): Book No. 9, 112 RCAHMS Shelf Number: Ref
Asset/Event Number	148
Asset/Event Name	Boath Farmstead
Type of Asset/Event	Farmstead (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH57NE 25.00
HER Number	MHG18719
Status	Non-designated Heritage Asset
Section:	N/A
Easting	255700
Northing	875100

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	*Recorded by AOC Archaeology during 2024 walkover survey -Asset 148/NH57NE 25.00/MHG18719 is to the immediate E of Asset 141/NH57NE 24.00/MHG8407. It seems likely that, given the title of this asset and its location amidst the post-medieval settlement remains and improved fields described in the Asset 141 listing, that this is a duplication of the same.* Https://canmore.org.uk/site/90002/ No description on Canmore. Https://her.highland.gov.uk/Monument/MHG18719 No description on HER.
Asset/Event Number	149
Asset/Event Name	Garvary, Suspension Bridge
Type of Asset/Event	Footbridge (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH58NE 8.00
HER Number	MHG18712
Status	Non-designated Heritage Asset
Section:	N/A
Easting	259660
Northing	886170
Council	Highland
Condition:	Good
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey* A pedestrian suspension bridge constructed from metal leads across the Wester Fearn Burn. Https://canmore.org.uk/site/90011/ No description. Https://her.highland.gov.uk/Monument/MHG18712 No description.
Asset/Event Number	150
Asset/Event Name	Loch Toftingall
Type of Asset/Event	Township (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND15SE 16.00
HER Number	MHG18918
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319600

Northing	952300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	See sub-elements of Asset 150 for details. Https://canmore.org.uk/site/90832/ RCAHMS First Edition Survey Project A small township comprising three unroofed buildings, one of which is a long building, and an enclosure, all lying within an area of cultivation is depicted on the 1st edition of the OS 6-inch map (Caithness 1877, sheet xxiii). A two compartment enclosure and a sheepfold are shown on the current edition of the OS 1:10000 map (1976). Information from RCAHMS (SAH) 23 November 1995
Asset/Event Number	151
Asset/Event Name	Leathad Breac
Type of Asset/Event	Farmstead (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH69NW 36.00
HER Number	MHG18357
Status	Non-designated Heritage Asset
Section:	N/A
Easting	261450
Northing	897080
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/91368/ RCAHMS First Edition Survey Project A farmstead, comprising two unroofed buildings and an enclosure, and some field walls are depicted on the 1st edition of the OS 6-inch map (Sutherland 1879-81, cviii) and on the current edition of the OS 1:10560 map (1970). Information from RCAHMS (AKK) 22 November 1995.
Asset/Event Number	152
Asset/Event Name	Acharole
Type of Asset/Event	Building (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND25SW 37.00
HER Number	MHG18400
Status	Non-designated Heritage Asset
Section:	N/A
Easting	322300
Northing	951400
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/90905/ RCAHMS First Edition Survey Project An unroofed long building is depicted on the 1st edition of the OS 6-inch map (Caithness 1877, sheet xxiii), but it is not shown on the current edition of the OS 1:10000 map (1994). Information from RCAHMS (SAH) 23 November 1995
Asset/Event Number	153
Asset/Event Name	Acharole
Type of Asset/Event	Building (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND25SW 43.00
HER Number	MHG19135
Status	Non-designated Heritage Asset
Section:	N/A
Easting	322100
Northing	951900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/90911/ RCAHMS First Edition Survey Project An unroofed building is depicted on the 1st edition of the OS 6-inch map (Caithness 1877, sheet xxiii), but it is not shown on the current edition of the OS 1:10000 map (1994). Information from RCAHMS (SAH) 23 November 1995
Asset/Event Number	154
Asset/Event Name	Glen Glass, 'Garabil'
Type of Asset/Event	Clearance Cairn(s) (Period Unassigned), Head Dyke (Post Medieval), Township (Period Unassi
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH56NE 26.00
HER Number	MHG14142
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256100
Northing	869000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/92101/ NH56NE 26 centred 561 690. This site consists of the footings of five features, of drystone construction, overgrown with

	gorse and is now in very boggy ground of bog myrtle and juniper. The name appears on the first edition 6" OS map with one ruin and has an entry in the OS name book, but local and estate enquiries have turned up no further information. (1) Turf-covered footings measuring 4.5m by 3m: walls are 1m thick. (2) Enclosure measuring 13m by 7.5m. (3) Footings measuring 6m by 3m, with a large pile of stones at one end. (4) Thick-walled feature, very overgrown with whins, measuring 12m by 3m. (5) An enclosure measuring c 6m by 6m. In the field to the N/W are large clearance heaps. The site may be Norse in origin. M Macdonald 1994a. What may be a township, comprising four unroofed buildings and a head-dyke are depicted on the 1st edition of the OS 6-inch map (Ross-shire & Cromartyshire 1881, sheet lxiv), but they are not shown on the current edition of the OS 1:10000 map (1992). Information from RCAHMS (AKK) 29 February 1996. References Macdonald, M. (1994a) 'Garabil, Glen Glass (Alness parish): settlement', Discovery Excav Scot, 1994. Page(s): 38
Asset/Event Number	155
Asset/Event Name	Langergill
Type of Asset/Event	Farmstead (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND15SE 20.00
HER Number	MHG19047
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318800
Northing	954700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/90861/ ND15SE 20 188 547 Longhouse farm (ND 1882 5477), comprising; A: Longhouse. Dimensions: 23 x 6m. Tripartite rectangular structure with a fireplace in the ESE unit. Orintation ESE-WNW. B: Longhouse/ outhouse. Dimensions: 7 x 5m. Bipartite rectangular structure following the same line as A. Orientation ESE-WNW. C: Mill. Dimensions: 7 x 5m. Rectangular structure associated with mill machinery and a lade running N lying 24m N of A. Orientation N-S. D: Dam. Diameter: 18m. Circular grassy bank 1.5m high at the other end of the lade. R J Mercer, NMRS MS/828/19, 1995 A farmstead comprising one roofed long building, one unroofed building and three enclosures is depicted on the 1st edition of the 6-inch map (Caithness 1877, sheet xviii). An unroofed building is shown on the current edition of the OS 1:10000 map (1976). Information from RCAHMS (SAH) 6 December 1995
Asset/Event Number	156
Asset/Event Name	Black Burn

Type of Asset/Event	Building (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND15SE 49.00
HER Number	MHG20030
Status	Non-designated Heritage Asset
Section:	N/A
Easting	319530
Northing	953680
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/96437/ ND15SE 49 1953 5368 Structure. Dimensions: 8.5 x 5m. Rectangular structure. Orientation E-W. R J Mercer, NMRS MS/828/19, 1995

Asset/Event Number	157
Asset/Event Name	Lodge Roques
Type of Asset/Event	Building (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND25SW 67.00
HER Number	MHG19994
Status	Non-designated Heritage Asset
Section:	N/A
Easting	321200
Northing	953300
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/96450/ ND25SW 67 2120 5330 Longhouse (ND 2117 5330). Dimensions: 14 x 5m. Rectangular structure, the N end of which is reduced to a rubble spread, the S end containing a fireplace. Orientation N-S. R J Mercer, NMRS MS/828/19, 1995 One roofed and one partially roofed building are depicted on the first edition of the OS 6-inch map (Caithness 1877, sheet xviii). One unroofed building is shown on the current edition of the OS 1:10,000 map (1994). Information from RCAHMS (FO) 26 March 1996

Asset/Event Number	158
Asset/Event Name	Viewfield
Type of Asset/Event	Structure(s) (Period Unassigned)
Date and/or Period	Post-medieval

Listing No./NRHE Number	ND25SW 68.00
HER Number	MHG20025
Status	Non-designated Heritage Asset
Section:	N/A
Easting	321490
Northing	953120
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/96451/ ND25SW 68 2149 5312 Structure (ND 2149 5315), Viewfield. Dimensions: 6.6 x 5m. Rectangular structure, probably a small croft containing a fireplace. Orientation E-W. R J Mercer, NMRS MS/828/19, 1995 Two unroofed structures are depicted on the first edition of the OS 6-inch map (Caithness 1877, sheet xviii) and on the current edition of the OS 1:10,000 map (1994). Information from RCAHMS (FO) 26 March 1996
Asset/Event Number	159
Asset/Event Name	Caen
Type of Asset/Event	Head Dyke (Post Medieval), Township (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND01NW 72.00
HER Number	MHG20250
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301700
Northing	917700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/97764/ ND01NW 72 centred on 017 177 A township comprising two roofed and sixteen unroofed buildings, nine enclosures, a field and a head-dyke is depicted on the 1st edition of the OS 6-inch map (Sutherland 1879, sheet lxxix). Four roofed and ten unroofed buildings, eight enclosures, one of four compartments, some field walls and a head-dyke are shown on the current edition of the OS 1:10560 map (1964). Information from RCAHMS (SAH) 13 October 1995.
Asset/Event Number	160
Asset/Event Name	Druim Dubh
Type of Asset/Event	Farmstead (Period Unassigned)
Date and/or Period	Post-medieval

Listing No./NRHE Number	ND25SW 60.00
HER Number	MHG19814
Status	Non-designated Heritage Asset
Section:	N/A
Easting	320600
Northing	952200
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/96100/ ND25SW 60 206 522 Longhouse (ND 2066 5225). Dimensions: 22.5 x 5m. Rectangular tripartite structure. Orientation E-W. Longhouse (ND 2064 5223), 'Druim Dubh'. Dimensions: 36 x 5m. Rectangular structure divided into five compartments. The E two units contain opposing fireplaces, the central unit possesses byre slots. Two lean-tos have been built against the N long wall. It is associated with a complex of enclosures, measuring 26 x 15m. Orientation E-W. R J Mercer, NMRS MS/828/19, 1995 Three roofed buildings are depicted on the first edition of the OS 6-inch map (Caithness 1877, sheet xxiii). One unroofed building is shown on the current edition of the OS 1:10,000 map (1994). Information from RCAHMS (FO) 20 March 1996
Asset/Event Number	161
Asset/Event Name	Cnoc Na Maranaich
Type of Asset/Event	Building (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND13SW 45.00
HER Number	MHG20290
Status	Non-designated Heritage Asset
Section:	N/A
Easting	313320
Northing	932820
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/97726/ RCAHMS First Edition Survey Project A single unroofed building is depicted on the 1st edition of OS 6-inch map (Caithness 1877, sheet xxxviii) and on the current edition of the OS 1:10560 map (1962). Information from RCAHMS (AKK), 5 January 1996
Asset/Event Number	162
Asset/Event Name	Borgue, Longall, Croft

Type of Asset/Event	Croft (Period Unassigned), Cruck Framed Cottage (Post Medieval)
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND12NW 60.00
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	312800
Northing	926230
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/101425/ No description. https://her.highland.gov.uk/Monument/MHG24189 No description.

Asset/Event Number	163
Asset/Event Name	Rogie
Type of Asset/Event	Enclosure (Period Unassigned), Head Dyke (Post Medieval), Township (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH46SW 3.00
HER Number	MHG24412
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243900
Northing	860000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/103155/ NH46SW 3 centred on 439 600 A township comprising three roofed, one partially roofed and thirteen unroofed buildings, eight enclosures and two short lengths of head-dyke is depicted on the 1st edition of the OS 6-inch map (Ross-shire and Cromartyshire 1881, sheet lxxv). Ten unroofed buildings and four enclosures are shown on the current edition of the OS 1:10000 map (1989). Information from RCAHMS (SAH) 28 February 1996 Activities Field Visit (February 2008 - May 2009) Publication Account (2009) Forest Heritage Scotland The website text produced for Rogie webpages on the Forest Heritage Scotland website (www.forestheritagescotland.com).

Introduction: A lovely little world of its own

This is how Nan Bray, from New Zealand, recalls growing up on Rogie farm during the Second World War.

Rogie farm lies close to the abandoned township of Rogie. In the 1940s only the McQueens still lived there; they were Nan's only neighbour. As a young girl Nan often felt isolated. Rogie was not easy to travel to, so few people visited. They did not even have electricity or a telephone.

In the past, however, Rogie had been a thriving farming community. Historical records show that in 1792 at least twelve families were living and paying rent at the township of Rogie.

At this time the township was part of the Coul Estate owned by the MacKenzies. In 1795 George MacKenzie inherited his father's land, fortune and title and, soon after, began to evict farming tenants from his land.

Mackenzie cleared Rogie in 1808. Shepherds moved in to the area instead to work on the new sheep farms. Nan Bray's memoirs tell us that over the following century many families, including her own, moved to New Zealand and Canada to find a new life.

The remains of the township are still visible spread across the Torrachilty forest clearing. Yet evidence of more may still be hidden within the trees and grassland surrounding them. Why not explore it for yourself?

People Story: The plan of mice and men….

Sir George McKenzie's obituary in the local newspaper described him as a landlord who was….

[i]
" substantially kind and liberal and disposed towards improvements",[/i]
Inverness Courier, November 9, 1848

Today it is difficult to see how he could be both.

Sir George MacKenzie held strong views about the need to improve the way that land was farmed in the Highlands. He did not believe that his small farm tenants had the money or capability to adapt to new ways of farming. These tenants, like the families at Rogie, were removed and replaced with large sheep farms.

Yet Mackenzie recognised that the people he moved would not like his actions. He even invested in a wool factory to create more jobs for those who lost their farms, but it was unsuccessful and closed.

Sir George MacKenzie believed that these changes would make more money and help the economy of the Highlands.

Ironically, Dr John MacKenzie noted that Sir George's tenants were hard workers, who always paid their rents. This MacKenzie believed that Sir George made more money with the old tenant system than he did from his so called [i]"improvements"[/i], the sheep farms.

If this was true it would seem that all Sir George's grand plans were for little gain, but caused a lot of people's lives to change completely. It is only fair to note, however, that Dr John MacKenzie went bankrupt trying to keep the old tenant system on his own land.

Srp Note (12 April 2012) Scotland's Rural Past (SRP)
In an area of perhaps half a square kilometre and centred on a rounded hill to the north of Rogie Farm and the railway line there are the remains of a large enclosure and 5 discrete settlements. The composition of the settlements is variable, some have just 1 building and 1

enclosure, others have several buildings with up to 2 enclosures. The central focus is the hill, around which there are the remains of a discontinuous stone and turf wall, several clearance cairns lie within the enclosure particularly in the NW part. The settlements are contiguous with the enclosure wall at varying intervals. The whole area has been grossly disturbed by forestry, having been planted with trees, felled, ploughed and replanted again. In addition the drainage has been substantially disturbed by forest roads and tracks - many areas, which would in the past have been well drained, are now marshy. The township is shown on the 1st edition OS map as 1 partially roofed building, 14 unroofed buildings, 6 enclosures and a head dyke. The enclosure and surrounding wall with a few associated features are described first followed by each settlement the structures of which have been grouped together. The individual settlements/farmsteads are described from the northeast working in an anticlockwise direction and are numbered A to F - see plan.

Enclosures (NOSAS survey site nos 54, 49 and 50)
54 Enclosure/Wall - NH 43746 59852 (SW corner/junction) A discontinuous wall defines an enclosure some 400m x 200m in size, it is now mostly planted with young trees but in the north part there are some open grassy ploughed areas. In the SW and W the wasted dry stone wall is clearly defined and 0.5m in height. To the north it is ploughed out and barely discernable. The east and south part appears to have been destroyed by the forest roads. To the south of the area and just SW of a prominent crossroads there are two features:
49 Clearance cairn - NH 44063 59918 A large cairn piled up against a prominent boulder.
50 Possible enclosure - NH 44046 59910 Two parallel stone and turf banks running parallel and 7m apart may be the remains of an enclosure. They are 0.7m height, have a spread of 2m and length of 12m. The whole area was overgrown with bracken at time of recording.
A. North-East settlement (NOSAS survey site nos 32 - 39) centred on NH 4416 6007 - comprises 4 buildings and 2 enclosures. The drainage of the settlement has been grossly affected by the construction of the road, it is now very marshy. Known as MacQueens Croft.
32 Building - NH 44253 60095 An L-shaped building with an outshot close to and on the west side of a small burn. The main compartment is rectangular and aligned NE-SW. It measures 8 x 3.5m internally and is recessed into a knoll at its SW end where the well made stone face of the gable is 1.5m high. The remaining stone wall footings are 0.5 - 1m high and 0.8m thick. There is an entrance in the centre of the SE wall.
The outshot to the SE is 4 x 4m and the walls are very wasted being 0.3m high with a spread of 1.5m. The structure is overhung with trees.
33 Building - NH 44209 60062 This rectangular structure on a slight knoll is aligned NE-SW and measures 6 x 2.5m internally. The remains of the substantial dry stone walls are 0.5 - 1m in height, the gable to the west is 1m high, and have a spread of 1.5m. Planted with trees. There may be an outshot to the SW indicated by truncated walls at the corners and a grassy platform c4.5 x 3m.
34 Enclosure - NH 44196 60045 An irregular shaped enclosure roughly 14 x 11m in the centre of an overgrown marshy area. There are substantial stone walls up to 1m height with a spread of 2m. The whole is overgrown with reeds and brambles. There is a possible entrance in the west of 2m width.
35 Building (alternative name - MacQueens croft) (figures 6 and 7) - NH 44165 60069 The main building of this settlement. It is the westernmost of 2 with an enclosure, 37, to the rear. The building has 2 compartments and an outshot to the SW. It has an internal measurement of 11m x 3.5m, with the main compartment to the west being 6m in length. The tumbled dividing wall is 0.5m high and has a spread of 1m. The walls are of dry stone construction, double faced and 0.7m in thickness. The rear wall is generally 1m in height and turfed up on the outside. The NE gable is 1.5m high and the SW 1.2m. The front wall is tumbled for the main part, 0.5m high and with a spread of 1.5m, although the eastern area is better preserved and there is an entrance into the NE compartment.
The outshot to the SW is more roughly constructed with walls to a height generally of 1m, it measures 3m x 2m and has an entrance in the E corner next to the main building.
This building is thought to be MacQueens croft. A photograph taken in the 1920s, is attached.
36 Building - NH 44169 60078 Immediately to the north of 35 this building on the same NE-SW alignment has 2 compartments and an overall internal measurement of 13m x 3.5m. The west compartment is better preserved and measures 5m x 3.5m. The walls are of dry stone construction, double faced and 0.7m in thickness. The SW gable is 2m in height, the rear NW wall 1 - 1.2m high, the SE wall 0.8m high and the dividing wall is 0.5m high. There is an

entrance 0.7m wide at the E end of the SE wall. The NE compartment is 7m x 3.5m and much more wasted, although the rear wall is 1m in height and the NE end has an external height of 1m. Otherwise it is generally 0.3m high. A large part of the SE wall is missing (alternatively this may have been a wide entrance).
37 Enclosure - centred on NH 44157 60079 An irregular enclosure to the rear/northwest of buildings 35 and 36. It is roughly 25m x 15m and is bounded by the remains of a stone wall, 0.5 -0.8m high in the NE part but much more wasted in its SW part. A line of trees are growing along the wall. The internal area is grassy and deeply ploughed but not planted
38 Clearance cairn - NH 44126 60107
39 Cup marked stone - NH 44057 60095 details of this feature are included with the main group of cup marked stones 350m to the SW

B. Middle North settlement (NOSAS survey site nos 40 - 44) - centred on NH 4400 6012. Comprises 4 buildings, one corn drying kiln and 1 enclosure. Much of the area is marshy, the drainage having been affected by the construction of forest roads.
40A Enclosure - centred on NH 44004 60103 A rectangular enclosure aligned NNW-SSE is 18m x 13m. It is surrounded by a moss covered wall which is, for the most part, of stone. The general level of the enclosure is raised above that of the surrounding ground which is marshy. The height of the wall is generally 1m on the outside and 0.5m on the inside. A number of trees are growing along the line of the wall. This is most probably a garden.
To the south of the enclosure there are two lengths of wall within a plantation of young trees, it is difficult to determine their extent, but they are probably associated with this settlement:
B Wall - centred on NH 44068 60084 This curvilinear wall is 23m in length and aligned NW-SE, it is 0.3-0.5m in height, and has a 2m spread.
C Wall - centred on NH 44046 60070 and at right angles to 40B this wall has been greatly disturbed by forest ploughing.
41 Building - NH 43998 60114 A rectangular building, aligned ENE-WSW, with 2 compartments. The east compartment is better preserved and has internal dimensions of 5.5 x 3m. The dry stone walls are double faced, 0.8m thick, and generally 1m in height, although the east gable is 2m high. There is an entrance at the west end of the south wall and a nice pair of cruck slots, opposite one another in the long walls. The west compartment is much more wasted with the walls being 0.3-0.5m height, although at the west end, where it is recessed into the bank, the stone face is 0.8m high.
There are two lengths of wall abutting; the one to the north stretches for 7.5m in a NNW direction and is of stone and turf construction, 0.5m high, the one to the south is of turf, it is 7m long and 1m in height. Both of these walls may be all that remains of an enclosure shown on the 1st edition OS map, the rest of it having been destroyed by the construction of the forest road nearby.
42 Building - NH 44001 60120 This is the main building of the settlement, it is aligned E-W and has internal dimensions of 16m x 4m. The internal area is raised above that of the surrounding land and is divided into 2 equally sized compartments by a setting of upright slabs 0.4m in height. The west compartment appears to be the main one, the walls here are generally 0.8-1m height (1-1.5m outside) but the west gable is 1.6m. On the outside this gable is 2m high and has complex buttressing, with a stone plinth 4m x 1.5m x c1.5m height covered by tumble.
The east compartment walls are generally 0.5m high (0.8m outside) although the east gable is 1m high (1.3m outside), and here again there appears to have been a form of “buttressing” supporting the gable. Internally there is an obvious drain, 0.4m deep, down the centre of the compartment and an entrance at the west end of the south wall.
An outshot to the east, in the form of a level platform, 2.5m x 2.5m, with a stone edge of 0.3m height may be a former building on this site. It is set at a slight angle to the main building and may indicate the line of an earlier building.
42A Building - Immediately to the north of 42, turf footings of what may be small building can be seen. It has the form of an L shaped turf bank, 0.3-0.5m in height with a spread of 1.5m.
43 Kiln and barn - NH 44009 60135 Aligned E-W this structure has an overall measurement of 7m x 3m. The kiln is of dry stone construction and well preserved, it is generally 1.6m high. The bowl has a diameter of 1.8m and it is 0.5-1m deep although although there is tumbled material inside. Unusually there are two flues in the straight west face which is 1.1m in height. The south one appears blocked although it can be probed to a depth of

0.9m, it has an aperture of 1m width x 0.3m height externally, narrowing to 0.3m width x 0.1m height. The north flue is 0.5m wide, 0.2-0.4m depth and 1m in length. Externally there is an abutting feature on the SE side of the structure, this has the form of a rising ramp of large stones and may have been steps up to the top of the kiln.
The internal area of the barn to the east is raised above the level of the surrounding ground. It is 6m x 2.5m internally and the remains of the walls are 0.3-0.5m height inside (0.6-1m outside). There is an entrance 0.7m in width at the east end of the south wall.
44 Building - NH 44021 60123 A few metres to the SE of the kiln the very wasted remains of this structure appear as a rectangular marshy depression. The structure is aligned ENE-WSW and has an overall measurement of 9m x 4m. Several large moss covered boulders outline the walls of the structure; the rest of the walls may have been robbed. The walls have a height of 0.5-0.6m inside (0.2-0.5m outside). There may be an entrance in the south wall.

C. NW Settlement (NOSAS survey site nos 59 - 65) centred on NH 438 601- Comprises two farmsteads within 100m of each other. The NE farmstead has 2 buildings, a corn-drying kiln, an enclosure and a small pen (61 – 65). The SW farmstead has 1 building and 1 enclosure (59 – 60).The remains of the dry stone walls of both farmsteads are in the main, quite low and between 0.8-1m in thickness, they are moss covered and possibly robbed of their stone. The NE farmstead is on a level shelf which slopes off to the north and west. The SW farmstead is on level ground within the forested area close to a small burn
61 Building/Possible Byre - NH 43796 60120 An L-shaped building, on a ENE-WSW alignment, comprising 3 compartments:
- The main, largest compartment, to the west, measures 7.8m x 3.8m internally, with the extension to the NW of an additional 4.4m x 3m. The dry stone walls in the south and west part are 0.2-0.3m high whilst those to the north are 0.6m high externally and that at the north end of the extension is 1.2m. A few features were noted - 1. An entrance in the SE wall possibly 1m in width, although the surviving aperture suggested 1.8m in width. 2. A stone edged drain in the E part of the compartment is 0.3m wide x 2m length x 0.2m deep. A possible further one is seen in the west part, see plan. 3. A regular moss covered stone plinth to the rear/N of the building. It measured 2m length x 0.6m width x 0.5m height. It may have been buttressing for the wall.
- The central compartment measures 1.8m x 3.8m and has an entrance of 1.2m in width in the south wall. The walls are very variable in height from 0.2-0.7m.
- the east compartment is 4.4m x 3.6m internally and the walls are 0.3-0.5m high. A stone edged drain 0.4m wide x 1.8m length x 0.3m deep occupies a central position. Adjacent to the east a roughly circular depression 1.6m diameter x 0.4m deep may be a stank or a sump.
To the SE of the building a terrace runs along the length of the building. It is 2m width in the west part and 1.2m in the east part. It is bounded by large boulders with a drop 0.3-0.5m to a marshy depression which appears to be man-made. The marshy depression is 8m N-S x 16m SW-NE narrowing at the NE end. It has steep banks to the south and east.
At the SE corner of the building a stone lined void, 0.2 x 0.2m x 0.8m depth may be the socket for a timber post. At the NE corner, the wasted turf and stone wall of enclosure 54 abuts 62.

62 Building - NH 43787 60116 A rectangular building on a NNW-SSE alignment, probably the main dwelling house of the farmstead. It measures 13.8m x 3.4m internally. The remains of the dry-stone walls are 0.4-0.5m high in the south part but 1-1.2m at the north end. There are two entrances, both 1m in width, in the east wall
63 Corn-drying kiln and barn - NH 43778 60124 A rectangular structure on a sloping E-W alignment comprising two parts - the bowl and the barn:
- the bowl at the east end is recessed into the slope. It is c 0.5m deep but filled with tumble. A defining edge of stonework is seen in places and possibly a scarcement, 0.5m in width, around the upper edge.
- the barn is 9m x 3.2m internally and recessed at its east end where the face of the kiln is 0.8m high, tumble obscured any flue that might exist. The stone walls at the east end were 1m in height internally but barely discernable externally. At the west end they were 0.6-0.8m high, both internally and externally. An obvious entrance, 0.7m in width, existed at the west end of the south wall and a possible drain was 0.3m deep.
64 Enclosure - NH 43783 60108 A rectangular enclosure on a NNW-SSW alignment measures 11m x 6m internally. The remains of crudely built stone walls on three sides are largely tumbled but generally 0.5m high and with a spread of 1.5m. There is no evidence of a wall

on the east side but this may have been provided by the west wall of building 62. To the west a possible track ran up the hill along the outside of the enclosure and at the north end the wall of enclosure 54 curves off in a southerly direction.
65 Pen - NH 43770 60102 Situated in an angle of wall 54 a few metres to the west of the settlement. This small pen is aligned N-S and measures 3m x 1m. The walls are of single stone thickness and are 0.6-0.7m high.
59 Building - NH 43731 60050 A rectangular structure on a NE-SW alignment measures c7.5m x 2.5m internally. The remains of the dry stone walls are generally 0.5-0.6m high and have a spread of 0.8m. There is a considerable amount of tumble in the NE end of the building and an entrance, 0.7m wide in the SE wall. The building is grass and moss covered and has been planted with trees
60 Enclosure - NH 43742 60042 A few metres to the south of 59, this enclosure is in a sheltered position close to a small burn. It abuts the wall of the main enclosure 54 and is D shaped, on a WSW-ENE alignment and measure 13m x 12m internally. The remains of the dry stone walls which are 0.3-0.7m high and have a 1-1.5m spread are more substantial in the north and east parts.

D. Middle west settlement (NOSAS survey site nos 55 - 58) - centred on NH 4375 5992 This settlement comprises 3, possibly 4 buildings, and an enclosure.
55 Building - NH 43737 59878 This small rectangular building, 40m to the south of the main group, abuts the wall of enclosure 54 and is grossly overgrown with trees, heather and moss. It is roughly square and measures c4m x 4m internally. The walls have been crudely constructed of stone and are better preserved on the west side where they are 0.5m high. This building is marked on the FES.
56 Building - NH 43745 59917 A small rectangular building a few metres to the south of the main building 57. It is aligned WNW-ESE and measures c4m x 3m internally. The dry stone walls are of rough construction, generally 0.5m high and 0.6m thick. There is a possible entrance, 0.8m in width, at the east end of the S wall.
57 Building - NH 43742 59919 This the main building is just 1.5m to the north of 56 and on the same alignment. It measures c6.5m x 3.2m internally. The remains of the dry-stone walls are 0.6m in height and 0.7m thick, but the west gable which appears to be largely intact and is 1.4m high and the east gable is 0.8m high. There is an entrance, 0.6m width, in the centre of the S wall.
57A Possible building - NH 43756 59921 This may be an outshot to the east of 57. Circa 11 metres to the east of 57 and slightly offset there is evidence of a further building in the form of a well built dry stone “end” wall. It is 0.7m high, with 1m spread and is 4m in length. In between this and 57 there is a slight rectangular depression, c 6m x 3m with a barely discernible low turf wall to the north. The extent of the building is difficult to make out because of forest ploughing and planted trees.
58 Enclosure - NH 43773 59920 A roughly square enclosure to the east of 57 and 56 measures c14m x 14m. It is surrounded by a substantial dry stone wall which in all probability has clearance material dumped in it. The wall is generally 0.4-0.5m high and has a spread of 1.5m but the west wall is 0.6m high. The enclosure is grassy, has been ploughed but not planted with trees
76 Enclosure - NH 43976 59607 Situated on the south side of a bracken covered knoll to the south of the railway and just 120m to the SW of the level crossing, the very wasted remains of the stone walls of this enclosure are seen. It appears to be roughly rectangular although its extent at the west side is uncertain. It is on an ENE-WSW alignment and c15m x 9m. The walls are obvious on the E and S side and are roughly 0.3m high, less obvious to the west and north. The whole area is significantly disrupted by forest operations with deep pits, brashings and newly planted trees overall.

E. SW settlement and quarry (NOSAS survey site nos 51 - 53 also 47 and 48) Centred on NH 4373 5977 This settlement of one building and one enclosure occupy a broad wooded knoll to the SW of the main enclosure, 54, a further small enclosure and a stretch of wall on a nearby knoll to the east has been included. A quarry, possibly associated with the railway, has also been included.
51 Quarry - NH 43742 59806 Probably associated with the railway and of more recent origin than the settlement which is situated immediately to the SW
52 Building - NH 43733 59777 The rectangular building aligned N-S and measuring 8m x 3m internally. The dry stone walls are double faced, 0.8m thick and generally 0.6m in height.

	Although the north gable, which is almost intact, is 1.6m high - it has a large alcove, 0.5m width x 0.6m height x 0.6m depth. There is an entrance of 0.7m width in the east wall. The building was very much overgrown with bracken at time of recording. 53 Enclosure - centred on NH 43687 59760 A large rectangular enclosure aligned ENE-WSW is roughly 100m x 50m and occupies a large undulating knoll. The surrounding stone wall is most evident in the west and north where it is generally bracken covered and c0.3-0.5m in height. It is not evident in the south part although there is a short turf stretch to the south of building 52 47 Wall - NH 43783 59756 (S end) A 28m length of wall crosses a west facing slope on the opposite side of the forest track to the east of building 52. It is 0.4m high, has a spread of 0.6m and is generally very wasted. It may have been part of an enclosure. The wall may continue to the south around the hill on the north side of the road, but the rest of the wall has been destroyed by forestry tracks and the railway. 48 Enclosure - centred on NH 43800 59736 A few metres to the south of 47 this square enclosure is was greatly overgrown with bracken at the time of recording. It is 11m x 11m internally and the wasted stone walls which are quite evident are up to 0.4m in height.
Asset/Event Number	164
Asset/Event Name	Enclosure, Cnoc an Fasgnaidh
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH56NE 30.00
HER Number	MHG20086
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256051
Northing	868713
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Low stone and turf covered mound surviving to less than 0.5m in height. Appears to be square or sub circular in shape, but only survives at SW end, other end presumably destroyed by planting of forestry. Cse NW oriented, however it is slightly curved. Https://canmore.org.uk/site/103699/ RCAHMS First Edition Survey Project An enclosure is depicted on the 1st edition of the OS 6-inch map (Ross-shire & Cromartyshire 1881, sheet lxiv) and on the current edition of the OS 1:10000 map (1992). Information from RCAHMS (AKK) 29 February 1996.
Asset/Event Number	165
Asset/Event Name	Boath
Type of Asset/Event	Farmstead (Period Unassigned), Lime Kiln (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH57SE 24.00
HER Number	MHG20469
Status	Non-designated Heritage Asset
Section:	N/A

Easting	256910
Northing	873491
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/103738/ RCAHMS First Edition Survey Project A farmstead comprising one unroofed building attached to a field wall, and a limekiln are depicted on the 1st edition of the OS 6-inch map (Ross-shire and Cromartyshire 1880, sheet lii). A field wall is shown on the current edition of the OS 1:10000 map (1990). Information from RCAHMS (SAH) 23 February 1996
Asset/Event Number	166
Asset/Event Name	Farmstead, Boathmore
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH57SE 25.00
HER Number	MHG20470
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256710
Northing	873650
Council	Highland
Condition:	Very Degraded
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Rectangular building under grass and heather, measuring c35m by 5.5m over walls. At least one central partition, forming two room with the NW measuring 7m internally by 4, the SE c23m long. Very degraded walls that stand up to 0.3m tall and 0,65m wide except at the partition wall, which stands 0.9m tall in parts. Entrances not discernible and stone spread extends from the SW elevation. Depicted on the 1st edition OS map as an unroofed building. Https://canmore.org.uk/site/103739/ RCAHMS First Edition Survey Project A farmstead comprising one unroofed long building lying adjacent to an area of cultivation is depicted on the 1st edition of the OS 6-inch map (Ross-shire and Cromartyshire 1880, sheet lii), but it is not shown on the current edition of the OS 1:10000 map (1990). Information from RCAHMS (SAH) 23 February 1996
Asset/Event Number	167
Asset/Event Name	Boath
Type of Asset/Event	Farmstead (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH57SE 27.00
HER Number	MHG20472
Status	Non-designated Heritage Asset
Section:	D1.1

Easting	256390
Northing	873770
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	*Recorded by AOC Archaeology during 2024 walkover survey - see sub-elements of Asset 167 for details. Https://canmore.org.uk/site/103741/ RCAHMS First Edition Survey Project NH57SE 27 5639 7377 Glack: "…the most westerly farm in Boath…" Name book 1881 A farmstead comprising one unroofed and four roofed buildings and an enclosure is depicted on the 1st edition of the OS 6-inch map (Ross-shire and Cromartyshire 1880, sheet lii). One unroofed building and two enclosures are shown on the current edition of the OS 1:10000 map (1990). Information from RCAHMS (SAH) 23 February 1996 References Ordnance Survey (Name Book. (1848-1878) Object Name Books of the Ordnance Survey (6 inch and 1/2500 scale). Page(s): Book No. 38, 165 RCAHMS Shelf Number: Ref
Asset/Event Number	168
Asset/Event Name	Ruigh Na Meinne
Type of Asset/Event	Head Dyke (Post Medieval), Township (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH58NE 12.00
HER Number	MHG20630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256000
Northing	889100
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/103752/ RCAHMS First Edition Survey Project A township comprising five unroofed buildings, two enclosures and a head-dyke is depicted on the 1st edition of the OS 6-inch map (Ross-shire and Cromartyshire 1881, sheet xxvi). Three unroofed buildings, three enclosures and a head-dyke are shown on the current edition of the OS 1:10000 map (1992). Information from RCAHMS (SAH) 16 February 1996
Asset/Event Number	169
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	

Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	170
Asset/Event Name	Aultgowrie Bridge
Type of Asset/Event	Farmstead (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45SE 9.00
HER Number	MHG24740
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247600
Northing	850700
Council	Highland
Condition:	Various
Alignment:	Various
Importance:	Negligible/Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey - see sub-elements of Asset 170 for details. Https://canmore.org.uk/site/103414/ RCAHMS First Edition Survey Project A farmstead comprising one unroofed long building, two unroofed structures, an enclosure and a length of field wall is depicted on the 1st edition of the OS 6-inch map (Ross-shire 1875-81, sheet xcviii), but it is not shown on the current edition of the OS 1:10000 map (1992). Information from RCAHMS (SAH), 7 March 1996.

Asset/Event Number	171
Asset/Event Name	Strathan
Type of Asset/Event	Building (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45SE 15.00
HER Number	MHG24713

Status	Non-designated Heritage Asset
Section:	N/A
Easting	245470
Northing	852520
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/103417/ RCAHMS First Edition Survey Project An unroofed building is depicted on the 1st edition of the OS 6-inch map (Ross-shire 1875-81, sheet xcviii), but it is not shown on the current edition of the OS 1:10000 map (1992). Information from RCAHMS (SAH) 7 March 1996
Asset/Event Number	172
Asset/Event Name	Seileach Mor
Type of Asset/Event	Building (Period Unassigned), Enclosure (Period Unassigned), Farmstead (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45SW 2.00
HER Number	MHG24680
Status	Non-designated Heritage Asset
Section:	N/A
Easting	242220
Northing	854690
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/103371/ NH45SW 2 4222 5469 A single unroofed building is depicted on the 1st edition of the OS 6-inch map (Ross-shire 1881, sheet lxxxvii). One unroofed building of two compartments is shown on the current edition of the OS 1:10000 map (1971). Information from RCAHMS (AKK) 7 March 1996. Activities Field Visit (22 March 2007 - 22 March 2007) Scotland's Rural Past (SRP) Srp Note (10 January 2011) Scotland's Rural Past (SRP) A farmstead (NOSAS site survey Nos 205) and associated enclosures (206, 207 & 208) centred on NH 4223 5467 are located in an elevated position above the N bank of the Allt na Fainich. The area surrounding the farmstead is has been improved and there are open birch woods further E. Further details of these and other associated sites can be found in the Strathconon Phase 1 Report (pages 33-35) produced by the North of Scotland Archaeology Society and appended to this record.

Asset/Event Number	173
Asset/Event Name	Seileach Mor
Type of Asset/Event	Enclosure (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45SW 3.00
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	241590
Northing	854250
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/103372/ NH45SW 3 4160 5427 An enclosure is depicted on the 1st edition of the OS 6-inch map (Ross-shire 1881, sheet lxxxvii), but it is not shown on the current edition of the OS 1:10000 map (1971). Information from RCAHMS (AKK) 7 March 1996. https://her.highland.gov.uk/Monument/MHG24681 This enclosure (210) was recorded by NOSAS in 2007 as part of the Scotland's Rural Past Project - NH 41591 54247 - and is also immediately adjacent to and on the north bank of the Allt na Fainich in a sheltered position. A sub-square enclosure measuring roughly 26m x 26m is surrounded on 3 sides by a low stone wall 0.5m in height. The south side is formed by the stream which at this point runs in a gully. Majority heather covered. Roughly halfway between 210 at NH 41705 54366 and 209 enclosures, also on the north bank of the stream, there is an area of improved ground in a sheltered re-entrant, with several clearance cairns. Both the enclosures may be associated with farmstead 205, to the NE or farmstead 217 to the SW. <1> Sources/Archives (1) <1> SHG24094 Text/Report/Fieldwork Report: Marshall, M.. 2009. A Project to Identify, Survey and Record Archaeological Remains in Strathconon, Ross-shire: Report of Phase One Scatwell and Lower Strathconon. North of Scotland Archaeological Society. 23/01/2009. Digital. p.34 Site 210.

Asset/Event Number	174
Asset/Event Name	Loch An Uird
Type of Asset/Event	Farmstead (Period Unassigned)(Possible)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH44SE 46.00
HER Number	MHG23319
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246700
Northing	843100
Council	Highland
Condition:	Unknown

Alignment:	Unknown
Importance:	Low
Description	*Observation by AOC Archaeology during 2024 walkover survey. No upstanding remains related to this asset were identified during the walkover survey, the locale of which was under long pasture, however elements may survive sub-surface. Https://canmore.org.uk/site/110009/ RCAHMS First Edition Survey Project What may be a farmstead comprising an unroofed building is depicted on the 1st edition of the OS 6-inch map (Inverness-shire 1876, sheet x), but it is not shown on the current edition of the OS 1:10000 map (1975). Information from RCAHMS (SAH) 15 May 1996 Field Visit (9 May 2023) NH 4645 4305 (centred) A desktop and walkover survey was conducted in May 2023 for an area of proposed woodland of 16 hectares, the area encompassing a number of recorded sites. Work revealed an unrecorded trackway. Information from Stuart Farrell.
Asset/Event Number	175
Asset/Event Name	Breakachy Burn
Type of Asset/Event	Farmstead (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH44NE 31.00
HER Number	MHG23303
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245640
Northing	845480
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/109993/ RCAHMS First Edition Survey Project A farmstead comprising two unroofed buildings, one of which has an attached enclosure, and a short length of wall is depicted on the 1st edition of the OS 6-inch map (Inverness-shire 1876, sheet x). An unroofed circular structure attached to the building may be a horse-gang. The building, the enclosure and further lengths of wall are shown on the current edition of the OS 1:10000 map (1975). Information from RCAHMS (SAH) 14 May 1996 https://her.highland.gov.uk/Monument/MHG23303 The North of Scotland Archaeological Society (NoSAS) undertook an archaeological survey of Urchany in 2015. Site V60; Allt na Criche settlement. The C19th settlement west of the Allt na Criche consists of extensive enclosure walls, a building, and a sunken area with perhaps a pond. On the estate maps covering this area there is no settlement shown until 1838. In the 1841 census there are three people living at “Aultnacrich”: Donald Mackay, agricultural labourer, Mary Mackay, and a 14 year old boy Finlay, presumably their son. We know from newspaper adverts that Urchany was used for sheep farming at this time. The settlement of two, possibly three, buildings lies at the northern upper end of a large enclosure bordered to the

	west by a stone dyke. A kiln, presumably corn-drying, lies just to the south of building A, with evidence of raised ground and walls between the two, suggesting that the kiln may have been part of a barn contiguous with the other buildings. <1> 1st Edition OS 6" <2> NGR adjusted based on 2009 aerial photographs. <3> Sources/Archives (3) <1> SHG28596 Text/Report/Fieldwork Report: Spencer-Jones, R.. 2020. A NoSAS Survey of the Lands of Urchany: A Multi-period Settlement on the Braes West of Beauly: 6th-10th April 2015. North of Scotland Archaeological Society. Digital. P.17-20, Site V60, Figures 18-28. XY <2> SHG23411 Image/Map: Ordnance Survey. 1881. Ordnance Survey 1st edition 6 inch map: Ross-shire. Digital. <3> SHG27382 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 2009. Getmapping aerial photography 2009.
Asset/Event Number	176
Asset/Event Name	Farmstead, Ardochy
Type of Asset/Event	Farmstead (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH44SE 40.00
HER Number	MHG23330
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246160
Northing	843480
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/110003/ RCAHMS First Edition Survey Project A farmstead comprising an unroofed building attached to an enclosure is depicted on the 1st edition of the OS 6-inch map (Inverness-shire 1876, sheet x). The building is shown on the current edition of the OS 1:10000 map (1975). Information from RCAHMS (SAH) 14 May 1996
Asset/Event Number	177
Asset/Event Name	Ardochy
Type of Asset/Event	Farmstead (Period Unassigned)(Possible)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH44SE 41.00
HER Number	MHG23314
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246090
Northing	843330
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	*Recorded by AOC Archaeology during 2024 walkover survey - see sub-elements of Asset 177 for details. Https://canmore.org.uk/site/110004/ RCAHMS First Edition Survey Project What may be a farmstead comprising an unroofed long building is depicted on the 1st edition of the OS 6-inch map (Inverness-shire 1876, sheet x) and on the current edition of the OS 1:10000 map (1975). Information from RCAHMS (SAH) 14 May 1996
Asset/Event Number	178
Asset/Event Name	Ardochy
Type of Asset/Event	Building (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH44SE 42.00
HER Number	MHG23301
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246400
Northing	843200
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Negligible/Low
Description	*Observation by AOC Archaeology during 2024 walkover survey. This building recorded on the NRHE/HER appears to be mis-placed, and likely relates to a structure visible on the 1st edition OS map situated along the extent of the N side of the survey corridor, and for which no upstanding remains could be discerned. HER Description: NH44SE 42 464 432An small unroofed building is depicted on the 1st edition of the OS 6-inch map (Inverness-shire 1876, sheet x), but it is not shown on the current edition of the OS 1:10000 map (1975).Information from RCAHMS (SAH) 14 May 199. https://canmore.org.uk/site/110005/ RCAHMS First Edition Survey Project An small unroofed building is depicted on the 1st edition of the OS 6-inch map (Inverness-shire 1876, sheet x), but it is not shown on the current edition of the OS 1:10000 map (1975). Information from RCAHMS (SAH) 14 May 1996 Field Visit (9 May 2023) NH 4645 4305 (centred) A desktop and walkover survey was conducted in May 2023 for an area of proposed woodland of 16 hectares, the area encompassing a number of recorded sites. Work revealed an unrecorded trackway. Information from Stuart Farrell.
Asset/Event Number	179
Asset/Event Name	Cnoc A' Leacachan
Type of Asset/Event	Clearance Cairn(s) (Period Unassigned), Hut Circle(s) (Prehistoric)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH57SE 34.00
HER Number	MHG41365
Status	Non-designated Heritage Asset
Section:	D1.2

Easting	257600
Northing	872600
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible/Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey - see sub-elements of Asset 177 for details. Https://canmore.org.uk/site/123544/ NH57SE 34 576 726 NH 576 726 A previously unrecorded roundhouse settlement already cut by the existing estate road was also clipped by the new windfarm access road. The remains of three roundhouses and associated clearance cairns survive on the E side of Cnoc a? Leacachan covering an area of c 2ha. The best-preserved is oval, 11 x 8m internally with a probable entrance to the SE. One roundhouse, 10m in internal diameter, was partially exposed during the construction work. It had already been damaged by the existing road. The exposed section was drawn and a radiocarbon sample (2400?60 BP) taken from a possible wattle fence lining the inner face of a ?turf bank 2m wide. The interior of the house was not excavated and was sealed by terram matting before the road metalling was laid. One worked quartz flake was found outside the structure. About half of the building remains undisturbed. Sponsor: National Power. J Wordsworth 1997 Activities Field Visit (1997) NH 576 726 A previously unrecorded roundhouse settlement already cut by the existing estate road was also clipped by the new windfarm access road. The remains of three roundhouses and associated clearance cairns survive on the E side of Cnoc a'Leacachan covering an area of c 2ha. The best-preserved is oval, 11 x 8m internally with a probable entrance to the SE. One roundhouse, 10m in internal diameter, was partially exposed during the construction work. It had already been damaged by the existing road. The exposed section was drawn and a radiocarbon sample (2400±60 BP) taken from a possible wattle fence lining the inner face of a ?turf bank 2m wide. The interior of the house was not excavated and was sealed by terram matting before the road metalling was laid. One worked quartz flake was found outside the structure. About half of the building remains undisturbed. J Wordsworth 1997. References Wordsworth, J. (1997ab) 'Novar Windfarm (Rosskeen parish), Bronze Age, modern settlement', Discovery Excav Scot, 1997. Page(s): 5
Asset/Event Number	180
Asset/Event Name	Upper Garvary, Sheep Fank
Type of Asset/Event	Sheepfold (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH58NE 18.00
HER Number	MHG28358
Status	Non-designated Heritage Asset
Section:	N/A
Easting	259100
Northing	885680
Council	Highland

Condition:	Fair
Alignment:	Various
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone constructed sheepfold, Z-shaped in plan measuring 40m by 30m. Walls stand to a height of 1.3m but some breaches have reduced it to ground level in parts. Constructed of roughly dressed stone and with three sheep creeps in the NW elevation and several internal compartments. Depicted on the 1st edition OS map. Https://canmore.org.uk/site/125428/ NH58NE 18 5910 8568 This sheepfold or fank is constructed of river washed dry stone rubble masonry and consists of four compartments. The walls are 1.4m to 1.5m in height by 0.9m in width at groundlevel, tapering to 0.5m in width at the wall head. There is a post with a clip for a 'mineral lick' on the extreme NW elevation, W end. For details on the sheepfold construction see NMRS MS 744/146 and DC 33190 Visited by RCAHMS (GJD), April 1987.
Asset/Event Number	181
Asset/Event Name	Allt Bad A' Chrasgaidh
Type of Asset/Event	Burnt Mound (Prehistoric)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 71.00
HER Number	MHG28233
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274730
Northing	902210
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Possible location of burnt mound. The area was under tall grass and the burnt mound could not be confidently identified. Https://canmore.org.uk/site/123952/ Field Visit (26 April 1995) RCAHMS Afforestable Land Survey, Rogart NC70SW 71 7473 0221 This oval burnt mound is situated on the NE bank of the Allt Bad a' Chrasgaidh and measures 8.1m from NW to SE by 3.4m transversely and 0.4m in height. The SW side of the mound has been cut by the burn, exposing cracked stone, charcoal and black soil. (ROG95 134) Visited by RCAHMS (DCC) 26 April 1995
Asset/Event Number	182
Asset/Event Name	Allt Bad A' Chrasgaidh
Type of Asset/Event	Burial Cairn (Prehistoric)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 103.00
HER Number	MHG28244
Status	Non-designated Heritage Asset

Section:	N/A
Easting	274900
Northing	902840
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low/Medium
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A kerb cairn as described by RCAHMS, though appears much diminished. The asset comprises a small low mound under heather 0.3m tall and 4m NW/SE by 3m, with occasional boulders (or exposed portions of bedrock) set in an intermittent kerb around this, some 2-4m from the mound. Situated on a low knoll with good views to the E. Https://canmore.org.uk/site/124375/ Field Visit (27 April 1995) NC70SW 103 7490 0284 This cairn, which stands on a rise to the N of the Allt Bad a' Chrasgaidh, is oval on plan, measures 3.8m from NE to SW by 3.5m transversely, stands 0.35m high, and is edged with a kerb of boulders. (ROG95 243) Visited RCAHMS (PJD) 27 April 1995 A kerb cairn as described by RCAHMS, though appears much diminished. The asset comprises a small low mound under heather 0.3m tall and 4m NW/SE by 3m, with occasional boulders (or exposed portions of bedrock) set in an intermittent kerb around this, some 2-4m from the mound. Situated on a low knoll with good views to the E. https://canmore.org.uk/site/124375/ Field Visit (27 April 1995) NC70SW 103 7490 0284 This cairn, which stands on a rise to the N of the Allt Bad a' Chrasgaidh, is oval on plan, measures 3.8m from NE to SW by 3.5m transversely, stands 0.35m high, and is edged with a kerb of boulders. (ROG95 243) Visited RCAHMS (PJD) 27 April 1995
Asset/Event Number	183
Asset/Event Name	Allt Bad A' Chrasgaidh
Type of Asset/Event	Township (Post Medieval)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 55.00
HER Number	MHG28537
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275000
Northing	902000
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey - see sub-elements of Asset 183 for details. Https://canmore.org.uk/site/130414/ Field Visit (24 April 1995) RCAHMS Afforestable Land Survey, Rogart NC70SE 55 7500 0200 This township is situated in the valley of the Allt Bad a' Chrasgaidh and lies within a head-dyke which encloses an area of about 500m from E to W by up to 250m. Patches of rough grassland within the head-dyke bear faint traces of ridging and lazy-beds. There are two loose groupings of buildings and enclosures situated on either side of the burn and, except for one structure (ROG95 125, NC 7497 0216), they all lie within the head-dyke. Four buildings (ROG95 126-8, 540) stand to the W of the burn, one of which (ROG95 127) is very much larger than the others and is attached to an enclosure. To the E of the burn there are eight buildings (ROG95 117-20, 122-5) - two of which are very much larger than the others, a kiln (ROG95 121) and six enclosures. All the buildings have faced-rubble footings. There is no depiction of the township on either the 1st or 2nd edition of the OS 6-inch map (Sutherland 1879, 1907, sheet civ). The three largest buildings measure respectively 16.1m by 2.5m (ROG95 124), 16.6m by 3.2m (ROG95 127) and 19.8m by 3.2m (ROG95 120), with two compartments in each of the two shorter structures and three in the longest. Two of these buildings (ROG95 120, 124) have two bedneuks opening out of a side wall, while another (ROG95 128) has a dished interior to one compartment suggesting that it may have been a byre house. The two largest buildings to the E of the burn are situated relatively discreetly of each other, and all three large buildings may have formed a focus for a family unit. The other buildings can be broken down into two broad size ranges: those measuring from 8.7m by 2.9m to 9.9m by 2.3m internally (ROG95 122, 127, 129); and a series of huts measuring from 4.1m by 1.7m to 5.8m by 2.7m internally (ROG95 117-9, 123, 125, 126, 540). These smaller buildings all have a single compartment. A kiln (ROG95 121, NC 7506 0212) is situated in a discrete cluster of structures on the E of the burn and comprises a bowl measuring 1.8m in diameter within a faced rubble bank 1.2m in thickness and 1m in height. The flue is on the SSW, opening out into a barn which measures 3.8m from NNE to SSW by 2.8m internally. The kiln bowl has been built onto the leading edge of a terrace and is set well above the level of the barn. (ROG95 117-29) Visited by RCAHMS (DCC) 24 April 1995
Asset/Event Number	184
Asset/Event Name	Dalnamein
Type of Asset/Event	Dyke (Period Unassigned), Enclosure(s) (Period Unassigned), Hut Circle (Prehistoric)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH79NW 46.00
HER Number	MHG28660; MHG44738; MHG14569
Status	Non-designated Heritage Asset
Section:	N/A
Easting	272130
Northing	898540
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/134181/ Dyke (Period Unassigned), Enclosure(s) (Period Unassigned), Hut Circle (Prehistoric) NH79NW 46 Centred on 7213 9854 NH 7213 9854 Drystone dyke/land boundary. Over 150m. NH 7245 9850 Slag deposits in mole upcast. NH 7213 9859 Hut circle associated with.

	NH 7212 9857 Sub-rectangular enclosures. Tain Archaeological Group 1995. References TAG. (1995i) 'Dalnamein (Dornoch parish)', Discovery Excav Scot, 1995, Tain Archaeological Group. Page(s): 47
Asset/Event Number	185
Asset/Event Name	Minera
Type of Asset/Event	Hut circle (Period Unassigned)
Date and/or Period	Prehistoric
Listing No./NRHE Number	ND13SE 119.00
HER Number	MHG28696
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315540
Northing	934900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	*Observation by AOC Archaeology during 2024 walkover survey.*The duplication mentioned and then queried below in the HER MHG28696 entry (https://her.highland.gov.uk/Monument/MHG28696) relate to the duplication of ND13SE 119.00 (https://canmore.org.uk/site/135143/minera) and ND13SE 112.00 (http://canmore.org.uk/site/135090), which are located at the same NGR and bear the same description. Https://canmore.org.uk/site/135143/ ND13SE 119 1554 3490 This small hut is situated on a terrace some 50m E and above the public road immediately S of a deeply cut burn channel and just N of a modern fence line. Measuring 8.3m in diameter over a bank about 2.5m in thickness and 0.2m in height. The interior is slightly dished and it is possible that this is a small hut-circle similar in size to that discovered to the S (ND13SE 115). Visited by RCAHMS (DE, IP) August 1997 https://her.highland.gov.uk/Monument/MHG28696 These two NMRS records appear to be duplicates of each other. Jhooper, 17/9/2002 It is not apparent on what basis J Hooper made the comment about this site record being a duplicate of another. However, this site is not readily apparent on any vertical aerial photographs until those taken in 2023 when a circular feature of around the right size is just about visible. There is also no modern fence line visible (as mentioned by RCAHMS) either. <1> Sources/Archives (1) <1> SHG29455 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 2023. Getmapping aerial photography 2023. XY
Asset/Event Number	186
Asset/Event Name	Minera
Type of Asset/Event	Burnt Mound (Prehistoric)(Possible), Field Boundary (Period Unassigned)(Possible)

Date and/or Period	Prehistoric
Listing No./NRHE Number	ND13SE 109.00
HER Number	MHG45469
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315690
Northing	934750
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/135083/ ND13SE 1569 3475 A possible grass-grown burnt mound is situated some 100m NE of the abandoned farmstead of Minera, about 10m S of the fence bounding the public road. The adjacent burn has now been recut as a ditch. Oval on plan, with shallow hollows in its SW side and its centre, the mound measures 10.1m from N to S by 8.7m transversely and stands up to 0.6m in height. No evidence of burnt stone could be seen at the date of visit. A possible field bank runs on to the S side of the mound. Visited by RCAHMS (DE, IP) August 1997 Field Visit (August 1997) A possible grass-grown burnt mound is situated some 100m NE of the abandoned farmstead of Minera, about 10m S of the fence bounding the public road. The adjacent burn has now been recut as a ditch. Oval on plan, with shallow hollows in its SW side and its centre, the mound measures 10.1m from N to S by 8.7m transversely and stands up to 0.6m in height. No evidence of burnt stone could be seen at the date of visit. A possible field bank runs on to the S side of the mound. Visited by RCAHMS (DE, IP) August 1997
Asset/Event Number	187
Asset/Event Name	Minera
Type of Asset/Event	Hut circle (Period Unassigned), Structure (Period Unassigned)
Date and/or Period	Prehistoric
Listing No./NRHE Number	ND13SE 110.00
HER Number	MHG28693
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315640
Northing	934730
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://canmore.org.uk/site/135084/ ND13SE 110 1564 3473 A small structure is visible in an improved field to the NE of the broch (ND13SE 19[Asset 56/SM568]) and immediately NE of the farmstead of Minera (ND13SE110.00). Roughly triangular on plan, the structure measures 7.5m from NE to SW by 6.6m within a bank spread to 1.9m in thickness and up to 0.3m in height. There is a possible entrance on the NE with appears to be a slight ramp at its SW end. The date and purpose of this structure are not known, but it may be connected with the use of the adjacent farmstead of Minera. Visited by RCAHMS (DE, IP) August 1997
Asset/Event Number	188
Asset/Event Name	Minera
Type of Asset/Event	Cruck Framed Building (Post Medieval), Farmstead (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND13SE 111.00
HER Number	MHG28694
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315540
Northing	934700
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/135088/ ND13SE 111.00 1554 3470 ND13SE 111.01 ND 1554 3468 Buildings The farmstead of Minera is situated immediately to the N of the broch ND13SE 13 and comprises a main range of buildings running E and W, with several outbuildings immediately S of its W end, and at least two, and possibly three, other buildings to the SE of the E end (ND13SE 111.01). The buildings, that are still roofed are presently covered with sheets of corrugated iron, but they have been thatched at some point. The roofless building at the E end of the main range has cruck-slots visible, and there is evidence of rebuilding in at least two parts of the range. Minera is described in the OS Name Book as a ?small " Hamlet" in Houstry: the property of Mrs B J Sinclair of Freswick? (Name Book 1870) and is depicted as partly roofed on the 1st edition of the OS 6-inch map (Caithness 1870-2, sheet xxxiii). Visited by RCAHMS (SPH, DE) August 1997
Asset/Event Number	189
Asset/Event Name	Minera
Type of Asset/Event	Building(s) (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND13SE 111.01
HER Number	MHG28695
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315540

Northing	934680
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/135089/ ND13SE 111.01 1554 3468 In the area between the broch (ND13SE 19) and the farmstead of Minera (ND13SE 111.00) there are three buildings that have been robbed to their stone footings. The southernmost has opposing entrances and may be a threshing barn, while one of the others displays evidence of two phases of construction and has the possible remains of a kiln at its NE end. Visited by RCAHMS (DE, IP) August 1997
Asset/Event Number	190
Asset/Event Name	Minera
Type of Asset/Event	Hut circle (Period Unassigned)
Date and/or Period	Prehistoric
Listing No./NRHE Number	ND13SE 112.00
HER Number	MHG28696
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315540
Northing	934900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	*Observation by AOC Archaeology during 2024 walkover survey. *The duplication mentioned and then queried below in the HER MHG28696 entry (https://her.highland.gov.uk/Monument/MHG28696) relate to the duplication of ND13SE 119.00 (https://canmore.org.uk/site/135143/minera) and ND13SE 112.00 (http://canmore.org.uk/site/135090), which are located at the same NGR and bear the same description. Https://canmore.org.uk/site/135090/ ND13SE 112 1554 3490 This small hut is situated on a terrace some 50m E and above the public road immediately S of a deeply cut burn channel and just N of a modern fence line. Measuring 8.3m in diameter over a bank about 2.5m in thickness and 0.2m in height. The interior is slightly dished and it is possible that this is a small hut-circle similar in size to that discovered to the S (new). Visited by RCAHMS (DE, IP) August 1997 https://her.highland.gov.uk/Monument/MHG28696 These two NMRS records appear to be duplicates of each other. Jhooper, 17/9/2002 It is not apparent on what basis J Hooper made the comment about this site record being a duplicate of another. However, this site is not readily apparent on any vertical aerial photographs until those taken in 2023 when a circular feature of around the right size is just about visible. There is also no modern fence line visible (as mentioned by RCAHMS) either. <1>

	Sources/Archives (1) <1> SHG29455 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 2023. Getmapping aerial photography 2023. XY
Asset/Event Number	191
Asset/Event Name	Burn Of Houstry
Type of Asset/Event	Cairn (Period Unassigned), Cairnfield (Period Unassigned)
Date and/or Period	Prehistoric
Listing No./NRHE Number	ND13SE 113.00
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	315150
Northing	932980
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/135092/ ND13SE 113 1552 3298 This heather-covered cairn is situated 210m SW of the chambered cairn ND13SE 1 and ND13SE 50 m W of a track that extends from SE to NW up the hill from the Burn of Houstry. Measuring 13m in diameter and up to 1m in height, the cairn has been severely disturbed by the removal of stone from a wedge-shaped quarry-pit into its W segment; what may be a small pen, measuring 1.7m by 1.1m and 0.2m in depth, has been sunk into the E side of the cairn. At least one small cairn is visible in the peat and deep heather to the W. Visited by RCAHMS (DE) August 1997
Asset/Event Number	192
Asset/Event Name	Fairburn House, Kennels
Type of Asset/Event	Kennels (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45SE 21.11
HER Number	MHG32439
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245430
Northing	852580
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/139361/ Architecture Notes see NH45SE 21.00 [Asset 97/LB14031] Fairburn House (Archaeology Notes) for full list of related sites

Asset/Event Number	193
Asset/Event Name	Dunrobin Glen
Type of Asset/Event	Building (Period Unassigned), Corn Drying Kiln (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 67.00
HER Number	MHG35870
Status	Non-designated Heritage Asset
Section:	N/A
Easting	279600
Northing	904900
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/157733/ NC70SE 67 796 049 NC 796 049 A longhouse and associated remains including a corn-drier were identified during planting operations. The site lies at c 270m OD. The area was excluded from planting. J Wordsworth 1999 References Wordsworth, J. (1999e) 'Dunrobin Glen (Golspie parish), deserted settlement', Discovery Excav Scot, 1999. Page(s): 54

Asset/Event Number	194
Asset/Event Name	Fairburn House, Gardener'S Cottage
Type of Asset/Event	Cottage (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45SE 21.14
HER Number	MHG36036
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245250
Northing	852710
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/161151/ Architecture Notes see NH45SE 21.00 [Asset 97/LB14031] Fairburn House (Archaeology Notes) for full list of related sites

Asset/Event Number	195
Asset/Event Name	Aultgowrie Mill
Type of Asset/Event	Watermill (Period Unassigned)

Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45SE 25.00
HER Number	MHG37361
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247767
Northing	851355
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/192757/ NH45SE 25 47767 51355 Aultgowrie Mill [NAT] OS 1:10,000 map, 1992.

Asset/Event Number	196
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	
Status	
Section:	N/A
Easting	
Northing	
Council	
Condition:	
Alignment:	
Importance:	
Description	VOID - number not assigned

Asset/Event Number	197
Asset/Event Name	Contin Mains
Type of Asset/Event	Geological Cropmark(s) (Period Unknown)
Date and/or Period	Unknown
Listing No./NRHE Number	NH45NE 146.00
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246530

Northing	855010
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/262691/ NH45NE 146 4653 5501 These indeterminate cropmarks have been recorded on oblique aerial photography (RCAHMSAP 2000) lying on level ground on the N bank of the Black Water, about 230m SE of Contin Mains, and are probably produced by previous courses of the Black Water. Information from RCAHMS (KMM) 16 July 2004
Asset/Event Number	198
Asset/Event Name	Fairburn House, Strathan
Type of Asset/Event	Estate Building (Period Unassigned), Policies (Post Medieval)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45SE 21.16
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245272
Northing	852540
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/272118/ Architecture Notes see NH45SE 21.00 [Asset 97/LB14031] Fairburn House (Archaeology Notes) for full list of related sites
Asset/Event Number	199
Asset/Event Name	Fairburn House, Estate Footbridge
Type of Asset/Event	Footbridge (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45SE 21.18
HER Number	MHG48426
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245401
Northing	852476
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://canmore.org.uk/site/272120/ NH45SE 21.18 45401 52476 This footbridge apparently carries an estate track or path over the River Orrin. Information from RCAHMS (RJCM), 4 May 2005.
Asset/Event Number	200
Asset/Event Name	Fairburn House, Estate Burial Ground
Type of Asset/Event	Burial Ground (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45SE 21.19
HER Number	MHG48428
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247318
Northing	851764
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/272122/ NH45SE 21.19 47318 51764 Burial Ground [NAT] OS 1:10,000 map, 1992. NMRS Report: (04/05/2005) NH45SE 21.19 47318 51764 https://her.highland.gov.uk/monument/MHG48428 NMRS Report: (04/05/2005) NH45SE 21.19 47318 51764 Burial Ground [NAT] OS 1:10,000 map, 1992. <1> Visited during the Highland Kirkyards project, run by Highland Buildings Preservation Trust. Rural private burial ground in woods to the north of the River Orrin. There are only around ten burials in total. The gravestones all face east and are all uprights of various designs. <2><3> Sources/Archives (3) <1> SHG24123 Dataset: RCAHMS. 02/2008. Annual update from Canmore. Digital. 272122. <2> SHG25133 Collection/Project Archive: Robinson, B; Scott, M; Wright, A. 03/2010. Highland Kirkyards: Ross and Cromarty. Highland Buildings Preservation Trust. 29/07/2010. Paper (Original). <3> SHG25134 Image/Photograph(s): Highlands Buildings Preservation Trust. 2009. Photographs of Ross and Cromarty Kirkyards. Colour. . Digital.
Asset/Event Number	201
Asset/Event Name	Aultgowrie
Type of Asset/Event	Farmhouse (19Th Century), Farmstead (19Th Century)
Date and/or Period	Post-medieval

Listing No./NRHE Number	NH45SE 35.00
HER Number	MHG48429
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247685
Northing	851465
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/272123/ Archaeology Notes NH45SE 35.00 47685 51465 NH45SE 35.01 NH 47495 51505 Bridge Cottage

Asset/Event Number	202
Asset/Event Name	Aultgowrie, Bridge Cottage
Type of Asset/Event	Cottage (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45SE 35.01
HER Number	MHG48430
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247495
Northing	851505
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/272124/ Archaeology Notes NH45SE 35.01 47495 51505

Asset/Event Number	203
Asset/Event Name	Aultgowrie Bridge
Type of Asset/Event	Road Bridge (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45SE 36.00
HER Number	MHG48431
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247772
Northing	850933

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/272125/ NH45SE 36 47772 50933 Aultgowrie Bridge [NAT] OS 1:10,000 map, 1992. Not to be confused with Aultgowrie, bridge over River Orrin (NH 47642 51570), for which see NH45SE 26 [Asset 100/LB14020]. This bridge carries an unclassified public road over the Allt Goibhre to the S of Aultgowrie Mill (NH45SE 25). Information from RCAHMS (RJCM), 4 May 2005.
Asset/Event Number	204
Asset/Event Name	Coul Of Fairburn Farm
Type of Asset/Event	Farmhouse (19Th Century), Farmstead (19Th Century)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45SE 38.00
HER Number	MHG48412
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247609
Northing	853549
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/272105/ No description. https://her.highland.gov.uk/Monument/MHG48412 No description.
Asset/Event Number	205
Asset/Event Name	Wester Balloan Cottage
Type of Asset/Event	Cottage (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45SE 41.01
HER Number	MHG48435
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247409
Northing	853840
Council	Highland

Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/272129/ NH45SE 41.01 47409 53840 https://her.highland.gov.uk/Monument/MHG48435 No description.
Asset/Event Number	206
Asset/Event Name	Langergill
Type of Asset/Event	Farmstead (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND15NE 80.00
HER Number	MHG49292
Status	Non-designated Heritage Asset
Section:	A1.1
Easting	318540
Northing	955010
Council	Highland
Condition:	Ruinous
Alignment:	ENE/WSW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Remains of a ruinous rectangular stone structure c40m by 5m over walls, which stand up to 1.7m tall and 0.6m wide. These are composed of randomly coursed stone slabs and roughly squared stones, neatly capped with concrete. Window apertures and entrances have been infilled with concrete blocks. The ESE end appears likely to have been an older structure, and the entirety has been much modified for use as livestock pens. The 1st edition OS map shows a small farmstead comprising an L-shaped roofed building with an enclosure to the N, and with an annex extending SE from ENE end of the building. Although the building is shown as still roofed by the time of the 2nd ediiton OS map, this annex has disappeared and could not be identified during the walkover survey. There is no HER description for this asset. OS. 1877. Caithness XVIII Surveyed: 1871, Published: 1877. OS. 1907. Caithness-shire XVIII. Surveyed: 1905, Published: 1907. https://canmore.org.uk/site/278271/ No description. Https://her.highland.gov.uk/Monument/MHG49292 No description.
Asset/Event Number	207
Asset/Event Name	Strath Sgitheach
Type of Asset/Event	Sheepfold(s) (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH56SW 54.00
HER Number	MHG50763
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252657

Northing	863403
Council	Highland
Condition:	Fair
Alignment:	Various
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A broadly L-shaped sheepfold measuring c70m by 50m and comprising several compartments, some of which are constructed with drystone walling which stands 1.5m tall and 0.7m wide, and appears to incorporate the remains of a building wall in the NW side where the remains of a fireplace can be seen, with other pens defined by post-and-wire fences and corrugated iron. A sheepfold is depicted on the 1st edition OS map with an adjacent building on the NW side. OS. 1875-6. Ross-shire & Cromartyshire (Mainland) LXXVI, Surveyed: 1875-6, Published: 1880. https://canmore.org.uk/site/288767/ No description. Https://her.highland.gov.uk/Monument/MHG50763 The Strath Sgitheach area was surveyed by Meryl Marshall in 2020. NGR adjusted based on 2009 aerial photographs. <2> Sources/Archives (1) <1> SHG24123 Dataset: RCAHMS. 02/2008. Annual update from Canmore. Digital. 288767.
Asset/Event Number	208
Asset/Event Name	Loch Achonachie
Type of Asset/Event	Farmstead (Period Unassigned), Head Dyke (Post Medieval), Road (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45SW 9.00
HER Number	MHG54447
Status	Non-designated Heritage Asset
Section:	N/A
Easting	242640
Northing	854870
Council	Highland
Condition:	Ruinous
Alignment:	ENE/WSW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular structure under dense bracken, measuring c19m by 6m over walls. Wall survives in good condition in ENE extent to c.0.5m tall and 0.5m wide. Elsewhere walls are collapsed, with stone tumble spread widely. Not depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXXVII, Surveyed: 1876, Published: 1881. https://canmore.org.uk/site/304821/ Field Visit (22 March 2007 - 22 March 2007) Scotland's Rural Past (SRP) Farmstead and enclosure walls (NOSAS Site Survey Nos 211-212, 226, 232-234) at NH 42642 54876 within a shallow saddle on a broad N facing spur amid birch woodland. Improved ground lies to the NE under the route taken by the power lines. The site comprises a main building, a further possible building and a series of discontinuous earth and stone dykes. See plan. The ruined walls of a rectangular building (211) at NH 42642 54876 measuring 12m x 3.5m internally on a NE-SW axis and originally of two compartments. Stone walls stand to a maximum 0.5m high and 0.5m thick with evidence for entrances at intervals in the long axis. Some 70m NW are the remains of a small building (226) at NH 42577 54913 located in a

shallow angular depression on a steep E facing slope. It measures 3m x 1.5m internally on a NW-SE axis and is scarped into the slope at the rear.
Sections of stone and earth dyke which still stand up to 0.5m high in places may have once formed part of the head dyke for the settlement. The two principal sections are over 200m in length; (212/232) contours the slope and (233) runs downslope toward Loch Achonachie and has been bisected by the modern road.
Below the modern road is a substantial earth bank 1m high with a spread of 2m bordering an overgrown track(234)on its S side which was traced for some 250m and may be a spur road accessing the farmstead and is not depicted on the 1st edition of the OS 6-inch map (Ross-shire 1881, sheet lxxxvii).
Information from the North of Scotland Archaeological Society

The site of the farmstead was visited during a walkover survey by Wardell and Armstrong in 2011 in advance of the proposed replacement Beauly-Mossford OHL project by SSE. Although it lay directly in the path of the new power line it was considered that the impact on the site would be negligible. <2>

https://her.highland.gov.uk/Monument/MHG54447
[As above with the addition of the below]
The site of the farmstead was visited during a walkover survey by Wardell and Armstrong in 2011 in advance of the proposed replacement Beauly-Mossford OHL project by SSE. Although it lay directly in the path of the new power line it was considered that the impact on the site would be negligible. <2>

Sources/Archives (2)
<1> SHG24094 Text/Report/Fieldwork Report: Marshall, M.. 2009. A Project to Identify, Survey and Record Archaeological Remains in Strathconon, Ross-shire: Report of Phase One Scatwell and Lower Strathconon. North of Scotland Archaeological Society. 23/01/2009. Digital. P.33 Sites 211-212, 226, 232-234.
<2> SHG25772 Text/Report/Fieldwork Report: Wardell Armstrong. 2012. Beauly Mossford 132kV Transmission Line Replacement Environmental Statement. Wardell Armstrong. Digital.

Asset/Event Number	209
Asset/Event Name	Loch Achonachie
Type of Asset/Event	Building (Period Unassigned), Distilling Site (Period Unassigned), Wall (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45NW 33.00
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	241810
Northing	855080
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/305900/

Asset/Event Number	210
Asset/Event Name	Black Water

Type of Asset/Event	House (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45NW 35.00
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	242522
Northing	859243
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/306290/ Field Visit (2009) The following features were recorded during a landscape management survey of the 18th-century military road network. […] NH 4248 5920 - Rogie - The remains of a longhouse with garden and at least one other building sitting in an extensive system of enclosure, presumably part of the dispersed settlement of Rogie (NH46SW 3). NH004 References Shepherd, C. (2009z) 'Survey of the 18th-century Military Road Network - North Highlands, Highland (Contin / Fodderty parishes), landscape assessment', Discovery Excav Scot, New, vol. 10, 2009. Cathedral Communications Limited, Wiltshire, England. Page(s): 95 https://her.highland.gov.uk/Monument/MHG54627 In 2009 Forestry Commission Scotland commissioned C Shepherd to undertake a survey and assessment of those parts of the 18th century Military Road network crossing the National Forest Estate in Inverness, Ross & Skye, Lochaber and North Highland Forest Districts. During the survey of Contin, the remains of a longhouse with garden and at least one other building sitting in an extensive system of enclosure, presumably part of the dispersed settlement of Rogie (NH46SW 3), was recorded. <1> Sources/Archives (1) <1> SHG24589 Text/Report/Fieldwork Report: Shepherd, C.. 12/2009. The 18th Century Military Road Network on the Forestry Commission National Forest Estate in the Highlands: Inverness, Ross & Skye, Lochaber and North Highland Districts. Forestry Commission Scotland. . Paper and Digital. NH004. XY
Asset/Event Number	211
Asset/Event Name	Uaigh Bheag
Type of Asset/Event	Farm (Period Unassigned), Farmhouse (Period Unassigned), Farmstead (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 50.00
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293607
Northing	913859

Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	*Recorded by AOC Archaeology during 2024 walkover survey - see sub-elements of Asset 211 for details. https://canmore.org.uk/site/307721/ Survey Stuart Farrell NC 938 148 (centred on) A desktop survey was undertaken for an area of proposed new woodland in August 2009. Work revealed the following unrecorded archaeological sites: NC 93607 13859 Farmstead [Asset 211] NC 93729 13950 Building NC 93542 13710 Building NC 9350 1380 Boundary marker NC 93987 14204 Building NC 93562 14607 Sheepfold NC 94172 14110 Sheepfold NC 93414 14603 Farmstead NC 93408 14545 Enclosure NC 9363 1482 Building NC 9388 1491 Building NC 94175 15446 Field system Report: HSMR and RCAHMS Funder: UPM Tilhill References Farrell, S. (2009q) 'Glen Loth, Highland (Loth parish), survey', Discovery Excav Scot, New, vol. 10, 2009. Cathedral Communications Limited, Wiltshire, England. Page(s): 111
Asset/Event Number	212
Asset/Event Name	Uaigh Bheag
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 51.00; NC91SW 52.00
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293729
Northing	913950
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular enclosure c16m by 14m composed of a stone and turf dyke under dense tall bracken. Dyke stands 0.7m tall and spread 1.5m wide. Very obscured by bracken and adjacent to access track. Note that NC91SW 51.00 and NC91SW 52.00 appear to be duplicate records utilising an identical grid reference. Not depicted on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.

	Https://canmore.org.uk/site/307722/ Survey Stuart Farrell NC 938 148 (centred on) A desktop survey was undertaken for an area of proposed new woodland in August 2009. Work revealed the following unrecorded archaeological sites: NC 93607 13859 Farmstead NC 93729 13950 Building [Assets 212/213] NC 93542 13710 Building NC 9350 1380 Boundary marker NC 93987 14204 Building NC 93562 14607 Sheepfold NC 94172 14110 Sheepfold NC 93414 14603 Farmstead NC 93408 14545 Enclosure NC 9363 1482 Building NC 9388 1491 Building NC 94175 15446 Field system Report: HSMR and RCAHMS Funder: UPM Tilhill References Farrell, S. (2009q) 'Glen Loth, Highland (Loth parish), survey', Discovery Excav Scot, New, vol. 10, 2009. Cathedral Communications Limited, Wiltshire, England. Page(s): 111
Asset/Event Number	213
Asset/Event Name	Uaigh Bheag
Type of Asset/Event	Building (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 52.00
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293729
Northing	913950
Council	Highland
Condition:	N/A
Alignment:	Unknown
Importance:	N/A
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Building locale under dense bracken, possibly within or adjacent to enclosure Asset 212, not definitiely identified on the ground. Very obscured by bracken and adjacent to access track. Note that NC91SW 51.00 and NC91SW 52.00 appear to be duplicate records utilising an identical grid reference. Not depicted on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907. Https://canmore.org.uk/site/307723/ https://canmore.org.uk/site/307722/ Survey Stuart Farrell NC 938 148 (centred on) A desktop survey was undertaken for an area of proposed new woodland in August 2009. Work revealed the following unrecorded archaeological sites: NC 93607 13859 Farmstead

NC 93729 13950 Building [Assets 212/213]
NC 93542 13710 Building
NC 9350 1380 Boundary marker
NC 93987 14204 Building
NC 93562 14607 Sheepfold
NC 94172 14110 Sheepfold
NC 93414 14603 Farmstead
NC 93408 14545 Enclosure
NC 9363 1482 Building
NC 9388 1491 Building
NC 94175 15446 Field system

Report: HSMR and RCAHMS
Funder: UPM Tilhill

References
Farrell, S. (2009q) 'Glen Loth, Highland (Loth parish), survey', Discovery Excav Scot, New, vol. 10, 2009. Cathedral Communications Limited, Wiltshire, England. Page(s): 111

Asset/Event Number	214
Asset/Event Name	Uaigh Bheag
Type of Asset/Event	Building (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 54.00
HER Number	MHG13174
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293987
Northing	914204
Council	Highland
Condition:	Various
Alignment:	NE/SW
Importance:	Negligible/Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey - see sub-elements of Asset 214 for details. https://canmore.org.uk/site/307725/ Survey Stuart Farrell NC 938 148 (centred on) A desktop survey was undertaken for an area of proposed new woodland in August 2009. Work revealed the following unrecorded archaeological sites: NC 93607 13859 Farmstead NC 93729 13950 Building NC 93542 13710 Building NC 9350 1380 Boundary marker NC 93987 14204 Building [Asset 214] NC 93562 14607 Sheepfold NC 94172 14110 Sheepfold NC 93414 14603 Farmstead NC 93408 14545 Enclosure NC 9363 1482 Building NC 9388 1491 Building NC 94175 15446 Field system Report: HSMR and RCAHMS Funder: UPM Tilhill

	References Farrell, S. (2009q) 'Glen Loth, Highland (Loth parish), survey', Discovery Excav Scot, New, vol. 10, 2009. Cathedral Communications Limited, Wiltshire, England. Page(s): 111
Asset/Event Number	215
Asset/Event Name	Houstry
Type of Asset/Event	Hut Circle(s) (Prehistoric)
Date and/or Period	Prehistoric
Listing No./NRHE Number	ND13SW 52.00
HER Number	MHG13583
Status	Non-designated Heritage Asset
Section:	N/A
Easting	314864
Northing	934910
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/307710/ Ground Survey (July 2009) Survey Stuart Farrell ND 164 339 (centred on) A desktop and walkover survey were undertaken for an area of proposed new forestry in July 2009. Work revealed a number of unrecorded archaeological sites including: ND 14890 34914 Hut circle – Houstry [Asset 215] ND 14837 34906 Hut circle – Houstry [Asset 215] ND 1677 3387 Buildings ND 16718 33606 Building ND 16974 33947 Building ND 16963 33669 Farmstead ND 17077 33972 Building with enclosure ND 17001 33315 Building ND 17143 33584 Building ND 16781 34008 Building ND 1716 3316 Farmstead – Upper Smerral ND 16037 34689 Building – Newlands of Houstry Report: HSMR and RCAHMS Funder: UPM Tilhill
Asset/Event Number	216
Asset/Event Name	Newlands Of Houstry
Type of Asset/Event	Building(s) (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND13SE 153.00
HER Number	n/a
Status	Non-designated Heritage Asset
Section:	N/A

Easting	316037
Northing	934689
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/307720/ Ground Survey (July 2009) Survey Stuart Farrell ND 164 339 (centred on) A desktop and walkover survey were undertaken for an area of proposed new forestry in July 2009. Work revealed a number of unrecorded archaeological sites including: ND 14890 34914 Hut circle – Houstry ND 14837 34906 Hut circle – Houstry ND 1677 3387 Buildings ND 16718 33606 Building ND 16974 33947 Building ND 16963 33669 Farmstead ND 17077 33972 Building with enclosure ND 17001 33315 Building ND 17143 33584 Building ND 16781 34008 Building ND 1716 3316 Farmstead – Upper Smerral ND 16037 34689 Building – Newlands of Houstry [Asset 216] Report: HSMR and RCAHMS Funder: UPM Tilhill
Asset/Event Number	217
Asset/Event Name	Garrimatic
Type of Asset/Event	Building (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45NW 40.00
HER Number	MHG39287
Status	Non-designated Heritage Asset
Section:	N/A
Easting	241420
Northing	855400
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/308492/ Field Visit (19 May 2007 - 19 May 2007) Scotland's Rural Past (SRP) A ruined building and dam [Asset X] (NOSAS site survey numbers 274 & 275) are located on a N facing slope on the S side of the River Conon above the road, among birch woods centred on NH 4142 5540. A small settlement [Asset 217] comprising at least three roofed buildings is depicted on the 1st edition OS map (Ross-shire 1881, sheet lxxxvii) and 3 households are recorded in the census records between 1841 and 1881.

The remains of the recorded building (274) are located to the SE of the principal building of the modern settlement. The dam and pond (275) are fed by the Allt na Talchainn which borders the E side of the settlement.

Further details of these and other associated sites can be found in the Strathconon Phase 1 Report (page 41) produced by the North of Scotland Archaeology Society and appended to this record.

Asset/Event Number	218
Asset/Event Name	Orrin Portal Valve
Type of Asset/Event	Valve House (Period Unassigned)
Date and/or Period	Modern
Listing No./NRHE Number	NH45SW 14.00
HER Number	MHG58728
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243591
Northing	854211
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/312899/ Field Visit (2010) The Hydro-Electric Digitisation Project This valve house contains the large butterfly valve which allows for the isolation of the penstock carrying water out of the tunnel from Orrin Dam and down to Orrin Power Station. This valve house echoes the functional style of the powerhouses on the Conon scheme and exhibits a similarly restrained use of architectural detailing, predominantly limited to some plain detailing to the door surround. In line with the wishes of James Shearer the buildings is constructed from local stone some of which may have been reclaimed from the excavation of the tunnel through to Orrin Dam as was the case with other underground structures such as Deanie and Cuilligran Power Stations (see separate items on Affric scheme). PL Payne, 1988, 5; E Wood, 2002, 38; J Miller, 2002. Note (25 October 2023) The Conon scheme This project involves three separate stages: the Fannich scheme, the Glascarnoch-Luichart-Torr Achilty scheme and the Orrin scheme. The first of these involved tunnels and aqueducts to increase the flow into Loch Fannich, and a tunnel from the bed of Loch Fannich to the Grudie Bridge power station at the west end of Loch Luichart. This involved a severe problem at the Loch Fannich end. Work began in 1946 and a dam was built later, completing the section in 1951. Work began on the second stage in 1951., producing two artificial lochs Vaich and Glascarnoch by damming the respective rivers, using the earth and rockfill method. Tunnels were excavated between these lochs and from Loch Glascarnoch to Mossford power station on Loch Luichart. A dam at the east end of Loch Achanalt allows loch to supply the Achsanalt power station near Grudie Bridge. Two artificial lochs Meig and Achonachie were produced by dams on the rivers Meig and Conon to supply power stations at Luichart and Torr Achilty respectively. Work on this section was completed in 1957. The Orrin scheme was started in 1955 and involved the building of a mass gravity dam 1000 feet long and an earth embankment also 1000 feet in length to seal off a branch valley, thus forming the Orrin Reservoir. The outflow is through a concrete -lined tunnel to a steel

pipeline supplying the Orrin power station at Loch Achonachie. Four Borland fish lifts had been installed at Luichart, Meig, Achanalt and Torr Achilty. The scheme was completed in 1961, the six power stations producing an output well over 100,000 kW.
Information from NRHE catalogue record WP007424, compiled by George Walker, 2005.

References
Miller, J. (2002) The dam builders: power from the glens. Edinburgh. RCAHMS Shelf Number: J.5.14.MIL
Payne, P L. (1988) The hydro: a study of the development of the major hydro-electric schemes undertaken by the North of Scotland Hydro-Electric Board. Aberdeen. RCAHMS Shelf Number: J.5.14.PAY
Wood, E. (2002) The Hydro Boys.

Asset/Event Number	219
Asset/Event Name	Orrin Portal Valve, Air Shaft
Type of Asset/Event	Air Shaft (Period Unassigned)
Date and/or Period	Modern
Listing No./NRHE Number	NH45SW 14.01
HER Number	MHG58729
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243579
Northing	853963
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/312900/ Note (25 October 2023) The Conon scheme This project involves three separate stages: the Fannich scheme, the Glascarnoch-Luichart-Torr Achilty scheme and the Orrin scheme. The first of these involved tunnels and aqueducts to increase the flow into Loch Fannich, and a tunnel from the bed of Loch Fannich to the Grudie Bridge power station at the west end of Loch Luichart. This involved a severe problem at the Loch Fannich end. Work began in 1946 and a dam was built later, completing the section in 1951. Work began on the second stage in 1951., producing two artificial lochs Vaich and Glascarnoch by damming the respective rivers, using the earth and rockfill method. Tunnels were excavated between these lochs and from Loch Glascarnoch to Mossford power station on Loch Luichart. A dam at the east end of Loch Achanalt allows loch to supply the Achsanalt power station near Grudie Bridge. Two artificial lochs Meig and Achonachie were produced by dams on the rivers Meig and Conon to supply power stations at Luichart and Torr Achilty respectively. Work on this section was completed in 1957. The Orrin scheme was started in 1955 and involved the building of a mass gravity dam 1000 feet long and an earth embankment also 1000 feet in length to seal off a branch valley, thus forming the Orrin Reservoir. The outflow is through a concrete -lined tunnel to a steel pipeline supplying the Orrin power station at Loch Achonachie. Four Borland fish lifts had been installed at Luichart, Meig, Achanalt and Torr Achilty. The scheme was completed in 1961, the six power stations producing an output well over 100,000 kW. Information from NRHE catalogue record WP007424, compiled by George Walker, 2005. References Payne, P L. (1988) The hydro: a study of the development of the major hydro-electric

	schemes undertaken by the North of Scotland Hydro-Electric Board. Aberdeen. RCAHMS Shelf Number: J.5.14.PAY
Asset/Event Number	220
Asset/Event Name	Orrin Power Station
Type of Asset/Event	Hydroelectric Power Station (Modern)
Date and/or Period	Modern
Listing No./NRHE Number	NH45SW 15.00
HER Number	MHG58730
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243603
Northing	854571
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/312902/ Field Visit (2010) The Hydro-Electric Digitisation Project Orrin power station receives water via tunnel and pipe from Orrin dam some 5KM to the South East. The station houses a single 18MW turbine. It is located on a steeply sloping site, the turbine hall oversails the tailrace and is built into the hillside with a single storey section to the rear adjacent to a large transformer station connecting the station to the grid. This is a good example of a smaller power station forming a component of a larger scheme. The design of the station is characteristic of this period with large windows to the turbine hall and relatively limited architectural detailing. The site is narrow and steeply sloping which has resulted in some changes from the characteristic design features. The turbine hall is very tall and narrow and has a shallow pitched roof with a recessed ashlar panel and small windows to the centre of the gable end over a large teak vehicular access door. The advanced flat roofed block built into the hillside to the rear of the turbine hall has a panel of ashlar with relief carving of the name of the station. PL Payne, 1988, 5; E Wood, 2002, 38; J Miller, 2002.
Asset/Event Number	221
Asset/Event Name	Loch Achonachie
Type of Asset/Event	Enclosure (Period Unassigned), Farmstead (Period Unassigned), Milestone (Period Unassigne
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45NW 37.00
HER Number	MHG39288
Status	Non-designated Heritage Asset
Section:	N/A
Easting	242300
Northing	855240
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	https://canmore.org.uk/site/308440/ Enclosure (Period Unassigned), Farmstead (Period Unassigned), Milestone (Period Unassigned), Township (Period Unassigned) Field Visit (15 March 2007 - 24 March 2007) Scotland's Rural Past (SRP) The former township of Drumandarach, farmstead buildings, enclosures, dykes, associated features and a milestone (NOSAS site survey numbers 170 -196 & 235-238) are located on the S side of the River Conon. The site extends across an area some 400m x 120m along an E facing ridge. The majority of the features included within the site record are contained within a large enclosure (170) that is shown on 1st edition of the OS 6-inch map (Ross-shire 1881, sheet lxxxvii) as is the remains of a farmstead (172 & 173) that is located outside and to the W of the enclosure. The S side of the site is bounded by a small stream and a rising craggy slope. The enclosure is grassy with some bracken and there is much evidence of recent sheep management. Birch woods and heather surround the settlement and a major power line traverses the site. The site comprises the remains of at least five buildings, a possible kiln, and there several clearance cairns which may conceal traces of earlier buildings. Further details of these and other associated sites can be found in the Strathconon Phase 1 Report (pages 38 - 40) produced by the North of Scotland Archaeology Society and appended to this record.
Asset/Event Number	222
Asset/Event Name	Loch An Uird
Type of Asset/Event	Track
Date and/or Period	Post-medieval; Modern
Listing No./NRHE Number	NH44SE 94.00
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.3
Easting	246539
Northing	842941
Council	Highland
Condition:	Fair
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A track, bare earth in some places and grass in others, measuring c2m wide. Some segments of which appear consistent with tracks shown on the 1st and 2nd edition OS maps. OS. 1876. Inverness-shire (Mainland) X, Surveyed: 1872, Published: 1876. OS. 1906. Inverness-shire (Mainland) X, Surveyed: 1902, Published: 1906. https://canmore.org.uk/site/377270/ Field Visit (9 May 2023) NH 4645 4305 (centred) A desktop and walkover survey was conducted in May 2023 for an area of proposed woodland of 16 hectares, the area encompassing a number of recorded sites. Work revealed an unrecorded trackway. Information from Stuart Farrell.
Asset/Event Number	223
Asset/Event Name	Lower Caen

Type of Asset/Event	Township (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND01NW 117.00
HER Number	n/a
Status	Non-designated Heritage Asset
Section:	N/A
Easting	301359
Northing	917834
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/348637/ Excavation (8 June 2013 - 23 June 2013) ND 01359 17834 A community excavation, planned to commemorate the bicentenary of the Kildonan Clearances, was undertaken 8–23 June 2013. The deserted township of Caen is located in the Strath of Kildonan, c2 miles upstream from the village of Helmsdale. Lower Caen is located on a river terrace above the Caen Burn. It is distinct from Upper Caen, which comprises a collection of ruins that extend N, up Caen Burn. A programme of topographical mapping and geophysical survey was carried out. As the structural remains were clearly visible the fluxgate gradiometer survey aimed to identify the location of hearths, middens and other possible internal features. Unfortunately, the underlying granite masked not only more subtle responses but even that from a large corn-drying kiln. As a result it was only possible to identify features already visible, such as extant walls and 'potato' pits. Meanwhile, topographic information was shared with a team from the University of St Andrews 'Virtual Worlds' group in order to develop an immersive 'Virtual Caen' (now available at: http://openvirtualworlds.org/unity-static/web-Timespan/web-Timespan.html). The first season of excavations at Lower Caen focused upon the final phase of occupation and subsequent abandonment of a single longhouse (Structure 1) and its associated outbuilding (Structure 2). Two L-shaped trenches were laid out to provide a half-section across both structures along the N–S (Trench B) and E–W (Trench A) axes. The removal of turf exposed rubble spreads across Structure 1 and across the E half of Structure 2. At the W end of Structure 2, removal of the turf exposed a compressed earth surface. Removal of the rubble across Structure 1 (the longhouse) exposed a high quality cobbled surface in the S end of the longhouse (upslope and upwind). This surface was constructed of rounded river pebbles and had been finished with a concreted lime treatment. At the N end of Trench A (within Structure 1) the end of a sub-rectangular void was found in this flooring, and was interpreted as potentially representing the laying of the flooring around a large rectangular item of furniture – such as a box-bed or similar. We recovered a significant number of sherds of post-medieval glazed wares (18th- and early 19th-century in date, predominantly local wares but including some English wares) lying directly on top of this floor surface. This included one low profile bowl which had clearly shattered in situ with a complete half of the vessel recovered (the other half appears to lie under the baulk). In addition to the ceramics a considerable number of fragments of glass, iron objects (all badly corroded) and two fragments of leather were recovered. Near the centre of Structure 1, at the S end of Trench B, a hearth was uncovered. Lying within a beaten earth floor, the hearth was made up of flat stones with a shallow depression at its centre. No accompanying features were identified, the central baulk ran immediately to the W and S of the hearth.

A single doorway was identified in the E-facing wall of the longhouse, with an accompanying internal and external area of rough paving. No threshold stone was present, although remains of a timber beam running across the entry at floor level were recovered from sockets on either side of the doorway, along with a substantial iron bolt and badly corroded iron object which may have been a door hinge. The stone-footing of an internal dividing wall was identified at the N of the internal paved area, along with a fragmented iron cauldron that had been deliberately incorporated into the paving during its construction.

The final northern third of Structure 1 represented the byre end of the longhouse, with an uneven and sloping surface of exposed natural. No drain was identified within this surface, although it is possible that it lay off-centre in the unexcavated W half of the structure.

In the space to the E of Structure 1, between the eastern flank of the longhouse and the gable end of two other (unexcavated) structures a metalled yard surface was exposed directly beneath the turf. Lying upon this, and butting against the E wall of Structure 1, we identified a stack of cut peat bricks.

The walls of Structure 1 consisted of a single skin of dry stone walling, using locally available and unfinished granite. The quality of construction was notably higher in the southern 'domestic' end of the building.

The excavations in Structure 2 revealed a very different structure. Here, removal of the rubble collapse spread revealed an uneven beaten earth floor across the interior of the structure. The construction of the walls varied significantly from E to W. The E gable end of the structure (separated from Structure 1 by a gap of c0.5m) was constructed of substantial dry stone walling, very similar in construction to that of Structure 1. However, the W wall was completely different in form, consisting of banked turf and rubble butting between two large granite boulders at the NW and SW corners of the structure. Meanwhile the N and S walls were thick double skinned turf and stone constructions.

Although removal of the collapse material produced finds including ceramic sherds, iron objects and sherds of glass, the density of finds from Structure 2 was far lower than in Structure 1. However, in the E end of the structure, the removal of the rubble collapse material revealed the presence of five fragments of riveted copper sheeting, almost certainly representing a fragmented copper pot-still, of the type used in 18th-century whisky distillation across the Highlands.

Archive: Timespan Museum (Helmsdale). Report: Highland HER and RCAHMS

References
Strickland, K. (2014) Kildonan, Lower Caen, Excavation, Discovery Excav Scot, New, vol. 14, 2013. Cathedral Communications Limited, Wiltshire, England. Page(s): 106-107

Asset/Event Number	224
Asset/Event Name	Strath Sgitheach Allt Na Criche 1
Type of Asset/Event	Cup Marked Rock (Neolithic) - (Bronze Age)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH56SW 65.00
HER Number	MHG8926
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252223
Northing	862909
Council	Highland
Condition:	N/A

Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/368635/ Note (7 August 2018) Scotland's Rock Art Project Date Fieldwork Started: 07/08/2018 Compiled by: NOSAS Location Notes: The panel lies on the lower slopes of Cioch Mhor to the N and overlooking the Abhainn Sgitheach to the S and views to the Cromarty Firth to the S. This cup marked rock is an outcrop and one of several scattered around a small knoll with the remains of a dry river bed to the NE. The river bed may have been part of the Allt an Criche which still flows to the NE. The knoll is to the NE of a much braided track from the Sgitheach in the SE to Cioch and Mhor and Ben Wyvis to the NW. There are a group of cup marked rocks and outcrops around the knoll, the majority to the N and W of the Scots pines. Strath Sgitheach has many prehistoric monuments, hut circles, chambered cairns and more groups of rock art. There are also signs of continuous cultivation into recent times with rig and furrow near the knoll. The area is presently rough grazing used by a few sheep and deer and it is likely that there is some game shooting. The knoll has a scatter of very old Scots pines and is partly grass and heather with some bracken around the outcrop. Panel Notes: The panel is an outcrop measuring 3.10m E-W by 2.10m and up to 0.70m high, sloping to the SE. There are 18 cupmarks scattered across the upper surface of the outcrop, mainly on the N section with a single cupmark on the SE edge. https://her.highland.gov.uk/Monument/MHG8926 NH56SW 13 522 630. Centred around NH 522630 are 8 cup marked rocks ('A' - 'H'). 'A' is a boulder measuring 3.1m x 1.9m x 0.6 m high with at least fifteen shallow cup marks on its upper surface. NH 5220 6292 [possibly Asset 224] 'B' a large block 3.6m x 1.8m x 1m maximum height. It is largely earth-covered. It has 23 cup marks on its two outer edges. NH 5213 6298 'C' a boulder 1.8m x 1.2m x 0.6m high with six cup marks. NH 5212 6297 'D' boulder 2.4m x 1m x 0.6m high with 7 small shallow cup marks. NH 5126 6296 'E' small boulder 1.1m x 0.7m x 0.3m high with 2 probable cup marks. NH 5201 6298 'F' a boulder lying close by has 7 shallow cup marks upon it. NH 5201 6301 'G', a boulder, 2.8m x 1.5m x 0.6m, lying on bank of a stream, has probably slipped from its original position due to erosion. It has 6 extremely shallow cup marks on its upper surface. NH 6196 6324 'H' is a slab 2.2m x 1.3m lying flush with ground; it has 3 probable cup marks on its surface. NH 5247 6295 Surveyed at 1:10 000. Visited by OS (J B) 16 November 1976 8 outcrops of rock with shallow cup-marks. RCAHMS 1979, visited September 1978 This panel was recorded as part of the ScRAP (Scotland's Rock Art project) by members of NoSAS in August 2018. The panel lies on the lower slopes of Cioch Mhor to the north and overlooking the Abhainn Sgitheach to the south and views to the Cromarty Firth to the south. This cup marked rock is an outcrop and one of several scattered around a small knoll with the remains of a dry river bed to the northeast. The river bed may have been part of the Allt an Criche which still flows to the northeast. The knoll is to the northeast of a much braided track from the Sgitheach in the southeast to Cioch and Mhor and Ben Wyvis to the northwest. There are a group of cup marked rocks and outcrops around the knoll, the majority to the north and west of the Scots pines. Strath Sgitheach has many prehistoric monuments, hut circles, chambered cairns and more groups of rock art. There are also signs of continuous cultivation into recent times with rig and furrow near the knoll. The area is presently rough grazing used by a few sheep and deer and it is likely that there is some game shooting. The knoll has a scatter of very old Scots pines and is partly grass and heather

with some bracken around the outcrop.

The panel is an outcrop measuring 3.10m east-west by 2.10m and up to 0.70m high, sloping to the southeast. There are 18 cupmarks scattered across the upper surface of the outcrop, mainly on the north section with a single cupmark on the southeast edge. <1>

Sources/Archives (3)
--- SHG2670 Text/Report: RCAHMS. 1979. The Royal Commission on the Ancient and Historical Monuments of Scotland. The archaeological sites and monuments of Easter Ross, Ross and Cromarty District, Highland Region. . 18, No. 133.
<1> SHG28055 Interactive Resource/Online Database: Historic Environment Scotland. 2017-. Scotland's Rock Art (ScRAP). ScRAP ID 3319.
<2> SHG29107 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 2021. Getmapping aerial photography 2021. XY

Asset/Event Number	225
Asset/Event Name	Strath Sgitheach Allt Na Criche 3
Type of Asset/Event	Cup Marked Rock (Neolithic) - (Bronze Age)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH56SW 66.00
HER Number	MHG63161
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252123
Northing	862974
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/368636/ Note (8 July 2018) Scotland's Rock Art Project Date Fieldwork Started: 08/07/2018 Compiled by: NOSAS Location Notes: This panel is recorded on Canmore 12923 as panel C. The panel is located on the lower S facing open slopes of Meall a'Ghuail, overlooking the river Sgitheach. It is one of a group of 8 panels (7 located at the time of writing) close to the Allt an Criche, in rough gazing interspersed with pine trees and patches of heath. A track crosses the river Sgitheach (ford and stepping stones) and heads NW and passes 60m W of the panel. Panel 2 (B in Canmore) is 5m to the E and is part of the same rock outcrop. There is a large broken down pine tree 7m E of the panel. Rigg is visible in the ground immediately S of the panel. The area generally has a number of hut circles, field systems and burnt mounds, including those identified in Canmore 12921 about 0.6km to the SW. Panel Notes: The panel is a low domed roughly triangular outcrop of schist, about 2.1m by 1.5m rising to about 0.6m in height. The carved surface is on a slightly sloping (10 degrees W) flatter section in the NW part of the panel. There are 5 distinct and 3 indistinct cups in a group. https://her.highland.gov.uk/Monument/MHG63161 NH56SW 13 522 630. Centred around NH 522630 are 8 cup marked rocks ('A' - 'H'). 'A' is a boulder measuring 3.1m x 1.9m x 0.6 m high with at least fifteen shallow cup marks on its upper surface. NH 5220 6292

'B' a large block 3.6m x 1.8m x 1m maximum height. It is largely earth-covered. It has 23 cup marks on its two outer edges. NH 5213 6298
'C' a boulder 1.8m x 1.2m x 0.6m high with six cup marks. NH 5212 6297
'D' boulder 2.4m x 1m x 0.6m high with 7 small shallow cup marks. NH 5126 6296
'E' small boulder 1.1m x 0.7m x 0.3m high with 2 probable cup marks. NH 5201 6298
'F' a boulder lying close by has 7 shallow cup marks upon it. NH 5201 6301
'G', a boulder, 2.8m x 1.5m x 0.6m, lying on bank of a stream, has probably slipped from its original position due to erosion. It has 6 extremely shallow cup marks on its upper surface. NH 6196 6324
'H' is a slab 2.2m x 1.3m lying flush with ground; it has 3 probable cup marks on its surface. NH 5247 6295
Surveyed at 1:10 000. Visited by OS (J B) 16 November 1976

8 outcrops of rock with shallow cup-marks.
RCAHMS 1979, visited September 1978

This panel was recorded as part of the ScRAP (Scotland's Rock Art project) by members of NoSAS in July 2018. This panel is recorded on Canmore 12923 as panel C. The panel is located on the lower south facing open slopes of Meall a'Ghuail, overlooking the river Sgitheach. It is one of a group of 8 panels (7 located at the time of writing) close to the Allt an Criche, in rough gazing interspersed with pine trees and patches of heath. A track crosses the river Sgitheach (ford and stepping stones) and heads NW and passes 60m west of the panel. Panel 2 (B in Canmore) is 5m to the east and is part of the same rock outcrop. There is a large broken down pine tree 7m E of the panel. Rigg is visible in the ground immediately south of the panel. The area generally has a number of hut circles, field systems and burnt mounds, including those identified in Canmore 12921 about 0.6km to the southwest.

The panel is a low domed roughly triangular outcrop of schist, about 2.1m by 1.5m rising to about 0.6m in height. The carved surface is on a slightly sloping (10 degrees west) flatter section in the northwest part of the panel. There are 5 distinct and 3 indistinct cups in a group. <1>

NGR adjusted based on 2021 vertical aerial photographs. <2>
Sources/Archives (3)
--- SHG2670 Text/Report: RCAHMS. 1979. The Royal Commission on the Ancient and Historical Monuments of Scotland. The archaeological sites and monuments of Easter Ross, Ross and Cromarty District, Highland Region. . 18, No. 133.
<1> SHG28055 Interactive Resource/Online Database: Historic Environment Scotland. 2017-. Scotland's Rock Art (ScRAP). ScRAP ID 3006.
<2> SHG29107 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 2021. Getmapping aerial photography 2021. XY

Asset/Event Number	226
Asset/Event Name	Strath Sgitheach Allt Na Criche 8
Type of Asset/Event	Cup Marked Rock (Neolithic) - (Bronze Age)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH56SW 70.00
HER Number	MHG63187
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252483
Northing	862943
Council	Highland
Condition:	N/A
Alignment:	N/A

Importance:	N/A
Description	https://canmore.org.uk/site/368640/ Note (7 August 2018) Scotland's Rock Art Project Date Fieldwork Started: 07/08/2018 Compiled by: NOSAS Location Notes: The panel located in a low-lying flat area of rough grazing, generally in the bottom of Strath Sgitheach. The Allt an Criche passes about 15m to the W. A vehicle track (not marked on the OS 1:25k map) crosses the Allt an Criche at a ford which is filled with large boulders. The panel is almost completely overgrown and located about 20m S of the ford. Panel Notes: The panel is a large flat slab of schist. The overall size and shape is uncertain, the edges were not exposed. There are 3 shallow cups together and a further (unlikely) indentation about 1m away. https://her.highland.gov.uk/Monument/MHG63187 NH56SW 13 522 630. Centred around NH 522630 are 8 cup marked rocks ('A' - 'H'). 'A' is a boulder measuring 3.1m x 1.9m x 0.6 m high with at least fifteen shallow cup marks on its upper surface. NH 5220 6292 'B' a large block 3.6m x 1.8m x 1m maximum height. It is largely earth-covered. It has 23 cup marks on its two outer edges. NH 5213 6298 'C' a boulder 1.8m x 1.2m x 0.6m high with six cup marks. NH 5212 6297 'D' boulder 2.4m x 1m x 0.6m high with 7 small shallow cup marks. NH 5126 6296 'E' small boulder 1.1m x 0.7m x 0.3m high with 2 probable cup marks. NH 5201 6298 'F' a boulder lying close by has 7 shallow cup marks upon it. NH 5201 6301 'G', a boulder, 2.8m x 1.5m x 0.6m, lying on bank of a stream, has probably slipped from its original position due to erosion. It has 6 extremely shallow cup marks on its upper surface. NH 6196 6324 'H' is a slab 2.2m x 1.3m lying flush with ground; it has 3 probable cup marks on its surface. NH 5247 6295 Surveyed at 1:10 000. Visited by OS (J B) 16 November 1976 8 outcrops of rock with shallow cup-marks. RCAHMS 1979, visited September 1978 This panel was recorded as part of the ScRAP (Scotland's Rock Art project) by members of NoSAS in August 2018. The panel located in a low-lying flat area of rough grazing, generally in the bottom of Strath Sgitheach. The Allt an Criche passes about 15m to the west. A vehicle track (not marked on the OS 1:25k map) crosses the Allt an Criche at a ford which is filled with large boulders. The panel is almost completely overgrown and located about 20m south of the ford. The panel is a large flat slab of schist. The overall size and shape is uncertain, the edges were not exposed. There are 3 shallow cups together and a further (unlikely) indentation about 1m away. <1> Note: Site not visible on aerial photographs so location based on grid coordinates. (T. Blackie 18/03/24) Sources/Archives (2) --- SHG2670 Text/Report: RCAHMS. 1979. The Royal Commission on the Ancient and Historical Monuments of Scotland. The archaeological sites and monuments of Easter Ross, Ross and Cromarty District, Highland Region. . 18, No. 133. <1> SHG28055 Interactive Resource/Online Database: Historic Environment Scotland. 2017-. Scotland's Rock Art (ScRAP). ScRAP ID 3023. XY
Asset/Event Number	227
Asset/Event Name	Cup-marked stone, Strath Sgitheach Cnoc A' Mhuilinn 4

Type of Asset/Event	Cup Marked Stone (Neolithic) - (Bronze Age)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH56SW 79.00
HER Number	MHG14146; MHG8928
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251456
Northing	862474
Council	Highland
Condition:	Fair
Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A cup-marked stone measuring 1m by 1m and standing 0.6m tall. Appears as a free standing boulder with some moss growing atop it. Bears 5 cup marks on the N edge, looking uphill, but the stone commands good views along the strath to the S and SE. https://canmore.org.uk/site/368649/ Field Visit (13 September 1973) Ordnance Survey Archaeology Division Revision Programme Within the settlement [NH56SW 11] and centred at NH 5150 6255 are six cup marked rocks (marked 1 - 6 on 6" plan) 1: Has 1 good cup mark and 2 possible cup marks. [see NH56SW 73] 2: Has 2 good cup marks and 2 possible cup marks. [see NH56SW 77] 3: At least 6 cup marks, but there is the slight possibility that they could be due to weathering. [see NH56SW 78] 4: Has 14 good cup marks. [see NH56SW 79] 5: Has 8 good cup marks. [see NH56SW 80] 6: Has 4 good, and 1 probable, cup marks. [see NH56SW 81] Surveyed at 1:10560. Visited by OS (I S S) 13 September 1973. Field Visit (September 1978) RCAHMS: The Archaeological Sites and Monuments of Easter Ross Strath Sgitheach 1 NH 515 625 NH56SW 11 This group of six cup-marked boulders stands within an area of unenclosed settlement [see NH56SW 11]. RCAHMS 1979, visited September 1978 Note (29 March 2019) Scotland's Rock Art Project [Formerly recorded under NH56SW 11, discovered by OS (ISS) 1973] Date Fieldwork Started: 29/03/2019 Compiled by: NOSAS Location Notes: The site lies within a conifer and deciduous plantation planted about 20 years ago on the S facing slope of Cioch Mhor overlooking Strath Sgitheach and the Cromarty Firth. The area immediately around the panel has been planted with deciduous trees just S (20m) of a block of conifer trees. There is an open area to the S and E and a high (1m) bank to the W. To the N of the plantation there is a Scheduled Monument (SM 10495 Strath Sgitheach, Settlement), NW of Cnoc A'Mhuilinn. The SM includes a number of cup marked panels and hut circles and field systems. The site is recorded on the HER along with the other rock art and hut circles in the area as MHG 8928. Panel Notes: The panel was covered with moss which was replaced after recording the panel. This is a free standing boulder 1.2m by 1m and 0.4m high located immediately beside

	an alder tree. The panel has a N facing slope of 25 degrees and is schist with some natural hollows. There are 14 cup marks scattered across the upper face of the boulder with the S-most and NW-most cups on the edge of the top of the boulder.
Asset/Event Number	228
Asset/Event Name	Cup-marked stone, Strath Sgitheach Cnoc A' Mhuilinn 5
Type of Asset/Event	Cup Marked Stone (Neolithic) - (Bronze Age)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH56SW 80.00
HER Number	MHG14146; MHG8928
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251590
Northing	862591
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A cup-marked stone visible as a flattish slab surrounded by heather. Contains 4 visible cup marks aligned NW/SE that 'face' towards the prehistoric settlement areas to the NW, while the stone's location offers good views over the strath to the east. https://canmore.org.uk/site/368650/ Field Visit (13 September 1973) Ordnance Survey Archaeology Division Revision Programme Within the settlement [NH56SW 11] and centred at NH 5150 6255 are six cup marked rocks (marked 1 - 6 on 6" plan) 1: Has 1 good cup mark and 2 possible cup marks. [see NH56SW 73] 2: Has 2 good cup marks and 2 possible cup marks. [see NH56SW 77] 3: At least 6 cup marks, but there is the slight possibility that they could be due to weathering. [see NH56SW 78] 4: Has 14 good cup marks. [see NH56SW 79] 5: Has 8 good cup marks. [see NH56SW 80] 6: Has 4 good, and 1 probable, cup marks. [see NH56SW 81] Surveyed at 1:10560. Visited by OS (I S S) 13 September 1973. Field visit (September 1978) RCAHMS: The Archaeological Sites and Monuments of Easter Ross Strath Sgitheach 1 NH 515 625 NH56SW 11 This group of six cup-marked boulders stands within an area of unenclosed settlement [see NH56SW 11]. RCAHMS 1979, visited September 1978 Note (29 March 2019) Scotland's Rock Art Project [Formerly recorded under NH56SW 11, first noted by OS (ISS) in 1973]. Date Fieldwork Started: 29/03/2019 Compiled by: NOSAS Location Notes: The panel is located on a south facing slope at an altitude of 250m above and to the north of the shallow upland valley of Strath Sgitheach. In the immediate vicinity there is heathery moorland with some self seeded fir trees, but also close by there are discrete patches of forest plantation. Also nearby are some deeply ploughed furrows which have not been planted. There are good wide views to south and east.

	Panel Notes: This flat slab has 7 definite cups and 1 possible cup. The panel is in an area of wet but not boggy ground, an area of poor drainage; the panel is being overwhelmed by heather and peat. The full extent of the panel was not explored because of this but it was believed that the full extent of the carved surface was identified.
Asset/Event Number	229
Asset/Event Name	Cup-marked stone, Strath Sgitheach Cnoc A' Mhuilinn 6
Type of Asset/Event	Cup Marked Stone (Neolithic) - (Bronze Age)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH56SW 81.00
HER Number	MHG14146; MHG8928
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251649
Northing	862542
Council	Highland
Condition:	Very Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A cup-marked stone measuring 1.5m by 1.5m and standing 0.5m tall, surrounded by bracken and partly overlaid by turf and moss. 2-3 cupmarks along the top of the panel. The stone overlooks the strath to the southeast. https://canmore.org.uk/site/368651/ Field Visit (13 September 1973) Ordnance Survey Archaeology Division Revision Programme Within the settlement [NH56SW 11] and centred at NH 5150 6255 are six cup marked rocks (marked 1 - 6 on 6" plan) 1: Has 1 good cup mark and 2 possible cup marks. [see NH56SW 73] 2: Has 2 good cup marks and 2 possible cup marks. [see NH56SW 77] 3: At least 6 cup marks, but there is the slight possibility that they could be due to weathering. [see NH56SW 78] 4: Has 14 good cup marks. [see NH56SW 79] 5: Has 8 good cup marks. [see NH56SW 80] 6: Has 4 good, and 1 probable, cup marks. [see NH56SW 81] Surveyed at 1:10560. Visited by OS (I S S) 13 September 1973. Field Visit (September 1978) RCAHMS: The Archaeological Sites and Monuments of Easter Ross Strath Sgitheach 1 NH 515 625 NH56SW 11 This group of six cup-marked boulders stands within an area of unenclosed settlement [see NH56SW 11]. RCAHMS 1979, visited September 1978 Note (29 March 2019) Scotland's Rock Art Project [Formerly recorded under NH56SW 11, discovered by OS (ISS) 1973] Date Fieldwork Started: 29/03/2019 Compiled by: NOSAS Location Notes: The panel lies about 100m N of panel 7 and 100m SE of panel 5, on a slight ridge in generally SE sloping ground. It overlooks Strath Sgitheach, where the river runs W to E. To the NW the ground rises gently and then increasingly steeply to Cnoc Mhor (482m).

	The immediate area is heather covered with self seeded trees and patches of ridged ground with planted trees. Panel Notes: The panel is a 2.1m long ridge of schist, set E-W, with flat faces sloping to the N and S. The N face has no carvings. The S face has 6 cups, 3 of which are less distinct than the others.
Asset/Event Number	230
Asset/Event Name	Cup-marked stone, Strath Sgitheach Cnoc A' Mhuilinn 9
Type of Asset/Event	Cup Marked Stone (Neolithic) - (Bronze Age)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH56SW 83.00
HER Number	MHG8928
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251310
Northing	862480
Council	Highland
Condition:	Unknown
Alignment:	N/A
Importance:	Low
Description	*Observation by AOC Archaeology during 2024 walkover survey. This asset could not be identified within a stand of commercial forestry, possibly displaced due to forestry operations. https://canmore.org.uk/site/368653/ Note (29 March 2019) Scotland's Rock Art Project [Formerly recorded under NH56SW 11, discovered by Driscoll and Foster 1989] Date Fieldwork Started: 29/03/2019 Compiled by: NOSAS Location Notes: This is cup-marked rock no. 9 in the record for Canmore 12921. The area has been visited and searched on two occasions and this particular panel has not been located. The area has been ploughed and forested and the ground under the trees is thickly carpeted with moss and pine needles.
Asset/Event Number	231
Asset/Event Name	Heights Of Fodderty (Duplicate) 1
Type of Asset/Event	Natural Feature (Period Unassigned)
Date and/or Period	N/A
Listing No./NRHE Number	NH56SW 56.00
HER Number	MHG58957
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251984
Northing	861042
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A

Description	*Recorded by AOC Archaeology during 2024 walkover survey. https://canmore.org.uk/site/350592/ Desk Based Assessment (6 May 2016) This cup-and-ring marked boulder, heavily-decorated on both sides, was found in a field of rough pasture (NH 5106 6071) in 2006 Highland Council HER (MHG 55106). It has since been moved to a new location - The Heights of Brae Neil Gunn Viewpoint. The boulder was Scheduled at its new location by Historic Environment Scotland in March 2016. Information from HES Survey and Recording (JRS) 6 May 2016. Note (16 May 2019) Scotland's Rock Art Project Date Fieldwork Started: 16/05/2019 Compiled by: NOSAS Location Notes: This panel is displayed at the Neil Gunn Viewpoint, Heights of Brae. There is car parking and an interpretation board. It was moved there for safekeeping on 16 January 2014 from NH 5106 6071. It has previously been recorded as Clash Vaan ScRAP 1349 Canmore 351657 (at its old location), and HEIGHTS OF BRAE, NEIL GUNN VIEWPOINT ScRAP 2234 Canmore 350592 (at its new location). As there are three records of the same panel, two of the records have been reclassified as natural features.
Asset/Event Number	232
Asset/Event Name	Strath Sgitheach (East) Ss8
Type of Asset/Event	Roundhouse (Period Unknown)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH56SW 95.00
HER Number	MHG8925
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252416
Northing	863233
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under heather and grass with a diameter of c10m. Banks are spread up to 3m wide and stand 0.15m tall, with a possible entrance in the SE quarter. https://canmore.org.uk/site/369792/ Field Visit (May 2020 - June 2020) NH 524 633 (roughly centred) This group of 12 roundhouses in the upper part of Strath Sgitheach is NE of the track from the bridge/stepping stones. The roundhouses are on a SE–facing slope in heathery ground at an altitude of c250m and on both sides of a small burn. Just four roundhouses have been previously recorded although more than this are seen on snowy aerial photographs taken by Jim Bone in February 2010 (see JSB collection). They were surveyed in May and June 2020. The majority of the roundhouses are circular and have internal diameters of between 6m and 9m. The surrounding banks are up to 0.5m height and are often damaged or incomplete. One of the roundhouses, SS5, has more substantial remains which are 0.6m high and have a spread of 2m. Only a few of the roundhouses have evidence of entrances. NH 52545 63270 Roundhouse (SS1) NH 52569 63323 Roundhouse (SS2) NH 52533 63331 Roundhouse (SS3) NH 52473 63284 Roundhouse (SS4)

NH 52418 63278 Roundhouse (SS5) (previously recorded as “B”)
NH 52396 63297 Roundhouse (SS6) (previously recorded as “D”)
NH 52385 63289 Roundhouse (SS7) (previously recorded as “C”)
NH 52416 63233 Roundhouse (SS8)
NH 52303 63332 Roundhouse (SS12) (previously recorded as “A”)
NH 52107 63397 Roundhouse (SS14)
NH 52297 63481. Roundhouse (SS15)
NH 52458 63350 Roundhouse (SS17)

Archive: Highland Council HER and NRHE
Meryl Marshall – NOSAS
(Source: DES Vol 21)

References
Marshall, M. (2021) Strath Sgitheach (East), Walkover survey and recording, in Jennifer Thoms, Discovery Excav Scot, New, vol. 21, 2020. Cathedral Communications Ltd, Wiltshire, England. Page(s): 67-68

Asset/Event Number	233
Asset/Event Name	Coul Woods
Type of Asset/Event	Cup And Ring Marked Stone (Neolithic) - (Bronze Age), Gate Post (19Th Century) - (20Th Cent
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH45NE 166.00
HER Number	n/a
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	247166
Northing	856282
Council	Highland
Condition:	Fair
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An ex-situ cup-marked stone, re-used at some point as a gate-post stone. The stone lies beside trees that form the the beech avenue along the road. Https://canmore.org.uk/site/368435/ Note (11 November 2019) Scotland’s Rock Art Project Date Fieldwork Started: 11/11/2019 Compiled by: NOSAS Location Notes: The panel lies within the area now called Coul Woods but which would have originally formed part of an avenue of planted beech trees leading to Coul House. The trees are over 100 years old and appear on the 1st Edition Ordnance Survey map but may date from the building of Coul House in 1821 by the Mackenzies of Coul or the improvements to the house in 1860. The cup marked stone lies beside a beech tree at present but has been reused as a support for a metal post which may have formed a gate post or fence post dating from the time of the planting of the trees or slightly later. The metal post has been cut off near to the surface of the stone, although there is a second stone nearby with its metal post intact. Both stones are not even in their original fence line but lying roughly on the line of the trees. To the N there are more trees, beech and birch, recently planted (c.20-30 years old) on the edge of cultivated ground further to the N. To the S the cultivated ground slopes down to the confluence of the Black Water and the Conon River. There is another cup marked stone at Preas Mairi (ScRAP 403, Canmore 12447) to the W and there are chambered cairns, a henge and a crannog in the area. Panel Notes: The panel is a block of stone measuring 1.1m N-S by 0.7m and 0.3m high. It is

	roughly rectangular with no signs of being shaped, however it has been reused as a base for a gate post or fence post in the past. At the N end of the stone there is the bottom section of a square metal post secured with lead into the stone and a small drill hole to the S of the metal post. There are 2 cups with single rings at the N end of the stone with another 5 cups and a possible very small cup. A natural fissure crosses the stone E-W. The stone is covered with lichen
Asset/Event Number	234
Asset/Event Name	Clyne
Type of Asset/Event	Cup Marked Rock (Neolithic) - (Bronze Age)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC80NE 62.00
HER Number	MHG30343
Status	Non-designated Heritage Asset
Section:	N/A
Easting	286830
Northing	907706
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/368452/ Note (21 July 2019) Scotland's Rock Art Project Date Fieldwork Started: 21/07/2019 Compiled by: NOSAS Location Notes: The rock art panel is on a small outcrop in open heather and grassy moorland on a hillside terrace at about 210m above sea level, above and to the W of Loch Brora. The outcrop is about 130m NE of a ruined broch (MGH 10805 broch Killin) and 50m SW of a 19th century sheep fank. A small group of visible outcrops are scattered across an undulating area of moorland with this carved outcrop lying on a very slight rise. A small standing stone (MHG39347) lies about 5om to the NW. Three brochs and a crannog in Loch Brora can be seen from the outcrop. There are also a number of cairns on the lower ground and many hut circles in the area. Panel Notes: The panel is on an almost circular outcrop 2.8 x 2.8m and a maximum height of 0.6m. The outcrop has a flat top with a very slight slope to the W. The edges of the outcrop are covered with heather and the visible surface of the outcrop is completely covered with a variety of lichens and a little moss. There are 5 cup marks scattered over the surface in no particular obvious pattern. https://her.highland.gov.uk/Monument/MHG30343 This panel was recorded as part of the ScRAP (Scotland's Rock Art project) by members of NoSAS in July 2019. The rock art panel is on a small outcrop in open heather and grassy moorland on a hillside terrace at about 210m above sea level, above and to the west of Loch Brora. The outcrop is about 130m northeast of a ruined broch (MGH 10805 broch Killin [Asset 121]) and 50m southwest of a 19th century sheep fank. A small group of visible outcrops are scattered across an undulating area of moorland with this carved outcrop lying on a very slight rise. A small standing stone (MHG39347) lies about 5om to the northwest. Three brochs and a crannog in Loch Brora can be seen from the outcrop. There are also a number of cairns on the lower ground and many hut circles in the area. The panel is on an almost circular outcrop 2.8 x 2.8m and a maximum height of 0.6m. The outcrop has a flat top with a very slight slope to the west. The edges of the outcrop are

	covered with heather and the visible surface of the outcrop is completely covered with a variety of lichens and a little moss. There are 5 cup marks scattered over the surface in no particular obvious pattern. <1> NGR adjusted based on 2020 vertical aerial photographs. <2> Sources/Archives (2) <1> SHG28055 Interactive Resource/Online Database: Historic Environment Scotland. 2017-. Scotland's Rock Art (ScRAP). ScRAP ID 333. <2> SHG28725 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 2020. Getmapping aerial photography 2020. XY
Asset/Event Number	235
Asset/Event Name	Strath Sgitheach (East) Ss2
Type of Asset/Event	Roundhouse (Period Unknown)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH56SW 89.00
HER Number	MHG62694
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252569
Northing	863331
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under heather and moss, measuring 11m by 8m over somewhat poorly defined banks which stand 0.2m tall and are spread up to 2.5m wide. Entrance not discernible. https://canmore.org.uk/site/369785/ Field Visit (May 2020 - June 2020) NH 524 633 (roughly centred) This group of 12 roundhouses in the upper part of Strath Sgitheach is NE of the track from the bridge/stepping stones. The roundhouses are on a SE–facing slope in heathery ground at an altitude of c250m and on both sides of a small burn. Just four roundhouses have been previously recorded although more than this are seen on snowy aerial photographs taken by Jim Bone in February 2010 (see JSB collection). They were surveyed in May and June 2020. The majority of the roundhouses are circular and have internal diameters of between 6m and 9m. The surrounding banks are up to 0.5m height and are often damaged or incomplete. One of the roundhouses, SS5, has more substantial remains which are 0.6m high and have a spread of 2m. Only a few of the roundhouses have evidence of entrances. NH 52545 63270 Roundhouse (SS1) NH 52569 63323 Roundhouse (SS2) [Asset 235] NH 52533 63331 Roundhouse (SS3) NH 52473 63284 Roundhouse (SS4) NH 52418 63278 Roundhouse (SS5) (previously recorded as “B”) NH 52396 63297 Roundhouse (SS6) (previously recorded as “D”) NH 52385 63289 Roundhouse (SS7) (previously recorded as “C”) NH 52416 63233 Roundhouse (SS8) NH 52303 63332 Roundhouse (SS12) (previously recorded as “A”) NH 52107 63397 Roundhouse (SS14) NH 52297 63481. Roundhouse (SS15)

	NH 52458 63350 Roundhouse (SS17) Archive: Highland Council HER and NRHE Meryl Marshall – NOSAS (Source: DES Vol 21) References Marshall, M. (2021) Strath Sgitheach (East), Walkover survey and recording, in Jennifer Thoms, Discovery Excav Scot, New, vol. 21, 2020. Cathedral Communications Ltd, Wiltshire, England. Page(s): 67-68
Asset/Event Number	236
Asset/Event Name	Strath Sgitheach (East) Ss3
Type of Asset/Event	Roundhouse (Period Unknown)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH56SW 90.00
HER Number	MHG62695
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252533
Northing	863331
Council	Highland
Condition:	Very degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under tall heather, measuring c10 in diameter over poorly defined banks that stand c 0.3m tall and spread up to 2m wide. No discernible entrance. Https://canmore.org.uk/site/369786/ Field Visit (May 2020 - June 2020) NH 524 633 (roughly centred) This group of 12 roundhouses in the upper part of Strath Sgitheach is NE of the track from the bridge/stepping stones. The roundhouses are on a SE–facing slope in heathery ground at an altitude of c250m and on both sides of a small burn. Just four roundhouses have been previously recorded although more than this are seen on snowy aerial photographs taken by Jim Bone in February 2010 (see JSB collection). They were surveyed in May and June 2020. The majority of the roundhouses are circular and have internal diameters of between 6m and 9m. The surrounding banks are up to 0.5m height and are often damaged or incomplete. One of the roundhouses, SS5, has more substantial remains which are 0.6m high and have a spread of 2m. Only a few of the roundhouses have evidence of entrances. NH 52545 63270 Roundhouse (SS1) NH 52569 63323 Roundhouse (SS2) [Asset 235] NH 52533 63331 Roundhouse (SS3) [Asset 236] NH 52473 63284 Roundhouse (SS4) NH 52418 63278 Roundhouse (SS5) (previously recorded as “B”) NH 52396 63297 Roundhouse (SS6) (previously recorded as “D”) NH 52385 63289 Roundhouse (SS7) (previously recorded as “C”) NH 52416 63233 Roundhouse (SS8) NH 52303 63332 Roundhouse (SS12) (previously recorded as “A”) NH 52107 63397 Roundhouse (SS14) NH 52297 63481. Roundhouse (SS15) NH 52458 63350 Roundhouse (SS17)

	Archive: Highland Council HER and NRHE Meryl Marshall – NOSAS (Source: DES Vol 21) References Marshall, M. (2021) Strath Sgitheach (East), Walkover survey and recording, in Jennifer Thoms, Discovery Excav Scot, New, vol. 21, 2020. Cathedral Communications Ltd, Wiltshire, England. Page(s): 67-68
Asset/Event Number	237
Asset/Event Name	Dunrobin Glen
Type of Asset/Event	Dyke (Period Unassigned)
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 69.00
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	279348
Northing	904912
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/371095/ Desk Based Assessment (1 April 2014) An archaeological desk-based assessment and walkover survey was carried out on 1 April 2014 on behalf of Scottish Water from Loch Farlary to Bridge of Horn, Golspie in advance of the proposed construction of a new water main. The work was undertaken to assess the nature and extent of any archaeology likely to be directly affected by the proposed development in order to inform recommendations for the protection and management of any sites identified. Seven archaeological sites, two of which will be directly impacted by the current development layout, were recorded. These included a burnt mound, hut circles and Post Medieval structures. Information from OASIS ID: rosscrom1-177267 (L Fraser and M Peteranna) 2014 Field Visit (1 April 2014) An archaeological desk-based assessment and walkover survey was carried out on 1 April 2014 on behalf of Scottish Water from Loch Farlary to Bridge of Horn, Golspie in advance of the proposed construction of a new water main. The work was undertaken to assess the nature and extent of any archaeology likely to be directly affected by the proposed development in order to inform recommendations for the protection and management of any sites identified. Seven archaeological sites, two of which will be directly impacted by the current development layout, were recorded. These included a burnt mound, hut circles and Post Medieval structures. Information from OASIS ID: rosscrom1-177267 (L Fraser and M Peteranna) 2014 Field Visit (1 April 2014) Turf-covered stone dyke that may have formed part of the Post Medieval cultivation and animal husbandry practices in the area. Information from OASIS ID: rosscrom1-177267 (L Fraser and L Peteranna) 2014
Asset/Event Number	238
Asset/Event Name	An Dun, Cornhill Wood

Type of Asset/Event	Promontory Fort (Prehistoric)
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH45SE 57.00
HER Number	MHG60939
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245840
Northing	851960
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Medium
Description	*Recorded by AOC Archaeology during 2024 walkover survey - see sub-elements of Asset 238 for details. Https://canmore.org.uk/site/339438/ Field Visit (3 September 1943) RCAHMS Emergency Survey (Archaeology) This fort, which is simply indicated on the 6 in. OS map by the place-name 'An Dun', in Roman type, is situated on a ridge-like summit about 600 ft. high which rises from the right bank of the Orrin about half a mile NNW of Cornhill. The highest point of the ridge is at its W end, and from here it descends E for about 400 ft., with precipitous sides on the N and S, to the lip of the steep slope that falls in that direction towards the valley. About 100 ft. W of this lip the ridge is traversed by the innermost rampart of a system of defences which faces W towards the summit. The ridge here is about 90 ft. broad, and the rampart, which now consists of a mere rickle of stony debris with some traces of a built face showing on its W side, is 15 ft. thick on the axis of the ridge and markedly convex towards the W. Eleven feet outside the face of the first rampart the ground begins to slope upwards to the second, evidently another construction of stonework but largely overgrown; the actual inner edge of the rampart is 19 ft. outside the face of the first, while its crest, which is 5 ft. high, and its outer edge are, respectively, 7 ft. and 15 ft. further W. The crest of the second rampart is 3 ft. high. The second rampart crosses the ridge in the same manner as the first, and on the S side connects with another defensive bank which returns E to connect with the first rampart towards its S end. A third rampart, 9 ft. thick and 2 ft. 6 in. high, is met 11 ft. W of the outer edge of the second; this likewise spans the ridge, which is here narrowing, and returns E at its S end. In the returned portion two very large blocks of stone appear, one of them 5 ft. in length, and the outer face of the rampart is defined by a row of large rounded boulders. The extreme W end of the defensive system consists of a D-shaped enclosure which projects 16 ft. along the axial line beyond the W face of the third rampart. This is of slighter construction than the rest of the works, and is the only part of them in which any wall appears along the lip of the precipitous N slope. A local tradition states that this enclosure has been used as a burying ground. The foregoing account was prepared after an unavoidably hurried visit when the site was largely obscured by bracken; while it is probably correct in the main, many details may be wrong and a definitive description should be based on a proper survey. The general similarity of this fort to the one on Craig Dhu, Kilmorack Parish, should be noted. Visited by RCAHMS (AG) 3 September 1943. Field Visit (28 February 2014) This fort, which was first recorded by Angus Graham (RCAHMS) during the Emergency Surveys of 1943, occupies a promontory 80m E of the summit of An Dùn, where it lies within the southern part of Cornhill Wood at a height of about 230m OD. The promontory is defined by cliffs on the N and S and a steep slope on the E; on the W, where approach is easiest, three parallel walls have been drawn across the neck of the promontory, thus enclosing a roughly rectangular area measuring 52m from E to W by 29m transversely. The innermost wall measures about 20m in length and has collapsed to form a rubble spread up to 7m in thickness and 1.8m in height in which a line of outer facing-stones is visible 2m

from the outer edge. This wall also appears to turn to the E at both ends, although it does not extend along either the N or S side. The second wall lies 4m from the first and comprises a grass-grown spread of rubble 5m in thickness and 1.2m in height, though the original thickness was probably nearer 2m. The third wall, which is situated 3m from the second, measures about 2.5m in thickness and 1m in height. The entrance to the fort may have been on the S, where the second and third walls stop short of the cliff-edge. No internal features were noted on the date of visit.
Visited by RCAHMS (GFG, JRS, IP) 28 February 2014.

Note (16 March 2017 - 16 March 2017)
Atlas of Hillforts of Britain and Ireland
This fort lies 80m E of the summit of An Dun, where cliffs on the N and S, and a steep slope falling away to the E form a promontory. Internally it measures about 52m from E to W by 29m transversely (0.15ha) and is defended by a band of three walls some 20m long by 21.5m deep barring access from the W. The innermost turns back briefly onto the N and S sides before disappearing, but the flanks are otherwise undefended. The walls are all reduced to mounds of rubble, but a line of outer facing-stones can be seen within the margin of the innermost, which rises 1.8m high and is spread 7m thick. The second wall lies 4m outside the first and is spread 5m in thickness by 1.2m in height, while the third, a further 3m to the exterior, about 2.5m in thickness by 1m in height. The two outer walls stop short of the cliff-edge on the S, possibly indicating the position of an entrance. The interior is featureless.
Information from An Atlas of Hillforts of Great Britain and Ireland – 16 March 2017. Atlas of Hillforts SC4381

References
RCAHMS. (1942-3) Emergency Survey of archaeological monuments in military training areas, 1981, 2v. Typescripts. Page(s): Ross 48 RCAHMS Shelf Number: A.1.1.SUR

Asset/Event Number	239
Asset/Event Name	Strath Sgitheach (East) Ss4
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH56SW 91.00
HER Number	MHG8925; MHG62696
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252473
Northing	863284
Council	Highland
Condition:	Degraded
Alignment:	Circular
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A degraded hut circle under heather, measures c12m in diameter over walls. Walls spread to 1.5m and stand to 0.3m tall. Entrance not discernible. Https://canmore.org.uk/site/369778/ https://canmore.org.uk/site/369786/ Field Visit (May 2020 - June 2020) NH 524 633 (roughly centred) This group of 12 roundhouses in the upper part of Strath Sgitheach is NE of the track from the bridge/stepping stones. The roundhouses are on a SE–facing slope in heathery ground at an altitude of c250m and on both sides of a small burn. Just four roundhouses have been previously recorded although more than this are seen on snowy aerial photographs taken by Jim Bone in February 2010 (see JSB collection). They were surveyed in May and June 2020.

	The majority of the roundhouses are circular and have internal diameters of between 6m and 9m. The surrounding banks are up to 0.5m height and are often damaged or incomplete. One of the roundhouses, SS5, has more substantial remains which are 0.6m high and have a spread of 2m. Only a few of the roundhouses have evidence of entrances. NH 52545 63270 Roundhouse (SS1) NH 52569 63323 Roundhouse (SS2) [Asset 235] NH 52533 63331 Roundhouse (SS3) [Asset 236] NH 52473 63284 Roundhouse (SS4) [Asset 239] NH 52418 63278 Roundhouse (SS5) (previously recorded as "B") NH 52396 63297 Roundhouse (SS6) (previously recorded as "D") NH 52385 63289 Roundhouse (SS7) (previously recorded as "C") NH 52416 63233 Roundhouse (SS8) NH 52303 63332 Roundhouse (SS12) (previously recorded as "A") NH 52107 63397 Roundhouse (SS14) NH 52297 63481. Roundhouse (SS15) NH 52458 63350 Roundhouse (SS17) Archive: Highland Council HER and NRHE Meryl Marshall – NOSAS (Source: DES Vol 21) References Marshall, M. (2021) Strath Sgitheach (East), Walkover survey and recording, in Jennifer Thoms, Discovery Excav Scot, New, vol. 21, 2020. Cathedral Communications Ltd, Wiltshire, England. Page(s): 67-68
Asset/Event Number	240
Asset/Event Name	Muir Of Fairburn
Type of Asset/Event	Cross Incised Stone (Early Medieval)
Date and/or Period	Early Historic
Listing No./NRHE Number	NH45SE 59.00
HER Number	MHG60932
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248250
Northing	852990
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/345694/ Field Visit (3 September 1943) RCAHMS Emergency Survey (Archaeology) This is a boulder incised with a consecration-cross only 6 1/2 inches in diameter. It forms part of the coping of the wall on the E side of the high-road just S of the entrance to the E avenue of Fairburn House, at the fence dividing the house called Cabar Feidh and the next to the N. The suggestion has been made to take it to Fairburn House for preservation indoors. Visited by RCAHMS (AG) 3 September 1943. References RCAHMS. (1942-3) Emergency Survey of archaeological monuments in military training areas, 1981, 2v. Typescripts. Page(s): Ross 52 RCAHMS Shelf Number: A.1.1.SUR

Asset/Event Number	241
Asset/Event Name	Arcan Muir
Type of Asset/Event	Cairn(s) (Period Unassigned)
Date and/or Period	Unknown
Listing No./NRHE Number	NH45SE 60.00
HER Number	n/a
Status	Non-designated Heritage Asset
Section:	N/A
Easting	248000
Northing	852000
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	https://canmore.org.uk/site/345696/ Field Visit (3 September 1943) RCAHMS Emergency Survey (Archaeology) An area densely overgrown with bracken extends W from a point about 100 yds S of the front of the house called Arcan Croft, No. 2. It is said to contain an unstated number of cairns, and should be examined at a season when the bracken is not an obstacle. Visited by RCAHMS (AG) 3 September 1943. References RCAHMS. (1942-3) Emergency Survey of archaeological monuments in military training areas, 1981, 2v. Typescripts. Page(s): Ross 50 RCAHMS Shelf Number: A.1.1.SUR
Asset/Event Number	37.1
Asset/Event Name	Hut circle, Cnoc na h-Uamha
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH56SW 10
HER Number	MHG8929
Status	Non-designated Heritage Asset
Section:	N/A
Easting	250751
Northing	862241
Council	Highland
Condition:	Very Degraded
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle within the Scheduled Area for SM4728, survives as a fairly poorly defined hut circle c10m in diameter over banks which appear to spread c1.5m wide and stand 0.4m tall. A modern track has cut over the centre, with modern signage erected to dissuade this. See SM description under Asset 37.
Asset/Event Number	37.2
Asset/Event Name	Hut circle, Cnoc na h-Uamha

Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH56SW 10.00
HER Number	MHG8929
Status	Non-designated Heritage Asset
Section:	N/A
Easting	250900
Northing	862351
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Hut circle under heather, measures c15m by 12m over banks which stand 0.4 tall and spread c2 .5m wide. Entrance in the SSE.

Asset/Event Number	37.3
Asset/Event Name	Hut circle, Cnoc na h-Uamha
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH56SW 10.00
HER Number	MHG8929
Status	Non-designated Heritage Asset
Section:	N/A
Easting	250914
Northing	862361
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Hut circle under heather, c23m by 19m NW/SE over banks, which stand c0.4 tall and spread c2.5m wide. Entrance in SE.

Asset/Event Number	37.4
Asset/Event Name	Hut circle, Cnoc na h-Uamha
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH56SW 10.00
HER Number	MHG8929
Status	Non-designated Heritage Asset
Section:	N/A

Easting	250773
Northing	862349
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Hut circle under heather, c16m diameter over banks c2-3m wide and 0.2-0.5m tall, poorly defined on S side. Entrance not discerned.

Asset/Event Number	44
Asset/Event Name	Achorn Bridge, prehistoric and post medieval settlement 400m ENE of
Type of Asset/Event	Prehistoric settlement
Date and/or Period	Prehistoric/Post-medieval
Listing No./NRHE Number	
HER Number	MHG1263; MHG38949
Status	Scheduled Monument
Section:	A1.4
Easting	313757
Northing	930605
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	High
Description	*Observed by AOC Archaeology during 2024 walkover survey. Scheduled prehistoric hut circles and post-medieval settlement remains along the Achorn burn, under dense bracken and grasses. Https://portal.historicenvironment.scot/designation/SM512 This site consists of a prehistoric settlement which is overlain to the W by a post medieval settlement. The prehistoric site is on 2 main levels on the SE flank of a rise protected on the S by the gorge of the Achorn Burn. The site is difficult to interpret, but appears to consist of at least 4 hut circles from 10 to 12m in diameter and an oblong structure. The settlement has been robbed of stone, probably to build the sheepfold and post medieval settlement immediately to the W. The walls are generally reduced to a scatter of turf-covered rubble stone. A number of 'box-like' compartments formed of slabs on edge occur within the walls of the houses. The post medieval settlement contains several phases of occupation including a long house with a later house built over the top. The long house was at least 36 by 5m and appears to have had 5 rooms. The later house is about 15 by 5m and has 2 rooms. The walls of this house survive to the gable, but the roof has fallen. The walls are partly mortared and partly dry-stone built and the date 1832 is carved to the left of the doorway. Traces of another rectangular building are visible between this building and a circular sheepfold to the E and there is a second rectangular sheepfold to the WSW of the house. The area to be scheduled measures 230m WSW-ENE by a maximum of 75m NNW-SSE, to include the prehistoric and post medieval settlements, as shown in red on the attached map.

Asset/Event Number	108.1
Asset/Event Name	Hut circle, Ousdale Burn

Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	ND02SE 16
HER Number	MHG814
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	306651
Northing	920611
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under grass and bracken, measuring 8m in diameter over banks c0.5-0.7m in width and 0.5m tall. A 1.5m wide entrance is visible in the SE side. A significant portion of stonework is exposed in the N of the bank. See Asset 108 for full HER description.

Asset/Event Number	108.2
Asset/Event Name	Dyke, Ousdale Burn
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND02SE 16
HER Number	MHG814
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	306658
Northing	920583
Council	Highland
Condition:	Very degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke partially under grass. Stands as only some intermittent boulders up to 1.5m long and likely once built up with turf that has since degraded. Partially encloses the hut circles Assets 108.1 and 108.3, but very ephemeral in parts. This portion measures c88m in length. Less uniform than the nearby dyke Asset 108.6, but the date is still uncertain. See Asset 108 for full HER description.

Asset/Event Number	108.2
Asset/Event Name	Dyke, Ousdale Burn
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND02SE 16
HER Number	MHG814
Status	Non-designated Heritage Asset

Section:	A1.4
Easting	306746
Northing	920605
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke partially under grass. Stands as only some intermittent boulders up to 1.5m long and likely once built up with turf that has since degraded. Partially encloses the hut circles Assets 108.1 and 108.3, but very ephemeral in parts. This portion measures c40m in length. See Asset 108 for full HER description.
Asset/Event Number	108.3
Asset/Event Name	Possible hut circle, Ousdale Burn
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	ND02SE 16
HER Number	MHG814; MHG39434
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	306706
Northing	920595
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Possible small hut circle or oval-shaped structure under heather and grass. Measures c6m in diameter with a bank c1m wide and up to 0.2m tall. A possible 1m-wide entrance visible in the SE. A deer/sheep path has eroded the N side. See Asset 108 for full HER description.
Asset/Event Number	108.4
Asset/Event Name	Hut circle, Ousdale Burn
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	ND02SE 16
HER Number	MHG814
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	306774
Northing	920643
Council	Highland
Condition:	Very Degraded

Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible small hut circle under heather and grass. Measures c8m in diameter over banks, which stand 0.4m tall and spread up to 1.5m wide. A c1m wide entrance is visible in the SE portion of the bank. See Asset 108 for full HER description.

Asset/Event Number	108.5
Asset/Event Name	Clearance cairn, Ousdale Burn
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	ND02SE 16
HER Number	MHG814
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	306785
Northing	920659
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn under heather, measuring 4m in diameter and standing 0.5m tall. Cairn is bisected by a deer/sheep path 0.3m wide. See Asset 108 for full HER description.

Asset/Event Number	108.6
Asset/Event Name	Dyke, Ousdale Burn
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND02SE 16
HER Number	MHG814
Status	Non-designated Heritage Asset
Section:	A1.4
Easting	306657
Northing	920596
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone and turf dyke mostly under grass, c60m long and standing to 0.3m tall, spread up to 2m wide. Predominantly composed of intermittent large stones that may have formed the foundation of the dyke, with the turf degraded away. Somewhat more uniform than the nearby dyke Asset 108.2, and may of later date. Not depicted on historic mapping. See Asset 108.2 for HER

	description.
Asset/Event Number	110
Asset/Event Name	Hut circle, Morvich Burn
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 25.00
HER Number	MHG10648
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275545
Northing	902080
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under grass, somewhat oval in plan and measuring 12m by 10m over walls, which are visible as stoney banks spread 1.7m wide and standing 0.7m tall. Entrance visible as a depression in the SE quarter. Situated on a small terrace. Description from HER: https://canmore.org.uk/site/5934/ A hut circle measuring 11.5m in diameter within a wall composed of an inner face of contiguous slabs on edge backed by rubble. In the main a wall thickness of 2m is indicated except around an entrance gap in S, where it is 3m. The entrance displays two outer portal slabs 1.5m apart (OS {RDL}). Contemporary cultivation is marked by a scattering of stone clearance heaps in the immediate vicinity. Visited by OS (R D L) 15 April 1964 and (J M) 31 July 1975.
Asset/Event Number	115.1
Asset/Event Name	Hut circle, Allt nan Sgeith
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 40.00
HER Number	MHG10597
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279517
Northing	904548
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle and heather under grass and heather, measuring c11m internally in diameter with banks spread up to 2m and standing 1m tall in some places. A possible entrance in the SE side with a collapsed orthostat visible. See Asset 115 for HER description.
Asset/Event Number	115.2
Asset/Event Name	Hut circle, Allt nan Sgeith
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 40.00
HER Number	MHG10597
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279512
Northing	904519
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle and heather under grass and heather, measuring c11m internally in diameter with banks spread up to 2m and standing 1m tall on the downslope side and partly revetted. No discernible entrance. See Asset 115 for HER description.
Asset/Event Number	115.3
Asset/Event Name	Hut circle, Allt nan Sgeith
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 40.00
HER Number	MHG10597
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279551
Northing	904508
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle and heather under grass and heather, measuring c16m in diameter over banks which are spread up to 2m and standing 1.4m tall. A possible entrance in the form of a c1.5m wide depression in the SW side is visible. The hut circle occupies a slight terrace above the burn to the west with views over the wider strath and the rest of the prehistoric settlement and agricultural remains to the NW. See Asset 115 for HER description.
Asset/Event Number	115.4

Asset/Event Name	Hut circle, Bridge of Horn
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 40.00
HER Number	MHG10597
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279526
Northing	904474
Council	Highland
Condition:	Very degraded
Alignment:	Curving
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An arc of turf and stone bank under heather and grass, likely the remains of a robbed-out hut circle. Measures c15m long with the bank spread up to c2m and standing 0.3m tall, forming a possible diameter of c10m internally. Likely robbed out for nearby hut circles. See Asset 115 for HER description.

Asset/Event Number	115.5
Asset/Event Name	Hut circle, Allt nan Sgeith
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 40.00
HER Number	MHG10597
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279493
Northing	904566
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under heather and grass with poorly defined banks. Measures c17m in diameter over banks, which stand 0.7m tall and are spread up to 2m wide. Best preserved along the NE and SW sides. Some boulder visible along the N edge. Possibly robbed out on the SE side for the adjacent hut circles, as this is very poorly defined in comparison to it and the other two well-preserved hut circles Assets 115.2 and 115.3. Entrance not discernible. See Asset 115 for HER description.

Asset/Event Number	115.6
Asset/Event Name	Dyke, Allt nan Sgeith
Type of Asset/Event	Dyke
Date and/or Period	Unknown
Listing No./NRHE Number	NC70SE 40.00

HER Number	MHG10597
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279481
Northing	904530
Council	Highland
Condition:	Very degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Remnants of a dyke or possible lynchet under grass and heather, visible as a slight ledge aligned NW/SE and standing 0.7m tall, with 2-3 stones visible protruding from edge. It is only a short segment of c25m, appearing to join a natural small hillock to the NW. See Asset 115 for HER description.

Asset/Event Number	115.7
Asset/Event Name	Clearance cairn, Allt nan Sgeith
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 40.00
HER Number	MHG10597
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279556
Northing	904415
Council	Highland
Condition:	Very Degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A probable prehistoric clearance cairn measuring c7m in diameter and standing 1.2m tall under grass and bracken. The cairn is situated above the stream course and a deer trail through it has revealed several large stones. See Asset 115 for HER description.

Asset/Event Number	115.8
Asset/Event Name	Clearance cairn, Allt nan Sgeith
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 40.00
HER Number	MHG10597
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279500
Northing	904501
Council	Highland

Condition:	Very Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass. Stands 0.7m tall and spread 5m by 4m. See Asset 115 for HER description.

Asset/Event Number	115.9
Asset/Event Name	Clearance cairn, Allt nan Sgeith
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 40.00
HER Number	MHG10597
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279485
Northing	904503
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under grass and moss, some stone visible. Stands 0.6m tall and spread 7m by 4.5m. See Asset 115 for HER description.

Asset/Event Number	115.10
Asset/Event Name	Clearance cairn, Allt nan Sgeith
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 40.00
HER Number	MHG10597
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279487
Northing	904491
Council	Highland
Condition:	Very Degraded
Alignment:	NW/SE
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Stands 0.6m tall and spread 7m by 4m. See Asset 115 for HER description.

Asset/Event Number	116.1
Asset/Event Name	Hut circle, Allt Bad A Chrasgaidh
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274995
Northing	902458
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under grass and heather with poorly defined banks, c7-8m in diameter. Banks stand 0.4m tall and spread 2m wide. Entrance not discernible. See Asset 116 for HER description.

Asset/Event Number	116.2
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274971
Northing	902451
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 5m in diameter and stands 0.6m tall. See Asset 116 for HER description.

Asset/Event Number	116.3
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh

Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274977
Northing	902455
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 2m in diameter and stands 0.5m tall. See Asset 116 for HER description.

Asset/Event Number	116.4
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274987
Northing	902450
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 6m in diameter and stands 0.7m tall. See Asset 116 for HER description.

Asset/Event Number	116.5
Asset/Event Name	Clearance cairn, Morvaich Estate
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A

Easting	274837
Northing	902592
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small clearance cairn measuring 2.5m in diameter and standing 0.9m tall, deposited against a small natural boulder. May be prehistoric given its proximity/location to the hut circles and field systems to the SW, but is also adjacent to an area of post-medieval peat cutting (Asset 416). See Asset 116 for HER description.
Asset/Event Number	116.6
Asset/Event Name	Clearance cairn, Morvaich Estate
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274832
Northing	902619
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small clearance cairn measuring 6m by 4.5m and standing 0.9m tall. May be prehistoric given its proximity/location to the hut circles and field systems to the SW, but is located within an area of shallow post-medieval peat cutting (Asset 416). See Asset 116 for HER description.
Asset/Event Number	116.7
Asset/Event Name	Structure, Allt Bad A Chrasgaidh
Type of Asset/Event	Structure
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274992
Northing	902444
Council	Highland
Condition:	Very Degraded
Alignment:	N/A

Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A heather and grass-covered bank c3m in diameter internally with banks that stand 0.3m tall and spread up to 1.5m wide, with a possible entrance to the NE. Possibly an augmented prehistoric clearance cairn. Function uncertain. See Asset 116 for HER description.
Asset/Event Number	116.8
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274983
Northing	902444
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 5m in diameter and stands 0.6m tall. See Asset 116 for HER description.
Asset/Event Number	116.9
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274988
Northing	902436
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 4m in diameter and stands 0.6m tall. See Asset 116 for HER description.
Asset/Event Number	116.10

Asset/Event Name	Prehistoric clearance cairn, Morvaich Estate
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274850
Northing	902569
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A probable prehistoric clearance cairn under grass, stands 0.8m tall and 6m in diameter. See Asset 116 for HER description.

Asset/Event Number	116.11
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274985
Northing	902420
Council	Highland
Condition:	Very Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 6m in diameter and stands 1m tall. See Asset 116 for HER description.

Asset/Event Number	116.12
Asset/Event Name	Prehistoric clearance cairn, Morvaich Estate
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34
HER Number	MHG10630
Status	Non-designated Heritage Asset

Section:	N/A
Easting	274863
Northing	902562
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small prehistoric clearance cairn under grass and heather, stands 0.7m tall and 6m in diameter. See Asset 116 for HER description.

Asset/Event Number	116.13
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274967
Northing	902443
Council	Highland
Condition:	Very Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 5.5m in diameter and stands 1m tall. See Asset 116 for HER description.

Asset/Event Number	116.14
Asset/Event Name	Prehistoric clearance cairn, Morvaich Estate
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274837
Northing	902548
Council	Highland
Condition:	Degraded
Alignment:	NE/SW

Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass. Measures 8m by 4m and stands 1m tall. See Asset 116 for HER description.

Asset/Event Number	116.15
Asset/Event Name	Clearance cairn, Allt Bad a' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274865
Northing	902531
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass, measures c5m in diameter and stands 0.7m tall. See Asset 116 for HER description.

Asset/Event Number	116.16
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274962
Northing	902425
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 5.5m in diameter and stands 1.1m tall. See Asset 116 for HER description.

Asset/Event Number	116.17

Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274970
Northing	902420
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 7m by 0.4m and stands 0.8m tall. See Asset 116 for HER description.

Asset/Event Number	116.18
Asset/Event Name	Hut circle, Allt Bad a' Chrasgaidh
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274926
Northing	902527
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under heather, c10m in diameter. Extent and form difficult to discern as a result of the vegetation but banks appear 0.7m tall and spread up to 2m wide. Entrance not discernible. See Asset 116 for HER description.

Asset/Event Number	116.19
Asset/Event Name	Clearance cairn, Allt Bad a' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34
HER Number	MHG10630
Status	Non-designated Heritage Asset

Section:	N/A
Easting	274928
Northing	902508
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass, measures c5m in diameter and stands 0.9m tall. See Asset 116 for HER description.

Asset/Event Number	116.2
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	
Northing	
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	VOID - asset number not used

Asset/Event Number	116.21
Asset/Event Name	Hut circle, Allt Bad a' Chrasgaidh
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274888
Northing	902494
Council	Highland
Condition:	Degraded

Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under heather, c12m in diameter over banks, with prominent banks that stand 1m tall externally and internally, with the interior of the hut circle a pronounced dish. Banks are spread 3m wide and bare stone visible in parts. The banks have ben breached in several places and a true entrance is not confidently discernible. See Asset 116 for HER description.

Asset/Event Number	116.22
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274948
Northing	902468
Council	Highland
Condition:	Very Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather, measuring 7m long and 1.5m wide and standing 0.3m tall. See Asset 116 for HER description.

Asset/Event Number	116.23
Asset/Event Name	Clearance cairn, Allt Bad a' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274839
Northing	902435
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible prehistoric clearance cairn under grass, much disturbed by rabbit burrowing. Stands c. 0.4m tall and spread up to 6m in diameter. See Asset 116 for HER description.

Asset/Event Number	116.24
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274971
Northing	902381
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 2.5m by 1.5m and stands 0.7m tall. See Asset 116 for HER description.

Asset/Event Number	116.25
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274975
Northing	902377
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 6m in diameter and stands 1m tall. See Asset 116 for HER description.

Asset/Event Number	116.26
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630

Status	Non-designated Heritage Asset
Section:	N/A
Easting	274958
Northing	902372
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 4m in diameter and stands 1m tall. See Asset 116 for HER description.

Asset/Event Number	116.27
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274976
Northing	902367
Council	Highland
Condition:	Very Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 4m by 3.5m and stands 0.8m tall. See Asset 116 for HER description.

Asset/Event Number	116.28
Asset/Event Name	Hut circle, Allt Bad A Chrasgaidh
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275003
Northing	902366
Council	Highland

Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under heather measuring 8m in diameter internally with banks that stand 1m tall and spread 1.5m wide. Possible entrance in the SW quarter. See Asset 116 for HER description.

Asset/Event Number	116.29
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274983
Northing	902368
Council	Highland
Condition:	Very Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 2m in diameter and stands 0.6m tall. See Asset 116 for HER description.

Asset/Event Number	116.30
Asset/Event Name	Clearance cairn, Allt Bad a' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274803
Northing	902608
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible prehistoric clearance cairn under grass and heather. Stands 4m in diameter and stands 0.3m tall. The cairn is within an area of post-medieval peat cutting (Asset 416). See Asset 116 for HER description.

Asset/Event Number	116.31
Asset/Event Name	Clearance cairn, Allt Bad a' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274810
Northing	902575
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass. Measures 6m by 4m and stands 0.5m tall. See Asset 116 for HER description.

Asset/Event Number	116.32
Asset/Event Name	Clearance cairn, Allt Bad a' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274818
Northing	902561
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass. Measures 6m in diameter and stands 0.3m tall. See Asset 116 for HER description.

Asset/Event Number	116.34
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh

Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274982
Northing	902350
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 5m in diameter and stands 0.7m tall. See Asset 116 for HER description.

Asset/Event Number	116.35
Asset/Event Name	Hut circle, Allt Bad A Chrasgaidh
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275012
Northing	902349
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under grass and heather measuring 8m in diameter over banks that are poorly defined, perhaps 0.6m tall and spread up to 2m wide. Entrance not discernible. See Asset 116 for HER description.

Asset/Event Number	116.36
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A

Easting	275032
Northing	902329
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 6m in diameter and stands 0.6m tall. See Asset 116 for HER description.

Asset/Event Number	116.37
Asset/Event Name	Hut circle, Allt Bad A Chrasgaidh
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274956
Northing	902323
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under heather and grass measuring 12.5m by 10m. Poorly defined banks and possibly partially constructed on boulder outcrop on S side. Set on a slight shelf of the S facing hill slope. Banks stand 0.3m tall and spread 1.5m wide. Entrance not discernible. See Asset 116 for HER description.

Asset/Event Number	116.38
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274964
Northing	902311
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small prehistoric clearance cairn under heather and grass. Measures 5m in diameter and stands 0.3m tall. See Asset 116 for HER description.

Asset/Event Number	116.39
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274986
Northing	902306
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 6m in diameter and stands 0.6m tall. See Asset 116 for HER description.

Asset/Event Number	116.40
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274973
Northing	902291
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass, possibly built onto an exposed protrusion of bedrock. Measures 7m by 5m and stands 0.4m.tall. See Asset 116 for HER description.

Asset/Event Number	116.41
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh

Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274995
Northing	902379
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass. Measures 8m in diameter and stands 1.5m tall. See Asset 116 for HER description.

Asset/Event Number	116.42
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275012
Northing	902403
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass. Measures 7m by 5m and 1m tall. See Asset 116 for HER description.

Asset/Event Number	116.43
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A

Easting	274999
Northing	902394
Council	Highland
Condition:	Very Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 6m by 3m and stands 0.6m tall. See Asset 116 for HER description.

Asset/Event Number	116.44
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275030
Northing	902287
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass. Measures 5m in diameter and stands 0.4m tall See Asset 116 for HER description.

Asset/Event Number	116.45
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275053
Northing	902288
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass. Measures 7m in diameter and stands 0.7m tall. See Asset 116 for HER description.

Asset/Event Number	116.46
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275078
Northing	902268
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 8m by 5m and stands 1m tall. See Asset 116 for HER description.

Asset/Event Number	116.47
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275062
Northing	902237
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 5m in diameter and stands 0.3m tall. See Asset 116 for HER description.

Asset/Event Number	116.48
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh

Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275059
Northing	902219
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass. Measures 4m in diameter and stands 0.5m tall. See Asset 116 for HER description.

Asset/Event Number	116.49
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274992
Northing	902355
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 3m in diameter and stands 0.5m tall. See Asset 116 for HER description.

Asset/Event Number	116.50
Asset/Event Name	Clearance cairn, Allt Bad a' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SW 34
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A

Easting	274901
Northing	902500
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass, measures 5m by 3m and stands 0.6m tall. See Asset 116 for HER description.

Asset/Event Number	117.1
Asset/Event Name	Enclosure, Allt Bad A Chrasgaidh
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SW 35
HER Number	MHG10631
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274683
Northing	902037
Council	Highland
Condition:	Very degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone and turf dykes under tall heather forming a small enclosure c16m by 6m over banks, c10m to the SE of homestead Asset 117.2. Difficult to trace extent in the vegetation, but banks stand c 0.6-0.9m tall. Not depicted on historic mapping. See Asset 117 for HER description.

Asset/Event Number	117.2
Asset/Event Name	Homestead, Allt Bad A Chrasgaidh
Type of Asset/Event	Structure
Date and/or Period	Prehistoric/Early Historic
Listing No./NRHE Number	NC70SW 35
HER Number	MHG10631
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274671
Northing	902056
Council	Highland
Condition:	Very degraded
Alignment:	Circular
Importance:	Low

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A homestead under tall heather, slightly bare along the internal N side of the inner ring of orthostats. On the whole the asset is under tall heather which obscures its definition, but appears much as described in the HER/Canmore as principally two rings of boulders. Not depicted on historic mapping. See Asset 117 for HER description.
Asset/Event Number	117.3
Asset/Event Name	Enclosure, Allt Bad A Chrasgaidh
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SW 35
HER Number	MHG10631
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274655
Northing	902019
Council	Highland
Condition:	Very degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone and turf dyke under tall heather forming a U-shaped enclosure c12m by 6m open banks, open to the NE, and located c30m SW of homestead Asset 117.2. Banks poorly defined due to vegetation, perhaps 0.4m tall and spread up to 1.5m wide. Not depicted on historic mapping. See Asset 117 for HER description.
Asset/Event Number	119.1
Asset/Event Name	Clearance cairn, Glen Sletdale
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC91SW 7.00
HER Number	MHG10027
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	292948
Northing	912692
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn under bracken and grass, measures 7m by 6m and stands 1m tall. See Asset 120 for HER description.
Asset/Event Number	119.2

Asset/Event Name	Hut circle, Glen Sletdale
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC91SW 7.00
HER Number	MHG10027
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	292935
Northing	912690
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under heather and bracken, truncated by the adjacent track on its N side, and the large associated dyke (Asset 448). The surviving remains of the hut circle are banks that extend c18m by 14m and c0.5m tall. Difficult to discern due to the vegetation. See Asset 120 for HER description.

Asset/Event Number	119.3
Asset/Event Name	Hut circle, Glen Sletdale
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC91SW 19.00
HER Number	MHG10048
Status	Non-designated Heritage Asset
Section:	N/A
Easting	292878
Northing	912790
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under bracken and heather, measuring c13m over banks which survive best along the W extent where they stand 0.7m tall and spread 3m wide. The hut circle has been constructed on a small terrace, which appears to be an artificial platform (Asset 119.7). Entrance not discernible but likely in the SE portion that overlooks the lower terrace of the strath in this direction. See Asset 119 for HER description.

Asset/Event Number	119.4
Asset/Event Name	Hut circle, Glen Sletdale
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC91SW 19.00
HER Number	MHG10048

Status	Non-designated Heritage Asset
Section:	A1.5
Easting	292875
Northing	912762
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under tall bracken. Extent difficult to discern due to vegetation. Measures 14m in diameter over banks, which stand to a height of c1m and spread perhaps 4m. Interior is depressed. Entrance not discernible. See Asset 119 for HER description.

Asset/Event Number	119.5
Asset/Event Name	Clearance cairn, Glen Sletdale
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC91SW 19.00
HER Number	MHG10048
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	292857
Northing	912713
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass, measures 6.6m by 3.4m and 1.2m tall. See Asset 119 for HER description.

Asset/Event Number	119.6
Asset/Event Name	Hut circle, Glen Sletdale
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC91SW 19.00
HER Number	MHG10048
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	292862
Northing	912735
Council	Highland

Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle and bracken and heather, measures c16m in diameter over banks which are spread up to 1.5m and stand 1m tall. Entrance is a visible depression in the bank in the SE. See Asset 119 for HER description.

Asset/Event Number	119.7
Asset/Event Name	Platform, Glen Sletdale
Type of Asset/Event	Platform
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC91SW 19.00
HER Number	MHG10048
Status	Non-designated Heritage Asset
Section:	N/A
Easting	292886
Northing	912779
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible platform of earth and stone platform or slightly augmented slope for the hut circle Asset 119.3 to occupy. Appears incongruous with the natural hope slope angle. Forms a small platform for the S and SE edge of the hut circle to occupy, measuring c20m by 15m and raised c0.7-1m above ground level. See Asset 119 for HER description.

Asset/Event Number	119.8
Asset/Event Name	Clearance cairn, Glen Sletdale
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC91SW 19.00
HER Number	MHG10048
Status	Non-designated Heritage Asset
Section:	N/A
Easting	292898
Northing	912775
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under bracken and grass. Measures 7m in diameter and stands 0.9m tall. See Asset 119 for HER description.

Asset/Event Number	119.9
Asset/Event Name	Lynchet, Glen Sletdale
Type of Asset/Event	Lynchet
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC91SW 19.00
HER Number	MHG10048
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	292847
Northing	912713
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A lynchet forming a 34m by 24m earth platform on S-facing slope. Bank on southern end measures 3m wide and 0.6m tall, extends for c35m. See Asset 119 for HER description.

Asset/Event Number	119.10
Asset/Event Name	Hut circle, Glen Sletdale
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC91SW 19.00
HER Number	MHG10048
Status	Non-designated Heritage Asset
Section:	N/A
Easting	292847
Northing	912767
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under dense bracken, measure c13m in diameter over banks which stand 0.7m tall externally and 0.4m internally. A possible entrance in the form of a slight depression in the bank was felt underfoot in the E side. See Asset 119 for HER description.

Asset/Event Number	119.11
Asset/Event Name	Hut circle, Glen Sletdale

Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC91SW 19.00
HER Number	MHG10048
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	292892
Northing	912749
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under grass and bracken, c17 m in diameter. The banks are not as pronounced as the other four nearby hut circles (Assets 19.3, 19.4, 19.6 and 19.10), standing to a height of 0.6m tall and spread up to 4m, possibly robbed for the nearby structures. Slightly depressed in centre. Entrance not discernible. See Asset 119 for HER description.

Asset/Event Number	119.11
Asset/Event Name	Ditch, Glen Sletdale
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 19.00
HER Number	MHG10048
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	292890
Northing	912759
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A c7m long curvilinear ditch c1m wide and 0.4m deep forming the drip gully of hut circle 119.11, visible along its NW side. See Asset 119 for HER description.

Asset/Event Number	122
Asset/Event Name	Morvich Burn
Type of Asset/Event	Settlement
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset

Section:	N/A
Easting	275680
Northing	901760
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey - see sub-elements of Assets 122.1-122.26; Assets 382.1-382.8, 397, 398, and 399 for details. A post-medieval township comprising several buildings and structures and for which there is no trace recorded on the 1st or 2nd edition OS maps. Roy's map of 1747-1752 is not particularly well-illustrated between Rogart Loch Fleet, and it does not appear to show any settlements in the vicinity (but also fails to depict the moderately large Loch Salachaidh to the NW, comparable in size to Loch Horn).The elements that were surveyed (Assets 122.1-122.26; Assets 382.1-382.8, 397, 398, and 399) comprise several buildings, a corn-drying or lime kiln, enclosures, pens, dykes and clearance cairns. The area is recorded in the OS Name Book records for Sutherland as belonging to the Duke of Sutherland, and Clearances are known to have occurred within the Rogart areas in the early part of the 19th century, and so this potentially too may represent Cleared settlement, though further archival research is needed to support this theory. 'Cnoc Bad a' Chrasgaidh' OS1/33/24/1/2 OS Name Books. OS. 1879. Sutherland CIV, Surveyed: 1873-74, Published: 1879. OS Name Book 1871-1775. Sutherland, Volume 24, p2. Roy, W. 1747-1752. Highland.* https://her.highland.gov.uk/monument/MHG11267 Centred NC 756 017 The footings or remains of at least eighteen dwellings ranging from 9m by 3m to 24m by 4.5m and from 0.4m to 1.2m in height, together with numerous associated enclosures. Visited by OS (R D L) 15 April 1964. A township, comprising thirty-one unroofed structures, of which sixteen are enclosures and fifteen are unroofed buildings, is depicted on the current edition of the OS 1:10,000 map (1970). Nothing is shown on the 1st edition of the OS 6-inch map (Sutherland 1879, sheet civ). Information from RCAHMS (AKK) 21 November 1995. A DBA and walkover survey was carried out by Wordsworth Archaeological Services in 1997 advance of a proposed woodland grant scheme at Morvich, Sutherland. 1/14; This rectangular structure on the S side of the burn and N of the track forms an isolated element of the settlement at Site 1/16. Its function is not known. 1/15; A substantial corn-drying kiln, not shown on the 1:2,500 map lies to the E of the path and the main settlement at Site 1/16. This is a well preserved feature. 1/16; The footings of at least 6 rectangular buildings and their associated enclosures survive here. They form part of a small post-medieval farm complex in fairly good preservation, apart from rabbit damage. Stone clearance lines to the W mark the area of former fields. 1/17; An irregular enclosure some 9m in diameter is based on substantial upright boulders and is similar to the ?earlier enclosures at Sites 1/11 & the earlier version of 1/19. It sites on a slight knoll and may well be based on an earlier site. A dyke runs between Sites 1/17 & 1/18 S to the main complex at Site 1/16. 1/18; An irregular enclosure some 9m in diameter is based on substantial upright boulders and is similar to the ?earlier enclosures at Sites 1/11 & the earlier version of 1/19. It sites on a slight knoll and may well be based on an earlier site. A dyke runs between Sites 1/17 & 1/18 S to the main complex at Site 1/16.

	1/19; The enclosure drawn here lies on the site of an earlier one as shown. An irregular boulder links to this and then continues to the W almost to Site1/18 as drawn. The earlier enclosure may be medieval in date. 1/20; 33m to the N of the enclosure at Site 1/19 is a line of stones 4m by 1m sited on a slight hill. This might be the remains of a robbed out cairn. There are no clearance cairns in the vicinity. <1>
Asset/Event Number	122.1
Asset/Event Name	Dyke. Bad A' Chrasgaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275678
Northing	901799
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A degraded stone and turf dyke partially under grass and heather with only intermittent stone remaining, the likely foundation courses for a turf dyke. Breached by existing track. Coursed base of boulders perhaps two stones high up to 0.5m.tall. Spread up to 1.5m wide and c20m 40m long, with enclosure (Asset 122.2) constructed on S side. Not depicted on historic mapping. See Asset 122 for HER description.
Asset/Event Number	122.2
Asset/Event Name	Pen, Bad A' Chrasgaidh
Type of Asset/Event	Pen
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275697
Northing	901802
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Remains of a possible degraded pen built onto E face of dyke Asset 122.1, measuring c11m NE/SW by 7m and standing 0.45m tall. Open to the E but possibly due to robbing. Founds appear as small boulders indicating possibly a turf element once atop, since degraded. Not depicted on historic mapping. See Asset 122 for HER description.

Asset/Event Number	122.3
Asset/Event Name	Building, Bad A' Chrasgaidh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275678
Northing	901775
Council	Highland
Condition:	Very Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone footings for a rectangular building under grass, measuring 8m by 4m and with boulder walls that stand 0.4m tall and spread 0.5m wide, potentially facilitating a turf upper wall since degraded. No discernible entrance. Not depicted on historic mapping. See Asset 122 for HER description.

Asset/Event Number	122.4
Asset/Event Name	Building, Bad A' Chrasgaidh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275669
Northing	901765
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone footings for a rectangular building under grass, measuring 8m by 4m and with boulder walls that stand 0.4m tall and spread 0.5m wide, potentially facilitating a turf upper wall since degraded. No discernible entrance. Not depicted on historic mapping. See Asset 122 for HER description.

Asset/Event Number	122.5
Asset/Event Name	Enclosure, Bad A' Chrasgaidh
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00

HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275712
Northing	901776
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An irregularly shaped enclosure c20m by 20m, constructed from a drystone wall with large boulders at base course and smaller stones atop that stands tallest at the corners up to 1m, and spread up to 1.5m. Not depicted on historic mapping. See Asset 122 for HER description.

Asset/Event Number	122.6
Asset/Event Name	Building, Bad A' Chrasgaidh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275691
Northing	901759
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small rectangular building with drystone walls, measures c8m by 4m over walls and walls stand to 0.8m tall. No internal partitions visible, entrance possibly in the SW elevation but difficult to discern. Not depicted on historic mapping. See Asset 122 for HER description.

Asset/Event Number	122.7
Asset/Event Name	Building, Bad A' Chrasgaidh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275673
Northing	901742
Council	Highland

Condition:	Degraded
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone footings for a rectangular building under grass, measuring 7m by 4m over walls that stand 0.5m tall and spread 0.7m wide. Entrance in the N elevation and situated on E side of enclosure Asset 122.9. Not depicted on historic mapping. See Asset 122 for HER description.

Asset/Event Number	122.8
Asset/Event Name	Kiln, Bad A' Chrasgaidh
Type of Asset/Event	Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275681
Northing	901725
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A kiln built along side the track into the slight slope of a hill, aligned N/S and measuring c12m long by 6m wide, with a small platform of stone to the S in front of the flue, which has collapsed. Possibly a lime kiln rather than corn-drying kiln considering the easily accessible roadside location but this is not definitive. Stands taller at the E side whereas the W is partially revetted into track edge. Not depicted on historic mapping. See Asset 122 for HER description.

Asset/Event Number	122.9
Asset/Event Name	Dyke, Bad A' Chrasgaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275658
Northing	901730
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A degraded stone and turf dyke under grass and moss, spread up to 2m wide and stands to 0.5m tall, c20m long, encloses nearby structures. Not depicted on historic mapping. See Asset 122 for HER description.
Asset/Event Number	122.10
Asset/Event Name	Dyke, Bad A' Chrasgaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275688
Northing	901709
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A degraded stone and turf dyke under grass and moss, spread up to 2.5m wide and stands to 0.6m tall, c50 m long where recorded within the survey corridor. Breached by existing track to the SW and continues out of the survey corridor to the NE. Not depicted on historic mapping. See Asset 122 for HER description.
Asset/Event Number	122.11
Asset/Event Name	Dyke, Bad A' Chrasgaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275664
Northing	901653
Council	Highland
Condition:	Very degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Very degraded stone and turf dyke under grass, stands 0.8m tall and spread up to 2m wide, extending c20m within survey corridor but continues beyond. Not depicted on historic mapping. See Asset 122 for HER description.
Asset/Event Number	122.12

Asset/Event Name	Dyke, Bad A' Chrasgaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275691
Northing	901690
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass, stands up to 1m tall and spread up to 2.5m wide, extending c20m within survey corridor but continues beyond. Mostly represented by intermittent boulders that likely formed the founds of a dyke constructed with turf. Not depicted on historic mapping. See Asset 122 for HER description.

Asset/Event Number	122.13
Asset/Event Name	Clearance cairn, Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275679
Northing	901635
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small clearance cairn under grass, measuring c1.5m in diameter and standing 0.7m tall. See Asset 122 for HER description.

Asset/Event Number	122.14
Asset/Event Name	Clearance cairn, Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267

Status	Non-designated Heritage Asset
Section:	N/A
Easting	275685
Northing	901632
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn under grass and moss, measures 4.5m by 2m and stands 0.4m tall. See Asset 122 for HER description.

Asset/Event Number	122.15
Asset/Event Name	Clearance cairn, Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275676
Northing	901615
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A field clearance cairn partially under grass, deposited at slight base of slope, measures 6m by 2m and stands up to 1m tall due to slope. See Asset 122 for HER description.

Asset/Event Number	122.16
Asset/Event Name	Building, Bad A' Chrasgaidh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275656
Northing	901607
Council	Highland
Condition:	Very Degraded

Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Footings for a rectangular building under grass measuring 6m by 6m with walls that stand up to 1m tall and 0.5m wide, with much stone rubble filled or placed in the interior. Not depicted on historic mapping. See Asset 122 for HER description.

Asset/Event Number	122.17
Asset/Event Name	Clearance cairn, Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275679
Northing	901588
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn of boulders and smaller stones, measuring 33m by 10m and stands 1.6m tall. Has been deposited atop a natural rocky outcrop. See Asset 122 for HER description.

Asset/Event Number	122.18
Asset/Event Name	Dyke, Bad A' Chrasgaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275646
Northing	901597
Council	Highland
Condition:	Very degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Dyke composed mainly of stones but does contain turf and covered in tall grass. Measures c20m long, 0.6m wide with 1m spread on S side and up to 0.5m tall. Not depicted on historic mapping. See Asset 122 for HER description.

Asset/Event Number	122.19
Asset/Event Name	Clearance cairn, Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275690
Northing	901567
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn, partially under grass, of boulders and smaller stones measuring 13m by 6.5m and standing 1.5m tall. It has been deposited against a natural rock outcrop. See Asset 122 for HER description.

Asset/Event Number	122.20
Asset/Event Name	Clearance cairn, Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275674
Northing	901551
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A linear spread of clearance material bisected by both existing tracks. The cairn is visible as some boulders and stone partially under grass, extending 20m by 5m and standing 1m tall on the NE side of the track, and 8m by 5m and 1m tall on the SW side of the track. See Asset 122 for HER description.

Asset/Event Number	122.21
Asset/Event Name	Building, Bad A' Chrasgaidh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267

Status	Non-designated Heritage Asset
Section:	N/A
Easting	275648
Northing	901566
Council	Highland
Condition:	Very Degraded
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Footings for a square building or pen measuring 6m by 6m and with drystone walls that stand up to 0.7m tall and spread 1m wide. A possible S entrance, but this may just be a robbed-out elevation. Not depicted on historic mapping. See Asset 122 for HER description.

Asset/Event Number	122.22
Asset/Event Name	Clearance cairn, Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275653
Northing	901534
Council	Highland
Condition:	Degraded
Alignment:	NNE/SSW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A linear spread of field clearance material partially under grass, measuring 20m by 20m and standing 1m tall. It has been deposited against a small bare section of natural bedrock outcrop. See Asset 122 for HER description.

Asset/Event Number	122.23
Asset/Event Name	Clearance cairn, Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275661
Northing	901557
Council	Highland

Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn measuring 5m by 3.5m and standing 1m tall. See Asset 122 for HER description.

Asset/Event Number	122.24
Asset/Event Name	Clearance cairn, Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275651
Northing	901552
Council	Highland
Condition:	Very Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn measuring 10m by 3m and standing 0.4m tall. See Asset 122 for HER description.

Asset/Event Number	122.25
Asset/Event Name	Clearance cairn, Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275645
Northing	901517
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn measuring 10m by 10m and standing 2m tall (mounded atop natural ridge of bedrock). See Asset 122 for HER description.

Asset/Event Number	122.26
Asset/Event Name	Enclosure, Bad A' Chrasgaidh
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275701
Northing	901751
Council	Highland
Condition:	Very degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An irregularly shaped enclosure, possibly turf and stone but the turf has degraded substantially and only some boulders are visible under grass and moss. The wall spread is up to 2m wide and stands to 0.6m tall. Large gaps adjacent to building Asset 122.6. Not depicted on historic mapping. See Asset 122 for HER description.

Asset/Event Number	130
Asset/Event Name	Polished Axe, Blar Nan Ceann
Type of Asset/Event	Findspot
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH45NE 10.00
HER Number	MHG7898
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247000
Northing	857000
Council	Highland
Condition:	Unknown
Alignment:	N/A
Importance:	Negligible
Description	https://her.highland.gov.uk/monument/MHG7898 A large, Neolithic, polished stone axe of Cumbrian type, 11.6" long, was found c1860 near Blar na Ceann (Blar nan Ceann: NH 476 577) Strathpeffer, and was donated to the NMAS by Alex Walker, FSA Scot, in 1948-9 (Acc No: AF 898). Probably originating in Lake District, it is thought to have reached this area by trade. Proc Soc Antiq Soc 1951; C L Fell 1964

Asset/Event Number	134.1
Asset/Event Name	Corn drying kiln, Strath Sgitheach
Type of Asset/Event	Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH56SW 31.00
HER Number	MHG8906
Status	Non-designated Heritage Asset
Section:	N/A
Easting	253456
Northing	864079
Council	Highland
Condition:	Ruinous
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A corn-drying kiln under grass, measuring 5m in diameter and standing 0.6m tall with a bowl only slightly visible. Flue extends to the SE. Very degraded. Not depicted on the historic maps. See Asset 134 for HER description.

Asset/Event Number	134.2
Asset/Event Name	Building, Strath Sgitheach
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH56SW 31
HER Number	MHG8906
Status	Non-designated Heritage Asset
Section:	N/A
Easting	253470
Northing	864086
Council	Highland
Condition:	Very Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Turf and stone footings for a rectangular building under moss and grass, measuring 14m by 6m over walls which stand up to 1m tall and spread 1.5m wide. Some large boulders visible, suggesting the walls had a turf component which has since degraded. The building has been constructed on a small area of raised ground that stands above the surrounding boggier ground. No discernible entrance. Not depicted on historic mapping. See Asset 134 for HER description.

Asset/Event Number	134.3
Asset/Event Name	Building, Strath Sgitheach
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH56SW 31.00

HER Number	MHG8906
Status	Non-designated Heritage Asset
Section:	N/A
Easting	253487
Northing	864097
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Turf and stone footings for a rectangular building under moss and grass, measuring 40m by 6m over walls which stand up to 0.6m tall and spread 1.5m wide. Some large boulders visible, suggesting the walls had a turf component which has since degraded. The building has been constructed on a small area of raised ground that stands above the surrounding boggier ground. No discernible entrances. Not depicted on historic mapping. See Asset 134 for HER description.
Asset/Event Number	136.1
Asset/Event Name	Building, Alltan Riabhach
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH69NE 24.00
HER Number	MHG10342
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	267477
Northing	898023
Council	Highland
Condition:	Fair
Alignment:	NNE/WSW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A single-storey building roofed in slate, chimneys at each gable end. C12m by 5m over walls. Single central window in the NNW elevation and flanking windows and central doorway in the SSE elevation. Depicted on 1st edition OS map. See Asset 136 for HER description. OS. 1879. Sutherland, Sheet CVIII, Survey date: 1874, Publication date: 1879.
Asset/Event Number	136.2
Asset/Event Name	Building, Alltan Riabhach
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH69NE 24.00
HER Number	MHG10342
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	267499

Northing	898018
Council	Highland
Condition:	Ruinous
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. The stone footings of a rectangular building under grass measuring 10m by 5m over walls. Walls survive to a height of 0.5m and are 0.8m wide. Depicted on 1st edition OS map. See Asset 136 for HER description. OS. 1879. Sutherland, Sheet CVIII, Survey date: 1874, Publication date: 1879.
Asset/Event Number	136.3
Asset/Event Name	Enclosure, Alltan Riabhach
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH69NE 24.00
HER Number	MHG10342
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	267477
Northing	898107
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass and bracken, stands up to 0.8m tall and spread up to 1.5m wide. Forms an enclosure to the NW of the farmstead buildings Assets 136.1 and 136.2. Depicted on 1st edition OS map. See Asset 136 for HER description. OS. 1879. Sutherland, Sheet CVIII, Survey date: 1874, Publication date: 1879.
Asset/Event Number	138.1
Asset/Event Name	Enclosure, Allt Cnoc na Gamhna
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 50.00
HER Number	MHG10395
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	278960
Northing	903909
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. An enclosure under dense bracken, measuring c18m by 8m. Composed of a drystone dyke with double-faced rubble, standing 0.8m tall and 0.6m wide but difficult to see in the bracken. The N compartment measures c7m by 5m while the S widens out and measures c10m by 7m. Entrances not discerned. Not depicted on historic mapping. See Asset 138 for HER description.
Asset/Event Number	138.2
Asset/Event Name	Enclosure, Allt Cnoc na Gamhna
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 50.00
HER Number	MHG10395
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279035
Northing	903940
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke enclosure under grass and bracken c40m by 16m, the dyke stands up to 1.2m tall in some areas and spread up to 1.5m.wide, while in the E segment along the burn it has been revetted into the slope. No clearly discernible entrance but the entirety was very obscured by bracken. Not depicted on historic mapping. See Asset 138 for HER description.
Asset/Event Number	138.3
Asset/Event Name	Enclosure, Allt Cnoc na Gamhna
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 50.00
HER Number	MHG10395
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279016
Northing	903918
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone enclosure under moss and bracken. D shaped in plan and c9m by 7m, stands 1m tall in places, with a double skinned wall 1m wide and rounded corners. A 3m-wide entrance defined by an orthostat and large boulders is present in the straight section of wall on the N side. Not depicted on historic mapping. See Asset 138 for HER description.
Asset/Event Number	138.4

Asset/Event Name	Enclosure, Allt Cnoc na Gamhna
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 50.00
HER Number	MHG10395
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	278977
Northing	903912
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An enclosure under dense bracken, c11m by 11m and composed of drystone wall standing c0.8m tall and 0.6m wide. Corners are rounded. No discernible entrances. Not depicted on historic mapping. See Asset 138 for HER description.

Asset/Event Number	138.5
Asset/Event Name	Dyke, Allt Cnoc na Gamhna
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 50.00
HER Number	MHG10395
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	278995
Northing	903925
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large stone dyke under dense bracken, stands c0.8m tall and spread up to 1m wide, c35m long, and appears to join two enclosures (Assets 138.4 and 138.2), stopping just short of the E Asset 138.2 at a large boulder, allowing for a small entranceway. Not depicted on historic mapping. See Asset 138 for HER description.

Asset/Event Number	139.1
Asset/Event Name	Building, Allt Cnoc na Gamhna
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 49.00
HER Number	MHG10398

Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279077
Northing	904023
Council	Highland
Condition:	Very degraded
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone footings of a long rectangular building under bracken, measures c20m by 5m over walls. Possible internal partitions but not readily visible due to vegetation. Walls stand 0.5m tall and spread up to 0.8m wide. Not depicted on historic mapping. See Asset 139 for HER description.

Asset/Event Number	139.2
Asset/Event Name	Building, Allt Cnoc na Gamhna
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 49.00
HER Number	MHG10398
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279059
Northing	904039
Council	Highland
Condition:	Very Degraded
Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone footings for a rectangular building under grass measuring 15m by 4.5m wide. Walls measure 0.6m wide and stand 0.3m tall. Entrances or partitions not discernible. Not depicted on historic mapping. See Asset 139 for HER description.

Asset/Event Number	139.3
Asset/Event Name	Dyke, Allt Cnoc na Gamhna
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 49.00
HER Number	MHG10398
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279047
Northing	904029
Council	Highland
Condition:	Degraded

Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A degraded stone and turf dyke under bracken, spread extends along to the S gable end of building 139-2. Possible forming a kale yard or similar, c20m by 6m. Stands 0.6m tall and spread up to 1.5m. Not depicted on historic mapping. See Asset 139 for HER description.

Asset/Event Number	139.4
Asset/Event Name	Lazy beds, Allt Cnoc na Gamhna
Type of Asset/Event	Field system
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 49.00
HER Number	MHG10398
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279059
Northing	904051
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of lazy bed cultivation recorded by the HER but barely discernible during the walkover survey. Likely extends into the surrounds to the E, S and W of the building remains but the areas was under tall bracken that screened visibility. Not depicted on historic mapping. See Asset 139 for HER description.

Asset/Event Number	147.1
Asset/Event Name	Corn Kiln, Innis Aonar
Type of Asset/Event	Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH79NW 38
HER Number	MHG19237
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272488
Northing	899065
Council	Highland
Condition:	Ruinous
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Rectangular roofless kiln under heather, measuring 11m by 5m, with walls to SE 0.6m tall and spread up to 0.7m wide and walls to N 1m tall. Possible flue to SE but internal collapse is obscuring the structure. Not depicted on historic mapping. See Asset 147 for HER description. OS. 1879. Sutherland, Sheet CIV, Survey date: 1873-74, Publication date: 1879.

Asset/Event Number	147.2
Asset/Event Name	Structure, Innis Aonar
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH79NW 38
HER Number	MHG19237
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272489
Northing	899091
Council	Highland
Condition:	Ruinous
Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Rectangular building, built into the side of dyke Asset 471 and partly under grass, measures 11m by 7m with 0.7m wall spread and 0.4m tall. Possibly a storage area or cart shed with wide open side entrance to the E. Not depicted on historic mapping.. See Asset 147 for HER description. OS. 1879. Sutherland, Sheet CIV, Survey date: 1873-74, Publication date: 1879.

Asset/Event Number	147.3
Asset/Event Name	Dyke, Innis Aonar
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH79NW 38
HER Number	MHG19237
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272541
Northing	899012
Council	Highland
Condition:	Very degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass, c0.4m tall and spread up to 1m wide, extends c190m to attach to the head dyke Asset 471. Not depicted on historic mapping.See Asset 147 for HER description. OS. 1879. Sutherland, Sheet CIV, Survey date: 1873-74, Publication date: 1879.

Asset/Event Number	147.4
Asset/Event Name	Pen, Innis Aonar
Type of Asset/Event	Pen
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH79NW 38

HER Number	MHG19237
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272486
Northing	898975
Council	Highland
Condition:	Very degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small section of degraded stone and turf dyke under heather and grass, constructed adjacent to existing dyke Asset 471 atop a small little hillock. Defined by very small bank and some bare stones, standing 0.3m tall and spread up to 1m wide, forming a small pen. Not depicted on the 1st edition OS map. See Asset 147 for HER description. OS. 1879. Sutherland, Sheet CIV, Survey date: 1873-74, Publication date: 1879.
Asset/Event Number	147.5
Asset/Event Name	Clearance cairn, Innis Aonar
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH79NW 38
HER Number	MHG19237
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272539
Northing	899031
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A spread of field clearance stones partially under grass, deposited on a SE facing slope. Measures c13m by 6m and stands 0.7m tall, situated within the improved ground area associated with farmstead, but tall bracken and grass limit visibility. Not depicted on the 1st edition OS map. See Asset 147 for HER description. OS. 1879. Sutherland, Sheet CIV, Survey date: 1873-74, Publication date: 1879.
Asset/Event Number	147.6
Asset/Event Name	Dyke, Innis Aonar
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH79NW 38
HER Number	MHG19237
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272573

Northing	899024
Council	Highland
Condition:	Very degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A length of possible stone and turf dyke, substantially robbed, under grass and bracken. All that remains are several visible boulders generally 1m long with a large protruding face of bedrock at the SE end 4m by 3m and standing 1m tall, along a length c25m long. Not depicted on the 1st edition OS map. See Asset 147 for HER description. OS. 1879. Sutherland, Sheet CIV, Survey date: 1873-74, Publication date: 1879.
Asset/Event Number	147.7
Asset/Event Name	Clearance cairn, Innis Aonar
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH79NW 38
HER Number	MHG19237
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272618
Northing	899075
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A spread of clearance material under grass, stands 0.8m tall and spread 5m by 3m. Not depicted on the 1st edition OS map. See Asset 147 for HER description. OS. 1879. Sutherland, Sheet CIV, Survey date: 1873-74, Publication date: 1879.
Asset/Event Number	147.8
Asset/Event Name	Dyke, Innis Aonar
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH79NW 38
HER Number	MHG19237
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272499
Northing	899115
Council	Highland
Condition:	Degraded
Alignment:	NE/SW

Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass, stands 0.6m tall and spread up to 1m. C55m long. Not depicted on the 1st edition OS map. See Asset 147 for HER description. OS. 1879. Sutherland, Sheet CIV, Survey date: 1873-74, Publication date: 1879.
Asset/Event Number	147.9
Asset/Event Name	Dyke, Innis Aonar
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH79NW 38
HER Number	MHG19237
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272647
Northing	899086
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A very degraded stone and turf dyke under grass along the S side of the stream, reduced to ground level in parts. The dyke stands to 0.4m tall and spread up to 2m wide. Not depicted on the 1st edition OS map. See Asset 147 for HER description. OS. 1879. Sutherland, Sheet CIV, Survey date: 1873-74, Publication date: 1879.
Asset/Event Number	147.9
Asset/Event Name	Dyke, Innis Aonar
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH79NW 38
HER Number	MHG19237
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272588
Northing	899141
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A very degraded stone and turf dyke under grass along the S side of the stream, reduced to ground level in parts. The dyke stands to 0.4m tall and spread up to 2m wide. Not depicted on the 1st edition OS map. See Asset 147 for HER description. OS. 1879. Sutherland, Sheet CIV, Survey date: 1873-74, Publication date: 1879.

Asset/Event Number	147.10
Asset/Event Name	Dyke, Innis Aonar
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH79NW 38
HER Number	MHG19237
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272665
Northing	899055
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A very degraded stone and turf dyke under grass along the S side of the stream, reduced to ground level in parts. This portion ends at the stream as depicted. C0.6m tall and spread up to 1m wide. Not depicted on the 1st edition OS map. See Asset 147 for HER description. OS. 1879. Sutherland, Sheet CIV, Survey date: 1873-74, Publication date: 1879.

Asset/Event Number	147.11
Asset/Event Name	Dyke, Innis Aonar
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH79NW 38
HER Number	MHG19237
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272658
Northing	899087
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A very degraded stone dyke under grass on the N side of the stream, possibly reworked from the adjacent dyke Asset 147.10. c10m long and 0.6m tall, spread up to 1.5m wide. Not depicted on the 1st edition OS map. See Asset 147 for HER description. OS. 1879. Sutherland, Sheet CIV, Survey date: 1873-74, Publication date: 1879.

Asset/Event Number	147.11
Asset/Event Name	Dyke, Innis Aonar
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH79NW 38

HER Number	MHG19237
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272620
Northing	899139
Council	Highland
Condition:	Very degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A c30m long portion of stone and turf dyke, part of the overall Asset 147.11 dyke that extends intermittently along the stream. Stands 0.5m tall and spread up to 1.5m wide. Not depicted on the 1st edition OS map. See Asset 147 for HER description. OS. 1879. Sutherland, Sheet CIV, Survey date: 1873-74, Publication date: 1879.
Asset/Event Number	147.12
Asset/Event Name	Dyke, Innis Aonar
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH79NW 38
HER Number	MHG19237
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272499
Northing	899125
Council	Highland
Condition:	Very degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass, stands 0.5m tall and spread 1m wide, forming a small pen c11m by 6m adjoined to the inside of head dyke Asset 471. Possibly part of this is depicted on the 1st edition OS map. See Asset 147 for HER description. OS. 1879. Sutherland, Sheet CIV, Survey date: 1873-74, Publication date: 1879.
Asset/Event Number	147.13
Asset/Event Name	Enclosure, Innis Aonar
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH79NW 38
HER Number	MHG19237
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272531
Northing	899101

Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. L-shaped enclosure under bracken, measuring 21m by 13m over dykes. Composed of degraded stone and turf dyke that primarily is now represented by boulders standing up to 0.7m tall and spread 1m wide. Possibly part of this is depicted on the 1st edition OS map. See Asset 147 for HER description. OS. 1879. Sutherland, Sheet CIV, Survey date: 1873-74, Publication date: 1879.
Asset/Event Number	147.14
Asset/Event Name	Building, Innis Aonar
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH79NW 38
HER Number	MHG19237
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272544
Northing	899101
Council	Highland
Condition:	Ruinous
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Rectangular building partially under heather, measures 11m by 5m. NW side is 0.5m tall and SE is up to 1m tall. 1m spread wall. See Asset 147 for HER description. Not depicted on the 1st edition OS map. See Asset 147 for HER description. OS. 1879. Sutherland, Sheet CIV, Survey date: 1873-74, Publication date: 1879.
Asset/Event Number	147.15
Asset/Event Name	Clearance cairn, Innis Aonar
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH79NW 38
HER Number	MHG19237
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272668
Northing	899066
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large spread of clearance over dyke Asset 147.10/471. Measures c40m long by c 8m wide and stands 1m tall. Comprises large boulders up to 1.2m long. Not depicted on the 1st edition OS map. See Asset 147 for HER description. OS. 1879. Sutherland, Sheet CIV, Survey date: 1873-74, Publication date: 1879.
Asset/Event Number	150.1
Asset/Event Name	Structure, Loch of Toftingall
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND15SE 16.00
HER Number	MHG18918
Status	Non-designated Heritage Asset
Section:	A1.1
Easting	319604
Northing	952237
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An abandoned farmstead is depicted on the 1st edition OS map as comprising three unroofed rectangular buildings or pens within and adjacent to an L-shaped enclosure in improved ground. By the time of 2nd edition OS map, the pens have disappeared but the L-shaped enclosure and circular sheep stell are depicted. The area has since been extensively planted with commercial forestry and a mature plantation stands across the locations. The assets were not identified during the walkover survey. OS. 1877. Caithness XXIII Surveyed: 1871, Published: 1877. OS. 1907. Caithness-shire XXIII. Surveyed: 1905, Published: 1907. See Asset 150 for HER description.
Asset/Event Number	150.2
Asset/Event Name	Structure, Loch of Toftingall
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND15SE 16.00
HER Number	MHG18918
Status	Non-designated Heritage Asset
Section:	A1.1
Easting	319605
Northing	952405
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An abandoned farmstead is depicted on the 1st edition OS map as comprising three unroofed rectangular buildings or pens within and adjacent to an L-shaped enclosure in improved ground. By the time of 2nd edition OS map, the pens have disappeared but the L-shaped enclosure and circular sheep

	stell are depicted. The area has since been extensively planted with commercial forestry and a mature plantation stands across the locations. The assets were not identified during the walkover survey. OS. 1877. Caithness XXIII Surveyed: 1871, Published: 1877. OS. 1907. Caithness-shire XXIII. Surveyed: 1905, Published: 1907. See Asset 150 for HER description.
Asset/Event Number	154.1
Asset/Event Name	Enclosure, Garabil
Type of Asset/Event	Enclosure
Date and/or Period	Unknown
Listing No./NRHE Number	NH56NE 26.00
HER Number	MHG14142
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256063
Northing	869026
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A turf and stone dyke under moss and grass, extending 130m long, standing 0.6m tall and spread up to 1m wide. Consistent with field boundary on the 1st edition OS map.

Asset/Event Number	154.2
Asset/Event Name	Structure, Garabil
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH56NE 26.00
HER Number	MHG14142; MHG19702
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256092
Northing	868992
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Drystone walled rectangular structure surviving to approx. 0.5m height. Not possible to survey in detail as largely overgrown with gorse, but appears to be 2-4m SW-NE and 1-2m SE-NW.

Asset/Event Number	154.3
Asset/Event Name	Clearance cairn, Garabil

Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH56NE 26.00
HER Number	MHG14142; MHG19702
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256103
Northing	869002
Council	Highland
Condition:	Degraded
Alignment:	Circular
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Roughly circular mound under grass, c1m in diameter and stands 0.25-5m tall.

Asset/Event Number	154.4
Asset/Event Name	Structure, Garabil
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH56NE 26.00
HER Number	MHG14142; MHG19702
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256143
Northing	869026
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular stone structure measuring 6m by 3m over walls, which stand 0.6m tall and spread 0.8m wide. A possible entrance sits in the SW elevation.. An unroofed structure or pen is depicted in the vicinity of this asset on the 1st edition OS map.

Asset/Event Number	155.1
Asset/Event Name	Building, Langergill
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND15SE 20.00
HER Number	MHG19047
Status	Non-designated Heritage Asset
Section:	A1.1

Easting	318820
Northing	954778
Council	Highland
Condition:	Ruinous
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular unroofed stone building measuring c11m by 5m over walls. Adjoins building Asset 155.2 to the NE, but these are not exactly contemporary as this asset is slightly recessed from the build level that 155.2 presents. Separated by a single partition into two compartments. Walls survive largely to 0.5-1m height, but in places fully reduced to ground level. Depicted on the 1st edition OS map as a single roofed building alongside 155.2. OS. 1877. Caithness XVIII Surveyed: 1871, Published: 1877. Description from the HER: Longhouse farm (ND 1882 5477), comprising;A: Longhouse. Dimensions: 23 x 6m. Tripartite rectangular structure with a fireplace in the ESE unit. Orientation ESE-WNW.B: Longhouse/ outhouse. Dimensions: 7 x 5m. Bipartite rectangular structure following the same line as A. Orientation ESE-WNW.C: Mill. Dimensions: 7 x 5m. Rectangular structure associated with mill machinery and a lade running N lying 24m N of A. Orientation N-S.D: Dam. Diameter: 18m. Circular grassy bank 1.5m high at the other end of the lade.R J Mercer, NMRS MS/828/19, 1995A farmstead comprising one roofed long building, one unroofed building and three enclosures is depicted on the 1st edition of the 6-inch map (Caithness 1877, sheet xviii). An unroofed building is shown on the current edition of the OS 1:10000 map (1976).Information from RCAHMS (SAH) 6 December 1995
Asset/Event Number	155.2
Asset/Event Name	Structure, Langergill
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND15SE 20.00
HER Number	MHG19047
Status	Non-designated Heritage Asset
Section:	A1.1
Easting	318832
Northing	954780
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A ruinous roofless rectangular stone building measuring c15m by 5m over walls which stand between 0.5-1m tall and 0.25m wide along the long elevations, and up to 2m tall at the E gable end which also contains a fireplace. The building adjoins building Asset 155.1 to the W but is slightly wider, with masonry of a slightly higher quality, and so not a continuous building. Depicted on the 1st edition OS map as a single roofed building alongside 155.1. See Asset 115.1 for HER description. OS. 1877. Caithness XVIII Surveyed: 1871, Published: 1877.
Asset/Event Number	155.3
Asset/Event Name	Building, Langergill
Type of Asset/Event	Mill

Date and/or Period	Post-medieval
Listing No./NRHE Number	ND15SE 20.00
HER Number	MHG19047
Status	Non-designated Heritage Asset
Section:	A1.1
Easting	318790
Northing	954792
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular unroofed watermill building measuring c7m by 5m with walls c0.6m wide, composed of randomly coursed sandstone slabs that stand to 0.7m tall. Upright flagstones set along the SE wall. An external wheel pit measuring c4m long and 1m wide and 1m deep under grass extends along the external side of the NE elevation, and the metal drive shaft is still in situ. A lade system is evident on the 1st edition OS map but this does not depict the mill building itself (but it is depicted on the 2nd edition OS map), and the lades appear silted up and under grass today. See Asset 115.1 for HER description. OS. 1877. Caithness XVIII Surveyed: 1871, Published: 1877. OS. 1907. Caithness-shire XVIII. Surveyed: 1905, Published: 1907.
Asset/Event Number	155.4
Asset/Event Name	Structure, Langergill
Type of Asset/Event	Other
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND15SE 20.00
HER Number	MHG19047
Status	Non-designated Heritage Asset
Section:	A1.1
Easting	318831
Northing	954767
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Concrete and stone block associated with the nearby buildings Assets 155.1 and 155.2, measuring c1m by 0.8m, drainage protrusion or similar embedded. See Asset 115.1 for HER description.
Asset/Event Number	155.5
Asset/Event Name	Structure, Langergill
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND15SE 20.00
HER Number	MHG19047

Status	Non-designated Heritage Asset
Section:	N/A
Easting	318844
Northing	954782
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A square-shaped stone-built structure under tall vegetation, measuring 5m by 4m over walls, which are reduced to ground level and measure 0.25m wide. A possible pen or small structure. Does not appear to be depicted on either the 1st or 2nd edition OS maps. See Asset 115.1 for HER description. S

Asset/Event Number	155.6
Asset/Event Name	Enclosure, Langergill
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND15SE 20.00
HER Number	MHG19047
Status	Non-designated Heritage Asset
Section:	A1.1
Easting	318826
Northing	954768
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Turf and stone dyke under dense vegetation, forming a three-sided enclosure or possible kale yard measuring c4m by 3m over dykes. One upright flagstone against northern wall on inside. Appears to comprise the N end of an enclosure depicted on the 1st edition OS map. OS. 1877. Caithness XVIII Surveyed: 1871, Published: 1877. See Asset 115.1 for HER description.

Asset/Event Number	155.7
Asset/Event Name	Hollow, Langergill
Type of Asset/Event	Other
Date and/or Period	Post-medieval
Listing No./NRHE Number	ND15SE 20.00
HER Number	MHG19047
Status	Non-designated Heritage Asset
Section:	A1.1
Easting	318816
Northing	954773
Council	Highland

Condition:	Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small SW to NE oriented (1mx0.25m) hollow with a few slabs defining the NW side, and an upright Caithness flag embedded in the ground at the NW end, which has a hole seemingly drilled into the face. Possibly a storage pit or feed pit. See Asset 115.1 for HER description.
Asset/Event Number	167.1
Asset/Event Name	Building, Glack
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH57SE 27
HER Number	MHG20472
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256382
Northing	873797
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A long linear stone building measuring 25m by 5.5m over walls, with at least two internal walls forming three rooms measuring internally 7m by 4m (S) 9m by 4m (central) and 3m by 3m (N). The N extent has been truncated by the adjacent track. Entrances and/or windows in E elevation only; N room the entrance is central, S room appears to have two at either end of the elevation. Walls are 0.6m wide and stand between 0.2-1m tall. It is depicted as a roofed building on the 1st edition OS map as part of the township of Glack.
Asset/Event Number	167.2
Asset/Event Name	Enclosure, Glack
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH57SE 27
HER Number	MHG20472
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256397
Northing	873807
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small drystone enclosure measuring c15m by 15m, with walls standing up to 1.2 m tall and 1m wide. Pen 167.3 built onto the SE external corner. It is depicted on the 1st edition OS map as part of the township of Glack.
Asset/Event Number	167.3
Asset/Event Name	Pen, Glack
Type of Asset/Event	Pen
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH57SE 27
HER Number	MHG20472
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256404
Northing	873801
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small stone- built pen abutting enclosure Asset 167.2. Measuring's 5m by 2.5m wide over walls that stand 0.7m tall and are 0.6m wide. A single partition evident. Possibly used as twinning pens. It is depicted on the 1st edition OS map as part of the township of Glack.
Asset/Event Number	167.4
Asset/Event Name	Kiln barn, Glack
Type of Asset/Event	Kiln barn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH57SE 27
HER Number	MHG20472
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256416
Northing	873807
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone building with a large kiln under grass erected in the SW end, measures 11m by 5m over walls which stand up to 1.2m tall and 0.6m wide, with the kiln standing to a height of 1.5m tall. The entrance to the building lies in the SW elevation towards the NE end of the building. The kiln box is still visible within the building but the bowl itself has infilled. It is depicted as a roofed building on the 1st edition OS map as part of the township of Glack.
Asset/Event Number	167.5

Asset/Event Name	Building, Glack
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH57SE 27
HER Number	MHG20472
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256417
Northing	873757
Council	Highland
Condition:	Ruinous
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular building measuring c12m by 5m over walls, with a single partition wall delineating a SW room 3m by 3m internally and a NE room 6m by 3m internally; the latter room is much more poorly preserved with walls obscured by grass. The SW room walls measure 1.5m tall and 0.7m wide. Entrances not discernible. It is depicted as a roofed building on the 1st edition OS map as part of the township of Glack.

Asset/Event Number	167.6
Asset/Event Name	Building, Glack
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH57SE 27
HER Number	MHG20472
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256389
Northing	873773
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Remnants of a terrace of stone buildings and further buildings or ancillary /pens extending from it. Broadly T-shaped arrangement with the principle NW/SE terraced buildings (possibly three, constructed end to end) measuring c30m by 5m over walls which stand to 1.2m tall and 0.5m wide in parts, but reduced to ground level in areas. The ancillary pens and structures to the NW measure 11m by 9m and are similar in form. Entrances not discernible. A roofed complex of this form is depicted on the 1st edition OS map as part of the township of Glack.

Asset/Event Number	167.7
Asset/Event Name	Enclosure, Glack
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval

Listing No./NRHE Number	NH57SE 27.00
HER Number	MHG20472
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256353
Northing	873794
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An enclosure c60m by 40m, comprising a drystone dyke which stand to c0.8m tall and are 0.5-0.7m wide.

Asset/Event Number	167.8
Asset/Event Name	Enclosure, Glack
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH57SE 27.00
HER Number	MHG20472
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256469
Northing	873757
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An enclosure c110m by 65m composed of a drystone dyke that stands up to 0.5m tall and 0.5m wide, spread up to 1.2m wide.

Asset/Event Number	167.9
Asset/Event Name	Enclosure, Glack
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH57SE 27.00
HER Number	MHG20472
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256390
Northing	873707

Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small enclosure c15m by 10m constructed along the drystone dyke Asset 360, and also composed of a drystone dyke that stands up to 0.7m tall and 0.6m wide.

Asset/Event Number	170.1
Asset/Event Name	Dyke, Fairburn
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45SE 9.00
HER Number	MHG24740
Status	Non-designated Heritage Asset
Section:	E1.1, E1.2
Easting	247602
Northing	850664
Council	Highland
Condition:	Very degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under dense bracken, stands c0.5m tall and spread up to 1m wide.

Asset/Event Number	170.2
Asset/Event Name	Enclosure, Aultgowrie Bridge
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45SE 9.00
HER Number	MHG24740
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	247633
Northing	850753
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A square-shaped enclosure measuring 10m by 10m and defined by a stone and turf dyke under dense bracken and moss. Dyke stands 0.2-0.4m tall and spread up to 2m wide.

Asset/Event Number	170.3
Asset/Event Name	Structure, Aultgowrie Bridge
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45SE 9.00
HER Number	MHG24740
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	247616
Northing	850756
Council	Highland
Condition:	Ruinous
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A structure measuring c3m by 3m under dense bracken and moss, constructed from rubble drystone standing 0.5m tall and spread 1.2m wide. Possible pen or structure.

Asset/Event Number	170.4
Asset/Event Name	Farmstead, Aultgowrie Bridge
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45SE 9.00
HER Number	MHG24740
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	247573
Northing	850777
Council	Highland
Condition:	Unknown
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An unroofed farmstead or pens are depicted on the 1st edition os map. This areas was under dense bracken at the time of survey, no structural remains were observed.

Asset/Event Number	177.1
Asset/Event Name	Building, Ardochy

Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH44SE 41.00
HER Number	MHG23314
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	246093
Northing	843338
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Grass covered footings for a rectangular building measuring 16.5m by 5m over walls with a single internal partition. The NE partition forms the smaller of the two, measuring 4m by 4m internally, while the SW measures 15m by 4m internally. Walls spread up to 1m wide and stand up to 0.8m tall. A spread of field clearance (Asset 305) overlies the SW end and obscures the remains. Building is consistent with an unroofed structure depicted on the 1st edition OS map.

Asset/Event Number	177.2
Asset/Event Name	Enclosure, Ardochy
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH44SE 41.00
HER Number	MHG23314
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	246107
Northing	843331
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A turf and stone dyke extending to SE of building Asset 177.1, with the dyke under grass and standing to a height of 0.8m tall and spread up to 1.4m wide. Forms a small enclosure c15m by 13m to the SE side of the building, and is open to the SW end. Not depicted on the 1st edition OS map.

Asset/Event Number	179.1
Asset/Event Name	Hut circle, Cnoc a' Leacachan
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH57SE 34.00
HER Number	MHG28205
Status	Non-designated Heritage Asset

Section:	D1.2
Easting	257565
Northing	872571
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A probable hut circle under heather, measures c. 10m in diameter over banks, which stand to a height of 0.7m and are spread up to 1.5-2m wide.

Asset/Event Number	179.2
Asset/Event Name	Prehistoric clearance cairn, Cnoc a' Leacachan
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH57SE 34.00
HER Number	MHG28205
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	257578
Northing	872620
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather measuring c6m by 4m and standing to a height of 0.6m.

Asset/Event Number	179.3
Asset/Event Name	Hut circle, Cnoc a' Leacachan
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH57SE 34.00
HER Number	MHG28205
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	257565
Northing	872607
Council	Highland
Condition:	Degraded
Alignment:	Curving

Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under tall heather, somewhat difficult to discern dimensions as a result. Appears to measure c. 12m in diameter over banks, which stand to a height of 0.8m and are spread up to 2m wide.

Asset/Event Number	179.4
Asset/Event Name	Prehistoric clearance cairn, Cnoc a' Leacachan
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH57SE 34.00
HER Number	MHG56490
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	257411
Northing	872634
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather measuring c7m by 4m and standing to a height of 0.7m.

Asset/Event Number	183.1
Asset/Event Name	Enclosure, Allt Bad a' Chrasgaidh
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 55.00
HER Number	MHG28537
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	274991
Northing	901974
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A diamond-shaped enclosure measuring 35m by 25m and composed of a drystone wall standing 0.7m tall and 0.7m wide. Not depicted on the 1st edition OS map.

Asset/Event Number	211.1

Asset/Event Name	Farmstead, Uaigh Bheag
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 50.00
HER Number	MHG54757
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293603
Northing	913851
Council	Highland
Condition:	Fair
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An unroofed single-storey stone cottage, measuring 13m by 8 over walls which stand to full height and relatively well-preserved, composed of mortared square-snecked rubble. The long elevations stand 2.5m tall and 0.7m wide, and the gable ends stand 4m tall and 0.75m wide. The S elevation contains a centrally situated entrance with flanking windows either side, and the N elevation contains a central entrance but no windows. Chimneys and associated fireplaces are present in ach gable. The wooden roof rafters have collapsed into the building interior, prohibiting access. Some stone slates still visible along the gable end. Forms the main farmstead building for the complex. Depicted on the 1st and 2nd edition OS maps as roofed, although it appears as an L-shaped building with an extension to the SW at the SE corner. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.

Asset/Event Number	211.2
Asset/Event Name	Enclosure, Uaigh Bheag
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 50.00
HER Number	MHG54757
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293621
Northing	913839
Council	Highland
Condition:	Fair
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Square drystone enclosure measuring 16m 16m, with the drystone wall standing 0.8m tall and 0.6m wide. Depicted on the 1st and 2nd edition OS maps, but appears more rounded in these. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.

Asset/Event Number	211.3

Asset/Event Name	Building, Uaigh Bheag
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 50.00
HER Number	MHG54757
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293618
Northing	913865
Council	Highland
Condition:	Ruinous
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An unroofed stone storage building, forming part of the outbuildings associated with the main farmstead building Asset 211.1. Measures c9m long by 5m wide over walls, attached to building Asset 211.4. Contains exterior small rectangular storage building, and an internal L shaped corridor. Walls stand c1.3m tall and measurs 0.5m wide, access gained from the S elevation. Depicted on the 1st and 2nd edition OS maps. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.

Asset/Event Number	211.4
Asset/Event Name	Building, Uaigh Bheag
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 50.00
HER Number	MHG54757
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293607
Northing	913871
Council	Highland
Condition:	Fair
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Outbuildings located to the rear (N) of the main farmstead building (Asset 211.1), comprising a somewhat sprawling range with four partitions delinieating five rooms, access to which is gained from the S elevation. Walls survive best at the E, W and N sides, up to 2m in height and measuring 0.6m wide, with the S elevation partially robbed and reduced to a low level. Building Asset 211.3 stands to the immediate E of these. Depicted on the 1st and 2nd edition OS maps. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.

Asset/Event Number	211.5
Asset/Event Name	Corn drying kiln, Uaigh Bheag

Type of Asset/Event	Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 50.00
HER Number	MHG54757
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293592
Northing	913859
Council	Highland
Condition:	Very Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Within the SW end of a length of drystone wall (Asset 211.6) is an odd portion of drystone wall with a square shaped opening overlain by long flat lintels on either side, continuing through the wall. The opening is 0.5m tall and 0.4m wide, with the SE side flush with the wall face but the NW side bulging out from the wall to 1.4m wide (wall is 0.6m wide) and 2.5m long until it narrows to the wall width as it continues to the NE. The opening continues through the entirety of the block of wall, and is reminiscent of the flue/heat box of a corn-drying kiln. Although no stone is obvious beyond it, there is a prominent mound dipping away to the NW. It is possible that this represents the remnants of an old kiln, mostly robbed away, with only a small portion retained where it could be incorporated into the drystone wall. Not depicted on the 1st and 2nd edition OS maps. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.
Asset/Event Number	211.6
Asset/Event Name	Dyke, Uaigh Bheag
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 50.00
HER Number	MHG54757
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293591
Northing	913866
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke, breached in places, adjoining the buildings Asset 211.1 and 211.4, and incorporating possible kiln remnants Asset 211.5. Dyke is c16m long and 0.6m wide and stands to c0.7m tall at tallest point. Not depicted on the 1st and 2nd edition OS maps. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.
Asset/Event Number	211.7

Asset/Event Name	Dyke, Uaigh Bheag
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 50.00
HER Number	MHG54757
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293635
Northing	913861
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Turf and stone dyke under grass and bracken, measuring c290m long and stands 0.5m tall and spread up to 1.5m wide. Continues to the SW as Asset 425. Depicted on the 1st and 2nd edition OS maps, but there is an extension (c55m long) to the SE that then turns S that although extant is not present on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.
Asset/Event Number	211.8
Asset/Event Name	Dyke, Uaigh Bheag
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 50.00
HER Number	MHG54757
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293684
Northing	913909
Council	Highland
Condition:	Very degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Possible length of very degraded dyke under bracken. Stone visible and spread up to 4m wide but no real height to the feature. Runs along N side of Glen Loth burn so possibly just a rough shoring/stream augmentation, but does appear to joining to the more defined dyke 211.7 that continues around to the SW. Not depicted on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.
Asset/Event Number	211.9
Asset/Event Name	Clearance cairn, Uaigh Bheag
Type of Asset/Event	Clearance cairn

Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 50.00
HER Number	MHG54757
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293608
Northing	913860
Council	Highland
Condition:	Very Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn under moss and grass, measuring 11m by 5m and standing 1m tall. May conceal structural remains below.

Asset/Event Number	211.10
Asset/Event Name	Structure, Uaigh Bheag
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 50.00
HER Number	MHG54757
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293615
Northing	913816
Council	Highland
Condition:	Very Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible structure under dense, tall bracken, very difficult to determine the nature of it due to the vegetation. Appears as a mound c13m by 5m, potentially rectangular, some 0.6m tall. Extent broadly estimated from walking over it. Potentially a very degraded long house/similar. Not depicted on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.

Asset/Event Number	214.1
Asset/Event Name	Building, Uaigh Bheag
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 54.00
HER Number	MHG13174
Status	Non-designated Heritage Asset

Section:	A1.5
Easting	293986
Northing	914210
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone footings for a rectangular building under bracken and grass, 20m by 5m over walls with one internal partition. Both compartments measures 9m by 3m internally. Entrances to both possibly in the NW elevation but walls degraded to ground level in parts and difficult to tell. Walls stand 1m tall at tallest point and spread up to 1.2m wide. Not depicted on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.
Asset/Event Number	214.2
Asset/Event Name	Dyke, Uaigh Bheag
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 54.00
HER Number	MHG13174
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293991
Northing	914204
Council	Highland
Condition:	Very degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible stone and turf dyke under bracken, very degraded and stands to 0.3m tall and spread up to 1.5m wide, measuring c12m by 5m. Possibly a kale yard/garden for the adjacent building Asset 214.1 to N. Not depicted on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.
Asset/Event Number	238.1
Asset/Event Name	An Dun fort, Cornhill Wood
Type of Asset/Event	Fort
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH45SE 57.00
HER Number	MHG60939
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245841
Northing	851962

Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Medium
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Inner wall of promontory fort Asset 238. The wall core can no longer be seen, and w consists of a wide spread of stones (c4m wide and 1.5m tall) aligned roughly N/S. The continuation of the inner wall face beyond the extent surveyed could not be identified.

Asset/Event Number	238.2
Asset/Event Name	An Dun fort, Cornhill Wood
Type of Asset/Event	Fort
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH45SE 57.00
HER Number	MHG60939
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245839
Northing	851955
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Medium
Description	*Recorded by AOC Archaeology during 2024 walkover survey. First line of outer defences of fort Asset 238/MHG60939, a defensive bank under dense bracken and trees.

Asset/Event Number	238.3
Asset/Event Name	An Dun fort, Cornhill Wood
Type of Asset/Event	Fort
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH45SE 57.00
HER Number	MHG60939
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245824
Northing	851956
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Medium

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Outer (third) wall of fort Asset 238/MHG60939, a defensive bank/wall under dense bracken and trees.

Asset/Event Number	242
Asset/Event Name	Clearance cairn, Breakachy
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	245682
Northing	844276
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn under moss, measuring 4m by 3m and standing 0.8m tall. Comprises large angular stones. Not depicted on the 1st or 2nd edition OS maps.

Asset/Event Number	243.1
Asset/Event Name	Dyke, Breakachy
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH44SE 37
HER Number	MHG23310
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245613
Northing	844217
Council	Highland
Condition:	Very degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Lengths of stone and turf dyke under heather and grass, stands up to 0.3m tall and spread up to 3m wide, some stone visible in places. Associated with the Break achy farmstead MHG23310. Not depicted on either the 1st or 2nd edition OS maps.

Asset/Event Number	243.2
Asset/Event Name	Building, Breakachy

Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH44SE 37
HER Number	MHG23310
Status	Non-designated Heritage Asset
Section:	
Easting	245566
Northing	844215
Council	Highland
Condition:	Very Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Ruinous remains of a rectangular building under bracken, partially revetted into the NE-facing slope. Measures 17m by 4.5m over 0.8m wide walls that stand up to 1.2m tall at SW end and 0.4m tall at NE end. Has a central partition but poorly defined due to vegetation. Possible entrances uncertain. Consistent with a roofless building depicted on the 1st edition OS map. OS. 1876. Inverness-shire (Mainland) X, Surveyed: 1872, Published: 1876

Asset/Event Number	243.4
Asset/Event Name	Clearance cairn, Breakachy
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH44SE 37
HER Number	MHG23310
Status	Non-designated Heritage Asset
Section:	
Easting	245575
Northing	844227
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn of large boulders under bracken. Measures by 13m by 8m and stands 0.8m tall. May conceal structural remains though none specifically depicted on the 1st or 2nd edition OS map in the vicinity.

Asset/Event Number	243.5
Asset/Event Name	Corn drying kiln, Breakachy
Type of Asset/Event	Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH44SE 37
HER Number	MHG23310
Status	Non-designated Heritage Asset

Section:	N/A
Easting	245584
Northing	844190
Council	Highland
Condition:	Ruinous
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large spread of field clearance c8m in diameter and standing 0.7m tall situate don the NE-facing slope. Likely obscures a corn-drying kiln considering the density of stone and slope location, but no internal features such as the bowl or flue could be discerned. No structures depicted in this locale on the 1st or 2nd edition OS maps.
Asset/Event Number	244
Asset/Event Name	Enclosure, Breakachy
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	245519
Northing	844399
Council	Highland
Condition:	Very degraded
Alignment:	Circular
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A sub-circular enclosure under tall heather, constructed from a turf and stone dyke standing to 1.2m tall and spread up to 2m, irregularly-shaped in plan and measuring c50m by 40m over banks. Interior is obscured by heather and grass and no clear entrances discernible. Not depicted on historic maps.
Asset/Event Number	245
Asset/Event Name	Clearance cairn, Breakachy
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	245594
Northing	844465
Council	Highland
Condition:	Degraded

Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn under moss, measuring 8m by 3m and standing 0.6m tall. Comprises large angular stones.

Asset/Event Number	246
Asset/Event Name	Track, Breakachy
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	245211
Northing	844962
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A relict track under heather and grass, measures 2m wide and extends NW/SE across the survey corridor. The track is still in use. Depicted as a track on the 1st edition OS map. OS. 1876. Inverness-shire (Mainland) X, Surveyed: 1872, Published: 1876

Asset/Event Number	247
Asset/Event Name	
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	
Northing	
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	VOID - Number not assigned

Asset/Event Number	248.1
Asset/Event Name	Dun, Auchmore Wood
Type of Asset/Event	Dun
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247852
Northing	850577
Council	Highland
Condition:	Degraded
Alignment:	Circular
Importance:	Medium
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Remains of a probable dun under dense bracken, moss and mature coniferous trees, somewhat disturbed by commercial forestry operations which have impacted the SW half of the structure. The structure appears oval-shaped in plan, c18m by 10m over walls, but it is difficult to discern its form given the overlying forestry and disturbance. It is best preserved along the NW side where the wall stands to an internal height of c1.4m, and as much as 2m tall externally and up to 2m wide, with rubble/wall core also visible spilling over the edge of the ravine downhill. Within the interior was recorded spreads of stone which may be internal features or material redeposited related to the forestry operations. Not depicted on any historic mapping, but the area is shown under dense woodland (Auchmore Wood) on the 1st edition OS map, and thus likely why the asset was not recorded previously. OS. Inverness-shire (Mainland) II, Surveyed: 1872, Published: 1875

Asset/Event Number	248.2
Asset/Event Name	Dun, Auchmore Wood
Type of Asset/Event	Structure
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247853
Northing	850574
Council	Highland
Condition:	Degraded
Alignment:	Circular
Importance:	Medium
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Mounded piles of angular stone within the interior of the probable dun, the extent and dimensions difficult to determine due to the bracken and trees. Possibly internal features related to the dun, or redeposited material from forestry operations. See 248.1 for full description.

Asset/Event Number	249

Asset/Event Name	
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	
Northing	
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	VOID - Number not assigned

Asset/Event Number	250
Asset/Event Name	
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	
Northing	
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	VOID - Number not assigned

Asset/Event Number	251
Asset/Event Name	Dyke, Strath Sgitheach
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	N/A
Easting	252214
Northing	862809
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke under moss, measures 0.5m tall and spread 1m wide, extends c520m. This is shown on the 1st edition OS map as a parish boundary between Dingwall parish to the E and Fodderty parish to the W. OS. 1880. Ross-shire & Cromartyshire (Mainland) LXXVI, Survyed: 1875-6, Published: 1880

Asset/Event Number	252
Asset/Event Name	Ditch, Strath Sgitheach
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252326
Northing	862676
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drainage ditch under grass 0.5m wide and 0.5-0.8m deep, extends down the strath c210m. Runs parallel with the degraded dyke Asset 251 which likely was sourced from this. Not depicted on historic mapping.

Asset/Event Number	253
Asset/Event Name	Shieling, Strath Sgitheach
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH56SW 31
HER Number	MHG62708
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252344
Northing	863140
Council	Highland
Condition:	Degraded

Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A probable shieling measuring c5m by 5m under grass with poorly defined banks spread c1m wide and 0.3m tall. Situated on a small knoll overlooking Strath Sgitheach. Not depicted on historic mapping.

Asset/Event Number	254
Asset/Event Name	Borrow pit, Strath Sgitheach
Type of Asset/Event	Quarry
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252519
Northing	863208
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An open, kidney shaped borrow pit under grass, measures 12m long by 7m wide and 1.5m deep. Not depicted on historic mapping.

Asset/Event Number	255
Asset/Event Name	Bridge, Strath Sgitheach
Type of Asset/Event	Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252600
Northing	863300
Council	Highland
Condition:	Good
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small stone-built culvert/bridge formed by a rubble spread 3m by 2m wide, constructed over a small un-named watercourse, along the Strath Sgitheach access track. Not depicted on historic mapping.

Asset/Event Number	256
Asset/Event Name	Hut circle, Strath Sgitheach
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH56SW 91.00
HER Number	MHG8925; MHG62693
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252544
Northing	863276
Council	Highland
Condition:	Very Degraded
Alignment:	Circular
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A degraded hut circle under grass and heather, measures c13m in diameter over walls. Two large stones on SE side may represent the remains of a porch. Walls spread up to 2m wide and stand to 0.3m tall.

Asset/Event Number	257
Asset/Event Name	Culvert, Strath Sgitheach
Type of Asset/Event	Other
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252599
Northing	863346
Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rubble culvert extending below the track, c3m, with an augmented stream course either side, and a plastic pipe. Not depicted on historic mapping.

Asset/Event Number	258
Asset/Event Name	Dyke, Strath Sgitheach
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	N/A
Easting	252712
Northing	863367
Council	Highland
Condition:	Very degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone boundary dyke standing 0.6m tall and spread 0.6m wide, extends across the survey corridor from sheep fold Asset 207 and outwith the corridor to the SE. Depicted on the 1st edition OS map. OS. 1880. Ross-shire & Cromartyshire (Mainland) LXXVI, Survyed: 1875-6, Published: 1880

Asset/Event Number	259
Asset/Event Name	Culvert, Strath Sgitheach
Type of Asset/Event	Other
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	252608
Northing	863389
Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rubble culvert extending below the track with an augmented stream course either side, and a plastic pipe.

Asset/Event Number	260.1
Asset/Event Name	Farmstead, Strath Sgitheach
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	253105
Northing	863778
Council	Highland

Condition:	Ruinous
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A ruinous rectangular farmstead with an ancillary building or pen extending from the NW end. The main building is constructed from roughly dressed stone and natural boulders and measures 20m by 5m over walls, which stand 1.8m tall and measure 0.8m wide, and contains a central partition delineating two rooms (S: 7m by 4m, N: 12m by 4m) with entrances to each in the SW elevation. The ancillary structure in the NW appears later in date, constructed of mortared red brick and measuring c3m by 4m. The building is depicted as one of two roofed buildings on the 1st edition OS map, and by the time of the 2nd edition only a single roofed building (this asset) is depicted. OS. 1880. Ross-shire & Cromartyshire (Mainland) LXXVI, Survyed: 1875-6, Published: 1880 OS. 1907. Ross and Cromarty LXXVI, Survyed: 1904, Published: 1880
Asset/Event Number	260.2
Asset/Event Name	Enclosure, Strath Sgitheach
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	253206
Northing	863735
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A trapezoidal shaped enclosure measuring c150m by 120m, formed by a drystone dyke under moss and grass that stands 0.6m tall in some places, though reduced to ground level in others and spread up to 2m wide. Entrance in the SW corner. The enclosure forms part of the farmstead remains associated with the building it encloses (Asset 260.1), and is depicted on the 1st edition OS map. OS. 1880. Ross-shire & Cromartyshire (Mainland) LXXVI, Survyed: 1875-6, Published: 1880
Asset/Event Number	260.3
Asset/Event Name	Clearance cairn, Sgitheach
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	253203
Northing	863804
Council	Highland

Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A spread of field clearance c6m in diameter, deposited atop a small natural knoll containing the cup-marked stone Asset 135, and within enclosure Asset 260.2.

Asset/Event Number	261
Asset/Event Name	Dyke, Strath Sgitheach
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	253578
Northing	864585
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A degraded drystone dyke measuring c100m long and 0.8m tall and 0.6m wide composed of a double-skin of roughly dressed stone with smaller hearting material between. Extends along the edge of a commercial forestry plantation and beyond the survey corridor to the NW and SE. This is shown on the 1st edition OS map as a parish boundary between Dingwall parish to the W and Kiltearn parish to the E. OS. 1880. Ross-shire & Cromartyshire (Mainland) LXXVI, Survyed: 1875-6, Published: 1880

Asset/Event Number	262
Asset/Event Name	Building, Sgitheach
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251947
Northing	862895
Council	Highland
Condition:	Very Degraded
Alignment:	NW/SE
Importance:	Low

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Poorly defined turf and stone footings for a rectangular structure under moss and grass measuring c6.5m by 4m over walls, which are spread up to 1m wide and stand to a height of 0.3m, with no easily discernible entrance. It has been constructed against the NE face of dyke Asset 263. No structures are depicted on the 1st edition OS map and the complex therefore predates the late 19th century. OS. 1880. Ross-shire & Cromartyshire (Mainland) LXXVI, Survyed: 1875-6, Published: 1880
Asset/Event Number	263
Asset/Event Name	Dyke, Strath Sgitheach
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	NA
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251932
Northing	862832
Council	Highland
Condition:	Very degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass barely visible as very-poorly preserved bank spread up to 1m wide and standing 0.2m tall, extending c160m, and sometimes represented only by very intermittent boulders, suggesting a possible turf component that has substantially degraded away. A structure (Asset 262) has been constructed against the NW elevation, with a another probable building (Asset 264) lying slightly further SE. No structures depicted here on the 1st edition OS map and so it predates the late 19th century. OS. 1880. Ross-shire & Cromartyshire (Mainland) LXXVI, Survyed: 1875-6, Published: 1880
Asset/Event Number	264
Asset/Event Name	Building, Strath Sgitheach
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	251940
Northing	862834
Council	Highland
Condition:	Very Degraded
Alignment:	NE/SW
Importance:	Low

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Poorly defined stone and turf footings for a rectangular building measuring 8m by 4m over wall spread. The walls survive as low banks spread 1.5m wide and standing 0.2m tall. No discernible entrances. It lies just to the SE of a similarly degraded dyke (Asset 263) and S of another poorly preserved building (Asset 262). No structures are depicted on the 1st edition OS map and the complex therefore predates the late 19th century. OS. 1880. Ross-shire & Cromartyshire (Mainland) LXXVI, Survyed: 1875-6, Published: 1880
Asset/Event Number	265
Asset/Event Name	Gravel bund, Muir of Fairburn
Type of Asset/Event	Other
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247918
Northing	852023
Council	Highland
Condition:	Good
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A modern gravel bund c2m tall and extending c12m, situated to the north of the existing access track.

Asset/Event Number	267
Asset/Event Name	Dyke, Fairburn
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247489
Northing	851927
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke measuring c250m long, and standing 1m wide at base and tapering to 0.7m, does not survive to full height. Double-skinned with roughly dressed rubble and a core of smaller hearting stones. Depicted on the 1st edition OS map. OS. 1875. Inverness-shire (Mainland) II, Surveyed: 1872, Published: 1875

Asset/Event Number	268
Asset/Event Name	Dyke, Fairburn
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247589
Northing	852492
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke field boundary extending c115m around field, well-preserved along the N side but very degraded along the W and S sides, breached by gate in the SE corner. Where degraded the spread is up to 3m wide under grass, standing c0.5m tall. In well preserved section it stands 1-1.3m tall with a splayed rubble profile with a rough coping of edge-set roughly shaped stones. Depicted on the 1st edition OS map. OS. 1875. Inverness-shire (Mainland) II, Surveyed: 1872, Published: 1875

Asset/Event Number	269
Asset/Event Name	Clearance cairn, Fairburn
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247465
Northing	852357
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Spread of post-medieval field clearance partially under grass at edge of agricultural field, stands 0.2-0.6m tall and composed of large boulders and smaller stones.

Asset/Event Number	270
Asset/Event Name	Bank, Muir of Fairburn
Type of Asset/Event	Bank
Date and/or Period	Post-medieval

Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247614
Northing	852868
Council	Highland
Condition:	Fair
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Linear stone and turf bank under moss running along edge of field, 300m long and 4m wide with 1.5m wide drainage ditch running along W side. Depicted on the 1st edition OS map. OS. 1875. Inverness-shire (Mainland) II, Surveyed: 1872, Published: 1875

Asset/Event Number	271
Asset/Event Name	Dyke, East Mains of Fairburn
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247643
Northing	853038
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A pair of drystone dykes flanking the road at East Mains of Fairburn. The dykes are partially revetted into the earth on the S sides, with the N of the pair situated at a lower elevation to the S. Both measure c0.4-0.6m tall and c1m wide, tapering to 0.3-4m wide at the top, with dressed boulders as coping stones. The N dyke has a hedge planted over the top of it. Both dykes are edged by mature deciduous trees. The dykes are depicted as field boundaries on both the 1st and 2nd edition OS maps, but only the 1st edition map shows some trees. OS. 1881. Ross-shire & Cromarty shire (Mainland XCVIII), Surveyed: 1876, Published: 1881. OS. 1907. Ross & Cromarty XCVIII, Surveyed: 1876, Published: 1881.

Asset/Event Number	273
Asset/Event Name	Dyke, Fairburn
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset

Section:	N/A
Easting	247427
Northing	853176
Council	Highland
Condition:	Fair
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke extending through fields, constructed from roughly dressed stone. Measures 0.8m wide at base and tapers to 0.3m at top, standing c1-1.3m tall. C210m long. Depicted on the 1st and 2nd edition OS maps. OS. 1881. Ross-shire & Cromarty shire (Mainland XCVIII), Surveyed: 1876, Published: 1881. OS. 1907. Ross & Cromarty XCVIII, Surveyed: 1876, Published: 1881.
Asset/Event Number	274
Asset/Event Name	Dyke, Fairburn
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247245
Northing	853703
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Remnants of a drystone dyke enclosing a field, breached in several areas and reduced to ground height. Generally of rubble construction, stands between 0.4-0.8m tall and spread up to 1.5m wide and extended outwith the survey corridor to the E and W. Some rubble coping in parts. Depicted on the 1st and 2nd edition OS maps. OS. 1881. Ross-shire & Cromarty shire (Mainland XCVIII), Surveyed: 1876, Published: 1881. OS. 1907. Ross & Cromarty XCVIII, Surveyed: 1876, Published: 1881.
Asset/Event Number	275
Asset/Event Name	Dyke, Wester Balloch
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247551
Northing	853800

Council	Highland
Condition:	Degraded
Alignment:	WNW/ESE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Pair of drystone dykes extending along the road edge on the approach to Marybank, measuring c1m tall and 0.5m wide. Mature deciduous trees planted alongside these. Consistent with field boundaries depicted on the 1st and 2nd edition OS maps, but trees are shown only on the 1st edition OS map. OS. 1881. Ross-shire & Cromarty shire (Mainland XCVIII), Surveyed: 1876, Published: 1881. OS. 1907. Ross & Cromarty XCVIII, Surveyed: 1876, Published: 1881.
Asset/Event Number	276
Asset/Event Name	Clearance cairn, Aultgowrie Bridge
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	247521
Northing	850677
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A probable clearance cairn c5m by 3m and 1m tall, under dense bracken which made determining extents difficult.

Asset/Event Number	277
Asset/Event Name	Building, Aultgowrie Bridge
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	247672
Northing	850631
Council	Highland
Condition:	Very Degraded
Alignment:	NW/SE
Importance:	Low

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Possible footings for a building, under bracken and moss and difficult to discern form and extent. Possibly rectangular and 5.5m by 2.5m wide over walls, which are spread up to 1.5m wide and 0.4m tall. Not depicted on historic mapping.

Asset/Event Number	279
Asset/Event Name	Clearance cairn, Aultgowrie Bridge
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	247595
Northing	850587
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A field clearance cairn under moss and trees, measures 4m in diameter and stands 0.75m tall.

Asset/Event Number	280
Asset/Event Name	Dyke, Fairburn
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1, E1.2
Easting	247418
Northing	850706
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass, standing 0.2m tall and spread up to 1.5m wide, very degraded.

Asset/Event Number	281
Asset/Event Name	Clearance cairn, Aultgowrie Bridge

Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG62286
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	247450
Northing	850639
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn/spread of stones under grass, measuring 30m by 5m and 0.1m tall.

Asset/Event Number	282
Asset/Event Name	Clearance cairn, Aultgowrie Bridge
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG62286
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	247470
Northing	850674
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn of stones under grass, measuring 2m in diameter and 0.3m tall.

Asset/Event Number	283
Asset/Event Name	Clearance cairn, Aultgowrie Bridge
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG62286
Status	Non-designated Heritage Asset
Section:	E1.1

Easting	247454
Northing	850683
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn of stones under moss, measuring 1m in diameter and 0.1m tall.

Asset/Event Number	284
Asset/Event Name	Clearance cairn, Aultgowrie Bridge
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG62286
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	247453
Northing	850734
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn/spread of stones under grass, measuring 40m by 8m and 0.1m tall.

Asset/Event Number	285
Asset/Event Name	Clearance cairn, Aultgowrie Bridge
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG62286
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	247390
Northing	850735
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn/spread of stones under grass at field edge, measuring 22m by 12m by 5m and 0.3m tall.

Asset/Event Number	286.1
Asset/Event Name	Farmstead, Aultgowrie Bridge
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG62288
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247611
Northing	850944
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Drystone walls of a rectangular building c10m by 6m over walls which stand up between 0.5-1.2m tall, entrance possibly in E end of structure. Enclosed by dyke 286.2. Consistent with building depicted on the 1st edition OS map. OS. 1875. Inverness-shire (Mainland) II, Surveyed: 1872, Published: 1875 https://her.highland.gov.uk/Monument/MHG62288 Remains of a farmstead near Aultgowrie Bridge. A farmstead comprising one roofed long building with an attached yard or enclosure is depicted on the 1st edition of the OS 25-inch map. <1> <1> SHG23422 Image/Map: Ordnance Survey. 1871-76. Ordnance Survey 1st edition 25 inch map: Ross-shire. Digital. XY

Asset/Event Number	286.2
Asset/Event Name	Dyke, Aultgowrie Bridge
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG62288
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247614
Northing	850946
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke under bracken and moss extending to the north of building Asset 286.1. Measures c25m long and stands 0.3m tall and spread up to 1m. Depicted on the 1st edition OS map. OS. 1875. Inverness-shire (Mainland) II, Surveyed: 1872, Published: 1875 https://her.highland.gov.uk/Monument/MHG62288 Remains of a farmstead near Aultgowrie Bridge. A farmstead comprising one roofed long building with an attached yard or enclosure is depicted on the 1st edition of the OS 25-inch map. <1> Sources/Archives (1) <1> SHG23422 Image/Map: Ordnance Survey. 1871-76. Ordnance Survey 1st edition 25 inch map: Ross-shire. Digital. XY
Asset/Event Number	287
Asset/Event Name	Dyke, Canreavan
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	247683
Northing	850562
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Drystone dyke under moss and grass, appeared c0.3m tall and spread perhaps 1m wide, extending along the S bank of the Allt Goibhre - length unknown. Viewed from N side of the river as not directly accessible due to land access permissions. Consistent with field boundary depicted on the 2nd edition OS map. OS. 1907. Inverness-shire - Mainland II, Surveyed: 1902, Published: 1907
Asset/Event Number	288.1
Asset/Event Name	Building, Aultgowrie Bridge
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG62289
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247536
Northing	851065
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Low

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Rectangular building with drystone walls, measuring 16m 4m over walls with single internal partition. Walls stand 1m tall and 0.7m wide. Entrance in W half of the N side. Potentially correlates with a building depicted on the 1st edition OS map. OS. 1875. Inverness-shire (Mainland) II, Surveyed: 1872, Published: 1875 https://her.highland.gov.uk/Monument/MHG62289 Remains of a farmstead to the northwest of Aultgowrie Bridge. A farmstead comprising one roofed long building with an attached yard or enclosure with two smaller huts to the south is depicted on the 1st edition of the OS 25-inch map. <1> Earthworks of the farmstead are visible on vertical aerial photographs taken in 2020. <2> <1> SHG23422 Image/Map: Ordnance Survey. 1871-76. Ordnance Survey 1st edition 25 inch map: Ross-shire. Digital. <2> SHG28725 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 2020. Getmapping aerial photography 2020. XY
Asset/Event Number	288.2
Asset/Event Name	Enclosure, Aultgowrie Bridge
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG62289
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247536
Northing	851078
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular enclosure measuring c20m by 10m and composed of a drystone dyke under dense bracken and moss, standing 0.3m tall and spread up to 1.5m wide. Enclosure stands on the NW side of the farmstead Asset 288.1, possibly a kale yard. Depicted on the 1st edition OS map. For HER description see Asset 288.1. OS. 1875. Inverness-shire (Mainland) II, Surveyed: 1872, Published: 1875
Asset/Event Number	288.3
Asset/Event Name	Enclosure, Aultgowrie Bridge
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG62289
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247533
Northing	851089
Council	Highland

Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Drystone dyke under bracken and moss, spread 2m wide and standing 1m tall. Forms enclosure 14m by 10m in size. Potentially correlates with a boundary depicted on the 1st edition OS map. For HER description see Asset 288.1. OS. 1875. Inverness-shire (Mainland) II, Surveyed: 1872, Published: 1875
Asset/Event Number	289
Asset/Event Name	Building, Bridgepark
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247411
Northing	851389
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone and turf footings for rectangular building under thick broom vegetation, 15.8m by 4.5m over walls, which are spread 1m wide and stand 0.8m tall. Consistent with a structure depicted on the 1st edition OS map. OS. 1875. Inverness-shire (Mainland) II, Surveyed: 1872, Published: 1875
Asset/Event Number	290
Asset/Event Name	Clearance cairn, Aultgowrie Bridge
Type of Asset/Event	Clearance cairns
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247475
Northing	851093
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Large area of field clearance under moss and tall bracken so single large polygon recorded 40m by 25m. Clearance material stands to 0.7m tall. Could obscure underlying structural remains.

Asset/Event Number	291
Asset/Event Name	Dyke, Bridgepark
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247352
Northing	851322
Council	Highland
Condition:	Very degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass and broom, stands 0.5m tall and spread up to 3m wide. Reduced to ground level in parts. Consistent with field boundary depicted on the 1st edition OS map. OS. 1875. Inverness-shire (Mainland) II, Surveyed: 1872, Published: 1875

Asset/Event Number	292
Asset/Event Name	Clearance cairn, Aultgowrie Bridge
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247447
Northing	851059
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Large area of field clearance under moss and tall bracken so single large polygon recorded c16m by 8m. Clearance material stands to 0.7m tall. Could obscure underlying structural remains.

Asset/Event Number	293
Asset/Event Name	Enclosure, Aultgowrie Bridge

Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247415
Northing	851091
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular enclosure measuring c30m by 10m, composed of a drystone dyke under dense bracken and grass. The dyke stands 0.5m tall and spread up to 2m wide. Not depicted on historic mapping.

Asset/Event Number	294
Asset/Event Name	Dyke, Bridgepark
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247429
Northing	851280
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass, stands up to 0.5m tall and spread up to 3m wide and extends c190m long. This is consistent with a boundary shown on the 1st edition OS map, which dissipates similarly to the W, but appears to have once formed an enclosure delineating an area of improved ground. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII, Surveyed: 1876, Published: 1881.

Asset/Event Number	295
Asset/Event Name	Dyke, Bridgepark
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset

Section:	N/A
Easting	247455
Northing	851164
Council	Highland
Condition:	Degraded
Alignment:	ENE/WSW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke standing up to 1.6m tall and 0.7m wide, extending c170m long, constructed from rounded stones. Appears to be continued by Asset 516, and is consistent with a boundary shown on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII, Surveyed: 1876, Published: 1881.
Asset/Event Number	296
Asset/Event Name	Dyke, Bridgepark
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247532
Northing	851282
Council	Highland
Condition:	Fair
Alignment:	NNW/SSE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke, standing to full height of 1m tall and measuring 1m wide at base, tapering to 0.2m at top. Boulder construction and well-preserved. Depicted on 1st edition OS map as a field boundary. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII, Surveyed: 1876, Published: 1881.
Asset/Event Number	297
Asset/Event Name	Clearance cairn, Bridgepark
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247493
Northing	851376
Council	Highland
Condition:	Ruinous

Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Large area of field clearance under moss and tall bracken so single large polygon recorded 50m by 30m. Clearance material stands to 1m tall in places. Could obscure underlying structural remains.

Asset/Event Number	298
Asset/Event Name	Dyke, Bridgepark
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247394
Northing	851447
Council	Highland
Condition:	Very degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass and trees, stands up to 0.4m tall and spread up to 2m wide, c50m long and very poorly preserved in parts. Broadly correlated with a degraded boundary shown on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII, Surveyed: 1876, Published: 1881.

Asset/Event Number	299
Asset/Event Name	Dyke, Ruttle Wood
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.3
Easting	247788
Northing	842785
Council	Highland
Condition:	Degraded
Alignment:	NNE/SSW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A turf and stone dyke under grass and trees, reduced to ground level in parts and difficult to discern to the S. Stands up to 0.6m tall and spread up to 2m wide, c90m long. Consistent with a boundary depicted on the 1st edition OS map. Truncated to the N by the existing track and not discerned in the commercial forestry beyond this.

	OS. 1876. Inverness-shire (Mainland) X, Surveyed: 1872, Published: 1876.
Asset/Event Number	300
Asset/Event Name	Dyke, Ruttle Wood
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.3
Easting	247927
Northing	842806
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass, stands up to 1.2m tall and spread 2.5m wide. Consistent with field boundary depicted on the 1st edition OS map. Continues outwith the survey corridor to the NE and SW. OS. 1876. Inverness-shire (Mainland) X, Surveyed: 1872, Published: 1876.
Asset/Event Number	301
Asset/Event Name	Dyke, Ardochy
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	246311
Northing	843948
Council	Highland
Condition:	Very degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Turf and stone dyke under grass, visible for c120m along field edge. Stands up to 0.5m tall and spread up to 2.5m wide. Consistent with field boundary depicted on the 1st edition OS map. OS. 1876. Inverness-shire (Mainland) X, Surveyed: 1872, Published: 1876.
Asset/Event Number	302
Asset/Event Name	Clearance cairn, Ardochy
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval

Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.2 (in access track corridor to section)
Easting	246317
Northing	843952
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Large area of field clearance under moss and field edge measuring 20m by 4m and standing 0.6m tall.

Asset/Event Number	303
Asset/Event Name	Culvert, Ardochy
Type of Asset/Event	Other
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246165
Northing	843392
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A grass covered stone-built culvert forming a crossing point over a field ditch. Plastic pipe inserted through with stone lintels atop. At least 4m wide but grass obscures dimensions. Consistent with a field boundary depicted on the 2nd edition OS map onwards. OS. 1906. Inverness-shire Mainland X, Surveyed: 1902, Published: 1906.

Asset/Event Number	304
Asset/Event Name	Clearance cairn, Torr a' Bhealaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.3 (in access track corridor to section)
Easting	246534

Northing	842990
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn of large boulders measuring 6m by 4m adjacent to track Asset 222.

Asset/Event Number	305
Asset/Event Name	Clearance cairn, Ardochy
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH44SE 41.00
HER Number	MHG23314
Status	Non-designated Heritage Asset
Section:	E1.2
Easting	246087
Northing	843331
Council	Highland
Condition:	Ruinous
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn under moss and grass, measuring 8m by 6m and 0.5m tall.

Asset/Event Number	306
Asset/Event Name	Clearance cairn, Cnocnagrashaig
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.2, E1.3
Easting	246185
Northing	843246
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn of stones under moss, measuring 13m in diameter and 0.5m tall.

Asset/Event Number	307
Asset/Event Name	Dyke, Strathconon
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	240809
Northing	856103
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass and standing up to 1m tall spread up to 2m, c125m long. It continues to the W in the form of a drystone dyke (Asset 308). Consistent with a field boundary on the 1st edition OS map. OS. 1876. Inverness-shire (Mainland) X, Surveyed: 1872, Published: 1876.

Asset/Event Number	308
Asset/Event Name	Dyke, Strathconon
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	240629
Northing	856137
Council	Highland
Condition:	Fair
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke c300m long and standing up to 1.6m tall and 0.6m wide top and 0.8m wide at base, slightly splayed and double faced wall with large roughly dressed blocks and a core of rubble. Coping stones set edge ways across the top. It continues to the E in the form of a degraded stone and turf dyke (Asset 307). Consistent with a field boundary on the 1st edition OS map. OS. 1876. Inverness-shire (Mainland) X, Surveyed: 1872, Published: 1876.

Asset/Event Number	309
Asset/Event Name	Flood defence, River Conon
Type of Asset/Event	Other
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	240836
Northing	855659
Council	Highland
Condition:	Fair
Alignment:	Various
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large flood embankment under bracken, gorse and trees, extending along the N side of the River Conon. Stands between 1.5-2m tall and spread up to 5m wide with a rounded profile. Extends beyond the survey corridor to the E and W. Depicted on the 1st edition OS map. OS. 1876. Inverness-shire (Mainland) X, Surveyed: 1872, Published: 1876.

Asset/Event Number	310
Asset/Event Name	Dyke, Comrie
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	240769
Northing	855802
Council	Highland
Condition:	Very degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A shallow linear ditch under grass, measures c470m long, c1m wide and 0.3m deep. Consistent with a field boundary depicted on the 1st edition OS map. OS. 1876. Inverness-shire (Mainland) X, Surveyed: 1872, Published: 1876.

Asset/Event Number	311
Asset/Event Name	Ditch, Comrie
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A

HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	240991
Northing	855826
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A shallow linear ditch under grass, measures c470m long, c1.8m wide and 0.6m deep. Consistent with a field boundary depicted on the 1st edition OS map. OS. 1876. Inverness-shire (Mainland) X, Surveyed: 1872, Published: 1876.

Asset/Event Number	312
Asset/Event Name	Culvert, Comrie
Type of Asset/Event	Other
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	240963
Northing	855950
Council	Highland
Condition:	Good
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone-built culvert, measuring 3m wide and 4m long and stands c1m deep, situated over field ditch Asset 311, with a farm track running over the top of it. The ditch is depicted on the 1st edition OS map, but the culvert is not identified. OS. 1876. Inverness-shire (Mainland) X, Surveyed: 1872, Published: 1876.

Asset/Event Number	313.1
Asset/Event Name	Peat cutting, Carn an Daraich
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	240998
Northing	857820

Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under heather and grass with banks up to 0.4m deep. Disu-used.

Asset/Event Number	313.2
Asset/Event Name	Peat cutting, Carn an Daraich
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	240985
Northing	857813
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under heather and grass with banks up to 0.4m deep. Dis-used.

Asset/Event Number	313.3
Asset/Event Name	Peat cutting, Carn an Daraich
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	240998
Northing	857791
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under heather and grass with banks up to 0.4m deep. Dis-used.

Asset/Event Number	313.4
Asset/Event Name	Peat cutting, Carn an Daraich
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	241025
Northing	857774
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under heather and grass with banks up to 0.4m deep. Dis-used.

Asset/Event Number	314
Asset/Event Name	Pen, Loch Ruith a' Phuil
Type of Asset/Event	Pen
Date and/or Period	Post-medieival
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	241390
Northing	858327
Council	Highland
Condition:	Degraded
Alignment:	Circular
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone wall constructed into a circular pen c16m in diameter, under bracken and grass. Walls stand 0.6m tall at their tallest and spread up to 1.5m wide. Not depicted on historic mapping.

Asset/Event Number	315
Asset/Event Name	Hut circle, Strathconon

Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	240666
Northing	856268
Council	Highland
Condition:	Unknown
Alignment:	Circular
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A probable hut circle is visible on phase 1 LiDAR imagery immediately N of an existing pylon. Could not be surveyed/ground/-proofed due to dense gorse.

Asset/Event Number	316
Asset/Event Name	Ditch, Loch Ruith a' Phuil
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	241569
Northing	858281
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drainage ditch c45m long, c0.2m wide and 0.4m deep, leading from relict track (Asset 307) to water course to the S. Not depicted on historic maps.

Asset/Event Number	317
Asset/Event Name	Track, Loch Ruith a' Phuil
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	

Easting	241549
Northing	858296
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A relict track under grass, c3m wide, along the W side of Loch a Phuill. Under grass and slightly raised up from the boggier ground, leading N to Druim-cruaidh and Cadha-fliuch farmsteads. Not depicted on historic mapping.

Asset/Event Number	318.1
Asset/Event Name	Peat cutting, Carn an Daraich
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	241533
Northing	857936
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under grass, 30m by 10m and 0.3m deep, along the flat terrace of Cairn an Daraich. Dis-used.

Asset/Event Number	318.2
Asset/Event Name	Peat cutting, Carn an Daraich
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	241457
Northing	857887
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under grass, 30m by 20m and 0.3m deep, along the flat terrace of Cairn an Daraich. Dis-used.

Asset/Event Number	318.3
Asset/Event Name	Peat cutting, Carn an Daraich
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	241508
Northing	857920
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under grass, 40m by 20m and 0.3m deep, with a projecting arm to the W, and along the flat terrace of Cairn an Daraich. Dis-used.

Asset/Event Number	319
Asset/Event Name	Peat Stack, Carn an Daraich
Type of Asset/Event	Other
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	241432
Northing	857889
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A mound under heather and grass measuring 12m by 4m and standing 1m tall, adjacent to peat cutting bank Asset 318.2 and likely the degraded remains of an old peat stack.

Asset/Event Number	320.1
Asset/Event Name	Clearance cairn, Carn an Daraich

Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	241028
Northing	857703
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible clearance cairn of stones under heather, measuring 2m in diameter and 0.75m tall. May be natural formations within the localised glen.

Asset/Event Number	320.2
Asset/Event Name	Clearance cairn, Carn an Daraich
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	241030
Northing	857696
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible clearance cairn of stones under heather, measuring 3m in diameter and 0.6m tall. May be natural formations within the localised glen.

Asset/Event Number	321
Asset/Event Name	Memorial, Lubnaceardaich
Type of Asset/Event	Memorial
Date and/or Period	Post-medieval/Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	

Easting	259553
Northing	886053
Council	Highland
Condition:	Fair
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small granite boulder adjacent to the track with an inscription, under somewhat heavy lichen and moss, can just read 'Ander_T'. Stands 0.9m tall. Possible memorial stone.

Asset/Event Number	322.1
Asset/Event Name	Dyke, Upper Garvary
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258991
Northing	885589
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A pair of degraded stone and turf dykes under moss, grass and heather, standing either side of the track that extends along the Wester Fearn burn . The dykes vary in preservation and extent, reduced to ground level in some places but generally stand c0.4m tall and 1m wide. Not depicted on historic mapping, but a track is delineated in varying proportions along the route.

Asset/Event Number	322.2
Asset/Event Name	Dyke, Upper Garvary
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258963
Northing	885521
Council	Highland
Condition:	Various
Alignment:	Various

Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A pair of degraded stone and turf dykes under moss, grass and heather, standing either side of the track that extends along the Wester Fearn burn . The dykes vary in preservation and extent, reduced to ground level in some places but generally stand c0.4m tall and 1m wide. Not depicted on historic mapping, but a track is delineated in varying proportions along the route.
Asset/Event Number	323
Asset/Event Name	Earthwork, Upper Garvary
Type of Asset/Event	Other
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	259244
Northing	885776
Council	Highland
Condition:	Good
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Large L-shaped laydown area/compound area measuring c40m by 40m and adjacent to the existing track, constructed of Type 1 material with a river-side embankment to the N constructed of large pebbles.
Asset/Event Number	324
Asset/Event Name	Structure, Allt a' Chuillin
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	258795
Northing	885333
Council	Highland
Condition:	Very Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Possible footings for a rectangular structure measuring 4.5m by 2m, much obscured by overlying field clearance. Possibly a small pen. Not depicted on historic mapping.
Asset/Event Number	325

Asset/Event Name	Kerb, Garbhairidh
Type of Asset/Event	Other
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	257652
Northing	884074
Council	Highland
Condition:	Good
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A row of large boulders c0.8m tall, set on the W side of the track alongside the stream, part of modern track upgrade.

Asset/Event Number	326
Asset/Event Name	Culvert, Garbhairidh
Type of Asset/Event	Other
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	257663
Northing	884094
Council	Highland
Condition:	Good
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rubble stone culvert c4m wide with plastic pipe underneath the access track, part of the modern track upgrade.

Asset/Event Number	327
Asset/Event Name	Ford and culvert, Garbhairidh
Type of Asset/Event	Structure
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	D1.1
Easting	257626
Northing	884028
Council	Highland
Condition:	Good
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A built up stone ford over a small un-named watercourse that leads into the Allt Coire Bhenneit to the NW. A stone-built culvert contains a plastic pipe to channel the flow. Appears to be a modern track upgrade.

Asset/Event Number	328
Asset/Event Name	Ford, Garbhairidh
Type of Asset/Event	Other
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	257564
Northing	883913
Council	Highland
Condition:	Good
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A fording point over a burn that feeds the Allt Choire Bhenneit. No structural elements visible, but identified as a ford on the 2nd edition OS map.

Asset/Event Number	330
Asset/Event Name	Track, Càrn na h-Uigeig
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256980
Northing	885118
Council	Highland
Condition:	Very degraded

Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A relict track at least 470m long extending along the E side of the Carn na h-Uigeig hill, visible in places as a slight holloway under and through the heather measuring between 1-1.5m wide. Would appear to lead towards Garvary bothy (Asset 143), though it was not discernible in that vicinity. Potentially part of a longer-ranging route between Strathrusdale to the S and the Kyle of Sutherland to the N. Not depicted on historic mapping.
Asset/Event Number	331
Asset/Event Name	Sheepfold, Càrn na h-Uigeig
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	257021
Northing	885085
Council	Highland
Condition:	Fair
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A circular drystone sheepfold c12m in diameter with walls standing 0.5m tall and 0.75m wide. Situated close to track Asset 330. Depicted on the 1st esition OS map and labelled as a 'stell'. OS. 1881. Ross-shire & Cromartyshire (Mainland) XXVI, Surveyed: 1875, Published: 1881.
Asset/Event Number	332
Asset/Event Name	Dyke, Allt na Moine
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256215
Northing	869821
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A turf dyke under heather, standing 1.3m tall and spread 2m wide. Runs along the NW side of the relict track Asset 333 and is likely contemporary. Traced for c200m. The track is depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXIV, Surveyed: 1875, Published: 1881.
Asset/Event Number	333
Asset/Event Name	Track, Allt na Moine
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256295
Northing	869884
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A track c2-2.5m wide, slightly overgrown with grass and gorse but with a visible metalled surface in places. Extends along the NW side of the Allt na Moine burn before crossing it to the E, towards the peat cutting areas (Asset 335.1 and 335.2) atop the Cnoc na Moine hill. The track is depicted on the 1st edition OS map, and may be an old peat transportation road considering the intensive peat cutting on the hill nearby, named Cnoc na Moine (Hill of the Peat) and and the fact that it runs alongside the 'Allt na Moine' (Stream of the Peat). OS. 1881. Ross-shire & Cromartyshire (Mainland) LXIV, Surveyed: 1875, Published: 1881.
Asset/Event Number	334
Asset/Event Name	Culvert, Torran an Sporain
Type of Asset/Event	Other
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256454
Northing	870100
Council	Highland
Condition:	Good
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A concrete culvert pipe c0.5m diameter, below the track Asset 333 where it crosses the Allt na Moine burn. Very obscured below moss and close growing trees, could not ascertain if there is a further stone structure or bridge the track is supported by. The track is depicted on the 1st edition OS map, but

	there is no indication of a bridge/similar structure. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXIV, Surveyed: 1875, Published: 1881.
Asset/Event Number	335.1
Asset/Event Name	Peat cutting, Torran an Sporain
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256599
Northing	870056
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large area of intensive peat cutting c120m by 80m under heather and grass on the N facing slope of the Torr na Sporain hill. The track Asset 333 passes close by and likely formed the old peat road for the collection of peats. Also too likely why the Allt na Moine (Stream of the Peat) is named such.
Asset/Event Number	335.2
Asset/Event Name	Peat cutting, Cnoc na Moine
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256463
Northing	869673
Council	Highland
Condition:	Very Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under heather and grass measuring 120m by 20m and up to 0.6m deep on Torr na Sporain hill. The track Asset 333 passes close by and likely formed the old peat road for the collection of peats. Also too likely why the Allt na Moine (Stream of the Peat) is named such.
Asset/Event Number	336.1
Asset/Event Name	Ditch, Torrain an Sporain
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval

Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256706
Northing	870281
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A narrow ditch under heather, less than 1m wide and 0.4m deep with a slight bank adjacent to the W that stands 0.3m tall and spread perhaps 1m wide. A peat grip to drain the peat into the Allt Buidheanach to the north. One of several peat grips on the S side of the water course with fairly wavering forms that suggest they have been hand-excavated, unlike the regular ditches visible on the N side (Asset 955 group) which appear to have been mechanically excavated. Not depicted on historic mapping.

Asset/Event Number	336.2
Asset/Event Name	Ditch, Torrain an Sporain
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256675
Northing	870255
Council	Highland
Condition:	Fair
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat creep (drainage ditch) 0.5m wide and 0.8m deep with associated bank on W side 0.25m tall and spread up to 1m wide, N/S aligned, used for draining the peat on the Torrain an Sporain hill into the Allt Buidheaneach to the N. Not depicted on historic mapping.

Asset/Event Number	336.3
Asset/Event Name	Ditch, Torrain an Sporain
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A

Easting	256739
Northing	870258
Council	Highland
Condition:	Fair
Alignment:	NNE/SSW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat creep (drainage ditch) 0.5m wide and 0.8m deep with associated bank on W side 0.25m tall and spread up to 1m wide, NNE/SSW aligned, used for draining the peat on the Torrain an Sporain hill into the Allt Buidheaneach to the N. Not depicted on historic mapping.

Asset/Event Number	336.4
Asset/Event Name	Ditch, Torrain an Sporain
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256786
Northing	870346
Council	Highland
Condition:	Fair
Alignment:	NNW/SSE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat creep (drainage ditch) 0.5m wide and 0.8m deep with associated bank on W side 0.25m tall and spread up to 1m wide, NNW/SSE aligned, used for draining the peat on the Torrain an Sporain hill into the Allt Buidheaneach to the N. Not depicted on historic mapping.

Asset/Event Number	336.5
Asset/Event Name	Ditch, Torrain an Sporain
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256802
Northing	870363
Council	Highland
Condition:	Fair
Alignment:	NNW/SSE
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat creep (drainage ditch) 0.5m wide and 0.8m deep with associated bank on W side 0.25m tall and spread up to 1m wide, NNW/SSE aligned, used for draining the peat on the Torrain an Sporain hill into the Allt Buidheaneach to the N. Not depicted on historic mapping.
Asset/Event Number	336.6
Asset/Event Name	Ditch, Torrain an Sporain
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	256815
Northing	870378
Council	Highland
Condition:	Fair
Alignment:	NNW/SSE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat creep (drainage ditch) 0.5m wide and 0.8m deep with associated bank on W side 0.25m tall and spread up to 1m wide, NNW/SSE aligned, used for draining the peat on the Torrain an Sporain hill into the Allt Buidheaneach to the N. Not depicted on historic mapping.
Asset/Event Number	336.7
Asset/Event Name	Ditch, Torrain an Sporain
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256629
Northing	870257
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat creep (drainage ditch) 0.5m wide and 0.8m deep with associated bank on W side 0.25m tall and spread up to 1m wide, N/S aligned, used for draining the peat on the Torrain an Sporain hill into the Allt Buidheaneach to the N. Not depicted on historic mapping.
Asset/Event Number	337.1
Asset/Event Name	Shooting butt, Allt Buidheachean

Type of Asset/Event	Shooting butt
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256815
Northing	870605
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A probable shooting butt under heather, excavated into a small natural mound rather than the typical built up bank. Internal cavity measures c.4m by 1.5m wide, 1m deep, and access to NE. Not depicted on historic mapping.

Asset/Event Number	337.2
Asset/Event Name	Shooting butt, Allt Buidheachean
Type of Asset/Event	Shooting butt
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256814
Northing	870610
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A shooting butt under heather, cut into natural mound and adjacent to Asset 337.1. Internal cavity measures c.4m by 1.5m wide 1m deep, access to NE. Not depicted on historic mapping.

Asset/Event Number	338.1
Asset/Event Name	Shooting butt, Torr Dearg
Type of Asset/Event	Shooting butt
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG56494
Status	Non-designated Heritage Asset
Section:	D1.2

Easting	256844
Northing	870832
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A shooting butt under heather, 1.1m tall and c5m in diameter, cut into the S-facing slope of a hill, with the entrance leading in from S. Not depicted on historic mapping. https://her.highland.gov.uk/Monument/MHG56494 A line of shooting butts at Cnoc Gille Mo Bhrianaig, noted during a walkover survey by RoCAS in 2013 in advance of a proposed woodland creation scheme on the Novar Estate. They are not shown on the 1st and 2nd Edition OS maps, which would indicate that they post-date 1902. <1> <1> SHG25865 Text/Report/Fieldwork Report: Fraser, L.. 2013. Novar Woodland Creation: Archaeological Desk-based Assessment and Walkover Survey. Ross & Cromarty Archaeological Services. Digital. Features 5a-5i.
Asset/Event Number	338.2
Asset/Event Name	Shooting butt, Torr Dearg
Type of Asset/Event	Shooting butt
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG56494
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256827
Northing	870877
Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A shooting butt under heather measuring c4.5m in diameter over banks which stand c1.2m tall. Entrance leading in from the S. The structure is partially revetted into the S-facing hill slope and stands within a line of previously recorded shooting butts (MHG56494) extending NW/SE. Not depicted on historic mapping. For HER description see Asset 338.1.
Asset/Event Number	338.3
Asset/Event Name	Shooting butt, Torr Dearg
Type of Asset/Event	Shooting butt
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG56494
Status	Non-designated Heritage Asset
Section:	D1.2

Easting	256810
Northing	870928
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A shooting butt under heather and moss, same as the one to the SE (Asset 338.2). Open to the SE. Not depicted on historic mapping. Not depicted on historic mapping. For HER description see Asset 338.1.

Asset/Event Number	338.4
Asset/Event Name	Shooting butt, Torr Dearg
Type of Asset/Event	Shooting butt
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG56494
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256794
Northing	870975
Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A shooting butt under heather with banks standing 1.2m tall and entrance leading in from SE, measures c4.5 by 3.5m over banks. Not depicted on historic mapping. For HER description see Asset 338.1.

Asset/Event Number	338.5
Asset/Event Name	Shooting butt, Torr Dearg
Type of Asset/Event	Shooting butt
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG56494
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256774
Northing	871028
Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A shooting butt under heather with banks standing 1.1m tall and entrance leading in from SE, measures c4.5 by 3.5m over banks. Not depicted on historic mapping. For HER description see Asset 338.1.

Asset/Event Number	339.1
Asset/Event Name	Deer salt lick, Torr Dearg
Type of Asset/Event	Other
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	257018
Northing	871162
Council	Highland
Condition:	Good
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A deer salt lick, constructed by cutting a section of peat and creating a mound adjacent to the cut area, salt visible on the mound. Mound stands 0.7m tall and measures c.2m in diameter. Will likely grow over with heather at a later date and appear similar to a prehistoric clearance cairn and so recorded for posterity.

Asset/Event Number	339.2
Asset/Event Name	Deer salt lick,Torr a' Mhulcan
Type of Asset/Event	Other
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	257060
Northing	871296
Council	Highland
Condition:	Good
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A deer salt lick, constructed by cutting a section of peat and creating a mound adjacent to the cut area, salt visible on the mound. Mound stands 0.7m tall and measures c.2m in diameter. Will likely grow over with heather at a later date and appear similar to a prehistoric clearance cairn and so recorded for posterity.

Asset/Event Number	339.3

Asset/Event Name	Deer salt lick, Torr a' Mhulcan
Type of Asset/Event	Other
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	257093
Northing	871430
Council	Highland
Condition:	Good
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A deer salt lick, constructed by cutting a section of peat and creating a mound adjacent to the cut area, salt visible on the mound. Mound stands 0.7m tall and measures c.2m in diameter. Will likely grow over with heather at a later date and appear similar to a prehistoric clearance cairn and so recorded for posterity.

Asset/Event Number	340
Asset/Event Name	Track, Cnoc Liath na h-Acain
Type of Asset/Event	Track
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	257231
Northing	873204
Council	Highland
Condition:	Good
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A track measuring 2-2.5m wide, extending outwith the survey corridor to the NW. Appears to be modern in date.

Asset/Event Number	341.1
Asset/Event Name	Soil bund, Allt a' Ghreaich
Type of Asset/Event	Other
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	D1.1
Easting	257347
Northing	873053
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A bund of soil and gravel under grass measuring 9m by 3m and standing 0.6m tall, adjacent to modern track and likely related to its construction.

Asset/Event Number	341.2
Asset/Event Name	Soil bund, Allt a' Ghreaich
Type of Asset/Event	Other
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	257353
Northing	873055
Council	Highland
Condition:	Good
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A bund of soil partially under grass, c3m in diameter and standing to 0.5m tall, adjacent to modern track and likely related to its construction.

Asset/Event Number	341.3
Asset/Event Name	Soil bund, Allt a' Ghreaich
Type of Asset/Event	Other
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	257378
Northing	873036
Council	Highland
Condition:	Fair

Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An L shape bund of soil and gravel under grass, extends c21m NE/SW and 35m NW/SE, c5-7m wide and c1m tall. Adjacent to modern track and likely related to its construction.

Asset/Event Number	342
Asset/Event Name	Dyke, Cnoc Liath na h-Acain
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	257422
Northing	873054
Council	Highland
Condition:	Very degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone and turf dyke under moss and heather, stands between 0.4- 1.1m tall and spread up to 1.5m wide. Surveyed extent measures c330m, but continues beyond survey corridor to the W. The SW portion is consistent with a field boundary depicted on the 1st edition OS map. OS. 1880. Ross-shire & Cromartyshire (Mainland) LII, Surveyed: 1875, Published: 1880

Asset/Event Number	343
Asset/Event Name	Possible structure, Novar
Type of Asset/Event	Structure
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	257144
Northing	873117
Council	Highland
Condition:	Unknown
Alignment:	NE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An unroofed structure or pen open to the SE is depicted on the 1st edition os map but no trace could be discerned during the survey. May lie below commercial forestry. OS. 1880. Ross-shire & Cromartyshire (Mainland) LII, Surveyed: 1875, Published: 1880

Asset/Event Number	344
Asset/Event Name	Dyke, Cnoc Liath na h-Acain
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	257464
Northing	873071
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Drystone dyke under tall grass and heather, stands 0.8m tall and 0.6m wide, c100m length recorded but may continue to the W on the opposite side of the modern track that truncates it. Not depicted on historic mapping.

Asset/Event Number	345
Asset/Event Name	Dyke, Boathvic
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1 (in access track corridor to section)
Easting	257030
Northing	874205
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone wall standing to 1.3m tall but degraded in parts to 0.4m, breached by access track and continues beyond survey corridor to NW and SE. Roughly dressed stones with slightly splayed faces, line of coping stones set across top. Consistent with a field boundary depicted on the 1st edition OS map. OS. 1880. Ross-shire & Cromartyshire (Mainland) LII, Surveyed: 1875, Published: 1880

Asset/Event Number	346
Asset/Event Name	Dyke, Boathvic
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval

Listing No./NRHE Number	NH57SE 27
HER Number	MHG20472
Status	Non-designated Heritage Asset
Section:	D1.1 (in access track corridor to section)
Easting	256919
Northing	874121
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A degraded stone and turf dyke under moss and grass, stands to 0.6m tall and spread to 2m wide. As it continues to the SW it has been improved and built up with stone, including a neat rectangular pen c20m long by 7m wide. As depicted on the 2nd edition OS map. OS. 1907. Ross and Cromarty LII, Surveyed: 1902, Published: 1907
Asset/Event Number	347
Asset/Event Name	Dyke, Boathvic
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1 (in access track corridor to section)
Easting	256943
Northing	874149
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke, just base stones remaining, stands 0.3m tall and spread up to 1.5m wide. Consistent with a field boundary depicted on the 1st edition OS map. OS. 1880. Ross-shire & Cromartyshire (Mainland) LII, Surveyed: 1875, Published: 1880
Asset/Event Number	348.1
Asset/Event Name	Clearance cairn, Boathvic
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1 (in access track corridor to section)
Easting	256858

Northing	874130
Council	Highland
Condition:	Ruinous
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn partially under grass, measures 4m by 0.7m and stands 0.3m tall.

Asset/Event Number	348.2
Asset/Event Name	Clearance cairn, Boathvic
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1 (in access track corridor to section)
Easting	256820
Northing	874154
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn partially under grass, measures 4m by 0.7m and stands 0.3m tall.

Asset/Event Number	348.3
Asset/Event Name	Clearance cairn, Boathvic
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1 (in access track corridor to section)
Easting	256817
Northing	874158
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn partially under grass, measures c3m in diameter and 0.5m tall.

Asset/Event Number	348.4
Asset/Event Name	Clearance cairn, Boathvic
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1 (in access track corridor to section)
Easting	256790
Northing	874162
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn partially under grass, measures c1.5 by 1m and stands 0.8m tall.

Asset/Event Number	349
Asset/Event Name	Enclosure, Boathvic
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1 (in access track corridor to section)
Easting	256739
Northing	874128
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A D-shaped enclosure measuring c25m by 18m, composed of a drystone dyke standing 0.6m at its tallest, and spread 1.2m wide. Consistent with a field boundary depicted on the 1st edition OS map. OS. 1880. Ross-shire & Cromartyshire (Mainland) LII, Surveyed: 1875, Published: 1880

Asset/Event Number	350
Asset/Event Name	Building, Boathvic

Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1 (in access track corridor to section)
Easting	256773
Northing	874135
Council	Highland
Condition:	Very Degraded
Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Footings of a rectangular building under grass and moss and field clearance are visible with the walls surviving best on the W side, visible as large boulders up to 0.6m long and standing c1m tall, with structure mueasures c6m by 4m. Consistent with the S portion of a roofed building depicted on the 1st edition OS map. OS. 1880. Ross-shire & Cromartyshire (Mainland) LII, Surveyed: 1875, Published: 1880
Asset/Event Number	351.1
Asset/Event Name	Building, Boathvic
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1 (in access track corridor to section)
Easting	256749
Northing	874159
Council	Highland
Condition:	Ruinous
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular single-storey building measuring 18m by 5.5m over walls, roofed in corrugated iron sheets over old wood slates; roof is collapsed to the W. Wall heads stand 2m tall and gable ends stand 4m tall, with walls measuring 0.5m wide. Corners have quoins and walls are constructed with large roughly dressed rectangular stones and smaller chinking stones in mortar. Slight projecting base stones suggest a likely older underlying building; these are more visible along the W side of the building, where a more roughly constructed building (Asset 351.2) extends, slightly set back from the building face of Asset 351.1, and the discordant base stones of Asset 351.1 appear to better match the alignment of this second building. Two entrances in S elevation 1.9m tall and 1.4m wide, and a similar proportioned entrance in the N elevation. One window in S elevation, W of W entrance. Depicted as a roofed building on the 1st edition OS map. OS. 1880. Ross-shire & Cromartyshire (Mainland) LII, Surveyed: 1875, Published: 1880
Asset/Event Number	351.2

Asset/Event Name	Building, Boathvic
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1 (in access track corridor to section)
Easting	256738
Northing	874161
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular building measuring 7m by 5m over walls, abutted by building Asset 351.1 to the E which appears to overlie possible foundations associated with this building that are set on a slightly different alignment. The walls stand 1.5m tall and measures 0.75m wide at base, tapering somewhat towards the top. An entrance is not readily discernible but collapsed wall on N side offers access. A roofed building is depicted here on the 1st edition OS map. OS. 1880. Ross-shire & Cromartyshire (Mainland) LII, Surveyed: 1875, Published: 1880

Asset/Event Number	352
Asset/Event Name	Dyke, Boathvic
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1 (in access track corridor to section)
Easting	256786
Northing	874158
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke, very degraded and represented by intermittent boulders. Stands 0.5m tall and spread up to 3m wide, c70m long. Depicted on the 1st edition OS map. OS. 1880. Ross-shire & Cromartyshire (Mainland) LII, Surveyed: 1875, Published: 1880

Asset/Event Number	353
Asset/Event Name	Clearance cairn, Boathvic
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A

HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1 (in access track corridor to section)
Easting	256756
Northing	874167
Council	Highland
Condition:	Fair
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A single large field-cleared stone measuring 1.6m × 1.6m × 0.9m.

Asset/Event Number	354
Asset/Event Name	Shed, Boathvic
Type of Asset/Event	Building
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1 (in access track corridor to section)
Easting	256737
Northing	874165
Council	Highland
Condition:	Good
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Modern wooden shed c4m by 4m and 3m tall with entrance in W elevation. In use for storage.

Asset/Event Number	355
Asset/Event Name	Dyke, Boathvic
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1 (in access track corridor to section)
Easting	256679
Northing	874180
Council	Highland

Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke, very degraded and represented by intermittent boulders. Stands 0.5m tall and spread up to 3m wide. Depicted on the 1st edition OS map. OS. 1880. Ross-shire & Cromartyshire (Mainland) LII, Surveyed: 1875, Published: 1880
Asset/Event Number	356
Asset/Event Name	Dyke, Boathvic
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1 (in access track corridor to section)
Easting	256646
Northing	874133
Council	Highland
Condition:	Very degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone and turf dyke, represented solely by intermittent boulders under grass, standing less than 0.4m tall and spread up to 1.5m wide, c80m long. Consistent with a field boundary depicted on the 1st edition OS map. OS. 1880. Ross-shire & Cromartyshire (Mainland) LII, Surveyed: 1875, Published: 1880
Asset/Event Number	357
Asset/Event Name	Dyke, Glack
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH57SE 27
HER Number	MHG20472
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256241
Northing	873899
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass, standing to a height of 0.8m tall and spread up to 4m wide in parts, c70m long. Consistent with field boundaries depicted on the 1st edition OS map. OS. 1880. Ross-shire & Cromartyshire (Mainland) LII, Surveyed: 1875, Published: 1880
Asset/Event Number	358
Asset/Event Name	Bridge, Glack
Type of Asset/Event	Bridge
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH57SE 27
HER Number	MHG20472
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256208
Northing	873875
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A simple bridge of slab stones set over narrow stream course, measures 3m by 1.5m (stream runs along the 3m alignment, NW/SE). Associated with the nearby settlement of Glack. Not on historic mapping.
Asset/Event Number	359
Asset/Event Name	Dyke, Glack
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH57SE 27
HER Number	MHG20472
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256283
Northing	873816
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under heather, stands 1.4m tall and spread 1.5m wide and runs broadly parallel with Dyke Asset 360. c150m long. Consistent with field boundaries depicted on the 1st edition OS map. OS. 1880. Ross-shire & Cromartyshire (Mainland) LII, Surveyed: 1875, Published: 1880
Asset/Event Number	360
Asset/Event Name	Dyke, Glack

Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256642
Northing	873579
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A turf and stone dyke under grass and heather, stands 1m tall and spread to 1.8m wide, runs broadly parallel with dyke Asset 359 on the W side, extends c1.1km. Consistent with head dyke depicted on the 1st edition OS map. OS. 1880. Ross-shire & Cromartyshire (Mainland) LII, Surveyed: 1875, Published: 1880

Asset/Event Number	361
Asset/Event Name	Dyke, Glack
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH57SE 27
HER Number	MHG20472
Status	Non-designated Heritage Asset
Section:	D1.1 (in access track corridor to section)
Easting	256518
Northing	873977
Council	Highland
Condition:	Very degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke standing 0.6m and 0.4m wide, spread up to 1.5m in the S extent. c50m long. Consistent with field boundary depicted on the 1st edition OS map. OS. 1880. Ross-shire & Cromartyshire (Mainland) LII, Surveyed: 1875, Published: 1880

Asset/Event Number	362
Asset/Event Name	Track, Boath
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset

Section:	D1.1
Easting	256692
Northing	873593
Council	Highland
Condition:	Fair
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A track measuring 2.5-3m wide under grass. C590m long, continues S beyond survey corridor extent. Depicted on the 1st edition OS map. OS. 1880. Ross-shire & Cromartyshire (Mainland) LII, Surveyed: 1875, Published: 1880

Asset/Event Number	363
Asset/Event Name	Dyke, Boathmore
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256795
Northing	873521
Council	Highland
Condition:	Very degraded
Alignment:	NNE/SSW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke under grass and moss, stands 0.4m tall and spread 1.5m wide, c90m long and continues outwith survey corridor to the NE and SW. Depicted on 1st edition OS map. OS. 1880. Ross-shire & Cromartyshire (Mainland) LII, Surveyed: 1875, Published: 1880

Asset/Event Number	364
Asset/Event Name	Cistern, Boathmore
Type of Asset/Event	Other
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.1
Easting	256649
Northing	873678
Council	Highland
Condition:	Good
Alignment:	N/A

Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A water cistern visible as a concrete slab atop a brick base, measuring 2m by 1.5m and 0.3m tall.

Asset/Event Number	365
Asset/Event Name	Memorial stone, Sgitheach
Type of Asset/Event	Memorial
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	252135
Northing	862926
Council	Highland
Condition:	GHood
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A modern memorial in the form of a standing stone overlooking Strath Sgiathach. The inscription reads "we are all part of the river of life" followed by the name "Kerr Yule", and a salmon is depicted below. The stone stands to a height of 1.5m.

Asset/Event Number	366
Asset/Event Name	Bank, Allt na Ciste Duibhe
Type of Asset/Event	Bank
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	258646
Northing	897132
Council	Highland
Condition:	Fair
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A bank under grass and trees standing up to 1.2m tall and spread 3m wide, extends along the edge of a forestry plantation and track and likely related to this. C540m long. Not on historic maps.

Asset/Event Number	367

Asset/Event Name	Peat cutting, Clais na Sinneig
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263995
Northing	897302
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting c300m by 300m under heather with peat banks standing to a height of between 0.2-0.6m deep.

Asset/Event Number	367.1
Asset/Event Name	Shooting butt, Clais na Sinneig
Type of Asset/Event	Shooting butt
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	263490
Northing	897758
Council	Highland
Condition:	Ruinous
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A shooting butt, one of three set out in a line to overlook the shallow valley formed by the Allt Clais na Faire burn. Butt comprises a pile of pallet wood indicating a simple screen set up for the butt that has since collapsed.

Asset/Event Number	367.2
Asset/Event Name	Shooting butt, Clais na Sinneig
Type of Asset/Event	Shooting butt
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset

Section:	C1.1
Easting	263495
Northing	897765
Council	Highland
Condition:	Ruinous
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A shooting butt, one of three set out in a line to overlook the shallow valley formed by the Allt Clais na Faire burn. Butt comprises a pile of pallet wood indicating a simple screen set up for the butt that has since collapsed.

Asset/Event Number	367.3
Asset/Event Name	Shooting butt, Clais na Sinneig
Type of Asset/Event	Shooting butt
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	263498
Northing	897771
Council	Highland
Condition:	Ruinous
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A shooting butt, one of three set out in a line to overlook the shallow valley formed by the Allt Clais na Faire burn. Butt comprises a pile of pallet wood indicating a simple screen set up for the butt that has since collapsed.

Asset/Event Number	368
Asset/Event Name	Building, Sithean Mor
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263954
Northing	897330
Council	Highland
Condition:	Very Degraded
Alignment:	NW/SE

Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Footings for a possible rectangular building under grass and heather measuring c4.5m by 2.5m over banks that stand 0.3m tall and spread up to 0.6m wide. Very ephemeral. Situated on a slight hill overlooking peat cutting Asset 367, which surrounds it. Possibly a shieling/similar more ephemeral structure. Not depicted on historic mapping.
Asset/Event Number	369
Asset/Event Name	Peat Stack, Sithean Mor
Type of Asset/Event	Other
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263935
Northing	897335
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small heather covered mound measuring 2m in diameter and standing 0.2m tall, a probable degraded peat stack or navigation mound.

Asset/Event Number	371
Asset/Event Name	Track, Clais na Sinneig
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263410
Northing	897246
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Relict track under heather and grass, c3m wide, only visible along the extent recorded c150m long within the survey corridor. Not depicted on historic mapping, but likely the old access to the settlement remains to the NE (Asset 372 group).

Asset/Event Number	372.1
Asset/Event Name	Structure, Clais na Sinneig
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263199
Northing	897297
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Footings for a rectangular building under grass and heather measuring 8m by 4.5m over walls. An internal partition defines two rooms, with the E side, internally measuring 4m by 1.8m, more poorly preserved with walls showing only as turf banks, while the W compartment, internally measuring 3m by 1.8m, has walls of visible stone spread 1m wide and standing 0.4m tall. A depression in the S elevation of this compartment may be its entrance. Not depicted on historic maps.

Asset/Event Number	372.2
Asset/Event Name	Building, Clais-na-sinneig
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263177
Northing	897283
Council	Highland
Condition:	Very Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular building measuring internally 4.2m by 3m, cut into the SW-facing slope of a hill. The back (NE) wall has been revetted into the hill slope, with the SW wall constructed of stone and turf and measuring 1m wide and standing 0.3m tall. Entrance is 1.5m wide and in the SW corner. Not depicted on historic maps.

Asset/Event Number	372.4
Asset/Event Name	Building, Clais na Sinneig
Type of Asset/Event	Building
Date and/or Period	

Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263118
Northing	897297
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular building under grass and heather measuring 10.5m by 5m over walls which stand 0.8m tall and spread 1m wide. Single portion wall measuring 0.6m wide and 0.2m tall separates the building into two rooms, the NW compartment measuring 3m by 2.5m a internally and SE compartment measuring 4m by 2.5m internally. Entrances not discernible. This likely is a small roofed building depicted on the 1st edition OS map related to the Clais-na-Sinneig township, and unroofed by the 2nd edition OS map. OS. 1879. Sutherland CVIII, Surveyed: 1874, Published: 1879. OS. 1907. Sutherland CVIII, Surveyed: 1903, Published: 1907.
Asset/Event Number	372.5
Asset/Event Name	Dyke, Clais na Sinneig
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263054
Northing	897300
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Drystone enclosure to NW of Asset 372.4, comprised of angular stone, surviving to one course. The wall is o.50m wide and 0.40m in height, there is no evidence of bonding material. L-shaped and c130m long, consistent with enclosure depicted on 1st edition SO map. OS. 1879. Sutherland CVIII, Surveyed: 1874, Published: 1879.
Asset/Event Number	372.6
Asset/Event Name	Pen, Clais na Sinneig
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	N/A
Easting	263052
Northing	897372
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Small enclosure or potential sheep pen, c10m by c10m, comprised of angular unbonded stone surviving to 5 courses or 1.2m in elevation. Possibly remnants of a building depicted on the 1st edition OS map related to the Clais-na-Sinneig township, and unroofed by the 2nd edition OS map. OS. 1879. Sutherland CVIII, Surveyed: 1874, Published: 1879. OS. 1907. Sutherland CVIII, Surveyed: 1903, Published: 1907.
Asset/Event Number	372.7
Asset/Event Name	Building, Clais na Sinneig
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263108
Northing	897390
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A linear stone building under heather and moss, abutting the adjacent building Asset 372.8 to the NW, but set on a slightly higher elevation. The building measures 10m by 6m over walls which stand to 1.2m tall and 0.7m wide, best preserved along the gable ends. The internal space measures 5m by 3m with no partitions discernible but much stone tumble. Entrances are not discernible. This likely is a small roofed building depicted on the 1st edition OS map related to the Clais-na-Sinneig township, and unroofed by the 2nd edition OS map. OS. 1879. Sutherland CVIII, Surveyed: 1874, Published: 1879. OS. 1907. Sutherland CVIII, Surveyed: 1903, Published: 1907.
Asset/Event Number	372.8
Asset/Event Name	Building, Clais na Sinneig
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A

Easting	263098
Northing	897393
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A linear stone building under heather and moss, abutting the adjacent building Asset 372.7 to the NW, but set on a slightly lower elevation. The building measures 7m by 6m over walls which stand to 1m tall and 0.7m wide, best preserved along the gable ends. The internal space measures 5m by 3m with no partitions discernible but much stone tumble. Entrances are not discernible. This likely is a small roofed building depicted on the 1st edition OS map related to the Clais-na-Sinneig township, and unroofed by the 2nd edition OS map. OS. 1879. Sutherland CVIII, Surveyed: 1874, Published: 1879. OS. 1907. Sutherland CVIII, Surveyed: 1903, Published: 1907.
Asset/Event Number	372.9
Asset/Event Name	Enclosure, Clais na Sinneig
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263108
Northing	897374
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone and turf embankments under grass, enclosing a rectangular space to S of buildings Asset 372.7 and 372.8, c1m wide and 0.3m tall embankments, c40m length with entrance possibly on E elevation. Not depicted on historic maps.
Asset/Event Number	372.10
Asset/Event Name	Track, Clais na Sinneig
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263158
Northing	897242

Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Linear embankment of stone and turf to W of trackway, 1m in width and 38m long, 0.40m height. Not depicted on historic maps.

Asset/Event Number	373.1
Asset/Event Name	Prehistoric clearance cairn, Clais na Sinneig
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH69NW 7
HER Number	MHG10097
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263181
Northing	897201
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather, measures 4m in diameter and 1m tall.

Asset/Event Number	373.2
Asset/Event Name	Prehistoric clearance cairn, Clais na Sinneig
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH69NW 7
HER Number	MHG10097
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263196
Northing	897194
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather, measures 6.5m in diameter and 1m tall.

Asset/Event Number	373.3
Asset/Event Name	Prehistoric clearance cairn, Clais na Sinneig
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH69NW 7
HER Number	MHG10097
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263211
Northing	897194
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather, measures 4m in diameter and 1m tall.

Asset/Event Number	373.4
Asset/Event Name	Prehistoric clearance cairn, Clais na Sinneig
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH69NW 7
HER Number	MHG10097
Status	Non-designated Heritage Asset
Section:	N/A
Easting	263205
Northing	897182
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather, measures 4m in diameter and 1m tall.

Asset/Event Number	374.1
Asset/Event Name	Dyke, Carrol

Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC80NW 24
HER Number	MHG19558
Status	Non-designated Heritage Asset
Section:	N/A
Easting	284817
Northing	907087
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass, between 0.2 and 0.7m tall and spread up to 2m, mostly visible as bare stone, c110m long. Consistent with boundary depicted on 1st edition OS map. OS. 1879. Sutherland XCVII, Surveyed: 1872, Published: 1879 https://her.highland.gov.uk/monument/MHG19558 A township comprising eight roofed and one unroofed building, five enclosures, and a head-dyke is depicted on the 1st edition of the OS 6-inch map (Sutherland 1879, sheet xcvii). One roofed and one unroofed building, four enclosures, some sheep pens and part of a head-dyke are shown on the current edition of the OS 1:10560 map (1969). Information from RCAHMS (SAH) 1 November 1995 NGR adjusted based on 1999-2001 vertical aerial photographs. <1> --- SHG8579 Image/Photograph(s): Carrol, township. Colour Print. . XY <1> SHG27491 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 1999-2001. Get Mapping colour vertical aerial photography 1999-2001 (The Millennium Map). XY
Asset/Event Number	374.2
Asset/Event Name	Dyke, Carrol
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC80NW 24
HER Number	MHG53871
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	284832
Northing	907227
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass, between 0.2 and 0.7m tall and spread up to 2m, c175, long. Consistent with boundary depicted on 1st edition OS map. For HER asset description see Asset 374.1. OS. 1879. Sutherland XCVII, Surveyed: 1872, Published: 1879
Asset/Event Number	374.3

Asset/Event Name	Pen, Carrol
Type of Asset/Event	Pen
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC80NW 24
HER Number	MHG19558
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	284841
Northing	907246
Council	Highland
Condition:	Very degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass, between 0.2 and 0.7m tall and spread up to 2m. Forms an enclosure against dyke Asset 374.2, measuring c25m by 25m. Consistent with boundary depicted on 1st edition OS map. For HER asset description see Asset 374.1. OS. 1879. Sutherland XCVII, Surveyed: 1872, Published: 1879

Asset/Event Number	374.4
Asset/Event Name	Dyke, Carrol
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC80NW 24
HER Number	MHG19558
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	284862
Northing	907156
Council	Highland
Condition:	Fair
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass, between 0.2 and 0.7m tall and spread up to 2m, c80m long.Consistent with boundary depicted on 1st edition OS map. For HER asset description see Asset 374.1. OS. 1879. Sutherland XCVII, Surveyed: 1872, Published: 1879

Asset/Event Number	375
Asset/Event Name	Clearance cairn, Carrol
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	B1.1
Easting	284973
Northing	907189
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn measuring approximately 6m by 3m and up to 0.5m tall. Not accessed directly as in field with calving cows but visible from afar.

Asset/Event Number	376
Asset/Event Name	Structure, Carrol
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC80NW 24
HER Number	MHG53871
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	284871
Northing	907273
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular pen measuring 2m by 8m over walls. Walls stand up to 0.7m tall and spread up to 1.2m wide. Degraded in parts to ground level, entrance not discernible. Depicted as an unroofed building or pen on the 1st edition OS map. For HER asset description see Asset 374.1. OS. 1879. Sutherland XCVII, Surveyed: 1872, Published: 1879

Asset/Event Number	377
Asset/Event Name	Ditch, Carrol
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	284576
Northing	907152
Council	Highland

Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Grass covered ditch, 3m wide used for water drainage running down to burn with small Embankment at either side measuring 0.6m wide and up to 0.4 tall.

Asset/Event Number	378.1
Asset/Event Name	Peat stack, Carrol
Type of Asset/Event	Other
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	284542
Northing	907036
Council	Highland
Condition:	Very Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible degraded peat stack or navigation marker visible as a small mound under heather, 1m tall and spread 6m by 3m. Situated at the edge of an area of peat cutting (Asset 378.2).

Asset/Event Number	378.2
Asset/Event Name	Peat cutting, Carrol
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	284526
Northing	907059
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A poorly defined area of peat cutting c40m by 20m under heather and grass, barely visible by eye but felt underfoot.

Asset/Event Number	379.1
Asset/Event Name	Peat cutting, Coire an Uisgeachaidh
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	283706
Northing	906726
Council	Highland
Condition:	Very degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Very degraded Peat Cutting, up to 0.4m tall and c12m long.

Asset/Event Number	379.2
Asset/Event Name	Peat cutting, Coire an Uisgeachaidh
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	283691
Northing	906712
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Very degraded Peat Cutting, up to 0.4m tall and c12m long.

Asset/Event Number	380
Asset/Event Name	Bridge, Carrol

Type of Asset/Event	Bridge
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	284580
Northing	907188
Council	Highland
Condition:	Good
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A bridge over the Carrol burn measuring 5m by 3.2m. The bridge has stepped concrete foundations either side of the bank with a flat wooden super structure across the top composed of large square beams, a single beam at either side delineating the course. No bridges are annotated here on the 1st or 2nd edition OS maps.

Asset/Event Number	381
Asset/Event Name	Peat cutting, Coire an Uisgeachaidh
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	283630
Northing	906482
Council	Highland
Condition:	Very Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under heather measuring 30m by 15m with banks 0.15m deep.

Asset/Event Number	382.1
Asset/Event Name	Clearance cairn, Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset

Section:	N/A
Easting	275615
Northing	901386
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A field clearance cairn partially under grass, measures 8.5m by 5m and stands 1m tall.

Asset/Event Number	382.2
Asset/Event Name	Clearance cairn, Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275648
Northing	901383
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A field clearance cairn partially under grass, measures 2m by 1m and stands 1m tall.

Asset/Event Number	382.3
Asset/Event Name	Clearance cairn, Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275638
Northing	901418
Council	Highland
Condition:	Degraded
Alignment:	NW/SE

Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A field clearance cairn partially under grass, measures 20m by 4m and stands 1m tall, situated against natural ridge of bedrock.

Asset/Event Number	382.4
Asset/Event Name	Clearance cairn, Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275656
Northing	901408
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A field clearance cairn partially under grass, measures 4.5m by 1m and stands 1m tall, situated against natural ridge of bedrock.

Asset/Event Number	382.5
Asset/Event Name	Clearance cairn, Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275645
Northing	901446
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A linear spread of field clearance material partially under grass, measuring 30m by 3.5m and standing 1m tall. It has been deposited against a small bare section of natural bedrock outcrop.

Asset/Event Number	382.6

Asset/Event Name	Clearance cairn, Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275625
Northing	901476
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn partially under grass, measuring 7m by 3m and stands 1.1m tall.

Asset/Event Number	382.7
Asset/Event Name	Building, Bad A' Chrasgaidh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275625
Northing	901500
Council	Highland
Condition:	Very Degraded
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible rectangular stone building measuring c20m 4.5m, much obscured by overlying clearance material. Possible walls stand 0.6m tall, spread 1.5m wide. Appears to be constructed onto a slight terrace of a small slope. Not depicted on historic mapping. See Asset 120 overall description.

Asset/Event Number	382.8
Asset/Event Name	Clearance cairn, Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00
HER Number	MHG11267
Status	Non-designated Heritage Asset

Section:	N/A
Easting	275629
Northing	901488
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn under moss, measuring 4m by 3m and standing 1.1m tall.

Asset/Event Number	383.1
Asset/Event Name	Clearance cairn, Morvich Burn
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275463
Northing	902064
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A probable prehistoric clearance cairn under grass and heather, measures 6m by 4m and stands 0.4m tall.

Asset/Event Number	383.2
Asset/Event Name	Clearance cairn, Morvich Burn
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275467
Northing	902050
Council	Highland
Condition:	Degraded
Alignment:	NE/SW

Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A probable prehistoric clearance cairn under grass and heather, measures 5 by 3m and stands 0.3m tall.

Asset/Event Number	384
Asset/Event Name	Clearance cairn, Cnoc Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 24
HER Number	MHG11115
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275353
Northing	902136
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn partially under grass, measures 2m by 1.7m and stands 1m tall.

Asset/Event Number	385.1
Asset/Event Name	Clearance cairn, Cnoc Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 24
HER Number	MHG11115
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275325
Northing	902018
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A probable prehistoric clearance cairn under heather, measures 4m in diameter and 1m tall.

Asset/Event Number	385.2

Asset/Event Name	Clearance cairn, Cnoc Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 24
HER Number	MHG11115
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275318
Northing	902052
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather, appearing as a prominent conical mound 6m in diameter and 1.2m tall.

Asset/Event Number	385.3
Asset/Event Name	Clearance cairn, Cnoc Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 24
HER Number	MHG11115
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275194
Northing	902141
Council	Highland
Condition:	Very Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn under grass, measures 3m by 2m and stands 0.5m tall.

Asset/Event Number	385.4
Asset/Event Name	Clearance cairn, Cnoc Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 24
HER Number	MHG11115
Status	Non-designated Heritage Asset

Section:	B1.2
Easting	275345
Northing	902062
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible prehistoric clearance cairn under heather. This possible cairn is not as prominent as its neighbours Assets 385.1 and 385.2, but is visible as a low mound measuring c5m in diameter and 0.4m tall.

Asset/Event Number	385.5
Asset/Event Name	Clearance cairn, Cnoc Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC70SE 24
HER Number	MHG11115
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275309
Northing	902084
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass, measuring 5m by 3m and standing 0.8m tall.

Asset/Event Number	386
Asset/Event Name	Building, Cnoc Bad A' Chrasgaidh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275272
Northing	902057
Council	Highland
Condition:	Very Degraded

Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone footings for a rectangular building under grass and heather. Measures c11m by 5m over walls. Walls themselves are a course of undressed boulders, likely forming the lower course of turf walls. Spread up to 2m. One possible internal partition and no discernible entrances. Not depicted on the 1st edition OS map. Situated in a slight saddle with hills rising to the N and S, overlooking the post-medieval settlement remains to the W.
Asset/Event Number	387.1
Asset/Event Name	Dyke, Bad A' Chrasgaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275200
Northing	902003
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Turf and stone dyke , 0.4m wide and 140m in length, up to 0.5m tall with 0.3m spread on either side

Asset/Event Number	387.2
Asset/Event Name	Enclosure, Bad A' Chrasgaidh
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 2; NC70SE 14
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275202
Northing	901951
Council	Highland
Condition:	Very Degraded
Alignment:	NW/SE
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible turf and stone enclosure, the turf having degraded fully away leaving only a loose setting of intermittent boulders delineating an irregular enclosure. Measures c. 15m by 7m and extends broadly NW/SE on a slight NW facing slope. Not depicted on the 1st edition OS map.
Asset/Event Number	387.3
Asset/Event Name	Building, Bad A' Chrasgaidh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275162
Northing	902070
Council	Highland
Condition:	Very Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Footings for long rectangular building measuring 22m by 5m over walls that stand 0.6m tall and spread up to 1.5m wide. Single partition within forming two internal compartments, both with entrance in the SW elevation. Situated on a raised terrace overlooking the broader terrace above the burn to the W. An enclosure (Asset 387.5) adjoins the NE elevation. Not depicted on the 1st edition OS map.
Asset/Event Number	387.4
Asset/Event Name	Structure, Bad A' Chrasgaidh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275157
Northing	902071
Council	Highland
Condition:	Very Degraded
Alignment:	ENE/WSW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A square drystone pen of structure extending off the SW elevation of building Asset 387.3, measuring 3m 4m with walls that stand 0.5m wide and 0.4m tall.
Asset/Event Number	387.5

Asset/Event Name	Enclosure, Bad A' Chrasgaidh
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275162
Northing	902081
Council	Highland
Condition:	Very degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Semi rectangular enclosure, Asset 387-5 attached on the northern side of main farmstead building 387-3. Walls measuring 0.5m wide and 0.4m tall

Asset/Event Number	387.6
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	
Northing	
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	VOID - number not assigned

Asset/Event Number	387.7
Asset/Event Name	Clearance cairn, Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 2; NC70SE 14
HER Number	MHG11267
Status	Non-designated Heritage Asset

Section:	B1.2
Easting	275209
Northing	901942
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small spread of field clearance next to enclosure (Asset 387.2). The stone has been mounded on a natural outcrop of stone and stands 1.3m tall and extends somewhat in an arc of 5m.

Asset/Event Number	387.8
Asset/Event Name	Clearance cairn, Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 2; NC70SE 14
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275185
Northing	901942
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small clearance cairn with bare stone visible under grass, measures 4m by 3m and stands 1m tall.

Asset/Event Number	387.9
Asset/Event Name	Enclosure, Bad A' Chrasgaidh
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275142
Northing	901988
Council	Highland
Condition:	Very Degraded
Alignment:	N/S

Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible very degraded turf and stone enclosure under grass, turfs have fully degraded leaving only some stone boulders forming a rough setting, with clusters at corners where the turf would be weaker. Encloses a small area 11m by 6m over walls. Not depicted on the 1st edition OS map.
Asset/Event Number	387.10
Asset/Event Name	Dyke, Bad A' Chrasgaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275118
Northing	902030
Council	Highland
Condition:	Very degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Very degraded series of what were likely stone and turf dykes with the turf element now very degraded so only a line of intermittent boulders is visible. Situated near the structures adjacent to Tower 260. Extends on the E side of the low drumlin the tow
Asset/Event Number	387.11
Asset/Event Name	Structure, Bad A' Chrasgaidh
Type of Asset/Event	Other
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275165
Northing	902060
Council	Highland
Condition:	Very Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Possible entranceway for the enclosure dyke (Asset 387.10), formed by a setting of stones revetted into the ground and defining a passage c1m wide and 4m long through the dyke and towards the building (Asset 387.3).
Asset/Event Number	387.12

Asset/Event Name	Clearance cairn, Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275118
Northing	901971
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large probable prehistoric clearance cairn under heather. Stands as a prominent mound measuring 10m by 5m and 0.9m tall.

Asset/Event Number	387.13
Asset/Event Name	Enclosure, Bad A' Chrasgaidh
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275123
Northing	901934
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A square shaped enclosure c14m by 14m with drystone walls that stand 0.6m tall and 0.8m wide. Not depicted on the 1st edition OS map.

Asset/Event Number	387.14
Asset/Event Name	Track, Bad A' Chrasgaidh
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 14.00; NC70SE 55.00
HER Number	MHG11267; MHG28537
Status	Non-designated Heritage Asset

Section:	B1.2
Easting	275063
Northing	901962
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A reluctant track under grass, visible as a depression and heading SW up hill to Asset 387. c3m wide.

Asset/Event Number	387.15
Asset/Event Name	Building, Bad A' Chrasgaidh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275152
Northing	902023
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone footings for a rectangular building measuring c21m by 4-6m under grass and bracken with boulder-defined walls that stand 0.6m wide and 0.7m tall. Two possible internal partitions forming three compartments, but difficult to discern in the vegetation. Possible entranceway on NE side. Not depicted on the 1st edition OS map.

Asset/Event Number	387.16
Asset/Event Name	Building, Bad A' Chrasgaidh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275048
Northing	902111
Council	Highland
Condition:	Degraded

Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone footings for a rectangular building under tall bracken and grass, measuring 12m by 4m with walls generally measuring 0.5m wide and 0.4m tall, but the SW end wall measures 0.8m wide and 1.1m tall. Possible entrance sin the NW and SE elevations. No internal partitions visible. Not depicted on the 1st edition OS map.
Asset/Event Number	387.17
Asset/Event Name	Enclosure, Bad A' Chrasgaidh
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275041
Northing	902121
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Rectangular Enclosure attached onto associated farmstead 287-16. 0.8m wide and 0.6m tall.

Asset/Event Number	388.1
Asset/Event Name	Dyke, Bad A' Chrasgaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	274895
Northing	901957
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone and turf dyke under grass, extending c20m long, stands c0.6m tall and spread 1m wide. Not depicted on historic maps.

Asset/Event Number	388.2
Asset/Event Name	Structure, Allt Bad a' Chrasgaidh
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	274890
Northing	901936
Council	Highland
Condition:	Very degraded
Alignment:	NE/SW
Importance:	Negligible/Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Footings for a possible rectangular building under tall bracken and grass, measuring 18m by 4m. Walls not easily discernible but vegetation change suggests the structure's presence. Not depicted on the 1st edition OS map.

Asset/Event Number	388.3
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	274840
Northing	902019
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small spread of stone c2m by 2m and 0.3m tall.

Asset/Event Number	388.5
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	N/A
Easting	
Northing	
Council	
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	VOID - number not assigned

Asset/Event Number	388.6
Asset/Event Name	Enclosure, Allt Bad a' Chrasgaidh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	274825
Northing	902075
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Footings for a rectangular building under tall heather and grass, measuring 8m by 4m over walls. Walls stand 0.6m tall and spread 1m wide and are composed of larger boulders as lower courses, suggesting a turf component may have been used above. Not depicted on the 1st edition OS map.

Asset/Event Number	388.7
Asset/Event Name	Dyke, Bad A' Chrasgaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	274846
Northing	902056
Council	Highland

Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone and turf dyke, a small length extending between correlate with aerial borders only possible for a turf and stone wall. Meets building and continues

Asset/Event Number	388.8
Asset/Event Name	Dyke, Bad A' Chrasgaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	274811
Northing	902075
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone and turf dyke under heather and grass, c21m long. Up to 0.6m tall, spread 0.7m wide. Not depicted on historic maps.

Asset/Event Number	388.9
Asset/Event Name	Enclosure, Allt Bad A Chrasgaidh
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	274788
Northing	901941
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Drystone dyke partly under grass, stands to 0.5m tall and spread up to 2m wide, forming an irregularly-shaped enclosure. A smaller rectangular pen is located in the SW corner, measuring 10m by 4m over walls.

Asset/Event Number	388.10
Asset/Event Name	Building, Allt Bad a' Chrasgaidh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	274735
Northing	902005
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone footings for a T-shaped building, measuring c10m by 4m E/W with a central projection measuring c5m by 5m on the S elevation. Walls spread c0.8m wide and stand 0.4m tall. Not depicted on historic maps.

Asset/Event Number	388.11
Asset/Event Name	Building, Allt Bad A Chrasgaidh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	274718
Northing	901984
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Footings for a rectangular building under grass, some stone evident. Measures 5m by 2.5m over walls with walls 0.4m tall. Entrance not discernible. Not depicted on the 1st edition OS map.

Asset/Event Number	389
Asset/Event Name	Hut circle, Morvich burn

Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	MHG9440
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275682
Northing	901909
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under heather measuring c10m in diameter over banks which are spread up to 1m wide and standing 0.6m tall. A possible entrance lies in the S quarter. https://her.highland.gov.uk/Monument/MHG9440 On the W edge of a small contemporary field system, well marked by stone clearance heaps, and contained in the E by a field wall, is a hut circle. There is a later deserted settlement just to the S [Asset 122 group], see NC70SE 2. The hut measures 7.5m in diameter within a wall composed of an inner face of contiguous slabs on edge, backed by rubble, with intermittent outer facing stones indicating a wall thickness of 1.4m widening to 2.0m at the entrance, 0.6m wide, in the S. Visited by OS (J M) 31 July 1975.

Asset/Event Number	390.1
Asset/Event Name	Peat cutting, Allt Strath Lunndaidh
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	276924
Northing	902251
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small area of peat cutting under grass and moss and heather. the banks are 0.3m deep. Disused.

Asset/Event Number	390.2
Asset/Event Name	Peat cutting, Allt Strath Lunndaidh
Type of Asset/Event	Peat cutting

Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	277005
Northing	902346
Council	Highland
Condition:	Very Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Area of peat cutting under heather and grass measuring 30m by 20m and 0.3m deep banks.

Asset/Event Number	390.3
Asset/Event Name	Peat cutting, Allt Strath Lunndaidh
Type of Asset/Event	Peat cutting
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	277135
Northing	902376
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large area of shallow peat cutting has been undertaken along a broad flat area between hillocks but looks like it may be related to drainage activity rather than the recovery of peat as the stream inn the centre has been augmented by metal slides. Corre

Asset/Event Number	391.1
Asset/Event Name	Enclosure, SW of Coire Cnoc na Gamhna
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG59240
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	277454

Northing	902481
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A circular enclosure under heather and grass of c45m diameter and comprising a stone and turf dyke measuring 0.5m tall and spread up to 1m wide, but poorly preserved along the S side where a small stream runs through the interior. Not depicted on the 1st edition OS map.

Asset/Event Number	391.2
Asset/Event Name	Track, Coire Cnoc na Gamhna
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG59242
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	277460
Northing	902527
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under heather and moss. Dyke stands up to 0.5m tall and spread up to 2m wide. Forms a large enclosure around the settlement remains on a SE facing slope, the dyke has been revetted into the slope on its SE most side.

Asset/Event Number	391.3
Asset/Event Name	Dyke, Coire Cnoc na Gamhna
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG59242
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	277553
Northing	902539
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under heather and moss. Dyke stands up to 0.5m tall and spread up to 2m wide. Forms a large enclosure around the settlement remains on a SE facing slope, the dyke has been revetted into the slope on its SE most side.
Asset/Event Number	391.4
Asset/Event Name	Building, SW of Coire Cnoc na Gamhna
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG59240
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	277549
Northing	902549
Council	Highland
Condition:	Very Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Footings for a rectangular building under heather and grass which obscured visibility. No visible internal partitions. Walls spread 0.5m wide and stand 0.3m tall and a possible entrance in the NW and NE corners. Not depicted on the 1st edition OS map.
Asset/Event Number	391.5
Asset/Event Name	Building, SW of Coire Cnoc na Gamhna
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG59240
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	277565
Northing	902560
Council	Highland
Condition:	Very Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Footings for a rectangular building under grass which obscured visibility. Walls spread 0.6m wideband stand 0.5m tall, with the NW end standing 0.9m tall. No internal partitions visible due to vegetation. Not depicted on the 1st edition OS map.
Asset/Event Number	391.6
Asset/Event Name	Kiln, SW of Coire Cnoc na Gamhna

Type of Asset/Event	Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG59240
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	277574
Northing	902581
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible degraded kiln visible as a drystone circular structure c3m in diameter under moss and grass set against the SW-facing slope. Walls stand 0.7m tall and spread perhaps 0.7m wide and flue channel extends NW . Not depicted on the 1st edition OS map.

Asset/Event Number	391.7
Asset/Event Name	Platform, Coire Cnoc na Gamhna
Type of Asset/Event	Platform
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	MHG59242
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	277588
Northing	902663
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small slightly projecting terrace or partially revetted structure footing of likely stone and turf, but all under grass and no turf visible, occupying the slope above the post-medieval settlement remains for the rest of Asset 390. The flat area of the platform forms a rectangular shape some 6m by 3.5m, with the build up fanning around this. Uncertain function.

Asset/Event Number	391.7
Asset/Event Name	Platform, SW of Coire Cnoc na Gamhna
Type of Asset/Event	Platform
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG59242
Status	Non-designated Heritage Asset

Section:	B1.2
Easting	277589
Northing	902663
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small slightly projecting terrace or partially revetted structure footing of likely stone and turf, but all under grass and no turf visible, occupying the slope above the post-medieval settlement remains for the rest of Asset 390. The flat area of the platform forms a rectangular shape some 6m by 3.5m, with the build up fanning around this. Uncertain function.
Asset/Event Number	391.8
Asset/Event Name	Building, Coire Cnoc na Gamhna
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG59242
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	277556
Northing	902571
Council	Highland
Condition:	Very degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Possible footings for a building, heavily obscured by dense heather but some stone and turf bank visible under grass at the NW end. Dimensions are difficult to discern as a result, but potentially somewhat rectangular in form with the visible bank standi
Asset/Event Number	391.9
Asset/Event Name	Building, SW of Coire Cnoc na Gamhna
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG59240
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	277595
Northing	902578
Council	Highland
Condition:	Degraded

Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Footings for a stone square building or structure under tall heather and grass, measuring 10m by 10m with walls that stand 0.6m wide and between 0.2-0.4m tall. Possible entrance on the W side.

Asset/Event Number	392
Asset/Event Name	Peat cutting, SW of Coire Cnoc na Gamhna
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	277697
Northing	902753
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An L-shaped area of peat cutting 25m by 25m under grass with depths generally c0.3m, but a large peat crevice has formed on the SE side over 1.5m deep and may represent an area where peat was quarried. Likely related to the settlement Asset 391 to the S.

Asset/Event Number	393.1
Asset/Event Name	Clearance cairn, Cnoc an t-Salachaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	276636
Northing	902383
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 7m by 5m and stands 1.3m tall on the down slope side to the SW.

Asset/Event Number	393.2
Asset/Event Name	Clearance cairn, Cnoc an t-Salachaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	276624
Northing	902392
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible prehistoric clearance cairn under heather, measures c3m in diameter and stands 0.7m tall.

Asset/Event Number	394
Asset/Event Name	Mill (possible), Morvich Burn
Type of Asset/Event	Mill
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275953
Northing	902067
Council	Highland
Condition:	Fair
Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A Z-shaped stone building under moss and heather, measuring c10m by 6m and situated over the Morvich burn. The building is composed of drystone walls standing up to 1.2m tall and 0.6m wide along N and W sides, and 0.6m tall and wide on the S and E side. Incorporates a large bare rock into the wall at the NW corner and an inlet in the N wall to allow the water to flow through. The stream, labelled as the Morvich Burn on OS mapping, diverges from a lrger stream to the north. It is abnormally straight and may be an augmented lade though no stone was observed due to dense heather vegeation. A probable mill. The building is not depicted on historic mapping.

Asset/Event Number	395.1
Asset/Event Name	Dyke, Bad A' Chrasgaidh
Type of Asset/Event	Dyke

Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	276087
Northing	902272
Council	Highland
Condition:	Very degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A degraded stone and turf dyke under heather and grass and bracken. Difficult to follow on the ground. Where visible the bank stands about 0.4m tall and spread up to 1m wide. Possibly forming a small network of dykes set in a small floodplain around the Morvich burn. Not on historic mapping.

Asset/Event Number	395.2
Asset/Event Name	Dyke, Bad A' Chrasgaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	276034
Northing	902239
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A degraded stone and turf dyke under heather and grass and bracken. Difficult to follow on the ground. Where visible the bank stands about 0.4m tall and spread up to 1m wide. This length abuts a natural rock face on its SE side which forms the natural continuation of the boundary to Asset 395.1. Not on historic mapping.

Asset/Event Number	396
Asset/Event Name	Structure, Bad A' Chrasgaidh
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2

Easting	275804
Northing	902194
Council	Highland
Condition:	Very Degraded
Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular shaped possible pen or small building, only the ephemeral footings of a few intermittent boulders remain under heather and grass. Measures 7m by 5m over the boulder line. Not on historic mapping.

Asset/Event Number	397
Asset/Event Name	Dyke, Bad A' Chrasgaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 56
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275655
Northing	902215
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A turf and stone dyke under grass and heather. Dyke stands to a height of 0.7m and spread up to 1.5m wide, c75m long but continues outwith survey corridor to the NE and NW and has been breached by the existing track. Not depicted on historic OS maps. See Asset 122 for HER description.

Asset/Event Number	398
Asset/Event Name	Dyke, Bad A' Chrasgaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 56
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275655
Northing	902116
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A revetment dyke of stone and turf for the existing track, built up on the W side. Stands up to 1.3m tall. See Asset 120 overall description. Not depicted on historic mapping.

Asset/Event Number	399
Asset/Event Name	Dyke, Bad A' Chrasgaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SE 56
HER Number	MHG11267
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275654
Northing	901463
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Remnants of a possible stone and turf dyke standing 1m tall and spread up to 1.2m wide, consisting of a dyke element of stone along the NW/SE extent, and a cut/revetted area along the NE/SW, and petering out as indicated in the survey at a length of c39m. The dyke element appears to be stone and turf and may augment a ridge of natural bedrock where clearance has been deliberately deposited in some areas but on the whole it appears to have a more earthen component. More of a revetment along the NE extent. Also see Asset 120 overall description. Not depicted on historic mapping.

Asset/Event Number	402
Asset/Event Name	Dyke, Loch Salachaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275483
Northing	903668
Council	Highland
Condition:	Very degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Dyke composed mainly of turf and occasional large stones, c100m long, 1m Wide and 0.4m tall. Degraded with many stones robbed.

Asset/Event Number	403.1
Asset/Event Name	Peat cutting, Loch Salachaidh
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275204
Northing	903527
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of shallow peat cutting under grass and dis-used. 0.3m deep.

Asset/Event Number	403.2
Asset/Event Name	Peat cutting, Loch Salachaidh
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275204
Northing	903565
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small area of shallow peat cutting under grass and dis-used, 0.3m deep. No photo.

Asset/Event Number	403.3
Asset/Event Name	Peat cutting, Loch Salachaidh
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A

HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275251
Northing	903573
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of shallow peat cutting under grass and dis-used. 0.3m deep. No photo.

Asset/Event Number	404
Asset/Event Name	Waymarker cairn, Cnoc Bad A' Chrasgaidh
Type of Asset/Event	Cairn
Date and/or Period	Post-medieval/Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275268
Northing	903417
Council	Highland
Condition:	Fair
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A triangular boulder 0.6m tall and 1m long, 0 4m wide, has been set upright on a small stone outcrop forming a very visible waymarker on the crest of the hill when approached from the west. Boulder is otherwise natural and not dressed in any fashion.

Asset/Event Number	405
Asset/Event Name	Clearance cairn, Cnoc Bad A' Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275220
Northing	903110
Council	Highland

Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass. Measures 3m by 2.5m and stands 0.6m tall.

Asset/Event Number	406
Asset/Event Name	Peat cutting, Cnoc Bad A' Chrasgaidh
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275035
Northing	902946
Council	Highland
Condition:	Very Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large area of peat cutting under grass and heather, c300m by 300m but extends beyond limit of the survey corridor, with banks 0.3m deep. Extends across a broad low valley. Dis-used.

Asset/Event Number	408
Asset/Event Name	Dyke Cnoc Bad a' Chrasgaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275179
Northing	903068
Council	Highland
Condition:	Very degraded
Alignment:	NW/SE
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone and turf dyke under grass, measuring c20m long, 0.5m wide with 1m spread and composed of mainly turf and occasional large stone, appeared to peter out to the NW and SE. May have been constructed as a flood-defence or augmentation to the small watercourse to the SW. Not depicted on historic mapping. OS. 1879. Sutherland CIV, Surveyed: 1873-4, Published: 1879. OS. 1907. Sutherland CIV, Surveyed: 1904, Published: 1907.
Asset/Event Number	409
Asset/Event Name	Hut circle, Cnoc Bad A' Chrasgaidh
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275114
Northing	903305
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. The possible very ephemeral remains of a hut circle under grass, c10m in diameter. The banks are very poorly defined and stand no taller than 0.2m tall and the spread is perhaps 1 5m. Some stones visible in a small portion. Entrance not discernible.

Asset/Event Number	410
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275337
Northing	902885
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible prehistoric clearance cairn visible as a mound under heather and grass, measures 4m by 3m and stands 0.7m tall.

Asset/Event Number	411
Asset/Event Name	Enclosure, Allt Bad A' Chrasgaidh
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274801
Northing	902688
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small turf and stone enclosure measuring 14m NE/SW by 12m over banks, irregular in plan, with a smaller rectangular pen measuring c8m NW/SE by 4m within the NW corner. The banks stands to 0.8m tall and spread up to 1m wide. Situated on a slight NW-facing slope. Not depicted on historic mapping. OS. 1879. Sutherland CIV, Surveyed: 1873-4, Published: 1879. OS. 1904. Sutherland CIV, Surveyed: 1904, Published: 1907.

Asset/Event Number	411
Asset/Event Name	Peat cutting. Allt Bad A Chrasgaidh
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	275070
Northing	902602
Council	Highland
Condition:	Very Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting measuring 40m by 30m and with banks 0.3m deep. Dis-used.

Asset/Event Number	413.1
Asset/Event Name	Enclosure, Allt Bad A' Chrasgaidh
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval

Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274765
Northing	902712
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A degraded turf and stone dyke under heather and grass, forming a large enclosure c110m wide and at least c180m long NE/SW, but continues beyond the survey corridor to the SW. Stands up to 0.5m tall and spread up to 1.5m wide. Encloses an area of broadly improved ground containing building Asset 414, a structure Asset 415, an enclosure Asset 412, and an additional segment of dyke Asset 413.2. Not depicted on historic mapping. OS. 1879. Sutherland CIV, Surveyed: 1873-4, Published: 1879. OS. 1904. Sutherland CIV, Surveyed: 1904, Published: 1907.
Asset/Event Number	413.2
Asset/Event Name	Dyke, Allt Bad A' Chrasgaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274769
Northing	902700
Council	Highland
Condition:	Very degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small section of stone and turf dyke under heather and grass, the extent of which is difficult to determine due to the vegetation. The dyke stands 0.5m at its tallest and spread up to 2m wide, possibly c17m long. Not depicted on historic mapping. OS. 1879. Sutherland CIV, Surveyed: 1873-4, Published: 1879. OS. 1904. Sutherland CIV, Surveyed: 1904, Published: 1907.
Asset/Event Number	414
Asset/Event Name	Building, Allt Bad A' Chrasgaidh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	N/A
Easting	274833
Northing	902685
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. The degraded stone footings of a long rectangular building appearing as drystone walls under moss and grass. Measures 14m by 4m over walls, which stand tallest at the corners to a height of 0.9m but have been robbed to the ground in some sections. No partitions visible and an entrance is not clearly discernible. Not depicted on historic mapping. OS. 1879. Sutherland CIV, Surveyed: 1873-4, Published: 1879. OS. 1904. Sutherland CIV, Surveyed: 1904, Published: 1907.
Asset/Event Number	415
Asset/Event Name	Structure, Allt Bad A' Chrasgaidh
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	274791
Northing	902680
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone footings for a structure under bracken and grass, measuring 4.5m by 2.5m. Difficult to discern form due to vegetation, but may be a small pen considering the proximity to the enclosure (Asset 411). Not depicted on historic mapping. OS. 1879. Sutherland CIV, Surveyed: 1873-4, Published: 1879. OS. 1904. Sutherland CIV, Surveyed: 1904, Published: 1907.
Asset/Event Number	416
Asset/Event Name	Peat cutting, Allt Bad A' Chrasgaidh
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274811

Northing	902613
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of shallow peat cutting 50m by 30m, with a peat bank between the two segments measuring less than 1m wide and 0.5m tall an. The entirety is dis-used and under grass. Likely associated with the small settlement to the NW (Assets 412-414). Two little clearance cairns Assets 116.30 and 116.6 stand within this but are likely prehistoric in date, associated with the cairn field further SE.
Asset/Event Number	417
Asset/Event Name	Sheepfold, Allt Bad a' Chrasgaidh
Type of Asset/Event	Sheepfold
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274747
Northing	902469
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A circular enclosure 19m in diameter and constructed from a drystone wall. The wall is degraded in parts but original height is retained in others as 1.6m, with a cap of turf, and 0.75m thick. The walls are double-skinned with large subrounded stones. The entrance measures 1.5m wide and is located in the SW quarter. The sheepfold is depicted on the 1st and 2 edition OS maps and labelled as such. OS. 1879. Sutherland CIV, Surveyed: 1873-4, Published: 1879. OS. 1904. Sutherland CIV, Surveyed: 1904, Published: 1907.
Asset/Event Number	418.1
Asset/Event Name	Building, Allt Bad A Chrasgaidh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275029
Northing	902117
Council	Highland

Condition:	Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone footings for a rectangular building under grass and bracken. Measures c17m long and 5m wide over walls, which stand to a height of 0.4m tall. Stone concentrated at the ends of the building, suggesting a turf component likely sat atop this. Entrances and partitions not discernible. Not depicted on historic mapping. OS. 1879. Sutherland CIV, Surveyed: 1873-4, Published: 1879. OS. 1904. Sutherland CIV, Surveyed: 1904, Published: 1907.
Asset/Event Number	418.2
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	
Northing	
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	VOID - number not assigned

Asset/Event Number	418.3
Asset/Event Name	Dyke, Allt Bad a' Chrasgaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	274829
Northing	902135
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass and bracken, the main portion of which extends some c350m long in a curvilinear fashion from E to W, with smaller branches extending to the NW and SE. Dyke stands c0.3-0.7m tall and spread up to 2m wide. Connects the corn-drying kiln Asset 418.5 and building Asset 387.6, and then continues from the building Asset 418.1 to enclosure 418.6, and then proceeds SW. Not depicted on historic mapping. OS. 1879. Sutherland CIV, Surveyed: 1873-4, Published: 1879. OS. 1904. Sutherland CIV, Surveyed: 1904, Published: 1907.
Asset/Event Number	418.4
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	
Date and/or Period	
Listing No./NRHE Number	
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	
Northing	
Council	Highland
Condition:	N/A
Alignment:	N/A
Importance:	N/A
Description	VOID - number not assigned

Asset/Event Number	418.5
Asset/Event Name	Corn drying kiln, Allt Bad A Chrasgaidh
Type of Asset/Event	Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	275069
Northing	902119
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A corn drying kiln partially under grass and bracken, partially built into the S-facing slope of the hill. Measures 5m in diameter over walls which stand to a height of c1m, with a bowl measuring 3m in diameter. A small squarish platform extending 4m out from the kiln wall and 2.5m wide. The flue opens to the SSW, with the lintel visible, but has been infilled with stone. Not depicted on

	historic mapping. OS. 1879. Sutherland CIV, Surveyed: 1873-4, Published: 1879. OS. 1904. Sutherland CIV, Surveyed: 1904, Published: 1907.
Asset/Event Number	418.6
Asset/Event Name	Enclosure, Allt Bad A Chrasgaidh
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC70SW 34.00
HER Number	MHG10630
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274988
Northing	902126
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An enclosure under grass and bracken constructed from a stone and turf dyke, measuring 18m by 12m with the dyke itself standing 0.5m tall and spread 1m wide. Not depicted on historic mapping. OS. 1879. Sutherland CIV, Surveyed: 1873-4, Published: 1879. OS. 1904. Sutherland CIV, Surveyed: 1904, Published: 1907.
Asset/Event Number	419
Asset/Event Name	Dyke, Allt Bad a' Chrasgaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	274758
Northing	902109
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass, stands 0.4m tall and spread up to 1m wide, measuring c150m long. Not depicted on historic mapping. OS. 1879. Sutherland CIV, Surveyed: 1873-4, Published: 1879. OS. 1904. Sutherland CIV, Surveyed: 1904, Published: 1907.
Asset/Event Number	420
Asset/Event Name	Dyke, Allt Bad a' Chrasgaidh

Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	274849
Northing	902079
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone and turf dyke under grass, forming somewhat of an L-shape in plan, open to the SW. The E-W aligned portion comprises predominantly stone and stands 0.4m tall and 0.6m wide, while the N-S aligned portion is appears mostly as a turf bank, 0.5m tall and spread 0.7m wide. Not depicted on historic mapping. OS. 1879. Sutherland CIV, Surveyed: 1873-4, Published: 1879. OS. 1904. Sutherland CIV, Surveyed: 1904, Published: 1907.
Asset/Event Number	421
Asset/Event Name	Enclosure, Allt Bad a' Chrasgaidh
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	274846
Northing	902086
Council	Highland
Condition:	Very degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A probable enclosure or pen of stone partially under grass, measuring c10m by 4m. Walls stand c0.3-0.6m tall and spread c0.7m wide, composed of large drystone boulders that may be the sole remnants of a turf and stone wall. Not depicted on historic mapping. OS. 1879. Sutherland CIV, Surveyed: 1873-4, Published: 1879. OS. 1904. Sutherland CIV, Surveyed: 1904, Published: 1907.
Asset/Event Number	422
Asset/Event Name	Clearance cairn, Allt Bad A Chrasgaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A

HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	274840
Northing	902056
Council	Highland
Condition:	Very Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and moss. Measures 6m by 3m and stands 0.7m tall.

Asset/Event Number	423
Asset/Event Name	Track, Glen Loth
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293534
Northing	913664
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Relict track under grass, c400m long and c2.5m wide, and forming slight holloway. Leads to farmstead Asset 211 from the Glen Loth road to the SW. Depicted on the 1st and 2nd edition OS maps. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.

Asset/Event Number	424
Asset/Event Name	Dyke, Glen Loth
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293474
Northing	913549

Council	Highland
Condition:	Fair
Alignment:	WNW/ESE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under moss, stands 0.7m tall and spread 1.1m wide. C70m long. Not depicted on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.

Asset/Event Number	425
Asset/Event Name	Dyke, Glen Loth
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 50.00
HER Number	MHG54757
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293590
Northing	913763
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Turf and stone dyke under grass and bracken, measuring c170m long and stands 0.5-7m tall and spread up to 2m wide. Continues to the NE as Asset 211.7. Depicted on the 1st and 2nd edition OS maps, but there is an extension (c55m long) to the SE that then turns S that although extant is not present on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.

Asset/Event Number	426
Asset/Event Name	Dyke, Uaigh Bheag
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293768
Northing	913928
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A length of stone and turf dyke under grass standing 0.7m tall and spread up to 2m wide and 10m long. Peters out at either end. Not depicted on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.
Asset/Event Number	427
Asset/Event Name	Dyke, Uaigh Bheag
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293841
Northing	913970
Council	Highland
Condition:	Very degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A turf and stone dyke under bracken, c65m long, stands 0.6m tall and spread c2m wide, extent difficult to determine due to vegetation. Appears to possibly be flooding-related as it respects a lower shelf above the river and diminishes where the ground rises uphill. Not depicted on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.
Asset/Event Number	428.1
Asset/Event Name	Building, Uaigh Bheag
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 54.00
HER Number	MHG13174
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293904
Northing	914169
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone footings for a building under grass and bracken, measures c8m by 6m. Walls stand 0.6m tall and spread up to 1m wide. Entrance in NW elevation, centrally situated. Enclosure Asset 428.2 joins at the SW and NE corners. Not depicted on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.

Asset/Event Number	428.2
Asset/Event Name	Dyke, Uaigh Bheag
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 54.00
HER Number	MHG13174
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293908
Northing	914159
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A turf and stone dyke under grass, measuring c35m long, 0.6m tall and spread up to 1.5m wide, adjoining building 428.1 and a small branch of which likely formed a kale yard/garden. The dyke is partially revetted into the top of the NE break of slope on the terrace the building Asset 428.1 is situated on. Not depicted on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.

Asset/Event Number	428.3
Asset/Event Name	Corn drying kiln, Uaigh Bheag
Type of Asset/Event	Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 54.00
HER Number	MHG13174
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293926
Northing	914168
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A corn-dying kiln under grass and bracken, visible as stone with a slight depression. The kiln bowl measures 1.5m in diameter, and although vegetation conceals the heat box, slightly projecting walls suggest the flue is aligned to the SE. The kiln has been constructed into the SE-facing hill slope overlooking the Loth Burn, SE of building Asset 428.1. Not depicted on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.

Asset/Event Number	428.4
Asset/Event Name	Corn drying kiln, Uaigh Bheag

Type of Asset/Event	Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 54.00
HER Number	MHG13174
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293940
Northing	914175
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A probable corn-drying kiln under grass and bracken, revetted into the SE facing slope overlooking the Glen Loth Burn, very degraded and likely robbed out to construct the nearby better-preserved kiln (Asset 428.3). Similarly constructed into the SE facing hill slope and appears as a mound of stone some 4m by 4m with little other structural elements apparent but the SE wall. Not depicted on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.
Asset/Event Number	428.5
Asset/Event Name	Clearance cairn, Uaigh Bheag
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 54.00
HER Number	MHG13174
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293961
Northing	914168
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large mound of clearance material extending 7m by 9m and 1.3m tall, under grass and bracken, presumed clearance cairn. Not depicted on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.
Asset/Event Number	428.6
Asset/Event Name	Dyke, Uaigh Bheag
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 54.00

HER Number	MHG13174
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293935
Northing	914144
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A 22m long length of stone and turf dyke under grass and bracken. Dyke stands 0.7m tall and spread up to 1.5m.wide, possibly used as a flood-defence or augmentation for the Loth Burn, along which it runs. The S end potentially continues into tall bracken and Could not be discerned fully. Not depicted on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.
Asset/Event Number	430
Asset/Event Name	Dyke, Uaigh Bheag
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 54.00
HER Number	MHG13174
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293877
Northing	914211
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Turf and stone dyke under bracken and heather, c60m long. Stands 0.5m tall and spread up to 1m wide, respecting the base of the hill on its N side. Not depicted on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.
Asset/Event Number	431
Asset/Event Name	Dyke, Uaigh Bheag
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	294044

Northing	914328
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Turf and stone dyke under bracken and grass, enclosing a slope, stands 0.3-0.5m tall and spread up to 1m wide. C115m long. Not depicted on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.
Asset/Event Number	432
Asset/Event Name	Dyke, Uaigh Bheag
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG13174
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293944
Northing	914366
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Turf and stone dyke under bracken and grass. C195m long. Stands 0.5m tall and spread up to 1m. Crosses dyke Asset 433. Not depicted on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.
Asset/Event Number	433
Asset/Event Name	Dyke, Uaigh Bheag
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG13174
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293928
Northing	914350
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Turf and stone dyke under bracken and grass, at least c200m long, stands 0.4m tall and spread 1m wide. Not depicted on historic mapping. Continues N outwith survey corridor but diminishes as shown at its S extent. Not depicted on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.
Asset/Event Number	434
Asset/Event Name	Clearance cairn, Uaigh Bheag
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG13174
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293924
Northing	914306
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn under moss and bracken, measures 6m in diameter and stands 0.8m tall.

Asset/Event Number	435
Asset/Event Name	Hut circle, Uaigh Bheag
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG13174
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293913
Northing	914317
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Small hut circle or enclosure under grass and bracken, measures c7m in diameter over banks which stand 0.7m tall and spread up to 2.5m. A possible entrance in the SW quarter.

Asset/Event Number	436

Asset/Event Name	Clearance cairn, Uaigh Bheag
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG13174
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293933
Northing	914330
Council	Highland
Condition:	Very Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn of possibly post-medieval date under bracken, measures 9 by 4m and stands 1m tall. Closely situated to dyke Asset 433.

Asset/Event Number	437
Asset/Event Name	Clearance cairn, Uaigh Bheag
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG13174
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293938
Northing	914317
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn under moss and bracken, measures 5m in diameter and stands 0.8m tall.

Asset/Event Number	438
Asset/Event Name	Dyke, Uaigh Bheag
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC91SW 54.00
HER Number	MHG13174
Status	Non-designated Heritage Asset

Section:	A1.5
Easting	293934
Northing	914186
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A very degraded stone and turf dyke under bracken extending along the rim of the terrace between Assets 412 and 428 remains. Dyke consists of intermittent boulders, likely originally contained a turf element and now degraded away. Stands 0.4m tall and spread up to 1.5m wide, c40m long. Not depicted on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.
Asset/Event Number	439.1
Asset/Event Name	Peat cutting, Uaigh Bheag
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	294109
Northing	914793
Council	Highland
Condition:	Very Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under grass and heather, measures 17m by 15m and 0.3m deep banks.

Asset/Event Number	439.2
Asset/Event Name	Peat cutting, Uaigh Bheag
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	294141
Northing	914822
Council	Highland

Condition:	Very Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of peat cutting under grass and heather, measures 45m by 32m and 0.5m deep banks.

Asset/Event Number	440
Asset/Event Name	Clearance cairn, Uaigh Bheag
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	MHG9934
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	294035
Northing	914660
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass, measures 6m by 5m and stands 0.4m tall.

Asset/Event Number	441
Asset/Event Name	Dyke, Loth Burn
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG19337
Status	Non-designated Heritage Asset
Section:	A1.5 (in access track corridor to section)
Easting	293621
Northing	912912
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A probable stone and turf and stone dyke c480m long, barely discernible below bracken. Stands c0.7m tall and spread up to 1m wide. No stone visible but can feel them underfoot. Breached by access track. Not depicted on historic mapping. OS. 1879. Sutherland, LXXXIX, Surveyed: 1871, Published: 1879. OS. 1907. Sutherland, LXXXIX, Surveyed: 1904, Published: 1907.
Asset/Event Number	442
Asset/Event Name	Structure, Glen Sletdale
Type of Asset/Event	Structure
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	MHG13173
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293605
Northing	912932
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible structure under grass and bracken, measuring 7m by 4.5m and appearing as a fairly level spread of stone with some corrugated iron also visible. A rectilinear building and small enclosure are depicted on the 1963 OS, but nothing is depicted on earlier historic mapping. The NRHE and HER record a township in this location based on 1st edition OS mapping, but the location appears to be wrong as there are no structures as described below in the listing present on the 1st edition OS map at this location, or on the later-mentioned 1963 OS map. OS. 1879. Sutherland LXXXIX, Surveyed: 1871, Published: 1879. OS. 1963. NC91 SW - A. Surveyed/Resurveyed: 1962, Published: 1963 https://highland.gov.uk/monument/MHG19337 A township comprising four unroofed buildings, a sheepfold, an enclosure, an area of cultivation, and a head dyke, is depicted on the 1st edition of the OS 6-inch map (Sutherland 1879, sheet lxxxix). One roofed and nine unroofed buildings, two of which are marked as ruins, two enclosures, a sheepfold, field walls and a head-dyke, are shown on the current edition of the OS:10560 map (1963). Information from the RCAHMS (SAH) 16 October 1995.
Asset/Event Number	443.1
Asset/Event Name	Building, Coille Bad Mheasain
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG13173
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293240

Northing	913045
Council	Highland
Condition:	Very degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Possible footings of a building, heavily obscured by turf and bracken and discerned more so by feeling underfoot than visually. Rectangular in plan c18m long by 5m wide, with banks up to 0.3m tall and spread 1m wide, one possible internal partition. Situated atop a small terrace overlooking Glen Loth to the NE. One roofless structure or pen, on an alternate NW/SE orientation, is depicted on the 1st edition OS map, so may not relate to this structure. Falls within the HER extent for the Coille Bad Mheasain township. OS. 1879. Sutherland LXXXIX, Surveyed: 1871, Published: 1879. https://highland.gov.uk/monument/MHG13173 No description.
Asset/Event Number	443.2
Asset/Event Name	Corn-drying kiln, Coille Bad Mheasain
Type of Asset/Event	Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG13173
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293253
Northing	913060
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible corn-drying kiln under grass and bracken, measuring 7m in diameter and excavated into a NE-face slope with possible flue visible leading N. Drystone construction with a wall spread of c1m and standing to a height of 0.6m tall. Not depicted on the 1st edition OS map. Falls within the HER extent for the Coille Bad Mheasain township. OS. 1879. Sutherland LXXXIX, Surveyed: 1871, Published: 1879. https://highland.gov.uk/monument/MHG13173 No description.
Asset/Event Number	443.3
Asset/Event Name	Kiln barn, Coille Bad Mheasain
Type of Asset/Event	Kiln barn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG13173
Status	Non-designated Heritage Asset

Section:	N/A
Easting	293237
Northing	913163
Council	Highland
Condition:	Very degraded
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A kiln barn under bracken and grass has been constructed on the NE facing slight slope. Measures c20m long over walls and kiln, by 5m over walls. The kiln is located at the SW end higher up the hill than the rest of the building. Only a shallow depression is visible atop the mound, c4m in diameter. Not depicted on the 1st edition OS map. Falls within the HER extent for the Coille Bad Mheasain township. OS. 1879. Sutherland LXXXIX, Surveyed: 1871, Published: 1879. https://highland.gov.uk/monument/MHG13173 No description.
Asset/Event Number	443.4
Asset/Event Name	Pen, Coille Bad Mheasain
Type of Asset/Event	Pen
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG13173
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293233
Northing	913156
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small square shaped drystone pen c6m by 6m, open on the NE side and defined by large roughly dressed boulders up to 0.8m long set in a single course, forming the stone component of what was likely a stone and turf dyke. Likely a small kale yard or pen. Not depicted on the 1st edition OS map. Falls within the HER extent for the Coille Bad Mheasain township. OS. 1879. Sutherland LXXXIX, Surveyed: 1871, Published: 1879. https://highland.gov.uk/monument/MHG13173 No description.
Asset/Event Number	443.5
Asset/Event Name	Clearance cairn, Coille Bad Mheasain
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG13173

Status	Non-designated Heritage Asset
Section:	N/A
Easting	293232
Northing	913178
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn partially under grass and bracken, extending 6m by 4m and 0.3m tall. May be obscuring footings for a structure below. Not depicted on the 1st edition OS map. Falls within the HER extent for the Coille Bad Mheasain township. OS. 1879. Sutherland LXXXIX, Surveyed: 1871, Published: 1879. https://highland.gov.uk/monument/MHG13173 No description.
Asset/Event Number	443.6
Asset/Event Name	Dyke, Coille Bad Mheasain
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG13173
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293222
Northing	913198
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An arrangement of a low stone and turf dykes standing 0.4m tall and spread 2.5m wide forming a D shape, set almost against the dyke Asset 453, but not quite touching it. The D-shape measures c15m long by 10m wide, with a small section in the NW forming a little pen 5.5m E/WS by 3.5m N/S. Both are open to the W. Not depicted on the 1st edition OS map. Falls within the HER extent for the Coille Bad Mheasain township. OS. 1879. Sutherland LXXXIX, Surveyed: 1871, Published: 1879. https://highland.gov.uk/monument/MHG13173 No description.
Asset/Event Number	444
Asset/Event Name	Marker cairn, Coille Bad Mheasaina
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval/Modern
Listing No./NRHE Number	N/A
HER Number	MHG13173

Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293257
Northing	913049
Council	Highland
Condition:	Good
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small stone-built cairn, measuring 2m by 0.7m and standing 0.8m tall. The cairn is prominent and may be of modern date, possibly used as a marker or navigation cairn. Not depicted on the 1st edition OS map. Falls within the HER extent for the Coille Bad Mheasain township. OS. 1879. Sutherland LXXXIX, Surveyed: 1871, Published: 1879. https://highland.gov.uk/monument/MHG13173 No description.
Asset/Event Number	445
Asset/Event Name	Hut circle, Gable burn
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	NC91NW 10
HER Number	MHG9981
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	294575
Northing	915318
Council	Highland
Condition:	Degraded
Alignment:	Circular
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Asset not directly accessed during the survey as situated within an area of old woodland regeneration with relict mounding and pits that could not be crossed safely. The area is fairly prominent as a patch of heather, bracken and rushes opposed to the wetland grasses the North Tower 176 is located on. Https://highland.gov.uk/monument/MHG9981 (NC 9455 1531) Enclosure (NR) (now Hut 'A'). OS 6" map, (1964) An enclosure (A) was located during field investigation. Visited by OS (E G C) 4 June 1961. Situated at the foot of a W-facing hill slope are two hut circles ('A' and 'B'). 'A', positioned at NC 9457 1532, measures 11.5m SSE-NNW by 9.5m within a peat-covered wall spread to approximately 2.5m. Several inner and outer facing stones are visible in the E arc. Th entrance gap is in the SSE. 'B' positioned at NC 9462 1540 has a considerable silt overlay, with the centre in a marshy condition. It measures, internally NNW-SSE,12.0m by 11.0m. The entrance in the SSE is flanked on its W side by a possible portal stone. A few clearance heaps are scattered to the S and W of the huts, but no plots are discernible. Surveyed and revised at 1:10,560. Visited by OS (J B) 14 January 1976.

Asset/Event Number	446.1
Asset/Event Name	Possible shieling, Glen Sletdale
Type of Asset/Event	Shieling
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293065
Northing	913020
Council	Highland
Condition:	Very Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Footings of a possible shieling under grass and heather. The structure measures 6m by 4m over banks, which stand to 0.4m tall. No stone visible, and the NW side is degraded to ground level. Internally measures 4m by 1.5m. Situated on a gently declining slope. Not depicted on the 1st edition OS map. OS. 1879. Sutherland LXXXIX, Surveyed: 1871, Published: 1879.

Asset/Event Number	446.2
Asset/Event Name	Possible shieling, Glen Sletdale
Type of Asset/Event	Shieling
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293060
Northing	913023
Council	Highland
Condition:	Very degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A turf bank, possibly forming part of a shieling but truncated and disturbed by tree planting moulding. Bank stands 0.4m tall and spread 1.5m wide, 4m long, slight return to the NW. Not depicted on the 1st edition OS map. OS. 1879. Sutherland LXXXIX, Surveyed: 1871, Published: 1879.

Asset/Event Number	446.3
Asset/Event Name	Dyke, Glen Sletdale
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A

HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293054
Northing	913023
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An L-shaped segment of dyke c6m long under grass and likely disturbed by tree planting present. Dyke possibly constructed solely from turf, no stone visible. Stands 0.5m tall and spread 1.5m wide. Not depicted on the 1st edition OS map. OS. 1879. Sutherland LXXXIX, Surveyed: 1871, Published: 1879.
Asset/Event Number	447
Asset/Event Name	Dyke, Glen Sletdale
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293168
Northing	912887
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf and stone dyke under heather and grass, c40m long, and stands 0.6m tall and spread 1m wide. Not visible beyond either side of survey corridor, meets the E-W aligned modern EU-funded track on its S end. Not depicted on historic mapping. OS. 1879. Sutherland LXXXIX, Surveyed: 1871, Published: 1879.
Asset/Event Number	448
Asset/Event Name	Dyke, Glen Sletdale
Type of Asset/Event	Dyke
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	292939
Northing	912697

Council	Highland
Condition:	Fair
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Large stone and turf dyke under heather, c830m long and stands 0.7-1.3m tall and spread up to 4m wide. Runs parallel with modern EU-funded track and likely related to its construction. Not depicted on historic mapping.

Asset/Event Number	449
Asset/Event Name	Borrow pit, Glen Sletdale
Type of Asset/Event	Borrow pit
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293091
Northing	912823
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Borrow pit measuring 8m in diameter and 2m deep, partially under grass, likely used for the construction of the adjacent modern EU-funded track in recent times.

Asset/Event Number	450
Asset/Event Name	Enclosure, Glen Sletdale
Type of Asset/Event	Enclosure
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293048
Northing	912813
Council	Highland
Condition:	Very degraded
Alignment:	Circular
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Semi-circular enclosure, measuring 22m by 17m over the bank. Bank, likely of stone and turf construction, stands 0.4m tall and spread up to 1m wide. Enclosure banks are slight and covered in heather with west bank in particular quite ill-defined. Possible entrance on SE side. Not depicted on historic mapping. OS. 1879. Sutherland LXXXIX, Surveyed: 1871, Published: 1879.
Asset/Event Number	451
Asset/Event Name	Borrow pit, Glen Sletdale
Type of Asset/Event	Borrow pit
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293063
Northing	912793
Council	Highland
Condition:	Good
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Borrow pit measuring 6.6m in diameter and 2.2m deep, partially under grass and heather, likely used for the construction of the adjacent EU-funded track in recent times.

Asset/Event Number	452
Asset/Event Name	Standing stone, Glen Sletdale
Type of Asset/Event	Standing stone
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	292949
Northing	912822
Council	Highland
Condition:	Good
Alignment:	NA
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large buff coloured stone 1.1m tall, 0.5m wide and 0.5m thick, has been set upright within an area of young woodland regeneration plantation. It appears very "fresh", with no lichen or moss growth present. Recorded for posterity.

Asset/Event Number	453

Asset/Event Name	Dyke, Glen Sletdale
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG13173
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293261
Northing	913045
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under heather and grass, bisected by modern track. Stands 0.8m tall and spread up to 1.5m wide, this portion measures 35m long but it extends beyond the survey corridor to the N and S. The dyke is consistent with a head dyke depicted on the 1st edition OS map, the N extent of which falls within the HER extent for the Coille Bad Mheasain township. OS. 1879. Sutherland LXXXIX, Surveyed: 1871, Published: 1879. https://highland.gov.uk/monument/MHG13173 No description.

Asset/Event Number	454
Asset/Event Name	Clearance cairn, Glen Sletdale
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293343
Northing	913118
Council	Highland
Condition:	Very Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn under grass, measuring 2.5m by 1.8m and stands 0.6m tall.

Asset/Event Number	455
Asset/Event Name	Sheepfold, Coille Bad Mheasain
Type of Asset/Event	Sheepfold
Date and/or Period	Post-medieval

Listing No./NRHE Number	N/A
HER Number	MHG13173
Status	Non-designated Heritage Asset
Section:	N/A
Easting	293244
Northing	913265
Council	Highland
Condition:	Fair
Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large drystone sheepfold measuring 50m by 25m, two smaller pens in the N end measuring 19m by 7m and 12m by 5. Walls are drystone constructed and stand c1-1.5m tall and 0.8-1m wide. Main entrance in S end with smaller entrance in the N. The sheepfold is depicted on the 1st edition OS map and named 'Glenhouse Sheepfold'. Falls within the HER extent for the Coille Bad Mheasain township. OS. 1879. Sutherland LXXXIX, Surveyed: 1871, Published: 1879. https://highland.gov.uk/monument/MHG13173 No description.
Asset/Event Number	456.1
Asset/Event Name	Borrow pit, Glen Sletdale
Type of Asset/Event	Quarry
Date and/or Period	Post-medieval/modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293477
Northing	913352
Council	Highland
Condition:	Degraded
Alignment:	Circular
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Borrow pit c20m in diameter with mounded material (Asset 456.2) surrounding it, accessed from the Glen Loth road to the E. Appears modern in date.
Asset/Event Number	456.2
Asset/Event Name	Dyke, Glen Sletdale
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	A1.5
Easting	293476
Northing	913358
Council	Highland
Condition:	Fair
Alignment:	Circular
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Turf-covered bank/dyke 0.7m tall and 1m wide, c140m long, enclosing borrow pit (Asset 456.1) to the E, likely contemporary and of modern date.

Asset/Event Number	457
Asset/Event Name	Dyke, Beinn na Meilich
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	294998
Northing	916272
Council	Highland
Condition:	Very degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A low turf dyke under heather and grass standing 0.3m tall and spread 0.8m wide, adjacent to a small stream which might be artificial, possibly running along the former ditch used for construction. Extends c370m long and consistent with the parish boundary depicted on the 1st edition OS map between Loth and Kildonon. OS. 1879. Sutherland LXXXIX, Surveyed: 1871, Published: 1879.

Asset/Event Number	458
Asset/Event Name	Clearance cairn, Allt nan Tullachan
Type of Asset/Event	Clearance cairn
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	294820
Northing	915998
Council	Highland

Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A probable clearance cairn under heather and grass, measures 7m by 5m and 0.6m tall. Very isolated from post-medieval settlement remains so possibly prehistoric, date uncertain.

Asset/Event Number	459
Asset/Event Name	Mound, Garskelly
Type of Asset/Event	Mound
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	271214
Northing	898151
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A mound under heather, measuring 8m by 5m and standing 0.7m tall. Possibly a prehistoric clearance cairn but the asset is very isolated and only possible other asset (Asset 460) of similar appearance is over 100m S. A possible hut circle (Asset 462) lies over 300m to the E, but these are all situated on a N-facing slope that is not very conducive to agricultural activity, so there may be less remains in the vicinity as a result.

Asset/Event Number	460
Asset/Event Name	Mound, Garskelly
Type of Asset/Event	Mound
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	271195
Northing	898031
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A mound under heather, measuring 7m by 6m and standing 0.4m tall. Possibly a prehistoric clearance cairn but the asset is very isolated and only possible other asset (Asset 459) of similar appearance is over 100m N. A possible hut circle (Asset 462) lies over 300m to the E, but these are all situated on a N-facing slope that is not very conducive to agricultural activity, so there may be less remains in the vicinity as a result.
Asset/Event Number	461
Asset/Event Name	Dyke, Garskelly
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	271430
Northing	898085
Council	Highland
Condition:	Very degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A turf and stone dyke under grass and heather. The dyke is much degraded, standing to a height of 0.4m and spread up to 3.5m wide, c200m long. The W extent appears to be depicted on the 1st edition OS map. OS. 1879. Sutherland CIX. Surveyed: 1874, Published: 1879.
Asset/Event Number	462
Asset/Event Name	Hut circle, Garskelly
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	271626
Northing	898087
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible hut circle under heather and grass, measuring c10m in diameter over banks where are 1m wide and stand 0.3m tall, but dimensions are difficult to determine due to vegetation. A possible entrance lies in the SE quarter.
Asset/Event Number	463.1

Asset/Event Name	Dyke, Achtaduach
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	271852
Northing	898138
Council	Highland
Condition:	Fair
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A turf and stone dyke under grass and heather, stands 0.4m tall and spread up to 3m wide. Dyke runs c80m long along the N side of a relict track Asset 463.2; the two are likely contemporary. Both are consistent with a boundary shown on the 1st edition OS map. OS. 1879. Sutherland CIX. Surveyed: 1874, Published: 1879.
Asset/Event Number	463.2
Asset/Event Name	Track, Achtaduach
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	271959
Northing	898257
Council	Highland
Condition:	Very degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A relict track under grass and heather with an adjacent dyke Asset 463.1 flanking the N side. The track has formed a very slight holloway, and measures 3m wide at the base and tapers up to 5m wide at the top. C140m long. Both are consistent with a boundary shown on the 1st edition OS map. OS. 1879. Sutherland CIX. Surveyed: 1874, Published: 1879.
Asset/Event Number	464
Asset/Event Name	Mound, Achtaduach
Type of Asset/Event	Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272109
Northing	898235
Council	Highland
Condition:	Very Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Turf mound or possible clearance cairn under heather. Measures c9.5m by c4.5m and stands 0.7m tall.

Asset/Event Number	465
Asset/Event Name	Dyke, Achtaduach
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272206
Northing	898245
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A turf and stone dyke under heather, stands 0.5m tall and spread 1m wide. C30m recorded but appears to continue to the E beyond the survey corridor. Consistent with a field boundary shown on the 1st edition OS map. OS. 1879. Sutherland CIX. Surveyed: 1874, Published: 1879.

Asset/Event Number	466.1
Asset/Event Name	Building, Dalnamain
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272122
Northing	898437
Council	Highland

Condition:	Good
Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A timber constructed shed measuring 9m by 5m, with an open entrance 4m by 2m to the S. Walls stand c2.5m tall and gable ends c5m tall - dense surrounding vegetation prohibited direct access. The structure is roofed with corrugated iron sheets and surrounded by dense vegetation. First depicted on the 1959 OS map. OS. 1959. NH79NW - A. Surveyed / Revised: 1930 to 1959, Published: 1959
Asset/Event Number	466.2
Asset/Event Name	Pens, Dalnamain
Type of Asset/Event	Pen
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272127
Northing	898433
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A block of concrete pens measuring c8m by 5m with walls that stand up to 1.3m tall and 0.2m wide. Constructed from yellow sandstone with cement mortar and a cement harl. The side of the pens have been breached haphazardly through the wall, and the interior contains tall trees and vegetation that prohibited direct access. No structures depicted on the 1st or 2nd edition OS maps, but may form part of a series of pens first depicted on the 1969 OS map labelled as sheep pens. OS. 1969. NH79NW - A. Surveyed / Revised: 1966 to 1969, Published: 1969.
Asset/Event Number	466.3
Asset/Event Name	Structure, Dalnamain
Type of Asset/Event	Structure
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272195
Northing	898441
Council	Highland
Condition:	Degraded
Alignment:	N/S

Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small ruinous wooden structure measuring 6m by 4m, bearing a slanted flat roof of corrugated iron. The building is 2.8m tall along the N end and 2,5m tall at the S end. The building had a door in the N elevation, and inside there is a small counter against the E internal wall. Likely used as a fishing bothy or similar for the nearby river. First depicted on the 1959 OS map. OS. 1959. NH79NW - A. Surveyed / Revised: 1930 to 1959, Published: 1959
Asset/Event Number	467
Asset/Event Name	Clearance cairn, Achtaduach
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272227
Northing	898275
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn under heather, measuring 2.8m by 2.5m and 0.7m tall.

Asset/Event Number	468
Asset/Event Name	Bridge, Dalnamain
Type of Asset/Event	Bridge
Date and/or Period	Post-medieval/Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272176
Northing	898458
Council	Highland
Condition:	Ruinous
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A bridge constructed with a single mortar and stone pier and mortar and stone footings either side of the Abhainn an s-Stratha Charnaig. A timber board bridge rests atop the pier and footings, measuring 7m long and 3m wide. The stone elements pre-date this. A foot bridge is identified on the 1st edition OS map at this crossing and is labelled us such until 1969, so potentially this bridge may be

	of mid-20th century date. OS. 1879. Sutherland CIV. Surveyed: 1873-4, Published: 1879. OS. 1969. NH79NW - A. Surveyed / Revised: 1966 to 1969, Published: 1969.
Asset/Event Number	469
Asset/Event Name	Dyke, Abhainn an t-Stratha Charnaig
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272156
Northing	898492
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under grass, extends parallel with track. Stands 0.5m tall and spread 1m wide, extends c60m. Not depicted on historic mapping.

Asset/Event Number	470
Asset/Event Name	Corn drying kiln, Dalnameine
Type of Asset/Event	Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH79NW 9
HER Number	MHG11728
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272347
Northing	898589
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A corn drying kiln under grass and heather, constructed into SE facing hill slope. Measures c5m in diameter. A small stone and turf dyke extends to the SW, creating a small enclosed area at the SE side of the kiln. The kiln bowl is partially visible through the vegetation with a diameter of 2m. The flue is not visible. Not depicted on historic mapping. Https://her.highland.gov.uk/monument/MHG11728 There is a possible souterrain at Daneman. There appears to be the outline of a passage, and lintel stones in position can be seen. Information contained in letter from Elizabeth R Mackay, Tigh Beag, Rearquhar, Dornoch,

	IV25 3NE, to OS. This would appear to be a well-preserved kiln-barn of pre-1811 date and associated with the depopulation around. Information contained in letter from R Mowat, RCAHMS to OS 2 October 1978. A well-preserved corn-drying kiln with flue exposed. Surveyed at 1:10,000. Visited by OS (N K B) 15 October 1980.
Asset/Event Number	471
Asset/Event Name	Dyke, Innis Aonar
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH79NW 38
HER Number	MHG19237
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272482
Northing	899068
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A very degraded turf and stone dyke under tall heather, stands 0.4m tall and spread up to c3m wide, but dimensions fairly difficult to see given vegetation, but visibility improves in N extent. Disappears to the SW in a dense cluster of woodland. C480m recorded but the dyke extends outwith the survey corridor to the E. Forms the enclosure for the Innis Aohmar farmstead. Partially depicted on the 1st edition OS map. OS. 1879. Sutherland CIV. Surveyed: 1873-4, Published: 1879. https://her.highland.gov.uk/monument/mhg19237 A farmstead, comprising one unroofed building and an enclosure within a field is depicted on the 1st edition of the OS 6-inch map (Sutherland 1879, sheet civ). One unroofed building and one enclosure are shown on the current edition of the OS 1:10560 map (1969). Information from RCAHMS (AKK) 21 November 1995. Innis Aonar. Footings of enclosures noted on the 6''OS map, and of a cruciform building and well-preserved corn-drying kiln were found (Macdonald 1995, fig 18). NH 725 992 The long axis of the cruciform building is c16.5m by 2m, with the extensions being 4m by 2m and 3m by 2m, and slightly offset. NH 725 991 Corn-drying kiln, with 1.5m bowl, flue opening to SE. NH 724 991 Oval outline of stones 4.6m by 2m. Sponsor: Tain Archaeological Group 1995. M Macdonald 1995.
Asset/Event Number	472.1
Asset/Event Name	Prehistoric clearance cairn, Allt na h-Innse Aonair
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH79NW 6
HER Number	MHG11725

Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272702
Northing	899205
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather, measures c7m in diameter and stands 0.8m tall.

Asset/Event Number	472.2
Asset/Event Name	Prehistoric clearance cairn, Allt na h-Innse Aonair
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH79NW 6
HER Number	MHG11725
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272722
Northing	899216
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. May be built on a small protrusion of bedrock. Measures 7.5m by 5m and stands 0.6m tall

Asset/Event Number	472.3
Asset/Event Name	Prehistoric clearance cairn, Allt na h-Innse Aonair
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH79NW 6
HER Number	MHG11725
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272714
Northing	899194
Council	Highland
Condition:	Degraded

Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 5m in diameter and stands 0.4m tall.

Asset/Event Number	472.4
Asset/Event Name	Prehistoric clearance cairn, Allt na h-Innse Aonair
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH79NW 6
HER Number	MHG11725
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272728
Northing	899198
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 5.5m in diameter and stands 0.5m tall.

Asset/Event Number	473
Asset/Event Name	Shooting butt, Allt na h-Innse Aonair
Type of Asset/Event	Shooting butt
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272810
Northing	899312
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible shooting butt under heather. The structure is defined by a circular bank under heather standing between 0.5 and 1.3m tall, spread up to 2m wide. Possibly incorporated some of the surrounding bedrock formation into. Possible entrances lead out to the NW, NE and SW but these may also be sheep/deer trails.

Asset/Event Number	474
Asset/Event Name	Prehistoric clearance cairn, Allt na h-Innse Aonair
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.2
Easting	272771
Northing	899361
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A probable prehistoric clearance cairn under heather, measures 5.5m by 4m and stands 1.5m tall. No stone visible but suspected to be a prehistoric clearance cairn like those found c60m to the S (Asset 472), although the HER extent for MHG11725 and Asset 472 does not extend this far.

Asset/Event Number	475
Asset/Event Name	Track, Am Bru-lochan
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	288988
Northing	908366
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Relict track under grass and partially sunken in places, 2.5-3m wide. Depicted on the 1st edition OS map and likely an old peat cutting road. Recorded extent is c800m long but continues outwith the survey corridor to the N and S. OS. 1872. Sutherland XCVIII (with inset of XCIX). Survey date: 1872, Publication date: 1879

Asset/Event Number	476
Asset/Event Name	Peat cutting, Creag an Lochain Deirg
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A

HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	288776
Northing	908369
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of old peat cutting c40m by 30m under heather, banks are up to 0.4m deep. Dis-used.

Asset/Event Number	477
Asset/Event Name	Peat cutting, Creag an Lochain Deirg
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	288894
Northing	908299
Council	Highland
Condition:	Very Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Large area of extensive peat cutting under heather on the top and E-facing side of the hill Creag an Lochain Deirg. Recorded extent measures c340m by 200m but it continues outwith the survey corridor to the N and S. The banks vary in depths from over 1m to 0.2m and suggest the area has been long in-use for peat cutting.

Asset/Event Number	478
Asset/Event Name	Peat cutting, Am Bru-lochan
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	288566
Northing	908125

Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of old peat cutting under heather, c70m by 70m and banks are up to 0.4m deep. Record extent measures c100m by 80m but the peat cutting continues outwith the survey corridor to the S. Dis-used.

Asset/Event Number	479
Asset/Event Name	Enclosure, Clyne
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	286909
Northing	907701
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A sub-circular enclosure under heather, c18m in diameter over banks. The banks stand to a height of 0.4m tall and spread up to 2m wide. Likely a post-medieval drover's enclosure given the proximity to the old drove road Asset 485. Not depicted on historic mapping.

Asset/Event Number	480.1
Asset/Event Name	Peat cutting, An Dubh Lochan
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	288342
Northing	908068
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Area of peat cutting under heather, c115m by 20m and banks up to 0.3m deep. Dis-used.

Asset/Event Number	480.2
Asset/Event Name	Peat cutting, An Dubh Lochan
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	288281
Northing	908119
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Area of peat cutting under heather, c20m by 10m, banks up to 0.3m deep. Dis-used.

Asset/Event Number	480.3
Asset/Event Name	Peat cutting, An Dubh Lochan
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	288250
Northing	908161
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Area of peat cutting under heather, c90m by 10m, banks up to 0.3m deep. Dis-used.

Asset/Event Number	480.4
Asset/Event Name	Peat cutting, An Dubh Lochan

Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	288191
Northing	908066
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Area of peat cutting under heather, c220m by 110m, banks up to 0.3m deep. Dis-used.

Asset/Event Number	480.5
Asset/Event Name	Peat cutting, An Dubh Lochan
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	288070
Northing	908104
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Area of peat cutting under heather, c180m by 60m, banks up to 0.3m deep. Dis-used.

Asset/Event Number	481.1
Asset/Event Name	Peat cutting, An Dubh Lochan
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1

Easting	287958
Northing	907951
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Area of peat cutting under heather, c340m by 200m (continues beyond survey corridor extent to N and S), around the un-named burn that runs S into the An Duch-lochan, banks up to 0.3m deep. Dis-used.

Asset/Event Number	481.2
Asset/Event Name	Peat cutting, An Dubh Lochan
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	287796
Northing	907891
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A discrete area of peat cutting under heather, c20m by 10m, banks up to 0.3m deep. Dis-used.

Asset/Event Number	482
Asset/Event Name	Track, An Dubh-lochan
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	288110
Northing	908064
Council	Highland
Condition:	Very degraded
Alignment:	E/W
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A relict track under heather and grass, 2m wide. Likely used for peat cutting and collection, appears to lead down to the loch An-Dubh Lochan, but is not easily visible. C35m long. Not depicted on historic mapping.

Asset/Event Number	483.1
Asset/Event Name	Clearance cairn, Killin
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC80NE 20
HER Number	MHG10799
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	285568
Northing	907217
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A mound of field clearance stones, measuring 7m by 5m and standing to 0.8m tall. Appears fairly modern.

Asset/Event Number	483.2
Asset/Event Name	Clearance cairn, Killin
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC80NE 20
HER Number	MHG10799
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	285584
Northing	907216
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A mound of field clearance stones, measuring 5m by 3m and standing to 0.7m tall. Appears fairly modern.

Asset/Event Number	484
Asset/Event Name	Peat cutting, Clyne

Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	286875
Northing	907559
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Area of peat cutting under heather and grass, c130m by 90m, banks are up to 0.6m deep and peter out to the N. Dis-used.

Asset/Event Number	485
Asset/Event Name	Track, Clyne
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG30283
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	286551
Northing	907485
Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A relict track c3m wide under heather, the centre of which is well-worn as a bare-earth trail c1m wide. Forms an historic drove road from Oldtown to Clyne, extending outwith the 200m survey corridor to the NW and SE. Note: the HER extent for this is a small point area outwith the survey corridor. Depicted on the 1st edition OS map. OS. Sutherland XCVII. Surveyed: 1872, Published: 1879. https://her.highland.gov.uk/monument/MHG30283 The road is also known locally as the Coffin Road or Garlet Road (Garbh Leathad, Rough Slope) - stretches from Oldtown at its north-western end to Clynekirkton in the south-east. (NC 8527 0883 TO 8940 0610). From the surrounding evidence, it is easy to imagine its origins as a prehistoric track. The Oldtown section, of what is now an estate road, is still in active use. The road passes Killin and makes its way towards the ruins of Clynekirkton Church and Belfry, the road narrows to little more than a sheep track. It preserves the trailmarks of the

bereaved from a not so distant age: hence, no doubt, its alternative title - 'Coffin Road'.

Finally, at its south-eastern end, the ancient road meets its modern counterpart as the latter skirts the belfry, church and graveyard.

Information supplied by Dr. Norman Gibson, 14.10.01
See assoc. docs. File.
J Aitken : 30.10.01

The Garlat or Garlet Road is the hill track from Clynekirkton to Oldtown. In it's first mile it climbs along the rough steep slope of Socach, behind the crofts of West Clyne; and this fact leads to the supposition that the original Gaelic was Garbh Leathad, Rough Slope. Local pronunciation would be Garruh Let. A very similar sounding word is gearraidh (pronounced garry nearly) which means, according to Bain, outland beyond township ploughed land; which is what this long slope would have been. Cregan a' Chorp which may be translated body stone, is a boulder beside this track, which used to be a resting place for funerals on their way out of Strathbrora to Clynekirkton graveyard.
J Maclennan, The Northern Times, 1957.
J Aitken : 15/05/02.

Asset/Event Number	486
Asset/Event Name	Dyke, Clyne
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG25168
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	286403
Northing	907439
Council	Highland
Condition:	Very degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A turf and stone dyke under heather, stands 0.5m tall and spread 0.8m wide. The recorded extent measures c210m long but the dyke extends beyond the survey corridor to the NW and SE. Becomes stonier where it crosses over rockier ground. Not depicted on historic mapping.

Asset/Event Number	487
Asset/Event Name	Hut circle, Killin
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	286348
Northing	907406

Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hut circle under heather and bracken. The banks stand 1.wm tall and spread up to 2m wide, difficult to tell due to vegetation. Somewhat oval shaped, measuring 12.5m NW/SE by 9.5m over banks. Situated on a gently declining W facing slope overlooking loc

Asset/Event Number	488
Asset/Event Name	Possible hut circle, Killin
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	286292
Northing	907364
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible hut circle under dense heather and bog willow, very difficult to trace bank, may measure c14m by 12m. Where bank survives it appears 0.7m tall and spread up to 2m. A small streamlet bisects it. Entrance not definite.

Asset/Event Number	489
Asset/Event Name	Possible hut circle, Killin
Type of Asset/Event	Hut circle
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	286155
Northing	907404
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Low

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible hut circle under heather with poorly defined banks, measuring c10m in diameter with banks spread to 2m wide and standing 0.7m tall. A depression in the SE portion is the likely entrance. Vegetation obscured this asset quite significantly.
Asset/Event Number	490.1
Asset/Event Name	Possible burnt mound, Killin
Type of Asset/Event	Burnt mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	286101
Northing	907393
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Crescent-shaped mound under heather, measuring 11m by 9.5m and stands 1m tall. Its form is reminiscent of burnt mounds although a clear water source is not immediately evident. Interpreted as a burnt mound, but may also be a large prehistoric clearance cairn.
Asset/Event Number	490.2
Asset/Event Name	Clearance cairn, Killin
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	286133
Northing	907263
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under grass and heather. Measures 3m in diameter and stands 0.6m tall.
Asset/Event Number	490.3
Asset/Event Name	Clearance cairn, Killin

Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	286102
Northing	907235
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible prehistoric clearance cairn under heather and grass. Measures c3m in diameter and stands 0.8m tall, but lots of vegetation growth.

Asset/Event Number	490.4
Asset/Event Name	Clearance cairn, Killin
Type of Asset/Event	Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	285985
Northing	907358
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather, measuring 3m by 2.2m and standing 0.7m tall.

Asset/Event Number	490.5
Asset/Event Name	Clearance cairn, Killin
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1

Easting	286034
Northing	907235
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather, measuring 10.5m by 6m and stands 0.7m tall.

Asset/Event Number	490.6
Asset/Event Name	Clearance cairn, Killin
Type of Asset/Event	Mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	285935
Northing	907327
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather, measuring 6m by 2m and standing 0.7m tall.

Asset/Event Number	490.7
Asset/Event Name	Clearance cairn, Killin
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	285948
Northing	907187
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather. Measures 4m by 3m and stands 0.7m tall.

Asset/Event Number	490.8
Asset/Event Name	Possible burnt mound, Killin
Type of Asset/Event	Burnt mound
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	285908
Northing	907192
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible burnt mound under heather and gorse, the vegetation making it difficult to determine the extent and form. Measures at least 9m by 4.5m and stands 1.2m tall, situated on the N side of a small un-named watercourse. Alternatively this may be another prehistoric clearance cairn that is just somewhat larger than the others in the Asset 490 group.

Asset/Event Number	490.9
Asset/Event Name	VOID - number not assigned
Type of Asset/Event	.
Date and/or Period	.
Listing No./NRHE Number	
HER Number	TBD
Status	Non-designated Heritage Asset
Section:	N/A
Easting	
Northing	
Council	Highland
Condition:	n/a
Alignment:	.
Importance:	TBD
Description	VOID - number not assigned.

Asset/Event Number	490.9

Asset/Event Name	VOID - number not assigned
Type of Asset/Event	.
Date and/or Period	.
Listing No./NRHE Number	
HER Number	TBD
Status	Non-designated Heritage Asset
Section:	N/A
Easting	
Northing	
Council	Highland
Condition:	n/a
Alignment:	.
Importance:	TBD
Description	VOID - number not assigned.

Asset/Event Number	490.10
Asset/Event Name	Clearance cairn, Clyne
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	285844
Northing	907274
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather, measuring 3m by 2m and standing 0.6m tall. One very pronounced boulder at the centre.

Asset/Event Number	491
Asset/Event Name	Peat cutting, Clyne
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset

Section:	B1.1
Easting	286658
Northing	907399
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Area of old peat cutting under grass and heather. c70m by 70m. Banks 0.3-0.5m deep and edges ephemeral.

Asset/Event Number	492.1
Asset/Event Name	Cistern, Killin
Type of Asset/Event	Other
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	285938
Northing	907190
Council	Highland
Condition:	Ruinous
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A concrete basin measuring 1.5m by 1m and 0.75m deep. Fed by a plastic pipe taking hill water in. Broken wooden door fragments around it presumably once formed a cover.

Asset/Event Number	492.2
Asset/Event Name	Mound, Killin
Type of Asset/Event	Mound
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	285939
Northing	907193
Council	Highland
Condition:	Degraded
Alignment:	N/A

Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Mound of stone and earth under heather, measuring 3m in diameter and 1m tall, under heather. Spoil heap for pit the cistern structure 492.1 is in.

Asset/Event Number	493
Asset/Event Name	Dyke, Killin
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC80NE 20
HER Number	MHG10799
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	285805
Northing	907217
Council	Highland
Condition:	Degraded
Alignment:	NNW/SSE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke under grass and moss, stands 0.4m tall and spread up to 1m wide. Recorded extent measures c200m long but the dyke extends outwith survey corridor to the SE. Depicted on the 1st edition OS map. Forms part of Killin township MHG10799. OS. 1879. Sutherland XCVII. Survey date: 1872, Published: 1879 https://her.highland.gov.uk/Monument/MHG10799 (Area Centred NC 8572 0714) Killin (NAT) OS 6" map, Sutherland, 1st ed., (1907) Carrall: shown as a group of about four buildings with arable. Kulen: shown as a group of about four buildings. (Roy appears to have transposed these names as "Carroll" is shown on the E side of L Brora at Killin, and "Kulen" on the W side, near Carrol). W Roy 1747-55. Area centred NC 8572 0714. The area is, for the most part, covered in bracken and no building foundations were found. There are several enclosures in the area, all of stone. The enclosure at NC 8574 0713 is 9.0m diameter, 0.5m maximum height but having no apparent entrance. The enclosure at NC 8571 0708 is 2.0m square and is 1.0m high on the SE side; it is situated on top of a small hill. The enclosure at NC 8575 0715 is 0.8m high. The area is bounded on the E and S sides by a stone and turf bank. The area may be wrongly sited, as Carrol is on the W side of Loch Brora, see NC80NE 26. Visited by OS (E G C) 16 July 1961.

Asset/Event Number	494
Asset/Event Name	Dyke, Killin
Type of Asset/Event	Dyke

Date and/or Period	Post-medieval
Listing No./NRHE Number	NC80NE 20
HER Number	MHG10799
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	285776
Northing	907237
Council	Highland
Condition:	Very degraded
Alignment:	NNE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible stone and turf dyke, much degraded so that only the intermittent boulders are apparent. Stands 0.2m tall and c1m wide spread, measuring c30m long. Not depicted on historic mapping. Forms part of Killin township MHG10799. For HER description see Asset 493.

Asset/Event Number	495
Asset/Event Name	Enclosure, Killin
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC80NE 20
HER Number	MHG10799
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	285775
Northing	907151
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An irregular shaped enclosure, measuring 31m by 20m and constructed from a turf and stone dyke that stands 0.3m-0.7m tall in places with 1m spread. Entrance not discernible. Depicted on the 1st edition OS map. Forms part of Killin township MHG10799. For HER description see Asset 493. OS. 1879. Sutherland XCVII. Survey date: 1872, Published: 1879

Asset/Event Number	496
Asset/Event Name	Enclosure, Killin
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC80NE 20
HER Number	MHG10799
Status	Non-designated Heritage Asset
Section:	B1.1

Easting	285750
Northing	907139
Council	Highland
Condition:	Very degraded
Alignment:	Circular
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A circular enclosure under grass, c12m in diameter and constructed of a turf and stone dyke that stands 0.4m tall and spread 0.7m wide. Entrance not apparent. One of several small enclosure features in the Killin area. Not depicted on historic mapping. Forms part of Killin township MHG10799. For HER description see Asset 493. OS. 1879. Sutherland XCVII. Survey date: 1872, Published: 1879
Asset/Event Number	497
Asset/Event Name	Dyke, Killin
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC80NE 20
HER Number	MHG10799
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	285747
Northing	907164
Council	Highland
Condition:	Very degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A very degraded stone and turf dyke under grass, measures 0.5m tall and spread up to 1.5m wide, c55m long. Likely robbed for surrounding structures. Not depicted on historic mapping. Forms part of Killin township MHG10799. For HER description see Asset 493. OS. 1879. Sutherland XCVII. Survey date: 1872, Published: 1879
Asset/Event Number	498
Asset/Event Name	Dyke, Killin
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC80NE 20
HER Number	MHG10799
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	285726
Northing	907131
Council	Highland
Condition:	Very degraded

Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under moss, 33m long in total, and stands 0.4m tall and spread 1m wide. Not depicted on historic mapping. Forms part of Killin township MHG10799. For HER description see Asset 493. OS. 1879. Sutherland XCVII. Survey date: 1872, Published: 1879

Asset/Event Number	499
Asset/Event Name	Dyke, Killin
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC80NE 20
HER Number	MHG10799
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	285716
Northing	907215
Council	Highland
Condition:	Very degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A very degraded stone and turf dyke under grass, measures 0.5m tall and spread up to 1.5m wide, c33m long. Forms a possible small pen or enclosure but open to the W. Not depicted on historic mapping. Forms part of Killin township MHG10799. For HER description see Asset 493. OS. 1879. Sutherland XCVII. Survey date: 1872, Published: 1879

Asset/Event Number	500
Asset/Event Name	Building, Killin
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC80NE 20
HER Number	MHG10799
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	285681
Northing	907240
Council	Highland
Condition:	Ruinous
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Footings for a possible building under grass, measuring 8.5m by 6m with banks standing 0.3m tall. Situated atop a small grass-covered knoll with nearby mounds Assets 501.1 and 501.2 possibly representing further structures. Not depicted on historic mapping. Within HER extent for Killin township MHG10799. For HER description see Asset 493.

	OS. 1879. Sutherland XCVII. Survey date: 1872, Published: 1879
Asset/Event Number	501
Asset/Event Name	Quarry, Allt Bad na h-Achlaise
Type of Asset/Event	Quarry
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	249768
Northing	862908
Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Small quarry c7m in diameter, situated beside modern forestry track and likely related to its construction.

Asset/Event Number	501.1
Asset/Event Name	Mound, Killin
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC80NE 20
HER Number	MHG10799
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	285670
Northing	907240
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A grass-covered mound measuring c5.8m by 4m and standing 0.6m tall. Difficult to discern form due to the vegetation. Occupies a low hill and near to a similar mound (Asset 501.2) and building footings (Asset 500), so may be the remains of structure. Not depicted on historic mapping. Within HER extent for Killin township MHG10799. For HER description see Asset 493. OS. 1879. Sutherland XCVII. Survey date: 1872, Published: 1879

Asset/Event Number	501.2
Asset/Event Name	Mound, Killin
Type of Asset/Event	Clearance cairn

Date and/or Period	Post-medieval
Listing No./NRHE Number	NC80NE 20
HER Number	MHG10799
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	285659
Northing	907244
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A grass-covered mound measuring c10m by 6m and standing 0.4m tall. Difficult to discern form due to the vegetation. Occupies a low hill and near to a similar mound (Asset 501.1) and building footings (Asset 500), so may be the remains of structure. Not depicted on historic mapping. Within HER extent for Killin township MHG10799. For HER description see Asset 493. OS. 1879. Sutherland XCVII. Survey date: 1872, Published: 1879

Asset/Event Number	502
Asset/Event Name	Corn drying kiln
Type of Asset/Event	Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC80NE 20
HER Number	MHG10799
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	285698
Northing	907219
Council	Highland
Condition:	Very Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A corn drying kiln under bracken and grass, measuring 7m by 5m. The bowl is 2m in diameter and the flue aligned NE/SW, with opposing walls extending each side some 4m from kiln which measure 1m wide and c0.8m tall. The kiln wall stands 0.8m tall at the NE end. Not depicted on historic mapping. Within HER extent for Killin township MHG10799. For HER description see Asset 493. OS. 1879. Sutherland XCVII. Survey date: 1872, Published: 1879

Asset/Event Number	503
Asset/Event Name	Enclosure, Killin
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NC80NE 20
HER Number	MHG10799

Status	Non-designated Heritage Asset
Section:	B1.1
Easting	285594
Northing	907110
Council	Highland
Condition:	Good
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An enclosure measuring c120m by 130m and composed of a drystone dyke. The dyke stands 1.1-1.4m tall, measuring 0.8m at base and 0.4m at top with coping of small stones. Depicted on the 1st edition OS map. Forms part of the Killin township MHG10799. For HER description see Asset 493. OS. 1879. Sutherland XCVII. Survey date: 1872, Published: 1879
Asset/Event Number	504.1
Asset/Event Name	Peat cutting, Asc na Greine
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	289891
Northing	908612
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An area of deeper peat cutting under grass, within larger overall peat area. Measures c19m by 8m and c0.3m deep.

Asset/Event Number	504.1
Asset/Event Name	Peat cutting, Asc na Greine
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	289904
Northing	908639
Council	Highland

Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Large area of extensively cut peat, now under heather and moss. C130m by 120m, the banks range in depth from 0.3-0.9m deep. Dis-used.

Asset/Event Number	504.2
Asset/Event Name	Peat cutting, Asc na Greine
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5/B1.1
Easting	290113
Northing	908754
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Large area of extensively cut peat, now under heather and moss. C240m long and extends beyond 200m survey corridor to N and S, the banks range in depth from 0.3-0.9m deep. Dis-used.

Asset/Event Number	504.3
Asset/Event Name	Peat cutting, Asc na Greine
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	290341
Northing	908953
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Large area of extensively cut peat, now under heather and moss. C400m long and extends beyond 200m survey corridor to W and E, the banks range in depth from 0.3-0.9m deep. Dis-used.

Asset/Event Number	504.4
Asset/Event Name	Peat cutting, Asc na Greine
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	290317
Northing	909114
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Large area of extensively cut peat, now under heather and moss. C180m long and 60m wide, extends beyond 200m survey corridor to W, the banks range in depth from 0.3-0.9m deep. Dis-used.

Asset/Event Number	504.5
Asset/Event Name	Peat cutting, Asc na Greine
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.5
Easting	290521
Northing	909332
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Large area of extensively cut peat, now under heather and moss. C270m long and extends beyond 200m survey corridor to E and W, the banks range in depth from 0.3-0.9m deep. Dis-used.

Asset/Event Number	505
Asset/Event Name	Track, Asc na Greine

Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	289944
Northing	908588
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A relict track measuring up to 2.5m wide and depressed in the peat under grass, recorded c40m length but continues beyond survey corridor to the SE. Likely an old peat road. Not depicted on historic mapping.

Asset/Event Number	506
Asset/Event Name	Dyke, Asc na Greine
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	290089
Northing	908744
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A low turf dyke standing 0.3-0.6m tall and spread up to 1m wide, extends across the peat cuttings Asset 504.2. Recorded extent measures c210m wide but the dyke extends outwith the survey corridor to the N and S. It is identified as a county boundary on the 1st edition OS map, representing the parish boundary between Loth to the NW and Clyne to the SE. OS. 1879. Sutherland XCVIII (with inset of XCIX). Survey date: 1872, Published: 1879.

Asset/Event Number	507
Asset/Event Name	Dyke, Glensgaich
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	NA
Status	Non-designated Heritage Asset

Section:	N/A
Easting	245157
Northing	860883
Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Drystone boundary dyke under bracken, stands up to 1m tall and spread c2m wide. Extends along edge of forestry plantation, recorded extent measures c500 but extends outwith survey corridor to the NW and SE. Depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXV. Survey date: 1875, Published: 1881.
Asset/Event Number	508.1
Asset/Event Name	Structure, Middle north settlement, Upper Rogie
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH46SW 3.00
HER Number	MHG53447; MHG24412; MHG14115
Status	Non-designated Heritage Asset
Section:	
Easting	244155
Northing	860073
Council	Highland
Condition:	Ruinous
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Remains of a ruinous structure, adjacent to asset 508.2. Measures 5m x 2m and surviving to a height of 1.50m. Depicted as roofed on the 1st edition OS map within the township of Rogie. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXV. Survey date: 1875, Published: 1881. https://her.highland.gov.uk/Monument/MHG53447 The main building of this settlement. It is the westmost of 2 with an enclosure, 37, to the rear. The building has 2 compartments and an outshot to the SW. It has an internal measurement of 11m x 3.5m, with the main compartment to the west being 6m in length. The tumbled dividing wall is 0.5m high and has a spread of 1m. The walls are of dry stone construction, double faced and 0.7m in thickness. The rear wall is generally 1m in height and turfed up on the outside. The NE gable is 1.5m high and the SW 1.2m. The front wall is tumbled for the main part, 0.5m high and with a spread of 1.5m, although the east part is better preserved and there is an entrance into the NE compartment. The outshot to the SW is more roughly constructed with walls to a height generally of 1m, it measures 3m x 2m and has an entrance in the E corner next to the main building. This building is thought to be MacQueens croft. A photograph taken in the 1920s, has been reproduced in the fieldwork report, Figure 7, page 25. <1> <1> SHG24685 Text/Report/Fieldwork Report: Marshall, M.. 2010. The Report of a Project to Identify, Survey and Record Archaeological Remains at Rogie, Ross-shire: February 2008 - May 2009. North of Scotland Archaeological Society. Digital. Feature 43. https://her.highland.gov.uk/Monument/MHG24412 (larger/more general) A township comprising three roofed, one partially roofed and thirteen unroofed buildings,

eight enclosures and two short lengths of head-dyke is depicted on the 1st edition of the OS 6-inch map (Ross-shire and Cromartyshire 1881, sheet lxxv). Ten unroofed buildings and four enclosures are shown on the current edition of the OS 1:10000 map (1989).
Information from RCAHMS (SAH) 28 February 1996

In an area of perhaps half a square kilometre and centred on a rounded hill to the north of the railway line there are the remains of a large enclosure and 5 discrete settlements. Their composition is variable, some have just 1 building and 1 enclosure, others have several buildings with up to 2 enclosures. The central focus is the hill, around which there are the remains of a discontinuous stone and turf wall, several clearance cairns lie within the enclosure particularly in the NW part. The settlements are contiguous with the enclosure wall at varying intervals. The whole area has been grossly disturbed by forestry, having been planted with trees, felled, ploughed and replanted again. In addition the drainage has been substantially disturbed by forest roads and tracks - many areas, which would in the past have been well drained, are now marshy. The surrounding wall and a few associated features are described first followed by each settlement the structures of which have then been grouped together.
The township is shown on the 1st edition OS map as 1 partially roofed building, 14 unroofed buildings, 6 enclosures and a head dyke.
The head dyke was noted during survey work in 2008-9 as a discontinuous wall. This appears to define an enclosure some 400m by 200m in size, mostly now planted with young trees but with some open grassy areas in the north part (previously ploughed). The SW corner of the enclosure was located by GPS at NH 43746 59852. In the SW and west the wasted dry stone wall is clearly defined and 0.5m in height. To the north it is ploughed out and barely discernable. The east part and south part appears to have been destroyed by the forest roads.
A small pen was noted to be situated in the angle of this wall a few metres to the west of the north-west settlement (MHG14114). The small pen is aligned north-south and measures 3m by 1m. The walls are of single stone thickness and are 0.6-0.7m high.
<1> SHG24685 Text/Report/Fieldwork Report: Marshall, M.. 2010. The Report of a Project to Identify, Survey and Record Archaeological Remains at Rogie, Ross-shire: February 2008 - May 2009. North of Scotland Archaeological Society. Digital.

Https://her.highland.gov.uk/Monument/MHG14115
Information received from the Forestry Commission (date unknown) suggested that only one ruin of a square building was visible at NH 442 601. Agreed management consisted of scrub clearance to the roadside and 10 metres around the ruin.
The same area has subsequently been surveyed by NOSAS and found to comprise four buildings and two enclosures. The drainage of the settlement has been grossly affected by the construction of the road and is now very marshy. See individual HER records for details.
<2><3>
<1> SHG24686 Text/Record Form: Easter Ross Forest District. Unknown. Record of Scheduled or Other Ancient Monuments. Digital (scanned as PDF). Rogie Croft 3.
<2> SHG24685 Text/Report/Fieldwork Report: Marshall, M.. 2010. The Report of a Project to Identify, Survey and Record Archaeological Remains at Rogie, Ross-shire: February 2008 - May 2009. North of Scotland Archaeological Society. Digital.
<3> SHG23297 Verbal Communication: Tilbury, S. Comment by Sylvina Tilbury, HER Officer. 01/04/2010.

Asset/Event Number	508.2
Asset/Event Name	Structure, Middle north settlement, Upper Rogie
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH46SW 3.00
HER Number	MHG53447; MHG24412; MHG14115
Status	Non-designated Heritage Asset
Section:	

Easting	244157
Northing	860076
Council	Highland
Condition:	Ruinous
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Ruinous rectangular drystone structure c10m by 2.5m over walls, which stand up to 1.5m tall. Trees are growing within the interior. A smaller structure (Asset 508.1), likely a lean-to/ancillary, abuts the NW end. Depicted as roofed on the 1st edition OS map within the township of Rogie. For HER descriptions see Asset 508.1. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXV. Survey date: 1875, Published: 1881.
Asset/Event Number	508.3
Asset/Event Name	Structure, Middle north settlement, Upper Rogie
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH46SW 3.00
HER Number	MHG53448; MHG24412; MHG14115
Status	Non-designated Heritage Asset
Section:	
Easting	244166
Northing	860090
Council	Highland
Condition:	Ruinous
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A square shaped drystone structure, roofless. Immediately to N of 508.1 and 508.2. Adjoins 508.4 to NE, separated by wall. Measures c4m NE to SW, and 3.5 SE to NW. Walls stand up to c2m at NE end. Possibly a small pen, or a more poorly preserved portion of the building Asset 508.4 as postulated below. Depicted potentially as a pen or roofless structure on the 1st edition OS map adjacent to the roofed Asset 508.4. For HER assets MHG24412 and MHG14115 see Asset 508.1. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXV. Survey date: 1875, Published: 1881. https://her.highland.gov.uk/Monument/MHG53448 Immediately to the north of 35 this building on the same NE-SW alignment has 2 compartments and an overall internal measurement of 13m x 3.5m. The west compartment is better preserved and measures 5m x 3.5m. The walls are of dry stone construction, double faced and 0.7m in thickness. The SW gable is 2m in height, the rear NW wall 1 - 1.2m high, the SE wall 0.8m high and the dividing wall is 0.5m high. There is an entrance 0.7m wide at the E end of the SE wall. The NE compartment is 7m x 3.5m and much more wasted, although the rear wall is 1m in height and the NE end has an external height of 1m. Otherwise it is generally 0.3m high. A large part of the SE wall is missing (or else it may have been a wide entrance). <1> <1> SHG24685 Text/Report/Fieldwork Report: Marshall, M.. 2010. The Report of a Project to Identify, Survey and Record Archaeological Remains at Rogie, Ross-shire: February 2008 - May 2009. North of Scotland Archaeological Society. Digital. Feature 43.
Asset/Event Number	508.4

Asset/Event Name	Structure, Middle north settlement, Upper Rogie
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH46SW 3.00
HER Number	MHG53449; MHG24412; MHG14115
Status	Non-designated Heritage Asset
Section:	
Easting	244171
Northing	860100
Council	Highland
Condition:	Ruinous
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Remains of a ruinous structure, adjacent to the W end of Asset 508.3. Measures c6.5m x 3m, standing to a maximum height of 1.25m. Depicted as a roofed structure on the 1st edition OS map within the township of Rogie. For HER description see Asset 508.3. For HER assets MHG24412 and MHG14115 see Asset 508.1. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXV. Survey date: 1875, Published: 1881.

Asset/Event Number	508.5
Asset/Event Name	Enclosure, Middle north settlement, Upper Rogie
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH46SW 3.00
HER Number	MHG53449; MHG24412; MHG14115
Status	Non-designated Heritage Asset
Section:	
Easting	244166
Northing	860096
Council	Highland
Condition:	Ruinous
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Drystone boundary/enclosure wall immediately to NW of ruined structures and buildings at Rogie. Measures c20-25m by 10-15m. Depicted on the 1st edition OS map within the township of Rogie. For HER assets MHG24412 and MHG14115 see Asset 508.1. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXV. Survey date: 1875, Published: 1881. https://her.highland.gov.uk/Monument/MHG53449 An irregular enclosure to the rear/northwest of buildings 35 and 36. It is roughly 25m x 15m and is bounded by the remains of a stone wall, 0.5 -0.8m high in the NE part but much more wasted in its SW part. A line of trees are growing along the wall. The internal area is grassy and deeply ploughed but not planted. <1> <1> SHG24685 Text/Report/Fieldwork Report: Marshall, M.. 2010. The Report of a Project to Identify, Survey and Record Archaeological Remains at Rogie, Ross-shire: February 2008 - May 2009. North of Scotland Archaeological Society. Digital. Feature 37.

Asset/Event Number	508.6
Asset/Event Name	Cultivation, Middle north settlement, Upper Rogie
Type of Asset/Event	Field system
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH46SW 3.00
HER Number	MHG53449; MHG24412; MHG14115
Status	Non-designated Heritage Asset
Section:	
Easting	244161
Northing	860086
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A series of 4 linear banks/ditches running in a NE/SW direction within the enclosure Asset 508.5. Banks are up to 0.5m tall measured from the ditches. Features c15-20m in length. For HER description see Asset 508.5. For HER assets MHG24412 and MHG14115 see Asset 508.1.

Asset/Event Number	509.1
Asset/Event Name	Kiln barn, Upper Rogie
Type of Asset/Event	Kiln barn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH46SW 3
HER Number	MHG53456; MHG24412; MHG14115
Status	Non-designated Heritage Asset
Section:	
Easting	244011
Northing	860153
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Footings for a rectangular kiln barn building under dense bracken and grass, as described below. Possibly depicted as a roofless structure on the 1st edition OS map within the township of Rogie. For HER assets MHG24412 and MHG14115 see Asset 508.1. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXV. Survey date: 1875, Published: 1881. https://her.highland.gov.uk/Monument/MHG53456 Aligned E-W this structure has an overall measurement of 7m x 3m. The kiln is well preserved and of dry stone construction, it is generally 1.6m high. The bowl has a diameter of 1.8m and it is 0.5-1m deep although there is some tumbled material inside. Unusually there are two flues in the straight west face which is 1.1m in height. The south one appears blocked although it can be probed to a depth of 0.9m, it has an aperture of 1m width x 0.3m height externally, narrowing to 0.3m width x 0.1m height. The north flue is 0.5m wide, 0.2-

	0.4m depth and 1m in length. Externally there is an abutting feature on the SE side of the structure, this takes the form of a rising ramp of large stones, this may have been steps up to the top of the kiln. The internal area of the barn to the east is raised above the level of the surrounding ground. It is 6m x 2.5m internally and the remains of the walls are 0.3-0.5m height inside (0.6-1m outside). There is an entrance 0.7m in width at the east end of the south wall. <1> <1> SHG24685 Text/Report/Fieldwork Report: Marshall, M.. 2010. The Report of a Project to Identify, Survey and Record Archaeological Remains at Rogie, Ross-shire: February 2008 - May 2009. North of Scotland Archaeological Society. Digital. Feature 43.
Asset/Event Number	509.2
Asset/Event Name	Building, Upper Rogie
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH46SW 3
HER Number	MHG53457; MHG24412; MHG14113
Status	Non-designated Heritage Asset
Section:	
Easting	244020
Northing	860149
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular building with boulder-defined walls. As described below. Not depicted on historic mapping. For HER asset MHG24412 see Asset 508.1. Https://her.highland.gov.uk/Monument/MHG53457 A few metres to the SE of the kiln the very wasted remains of this structure appear as a rectangular marshy depression. The structure is aligned ENE-WSW and has an overall measurement of 9m x 4m. Several large moss covered boulders outline the walls of the structure; the rest of the walls may have been robbed. The walls have a height of 0.5-0.6m inside (0.2-0.5m outside). There may be an entrance in the south wall. <1> <1> SHG24685 Text/Report/Fieldwork Report: Marshall, M.. 2010. The Report of a Project to Identify, Survey and Record Archaeological Remains at Rogie, Ross-shire: February 2008 - May 2009. North of Scotland Archaeological Society. Digital. Feature 44. https://her.highland.gov.uk/Monument/MHG14113 Information received from the Forestry Commission (date unknown) described the site as consisting of a kiln, longhouse and two other ruins.. Agreed management consisted of clearance of windblow and standing conifers to 10 metres from the perimeter and the avoidance of the area by extraction machinery. <1> The same area has subsequently been surveyed by NOSAS and found to comprise four buildings, one kiln barn and one enclosure. The drainage of the settlement has been affected by the construction of the road and is now very marshy. See individual HER records for details. <2><3> <1> SHG24686 Text/Record Form: Easter Ross Forest District. Unknown. Record of Scheduled or Other Ancient Monuments. Digital (scanned as PDF). Rogie Croft 1. <2> SHG24685 Text/Report/Fieldwork Report: Marshall, M.. 2010. The Report of a Project to Identify, Survey and Record Archaeological Remains at Rogie, Ross-shire: February 2008 - May 2009. North of Scotland Archaeological Society. Digital. <3> SHG23297 Verbal Communication: Tilbury, S. Comment by Sylvina Tilbury, HER Officer. 06/04/2010.

Asset/Event Number	509.3
Asset/Event Name	Building, Upper Rogie
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH46SW 3
HER Number	MHG53454; MHG24412; MHG14113
Status	Non-designated Heritage Asset
Section:	
Easting	244005
Northing	860131
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular building with stone walls and raised interior, two compartments. As described below. Depicted as a roofed structure on the 1st edition OS map within the township of Rogie. For HER asset MHG24412 see Asset 509.1. For HER asset MHG24412 see Asset 508.1. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXV. Survey date: 1875, Published: 1881. Https://her.highland.gov.uk/Monument/MHG53454 This is the main building of the settlement, it is aligned E-W and has internal dimensions of 16m x 4m. The internal area is raised above that of the surrounding land and is divided into 2 equally sized compartments by a setting of upright slabs 0.4m in height. The west compartment appears to be the main one, the walls here are generally 0.8-1m height (1-1.5m outside) but the west gable is 1.6m. On the outside this gable is 2m high and has complex buttressing, with a stone plinth 4m x 1.5m x c1.5m height covered by tumble. The east compartment walls are generally 0.5m high (0.8m outside) although the east gable is 1m high (1.3m outside), and here again there appears to have been a form of “buttressing” supporting the gable. Internally there is an obvious drain, 0.4m deep, down the centre of the compartment and an entrance at the west end of the south wall. An outshot to the east, in the form of a level platform, 2.5m x 2.5m, with a stone edge of 0.3m height may be a former building on this site. It is set at a slight angle to the main building and may indicate the line of an earlier building. <1> <1> SHG24685 Text/Report/Fieldwork Report: Marshall, M.. 2010. The Report of a Project to Identify, Survey and Record Archaeological Remains at Rogie, Ross-shire: February 2008 - May 2009. North of Scotland Archaeological Society. Digital. Feature 42.

Asset/Event Number	509.4
Asset/Event Name	Building, Upper Rogie
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH46SW 3
HER Number	MHG53454; MHG24412; MHG24412
Status	Non-designated Heritage Asset
Section:	
Easting	243993
Northing	860123
Council	Highland

Condition:	Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Remnants of a rectangular building under dense bracken and grass. As described below. Depicted as a roofed structure on the 1st edition OS map within the township of Rogie. For HER asset MHG24412 see Asset 509.1. For HER asset MHG24412 see Asset 508.1. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXV. Survey date: 1875, Published: 1881. Https://her.highland.gov.uk/Monument/MHG53453 A rectangular building, aligned ENE-WSW, with 2 compartments. The east compartment is better preserved and has internal dimensions of 5.5 x 3m. The dry stone walls are double faced, 0.8m thick and generally 1m in height, although the east gable is 2m high. There is an entrance at the west end of the south wall and a nice pair of cruck slots, opposite one another in the long walls. The west compartment is much more wasted with the walls being 0.3-0.5m height, although at the west end, where it is recessed into the bank, the stone face is 0.8m high. There are two lengths of wall abutting; the one to the north stretches for 7.5m in a NNW direction and is of stone and turf construction, 0.5m high, the one to the south is of turf, it is 7m long and 1m in height. Both of these walls may be all that remains of an enclosure shown on the 1st edition OS map, the rest of it having been destroyed by the construction of the forest road nearby. <1> <1> SHG24685 Text/Report/Fieldwork Report: Marshall, M.. 2010. The Report of a Project to Identify, Survey and Record Archaeological Remains at Rogie, Ross-shire: February 2008 - May 2009. North of Scotland Archaeological Society. Digital. Feature 41.
Asset/Event Number	509.5
Asset/Event Name	Enclosure, Upper Rogie
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH46SW 3
HER Number	MHG53454; MHG24412; MHG24412
Status	Non-designated Heritage Asset
Section:	
Easting	244012
Northing	860109
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An enclosure under tall bracken and grass. As described below. Depicted on the 1st edition OS map within the township of Rogie. For HER asset MHG24412 see Asset 509.1. For HER asset MHG24412 see Asset 508.1. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXV. Survey date: 1875, Published: 1881. https://her.highland.gov.uk/Monument/MHG53452 A rectangular enclosure aligned NNW-SSE is 18m x 13m. It is surrounded by a moss covered wall which is, for the most part, of stone. The general level of the enclosure is raised above that of the surrounding ground which is marshy. The height of the wall is generally 1m on the outside and 0.5m on the inside. A number of trees are growing along the line of the wall. This is most probably a garden. To the south of the enclosure there are two lengths of wall within a plantation of young

	trees, it is difficult to determine their extent, but they are probably associated with this settlement. Centred on NH 44068 60084 is a winding wall 23m in length and aligned NW-SE. It is 0.3-0.5m in height, and has a 2m spread. Centred on NH 44046 60070 and at right angles to 40B this wall has been grossly disturbed by forest ploughing. <1> <1> SHG24685 Text/Report/Fieldwork Report: Marshall, M.. 2010. The Report of a Project to Identify, Survey and Record Archaeological Remains at Rogie, Ross-shire: February 2008 - May 2009. North of Scotland Archaeological Society. Digital. Feature 40.
Asset/Event Number	509.6
Asset/Event Name	Structure, Upper Rogie
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH46SW 3
HER Number	MHG53455; MHG24412; MHG24412
Status	Non-designated Heritage Asset
Section:	
Easting	244003
Northing	860140
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone-built structure under tall bracken. As described below. Not depicted on historic mapping. For HER asset MHG24412 see Asset 509.1. For HER asset MHG24412 see Asset 508.1. Https://her.highland.gov.uk/Monument/MHG53455 Immediately to the north of 42, the turf footings of what may be small building are seen. It has the form of an L shaped turf bank, 0.3-0.5m in height with a spread of 1.5m. <1> <1> SHG24685 Text/Report/Fieldwork Report: Marshall, M.. 2010. The Report of a Project to Identify, Survey and Record Archaeological Remains at Rogie, Ross-shire: February 2008 - May 2009. North of Scotland Archaeological Society. Digital. Feature 42A.
Asset/Event Number	510
Asset/Event Name	Forestry cultivation, Upper Rogie
Type of Asset/Event	Cultivation
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243852
Northing	860152
Council	Highland
Condition:	Good
Alignment:	Curving

Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large area of furrows formed for modern commercial forestry plantation that curves through a clearing between the plantations. The furrows are well-defined and under grass.

Asset/Event Number	511.2
Asset/Event Name	Building, Upper Rogie
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH46SW 3
HER Number	MHG53458; MHG24412; MHG14114
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243798
Northing	860133
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A ruinous L-shaped building of drystone wall construction. As described below. Depicted as a roofless structure on the 1st edition OS map within the township of Rogie. For HER asset MHG24412 see Asset 508.1. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXV. Survey date: 1875, Published: 1881. Https://her.highland.gov.uk/Monument/MHG53458 A reversed L-shaped building, on a ENE-WSW alignment, comprising 3 compartments. - The main, largest compartment, to the west, measures 7.8m x 3.8m internally, with the extension to the NW of an additional 4.4m x 3m. The dry stone walls in the south and west part are 0.2-0.3m high whilst those to the north are 0.6m high externally and that at the north end of the extension is 1.2m. A few features were noted - 1. An entrance in the SE wall possibly 1m in width, although the surviving aperture suggested 1.8m in width. 2. A stone edged drain in the E part of the compartment is 0.3m wide x 2m length x 0.2m deep. A possible further one is seen in the west part, see plan. 3. A regular moss covered stone plinth to the rear/N of the building. It measured 2m length x 0.6m width x 0.5m height. It may have been buttressing for the wall. - The central compartment measures 1.8m x 3.8m and has an entrance of 1.2m in width in the south wall. The walls are very variable in height from 0.2-0.7m. - the east compartment is 4.4m x 3.6m internally and the walls are 0.3-0.5m high. A stone edged drain 0.4m wide x 1.8m length x 0.3m deep occupies a central position. Adjacent to the east a roughly circular depression 1.6m diameter x 0.4m deep may be a stank or a sump. To the SE of the building a terrace runs along the length of the building. It is 2m width in the west part and 1.2m in the east part. It is bounded by large boulders with a drop 0.3-0.5m to a marshy depression which appears to be man-made. The marshy depression is 8m N-S x 16m SW-NE narrowing at the NE end. It has steep banks to the south and east. At the SE corner of the building a stone lined void, 0.2 x 0.2m x 0.8m depth may be the socket for a timber post. At the NE corner, the wasted turf and stone wall of enclosure 54 abuts. <1> <1> SHG24685 Text/Report/Fieldwork Report: Marshall, M.. 2010. The Report of a Project to Identify, Survey and Record Archaeological Remains at Rogie, Ross-shire: February 2008 - May 2009. North of Scotland Archaeological Society. Digital. Feature 61. https://her.highland.gov.uk/Monument/MHG14114

	This site was visited and described by Forestry Commission staff (date unknown). It is described as comprising an L-shaped ruin, long house and two other ruins. Proposed management included clearance to within 10 metres of the remains and the avoiding the use of extraction machinery. <1> The NE farmstead has 2 buildings, a corn-drying kiln, an enclosure and a small pen (61 – 65). The SW farmstead has 1 building and 1 enclosure (59 – 60). The remains of the dry stone walls of both farmsteads are in the main, quite low and between 0.8-1m in thickness, they are moss covered and possibly robbed of their stone. The NE farmstead is on a level shelf which slopes off to the north and west. The SW farmstead is on level ground within the forested area close to a small burn. <2> See individual monument records for full details. <3> <1> SHG24686 Text/Record Form: Easter Ross Forest District. Unknown. Record of Scheduled or Other Ancient Monuments. Digital (scanned as PDF). Rogie Croft 2. <2> SHG24685 Text/Report/Fieldwork Report: Marshall, M.. 2010. The Report of a Project to Identify, Survey and Record Archaeological Remains at Rogie, Ross-shire: February 2008 - May 2009. North of Scotland Archaeological Society. Digital. Features 59-65. <3> SHG23297 Verbal Communication: Tilbury, S. Comment by Sylvina Tilbury, HER Officer.
Asset/Event Number	511.3
Asset/Event Name	Building, Upper Rogie
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH46SW 3
HER Number	MHG53459; MHG24412; MHG14114
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243788
Northing	860127
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A ruinous rectangular building, c14.5m by 4.5m over walls which stand up to 1.2m tall. Flanking entrances in the northeast elevation. As described below. Depicted as a roofless structure on the 1st edition OS map within the township of Rogie. For HER asset MHG24412 see Asset 508.1. For HER asset MHG14114 see Asset 511.2. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXV. Survey date: 1875, Published: 1881. https://her.highland.gov.uk/Monument/MHG53459 A rectangular building on a NNW-SSE alignment, probably the main dwelling house of the farmstead. It measures 13.8m x 3.4m internally. The remains of stone walls are 0.4-0.5m high in the south part but 1-1.2m at the north end. There are two entrances, both 1m in width, in the east wall. <1> <1> SHG24685 Text/Report/Fieldwork Report: Marshall, M.. 2010. The Report of a Project to Identify, Survey and Record Archaeological Remains at Rogie, Ross-shire: February 2008 - May 2009. North of Scotland Archaeological Society. Digital. Feature 62.
Asset/Event Number	511.4
Asset/Event Name	Kiln barn Upper Rogie
Type of Asset/Event	Kiln barn
Date and/or Period	Post-medieval

Listing No./NRHE Number	NH46SW 3
HER Number	MHG53460
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243776
Northing	860126
Council	Highland
Condition:	Degraded
Alignment:	WNW/ESE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A ruinous kiln barn with corn-drying kiln in the NE end. Measures c10m by 4.5m over walls, which stand up to 0.8m tall. Entrance 1.9 m wide in S elevation. As described below. Depicted as a roofless structure on the 1st edition OS map within the township of Rogie. For HER asset MHG24412 see Asset 508.1. For HER asset MHG14114 see Asset 511.2. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXV. Survey date: 1875, Published: 1881. Https://her.highland.gov.uk/Monument/MHG53460 A rectangular structure on a sloping E-W alignment comprising two parts - the bowl and the barn: - the bowl at the east end is recessed into the slope. It is c 0.5m deep but filled with tumble. A defining edge of the stonework is seen in places and possibly a scarcement, 0.5m in width, around the upper edge. - the barn is 9m x 3.2m internally and recessed at its east end where the face of the kiln is 0.8m high, tumble obscured any flue that might exist. The stone walls at the east end were 1m in height internally but barely discernible externally. At the west end they were 0.6-0.8m high, both internally and externally. An obvious entrance, 0.7 in width, existed at the west end of the south wall and a possible drain was 0.3m deep. <1> <1> SHG24685 Text/Report/Fieldwork Report: Marshall, M.. 2010. The Report of a Project to Identify, Survey and Record Archaeological Remains at Rogie, Ross-shire: February 2008 - May 2009. North of Scotland Archaeological Society. Digital. Feature 63. Map
Asset/Event Number	511.5
Asset/Event Name	Enclosure, Upper Rogie
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG53461; MHG24412; MHG14114
Status	Non-designated Heritage Asset
Section:	
Easting	243780
Northing	860115
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. An enclosure under tall bracken and grass c12m by 10m over walls. As described below. Not depicted on historic mapping. For HER asset MHG24412 see Asset 508.1. For HER asset MHG14114 see Asset 511.2. Https://her.highland.gov.uk/Monument/MHG53461 A rectangular enclosure on a NNW-SSW alignment measures 11m x 6m internally. The remains of crudely built stone walls on three sides are largely tumbled but generally 0.5m high and with a spread of 1.5m. There is no evidence of a wall on the east side but this may have been provided by the west wall of building 62. To the west a possible track ran up the hill along the outside of the enclosure and at the north end the wall of the enclosure 54 curves off in a southerly direction. <1> <1> SHG24685 Text/Report/Fieldwork Report: Marshall, M.. 2010. The Report of a Project to Identify, Survey and Record Archaeological Remains at Rogie, Ross-shire: February 2008 - May 2009. North of Scotland Archaeological Society. Digital. Feature 64.
Asset/Event Number	512
Asset/Event Name	Dyke, Upper Rogie
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG14114; MHG24412; MHG14114
Status	Non-designated Heritage Asset
Section:	
Easting	243758
Northing	860098
Council	Highland
Condition:	Degraded
Alignment:	NNE/SSW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Remnants of a drystone dyke under bracken, measuring c5m in length and stands 0.4m tall. Not depicted on historic mapping. Falls with HER extent for Rogie township MHG14114. For HER asset MHG24412 see Asset 508.1. For HER asset MHG14114 see Asset 511.2.

Asset/Event Number	513.1
Asset/Event Name	Structure, Upper Rogie
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG53462; MHG24412; MHG14114
Status	Non-designated Heritage Asset
Section:	
Easting	243728
Northing	860063
Council	Highland
Condition:	Degraded
Alignment:	NE/SW

Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone footings for a building under dense bracken. As described below. For HER asset MHG24412 see Asset 508.1. For HER asset MHG14114 see Asset 511.2. Depicted as a roofless structure on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXV. Survey date: 1875, Published: 1881. https://her.highland.gov.uk/Monument/MHG53462 A rectangular structure on a NE-SW alignment measures c7.5m x 2.5m internally. The remains of the dry stone walls are generally 0.5-0.6m high and have a spread of 0.8m. There is a considerable amount of tumble in the NE end of the building and an entrance, 0.7 m wide in the SE wall. The building is grass and moss covered and has been planted with trees. <1> SHG24685 Text/Report/Fieldwork Report: Marshall, M.. 2010. The Report of a Project to Identify, Survey and Record Archaeological Remains at Rogie, Ross-shire: February 2008 - May 2009. North of Scotland Archaeological Society. Digital. Feature 59.
Asset/Event Number	513.2
Asset/Event Name	Enclosure, Upper Rogie
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG53463; MHG24412; MHG14114
Status	Non-designated Heritage Asset
Section:	
Easting	243734
Northing	860057
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone enclosure under tall bracken As described below. For HER asset MHG24412 see Asset 508.1. For HER asset MHG14114 see Asset 511.2. Depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXV. Survey date: 1875, Published: 1881. hthttps://her.highland.gov.uk/Monument/MHG53463 A D-shaped enclosure which abuts the wall of the main enclosure described (but not mapped) under the township record MHG24412. The enclosure is on a WSW-ENE alignment and measure 13m x 12m internally. The remains of the dry stone walls which are 0.3-0.7m high and have a 1-1.5m spread are more substantial in the north and east parts. <1> SHG24685 Text/Report/Fieldwork Report: Marshall, M.. 2010. The Report of a Project to Identify, Survey and Record Archaeological Remains at Rogie, Ross-shire: February 2008 - May 2009. North of Scotland Archaeological Society. Digital. Feature 60.
Asset/Event Number	513.3
Asset/Event Name	Dyke, Upper Rogie
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG53463; MHG14114

Status	Non-designated Heritage Asset
Section:	
Easting	243742
Northing	860070
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Remnants of a drystone dyke extending off the enclosure Asset 513.3. Under bracken and grass. Stands c0.3-0.5m tall and spread up to 1.5m wide, measures c30m long. As described below. Not depicted on historic mapping. For HER asset MHG24412 see Asset 508.1. For HER asset MHG14114 see Asset 511.2.

Asset/Event Number	515
Asset/Event Name	Mound, Bridgepark
Type of Asset/Event	Mound
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	247113
Northing	850959
Council	Highland
Condition:	Very degraded
Alignment:	Circular
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A sub-oval shaped mound 5m by 4m and c1m tall, under dense bracken. Function uncertain. Not depicted on historic mapping.

Asset/Event Number	516
Asset/Event Name	Dyke, Bridgepark
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	247248
Northing	851076
Council	Highland

Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke under bracken and grass, stands up to 1.2m tall and measures 1m wide, extending beyond survey corridor to NW and SE. Consistent with a boundary depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII. Survey date: 1876, Published: 1881.
Asset/Event Number	517
Asset/Event Name	Dyke, Bridgepark
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	247050
Northing	851191
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Ruinous drystone dyke stands 0.6m tall and spread up to 1m wide, measures c200m long. Full extent difficult to trace through vegetation, likely continue to join dyke Asset 516 as depicted on the historic mapping. Consistent with a boundary depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII. Survey date: 1876, Published: 1881.
Asset/Event Number	518
Asset/Event Name	Track, Bridgepark
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	246980
Northing	851119
Council	Highland
Condition:	Very degraded
Alignment:	NW/SE
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Possible track, superseded by a later forestry road. Measures c2m wide and c300m long. Not depicted on historic mapping.

Asset/Event Number	519
Asset/Event Name	Dyke, Bridgepark
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	246456
Northing	851578
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke under grass and bracken, stands up to 1m tall and spread 1.2m wide and recorded extent of c850m. Consistent with a boundary depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII. Survey date: 1876, Published: 1881.

Asset/Event Number	520.1
Asset/Event Name	Enclosure, Bridgepark
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	246896
Northing	851222
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An irregularly-shaped enclosure measuring c180m by 160m, composed of a double-faced drystone dyke under bracken. Stands 0.6m tall and spread 1m wide, partially revetted on the N side. Forms the enclosure that building Asset 520.2 is situated alongside. Depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII. Survey date: 1876, Published: 1881.

Asset/Event Number	520.2

Asset/Event Name	Building, Bridgepark
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	246905
Northing	851307
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone footings for a rectangular building under dense bracken. Measures c25m long and 5m wide over walls which stand c0.5m tall and c1m wide. Possibly three internal partitions and a possible corn-drying kiln stands at the NW end but the density of vegetation across the structure obscured visibility. Entrances not discernible. Depicted as a roofed building on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII. Survey date: 1876, Published: 1881.

Asset/Event Number	520.3
Asset/Event Name	Enclosure, Bridgepark
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	246907
Northing	851300
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone and turf dyke forming an L-shaped enclosure 21m by 12m off the SW side of building Asset 520.2. Dyke is 1m tall and spread 1.5m wide, under turf and bracken. Depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII. Survey date: 1876, Published: 1881.

Asset/Event Number	522.1
Asset/Event Name	Enclosure, Bridgepark
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG62290

Status	Non-designated Heritage Asset
Section:	E1.1
Easting	247195
Northing	851163
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A double faced drystone dyke partially under bracken and grass, stands up to 1m tall and 0.9m wide. Diminishes as it proceeds through poor ground to SE. Depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII. Survey date: 1876, Published: 1881.

Asset/Event Number	522.2
Asset/Event Name	Building, Bridgepark
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG62290
Status	Non-designated Heritage Asset
Section:	
Easting	247230
Northing	851154
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. The stone footings for a rectangular building under dense bracken and moss. Extends c16m by 4.5m over the walls, which stand to 0.4m tall. No entrances or internal partitions could be identified. Consistent with a roofless building or pen depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII. Survey date: 1876, Published: 1881.

Asset/Event Number	522.2
Asset/Event Name	Structure, Bridgepark
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG62290
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247237
Northing	851145
Council	Highland

Condition:	Degraded
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Drystone dyke under bracken measuring 1m tall and 0.5m wide forming a rectangular structure 22m by 15m, with a single partition defining two compartments. Possibly pens. There are roofless structures depicted here on the 1st edition OS map and these may correlate. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII. Survey date: 1876, Published: 1881.
Asset/Event Number	522.3
Asset/Event Name	Enclosure, Bridgepark
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG62290
Status	Non-designated Heritage Asset
Section:	
Easting	247242
Northing	851148
Council	Highland
Condition:	Very degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An enclosure measuring c14m by 9m, composed of a low-lying drystone dyke or boulder dyke below dense bracken and grass that stands c0.4m tall and spread 1m wide. Consistent with a small enclosure depicted on the 1st edition OS map, which appears to show a small structure present within but this could not be discerned during the survey. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII. Survey date: 1876, Published: 1881.
Asset/Event Number	522.3
Asset/Event Name	Structure, Bridgepark
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG62290
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247247
Northing	851142
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Low

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Degraded stone and turf footings under grass and bracken, for a structure, likely a small pen or enclosure. Measures 8m by 7m and banks spread 1m wide and 0.25m tall. There are roofless structures depicted here on the 1st edition OS map and these may correlate. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII. Survey date: 1876, Published: 1881.
Asset/Event Number	523
Asset/Event Name	Dyke, Bridgepark
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG62290
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247268
Northing	851137
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A double-faced drystone dyke, stands up to 1m tall and measures 0.6m wide, c120m long but may continue to the NW. Coping stones set vertically across top. Depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII. Survey date: 1876, Published: 1881.
Asset/Event Number	524
Asset/Event Name	Enclosure, Bridgepark
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	247284
Northing	851075
Council	Highland
Condition:	Very degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke forming an enclosure under bracken, stands 0.7m tall and spread up to 1.5m wide. Almost but not quite connected to the dyke Asset 516 to the NW, so possible entrances where these dykes do not meet. Not depicted on historic mapping.
Asset/Event Number	525

Asset/Event Name	Pond, Allt na Talchainn
Type of Asset/Event	Pond
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG54822
Status	Non-designated Heritage Asset
Section:	N/A
Easting	241487
Northing	855384
Council	Highland
Condition:	Fair
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Artifical and augmented pond, c50m long by 30m wide, with stone augmenting the north extent and east extent. This is not depicted on historic mapping. The stone is suggested to form a dam, as described below. Https://her.highland.gov.uk/Monument/MHG54822 Garrimatic Dam - NH 41471 55382 - Encloses a small body of water at the NW side of a large marshy area. The retaining wall or embankment, which is 2 to 3m thick and 0.9m in height, forms a 2 sided "dog-leg" - that side on the north edge of the pond being 30m long and that on the west side 15m long. The outlet is part way along the N side and there is no evidence of a sluice. There was no evidence of a building which could have been a mill on the course of the stream, although any evidence may have been destroyed during the construction of the road. <1> <1> SHG24094 Text/Report/Fieldwork Report: Marshall, M.. 2009. A Project to Identify, Survey and Record Archaeological Remains in Strathconon, Ross-shire: Report of Phase One Scatwell and Lower Strathconon. North of Scotland Archaeological Society. 23/01/2009. Digital. P.41 Site 275.

Asset/Event Number	526
Asset/Event Name	Mound, Drumandarach
Type of Asset/Event	Mound
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	241789
Northing	855369
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible/Low

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Flat topped mound in a burn valley just to the N of a steep slope. C6m diameter, surviving up to 1m in height. Bracken covered. No visible stone etc, but surveyed due to flatness of top and unusualness in surrounding landscape. A possible platform?
Asset/Event Number	527.1
Asset/Event Name	Structure, Drumandarach
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45NW 37.00
HER Number	MHG39288
Status	Non-designated Heritage Asset
Section:	N/A
Easting	242054
Northing	855255
Council	Highland
Condition:	Ruinous
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular structure under bracken, better preserved on the W side where walls stand 1.3m high and 1m wide, elsewhere walls are low and tumbled. Measures c16m by 6m over tumble. A possible internal partition exists but this was difficult to discern with the vegetation. Not depicted on historic mapping. Does not quite fall within the HER extent for MHG39288 but should likely be considered to be part of this township. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXXVII. Survey date: 1876, Published: 1881. Https://her.highland.gov.uk/Monument/MHG39288 Drumandarroch - 2 buildings named and marked at W end of v large enclosure within the woodland and marked on 1st ed OS. One inside wall, one outside. The enclosure walls are still in place as good quality dry stone walling, but the modern buildings are now at the E end 242416 855269 (ie beside the road). Photos from road - 07/06/2005 - HAW The former township of Drumandarroch, farmstead buildings, enclosures, dykes, associated features and a milestone are located on the south side of the River Conon and was surveyed by NOSAS in 2007 as part of the Scotland's Rural Past Project. The site extends across an area some 400m x 120m along an east facing ridge. The majority of the features included within the site record are contained within a large enclosure (170) that is shown on 1st edition of the OS 6-inch map (Ross-shire 1881, sheet lxxxvii) as is the remains of a farmstead (172 & 173) that is located outside and to the west of the enclosure. The south side of the site is bounded by a small stream and a rising craggy slope. The enclosure is grassy with some bracken and there is much evidence of recent sheep management. Birch woods and heather surround the settlement and a major power line traverses the site. The site comprises the remains of at least five buildings, a possible kiln, and there several clearance cairns which may conceal traces of earlier buildings. <1> <1> SHG24094 Text/Report/Fieldwork Report: Marshall, M.. 2009. A Project to Identify, Survey and Record Archaeological Remains in Strathconon, Ross-shire: Report of Phase One Scatwell and Lower Strathconon. North of Scotland Archaeological Society. 23/01/2009. Digital. Pp.38-40 (survey numbers 170-196 & 235-238).
Asset/Event Number	527.2
Asset/Event Name	Structure, Drumandarach

Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH45NW 37.00
HER Number	MHG39288
Status	Non-designated Heritage Asset
Section:	N/A
Easting	242081
Northing	855255
Council	Highland
Condition:	Ruinous
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Rectangular drystone wall building under bracken, measure c16m by 6m over walls which stand 0.5m wide and 0.5-1m tall. Situated internally on SW side of enclosure Asset 527.3 (within which it is enclosed). No discernible entrances. Depicted on the 1st edition OS map, but as likely partially ruinous with only the NE extent shown as roofed. For HER asset description see Asset 527.1. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXXVII. Survey date: 1876, Published: 1881.
Asset/Event Number	527.3
Asset/Event Name	Enclosure, Drumandarach
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG39288
Status	Non-designated Heritage Asset
Section:	N/A
Easting	242097
Northing	855255
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A sub rectangular enclosure c50m by 15m in size, composed of a drystone dyke under tall bracken. The dyke stands up to 1m tall and between 0.5-1m wide, and has been robbed out completely in places. The S portion of this is depicted on the 1st edition OS map, to the S of the building Asset 527.2, but a degraded form likely existed as a dashed line is shown enclosing an area of pasture. Forms part of the Drumandarroch township. For HER asset description see Asset 527.1. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXXVII. Survey date: 1876, Published: 1881.
Asset/Event Number	527.4
Asset/Event Name	Dyke, Drumandarach
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval

Listing No./NRHE Number	N/A
HER Number	MHG39288
Status	Non-designated Heritage Asset
Section:	N/A
Easting	242093
Northing	855232
Council	Highland
Condition:	Degraded
Alignment:	ENE/WSW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Remnants of a drystone dyke extending around an open area south of the Drumandarach buildings (Assets 527.1 and 527.2) and continuing to the E and N beyond survey corridor extent where it appears to form a large enclosure as depicted on the 1st edition OS map. The dyke stands c1.5m tall in places and spread up to 1.5m wide, the recorded extent measuring c260m. Forms part of the Drumandarroch township. For HER asset description see Asset 527.1. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXXVII. Survey date: 1876, Published: 1881.
Asset/Event Number	528
Asset/Event Name	Structure, Strathconon
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG57280
Status	Non-designated Heritage Asset
Section:	N/A
Easting	242170
Northing	854956
Council	Highland
Condition:	Ruinous
Alignment:	Curving
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A sub rectangular drystone structure under bracken and trees, measuring c9m by 5m and open to the SE. Stands to c1m tall at the NW side with walls c0.25-0.5m wide. Considered to be a still bothy (MHG57280). Not depicted on historic mapping. Https://her.highland.gov.uk/Monument/MHG57280 Distilling sites and potentially associated structures situated on a shoulder ground characterised by rock outcrops and dense heather ground cover above the enclosed fields at Drumindarroch farm to the NE. There are at least four probable still bothies and two other structures distributed above the N bank of the Allt na Criche (NOSAS Site Survey Nos 199 – 204 and 228). Presumably these features were associated with the production of illegal whisky. 204 Building/Still bothy (Allt na Criche) - NH 42174 54938 This structure was recorded by NOSAS in 2007 as part of the Scotland's Rural Past Project. It is secluded in a small ravine on the NW bank of the Allt na Criche and only 2.8m from it. Birch woods surround. The remains

	of the rectangular structure, on a NW-SE axis, measure 5.5m x 3.5m internally. The NW and SW walls are 0.5m-1m in height and 0.5m in thickness with little tumble. The NE wall is recessed into the slope and is generally 0.8m in height. Its east end extends to form part of the arc of a circle, c1.75m diameter. The structure is open at its south end and there may be an entrance at the NE corner. Heavy growth of heather. This building is almost certainly a still bothy and the other structures to be found in the surrounding landscape reinforce this interpretation. It may be significant that all these structures are to be found on the NW side of the Allt na Criche which was the former parish boundary and also the march between the two estates of Fairburn and Scatwell, perhaps the Scatwell owners may have turned a "blind eye" to the illicit activities, whereasthe Fairburn landowners were less tolerant!! <1> <1> SHG24094 Text/Report/Fieldwork Report: Marshall, M.. 2009. A Project to Identify, Survey and Record Archaeological Remains in Strathconon, Ross-shire: Report of Phase One Scatwell and Lower Strathconon. North of Scotland Archaeological Society. 23/01/2009. Digital. P37 Site 204.
Asset/Event Number	529
Asset/Event Name	Dyke, Strathconon
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	242710
Northing	854725
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under dense bracken and grass, measures c50m long and stands c0.5m tall and spread up to 0.5m wide. Not depicted on historic mapping.

Asset/Event Number	530
Asset/Event Name	Quarry, Orrin
Type of Asset/Event	Quarry
Date and/or Period	Post-medieval/Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	243496
Northing	854233
Council	Highland
Condition:	Fair
Alignment:	Curving

Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Quarry c17m in diameter, visibly extending into the N-facing rockface of hill, forming a hollow 2-3m deep and the S side where closest to the slope. Not depicted on historic mapping.

Asset/Event Number	531
Asset/Event Name	Dyke, Coille Mhor
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244135
Northing	853889
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A turf and stone dyke under dense bracken and woodland, stands up to 1m tall and spread c2m wide, c140m long, continuing outwith the survey corridor to the NE and SW. Consistent with a field boundary depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXXVII. Survey date: 1876, Published: 1881.

Asset/Event Number	533
Asset/Event Name	Dyke, Newton
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	245272
Northing	854288
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke that extends along the S side of the road at the field edge, well-preserved towards the W side of the survey corridor and access track area, standing c1.2m tall and 0.5m wide as a neatly coursed rubble wall with boulder coping set atop it, and declining in preservation towards the E side of the survey corridor and under long grass. Extends beyond the corridor to the E and W.

	Consistent with a field boundary depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXXVII. Survey date: 1876, Published: 1881.
Asset/Event Number	534
Asset/Event Name	Dyke, Newton
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	245278
Northing	854042
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke standing 1.2m tall, 0.8m wide at base and tapering to 0.3m wide at top, extends outwith survey corridor to S and E. Consistent with a field boundary depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXXVII. Survey date: 1876, Published: 1881.
Asset/Event Number	535
Asset/Event Name	Possible structure, Newton
Type of Asset/Event	Unknown
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	245039
Northing	854011
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible/Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular spread of stones under grass and moss measuring 6m by 4m. Possibly a small pen or similar but too degraded to be certain. Not depicted on historic mapping.
Asset/Event Number	536.1
Asset/Event Name	Dyke, Newton

Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1 (in access track corridor to section)
Easting	244892
Northing	854116
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Drystone dyke, measures 0.8m wide at base and tapers to c0.4m top, standing to a height of between 1- 1.5m tall but in parts robbed out to less than 0.2m in height. More degraded section (Asset 536.2) extends SE from this. Recorded extent measures c230m, but the dyke continues outwith survey corridor to NE and SW. Consistent with field boundary depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXXVII. Survey date: 1876, Published: 1881.
Asset/Event Number	536.2
Asset/Event Name	Dyke, Newton
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	244817
Northing	854028
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A short length (c12m) of drystone dyke extending SE from the dyke Asset 536.1. Stands c1m tall and 0.8m wide, more poorly preserved in comparison to 536.1. Robbed away from the SE end. Consistent with field boundary depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXXVII. Survey date: 1876, Published: 1881.
Asset/Event Number	537
Asset/Event Name	Track, Newton
Type of Asset/Event	Track
Date and/or Period	Post-medieval

Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	244794
Northing	854005
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Track under grass measuring c3m wide, diminishes to the NW and continues beyond survey corridor to the SE. c100m long. Not depicted on historic mapping.

Asset/Event Number	538
Asset/Event Name	Bank, Newton
Type of Asset/Event	Bank
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	244764
Northing	854023
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Remnants of a ditch and bank under grass and trees. Ditch measures c3m wide and the bank measures 3m wide and c1.5-2m tall, c30m long. Possibly related to drainage for the woodland. Not depicted on historic mapping.

Asset/Event Number	539
Asset/Event Name	Dyke, Coille Mhor
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	244519
Northing	853580

Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke under bracken and grass, very degraded and standing to a height of c0.25m and spread up to 0.5m wide, c325m long but continues outwith survey corridor to the NE and SW. Consistent with field boundary depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXXVII. Survey date: 1876, Published: 1881.
Asset/Event Number	540.1
Asset/Event Name	Enclosure, Cnocanarve
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	246419
Northing	851741
Council	Highland
Condition:	Very degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Turf and stone dyke under bracken and grass, measures c90m long with visible extent recorded and stands 0.4m tall, spread up to 2m wide in parts. Consistent with an enclosure boundary depicted on the 1st edition OS map, but does not survive within the survey corridor beyond the extent recorded. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII. Survey date: 1876, Published: 1881.
Asset/Event Number	540.2
Asset/Event Name	Building, Cnocanarve
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246482
Northing	851738
Council	Highland
Condition:	Ruinous
Alignment:	E/W
Importance:	Low

Description	*Recorded by AOC Archaeology during 2024 walkover survey. An un-roofed rectangular stone building measuring 12m by 5m over walls, which stand to 2.5m tall along the long elevations and 6m tall at the gable ends, all of which survive to full height. Fireplaces present at both gable ends. Entrance is in the SE elvation with a window flanking this ether side, and an additional window in the N elevation. Forms the best preserved building of Asset group 540. While a small roofed structure is depicted in the vicinity on the 1st edition OS, this appears more likely to be the larger roofed building depicted on the 2nd edition OS map given its good level of preservation and size. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII. Survey date: 1876, Published: 1881. OS. 1907. Ross and Cromarty XCVIII. Survey date: 1902, Published: 1907.
Asset/Event Number	540.3
Asset/Event Name	Structure, Cnocanarve
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246485
Northing	851760
Council	Highland
Condition:	Ruinous
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Small square structure measuring 4m by 4m over walls, which stand to 1.5m tall at NE end and are 0.25m wide but are collapsed on the SW side. Potentially an entrance in the SE side. Depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII. Survey date: 1876, Published: 1881.
Asset/Event Number	540.4
Asset/Event Name	Dyke, Cnocanarve
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	246486
Northing	851765
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A section of drystone wall c5m long and 0.5m tall, forming a small revetment into the NE-facing slope adjacent to structure Asset 540.3. Not depicted on historic mapping.

Asset/Event Number	540.5
Asset/Event Name	Building, Cnocanarve
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246477
Northing	851755
Council	Highland
Condition:	Ruinous
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Rectangular building measuring 8.5m by 4m over walls which stand between 0.25 and 1.5m in height, with the SE end standing to 2m tall. Conjoins building Asset 540.6 to the NW, but this portion of the structure appears to be in much poorer condition and likely represents an older building. Entrances not readily discernible but considered to be in the SW elevation based on the presence of the entrance in Asset540.6 being in this elevation. Depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII. Survey date: 1876, Published: 1881.

Asset/Event Number	540.6
Asset/Event Name	Building, Cnocanarve
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246470
Northing	851759
Council	Highland
Condition:	Ruinous
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular stone and mortared building measuring c 8.5m by 4.5m over walls, conjoined with building Asset 540.5 on the SE gable end. This building is in better condition than 540.5, with walls measuring up to 1.5m tall and 0.5m wide, with an entrance c1m wide visible in the SW elevation. Possibly built as a later replacement for 540.6. Depicted on the 1st edition OS map.

	OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII. Survey date: 1876, Published: 1881.
Asset/Event Number	540.7
Asset/Event Name	Structure, Cnocanarve
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	246472
Northing	851720
Council	Highland
Condition:	Ruinous
Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular structure measuring 9m by 5m over walls, which stand between 0.3 and 1.5m tall and 0.4m wide. The two walls are constructed differently, with the E comprising large boulders at base and neater stacked stone atop and the W a more uniform construction of smaller stone. Entrance was possibly in the SE corner. Consistent with a roofed building depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII. Survey date: 1876, Published: 1881.
Asset/Event Number	540.8
Asset/Event Name	Structure, Cnocanarve
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	246470
Northing	851711
Council	Highland
Condition:	Ruinous
Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A U-shaped section of drystone walling likely representing the remains of a structure or building attached to the S side of building Asset 540.7, but substantially robbed so that only the three walls (E, S and W) survive, encompassing an area c5m by 4m over walls. Walls stand c0.4m tall and spread up to 2m wide as tumble. Building Asset 540.7 is depicted on the 1st edition OS map but this asset does not appear to be so.
Asset/Event Number	541

Asset/Event Name	Clearance cairn, Cnocanarve
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	246413
Northing	851700
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn partially under grass, measuring 6m in diameter and standing 1m tall.

Asset/Event Number	542
Asset/Event Name	Dyke, Cnocanarve
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	E1.1
Easting	246540
Northing	851627
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Stone and turf dyke under grass. Very diminished, represented mostly by intermittent boulders that stand less than 0.5m tall and spread 0.5m wide, c75m long. Consistent with a field boundary on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII. Survey date: 1876, Published: 1881.

Asset/Event Number	543
Asset/Event Name	Dyke, Allt na Criche
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	
Easting	241497
Northing	854584
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Drystone dyke partly under bracken, measure c50m long and stands up to 1.2m tall and 1m wide and bridges a low gap between two hills to the NE and SW. Consistent with an isolated length of a boundary on the 1st edition OS map, to the N of the Allt na Criche burn which forms the parish boundary between Urray to the S and Contin to the N. Asset 543 appears to be a continuation of dyke Asset 544 to the NE, but the visible extents of each have been recorded separately. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII. Survey date: 1876, Published: 1881.
Asset/Event Number	544
Asset/Event Name	Dyke, Allt na Criche
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	241598
Northing	854630
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Drystone wall under bracken and grass, measures c50m long and stands c0.5-1m tall, partly revetted against hill. Consistent with an isolated length of a boundary on the 1st edition OS map, to the N of the Allt na Criche burn which forms the parish boundary between Urray to the S and Contin to the N. Asset 544 appears to be a continuation of dyke Asset 543 to the SW, but the visible extents of each have been recorded separately. OS. 1881. Ross-shire & Cromartyshire (Mainland) XCVIII. Survey date: 1876, Published: 1881.
Asset/Event Number	545
Asset/Event Name	Clearance cairn, Allt na Fainich
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	

Easting	241695
Northing	854377
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn, c4m in diameter and 1m high, moss covered large stones.

Asset/Event Number	546.1
Asset/Event Name	Footings, Comrie
Type of Asset/Event	Footing
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	MHG57259
Status	Non-designated Heritage Asset
Section:	N/A
Easting	241457
Northing	855787
Council	Highland
Condition:	Fair
Alignment:	NE/SW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Rectangular concrete or packed gravel footing measuring 26m by 8.5m in the middle of an improved field near to extant farmstead. Although overgrown with grass this is still clearly visible as a feature. Surrounded on SW and NW side by a bank Asset 546.2. Not depicted on historic mapping.

Asset/Event Number	546.2
Asset/Event Name	Bank, Comrie
Type of Asset/Event	Bank
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG57259
Status	Non-designated Heritage Asset
Section:	N/A
Easting	241456
Northing	855797
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A curving stone and turf bank under grass, measuring 1m tall and spread up to 1m wide, around the N side of structure Asset 546.1. Some visible stone particularly at the SE end, with some modern detritus sticking out of this section, suggesting this may be fairly recent. Uncertain function. Not depicted on historic mapping.
Asset/Event Number	546.3
Asset/Event Name	Clearance cairn, Comrie
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG57259
Status	Non-designated Heritage Asset
Section:	N/A
Easting	241450
Northing	855759
Council	Highland
Condition:	Fair
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Irregular spread of clearance material under grass measuring c9m by 7m and 1m tall, and forming a triangular clearance cairn.

Asset/Event Number	547
Asset/Event Name	Flood defence, River Conon
Type of Asset/Event	Other
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	240429
Northing	856064
Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large flood embankment under grass and gorse on the S side of the River Conon. Stands between 1-2m tall and c1m wide, possibly augmenting a natural terrace above the river. Recorded extent c1.25km, but it extends beyond the survey corridor to the NW and E. Depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXXXVII. Survey date: 1876, Published: 1881

Asset/Event Number	550
Asset/Event Name	Borrow pit, Fannyfield Wood
Type of Asset/Event	Borrow pit
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	255237
Northing	866264
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A borrow pit measuring 5m by 5m and 1m deep, under moss and forestry. Likely related to the construction of the modern adjacent forestry track.

Asset/Event Number	551
Asset/Event Name	Dyke, Fannyfield Forest
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	255252
Northing	866251
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A length of drystone dyke that stands c1m tall and 0.5m wide. Terminates at NE end where the modern forestry track runs, but continues beyond the survey corridor to the SE. Recorded extent c40m long. Consistent with a boundary depicted on the 1st edition OS map. OS. 1880. Ross-shire & Cromartyshire (Mainland) LXXVI. Survey date: 1875-6, Published: 1880

Asset/Event Number	552
Asset/Event Name	Borrow pit, Fannyfield Wood
Type of Asset/Event	Borrow pit
Date and/or Period	Modern
Listing No./NRHE Number	N/A

HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	255203
Northing	866263
Council	Highland
Condition:	Fair
Alignment:	ENE/WSW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A long borrow pit measuring 22m by 4m and 1m deep. Excavated along the existing forestry track and likely as part of the track construction or drainage management.

Asset/Event Number	553
Asset/Event Name	Borrow pit, Fannyfield Wood
Type of Asset/Event	Borrow pit
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	255144
Northing	866258
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A long borrow pit measuring 65m by 4m and 1m deep. Excavated along the existing forestry track and likely as part of the track construction or drainage management.

Asset/Event Number	556.1
Asset/Event Name	Structure, Eilean Na Cabhaig
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH56NE 29.00
HER Number	MHG20792
Status	Non-designated Heritage Asset
Section:	D1.2 (in access track corridor to section)
Easting	256011
Northing	869207
Council	Highland

Condition:	Fair
Alignment:	NNE/SSW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Rectangular structure largely surviving as a low turf covered linear mound with some visible stone, c13m by 6m. The long NNW elevation wall incorporates a section of a larger field boundary/enclosure wall (Asset 556.3). No evidence for an entry or internal divisions. An unroofed structure or pen is depicted in the vicinity of this asset on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXIV. Survey date: 1875, Published: 1881
Asset/Event Number	556.2
Asset/Event Name	Dyke, Eilean Na Cabhaig
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH56NE 29.00
HER Number	MHG20792
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256029
Northing	869222
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Length of drystone dyke c200m long under moss, grass and trees. Composed of boulders and degraded, stands 0.4m tall and spread up to 2m wide. Consistent with field boundary on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXIV. Survey date: 1875, Published: 1881
Asset/Event Number	556.3
Asset/Event Name	Dyke, Eilean Na Cabhaig
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH56NE 29.00
HER Number	MHG20792
Status	Non-designated Heritage Asset
Section:	D1.2 (in access track corridor to section)
Easting	256011
Northing	869210
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke under moss and gorse, standing c0.7 tall and spread up to 2m wide. Composed of fairly large boulders. Partially consistent with field boundaries depicted on the 1st edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXIV. Survey date: 1875, Published: 1881
Asset/Event Number	556.4
Asset/Event Name	Clearance cairn, Eilean Na Cabhaig
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	NH56NE 29.00
HER Number	MHG20792
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256041
Northing	869209
Council	Highland
Condition:	Ruinous
Alignment:	E/W
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A clearance cairn under moss measuring 6m by 2m and standing 0.5m tall.

Asset/Event Number	560
Asset/Event Name	Dyke, Cnoc an Fhasgnaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	255975
Northing	868734
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Small remnants of a drystone revetted dyke c25m long under moss, c0.5m tall, on the SW side of the existing track. May continue further than the extent surveyed but vegetation limited certainty. Consistent with a boundary depicted on the 1st edition OS map, so this may be contemporary. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXIV. Survey date: 1875, Published: 1881
Asset/Event Number	561

Asset/Event Name	Clearance cairn, Cnoc an Fhasgnaidh
Type of Asset/Event	Other
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	255995
Northing	868828
Council	Highland
Condition:	Fair
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Spread of field clearance partially under grass, measuring 13m by 7m and up to 0.2m tall. Situated along the fence line of the improved fields. Part of the field clearance has been reworked into foundations for a water trough.

Asset/Event Number	562.1
Asset/Event Name	Enclosure, Cnoc an Fhasgnaidh
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256003
Northing	868799
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A curving portion of stone and turf dyke measuring c40m long, spread between 1-3m wide and standing up to 1m tall. This represented the partial remains of a N/S field boundary depicted on the 2nd edition OS map that has since mostly been removed. OS. 1907. Ross and Cromarty LXIV. Survey date: 1902, Published: 1907

Asset/Event Number	562.2
Asset/Event Name	Pen, Cnoc an Fhasgnaidh
Type of Asset/Event	Pen
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256022
Northing	868791
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Roughly rectangular drystone pen c13m by 7m, which juts out at SE end of dyke Asset 562.1, to the W. Made up of drystone boulder dyke standing 0.5m tall and 0.25m wide, open to the N. Not depicted on historic mapping.

Asset/Event Number	565
Asset/Event Name	Ditch, Eilean Na Cabhaig
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256037
Northing	869145
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Drainage ditch under grass measuring c140m long and 1-2m wide, depth varying from 0.8-1.5m. The NW extent is consistent with field boundaries depicted on the 1st and 2nd edition OS map. OS. 1881. Ross-shire & Cromartyshire (Mainland) LXIV. Survey date: 1875, Published: 1881 OS. 1907. Ross and Cromarty LXIV. Survey date: 1902, Published: 1907

Asset/Event Number	567
Asset/Event Name	Clearance cairn, Eilean na Cabhaig
Type of Asset/Event	Clearance cairn
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	256075
Northing	869134
Council	Highland

Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Small clearance cairn, c0.25m high, 0.5m across. Some visible stone, turf covered.

Asset/Event Number	568
Asset/Event Name	Rock shelter, Hill of the Cave
Type of Asset/Event	Other
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	255709
Northing	868110
Council	Highland
Condition:	Good
Alignment:	NW
Importance:	Negligible/Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Rock shelter, a natural cave formation that aligns NE/SW and is situated above two waterfalls and a gorge to the SW, accessible through a dried river bed to the NE. The shelter has a large NE entry point 5 to 7m in width, the shelter is about 4m in interior depth, and a smaller entry is visible at the SW end. It is likely the cave referred to with the placename 'Tòrr na h-Uamhaig' (hill/knoll of the cave) on the 1st edition OS map. Some modern detritus was visible, but further/older remains may be concealed at a sub-surface level. The OS name book describes it as: 'A very small knoll situated between River Glass and Allt nan Caorach where both streams nearly meet a distance of about 1/4 mile from where they form a junction. It has derived its name from a little cave on the South side of it. Name means The Knoll of the little cave.' OS. 1881. Ross-shire & Cromartyshire (Mainland) LXIV. Survey date: 1875, Published: 1881 OS Name Book. Ross and Cromarty OS Name Books, 1848-1876. Volume 1. p24. OS1/28/1/24.

Asset/Event Number	569
Asset/Event Name	Bridge, Eas a' Chonaisg
Type of Asset/Event	Bridge
Date and/or Period	Post-medieval/Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D1.2
Easting	255634
Northing	868332

Council	Highland
Condition:	Ruinous
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Former site of bridge over deep gorge with waterfalls along the River Glass. Possible stone footings for the bridge observed from the NE side of the gorge from the opposite bank, with a drystone dyke (outwith track survey corridor) visible extending beyond to the NW. No structural remains visible on the SW bank side. A bridge pier, possibly natural or augmented rock formation, or constructed in stone and mortar but overgrown and obscured by vegetation, stands in the middle of the crossing point. A large wooden beam currently straddles the gap between the SW side of the watercourse and the pier. The bridge has fully collapsed, but would have measured c20m by 7.5m. No bridges are depicted on historic mapping.

Asset/Event Number	570
Asset/Event Name	Clearance cairn, Eas a' Chonaisg
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	D2.1 (within access
Easting	255566
Northing	868320
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Small spread of clearance material within area of mature trees. Irregularly shaped, c0.1-0.25m in height, around 1m across. Largely visible stone but is overgrown with turf and moss.

Asset/Event Number	573
Asset/Event Name	Ditch, Luachair Bhan
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval/modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	C1.2
Easting	255974
Northing	893798
Council	Highland
Condition:	Degraded

Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drainage ditch c1m wide and 0.5m deep, evidence of some banking to either side, but hard to identify due to felled forestry. Not depicted on historic mapping.

Asset/Event Number	575
Asset/Event Name	Clearance cairn, Coir' an t-Seilich Mor
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	259507
Northing	896949
Council	Highland
Condition:	Fair
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An irregular spread of stones under grass and moss, measures 7m by 5m and 0.2m tall.

Asset/Event Number	576
Asset/Event Name	Dyke, Coir' an t-Seilich Mor
Type of Asset/Event	Dyke
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	259532
Northing	896948
Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Large stone and turf dyke c1-1.5m tall and spread up to 5m wide, under moss and grass. Likely related to forestry operations as appears to be at the edge of a former laydown area/turning circle.

Asset/Event Number	577
Asset/Event Name	Dam, Balblair Wood
Type of Asset/Event	Dam
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	
Easting	258619
Northing	896457
Council	Highland
Condition:	Fair
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Possible ford, dam or weir along an un-named burn that forms a tributary of the Allt a' Choir'-uisge. Visible as a line of stones c0.5m wide running from jutting dry ground on N side across to the S side, c4-5m long. Not depicted on historic mapping.

Asset/Event Number	578.1
Asset/Event Name	Clearance cairn, Henman's Burn
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH59NE 24
HER Number	MHG12918
Status	Non-designated Heritage Asset
Section:	N/A
Easting	258252
Northing	896412
Council	Highland
Condition:	Very Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Large spread of field clearance under moss with indeterminate edges, measuring's 20m by 15m and stands up to 0.3m tall. Https://her.highland.gov.uk/Monument/MHG12918 Centred on NH 582 964 is a field system of a type usually associated with hut circle settlement. It is best seen as an open to scattered density of stone clearance mounds interspersed with sporadic linear clearance; occasional lynchets are also in evidence. One or two cultivation plots of approximately 20.0m by 25.0m are discernible. The situation is in rising moorland open to the W. Visited by OS (J M) 4 November 1976. (NH 5806 9640) A possible hut circle, 5m in diameter and 0.5m high.

	R J Mercer 1980. There is no hut circle at this map reference or in the vicinity. The feature was not positively identified but there are one or two configurations of stone clearance which could fit the description. This field-system has largely been destroyed by the creation of a forestry plantation. Visited by RCAHMS (JRS) October 1989. --- SHG2510 Text/Report/Fieldwork Report: Mercer, R. J. & Howell, J.M.. 1980. Archaeological field survey in northern Scotland, 1976-1979. University of Edinburgh. 30/01/1980. Paper and Digital. 44-5, 130, BAL No. 9.
Asset/Event Number	578.2
Asset/Event Name	Clearance cairn, Henman's Burn
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH59NE 24
HER Number	MHG12918
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257976
Northing	896407
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn forming part of the wider field system that comprises MHG12918. The clearance cairns are visible on Scotland (Phase 2) LiDAR imagery but could not be confidently identified during the walkover survey due to dense bracken and heather vegetation. For HER asset description see Asset 578.1.
Asset/Event Number	578.3
Asset/Event Name	Clearance cairn, Henman's Burn
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH59NE 24
HER Number	MHG12918
Status	Non-designated Heritage Asset
Section:	
Easting	258018
Northing	896375
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn forming part of the wider field system that comprises MHG12918. The clearance cairns are visible on Scotland (Phase 2) LiDAR imagery but could not be confidently identified during the walkover survey due to dense bracken and heather vegetation. For HER asset description see Asset 578.1.
Asset/Event Number	578.4
Asset/Event Name	Clearance cairn, Henman's Burn
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH59NE 24
HER Number	MHG12918
Status	Non-designated Heritage Asset
Section:	
Easting	258025
Northing	896357
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn forming part of the wider field system that comprises MHG12918. The clearance cairns are visible on Scotland (Phase 2) LiDAR imagery but could not be confidently identified during the walkover survey due to dense bracken and heather vegetation. For HER asset description see Asset 578.1.
Asset/Event Number	578.5
Asset/Event Name	Clearance cairn, Henman's Burn
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH59NE 24
HER Number	MHG12918
Status	Non-designated Heritage Asset
Section:	
Easting	258039
Northing	896343
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn forming part of the wider field system that comprises MHG12918. The clearance cairns are visible on Scotland (Phase 2) LiDAR imagery but could not be confidently identified during the walkover survey due to dense bracken and heather vegetation. For HER asset description see Asset 578.1.
Asset/Event Number	578.6

Asset/Event Name	Clearance cairn, Henman's Burn
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH59NE 24
HER Number	MHG12918
Status	Non-designated Heritage Asset
Section:	
Easting	258042
Northing	896334
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn forming part of the wider field system that comprises MHG12918. The clearance cairns are visible on Scotland (Phase 2) LiDAR imagery but could not be confidently identified during the walkover survey due to dense bracken and heather vegetation. For HER asset description see Asset 578.1.

Asset/Event Number	578.7
Asset/Event Name	Clearance cairn, Henman's Burn
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH59NE 24
HER Number	MHG12918
Status	Non-designated Heritage Asset
Section:	
Easting	258057
Northing	896336
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn forming part of the wider field system that comprises MHG12918. The clearance cairns are visible on Scotland (Phase 2) LiDAR imagery but could not be confidently identified during the walkover survey due to dense bracken and heather vegetation. For HER asset description see Asset 578.1.

Asset/Event Number	578.8
Asset/Event Name	Clearance cairn, Henman's Burn
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH59NE 24
HER Number	MHG12918

Status	Non-designated Heritage Asset
Section:	
Easting	258050
Northing	896348
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn forming part of the wider field system that comprises MHG12918. The clearance cairns are visible on Scotland (Phase 2) LiDAR imagery but could not be confidently identified during the walkover survey due to dense bracken and heather vegetation. For HER asset description see Asset 578.1.

Asset/Event Number	578.9
Asset/Event Name	Clearance cairn, Henman's Burn
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH59NE 24
HER Number	MHG12918
Status	Non-designated Heritage Asset
Section:	
Easting	258055
Northing	896370
Council	Highland
Condition:	Unknown
Alignment:	Unknown
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn forming part of the wider field system that comprises MHG12918. The clearance cairns are visible on Scotland (Phase 2) LiDAR imagery but could not be confidently identified during the walkover survey due to dense bracken and heather vegetation. For HER asset description see Asset 578.1.

Asset/Event Number	578.10
Asset/Event Name	Clearance cairn, Henman's Burn
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	NH59NE 24
HER Number	MHG12918
Status	Non-designated Heritage Asset
Section:	
Easting	258040
Northing	896372
Council	Highland

Condition:	Unknown
Alignment:	Unknown
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn forming part of the wider field system that comprises MHG12918. The clearance cairns are visible on Scotland (Phase 2) LiDAR imagery but could not be confidently identified during the walkover survey due to dense bracken and heather vegetation. For HER asset description see Asset 578.1.
Asset/Event Number	580
Asset/Event Name	Dyke, Invershin Castle
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	257543
Northing	896240
Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Low linear earth mound confirming to modern fenced field boundary. Variable height, but up to 1m tall, and measures 0.5 across. Fully turf, no visible stone. Recorded extent c150m long, but continued outwith survey corridor to the NW and SE. Depicted on the 2nd edition OS map. OS. 1907. Ross and Cromarty XVIII, Surveyed: 1903, Published: 1907.
Asset/Event Number	581.1
Asset/Event Name	Possible earthwork, Invershin
Type of Asset/Event	Earthwork
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257638
Northing	896216
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Negligible/Low

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A mound under grass measuring 80m by 20m and standing c10m tall, forming an irregular-shaped earthwork set on the edge of a hill. Possibly natural, or accumulated bunds related to modern farming. Not depicted on historic mapping.

Asset/Event Number	581.2
Asset/Event Name	Earthwork, Invershin
Type of Asset/Event	Earthwork
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257731
Northing	896198
Council	Highland
Condition:	Very degraded
Alignment:	Curving
Importance:	Negligible/Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An arcing mound under grass measuring c45m long by 10m wide and c5m tall, situated atop a W facing slope. Possibly natural, or accumulated bunds related to modern farming. Not depicted on historic mapping.

Asset/Event Number	581.3
Asset/Event Name	Borrow pit or hollow, Invershin
Type of Asset/Event	Hollow
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257732
Northing	896211
Council	Highland
Condition:	Very degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hollow under grass, measuring c5m in diameter and 1m deep. Closely situated to similar hollow Asset 581.4. Possibly mechanically excavated.

Asset/Event Number	581.4
Asset/Event Name	Borrow pit or hollow, Invershin

Type of Asset/Event	Hollow
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	N/A
Easting	257734
Northing	896207
Council	Highland
Condition:	Very degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A hollow under grass, measuring c5m in diameter and 1m deep. Closely situated to similar hollow Asset 581.3. Possibly mechanically excavated.

Asset/Event Number	582
Asset/Event Name	Dyke, Salachaidh
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG63032
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	264657
Northing	897532
Council	Highland
Condition:	Very degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke under heather, standing up to 0.5m tall and spread 1.5m wide, c570m long. Not depicted on historic mapping. Https://her.highland.gov.uk/Monument/MHG63032 A stretch of dyke was recorded near Loch Bhuidhe by CFA Archaeology in 2006 in advance of the Beauly to Dounreay 275kV overhead transmission line. Field survey identified the remains of a stone and turf bank aligned E-W and measuring approximately 50m in length near the location for Tower 277. The bank was 1-1.2m wide and 0.5m high, and covered in heather. <1> The feature can be clearly seen on vertical aerial photographs extending for a considerable distance eastwards and south-southeastwards and may have been an enclosure or head dyke for a farmstead the remains of which remain to be identified - they may lie under the conifer plantation to the east. The dyke is not shown on any historic OS mapping. <2> <1> SHG24982 Text/Report/Fieldwork Report: CFA Archaeology Ltd. 2008-2010. Beauly-Dounreay 275kV Overhead Transmission Line: Second Circuit Environmental Statement.

	Chapter 10: Cultural Heritage. CFA Archaeology Ltd. Digital. Site 277.1. <2> SHG27491 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 1999-2001. Get Mapping colour vertical aerial photography 1999-2001 (The Millennium Map). XY
Asset/Event Number	583
Asset/Event Name	Peat cutting, Salachaidh
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG63030
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	264451
Northing	897598
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An arcing area of peat cutting under grass, measuring c30m long and 2-5m wide.

Asset/Event Number	584
Asset/Event Name	Clearance cairn, Salachaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG63030
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	264401
Northing	897587
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Oval shaped spread of clearance material under moss and turf measures 4.8m by 2m and stands 0.2m tall.

Asset/Event Number	585.1
Asset/Event Name	Farmstead, Salachaidh
Type of Asset/Event	Building

Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG63030
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	264277
Northing	897635
Council	Highland
Condition:	Degraded
Alignment:	ENE/WSW
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Ruinous farmstead under grass and moss measuring 27m by 4m over walls constructed from rubble that delineate three compartments over raised undulating ground, suggesting possible three terraced buildings. Walls stand 0.6m tall and 0.7m wide and entrances appear to be in the S elevation due to visible depressions in the walls. The W compartment measures 5m by 4m internally, the middle compartment measures 11m by 4m internally, and the E compartment measures 5m by 4m internally. Consistent with a roofed building depicted on the 1st edition OS map associated with the Salachaidh farmstead. The building is shown as unroofed by the time of the 2nd edition OS map. OS. 1879. Sutherland CVIII, Surveyed: 1874, Published: 1879 OS. 1907. Sutherland CVIII, Surveyed: 1903, Published: 1907 https://her.highland.gov.uk/Monument/MHG63032 A ruined farmstead at Sallachy near Loch Bhuidhe. The remains of a multi-roomed building orientated approximately east-west and enclosure dykes are visible on vertical aerail photographs taken in 1999-2001. <1> <1> SHG27491 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 1999-2001. Get Mapping colour vertical aerial photography 1999-2001 (The Millennium Map). XY
Asset/Event Number	585.2
Asset/Event Name	Building, Salachaidh
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG63030
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	264271
Northing	897622
Council	Highland
Condition:	Very Degraded
Alignment:	E/W
Importance:	Low

Description	*Recorded by AOC Archaeology during 2024 walkover survey. Small building under grass and moss measuring 6.5m by 4m over walls, which stand 0.6m wide and 0.4m tall. Two possible compartments but rubble is obscuring. Situated on low terrace of E-facing slope. Possibly the roofed building depicted on the 1st edition OS map associated with the Salachaidh farmstead. This building is shown as unroofed by the time of the 2nd edition OS map. For HER asset description see Asset 585.1. OS. 1879. Sutherland CVIII, Surveyed: 1874, Published: 1879 OS. 1907. Sutherland CVIII, Surveyed: 1903, Published: 1907
Asset/Event Number	585.3
Asset/Event Name	Agricultural landscape, Salachaidh
Type of Asset/Event	Field system
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG63030
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	264367
Northing	897614
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Improved grassy field c55m by 22m, associated with the Salachaidh farmstead Asset 585/MHG63030. For HER asset description see Asset 585.1.

Asset/Event Number	585.4
Asset/Event Name	Agricultural landscape, Salachaidh
Type of Asset/Event	Field system
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG63030
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	264293
Northing	897594
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Improved grassy field c140m by 60m, associated with the Salachaidh farmstead Asset 585/MHG63030. For HER asset description see Asset 585.1.

Asset/Event Number	585.5
Asset/Event Name	Storage pit, Salachaidh
Type of Asset/Event	Hollow
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG63030
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	264320
Northing	897602
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Small rectangular shaped hollow under grass measuring 4m by 1.8m and 0.2-0.4m deep with a rounded profile, one of four (Assets 585.6-585.8) situated along a raised ridge from the surrounding area. Some stone is felt underfoot along the base. Likely a series of storage pits for vegetables. Not depicted on historic mapping. For HER asset description see Asset 585.1.

Asset/Event Number	585.6
Asset/Event Name	Storage pit, Salachaidh
Type of Asset/Event	Hollow
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG63030
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	264322
Northing	897606
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Small rectangular shaped hollow under grass measuring 4m by 1.8m and 0.2-0.4m deep with a rounded profile, one of four (Assets 585.6-585.8) situated along a raised ridge from the surrounding area. Some stone is felt underfoot along the base. Likely a series of storage pits for vegetables. Not depicted on historic mapping. For HER asset description see Asset 585.1.

Asset/Event Number	585.7
Asset/Event Name	Storage pit, Salachaidh
Type of Asset/Event	Hollow
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A

HER Number	MHG63030
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	264325
Northing	897610
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Small rectangular shaped hollow under grass measuring 4m by 1.8m and 0.2-0.4m deep with a rounded profile, one of four (Assets 585.6-585.8) situated along a raised ridge from the surrounding area. Some stone is felt underfoot along the base. Likely a series of storage pits for vegetables. Not depicted on historic mapping. For HER asset description see Asset 585.1.
Asset/Event Number	585.8
Asset/Event Name	Storage pit, Salachaidh
Type of Asset/Event	Hollow
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG63030
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	264327
Northing	897614
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Small rectangular shaped hollow under grass measuring 4m by 1.8m and 0.2-0.4m deep with a rounded profile, one of four (Assets 585.6-585.8) situated along a raised ridge from the surrounding area. Some stone is felt underfoot along the base. Likely a series of storage pits for vegetables. Not depicted on historic mapping. For HER asset description see Asset 585.1.
Asset/Event Number	585.9
Asset/Event Name	Agricultural landscape, Salachaidh
Type of Asset/Event	Field system
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG63030
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	264246
Northing	897600

Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Improved grassy field c70m by 22m, associated with the Salachaidh farmstead Asset 585/MHG63030. For HER asset description see Asset 585.1.

Asset/Event Number	585.10
Asset/Event Name	Corn drying kiln, Salachaidh
Type of Asset/Event	Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG63030
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	264245
Northing	897616
Council	Highland
Condition:	Ruinous
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A corn-drying kiln under grass, measuring c6m in diameter over the walls/banks, constructed against and partially revetted into a SE-facing slope. Stands 0.7m tall with a slightly dished interior, very infilled. The flue is visible extending to the SSW. A roofed rectangular structure in the vicinity is shown on the 1st edition OS map and may be meant to indicate this. This building is shown as unroofed by the time of the 2nd edition OS map. For HER asset description see Asset 585.1. OS. 1879. Sutherland CVIII, Surveyed: 1874, Published: 1879 OS. 1907. Sutherland CVIII, Surveyed: 1903, Published: 1907

Asset/Event Number	585.11
Asset/Event Name	Enclosure, Salachaidh
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG63030
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	264276
Northing	897639
Council	Highland
Condition:	Very degraded
Alignment:	E/W

Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Remnants of a yard attached to the N side of the farmstead building Asset 585.11. Drystone dyke under moss and grass, measuring 18m by 11m over walls. Depicted on the 1st edition OS map. For HER asset description see Asset 585.1. OS. 1879. Sutherland CVIII, Surveyed: 1874, Published: 1879
Asset/Event Number	585.12
Asset/Event Name	Corn drying kiln, Salachaidh
Type of Asset/Event	Kiln
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG63030
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	264238
Northing	897610
Council	Highland
Condition:	Ruinous
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A probable corn-drying kiln under reeds and grass, visible as a slight mound partially lying over the SE-facing hill slope. Similar situated as kiln Asset 585.13, but more poorly preserved. Mound stands less than 0.5m tall and has no visible flue. Perhaps robbed for the nearby kiln. Not depicted on historic mapping. For HER asset description see Asset 585.1.
Asset/Event Number	585.14
Asset/Event Name	Clearance cairn, Salachaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG63030
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	264237
Northing	897538
Council	Highland
Condition:	Degraded
Alignment:	Circular
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn under grass measuring 0.m in diameter and c0.5m tall. For HER asset description see Asset 585.1.

Asset/Event Number	585.15
Asset/Event Name	Clearance cairn, Salachaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG63030
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	264226
Northing	897554
Council	Highland
Condition:	Fair
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn under grass, measuring 4.5m by 3m and stands 1m tall. For HER asset description see Asset 585.1.

Asset/Event Number	585.16
Asset/Event Name	Clearance cairn, Salachaidh
Type of Asset/Event	Clearance cairn
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG63030
Status	Non-designated Heritage Asset
Section:	C1.1
Easting	264217
Northing	897593
Council	Highland
Condition:	Fair
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Clearance cairn under grass, measuring 4m by 3m and stands 0.25m tall. For HER asset description see Asset 585.1.

Asset/Event Number	600.1
Asset/Event Name	Clearance cairn, Bridge of Horn
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	MHG10597

Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279768
Northing	904714
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A small mound under bracken and grass measuring c5m in diameter and standing 0.7m tall. No stone visible. Https://her.highland.gov.uk/monument/MHG10597 At NC 795 045, at the base of a steepening south-facing slope, is a close group of three similar hut circles (A-C), now overgrown with heather. They measure from 13m by 11.5m to 12.5m by 10.5m within tumbled walls spread from 2.5m-3.5m, and up to 0.6m high. The entrance in each case is in the south or south-south-east on the line of the longer axis. There is no definite evidence of cultivation around the huts, but some 200m to the NE are several stone clearance heaps and cleared ground, which are probably contemporary with the huts. Surveyed at 1:10,000. Visited by OS (N K B) 15 May 1981. NGR adjusted based on 2020 vertical aerial photographs. <1> --- SHG1568 Text/Publication/Article: Harden, J. 1990. 'Survey Dunrobin Glen (Golspie parish)', Discovery and Excavation in Scotland 1990, p.28. Discovery and Excavation in Scotland. 28. 28. <1> SHG28725 Image/Photograph(s)/Aerial Photograph/Vertical: Get Mapping. 2020. Getmapping aerial photography 2020. XY
Asset/Event Number	600.2
Asset/Event Name	Clearance cairn, Bridge of Horn
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	MHG10597
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279759
Northing	904710
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A possible clearance cairn under bracken and moss. Stands 1.2m tall and spread up to 4m in diameter. For HER asset description see Asset 600.1.
Asset/Event Number	600.3
Asset/Event Name	Clearance cairn, Bridge of Horn

Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	MHG10597
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279737
Northing	904720
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass, stands 0.9m tall and spread 6m by 4m. For HER asset description see Asset 600.1.

Asset/Event Number	600.4
Asset/Event Name	Clearance cairn, Bridge of Horn
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	MHG10597
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279727
Northing	904710
Council	Highland
Condition:	Degraded
Alignment:	N/A
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass. Measures 0.6m tall and diameter of 6m. For HER asset description see Asset 600.1.

Asset/Event Number	600.5
Asset/Event Name	Lynchet, Bridge of Horn
Type of Asset/Event	Lynchet
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	MHG10597
Status	Non-designated Heritage Asset
Section:	B1.1

Easting	279771
Northing	904684
Council	Highland
Condition:	Very degraded
Alignment:	E/W
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf bank under bracken, partly revetted and spread to c2m wide and up to 0.5m tall, forming a lynchet c8m long. Large stones visible under vegetation. For HER asset description see Asset 600.1.

Asset/Event Number	600.6
Asset/Event Name	Clearance cairn, Bridge of Horn
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	MHG10597
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279710
Northing	904717
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass. Stands 0.8m tall and spread 6m by 3.5m. For HER asset description see Asset 600.1.

Asset/Event Number	600.7
Asset/Event Name	Clearance cairn, Bridge of Horn
Type of Asset/Event	Clearance cairn
Date and/or Period	Prehistoric
Listing No./NRHE Number	N/A
HER Number	MHG10597
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279709
Northing	904696
Council	Highland
Condition:	Degraded
Alignment:	E/W
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A prehistoric clearance cairn under heather and grass. Stands 0.6m tall and spread 5m by 3.5m. For HER asset description see Asset 600.1.

Asset/Event Number	601
Asset/Event Name	Structure, Allt nan Sgeith
Type of Asset/Event	Structure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279564
Northing	904448
Council	Highland
Condition:	Very Degraded
Alignment:	N/S
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A rectangular stone and turf structure measuring 9m by 5m, situated within a large circular hollow next to hut circle settlement (Asset 115 group) to the NE. Banks are spread up to 2m wide with large boulder visible that stand 0.5m tall, and a possible partition is somewhat discernible. May be contemporary with the nearby prehistoric settlement (MHG10597; For HER asset description see Asset 600.1), but its regular form is more in keeping with a post-medieval structure.

Asset/Event Number	602
Asset/Event Name	Dyke, Allt Cnoc na Gamhna
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279574
Northing	904371
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A series of turf and stone dykes under grass and heather, running intermittently alongside the stream and enclosing small meanders. The dyke stands 0.3m tall and 0.5m wide and 0.3m tall and partly revetted. Uncertain function, possibly related to water course augmentation. Not depicted on historic mapping.

Asset/Event Number	603
Asset/Event Name	Dyke, Allt nan Sgeith
Type of Asset/Event	Dyke
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279458
Northing	904463
Council	Highland
Condition:	Very degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A very degraded dyke, likely stone and turf but now only intermittent stones survive, with some spread up to 2m wide and c40m long, but marked only by occasional stone rather than a true spread. Possibly related to Asset 602 but did not clearly cross the burn to join. Possibly of a later date than the nearby hut circle settlement. Not depicted on historic mapping.

Asset/Event Number	604
Asset/Event Name	Dyke, Allt Cnoc na Gamhna
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	279156
Northing	904028
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drystone dyke under dense bracken, spread to 0.8m wide and up to 0.5m tall. C40m long. Not depicted on historic mapping. Likely associated with nearby farmstead Asset 139/MHG10398, but falls outwith the HER asset extent. For HER asset description see Asset 139.

Asset/Event Number	605.1
Asset/Event Name	Drainage ditch and upcast bank, Allt Cnoc na Gamhna
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A

HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	278524
Northing	903448
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat grip (drainage ditch) measuring c0.75m wide and up to 1m deep, c150m long with an associated tussocky bank beside it up to c1m wide and c0.2m tall representing the excavation upcast. The peat grip has been excavated into a slight NW-facing slope allowing drainage into the Allt Cnoc na Gamhna burn. The peat grip is contained within the survey corridor. Not depicted on historic mapping.
Asset/Event Number	605.2
Asset/Event Name	Drainage ditch and upcast bank, Allt Cnoc na Gamhna
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	278495
Northing	903383
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat grip (drainage ditch) measuring c0.75m wide and up to 1m deep, recorded extent measures c210m with an associated tussocky bank beside it up to c1m wide and c0.2-3m tall representing the excavation upcast long but continues outwith survey corridor to the SE. The peat grip has been excavated into a slight NW-facing slope allowing drainage into the Allt Cnoc na Gamhna burn. Not depicted on historic mapping.
Asset/Event Number	605.3
Asset/Event Name	Drainage ditch and upcast bank, Allt Cnoc na Gamhna
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	278475

Northing	903323
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat grip (drainage ditch) measuring c0.75m wide and up to 1m deep, recorded extent measures c140m long with an associated tussocky bank beside it up to c0.8m wide and c0.2m tall representing the excavation upcast but continues outwith survey corridor to the SE. The peat grip has been excavated into a slight NW-facing slope allowing drainage into the Allt Cnoc na Gamhna burn. Not depicted on historic mapping.
Asset/Event Number	605.4
Asset/Event Name	Drainage ditch and upcast bank, Allt Cnoc na Gamhna
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	278448
Northing	903272
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat grip (drainage ditch) measuring c0.75m wide and up to 1m deep, the recorded extent measures c85m long with an associated tussocky bank beside it up to c1m wide and c0.2m tall representing the excavation upcast but continues outwith survey corridor to the SE. The peat grip has been excavated into a slight NW-facing slope allowing drainage into the Allt Cnoc na Gamhna burn. Not depicted on historic mapping.
Asset/Event Number	605.5
Asset/Event Name	Drainage ditch and upcast bank, Allt Cnoc na Gamhna
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	278410
Northing	903235
Council	Highland
Condition:	Degraded

Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat grip (drainage ditch) measuring c0.75m wide and up to 1m deep, recorded extent measures c75m long with an associated tussocky bank beside it up to c1m wide and c0.2m tall representing the excavation upcast, but continues outwith the survey corridor to the SE. The peat grip has been excavated into a slight NW-facing slope allowing drainage into the Allt Cnoc na Gamhna burn. Not depicted on historic mapping.
Asset/Event Number	605.6
Asset/Event Name	Drainage ditch and upcast bank, Allt Cnoc na Gamhna
Type of Asset/Event	Ditch
Date and/or Period	Modern
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	278386
Northing	903232
Council	Highland
Condition:	Fair
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A cut earth drain c65m long in the peat measuring 1.3m deep and c1m wide, with a clear bank of relict upcast material respecting the E side measuring c0.8m wide and 0.2m tall, itself visible as a series of turfy tussocks. Extends down to the stream to the N and extent contained within the survey corridor. Not depicted on historic mapping.
Asset/Event Number	605.7
Asset/Event Name	Drainage ditch and upcast bank, Allt Cnoc na Gamhna
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	278298
Northing	903212
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat grip (drainage ditch) measuring c0.75m wide and up to 1m deep, c100m long with an associated tussocky bank beside it up to c1m wide and c0.2m tall representing the excavation upcast. The peat grip has been excavated into a SE-facing slope allowing drainage into the Allt Cnoc na Gamhna burn. The peat grip is contained within the survey corridor. Not depicted on historic mapping.
Asset/Event Number	605.8
Asset/Event Name	Drainage ditch and upcast bank, Allt Cnoc na Gamhna
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	278254
Northing	903206
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat grip (drainage ditch) measuring c0.75m wide and up to 1m deep, recorded extent measuring c190m long with an associated tussocky bank beside it up to c1m wide and c0.2m tall representing the excavation upcast, but continuing outwith survey corridor to the NW. The peat grip has been excavated into a SE-facing slope allowing drainage into the Allt Cnoc na Gamhna burn. Not depicted on historic mapping.
Asset/Event Number	605.9
Asset/Event Name	Drainage ditch and upcast bank, Allt Cnoc na Gamhna
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	278338
Northing	903042
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat grip (drainage ditch) measuring up to 1m wide and up to 1m deep, with an associated tussocky bank beside it up to c0.8m wide and c0.2m tall representing the excavation upcast. The peat grip has been excavated into a gentle NE-facing slope allowing drainage into the Allt Cnoc na Gamhna burn. The peat grip continues outwith the survey corridor to the S, c190m long. Not

	depicted on historic mapping.
Asset/Event Number	605.10
Asset/Event Name	Drainage ditch and upcast bank, Allt Cnoc na Gamhna
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	278227
Northing	903038
Council	Highland
Condition:	Degraded
Alignment:	N/S
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat grip (drainage ditch) measuring up to 1m wide and up to 1m deep with an associated tussocky bank beside it up to c1m wide and c0.1m tall representing the excavation upcast. The peat grip has been excavated into a gentle NE-facing slope allowing drainage into the Allt Cnoc na Gamhna burn. Recorded extent measures c190m long, but the peat grip continues outwith the survey corridor to the S. Not depicted on historic mapping.
Asset/Event Number	605.11
Asset/Event Name	Drainage ditch and upcast bank, Allt Cnoc na Gamhna
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1 (in access track corridor to section)
Easting	278203
Northing	902976
Council	Highland
Condition:	Degraded
Alignment:	WSW/ENE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat grip (drainage ditch) measuring up to 1m wide and up to 1m deep, measuring c80m long with an associated tussocky bank beside it up to c0.7m wide and c0.2m tall representing the excavation upcast. The peat grip has been excavated into a gentle E-facing slope allowing drainage into a larger drain (Asset 605.10) that drains into the Allt Cnoc na Gamhna burn. Not depicted on historic mapping.
Asset/Event Number	605.12
Asset/Event Name	Drainage ditch and upcast bank, Allt Cnoc na Gamhna

Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	278174
Northing	903051
Council	Highland
Condition:	Degraded
Alignment:	WSW/ENE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat grip (drainage ditch) measuring up to 1m wide and up to 1m deep, measuring c120m long with an associated tussocky bank beside it up to c0.8m wide and c0.2m tall representing the excavation upcast. The peat grip has been excavated into a gentle E-facing slope allowing drainage into a larger drain (Asset 605.10) that drains into the Allt Cnoc na Gamhna burn. Not depicted on historic mapping.

Asset/Event Number	605.13
Asset/Event Name	Drainage ditch and upcast bank, Allt Cnoc na Gamhna
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	B1.1
Easting	277955
Northing	902882
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat grip (drainage ditch) measuring up to 1m wide and up to 1m deep, recorded extent measuring c220m long with an associated tussocky bank beside it up to c0.7m wide and c0.1m tall representing the excavation upcast, but continues outwith the survey corridor to the E. The peat grip has been excavated into a gentle E-facing slope allowing drainage into a larger drain (Asset 605.10) that drains into the Allt Cnoc na Gamhna burn. Not depicted on historic mapping.

Asset/Event Number	606
Asset/Event Name	Peat bank, Feithe Ruadh
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A

Status	Non-designated Heritage Asset
Section:	
Easting	277661
Northing	904551
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A peat bank under grass and heather, very narrow cut c1m wide extending in an L-shape 20m by 20m.

Asset/Event Number	607
Asset/Event Name	Quarry, Halsary
Type of Asset/Event	Quarry
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG53515
Status	Non-designated Heritage Asset
Section:	A1.2
Easting	318173
Northing	948978
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An old stone quarry under grass, visible as the cut in remnants to the SE face of a small rocky knoll. Some bare stone visible in parts. C25m by 6m. Within larger peat cutting area Asset 608.1. Not depicted on historic mapping.

Asset/Event Number	608.1
Asset/Event Name	Farmstead, Halsary
Type of Asset/Event	Farmstead
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG53513
Status	Non-designated Heritage Asset
Section:	A1.2
Easting	318096
Northing	949051
Council	Highland

Condition:	Unknown
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Part of the Halsary farmstead (MHG53513), the polygon represents the asset extent from the HER, which in turn appears to be drawn from the 1st edition OS map. The farmstead buildings are included within this, surrounded by improved ground. OS. 1877. Caithness XXIII, Surveyed: 1871, Published: 1877. Https://her.highland.gov.uk/monument/MHG53513 Desk-based assessment in July 2008 identified "Helvry" Farmstead, depicted on Roy's Military Survey map (1747-55) as a cluster of buildings either side of a watercourse and surrounded by unenclosed fields. The main survey settlement appears to be on the west bank of the watercourse. Thomson's map (1822) depicts the farmstead, named there as 'Halzary'. The Ordnance Survey 1st Edition map (1877) shows 'Halsary' as a group of four roofed structures, including one long building, and two enclosed fields at the north end of an area of unenclosed improved ground. There are also two wells depicted.Field survey recorded one harled roofed farmhouse and three associated outbuildings. One of these is built of wood, one of concrete blocks and the third is a large metal shed. It was not possible to determine the date of the present farmhouse. Two short sections of field bank (amounting to no more than 75m in total length) were recorded at the extreme southern corner of the clearing around the farmstead. The existing field boundaries are all post and wire fences. An area of remnant rig and furrow is present at the southern end of the clearing. <1>Sources/Archives (1)<1> SHG24678 Text/Report/Environmental Statement: CFA Archaeology Ltd. 2009. Halsary Windfarm Environmental Statement: Archaeology and Cultural Heritage. CFA Archaeology Ltd. 11/2009. Digital (scanned as PDF). Site 6.
Asset/Event Number	608.2
Asset/Event Name	Farmstead, Halsary
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG53513
Status	Non-designated Heritage Asset
Section:	A1.2
Easting	318330
Northing	949114
Council	Highland
Condition:	Unknown
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Part of the Halsary farmstead (MHG53513), the polygon represents the asset extent from the HER, which in turn appears to be drawn from the 1st edition OS map. Depicted as a small area of improved ground on the 1st edition OS map, at the time of the survey this area was under cleared forestry. For HER description see Asset 608.1. OS. 1877. Caithness XXIII, Surveyed: 1871, Published: 1877.
Asset/Event Number	608.3
Asset/Event Name	Farmstead, Halsary
Type of Asset/Event	Enclosure

Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG53513
Status	Non-designated Heritage Asset
Section:	A1.2
Easting	318174
Northing	948809
Council	Highland
Condition:	Unknown
Alignment:	N/A
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Part of the Halsary farmstead (MHG53513), the polygon represents the asset extent from the HER, which in turn appears to be drawn from the 1st edition OS map. Depicted as a small area of improved ground on the 1st edition OS map, at the time of the survey this appeared as an area of felled forestry. For HER description see Asset 608.1. OS. 1877. Caithness XXIII, Surveyed: 1871, Published: 1877.
Asset/Event Number	608.4
Asset/Event Name	Farmstead, Halsary
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	MHG53513
Status	Non-designated Heritage Asset
Section:	N/A
Easting	318050
Northing	949235
Council	Highland
Condition:	Unknown
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Part of the Halsary farmstead (MHG53513), the polygon represents the asset extent from the HER, which in turn appears to be drawn from the 1st edition OS map. Depicted as an enclosure surrounding improved land, this was not visited during the walkover survey as outwith the survey corridor. For HER description see Asset 608.1. OS. 1877. Caithness XXIII, Surveyed: 1871, Published: 1877.
Asset/Event Number	609
Asset/Event Name	Ditch, Halsary Burn
Type of Asset/Event	Ditch
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset

Section:	A1.2
Easting	318880
Northing	949576
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A drainage ditch (peat grip) under heather and moss, measuring 1.5m wide and 0.4m deep, the recorded extent measures c210m long but extends outwith the survey corridor to the SE. It is depicted on the 1st edition OS map, leading NW from a boggy area annotated as 'The Flows', draining it into the Halsary Burn to the NW. OS. 1877. Caithness XXIII Surveyed: 1871, Published: 1877.
Asset/Event Number	610
Asset/Event Name	Mound, Black Hillocks
Type of Asset/Event	Mound
Date and/or Period	Unknown
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.1
Easting	319265
Northing	950216
Council	Highland
Condition:	Fair
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large mound under grass, measuring c20m long and 11m wide and standing 2m tall. Situated to the immediate W of the Halsary burn. The vegetation does not appear long-established and so the asset is potentially modern, possibly related to the adjacent wind farm construction.
Asset/Event Number	611
Asset/Event Name	Peat cutting, Achavanich
Type of Asset/Event	Peat cutting
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.2
Easting	318142
Northing	942456
Council	Highland

Condition:	Degraded
Alignment:	NW/SE
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. An L-shaped peat cutting under grass and moss, c27m by 7m with banks 0.3m deep. Dis-used.

Asset/Event Number	612
Asset/Event Name	Track, Achavanich
Type of Asset/Event	Track
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.2
Easting	318326
Northing	942136
Council	Highland
Condition:	Degraded
Alignment:	Curving
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A relict track under grass, possibly augmented/widened by peat cutting at edges. Measures as much as 6m wide and leads through the large enclosure Asset 612, along the N side of the Burn of Aultachlevan Burn. It extends beyond the survey corridor to the NE and SW, c650m long, linking the Achavanich road to the NE with the A9 to the SW. It is depicted on the 1st and 2nd edition OS maps. OS. 1877. Caithness XXVIII Surveyed: 1871, Published: 1877. OS. 1907. Caithness-shire XXVIII. Surveyed: 1905, Published: 1907.

Asset/Event Number	613
Asset/Event Name	Enclosure, Achavanich
Type of Asset/Event	Enclosure
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.2
Easting	318269
Northing	941914
Council	Highland
Condition:	Degraded
Alignment:	Various
Importance:	Negligible

Description	*Recorded by AOC Archaeology during 2024 walkover survey. A large irregular-shaped enclosure under grass, measuring c340m by 300m and terminating at the A9 road to the W. It has been constructed around the Burn of Aultachlevan, and is composed of a large turf dyke that stands up to 1.1m tall and spread up to 6m wide, constructed from the upcast material of the ditch that runs externally to this, visible under grass and c1m wide at the base, 2.5m wide at the top, and c0.7-1m deep. A broad track (Asset 612) bisects the enclosure from the NE to the SW, leading from the Achavanich road to the NE to the A9 to the SW. Three possible structures (Assets 6144-616) are situated within the enclosure. It is depicted on the 1st and 2nd edition OS maps. OS. 1877. Caithness XXVIII Surveyed: 1871, Published: 1877. OS. 1907. Caithness-shire XXVIII. Surveyed: 1905, Published: 1907.
Asset/Event Number	614
Asset/Event Name	Mound, Achavanich
Type of Asset/Event	Mound
Date and/or Period	Unknown/Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.2
Easting	318193
Northing	942090
Council	Highland
Condition:	Very Degraded
Alignment:	NNW/SSE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A sub-rectangular mound under grass, measuring c10m by 4m and up to 1m tall, possibly the very degraded remains of a structure or a house platform. Not depicted on historic mapping.

Asset/Event Number	615
Asset/Event Name	Mound, Achavanich
Type of Asset/Event	Mound
Date and/or Period	Unknown/Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.2
Easting	318218
Northing	942041
Council	Highland
Condition:	Very Degraded
Alignment:	N/A
Importance:	Low

Description	*Recorded by AOC Archaeology during 2024 walkover survey. An irregularly shaped mound under grass measuring c8m in diameter and standing up to 1m tall and may be the very degraded remains of a structure or a house platform. Not depicted on historic mapping.
Asset/Event Number	616
Asset/Event Name	Building, Achavanich
Type of Asset/Event	Building
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.2
Easting	318319
Northing	942081
Council	Highland
Condition:	Degraded
Alignment:	NW/SE
Importance:	Low
Description	*Recorded by AOC Archaeology during 2024 walkover survey. Very ephemeral possible footings for a rectangular building under grass and moss. Very difficult to see in somewhat tall vegetation but can be felt underfoot. Measures 12m by c. 4.5m over banks, which are 0.3m tall and spread up to 1.2m wide. Very boggy surrounds. Not depicted on historic mapping.
Asset/Event Number	617
Asset/Event Name	Dyke, Achavanich
Type of Asset/Event	Dyke
Date and/or Period	Post-medieval
Listing No./NRHE Number	N/A
HER Number	N/A
Status	Non-designated Heritage Asset
Section:	A1.2
Easting	318372
Northing	942079
Council	Highland
Condition:	Degraded
Alignment:	NE/SW
Importance:	Negligible
Description	*Recorded by AOC Archaeology during 2024 walkover survey. A stone and turf dyke running parallel with burn on the W side, under grass. Stands 0.3m tall and spread 1m wide for c16m, but possibly revetted partially into stream bank to serve as a flood guard or augmentation of stream. Not depicted on historic mapping.
Asset/Event Number	618